

**NQ ASPHALT PTY LTD (2047240)**

**Tel:** 0740522600 **City:** PORTSMITH **Branch:** CNS **Acct Type:** AX **Business Type:** End-User

**Stock No:** 100031465 **Make:** AA **Model:** AP300F **Serial No:** YE500116 **Division:** G **FPC:** AP

**Eq Sts:** C **Inv Sts:** S **Last SMU:** 3847 H **SMU Date:** Feb 17, 2026

**Eng Make:** AA **Eng Model:** 8JC0731 **Eng Arr No:** **Trans Make:** **Trans S/N:**

Segment View

[Invoice View](#)

Cust: All



Job Code: All



Comp Code: All



**Customer Open Date Hours Work Order A/I Job COMP Pt Cust Lbr Cust Misc Cust Seg Total Notes**

2047240	Aug 25, 2025 12:00 AM	3643	117585339 - 001	C	035	6640					Customer complaint: Machine leaving defects in asphalt Complication of Repair: Screed to be diagnosed Cause of failure: Temp sensors shorting Corrective Action: Traveled to site and met with site foreman Amy to discuss reported fault. Started machine and activated screed heaters. Verified all screed heaters reached operational temperature (110°C). Used temperature gun to confirm screed temperature s. Inspected screed plates for any signs of damage - no major issues found. Cleared asphalt buildup from temperature sensors to ensure accurate readings. Identified exposed (bare) wires on temperature sensors. Shorted the wires to replicate the fault condition for diagnostic confirmation. Advised customer on required replacement parts to complete proper repair of the machine.
			117585339 - 002	C	608	0313					
			117585339 - 003	C	035	6640					
			<b>WO Total:</b>								

2047240	May 29, 2025 12:00 AM	3643	117569177 - 001	C	023	6640					Customer complaint: Screed plates heavily worn and damaged Complication of Repair: Screed plates worn beyond minimum wear percentage and broken on one edge Cause of failure: Excessive wear and age Corrective Action: - Check wear plate measurement
---------	-----------------------	------	-----------------	---	-----	------	--	--	--	--	---

s against minimum and maximum - Clean screed and prepare to disassemble - Remove screed plates, temp sensors and heating element clamp plates - Clean any asphalt buildup around edges of screed frame - Install new studs in new screed plates - Cut excess stud length from bottom side of screed plates for a smooth surface - Install new screed plates using new bolts and washers - Install temp sensor on LH side screed plate to replace broken sensor

117569177 - 002 C 023 6282

Customer complaint: Auger bearings heavily worn and need to be replaced  
Complication of Repair: Heavily worn outer carrier bearings and collapsed LH inner auger bearing  
Cause of failure: Heavy wear and asphalt ingress  
Corrective Action: - Clean auger and general area - Chisel excess asphalt away from bolt heads and mounting surfaces - Remove step hatches from top side of screed to gain access to auger drop box - Remove both outer carrier bearings and associated grease lines - Loosen LH auger shaft chain to remove shaft - Remove drop box hatches to gain access - Remove auger shaft and clean - Clean grease from drop box to locate old roller bearings - Fit new inner and outer bearings to auger shaft and reinstall - Re tension auger shaft chain - Grease auger drop box and reinstall drop box hatches - Reinstall screed step hatches

117569177 - 003 C 035 4300

Customer complaint: Steering system loose and will not lock in place  
Complication of Repair: Stripped threads in upper lockout pin hole  
Cause of failure: Worn/missing lockout pins for steering system  
Corrective Action: - Replace lower lockout pin - Replace upper lockout pin using a nut on the underside to tighten against the upper retention nut

117569177 - 004 C 023 6922

Customer complaint: Rear step brackets bent, brackets from dampener blocks broken and travel pin is missing  
Complication of Repair: Bent retainer brackets  
Missing travel pins  
Broken dampener brackets

ts Cause of failure: Rear step impact due to travel pin not being used  
 Corrective Action: - Remove rear step - Remove dampener brackets - Remove mounting brackets - Used press to straighten mounting brackets - Weld broken dampener brackets back together - Re mount brackets to step and mount step to screed - Fit new travel pin

117569177 - 005 C 608 0313

117569177 - 006 C 023 6640

**WO Total:**

117530990 - 001 C 041 7000

Customer complaint: 1000 hour service. Resultant damage: N/A Cause of failure: N/A Repair process comments: Machine cleaned before bringing into workshop, engine and radiator done also Completed 1000 hour service. Auger and drag chains were adjusted. Engine Valves were adjusted Engine oil, hydraulic fluid, final drives and coolant samples collected. Generator belts changed. Alternator belt adjusted. Engine oil and filter changed. Coolant added. Final drive had an oil change. Fuel filters changed. Defects found. - Front pin on the tow point is missing, front of the machine. - 4 fasteners on the front hatch to the engine missing - 3 fasteners for the hatch to the diesel tank missing. - Latch on the air filter cover missing. - both seat belts do not retract completely. left seatbelt is jammed. - Hose from the diesel tank to the pump for the sprayer is cracked. - Left side door is damaged. - No fire extinguisher

117530990 - 002 C 041 7000

**WO Total:**

117482241 - 001 C 023 1408

Customer complaint: Machine not starting. Fault codes displayed. Resultant damage: Machine will not start with key switch. Engine RPM will not increase. Cause of failure: Open circuit in ground wiring in engine harness. Repair process comments: Tracked down to machine. Downloaded PSR. Fault codes displayed were: (444- 3) Starter Motor Relay : Voltage Above Normal (3514- 9) Engine Throttle Actuator

2047240 2983 Oct 24, 2024 12:00 AM

2047240 2050 Feb 13, 2024 12:00 AM

or : Abnormal Update Rate. Starter motor wiring was checked. All was okay. Starter relay was checked. All was okay. Delayed engine power relay was checked. All was okay. Placed a jump wire between the ground wire for the starter relay and battery negative. Fault codes were corrected pointing towards an open in the ground circuit. Wire was traced on schematic and found to have 4 wires connected to it in the engine harness. Continuity and resistance was checked from the 12 pin connector before the 4 way ground circuit joining the engine components: Continuity and resistance was found between the connector and the air filter restriction sensor. Continuity and resistance was found between the connector and the throttle actuator. Continuity was found between the connector and the separate engine ground wire but was displaying open circuit on and off erratically. A jump wire from the 12 pin connector and the separate earth wire. Faults were rectified. Engine was able to start and engine RPM was able to be adjusted. Alternator belts were adjusted due to being loose and squealing.

**WO Total:**

2047240	Aug 31, 2023 12:00 AM	2050	117453541 - 001	C	540	7755	9000036	9000036	9000036	9000036	Customer complaint: install new product link module Resultant damage: N/A Cause of failure: updated Repair process comments: Old product link ECM and antenna removed New product link ecm and antenna installed
			117453541 - 002	C	540	7755	9000036	9000036	9000036	9000036	Customer complaint: Replace emergency stops Resultant damage: N/A Cause of failure: Updated Repair process comments: Emergency stops on consoles replaced
			117453541 - 003	C	540	752B					Customer complaint: Perform 500HR service Resultant damage: N/A Cause of failure: PM Repair process comments: Machine washed (r.g) Engine oil and filter replaced (n.m) Fuel filters replaced (n.m) Generator belts replaced (t.s) Oil samples taken (Engine, coolant, F/D) (n.m) Final drive oil changed. (LHR final drive over full with hydraulic oil) (n.m)

) Screed, auger lubricated (b.v) Diesel wash down  
 filter cleaned Auger chain adjusted (b.v) Drag con  
 veyor chain adjusted (b.v) V-belts inspected (b.v)  
 Radiator cleaned (r:g) Brakes tested ok (r:g)

117453541 - 004 C 01B 730H

Customer complaint: Install locking pin Resultant  
 damage: no locking pin Cause of failure: no lockin  
 g pin Repair process comments: Locking pin install  
 ed

117453541 - 005 C 040 5095

Customer complaint: Inspect final drive/hydrostati  
 c motor Resultant damage: hydraulic oil leaking in  
 to final drive Cause of failure: Park brake piston  
 seal Repair process comments: Screed support remo  
 ved Machine jacked and chocked Wheel, final drive,  
 housing and motor removed Final drive brake pack  
 was pressure tested (Failed) Lip seal on hydrosta  
 tic motor inspected (okay) Park brake was remove  
 d from final drive assembly. Upon disassembly it w  
 as noticed that the park brake seal was damaged. N  
 ew seals were installed and park brake assembled.  
 Final drive, housing and motor installed back ont  
 o machine Hoses fitted to motor and final drive fi  
 lled Wheel was installed back on machine and scre  
 ed linkage assembled. Machine started and run. No  
 leaks were present and park brake was operational  
 Machine washed and returned to Go line Park brak  
 e piston seal was leaking causing F/D to fill with  
 hydraulic oil Parts clean and seal kit ordered

117453541 - 006 C 01B 5801

Hose reel for washdown wont retract and is leaking  
 bad Customer complaint: Replace wash down hose re  
 el Resultant damage: Leaking hose, will not retrac  
 t Cause of failure: wear and tear Repair process c  
 omments: Supply lines removed Old hose reel remove  
 d New hose reel installed Supply lines installed

**WO Total:**

2047240 Feb 7, 2023 12:00 AM 2050 117416774 - 001 C 510 6639

**WO Total:**

2047240 Nov 17, 2022 12:00 AM 2050 117404687 - 001 C 540 7524

117404687 - 002 C 540 7524

Every 250 Service Hours TAI Inspection Engine Oil  
 Sample - Obtain Engine Oil and Filter - Change B  
 elt - Inspect/Adjust/Replace Condenser (Refrigera



**WO Total:**

2047240	Feb 1, 2022 12:00 AM	1792	117354760 - 001	C	540	7524	9000643	9000643	9000643	Customer complaint: Machine due for PM1. Resultant damage: No resultant damage. Cause of failure: No cause of failure PM1 due. Repair process comments : Carried out take 5 to undertake service procedures on machine. Operated machine to wash bay. Isolated machine and washed machine to meet CC requirements in workshop. Operated machine to work area. Reviewed service procedure and parts. Carried out service as per OMM interval and procedure. Disposed of waste oils and filters. Replaced generator belts. Completed chain adjustment on Auger and conveyor drag adjustment chains. Cleaned work area. Washed down affected areas of machine. Carried out PSR. Tested machine operation. Carried out reports, submitted oil sample. Park up ready for collection.
2047240	Feb 1, 2022 12:00 AM	1792	117354780 - 001	C	511	1431	9000643	9000643	9000643	Customer complaint: Supply and install 2 new orange flashing beacons. Resultant damage: No beacons working on machine. Cause of failure: One light not working and one light missing. Repair process comments: Parked and isolated machine. Ordered and sourced 2 x LED beacons. Manufactured beacon light bracket that was missing. Painted brackets x2 Mounted x2 beacon lights and wired into harness with new pins and plugs where required. Tested operation. Both lights worked with no faults. Complete reports.

**WO Total:**

2047240	Feb 1, 2022 12:00 AM	1792	117354780 - 002	C	023	7189	9000643	9000643	9000643	Customer complaint: Center conveyor drive guard has become loose and dislodged. Potential for guard to get caught in auger at rear of machine and cause major damage. Resultant damage: Center chain guard loose and not secured. Cause of failure: Welds worn down due to wear and normal operation. Material getting dragged past welds over time has worn them down. Repair process comments: Moved machine to fabrication bay and isolate. Bent guard back straight that was bent on curved end. Prepped chain guard. Grind back previous welds and clean up for rewelding. Prepped hopper mounting points for chain.
---------	----------------------	------	-----------------	---	-----	------	---------	---------	---------	---

in guard. With use of fire spotter due to potential fire risk, guard was rewelded back into position. Ground back excess weld and cleaned up area. Test operation of conveyor to ensure no problems were present post repair- None found. Cleaned work area. Complete reports.

**WO Total:**

2047240	Oct 18, 2021 12:00 AM	1641	117337995 - 001	C	510	6282	Customer complaint: Replace Auger Segments. Resultant damage: No resultant damage. Segments require replacement. Cause of failure: Wear and tear through machine operation. Repair process comments: Moved machine into the workshop. Lift screed and lock into place. Gather heating equipment and set up. Heat up shaft with LPG heat torch to make caked on asphalt malleable. Scrape off asphalt mix and dig out bolts. Undo mounting hardware and removed old auger segments. Cleaned shafts with diesel and bolt holes. Upon inspection of shaft, it was discovered that both auger support bearings were worn and full of asphalt. Inform customer and discuss repair options. Approval given to replace bearings. Remove bearings and grease lines on both sides. Replaced bearings with new and installed grease seals. Fitted new auger segments with new hardware. Tested auger operation. All operated correctly. Grease bearings. Move machine down to backyard and park up for customer collection. Completed service report and cleaned work area.
2047240	Oct 4, 2021 12:00 AM	1503	117335412 - 001	C	540	7525	Customer complaint: Replace engine primary and secondary air cleaners. Resultant damage: No resultant damage. Cause of failure: No cause of failure due for change. Repair process comments: Remove primary and secondary air cleaners. Wipe out filter housing. Install primary and secondary air cleaners. Complete reports.
			117335412 - 002	C	510	105B	
			<b>WO Total:</b>				

**WO Total:**

2047240	Jun 21, 2021 12:00 AM	1238	117317474 - 001	C	540	7524	Customer complaint: 250 Hour service Resultant damage: N/A Cause of failure: N/A Repair process comments:
---------	-----------------------	------	-----------------	---	-----	------	---

ents: Machine was washed and then set up in the workshop. A TA1 inspection completed. PSR Downloaded. Engine oil and filter replaced. Primary and secondary fuel filter replaced. Generator belts replaced. All grease points greased. Run machine and test. No faults found. Complete reports.

117317474 - 002 C 510 105B 9000643 9000643 9000643

Customer complaint: Replace Air Filters Resultant damage: N/A Cause of failure: N/A Repair process comments: Primary and secondary Air filters replaced.

**WO Total:**

9000036

Customer complaint: Replace cracked guard with updated part. Apply PS46882 Resultant damage: Cracked guard. Cause of failure: Vibration, structural defect. Repair process comments: Apply PS46882 to AP 300F

117289190 - 003 C 510 105B 9000643 9000643 9000643

Customer complaint: Replace air filters as part of 1000hr service. Resultant damage: N/A Cause of failure: N/A Repair process comments: Old air filters removed. New air filters installed.

117289190 - 004 C 540 7526 9000643 9000643 9000643

Customer complaint: Machine due for 1000hr service. Resultant damage: N/A Cause of failure: N/A Repair process comments: Machine moved into workshop and set up for repair. 1000hr service completed as per OMM including:- Engine, Planetary, Hydraulic oil SOS samples taken. Conveyor Drive Chains (Auger) - Adjusted Conveyor Drive Chains (Drag) - Adjusted Engine Oil and Filter - Changed Hydraulic Oil Filter - Changed Final Drive Planetary Oil - Changed Primary and Secondary Air Filters - Changed Fuel System Filter (In-Line) - Replaced Fuel System Primary Filter (Water Separator) Element - Replaced Fuel Tank Strainer - Cleaned Fuel Tank Water and Sediment - Drained Generator - Inspected Bearings - Lubricated Hopper Cylinder Bearings - Lubricated Engine Valve Lash - Checked and adjusted. Moved machine to backyard and complete reports.

**WO Total:**

9000036

Customer complaint: Replace canopy hydraulic tank. Resultant damage: Tank leaks oil. Cause of failure

2047240 964 Dec 16, 2020 12:00 AM

117289190 - 001 C 540 7755 9000036 9000036 9000036

2047240 964 Aug 21, 2020 12:00 AM

117269858 - 001 C 510 5056

e. Tank had been struck and cracked. Tank taped up . Repair process comments: Moved paver into workshop and set up for repairs. Lower screed, chock wheels and isolate. Remove tank cover and disconnect wiring harness. Drain hydraulic fluid from tank. Disconnect and remove broken tank. Clean up sealing surface and install new tank with new seal. Fill hydraulic oil to correct operating level. Check for leaks- none found. Re-connect wiring harnesses and install cover. Test operation of canopy through full range of motions multiple times. All okay. Wash residual oil off machine after repair. Move machine to back yard to ready for customer collection. Complete reports.

Customer complaint: Machine due for PM1 service. Resultant damage: N/A Cause of failure: N/A Repair process comments: Machine moved into workshop and set up for repair. The following was completed as part of the PM1: TA1 Inspection Auger Slide - Lubricated Belt (Generator Drive) - Replaced Belts - Inspected Conveyor Drive Chains (Drag) - Adjusted Cooling Cores - Cleaned Engine Air Cleaner Inlet - Cleaned Engine Air Filter Primary Element - Replaced Engine Oil Sample - Obtained Fuel System Filter (In-Line) - Replaced Fuel System Primary Filter (Water Separator) Element - Replaced Engine Oil and Filter - Changed Completed reports

Customer complaint: Troubleshoot fault code. Resultant damage: No power to material height sensors. Cause of failure: Blown Fuse. Repair process comments: During the PM1 it was noted that there were a few active codes present. Complete troubleshooting as per UENR5499. Confirmed that there was no voltage to the connector. Checked wiring for a short to ground none present. Checked fuse and found to be blown. Replaced fuse. Checked the harness for an open circuit - none found Checked for short to battery +ve - none found At the machine harness connector for the sensor, a jumper wire was connected to

117269858 - 002 C 540 7524 9000643 9000643 9000643

117269858 - 003 C 595 1706

117269858 - 004 C 023 5943 9000230 9000230 9000230

between the sensor return contact and signal contact - code changed. Blown fuse determined to be the cause of the code. Complete reports

117269858 - 005 C 023 7168 9000230 9000230 9000230

Customer complaint: Repair cracked alternator guard. Resultant damage: Cracked guard. Cause of failure: Generator vibrations - guard does not have enough crack resistance. Repair process comments: Upon generator belt replacement as part of the PM1 service, when the alternator guard was removed it was noted that it was starting to crack. Informed leading hand and the guard cracks were repaired. Guard was taken to boilermaker and cracks ground out and welded. The guard was then painted and installed onto the machine. Complete reports.

117269858 - 006 C 023 6640 9000230 9000230 9000230

Customer complaint: LH screed extension extends but will not retract randomly. Resultant damage: Screed extensions will not retract on their own. Cause of failure: Screed bushes sticking. Repair process comments: Machine was brought into workshop and run until at operating temperature. Screed would not fault so the extend/retract pressures were checked for both LH and RH cylinders. The pressures were: LH extend: 2400PSI (A1) LH retract: 2300PSI (B1) RH extend: 2350PSI (A2) RH retract: 2290PSI (B2) The LH screed extension was removed from machine and both guide rods were removed. The guide rods were placed on V blocks and spun, using a dial indicator to check if they were bent. The dial indicator did not move meaning they were both straight. The rods and bushes were measured: Top bush vertical measurement: 1.974" Top bush horizontal measurement: 1.976" Top Rod: 1.967" Bottom bush Vertical/horizontal measurement: 3.4635" Bottom Rod: 3.462" When Guide rods were removed some minor rust was observed between the two top bushes but nothing of note that would contribute to binding. The bushes are made from hard plastic with no lube at all. Screed extension was assembled, and machine was tested. Gauges were fitted to the retract and extend circuit of both L.H. and R.H. cylinder

circuits to see if the pressure increased at any stage. The retracting pressure for both L.H. and R.H. cylinders was roughly 900-1000PSI and the return to tank pressure was 0 PSI with no major spikes in pressure until at end of stroke. This meant the screed was moving normally and not binding. It was noticed on both the L.H. and R.H. extend circuits that both extending pressures were 2000 PSI and return to tank pressures were 2000 PSI. Machine was driven and tested for approx. 1 HR and did not fault. Tech request 10963 was logged with all details of finding for CAT'S direction and input. CAT request that all the screed bushes be replaced and sent back to them for inspection. The tech request also recommended installing grease lines to the bushes. Ordered required bushes from overseas and await the arrival of parts. In the interim the machine was sent back to work. When all parts had arrived, the paver was brought in and set up for repairs. Screed cover plates removed. Screed side plates removed. Support rods unbolted. Screed cylinders disconnected. Screed moved rearwards to remove support rods. Bushes removed and labelled to be sent to Caterpillar. Holes drilled and tapped in to barrels for grease lines. Barrels cleaned and new bushes installed. Screed reassembled. Holes drilled in cover plates for remote grease point. Grease lines installed and barrels filled with high temperature grease. Screed extension tested extensively. No further faults found. Complete reports.

Customer complaint: Supply screed sensors as requested by customer. Resultant damage: N/A Cause of failure: N/A Repair process comments: Supply screed material feed sensors and related componentry as requested by customer.

**WO Total:**

2047240	Jun 23, 2020 12:00 AM	607	117259680 - 001	C	023	7302
---------	-----------------------	-----	-----------------	---	-----	------

**WO Total:**

2047240	Jun 5, 2020 12:00 AM	567	117257042 - 002	C	540	752B
---------	----------------------	-----	-----------------	---	-----	------

Customer complaint: Perform 500HR service. Resultant damage: No damage. Cause of failure: No failure

. Repair process comments: Machine was brought into workshop and a PSR download was completed. A TA1 inspection was completed. The following SOS samples were obtained: Engine, LH rear final, RH rear final, LH front final, RH front final and coolant. The engine oil was drained and old engine oil filter was removed. New engine oil filter was fitted and engine was filled with new engine oil. The fuel filter and fuel/water separator were both replaced. The secondary air filter was cleaned and the primary was replaced. The fuel tank strainer was removed and cleaned. The conveyor chains were checked and adjusted and the auger chains were checked and adjusted. Machine was greased and all operation checks completed.

117257042 - 003 C 510 1054

117257042 - 004 C 023 4192 9000230 9000230 9000230 9000230

Customer complaint: Right front spindle bearing collapsed. Resultant damage: Bearing U/S. Cause of failure: Loose retaining bolt. Repair process comments: When completing the P133172 on the front spindles it was found that the king pin retaining bolt had come loose until it had hit the lower bearing cover. Then when removing the king pin, the lower bearing assembly collapsed. Fitted new bearing when the spindle was reassembled. Refitted kingpin retaining bolt, torqued to standard CAT spec and inspected.

117257042 - 005 C 023 4305 9000230 9000230 9000230 9000230

Customer complaint: Loose/missing steering linkage nuts. Resultant damage: Contact with Bogie frame. Cause of failure: Loose nuts due to machine vibration/operation. Repair process comments: When completing P133172 on the front spindles it was found that the steering linkage control nuts had become loose. Remove all bogie steering rods on both sides of the machine, found that one of the nuts were missing. Ordered new nut. Cleaned all threads. Refitted rods and loctite all nuts and bolts. Torqued to standard CAT specs. Completed service report.

117257042 - 006 C 510 7174 9000230 9000230 9000230 9000230

Customer complaint: When replacing alternator belt as per 500hr service the belt guard was removed

and found to be cracked. Resultant damage: No further damage. Cause of failure: Vibration/bad design /not strong enough. Repair process comments: Old guard was removed whilst changing belts and was found to had structural cracks. A new guard was ordered and fitted to machine. Place old guard in warranty shed.. Complete Paperwork.

Customer complaint: Canopy switch has intermittent fault where it will not go down but pump still works. Resultant damage: No further damage. Cause of failure: Faulty switch contacts. Repair process comments: Move machine into workshop. Isolate and check wheels. Remove guard that switch is mounted in removed. The switch was replaced with new switch and guard was fitted to machine. Switch was tested to ensure correct operation. No further intermittent faults found. Move machine to backyard for customer collection.

**WO Total:**

2047240	May 29, 2020 12:00 AM	536	117255666 - 001	C	023	4000	9000230	9000230	9000230	9000230	Customer complaint: DRIVE MOTORS LOCKED UP WHEN MACHINE MOVING ON SITE, CODES FLAGGED ON MONITOR:- FMI 8 CID 2687, FMI 8 CID 2686, FMI 8 CID 2685. DIAGNOSE / REPAIR Resultant damage: UNABLE TO REPLICATE FAULT. Cause of failure: UNABLE TO REPLICATE FAULT. Repair process comments: - MOVE MACHINE FROM PARKED LOCATION INTO WORKSHOP. - CHECK DIAGNOSTICS, FIND LOGGED CODES, CONNECT ET AND CHECK CODES / DOWNLOAD PRODUCT STATUS REPORT. - FIND CODES RELATING TO DRIVE MOTORS, LHS / RHS DRIVE MOTORS UNEXPECTED FORWARD MOVEMENT. - CHECK DIAGNOSTICS PROCEDURE, VERY LITTLE INFORMATION AVAILABLE. - GET TOO LING AND JACK UP MACHINE / BLOCK TO SECURE MACHINE OFF GROUND. - CHECK CONDITION OF SENSORS ON BOTH WHEELS, DUE TO ACCESS BEHIND REAR DRIVE WHEELS UNABLE TO FULLY INSPECT, REMOVAL OF SCREED BRACING BAR AND WHEELS REQUIRED TO ACCESS SENSORS. - CHECK MACHINE SCHEMATICS AND INSPECT HARNESS ASSY FROM PLATFORM UP TO ECM, PERFORM WIGGLE TEST TO CHECK FOR LOOSE CONNECTIONS- NIL DETECTED. - MOVE MACHINE TO TESTING AREA AND TEST IN ALL CONDITIONS, UNABLE
---------	-----------------------	-----	-----------------	---	-----	------	---------	---------	---------	---------	--

TO FAULT OPERATION. - CONTACT CUSTOMER TO GET UPDA  
 TE ON ACTUAL OPERATING CONDITION WHEN FAULT OCCURR  
 ED TO FOCUS TESTING ON THIS OPERATION. - RUN TEST  
 MACHINE OPERATION IN HIGH SPEED FORWARD FOR EXTEND  
 ED PERIOD, FORWARDS / BACKWARDS UP LOADING RAMP, A  
 TTEMPT TO GET MACHINE TO ROLL, MACHINE WILL ROLL F  
 OR 1.5M THEN AUTOMATICALLY APPLY PARKING BRAKE TO  
 STOP MACHINE MOVEMENT. -MACHINE REQUIRED TO GO BAC  
 K TO CUSTOMER FOR WORK AND DUE TO FAULT NOT OCCURR  
 ING AND FREQUENCY OF CODE ONLY HAPPENED ONCE, OPER  
 ATIONAL ENVIRONMENT OR INTERMITTANT FAULT SUSPECTE  
 D. -UNABLE TO CONFIRM FAULT. -CONTINUE TO MONITOR.

**WO Total:**

9000036

9000036

9000036

7751

540

C

117253425 - 001

567

May 15, 2020 12:00 AM

2047240

Customer complaint: Complete PB3172 as per CAT Se  
 vice letter. Resultant damage: - Cause of failure  
 : - Repair process comments: Completed Take 5. Gat  
 hered all parts and checked to ensure they were al  
 l delivered, Drove machine into the washpad. Pressur  
 e washed machine to meet CC guidelines. Drove int  
 o workshop. Carried out PB3172 as instructed by se  
 vice letter. Torqued wheel bearings as per Media  
 Number -M0068282-05 Tested machine after repair.  
 Completed service report. Clean work Area. \*\*\* A  
 s per CAT Global Machine Policy the \$1882.52 is fr  
 eight charge is claimable to CAT as the wheels had  
 to be sourced from overseas (Grimbergen) as this  
 service letter was to be completed as a "Priority"  
 . At time of ordering parts these were the only on  
 es available in the world.\*\*\*

**WO Total:**

9000230

9000230

9000230

1400

035

C

117245898 - 001

363

Mar 31, 2020 12:00 AM

2047240

Customer complaint: Please identify why the fuse k  
 eeps blowing on the Crown circit. Resultant damage  
 : Shaft stripped threads and rod ends thread strip  
 ped. Cause of failure: Motor works hard and gets h  
 ot and blows the fuse. Motor is working hard becau  
 se the threaded rod/shaft that drives the crown ang  
 le, appears to have wound out and stripped the th  
 reads. Repair process comments: Traveled to site a  
 t Mareeba. Liased with customer. Inspected machine  
 and confirm fault. Tested machine and found to bl  
 ow a 20 Amp Crown fuse when the motor lugged down.



e found. Complete paperwork.

**WO Total:**

2047240	Mar 27, 2020 12:00 AM	351	117245406 - 001	C	735	7000	9000230	9000230	9000230	Customer complaint: Erratic movement of screed up and down during paving operation. Resultant damage: N/A Cause of failure: Bent control arm bolts. Repair process comments: Test drove machine with operator present to verify faults/machine behaviour in the backyard. Move machine into workshop for further investigation/diagnosis. Check screed control arms. All ok. Check screed control arm mounts. LHS mount appears to be bent and RHS is beginning to show signs of bending. Check PS/PI service literature. Found that PS53911 was listed for replacing control arm bolts, but machine was not in the eligible serial number range. As machine still has new equipment warranty, control arm bolts were replaced as machine was showing symptoms as outlined in the PS Ordered new bolts. Replaced new bolts when they arrived. Set screed attachment calibration back to zero. Test machine operation. All operations okay. Move machine down to customer collect area. Complete paperwork.
---------	-----------------------	-----	-----------------	---	-----	------	---------	---------	---------	--

**WO Total:**

2048553	Mar 18, 2020 12:00 AM	351	117243922 - 001	C	510	7168	9000230	9000230	9000230	Customer complaint: Alternator guard cracked. Resultant damage: Cracked Gaurd. Cause of failure: Machine Vibration. Repair process comments: Wash machine prior to entering workshop. Move machine into workshop and position for repair. Disconnected and remove ECMs to allow enough room to remove guard. Old guard was removed. New guard was fitted. Active diagnostic codes present after reinstalling ECM connectors. Removed connectors and found seals had moved and split during installation causing bad connections. Replaced split ECM connector seals and reinstalled. Tested operation, no active codes. Move machine down to customer collect area. Complete paperwork. Photos of cracked guard attached to Service Report.
---------	-----------------------	-----	-----------------	---	-----	------	---------	---------	---------	---

**WO Total:**

2048553	Mar 10, 2020 12:00 AM	315	117242450 - 001	C	540	7755	9000036	9000036	9000036	Customer complaint: PS46484 available for Muffler.
---------	-----------------------	-----	-----------------	---	-----	------	---------	---------	---------	--

Resultant damage: N/A Cause of failure: Fault from factory  
 Repair process comments: Washed machine prior to entering workshop. Move machine into workshop. Remove old muffler. Install new muffler and hardware as per PS46484. Test machine to ensure there is no leaks. No exhaust leaks found. Complete paperwork and move machine down to customer collection area. old Muffler was removed new bracket and muffler was fitted with new hardware

Customer complaint: 250hr serv Resultant damage: N/A Cause of failure: N/A Repair process comments: TA1 Inspection Auger Slide - Lubricate Belts (Generator Drive) - Replaced Other Belts - Inspected Conveyor Drive Chains (Auger) - Adjusted Conveyor Drive Chains (Drag) - Adjusted Cooling Cores - Cleaned Cooling System Coolant Sample (Level 1) Engine Air Cleaner Inlet - Clean Engine Air Filter Primary Element - Replaced Engine Oil Sample Wash Down Filter - Cleaned Fuel System Filter (In-Line) - Replaced Fuel System Primary Filter (Water Separator) Element - Replaced Engine Oil and Filter - Changed Machine Greased RH Hand Rail Tightened Conveyor drag chains Adjusted

Customer complaint: Replace air filters as required. Resultant damage: Restricted. Cause of failure: Dirty. Repair process comments: Replaced air filters as part of PM1 service.

Customer complaint: Screenshot heaters not working correctly. Resultant damage: Heater element not working Cause of failure: Ground fault. Repair process comments: Machine driven into workshop. Machine ran for 30 minutes to get fault code E715 to come up. Product Status Report downloaded. Fault code checked in ET, no test procedures or diagnostic test available. Fault code searched in SIS, code did not come up. Ground connections were checked. Ecm plugs were checked. Tech request made and submitted. Code E715 does not come up under AP300, no test procedure could be found, no info on ground fault c

117242450 - 003 C 540 7524 9000643 9000643 9000643

117242450 - 004 C 510 1054 9000643 9000643 9000643

**WO Total:**

117239287 - 001 C 035 8225 9000230 9000230 9000230

2048553 Feb 20, 2020 12:00 AM 216

could be found. Code searched under AP600 and test procedures found. Fault code would not come up for remainder of testing. Ground fault possibly caused by moisture/water getting into screed heating element plug. As the screed heaters are high voltage a high electrician was organised to diagnose screed heater faults. Electrician performed testing on high voltage components in screed, mainly the heating elements. Electrician disconnected and tested resistance through all heating elements. One of the rear left heating elements in the L/H extension has shown a resistance below spec. Electrician was expecting an absolute minimum of 1MegOhm of resistance across each heating element, L/H/R was 0.3MegOhm, indicating a ground fault in the element. New heating element was ordered. Installed new heating element. Tested on machine. Heater element was now working correctly. Complete job paperwork.

**WO Total:**

2048553	Jan 16, 2020 12:00 AM	192	117233209 - 001	C	035	4300	9000230	9000230	9000230	Customer complaint: Troubleshoot steering active alarm Resultant damage: Steering active alarm 164-3 Cause of failure: Corroded sockets in connector Repair process comments: Pack ute and travel to site. Connect E.T and compete download and check fault. As machine was still operating could only complete quick harness check. Appeared ok and disconnecting harness changed code from -3 to -4. Suggested bringing machine to workshop so the machine could be lifted to inspect steering cylinder. Packed up tools and returned to workshop. Machine was brought into workshop and no active fault present. Tested machine to try and get fault to occur. Unable to lift machine. Brought machine into workshop and lifted front of machine. Removed electrical connector to steering cylinder and inspected. Found inside of connector to be corroded. Cleaned up corrosion and installed plug and parked machine in the yard waiting for the new harness to arrive. New harness arrived and machine was brought into the workshop. The front of the machine was lifted and the old harness removed. Installed new harness and and tested
---------	-----------------------	-----	-----------------	---	-----	------	---------	---------	---------	--

d operation. Test results were all good. Complete  
d service report

Customer complaint: Unable to calibrate left hand  
side material height sensor Resultant damage: Unab  
le to calibrate Cause of failure: Sensor out of ra  
nge Repair process comments: Connect E.T to machin  
e and attempt to calibrate sensor - Unsuccessful.  
Check machine software files and updated to latest  
. Attempt to calibrate sensor - Unsuccessful Check  
values against right hand side and found to be di  
fferent. Tested sensor and found to be faulty. Ord  
ered new sensor. Removed old sensor and fitted new  
sensor. Complete calibration - successful Complet  
e reports and warranty paperwork

**WO Total:**

Customer complaint: Screed extender wings will not  
extend or retract Resultant damage: Screed pressu  
re reducing valve adjusted Cause of failure: Incor  
rect pressured reducing valve adjustment Repair p  
rocess comments: Travel to site Take download. Te  
st screed extenders. Extenders are slow to move,  
with material in auger hopper arms need to be push  
ed to move. With no material in hopper extender  
arms will work. Road crew operate machine to compl  
ete project, connect gauges to screed manifold and  
check pressures. Pressure at 1500 psi. Specifica  
tion is 1770 - 1870 psi. Wait until road crew ha  
ve completed project so pressure can be adjusted a  
nd tested. Pressure at screed pressure reducing  
valve adjusted to 1870 psi. Test screed extender  
s. Extenders will retract and extend quicker. Tra  
vel off site

**WO Total:**

Customer complaint: Investigate engine noise Resul  
tant damage: Nil Cause of failure: Unknown Repair  
process comments: 19-11-19 David Traveled out th  
e machine to investigate suspect engine noise Did  
machine pre start Liaised with the client and deci  
ded that we could not hear the noise unless it was  
working. Run the machine for approx 30mins but co

117233209 - 002 C 023 5628 9000230 9000230 9000230

2048553 182 117232240 - 001 C 023 7222 9000230 9000230 9000230

2048553 117 117224830 - 001 C 035 1000 9000230 9000230 9000230

Jan 10, 2020 12:00 AM

Nov 19, 2019 12:00 AM

uld identify a rattle or any unusual sounds coming from engine bay. Did machine download Traveled h  
ome Did service report 20/11/2019 Sam Travel out  
to machine to investigate suspect engine noise. Sa  
t on the machine while it was operating for approx  
imately 2 hours. Noise did not occur. Pack up and  
head back to workshop

**WO Total:**

2048553      Oct 15, 2019 12:00 AM      77      117218284 - 001      C      540      7500      9000643      9000643      9000643      9000643      9000643

Customer complaint: Initial 50 hour service. Resultant damage: No resultant damage. Cause of failure : No cause of failure. Repair process comments: Machine was driven into workshop, wheels chocked and isolated. Initial 50 hour service was completed. Engine oil and filter were changed. Rear final drive oil were changed. Front final drive oil were changed. Tension of the auger conveyor drive chain was checked and found to be okay. Tension of the conveyor chain was checked and found to be okay.

**WO Total:**

2048553      Oct 14, 2019 12:00 AM      20      117218226 - 001      C      023      4801

Customer complaint: Front wheel assist not working  
Resultant damage: . Cause of failure: . Repair process comments: JW During testing in carns it was noted Front wheel assist not working. Checked tire action control was enabled. Reflashed machine software. Sent Tech request. Tech request advised to send PSRPT. Obtained PSRPT and sent back. Tech request advised to Test Via a ceartin method. Tested machine in this method and front wheel assist still did not work. Responded to tech request with Video and awaited further action BW Spent time reading through previous emails relating to the fault. Travelled to machine location and communicated with customer in relation to faults. Operator did not feel that the machine had an issue with the travel assist system. Connected electronic diagnostic tooling. Monitored system parameters. Noted that the control solenoid would energize when the system was turned on and propel handle moved to initiate machine movement. System would not function if the machine was already in motion and the control button was actuated to turn on the function. Jacked up m

achine and confirmed this and that the front wheel  
s were in fact moving. Captured video evidence to  
confirm this further. Return to workshop and began  
researching manual to find the description of the  
system and the Foreman in charge of the job requ  
sted to stop and write a report stating the findin  
gs so far.

**WO Total:**

2047240      Oct 10, 2019 12:00 AM      77      117217611 - 001      C      012      1429

Customer complaint: Install aftermarket lighting po  
int on AP300 paver. Require wiring connectors for  
magnetic base lights in four locations. Resultant  
damage: N/A Cause of failure: N/A Repair process  
comments: Checked harness schematic for power, gro  
und and capacity of electrical circuits in desired  
areas of machine. Located power supply and ground  
in L/H and R/H screed panels. Altered wiring of c  
onnectors in panel for secure, reliable connection  
s. Extended 2 wire harness out of remote panels, p  
-clamped harness in position and secured power soc  
ket with blanked 2 pin connector. Fitted labels to  
panels near power sockets. Located factory light  
wiring behind L/H and R/H seats. R/H harness was f  
ine as is. L/H harness was extended to match lengt  
h of R/H. Fitted labels to panels near power socke  
ts. Circuits tested with a multimeter once all wi  
ring was complete.

117217611 - 002      C      012      7259

Customer complaint: Customer requested tool box to  
be fitted to L/H rear of machine. Resultant damag  
er: N/A Cause of failure: N/A Repair process commen  
ts: Measured and test fitted various locations at  
rear of machine. Best location on top of L/H side  
of screed. Sat toolbox in position, raised screed  
and checked for clearance. Lowered screed, marked  
bolt hole locations. Drilled holes in toolbox and  
screed deck. Painted bare metal and fitted bolts t  
o holes with Loctite on threads. Checked operation  
of toolbox, lid and screed once complete.

**WO Total:**

2048553      Sep 23, 2019 12:00 AM      77      117214488 - 001      C      036      9042      9000230      9000230      9000230      9000230

Customer complaint: Inspect bogie wheel bearings p  
rior to delivery Resultant damage: nil Cause of fa

Failure: Over tensioned RHS bogie wheel bearing excessive pre load Repair process comments: Machine driven into workshop and isolated Take 5 completed and front of machine raised off the ground. Remove cover and split pin. Check tension with torque wrench. Found LHS in spec and RHS to be 4 times over spec and wheel would not free spin. Complete preload procedure to check if correct. found to be correct however castle nut would not line up. Decision made to skim the nut until correct preload was achieved and the castle nut lined up with the split pin hole. installed cover. tested machine and completed report

117214488 - 002 C 023 726M 9000230 9000230 9000230

Customer complaint: Some Floor mats lifting Resultant damage: Floor mat to not be secure Cause of failure: Adhesive not bonding to floor Repair process comments: machine was brought in and isolated removed old floor mats that were lifting and adhesive clean surfaces and reapply adhesive install floor mats complete reports

117214488 - 003 C 023 7273 9000230 9000230 9000230

Customer complaint: L/H side door loose, not closing properly, latch not lining up when closing. Resultant damage: Door latch not lining up correctly . Cause of failure: Hinge have excessive movement. Repair process comments: Sourced new hinge. Replaced worst hinge. Adjusted position of hinge and door to line up with latches.

**WO Total:**

1000127 Aug 28, 2019 12:00 AM 20 117209681 - 001 C 016 7000

Customer complaint: Predelivery Resultant damage: NA Cause of failure: Repair process comments:

117209681 - 002 C 600 7606

117209681 - 003 C 524 0334

Customer complaint: Cant close segment without sim  
s Resultant damage: Cant close segment without sim  
s Cause of failure: Repair process comments:

117209681 - 004 C 012 7307

117209681 - 005 C 012 7307

117209681 - 007 C 012 7419

117209681 - 008 C 036 6631

117209681 - 009 C 012 1411

117209681 - 010 C 012 1431

Customer complaint: Install two rotating beacons.  
Resultant damage: No resultant damage. Cause of failure: No cause of failure. Repair process comments: Ordered Mini LED beacons from ashdown ingrams as beacons available through HD are too large and cause fibreglass to crack as previously found with YES00115. Machine was brought into workshop, wheels chocked and isolated. Brackets for both rotating beacons were removed from machine. Brackets were modified to allow correct mounting of beacons. Deutsch plugs were fitted to each rotating beacon wiring and conduit run along the wiring. Front rotating beacon was installed onto bracket, mounted onto machine and connected to the appropriate wiring harness. Rear rotating beacon bracket and beacon were installed onto machine. Machine was then cleaned and prepared for dispatch. Rear beacon was fitted to machine on arrival

117209681 - 011 C 025 7334

117209681 - 012 C 025 1814

Customer complaint: Adjust modular front end. Customer request: Resultant damage: No resultant damage. Cause of failure: front Beam needs to be adjusted in as advised by Ryan Van der brooke  
Repair process comments: Machine was brought into workshop, wheels chocked and isolated. Spacers and bolts were removed from modular front end allowing it to be mounted using the second mounting pin holes. Machine was washed. Spacers and bolts were provided with machine upon dispatch.

117209681 - 013 C 510 7150

Customer complaint: Instrument panel guard arrived in Damaged on machine at HD Cairns  
Resultant damage: Nil  
Cause of failure: Operator console was not centred before Canopy was lowered resulting in canopy rubbing on operator panel  
vandal guard being damaged.  
Repair process comments: Advised matt per email and sent email of guard damage.  
Ordered replacement Guard on project service call as advised by att perry

117209681 - 014 C 023 4801

**WO Total:**