

Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca



Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 Weyburn 306-842-2629

Ship To:

Invoice To:

		WITIG	ciloisc		300 ZZ- ZIIU
Branch		·			·
REGINA		*REPRI	NT*		
Date	Time				Page
10/25/21	22:	00:16	(B)		01
Account #	Phone #			Inv #	ŧ
Ship Via		Purchase C	Order -	#	
Tax ID #					
		•	Sales	perso	n
			;	S76	
			•		

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

018084

WARRANTY DATE

HRS

002724

COMBINE 1680

09/20/21 09/23/21

3547

REPLACE SHAKER BUSHINGS

SEGMENT# 1 C 14029 NA

COMPLAINT:

-REPLACE SHAKER BUSHINGS

CORRECTION:

Replaced all the shaker arm bushings. Customer did not request to square the backend. In order to remove shaker arms, had to remove spreaders and sieves. Inspected all the rails and sieves, no cracks found. Replaced pitman arm bearings. When installing the shaker arms I just put all the washers in the same spot and pressed the bushings to the same spot. Ran combine.

в94553	BUSHING/KIT	1	307.80	307.80
169256C2	WASHER	5	5.09	25.45
193132C91	BEARING	2	245.16	490.32
993	CONDITIONER 1L	1	10.48	10.48
			PARTS	834.05
			LABOR	1490.00
11008001		SEGMENT	TOTAL==>	2324.05

SEGMENT# 2 C 14029 NA

09/20/21 09/21/21

CHANGE PTO OIL AND FILTER/CHECK PTO PRESSURE/ADVISE CUSTOMER **COMPLAINT:**

CUSTOMER OF FINDINGS

FILTER IN CAB

CORRECTION:

Teed in gauge to check PTO clutch pressure. Pressure was 235psi with clutches not engaged and 210psi with clutches

-CHANGE PTO OIL AND FILTER/ CHECK PTO PRESSURE/ ADVISE

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment her reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Standars are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!





Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca



Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 306-842-2629 Weyburn

Ship To:

Invoice To:

	WITIG	criorac		300-224-2110
Time				Page
22:0	00:16	(B)		02
Phone #			Inv #	ŧ
	Purchase (Order -	#	
		Sales	perso	n
			S76	
	22:0 Phone #	Time 22:00:16 Phone #	22:00:16 (B) Phone # Purchase Order	Time 22:00:16 (B)

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN WARRANTY DATE

HRS

002724 1680

COMBINE

3547 018084

engaged. In spec. Changed PTO oil and filter.

Notified customer of findings, found out that customer was having problems with delayed engagement.

Adjusted regulator pressure to be 220psi with clutches engaged, removed the gauge. Went to check the accumulator pressure. Was having a hard time finding the fitting to check the pressure so removed the accumulator to get a closer look. Pushed valve open and it had no pressure, also hydraulic oil came out.

Priced out new accumulator and phoned the customer. He approved to order and replace accumulator. Noticed as I was installing gauges and removing accumulator that the valve was sitting on plate loose.

Recommended replacing o-ring and tightening bulkhead fitting. Have to remove plate to gain access. Removed top plate, removed valve and replace sealing washer with o-ring, copper washer and sealant. Replaced top plate gasket. When new accumulator came in replaced the accumulator, hooked up nitrogen tank to the new accumulator and set the pressure to 100psi, top end of spec.

EHCOIL	EHC CHARGE	12	.05	.60
191830C2	GASKET	1	19.89	19.89
272344	O-RING	1	2.51	2.51
77400001US	ULTRACTION BULK	12	3.99	47.88
87746954	ACCUMULATOR	1 N	502.20	502.20
			PARTS	573.08
			LABOR	670.50
11008001		SEGMENT	TOTAL==>	1243.58

SEGMENT# 3 C 14029 NA

09/20/21 09/29/21

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees a town nax.
An express a town nax.
An express a town nax.
An express mechanic's Lien is admowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment until such a point as invoices have been paid.

• Stimates are for the tennes specifically identified in the estimate only, and are non-binding.

• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!





Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca



Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 306-842-2629 Weyburn

Ship To:

Invoice To:

		VVIII	utiloist	•	300-224-2110
Branch					
REGINA					
Date	Time				Page
10/25/21	22:	00:16	(B)		03
Account #	Phone #			Inv#	
Ship Via		Purchase	Order	#	
Tax ID #					
			Sales	sperso	n
				S76	
			•		

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

018084

3547

WARRANTY DATE

HRS

002724 COMBINE 1680

REPLACE HYDRO CABLE/ CUSTOMER SUPPLIED**USED**

COMPLAINT: -REPLACE HYDRO CABLE/ CUSTOMER SUPPLIED**USED**

CABLE IN CAB

CORRECTION:

Replaced the hydro cable with customer supplied used cable. Cable was slightly longer than the one I replaced. Had to do a lot of adjustments to get the cable to work. Hydro lever goes all the way forward but not all the way rearward. But you are able to stroke the hydro in full reverse. Newer cable thinner than the older one, filled grommet gaps with silicone.

130004	PIN, SPLIT (COT	1	.35	.35
199953C1	SCREW	3	3.92	11.76
86624096	PIN, SPLIT	1	2.44	2.44
87000226	P CLAMP	1	13.32	13.32
87365	WASHER	1	1.19	1.19
88788	PIN, SPLIT (COT	1	2.38	2.38
			PARTS	31.44
			LABOR	670.50
11008001		SEGMENT	TOTAL==>	701.94

SEGMENT# 4 C 14029 NA

09/20/21 09/21/21

DIAGNOSE HARD TO TURN RIGHT/ ADVISE CUSTOMER OF FINDINGS **COMPLAINT:**

-DIAGNOSE HARD TO TURN RIGHT/ ADVISE CUSTOMER OF FINDINGS **CORRECTION:**

Made up tee fitting to check pressure at both sides of steering cylinder. Checked pressure when it goes to a stop, 1340psi on both sides. Looked at schematics. Teed in flow

CONTINUED ON PAGE 04

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees a town nax.
An express a town nax.
An express a town nax.
An express mechanic's Lien is admowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment until such a point as invoices have been paid.

• Stimates are for the tennes specifically identified in the estimate only, and are non-binding.

• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!

Thank You!

We Appreciate Your Business

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.



Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca



Assiniboia 306-642-5991 Chamberlain 306-638-4516 306-567-3074 Davidson Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 306-842-2629 Weyburn 306-224-2110

Ship To:

Invoice To:

2110

SERVICE INVOICE

STK#/FLEET#

002724

COMBINE

HRS PIN/EIN 3547 018084

WARRANTY DATE

HRS

1680

meter and gauge right after header control valve going to the manual steering valve. At high RPM it is getting 4gpm to the steering hand pump. Closed the needle valve on the flowmeter and the secondary relief valve opened at 1450psi, the spec is 2000-2100psi. Plumbed in a flow meter right after the pump going to the header control valve. Checked flow at high RPM and it was 15gpm, closed needle valve until I was getting 2000psi backpressure and the pump was still putting out 15gpm. Pump is good. Teed in a gauge after the control valve going to the header lift cylinders. Raised feeder house all the way to the top and the primary relief valve opened up at 2350psi. Primary relief valve is good. Problem with the secondary relief valve. Washed off the block and removed the secondary relief valve. Replaced two o-rings and added a shim. Installed the relief valve. With gauge teed between the control valve and the steering pump I checked the pressure with needle valve closed, it was reading 1500psi. Removed secondary relief and installed another shim, only brought it up to 1550psi. I couldn't order the shim pack because it was back ordered. Found some copper washers and installed 2. That brought the relief pressure up to 2175psi, thought that was close enough. Teed in gauge at the steering cylinder again and read pressure, it was now 1450psi and it was still hard to steer. Still another problem in the system. Removed line from base end of steering cylinder and capped the line. Had someone steer to the right while I watched for leakage, no leakage in the steering cylinder. I suspect that we are getting excessive internal leakage in the steering hand pump. Went to get a price and availability and we can't order it through Case.

CONTINUED ON PAGE 05

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees a town nax.

An express a town nax.

An express a town nax.

An express mechanic's Lien is admowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment to reserves the right, at it so de discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Stianates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.



I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage is to the equipment, or its contents, whether due to collision, life, theft, or any other cause, except where such loss and/or damage is to the negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment I



Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca



Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 306-842-2629 Weyburn

Ship To:

Invoice To:

	TTITIO	ti loi st		300-224-2110
Time				Page
22:	00:16	(B)		05
Phone #			In∨ #	#
	Purchase (Order	#	
		Sales	sperso	n
			S76	
	22:	Time 22:00:16 Phone #	22:00:16 (B) Phone # Purchase Order Sale:	Time 22:00:16 (B)

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN WARRANTY DATE

HRS

002724

COMBINE 1680

3547 018084

Jacked up the backend and tried steering, only takes 230psi to turn off the ground, no seized steering components. Recommended to remove the steering hand pump and send it away to get matched up but customer denied repair. At this point the secondary relief pressure is resolved but the steering hand pump is at fault.

1301642C1	WASHER	2	39.51	79.02
167269	O-RING	1	1.60	1.60
9992298	O-RING	1	1.44	1.44
			PARTS	82.06
			LABOR	1788.00
11008001		SEGMENT	TOTAL==>	1870.06

SEGMENT# 5 C 14029 NA

09/20/21 09/23/21

DIAGNOSE ROTOR VIBRATION OVER 800 RPM/ ADVISE CUSTOMER COMPLAINT:

-DIAGNOSE ROTOR VIBRATION OVER 800 RPM/ ADVISE CUSTOMER CORRECTION:

Ran separator and confirmed the complaint. Could feel a shudder/vibration that would start at about 800rpm. Drove combine in the shop. Removed the concaves, the front half moon and the shield in front of the rotor bearing. Inspected the rotor, the rub bars and the front impellers. Couldn't see any broken pieces or missing bolts. The rotor is acting like its out of balance. After rotating the rotor it always stops at the same spot. Recommended getting the rotor balanced. Removed the rear grates and tied up the s-plate. Drove the combine out of the shop and blew out the rotor. Put all the shield, concaves and grates in a cage and set them outside. Myles helped out rotor balance guy to

CONTINUED ON PAGE 06

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees a town nax.

An express a town nax.

An express a town nax.

An express mechanic's Lien is admowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment to reserves the right, at it so de discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Stianates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Thank You! We Appreciate Your Business

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.



Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7 Phone: 306-565-2405 • Fax: 306-565-2420

www.youngs.ca

Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 Weyburn 306-842-2629 306-224-2110

Ship To:

Invoice To:

		William		000 22: 2110
Branch				
REGINA				
Date	Time			Page
10/25/21	22:	00:16 (В)	06
Account #	Phone #		Inv	#
Ship Via		Purchase C	order #	
Tax ID #				
			Salespers	son
			s76	5

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 002724 3547 018084 COMBINE

1680

weld on weights. After balancing, installed rear grates,

concaves and all shields.

SUBLET BALANCE ROTOR 1 1500.00 1500.00 PM TECH 281885 SEG 5 407211R1 #9 CLIP 1.84 3.68 7 86512168 8.75 SCREW 1.25 PARTS 12.43 1341.00 LABOR SUBLET 1500.00 11008001 SEGMENT TOTAL ==> 2853.43

SEGMENT# 6 C 14029 NA

09/20/21 09/22/21

REPAIR OIL PRESSURE GAUGE NOT WORKING/ CUSTOMER REPLACED SEN COMPLAINT:

-REPAIR OIL PRESSURE GAUGE NOT WORKING/ CUSTOMER REPLACED SENDING UNIT STILL NOT WORKING

CORRECTION:

Grounded wire going to the pressure switch, because I thought it was the engine oil pressure sensor. Grounding out wire to switch made the oil pressure light go on. After checking schematics and parts book I found out that this serial number breaks sensors is facing the front of the combine. Grounded out wire going to the sensor and it made the gauge go all the way to maximum. Hooked up an oil pressure gauge to the engine and measure the engine oil pressure. It was 48psi low idle and 65psi high idle. Pressure was holding steady. Removed pressure sensor and checked the continuity, it had no continuity, suspect that a switch was put in instead of a sensor. Ordered oil pressure sensor. Replaced the oil pressure sensor and ran

CONTINUED ON PAGE 07

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees a town nax.
An express a town nax.
An express a town nax.
An express mechanic's Lien is admowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment until such a point as invoices have been paid.

• Stimates are for the tennes specifically identified in the estimate only, and are non-binding.

• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!

Received By

Thank You! We Appreciate Your Business

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.



Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7 Phone: 306-565-2405 • Fax: 306-565-2420

www.youngs.ca

Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 306-694-1800 Moose Jaw 306-746-2288 Raymore Watrous 306-946-3387 306-842-2629 Weyburn Windthorst 306-224-2110

Ship To:





SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

002724 3547 018084 COMBINE

1680

the combine and the oil pressure gauge works well now.

1341330C2 SENDER 1 N 261.36

> PARTS 261.36 596.00 LABOR

261.36

11008001 857.36 SEGMENT TOTAL ==>

SEGMENT# 7 C 14029 NA

09/20/21 09/24/21

HYDRAULICS

COMPLAINT:

- -REMOVE INLINE FILTER/ CLEAN AND INSPECT
- -PUMP HAD OIL ON IT/ WASH OFF AND INSPECT FOR LEAK
- -CHANGE HYDRAULIC OIL AND FILTER

CORRECTION:

Changed oil and filter. Cleaned inline filter. Tightened

suction hoses then checked for leak when ran.

EHCFILT1	EVIRO	1	.50	.50
EHCOIL	EHC CHARGE	40	.05	2.00
528493R3	HYD FILTER	1	25.90	25.90
70923605	O-RING	1 N	20.98	20.98
77400001US	ULTRACTION BULK	40	3.99	159.60
			PARTS	208.98
			LABOR	298.00
11008001		SEGMENT '	TOTAL==>	506.98

SEGMENT# 8 C 14029 NA

09/20/21 09/24/21

ROTOR DRIVE

COMPLAINT:

REPLACE PINS / BUSHINGS/ THRUST BEARINGS

-REPLACE LIMIT SWITCHES IF INOPERABLE AND SET SPEEDS

CORRECTION:

CONTINUED ON PAGE 08

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

and/or in possession of the above-noted equipment.
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for artides left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment the reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Standars are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!

Thank You! We Appreciate Your Business



Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca



Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 306-842-2629 Weyburn

Ship To:

Invoice To:

	****	idti ioi st		300-224-2110
Time				Page
22:	00:16	(B)		08
Phone #			In∨ #	#
	Purchase	Order	#	<u>'</u>
		Sale	sperso	n
			S76	
	22:	Time 22:00:16 Phone #	Time 22:00:16 (B) Phone # Purchase Order Sale:	22:00:16 (B)

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN 3547 018084

WARRANTY DATE

HRS

002724 COMBINE

1680

On the quick inspection found that rotor drive pins and pins were very worn. Removed separator drive jackshaft assembly. Found that the inside drive pulley had worn the internal splines. Little bit of wear on the shaft but still think the shaft is ok. Ordered pulley after getting customers ok. Installed new pulley, replaced bushings on outside pulley and reinstalled. Replaced thrust bearings and reinstalled rotor drive assembly. Aligned rotor drive stationary pulleys, had to adjust the angle of the chopper gearbox. Replaced the rotor limit switches and set the low and high speeds. Had to adjust rotor gearbox draw bolt. Ran combine and double checked the speeds. 420rpm low and 1050rpm high.

128298A2	SWITCH LIMIT	2 43.60	87.20
193622C92	PULLEY ASSY.	1 N 1936.90	1936.90
217408	O-RING	2 5.58	11.16
278927A1	BEARING	2 128.36	256.72
87307839	BUSHING	3 18.53	55.59
		PARTS	2347.57
		LABOR	1341.00
11008001		SEGMENT TOTAL ==>	3688.57

SEGMENT# 9 C 14029 NA

09/20/21 10/02/21

INSTALL 1/2 INCH BOLT FOR RH CONCAVE SUPPORT WALL

COMPLAINT:

-INSTALL 1/2 INCH BOLT FOR RH CONCAVE SUPPORT WALL

CORRECTION:

Installd 1/2 inch bolt for the RH concave support wall.

86512371

.93 PARTS

.93 .93

CONTINUED ON PAGE 09



I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees a town nax.
An express a town nax.
An express a town nax.
An express mechanic's Lien is admowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment until such a point as invoices have been paid.

• Stimates are for the tennes specifically identified in the estimate only, and are non-binding.

• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.



Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 Weyburn 306-842-2629

Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca

Ship To:

Invoice To:

		WITIG	tiloist		300-224-2110
Branch					
REGINA					
Date	Time				Page
10/25/21	22:	00:16	(B)		09
Account #	Phone #			Inv #	ŧ
Ship Via		Purchase C	Order	#	
Tax ID #					
			Sales	perso	n
				S76	

SERVICE INVOICE

STK#/FLEET#

002724

COMBINE 1680

HRS PIN/EIN 3547 018084

09/20/21 09/24/21

WARRANTY DATE

HRS

LABOR 74.50

11008001

SEGMENT TOTAL ==>

75.43

SEGMENT#10 C 14029 NA

REPLACE A/C BELT

COMPLAINT:

-REPLACE A/C BELT

CORRECTION:

Replaced A/C belt.

When doing a final run after all the repairs the A/C compressor started squealing and smoking. Grabbed the shop's water extinguisher and cooled down the compressor. Performed the rest of the final checks with the A/C off. Got the ok from the customer to repair the A/C. Removed the compressor clutch, magnetic pick-up was very burnt and bearing was seized. Turned the compressor over with a set of pliers, would turn for a bit and then go to a dead stop, needs a new compressor and clutch. Ordered, clutch, compressor and the receiver drier. Recovered refrigerant from the system. Replaced the compressor and the compressor clutch. Filled new compressor with 400cc of oil. Removed the old compressor head to inspect system side of compressor to make sure contamination won't be an issue, doesn't look like issues in the system side. Replaced receiver drier. Vacuumed system, injected oil. Ran combine outside and checked pressures. 120psi high, 10psi low and vent temp was 39°F. Ambient temp was around 65°F.

128483A1 143405C91 1924008C2 O-RING CLUTCH ASY REMAN/COMP

2 4.20 1 275.10 1 N 794.23

8.40 275.10 794.23

CONTINUED ON PAGE 10

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees a town nax.
An express a town nax.
An express a town nax.
An express mechanic's Lien is admowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment until such a point as invoices have been paid.

• Stimates are for the tennes specifically identified in the estimate only, and are non-binding.


• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!





Phone: 306-565-2405 • Fax: 306-565-2420






Assiniboia 306-642-5991 Chamberlain 306-638-4516 306-567-3074 Davidson Moose Jaw 306-694-1800 306-746-2288 Raymore Watrous 306-946-3387 Weyburn 306-842-2629 Windthorst 306-224-2110

Ship To:





SERVICE INVOICE							
STK#/FLEET#		HRS	PIN/EIN	WARR	ANTY DATE	HRS	
002724	COMBINE	3547	018084				
	1680						
1924009C1		CORE-CC	MPRESSOR		34.75		34.75
1924009C1		CORE-CO	MPRESSOR	1-	34.75		34.75-
	on core rtn	984373					
1990758C2		REC/DRY	ER.	1	100.80		100.80
488016PX		PAG OII	J W/ DYE	14	2.26		31.64
75629		V-BELT		1	22.32		22.32
9827059		O-RING		2	2.23		4.46
					PARTS		1236.95
					LABOR		819.50
11008001				SEGMENT	TOTAL==>		2056.45
SEGMENT#11 (C 14029 NA	09/20/2	1 09/24/21				 -
REPLACE RAS	S BRUSH/ ADJUST RA	S SCREEN					
COMPLAINT:							
-REPLACE RA	AS BRUSH/ ADJUST R	AS SCREEN					
CORRECTION:	<u>:</u>						
Adjusted th	he RAS brush scree	n to sit i	n the center	ſ.			
Replaced th	he RAS brushes.						
164615C93		BRUSH,	COMMUTAT	1 N	361.80		361.80
194231C2		BRUSH,	COMMUTAT	1 N	94.18		94.18
					PARTS		455.98
					LABOR		298.00
11008001				SEGMENT	TOTAL==>		753.98

SEGMENT#12 C 14029 NA

09/20/21 09/24/21

REPLACE ALL 6 SPREADER BEARINGS

COMPLAINT:

-REPLACE ALL 6 SPREADER BEARINGS

CORRECTION:

Replaced all 6 spreader bearings.

CONTINUED ON PAGE 11

• I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at mry risk. Young's Equipment inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, life, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Inc. where the properties of the or any and all claims for loss and/or anage not caused by the negligence of Young's Equipment inc.

1 It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment inc. is working on, and/or in possession of the above-noted equipment.

• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptance to mat customer is in piace at an universement countries, any only and/or in possession of the above noted equipment.

• Young's Equipment inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

• An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment her reserves the right, at it is ode discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

• Stianates are for the items specifically identified in the estimate only, and are non-bindings, on any repairs incomed on equipment that has been modified.

• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs in pair.





Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7 Phone: 306-565-2405 • Fax: 306-565-2420

Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 306-694-1800 Moose Jaw 306-746-2288 Raymore Watrous 306-946-3387 Weyburn 306-842-2629 306-224-2110

www.youngs.ca

Ship To:



SEGMENT#14 C 14012 NA

RINSE OFF MUD

Branch					
REGINA					
Date	Time				Page
10/25/21	22:	00:16	(B)		11
Account #	Phone #			Inv #	ŧ
Ship Via		Purchase	Order :	#	
Tax ID #					
	·	·	Sales	perso	n
				S76	

SERVICE INVOICE STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 002724 3547 018084 COMBINE 1680 47508387 7 S 366.24 BEARING, BALL 52.32 571424R1 FLANGE 4 M 5.72 22.88 PARTS 389.12 640.70 LABOR 11008001 SEGMENT TOTAL ==> 1029.82 09/20/21 09/23/21 SEGMENT#13 C 14029 OC Young's Complimentary QuickCheck Inspection

***** WORK ORDER TOTALS ***** PARTS 6433.95 LABOR 10027.70 SUBLET 1500.00 shop supplies 200.00 SUB TOTAL ==> 18161.65 908.16 GST 5%

06743Z 19069.81 TOTAL CREDIT CARD

09/20/21

employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment the reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Standars are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.





I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

and/or in possession of the above-noted equipment.
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s