INSTRUCTIONS FOR CARE AND OPERATION OF WYSONG AND MILES NO. 410 COMBINATION SHEET METAL MACHINE

The machine has been adjusted and fully tested. Before using the machine, however, check the adjustments as they may have been disturbed in transit.

The machine should be firmly fastened to a solid and level floor. Shim between the floor and the base, if necessary, to level the machine.

Clean off all dirt that may have accumulated in transit. Clean off the compound that is on all finished surfaces as it is not a lubricant. Be sure that all oil holes are open and clean.

Check the direction of roll rotation. The rolls should operate so that the material moves from left to right as you face the ends of the roll shafts. The clutch will not function properly in the reverse direction.

LUBRICATION: The machine is provided with oil holes for proper lubrication which are obvious or stamped "OIL". Use light oil. The rear motor bearing is easily reached. To reach the front motor bearing, remove the plate from the rear of the machine. This plate also gives access to the gearing. All gear bearings are grease sealed and require no lubrication.

ADJUSTMENTS: The adjustments of this machine are easily made but very important. The lateral adjustment of the upper roll shaft is made by means of two hand wheels at the top of the machine; loosen one and tighten the other until the correct adjustment is made. Slitting cutters should be adjusted for a clearance of .002" for metal 16 to 24 gauge. For metal 26 gauge or lighter, the cutters should be adjusted with a clearance of .0015" to .0010". Be sure both hand wheel screws are tight before starting to operate. The spring on the top fastened by lock nuts elevates the upper roll. When using slitting cutters, the cutters should lap from .015" for 16 gauge to .005" for 30 gauge. The pivots on each side of the housing, held up by a lock nut, provide for the rocking motion of the upper shaft. These pivots should not need adjustment.


FOOT LEVERS OR TREADLES: The foot treadle controls the clutch, engaging and disengaging the driving mechanism. The second foot treadle when depressed lowers the upper roll into contact with the work.

CLUTCH: The clutch is controlled either by hand, by foot treadle or may be locked in the engaged position by means of two thumb screws on the shifter bracket.


OPERATION: Adjust the upper rolls by means of the crankscrew for the correct distance from the lower roll. If operating by the foot lever, greater distance may be given than if operating with the upper shaft maintained in the locked position. When operating with the upper shaft maintained in the locked position, be sure there is sufficient clearance between the rolls to accommodate the work. Insufficient clearance will spring the shaft.

Combination Sheet Metal Machine No. 410





Detail view showing No. 410
With Flanging Attachment




Detail view showing No. 410 With Circle Cutting Attachment

A MULTI-PURPOSE MACHINE-A NECESSITY IN ANY SHEET METAL SHOP

COMBINATION SHEET METAL MACHINE No. 410

DIAGRAM OF PARTS

LIST OF PARTS



•	LIST U	FPAI	NIS CLI
6D-S2	Lower Spindle	6D-S50	Foot Treadle
6D-S3	Top Spindle	6D-S51	Clutch Shoe
6D-S4	Stud	6D-S52	Gear
6D-S5	Stud	6D-S53	Thimble
6D-S6	Adjusting Screw	6D-S54	Clutch Hand Rod
6D-S7	Clutch	6D-S55	Clutch Yoke Stud
6D-S8	Clutch Plate	6D-S56	Pin for 6D-24
6D-S9	Stud	6D-S57	Spacing Collar
6D-S10	Collar for 6D-S2	6D-S58	Spacing Collar
6D-S11	Stud for 6D-8	6D-S59	Spacing Collar
6D-S12	Gear for Motor	6D-S60	Cover for Bearing
6D-S13	Gear	6D-S61	Upper Spindle Nut
6D-S14	Gear Stud	6D-S62	Lower Spindle Nut
6D-S15	Clutch Rod	6D-S63	Spacing Collar
6D-S16	Connecting Rod	6D-S64	Spacing Collar
6D-S17	Spring Stud	6D-S65	Sleeve Rack
6D-S18	Lug for Spring Stud	6D-S66	Spring for Raising Upper Spindle
6D-S19	Pin for 6D-5	6D-S67	Clutch Spring
6D-S20	Spring Stud for Clutch Spring	6D-S68	Spring for Clamping Disc
6D-S21	Support Arm	6D-S69	Top Spindle Adjusting Screw
6D-S22	Stud for Clamping Disc	6D-S70	Wrench
6D-S23	Collar for Stud	6D-S71	Switch
6D-S24	Upper Clamping Disc	6D-S72	Switch Cover
6D-S25	Centering Pin	6D-S73	Ball Bearing
6D-S26	Lower Clamping Disc	6D-S74	Cone Point Set Screw
6D-S27	Link	6D-2	Bearing Housing
6D-S29	Locking Stud	6D-3	Bracket for Motor and Bearings
6D-S30	Stud for 6D-14	6D-4	Cap for Bearings
6D-S31	Support Rod for 6D-15	6D-5	Top Spindle Housing
6D-S32	Crimping Roll	6D-6	Clutch Yoke
6D-S33	Ogee Lower Beading Roll	6D-7	Lever
6D-S34	Ogee Upper Beading Roll	6D-8	Clutch Rocker Arm
6D-S35	Single Bead Lower Roll	6D-9	Turnbuckle
6D-S36	Single Bead Upper Roll	6D-10	Gear
6D-S37	Slitting Cutter	6D-11	Gear
6D-S38	Lower Burring Roll	6D-14	Bracket for Flanging Attachment
6D-S39	Upper Burring Roll	6D-15	Frame for Flanging Attachment
6D-S40	Lower Elbow Edging Roll	6D-16	Yoke for Flanging Attachment
6D-S41	Upper Elbow Edging Roll	6D-17	Clamping Lug
6D-S42	Lower Turning Roll	6D-18	Clamping Link
6D-S43	Upper Turning Roll	6D-19	Clamp Handle
6D-S44	Gage	6D-20	Base for Support Arm
6D-S45	Gage	6D-21	Clamp Base Frame for Circle
6D-S46	Gage	6D-22	
6D-S47	Gage	6D-23	Cutting Attachment Crank Handle
6D-S48	Gage	6D-23 6D-24	Bracket for Top Spindle Housing
6D-S49	Foot Treadle	UD-24	Dracket for Top Spinite Housing

COMBINATION METAL MACHINE No. 410

SPECIFICATIONS

A rugged, well proportioned and versatile machine for burring, turning, wiring, beading, crimping, elbow edging, slitting and other operations.

The interchangeable rolls are power driven, thus enabling the operator to use both hands for manipulation of the work. A clutch, operated either by hand or foot, controls rotation of the rolls. Clutch can be locked when continuous motion is desired.

Motor, clutch and gears are enclosed in frame of machine, which assures protection from dirt and scale, etc.

The machine is a self-contained unit, notable for ease of operation and adjustment. The frame is a nicely finished and accurately machined semi-steel casting—base heavy gage steel—no excess weight but sufficient to provide necessary rigidity.

The drive is by motor through machine cut gears. Bronze bearings for roll shafts. Clutch is of the cup type. It is quick acting and very positive. It can be operated by either hand or foot.

The motor starting switch is mounted on frame of machine within easy reach of operator and it has overload protection.

Convenience and ease of adjustments. The upper shaft can be raised and lowered by means of either foot treadle or crank screw and the crank screw serves as stop for shaft and roll when foot treadle is used. Lateral adjustment of upper shaft is controlled by screws located on top of frame.

Proper relationship of upper shaft to bearings is maintained by movement of rocking box.

Circle attachment consists of a horn and a circle arm.

Flanging attachment. A swinging yoke carried by the horn holds the circles. Desired angle is obtained by tilting the yoke.

Motor—1/4 H.P., 110 volt, 60 cycle, single phase or 220/440 volt, 3 phase.
Capacity, mild steel with standard burring, turning, wiring and beading rolls 18 gage
Capacity, mild steel with standard crimping rolls
Capacity, mild steel with standard slitting cutters
With circle attachments will cut 16 gage circles dia. 4½" to 22".
With flanging attachment will flange 18 gage circles dia. 4" to 30".
Diameter of shafts in front bearings
Distance between shaft centers
Distance center of rolls to gage
Distance center of rolls to frame
Length of shaft ends for rolls
Diameter of horn at frame
Diameter of horn at end $2\frac{1}{8}$ "
Peripheral speed of rolls with 60-cycle motor
Floor space, F to B x R to L x H
Shipping weight, (domestic)

Wysong and Miles 100% jig and fixture construction is your guarantee of uniformly superior machines.



GREENSBORO, NORTH CAROLINA

DESIGNERS AND BUILDERS OF MACHINERY SINCE 1900