



Lubricant Analysis Report

North America: +1-866-341-0487



Overall report severity based on comments.

Acco	unt Information	Component Information	Sample Information
ccount Number:	LUB307-0037-0000	Component ID: 8952 E	Tracking Number: 24190V03942
Company Name:	PIDHERNEY'S	Secondary ID: 1T0331FKCMF390863	Lab Number: E-016207
Contact:	CARLA MERKLIN	Component Type: DIESEL ENGINE	Lab Location: Edmonton
Address:	RANGE RD 70 PO BOX 940	Manufacturer: YANMAR	Data Analyst: KDN
	ROCKY MOUNTAIN HOUSE,	Model: 4TNV94-FHT	Sampled: 23-Jun-2025
	AB T4T 1A7 CA	Application: CONSTRUCTION	Submitted: 25-Jun-2025
Phone Number:	403-845-3072	Sump Capacity:	Received: 26-Jun-2025
			Completed: 27-Jun-2025
Filte	r Information	Miscellaneous Information	Product Information
Filter Type: Micron Rating:	Information Requested 0	Wildcard 1: Your Rep.: Cary Maxwell Wildcard 2: Ph:(403) 861-9957 Wildcard 3: _	Product Manufacturer: CHEVRON Product Name: DELO 400 XSP Viscosity Grade: SAE 5W40

all	710 110 4			We	ar Mei	tals (p	pm)					ntamir tals (p		N	Лulti-Տ	ource	Metals	s (ppm	1)	А	dditiv	e Meta	ls (ppn	n)
ımple #	on	romium	ickel	uminum	opper	ad		admium	ver	ınadium	icon	ndium	tassium	tanium	olybdenum	ıtimony	anganese	hium	ıron	agnesium	ılcium	ırium	osphorus	

BL 775 1323

			Sampl	e Inforr	nation		i vitte			Contaminants			1-07/1-10	luid Pr	opertie	S	
ple #	Sampled		Received	Lube Time	Unit Time	Change	Lube Added	Change	Fuel Dilution	Soot	Water	Viscosity 40°C	Viscosity 100 °C	Acid Number	Base Num. ASTM4739	Oxidation	Nitration
Sam	Date		Date	_ h	h	Lube	L	Filter	%	%	%	cSt	cSt	mg KOH/g	mg KOH / g	abs / cm	abs / 0.1mm
BL	01-Jan-2023	18	-Sep-2023	0	0	Unk	0	Unk			<.1 - FTIR		15.3		6.21	10	7
5	03-Jun-2023	15	-Jun-2023	0	1229	No	0	No	<2 - Estimate	0.1 - E2412	<.1 - FTIR		15.1		2.72	18	13
6	04-Sep-2023	07	-Sep-2023	470	1441	Yes	0	Yes	<2 - Estimate	0.3 - E2412	<.1 - FTIR		15.0		2.08	19	12
7	17-Aug-2024	22	-Aug-2024	289	1730	No	0	No	<2 - Estimate	<.1	<.1 - FTIR		13.9	3.32		12	8
8	26-Mar-2025	10	-Apr-2025	474	1915	Yes	0	Yes	5.6 - GC	0.3 - E2412	<.1 - FTIR		12.3	3.63		14	11
9	23-Jun-2025	26	-Jun-2025	253	2168	No	0	No	<2 - Estimate	0.3 - E2412	<.1 - FTIR		14.0	4.77		15	11

										The state of the s	,	r age 2
	STATE OF	Litary 1		Parti	cle Coun	t (particle	es/mL)				Additional Testing	
Sample #	Based On 4/6/14	4 ^ particles mL	o ^ /particles / mL	01 ^ /particles / mL	mL v barticles	/particles mL	&	02 ^ /particles mL	00 ^ /particles / mL	Test Method		
BL	11				500							
5	11											
6	11											
7	11											
8	11											
9	11											

Comments are advisory only and are based on the sample information provided by the customer being valid. Results related only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.


Historical Comments

Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Base Number is MODERATELY LOW. As Base Number depletes, the ability to neutralize acids is diminished. LUBRICANT TIME was not provided for this sample. Please provide this units sump capacity with next sample.

Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Base Number is MODERATELY LOW. As Base Number depletes, the ability to neutralize acids is diminished. Iron is at a MINOR LEVEL. IRON SOURCES in engines can be cylinder liners, iron pistons, hardened steel camshafts, crankshafts, gears, hardened rocker arms, valve bridges, alloyed steel cam follower rollers, etc. Please provide this units sump capacity with next sample. Lubricant and filter change acknowledged.

Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Flagged additive levels are higher than expected for the identified lubricant. This may have been topped off with a different lubricant, the fluid may be misidentified, or a different lubricant or formulation may have been in use prior to a recent change.


Check for source of FUEL LEAK. Fuel is at a SIGNIFICANT LEVEL. Fuel dilution may be caused by component faults related to injectors, ignition/timing or excessive blow-by. Additional causes include heavy throttle application, engine lugging, frequent short trips, and excessive idling. Iron is at a MINOR LEVEL. IRON SOURCES in engines can be cylinder liners, iron pistons, hardened steel camshafts, crankshafts, gears, hardened rocker arms, valve bridges, alloyed steel cam follower rollers, etc. FUEL DILUTION has caused viscosity to decrease slightly below grade; FUEL DILUTION reduces the viscosity of the lubricant which decreases FILM STRENGTH and LUBRICITY and may lead to increased wear. Flagged additive levels are different than what should be present for the identified lubricant. This may have been topped off with a different lubricant, the fluid may be misidentified, or a different lubricant or formulation may have been in use prior to a recent change. Lubricant and filter change acknowledged. Resample at half interval.





Lubricant Analysis Report

North America: +1-866-341-0487



Overall report severity based on comments.

Account Information	Component Information	Sample Information
Account Number: LUB307-0037-0000 Company Name: PIDHERNEY'S	Component ID: 8952 H Secondary ID: 1T0331FKCMF390863	Tracking Number: 24256T68961 Lab Number: E-003069
Contact: CARLA MERKLIN Address: RANGE RD 70 PO BOX 940 ROCKY MOUNTAIN HOUSE, AB T4T 1A7 CA Phone Number: 403-845-3072	Component Type: HYDRAULIC Manufacturer: JOHN DEERE Model: 331G Application: CONSTRUCTION Sump Capacity:	Lab Location: Edmonton Data Analyst: MAC Sampled: 26-Mar-2025 Submitted: 09-Apr-2025 Received: 10-Apr-2025 Completed: 11-Apr-2025
Filter Information	Miscellaneous Information	Product Information
Filter Type: Information Requested Micron Rating: 0	Wildcard 1: Your Rep.: Cary Maxwell Wildcard 2: Ph:(403) 861-9957	Product Manufacturer: CHEVRON Product Name: RANDO HDZ Viscosity Grade: ISO 46

Comments

Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Acid Number is MODERATELY HIGH, which may be due to oxidation, contamination with an acidic product, extended drain interval, or lubricant mixing. Iron is at a MINOR LEVEL. IRON in hydraulic systems could possibly be pistons/rods (if piston pump), gears or bearings (if gear pump), or fluid conductors such as piping, tubing or steel fittings; Infrared results indicate beginning lube oxidation; Viscosity is SLIGHTLY LOW. Causes include contamination, incorrectly identified viscosity grade, or adding a different viscosity grade to the component. Flagged additive levels are different than what should be present for the identified lubricant. This may have been topped off with a different lubricant, the fluid may be misidentified, or a different lubricant or formulation may have been in use prior to a recent change. LUBRICANT TIME was not provided for this sample.

				We	ar Mei	als (pr	om)					tamir tals (p		N	/ulti-S	ource	Metal	s (ppm	1)	Д	dditive	Meta	ls (ppn	n)
Sample #	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
BL	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	56	0	399	505
1	7	0	0	0	4	1	0	0	0	0	4	2	2	0	0	0	0	0	9	62	187	0	548	821
2	18	0	0	2	6	1	0	0	0	0	7	2	3	0	3	0	1	0	25	144	351	0	600	816
3	27	1	0	3	9	1	0	0	0	0	10	3	3	0	5	0	1	0	36	204	461	0	642	784
4	33	2	0	4	8	0	0	0	0	0	13	3	3	0	7	0	1	0	36	205	559	0	602	771

100		Sample	e Inforr	nation					Contaminants				Fluid Pr	operties	5	
nple #	e Sampled	ate Received	Lube Time	Unit Time	e Change	Lube Added	er Change	Fuel Dilution	Soot	Water	Viscosity 40°C	Viscosity 100°C	a Acid Number	Base Num. ASTM4739	oxidation	vsd Nitration
Sar	Dat	Dat	h	h	Lube	L	Filte	%	96	%	cSt	cSt	_	KOH/g	Wiley Williams	0.1mm
BL	10-May-2023	15-May-2023	0	0	Unk	0	Unk			<.1 - FTIR	47.8		0.52		16	2
1	04-Feb-2022	25-Feb-2022	440	440	No	0	No			<.1 - FTIR		9.9	1.23		37	4
2	21-Jan-2023	10-Feb-2023	971	971	No	0	No			<.1 - FTIR	44.8		1.06		31	4
3	04-Sep-2023	07-Sep-2023	1441	1441	No	0	No			<.1 - FTIR	42.1		0.86		25	4
4	26-Mar-2025	10-Apr-2025	0	1915	No	0	Yes			<.1 - FTIR	41,3		1.00		24	4

,05005		055211						,, 005,		115/12/1/12/15
100	Name of	Tall res	Parti	cle Coun	t (particle	s/mL)		- Even		Additional Testing
O C S Based On 4/6/14	particles 7	φ ^ /particles mL	0 ^ /particles / mL	mL v 4t	/particles /	∞ m ^ /particles / mL	02 ^ particles mL	00 /particles / mL	Test Method	
. 11						Evel				
11										
11										
11										
11										
	Based On 4/6/14	Based On particles 4/6/14 mL	Based On particles / particles / ML	Particles / partic	Particle Count Particle Count	Particle Count (particles of particles / p	Particle Count (particles/mL) Particle Count (particles/mL)	Particle Count (particles/mL) Particle Count (particles/mL)	Particle Count (particles/mL) **Example Count (particles/mL) **E	Particle Count (particles/mL) Population of the properties of the particles of the particl


Comments are advisory only and are based on the sample information provided by the customer being valid. Results related only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.

Historical Comments

Maintenance action indicated at time of submission (fluid/filter change, filtration, etc.) will have corrected the issue this system is exhibiting. No further maintenance action is recommended at this time. Infrared results indicate OXIDATION is SEVERELY HIGH; V scosity is SIGNIFICANTLY LOW. Causes include contamination, incorrectly identified viscosity grade, or adding a different viscosity grade to the component. Increased component wear possible. If grade is misidentified, it can be updated in HORIZON. Flagged additive levels are different than what should be present for the identified lubricant. This may have been topped off with a different lubricant, the fluid may be misidentified, or a different lubricant or formulation may have been in use prior to a recent change. Is the FLUID MANUFACTURER, PRODUCT NAME and/or VISCOSITY GRADE correctly identified? Please provide this units sump capacity with next sample.

Suggest sweetening sump by adding fresh lubricant. Please contact your lubricant supplier for recommendations. Infrared results indicate OXIDATION is SEVERELY HIGH; Acid Number is MODERATELY HIGH, which may be due to oxidation, contamination with an acidic product, extended drain interval, or lubricant mixing. Flagged additives do not match current baseline reference for the specified product (this does not imply the lubricant does not meet proper API, SAE, or ISO classifications). Resample at half interval.

Suggest sweetening sump by adding fresh lubricant. Please contact your lubricant supplier for recommendations. Infrared results indicate OXIDATION is SEVERELY HIGH; Acid Number is SLIGHTLY HIGH, which may be due to oxidation, contamination with an acidic product, extended drain interval, or lubricant mixing. Flagged additives do not match current baseline reference for the specified product (this does not imply the lubricant does not meet proper API, SAE, or ISO classifications). Please provide this units sump capacity with next sample. Resample at half interval.






3 0

Lubricant Analysis Report

North America: +1-866-341-0487



Overall report severity based on comments.

Accou	int Information	Component Information	Sample Information
Account Number:	LUB307-0037-0000	Component ID: 8952 LFD	Tracking Number: 23045U94300
Company Name:	PIDHERNEY'S	Secondary ID: 1T0331FKCMF390863	Lab Number: E-912891
Contact:	CARLA MERKLIN	Component Type: FINAL DRIVE	Lab Location: Edmonton
Address:	RANGE RD 70 PO BOX 940	Manufacturer: JOHN DEERE	Data Analyst: ARF
	ROCKY MOUNTAIN HOUSE,	Model: 331G	Sampled: 04-Sep-2023
	AB T4T 1A7 CA	Application: CONSTRUCTION	Submitted: 05-Sep-2023
Phone Number:	403-845-3072	Sump Capacity:	Received: 07-Sep-2023
			Completed: 07-Sep-2023
Filte	r Information	Miscellaneous Information	Product Information
Filter Type: Micron Rating:	Information Requested 0	Wildcard 1: Your Rep.: Cary Maxwell Wildcard 2: Ph:(403) 861-9957	Product Manufacturer: CHEVRON Product Name: MULTIGEAR EP-5 Viscosity Grade: SAE 80W90

change acknowledged. Contaminant Wear Metals (ppm) Metals (ppm) Multi-Source Metals (ppm) Additive Metals (ppm) Molybdenum Phosphorus Manganese Magnesium Aluminum Vanadium Potassium Sample # Cadmium Antimony Titanium Calcium Sodium Lithium Copper Barium Silicon Silver Lead Zinc BL

48			Sample	e Inforr	mation		1111		Symposium (Williams)	Contaminants				Fluid Pr	operties	5	
Sample #	Date Sampled		Date Received	ح Lube Time	ع Unit Time	Lube Change	Lube Added	Filter Change	Fuel Dilution	Soot	% Water	Viscosity 40°C	Viscosity م 100°C	HON Acid	Base Num.	a sq Oxidation	m Nitration
BL	N/A	18	-Sep-2017	0	0	Unk	0	Unk			<.1 - FTIR		14.1	1.59		3	2
1	04-Feb-2022	25	-Feb-2022	440	440	Yes	0	No			<.1 - FTIR		13.7	2.11		4	3
2	21-Jan-2023	10	-Feb-2023	1	971	Yes	0	No			<.1 - FTIR		14.3	1.72		4	3
3	04-Sep-2023	07	Sep-2023	470	1441	Yes	0	No			<.1 - FTIR		13.8	1.88		3	3

Additional Testing


600 1

				Partio	le Count	(particle	s/mL)	W.O.		
Sample #	OQ Coque Based On 4/6/14	particles mL	φ ^ /particles / mL	0 A particles / mL	A barticles /	72 ^ particles / mL	& M M ^ particles / mL	OZ ^ particles / mL	00 A particles / mL	Test Method
BL	11									
1	11									
2	11									
3	11									

Comments are advisory only and are based on the sample information provided by the customer being valid. Results related only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.

E-912891 8952 LFD LUB307-0037-0000 PIDHERNEY'S Historical Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment Comments

and fluid conditions. Acid Number is SLIGHTLY HIGH, which may be due to oxidation, contamination with an acidic product, extended drain interval, or lubricant mixing. Boron is slightly low for this lubricant. Boron levels may naturally decline with use so this is not a cause for concern. Lubricant change acknowledged. 2 Data indicates no abnormal findings. Resample at normal interval. Lubricant change acknowledged.





Lubricant Analysis Report

North America: +1-866-341-0487



Overall report severity based on comments.

Additional Testing

Account Information	Component Information	Sample Information
Account Number: LUB307-0037-0000	Component ID: 8952 RFD	Tracking Number: 23045U94301
Company Name: PIDHERNEY'S	Secondary ID: 1T0331FKCMF390863	Lab Number: E-912892
Contact: CARLA MERKLIN	Component Type: FINAL DRIVE	Lab Location: Edmonton
Address: RANGE RD 70 PO BOX 940	Manufacturer: JOHN DEERE	Data Analyst: ARF
ROCKY MOUNTAIN HOUSE,	Model: 331G	Sampled: 04-Sep-2023
AB T4T 1A7 CA Phone Number: 403-845-3072	Application: CONSTRUCTION Sump Capacity:	Submitted: 05-Sep-2023 Received: 07-Sep-2023 Completed: 07-Sep-2023
Filter Information	Miscellaneous Information	Product Information
Filter Type: Information Requested Micron Rating: 0	Wildcard 1: Your Rep.: Cary Maxwell Wildcard 2: Ph:(403) 861-9957	Product Manufacturer: CHEVRON Product Name: MULTIGEAR EP-5 Viscosity Grade: SAE 80W90

	Wear Metals (ppm)								Contaminant Metals (ppm)			Multi-Source Metals (ppm)					Additive Metals (ppm)							
Sample #	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
BL	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	133	1	2	0	775	3
1	0	0	0	0	0	0	0	0	0	0	1	0	2	0	0	0	0	0	3	0	12	0	557	3
2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	2	0	627	3
3	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	602	0

		Sample	e Inforr	mation	N GEO			Contaminants				Fluid Properties					
Sample #	Date Sampled	Date Received	ح Lube Time	ə Unit Time	Lube Change	Lube Added	Filter Change	Fuel Dilution	800t	% Water	Niscosity 40°C	Viscosity 100°C	HON Acid	Base Num.	a g Oxidation	waterion / sate	
BL	N/A	18-Sep-2017	0	0	Unk	0	Unk	- EART		<.1 - FTIR		14.1	1.59		3	2	
1	20-Feb-2022	25-Feb-2022	440	440	Yes	0	No			<.1 - FTIR		13.7	2.06		4	3	
2	21-Jan-2023	10-Feb-2023	1	971	Yes	0	No			<.1 - FTIR		14.2	1.71		4	3	
3	04-Sep-2023	07-Sep-2023	470	1441	Yes	0	No			<.1 - FTIR		13.9	1.40		3	3	

	Particle Count (particles/mL)													
Sample #	opo OSI Based On 4/6/14	7 A particles a mL	o ^ /particles / mL	Ot ^ particles / mL	mL A particles /	particles / mL	& & & & & & & & & & & & & & & & & & &	02 ^ 'particles / mL	00 ^ 'particles / mL	Test Method				
BL	11	ACCEPTED IN		Linen				12 555						
1	11													
2	11													
3	11													

Comments are advisory only and are based on the sample information provided by the customer being valid. Results related only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.

2 Data indicates no abnormal findings. Resample at normal interval. Lubricant change acknowledged.

