

208-16
BLUE-MAR



Lubricant Analysis Report

North America: +1-866-341-0487

| | | | | |
|--------|---|----------|---|----------|
| 0 | 1 | 2 | 3 | 4 |
| NORMAL | | ABNORMAL | | CRITICAL |

Overall report severity based on comments.

| Account Information | | Component Information | | Sample Information | |
|--|--|---|--|--|--|
| Account Number: LUB307-0037-0000 Company Name: PIDHERNEY'S Contact: CARLA MERKLIN Address: RANGE RD 70 PO BOX 940 ROCKY MOUNTAIN HOUSE, AB T4T 1A7 CA Phone Number: 403-845-3072 | | Component ID: 8980 H Secondary ID: 1T0333GKJRF457348 Component Type: HYDRAULIC Manufacturer: JOHN DEERE Model: 333G Application: CONSTRUCTION Sump Capacity: | | Tracking Number: 25062Y44243 Lab Number: E-045887 Lab Location: Edmonton Data Analyst: FLG Sampled: 05-Dec-2025 Submitted: 17-Dec-2025 Received: 18-Dec-2025 Completed: 19-Dec-2025 | |
| Filter Information | | Miscellaneous Information | | Product Information | |
| Filter Type: Information Requested Micron Rating: 0 | | Wildcard 1: Your Rep.: Cary Maxwell Wildcard 2: Ph:(403) 861-9957 | | Product Manufacturer: CHEVRON Product Name: RANDO HDZ Viscosity Grade: ISO 46 | |
| Comments | | LUBRICANT CHANGE is suggested if not done at sampling time. OXIDATION is at a SIGNIFICANT level. Drain interval may be over-extended, or unit may be running too hot. Viscosity is SLIGHTLY LOW. Causes include contamination, incorrectly identified viscosity grade, or adding a different viscosity grade to the component. Flagged additives do not match current baseline reference for the specified product (this does not imply the lubricant does not meet proper API, SAE, or ISO classifications). Please provide this units sump capacity with next sample. Filter change acknowledged. | | | |











| Sample # | Wear Metals (ppm) | | | | | | | | | | Contaminant Metals (ppm) | | | Multi-Source Metals (ppm) | | | | | Additive Metals (ppm) | | | | | |
|----------|-------------------|----------|--------|----------|--------|------|-----|---------|--------|----------|--------------------------|--------|-----------|---------------------------|------------|----------|-----------|---------|-----------------------|-----------|---------|--------|------------|------|
| | Iron | Chromium | Nickel | Aluminum | Copper | Lead | Tin | Cadmium | Silver | Vanadium | Silicon | Sodium | Potassium | Titanium | Molybdenum | Antimony | Manganese | Lithium | Boron | Magnesium | Calcium | Barium | Phosphorus | Zinc |
| BL | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 56 | 0 | 399 | 505 |
| 1 | 2 | 0 | 0 | 1 | 2 | 2 | 0 | 0 | 0 | 0 | 3 | 1 | 0 | 0 | 2 | 0 | 0 | 0 | 6 | 34 | 163 | 0 | 597 | 971 |
| 2 | 8 | 0 | 0 | 0 | 4 | 1 | 0 | 0 | 0 | 0 | 3 | 2 | 0 | 0 | 3 | 0 | 0 | 0 | 12 | 31 | 151 | 0 | 573 | 805 |

| Sample # | Sample Information | | | | | | | Contaminants | | | Fluid Properties | | | | | | |
|----------|--------------------|---------------|-----------|-----------|-------------|------------|---------------|---------------|------|-------|------------------|------------------|-------------|--------------------|-----------|-------------|---|
| | Date Sampled | Date Received | Lube Time | Unit Time | Lube Change | Lube Added | Filter Change | Fuel Dilution | Soot | Water | Viscosity 40°C | Viscosity 100 °C | Acid Number | Base Num. ASTM4739 | Oxidation | Nitration | |
| | | | h | h | | L | | % | % | % | cSt | cSt | mg KOH / g | mg KOH / g | abs / cm | abs / 0.1mm | |
| BL | 10-May-2023 | 15-May-2023 | 0 | 0 | Unk | 0 | Unk | | | | <.1 - FTIR | 47.8 | | 0.52 | | 16 | 2 |
| 1 | 31-Jan-2025 | 21-Feb-2025 | 0 | 496 | No | 0 | No | | | | <.1 - FTIR | 44.2 | | 0.91 | | 40 | 3 |
| 2 | 05-Dec-2025 | 18-Dec-2025 | 1105 | 1105 | No | 0 | Yes | | | | <.1 - FTIR | 40.3 | | 0.92 | | 33 | 2 |

| Sample # | Particle Count (particles/mL) | | | | | | | | | | Test Method | Additional Testing | |
|----------|-------------------------------|----------------|----------------|----------------|----------------|----------------|----------------|----------------|----------------|----------------|-------------|--------------------|--|
| | ISO Code | > 4 | > 6 | > 10 | > 14 | > 21 | > 38 | > 70 | > 100 | | | | |
| | Based On 4/6/14 | particles / mL | | | |
| BL | / / | | | | | | | | | | | | |
| 1 | / / | | | | | | | | | | | | |
| 2 | / / | | | | | | | | | | | | |

Comments are advisory only and are based on the sample information provided by the customer being valid. Results related only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.

| | | |
|------------------------|---|--|
| Historical Comments | 1 | Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Acid Number is SLIGHTLY HIGH, which may be due to oxidation, contamination with an acidic product, extended drain interval, or lubricant mixing. Infrared results indicate beginning lube oxidation; Flagged additive levels are higher than expected for the identified lubricant. This may have been topped off with a different lubricant, the fluid may be misidentified, or a different lubricant or formulation may have been in use prior to a recent change. LUBRICANT TIME was not provided for this sample. |
|------------------------|---|--|





| | | | | |
|--------|---|----------|----------|---|
| 0 | 1 | 2 | 3 | 4 |
| NORMAL | | ABNORMAL | CRITICAL | |

Overall report severity based on comments.

| Account Information | | Component Information | | Sample Information | |
|--|--|--|--|--|--|
| Account Number: LUB307-0037-0000 Company Name: PIDHERNEY'S Contact: CARLA MERKLIN Address: RANGE RD 70 PO BOX 940 ROCKY MOUNTAIN HOUSE, AB T4T 1A7 CA Phone Number: 403-845-3072 | | Component ID: 8980 E Secondary ID: 1T0333GKJRF457348 Component Type: DIESEL ENGINE Manufacturer: YANMAR Model: 4TNV94-FHT Application: CONSTRUCTION Sump Capacity: | | Tracking Number: 25062Y44287 Lab Number: E-045913 Lab Location: Edmonton Data Analyst: FLG Sampled: 05-Dec-2025 Submitted: 17-Dec-2025 Received: 18-Dec-2025 Completed: 19-Dec-2025 | |
| Filter Information | | Miscellaneous Information | | Product Information | |
| Filter Type: Information Requested Micron Rating: 0 | | Wildcard 1: Your Rep.: Cary Maxwell Wildcard 2: Ph:(403) 861-9957 Wildcard 3: _ | | Product Manufacturer: CHEVRON Product Name: DELO 400 XSP Viscosity Grade: SAE 5W40 | |
| Comments | Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Copper is at a MODERATE LEVEL; COPPER is most likely LEACHING into the oil via the OIL COOLER core tubing. This typically DOES NOT REQUIRE MAINTENANCE ACTION unless there is evidence of COOLANT in the oil. Iron is at a MINOR LEVEL. IRON SOURCES in engines can be cylinder liners, iron pistons, hardened steel camshafts, crankshafts, gears, hardened rocker arms, valve bridges, alloyed steel cam follower rollers, etc. Silicon is at a MINOR LEVEL; SILICON sources can be abrasives (dirt, Alumina Silica), seals and gasket material, lube additive or lube supplement, and/or environmental contaminant; Flagged additives do not match current baseline reference for the specified product (this does not imply the lubricant does not meet proper API, SAE, or ISO classifications). Please provide this units sump capacity with next sample. Lubricant and filter change acknowledged. | | | | |

| Sample # | Wear Metals (ppm) | | | | | | | | | | Contaminant Metals (ppm) | | | Multi-Source Metals (ppm) | | | | | Additive Metals (ppm) | | | | | |
|----------|-------------------|----------|--------|----------|--------|------|-----|---------|--------|----------|--------------------------|--------|-----------|---------------------------|------------|----------|-----------|---------|-----------------------|-----------|---------|--------|------------|------|
| | Iron | Chromium | Nickel | Aluminum | Copper | Lead | Tin | Cadmium | Silver | Vanadium | Silicon | Sodium | Potassium | Titanium | Molybdenum | Antimony | Manganese | Lithium | Boron | Magnesium | Calcium | Barium | Phosphorus | Zinc |
| BL | 3 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 6 | 3 | 3 | 1 | 0 | 0 | 0 | 1 | 98 | 775 | 1323 | 0 | 768 | 869 |
| 1 | 24 | 1 | 0 | 3 | 142 | 1 | 1 | 0 | 2 | 0 | 48 | 9 | 0 | 0 | 210 | 0 | 2 | 0 | 191 | 648 | 1698 | 3 | 888 | 1033 |
| 2 | 36 | 1 | 0 | 4 | 364 | 2 | 1 | 0 | 1 | 0 | 48 | 9 | 1 | 0 | 215 | 0 | 2 | 0 | 158 | 741 | 1867 | 3 | 880 | 1105 |
| 3 | 19 | 0 | 0 | 2 | 161 | 1 | 0 | 0 | 1 | 0 | 17 | 4 | 2 | 0 | 57 | 0 | 1 | 0 | 93 | 742 | 1515 | 1 | 780 | 909 |
| 4 | 50 | 1 | 0 | 4 | 167 | 1 | 0 | 0 | 0 | 0 | 20 | 5 | 3 | 0 | 59 | 0 | 1 | 0 | 48 | 778 | 1509 | 1 | 780 | 906 |

| Sample # | Sample Information | | | | | | | | Contaminants | | | Fluid Properties | | | | | |
|----------|--------------------|---------------|-----------|-----------|-------------|------------|---------------|---------------|--------------|------------|----------------|------------------|-------------|--------------------|-----------|-------------|--|
| | Date Sampled | Date Received | Lube Time | Unit Time | Lube Change | Lube Added | Filter Change | Fuel Dilution | Soot | Water | Viscosity 40°C | Viscosity 100 °C | Acid Number | Base Num. ASTM4739 | Oxidation | Nitration | |
| | | | h | h | Lube Change | L | Filter Change | % | % | % | cSt | cSt | mg KOH / g | mg KOH / g | abs / cm | abs / 0.1mm | |
| BL | 01-Jan-2023 | 18-Sep-2023 | 0 | 0 | Unk | 0 | Unk | | | <.1 - FTIR | | 15.3 | | 6.21 | 10 | 7 | |
| 1 | 15-Oct-2024 | 18-Oct-2024 | 0 | 205 | No | 0 | No | 0.2 - GC | <.1 | <.1 - FTIR | | 12.1 | 2.06 | | 17 | 8 | |
| 2 | 31-Jan-2025 | 21-Feb-2025 | 0 | 496 | Yes | 0 | Yes | 1.0 - GC | 0.1 - E2412 | <.1 - FTIR | | 12.1 | 4.11 | | 19 | 9 | |
| 3 | 28-Apr-2025 | 04-Jun-2025 | 182 | 678 | No | 0 | No | <2 - Estimate | <.1 | <.1 - FTIR | | 13.3 | 3.49 | | 13 | 9 | |
| 4 | 05-Dec-2025 | 18-Dec-2025 | 609 | 1105 | Yes | 0 | Yes | 0.9 - GC | .3 - E2412 | <.1 - FTIR | | 12.8 | 4.37 | | 17 | 11 | |

| Sample # | ISO Code | Particle Count (particles/mL) | | | | | | | | Test Method | Additional Testing |
|----------|----------|-------------------------------|----------------|----------------|----------------|----------------|----------------|----------------|----------------|-------------|--------------------|
| | | > 4 | > 6 | > 10 | > 14 | > 21 | > 38 | > 70 | > 100 | | |
| Based On | 4/6/14 | particles / mL | particles / mL | particles / mL | particles / mL | particles / mL | particles / mL | particles / mL | particles / mL | | |
| BL | // | | | | | | | | | | |
| 1 | // | | | | | | | | | | |
| 2 | // | | | | | | | | | | |
| 3 | // | | | | | | | | | | |
| 4 | // | | | | | | | | | | |

Comments are advisory only and are based on the sample information provided by the customer being valid. Results related only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.

| | | |
|---------------------|---|---|
| Historical Comments | 1 | Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Suspect most of the copper may be coming from the lubricant cooler and/or EGR cooler (as applicable). Silicon is at a MODERATE LEVEL; SILICON sources can be abrasives (dirt, Alumina Silica), seals and gasket material, lube additive or lube supplement, and/or environmental contaminant; Viscosity is SLIGHTLY LOW. Causes include contamination, incorrectly identified viscosity grade, or adding a different viscosity grade to the component. Silver Possibly from solder; Flagged additive levels are different than what should be present for the identified lubricant. This may have been topped off with a different lubricant, the fluid may be misidentified, or a different lubricant or formulation may have been in use prior to a recent change. LUBRICANT TIME was not provided for this sample. |
| | 2 | Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Flagged data may be 'wear-in' or contamination from overhauled or new unit; Copper is at a MODERATE LEVEL; COPPER is most likely LEACHING into the oil via the OIL COOLER core tubing. This typically DOES NOT REQUIRE MAINTENANCE ACTION unless there is evidence of COOLANT in the oil. Silicon/Dirt may be present due to new unit contamination; Lead possibly from solder; Viscosity is SLIGHTLY LOW. Causes include contamination, incorrectly identified viscosity grade, or adding a different viscosity grade to the component. Flagged additive levels are higher than expected for the identified lubricant. This may have been topped off with a different lubricant, the fluid may be misidentified, or a different lubricant or formulation may have been in use prior to a recent change. Lubricant and filter change acknowledged. |
| | 3 | Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Copper is at a MODERATE LEVEL; COPPER is most likely LEACHING into the oil via the OIL COOLER core tubing. This typically DOES NOT REQUIRE MAINTENANCE ACTION unless there is evidence of COOLANT in the oil. Molybdenum is slightly high for this lubricant. |

