
Leakage Tests - 12-9010 - 2023-11-06

A sale order at landous at	
Authoring Information	CONTRACTOR
Created By	Shane Arps 17808753459
Encility	Fusion Tank Services
Facility	780-875-3459
	6007 52nd ave
· ·	Lloydminster, AB
	T9V 2S7
Created	2023-11-06 10:13:42
Updated	2023-11-06 10:13:42
Client	
ŀ	
Company	Torq Trucking 2015 Ltd. 1810-250 6Ave SW
:	Calgary, AB
	T2P3H7
Contact	Torq Trucking Ltd.
	7808759693
	agent and was recorded to the second of the
Tank Data	.,
Ser. No.	12-9010
Unit Number	Torq T2045
TC Spec.	TC 406Crude
Date of mfr.	2011-07-01
Cert. date	2011-07-01
VIN	2H9AEBHGXCT002010
Tank mfr.	Hutchinson
Assembler	Hutchinson
MDIN	8932
MAWP	20.7 kPa
Test P.	34.5 kPa
Mfd. head thick	6.35 mm
Min. head thick	4.39 mm
Mfd. shell thick	6.35 (bottom) 4.75 (upper) mm
Min. shell thick	4.39 mm 84.5 m2
Exposed Surface	38000 litres
Cap.	NONE
Lining Design Temp. Range	-40 C to 100 C
Max. Lading Density	0.85 kg/L
Shell Material	5454-H32
Head Material	5454-H0
Weld Material	5356
Max. Payload	32300 kg
Max. Load Rate	1893 L/m at 20.7 kPa
Max. Unload Rate	1893 L/m at 20.7 kPa
Heating Sys. Press	NONE
aring ayarı ipaa	· IT WITH

Original Test Date	2011-07-01												
Original rest bate	2011 07 01												
Leakage Test		and the said											
Inspection Date	2023-11-06												
Inspection Expiry Date	2026-05-06	184	Julia I										
Test Medium	Air												
No. of Compartments	1												
Compartment 1	Start (psi)	E	nd (psi)	Hold Time (min)	Ca	pacity							
	2.4	2.	.4	60	38	000							
Test Results	Venting device pressure as a	are bench tested a	and hold										
	Pass												
	Product piping and valves hold pressure without leakage Repair												
-	Manways and closures inspected for leaks or deformation Repair												
	Flanged connections checked for leakage Pass												
	Inspect the entire area of the head, shell and welds for leaks or deformation including voids and adjacent compartments Pass												
	Test pressure maintained for minimum of 5 minutes Pass												
7	All leaks are repaired before the tank is marked Pass												
Defects	Valves -both front manifold valves (remove/replace)												
	PRVs -#1 Tiona lid leaks before spec (remove/reset)												
	Connections -vent line exte		from camlock (r	emove/replace gasket	:)								
PRV List	Lland												
Type of PRV	Manufacturer	PRV Criteria	Discharge Pressure	Opening Pressure	Reseating Pressure	Dispositio							

Type of PRV	Manufacturer	PRV Criteria	Discharge Pressure	Opening Pressure	Reseating Pressure	Disposition
Tank Disposition						
Current Disposition	Tank Renaired	/ Re-Tested	d / Returned to Ser	vice		



Inspector Shane Arps

Tester Shane Arps

Service provided by eStandard Solutions.

External Visual Inspections - 12-9010 - 2023-11-06

Authoring Information	on
Created By	Shane Arps 17808753459
Facility	Fusion Tank Services 780-875-3459 6007 52nd ave Lloydminster, AB T9V 2S7
Created	2023-11-06 10:9:57
Updated	2023-11-06 10:15:32
Client	
Company	Torq Trucking 2015 Ltd. 1810-250 6Ave SW Calgary, AB T2P3H7
Contact	Torq Trucking Ltd. 7808759693
Tank Data	
Ser. No.	12-9010
Unit Number	Torq T2045
TC Spec.	TC 406Crude
Date of mfr.	2011-07-01
Cert. date	2011-07-01
VIN	2H9AEBHGXCT002010
Tank mfr.	Hutchinson
Assembler	Hutchinson
MDIN	8932
MAWP	20.7 kPa
Test P.	34.5 kPa
Mfd. head thick	6.35 mm
Min. head thick	4.39 mm
Mfd. shell thick	6.35 (bottom) 4.75 (upper) mm
Min. shell thick	4.39 mm
Exposed Surface	84.5 m2
Cap.	38000 litres
Lining	NONE
Design Temp. Range	-40 C to 100 C
Max. Lading Density	0.85 kg/L
Shell Material Head Material	5454-H32 5454-H0
Weld Material	5356
Max. Payload	32300 kg
Max. Load Rate	1893 L/m at 20.7 kPa
Max. Unload Rate	1893 L/m at 20.7 kPa
Heating Sys. Press	NONE

Original Test Date

2011-07-01

External Visual Inspection

Inspection Date

2023-11-06

Inspection Expiry Date

2026-05-06

Manway Pressure

3.63 psi

Inspection

Inspect jacketing for dents, digs, scrapes, gouges, perforations, stains, or other defects or signs of damage to the inner vessel or any other condition that might make it unsafe as per 7.2.1(a)

Not Applicable

Inspect the entire area of head and shell for dents, gouges, bulges, corrosion, abrasion, cracks, or signs of leakage or other conditions that might render it unsafe for transport as per 7.2.1(a)

Pass

Inspect the entire length of every weld for cracks, defects or signs of leakage as per 7.2.1(a) Repair

Ensure devices for tightening manhole covers are operative and covers are leak tight as per 7.2.1(b)

Pass

Check all valves, vents, emergency devices and remote closures for corrosion, distortion, cracks, signs of weakness and loose or missing fasteners as per 7.2.1(c)

Repair

Ensure all required markings are legible including manway, PRV, couplings, valves and specification plate as per 7.2.1(e)

Pass

Inspect supporting structures, pads, bolsters, tie-downs and protective devices for dents, distortion, cracks, signs of weakness and loose or missing fasteners as per 7.2.1(f)

Repair

Ensure accompanying or mounted hoses comply with inspection and marking requirements as per 7.2.10.4 and 7.2.10.6

Not Applicable

Check to ensure voids are unplugged and show no signs of leakage as per 7.2.1.2 Not Applicable

Corroded or abraded areas are thickness tested as per 7.2.1.3

Not Applicable

All pressure relief devices are inspected for corrosion or damage as per 7.2.1.4 Repair

If lading is corrosive to PRV: re-closing pressure relief valves are replaced or tested as per 7.2.1.4(b)

Not Applicable

Gaskets on full opening rear head is inspected and replaced if cut, cracked or split as per 7.2.1.5

Not Applicable

Internal self closing valve and off truck emergency shut down system tested as per 7.2.1.6 Pass

Ensure that all bolts or nuts on any flanged connection or blank flange are in place and properly tightened

Pass

Defects

Welds-Structure

-#8 C\S outrigger cracked (repair)

Valves-PRV-Manways

-Tiona vents fail (remove/replace)

Hoses-Other

- -Hose hanger bent/seized (remove/replace)
- -Float stiff/seized (remove/replace packing rope)

PRV List

Type of PRV

PRV Manufacturer Criteria

Discharge Pressure Opening Pressure

Reseating Pressure

Disposition

Tank Disposition

Current Disposition

Tank Repaired / Re-Tested / Returned to Service

Approval

A

Inspector Shane Arps **Tester** Shane Arps

Service provided by eStandard Solutions.



Internal Visual Inspections - 12-9010 - 2021-03-23

Authoring Information

Croated By Nathan Hannah

780-875-3459

TC Registration

25-1118 (Expires: 2020-11-01)

Facility

Fusion Tank Services

780-875-3459 6007 52nd ave Lloydminster, AB

T3V 2S7

Created

2021-03-23 10:09:11

Updated

2021-03-23 10:09:11

Client

Company Larson Management Inc.

5101-63st

Lloydminster, AB

T9V 2E7 780-205-9243

12-9010

Larson T-52

TC 406Crude

Hutchinson

Contact Tank Data

Ser. No.

Unit Number

TC Spec.

Date of mfr.

2011-07-01 Cert. date 2011-07-01

VIN

2H9AEBHGXCT002010

Tank mfr. Assembler

Hutchinson

TCRN or CRN

N/A 8932

MDIN

CTMV Orig. Test 2011-07-01

Date **CTMV Cert Date**

2011-07-01

MAWP

20.7 Kpa

Test P.

34.5 Kpa

Mfd. head thick

6.35 mm

Min. head thick Mfd. shell thick 4.39 mm 6.35 (bottom) 4.75 (upper) mm

Min. shell thick

4.39 mm

Exposed Surface

84.5 m2 38000 litres

Cap.

N/A

Lining

Original Test Date 2011-07-01

Internal Visual Inspection

Inspection Date

Inspection Expiry Date

2026-03-31

3/23/2021

Internal Visual Inspections » eStandard Solutions

Inspection

Lining test completed if lined as per 7.2.2.1(c)

Not Applicable

Enter the tank and inspect for: dents, gouges, cracks, corrosion, abrasions or signs of leakage

in the shell or heads including bulkheads as per 7.2.2.1(a)

Inspect piping, valves and gaskets for damage as per 7.2.2.1(a)

Inspect every weld for cracks, defects or signs of leakage as per 7.2.2.1(b)

Corroded areas are thickness tested if found as per 7.2.2.1(d)

Not Applicable

Defects

Piping

LOADLINE BRACKETS WEARING THROUGH LOADLINE, 1/2 WAY THROUGH, REMOVED AND

REPLACED LOAD LINE WITH NEW.

FLOAT BEARING BLOWN OUT, REMOVED AND REPLACED WITH NEW.

Tank Disposition

Current Disposition Tank Repaired / Re-Tested / Returned to Service

Approva!

Inspector

Nathan Hannah

Tester Nathan Hannah

Service provided by eStandaro Solutions

3/23/2021

Pressure Tests » eStandard Solutions

Pressure Tests - 12-9010 - 2021-03-23

Authoring Information

Created By Nathan Hannah

780-875-3459

TC Registration

25-1118 (Expires: 2020-11-01)

Facility

Fusion Tank Services

780-875-3459 6007 52nd ave

Lloydminster, AB

T9V 2S7

Created

2021-03-23 10:12:10

Updated

2021-03-23 10:12:10

Client

Larson Management Inc. Company

5101-63st

Lloydminster, AB

T9V 2E7

12-9010

Larson T-52

Contact

780-205-9243

Tank Data

Ser. No.

Unit Number

TC Spec. TC 406Crude

Date of mfr. Cert. date

2011-07-01 2011-07-01

VIN

2H9AEBHGXCT002010 Tank mfr. Hutchinson

Assembler

Hutchinson

TCRN or CRN

N/A

MDIN

8932 2011-07-01

CTMV Orig. Test Date

CTMV Cert Date 2011-07-01

MAWP

20.7 Kpa

Test P.

34.5 Kpa

Mfd. head thick

6.35 mm

Min. head thick

4.39 mm

Mfd. shell thick

6.35 (bottom) 4.75 (upper) mm

Min. shell thick

4.39 mm

Exposed Surface

84.5 m2

Cap.

38000 litres N/A

Lining

Original Test Date 2011-07-01

Pressure Test

Inspection Date -2021-03-23

Inspection Expiry Date

2026-03-31

https://app.estandardsolutions.com/member-dashboard/pressure-tests/view/6110

3/23/2021

Pressure Tests > eStandard Solutions

PRV set to

discharge P

Test Medium

No. of

Compartments

Compartment 1

Start (psi) 34.5KPA

End (psl)

Hold Time

34.5KPA

Test Results When venting devices are removed, they are bench tested and meet the requirements for the

Pass

3.63 psi

Air

Product piping with all valves and accessories in place and operative must be pressure tested at

not less than 80% MAWP

When removed from the pressure supply, the test pressure is retained for the specified time for

the pneumatic or hydrostatic test

Inspect the entire area of the head, shell and welds for leaks or deformation. If defects found

note the location on the report

Pass

Defects No defects found.

Tank Disposition

Current Disposition Passed / No Defects Found

Approval

Nathan Hannah

Nathan Hannah

Service provided by eStandard Solutions.



Upper Coupler Inspections - 12-9010 - 2021-03-23

Inspection Date Inspection Expiry Date		Upper Coupler Inspection	Original Test Date	Lining	Cap.	Exposed Surface	Min. shell thick	Mfd. shell thick	Min. head thick	Mfd. head thick	Test P.	MAWP	CTMV Cert Date	Date Date	MDIN	TCRN or CRN	Assembler	Tank mfr.	≤IN	Cert. date	Date of mfr.	TC Spec.	Unit Number	Ser. No.	Tank Data	Contact			Company	Client	Updated	Created		Facility	TC Registration	Created By
2021-03-23 2026-03-31	2021 03-23	pection	2011-07-01	NA	38000 litres	84.5 m2	4.39 mm	6.35 (bottom) 4.75 (upper) mm	4.39 mm	6.35 mm	34.5 Kpa	20.7 Kpa	2011-07-01	2011-01-01	8932	NA	Hutchinson	Hutchinson	2H9AEBHGXCT002010	2011-07-01	2011-07-01	TC 406Crude	Larson T-52	12-9010		780-205-9243	T9V 2E7	1 loudnington AB	Larson Management Inc.		2021-03-23 10:13:55	2021-03-23 10:13:55	6007 52nd ave Lloydminster, AB T9V 2S7	Fusion Tank Services 780-875-3459	25-1118 (Expires: 2020-11-01)	Nathan Hannah 780-875-3459

3/23/2021

Upper Coupler Inspections * eStandard Solutions

Inspection

Corroded or abraded areas Pass

Cracks or defects in welds

Dents or distortions

No defects found.

Defects

Tank Disposition Passed / No Defects Found

Approval

Tester Nathan Hannah

Inspector Nathan Hannah

Service provided by eStandard Solutions.

/member-dashboard/upper-coupler-inspections/view/2255

1/2