

KOA-1

To:

RE: Examination of Tadano Boom Truck Crane

Product ID: 35-7-3207

M/N: TM-3500-1-90101

S/N: 29107835

Owner:

Capacity: 35 Ton

Engine Hrs: 5258

Kms: 161,409

Attention.

Your Reference:

Date: March 10, 2025

Our File: 103063

Technical Report

Visual and magnetic particle examinations were performed on the above-described equipment. The specific components examined and our findings were as follows:

<u>COMPONENTS</u>	<u>DATE COMPLETED</u>	<u>INSPECTOR</u>	<u>RESULT</u>
Front Stabilizer	3/10/2025	JORDANG	NO DEFECT NOTED
Outriggers (4x)	3/10/2025	JORDANG	NO DEFECT NOTED
Mainframe	3/10/2025	JORDANG	DEFECT NOTED
Corrosion/Material loss/ pitting on subframe between front and rear outrigger on both the sub frame and truck frame rail approximately 1/16" to 3/32 material loss noted fro mcursory thickness tests			
Turret	3/10/2025	JORDANG	NO DEFECT NOTED
Winch Weldment	3/10/2025	JORDANG	NO DEFECT NOTED
Boom Butt Section	3/10/2025	JORDANG	NO DEFECT NOTED
First Boom Intermediate Section	3/10/2025	JORDANG	NO DEFECT NOTED
Second Boom Intermediate Section	3/10/2025	JORDANG	NO DEFECT NOTED
Boom Tip Section	3/10/2025	JORDANG	NO DEFECT NOTED
Swing Away Jib Butt section	3/10/2025	JORDANG	NO DEFECT NOTED
Swing away Jib stinger tip section	3/10/2025	JORDANG	NO DEFECT NOTED
Sheaves	3/10/2025	JORDANG	NO DEFECT NOTED
32-Ton SWL Load Block and Hook (S/N: 291078), (P/N: 9128-96)	3/10/2025	JORDANG	NO DEFECT NOTED
7-Ton SWL Headache Ball and Hook (S/N: 07-16360), (P/N: 9129-96)	3/10/2025	JORDANG	NO DEFECT NOTED
Wedge Socket (1x)	3/10/2025	JORDANG	NO DEFECT NOTED

Repair recommendations:

It is recommended that truck frame rails and subframe be cleaned of all oxidation and scale to clean steel for further examinations to determine material losses

March 11-25 DH

Following further removal of oxidation and scale on frame and subframe the following was noted

- 1) Material loss on frame rail was noted to be approximately 1/16"
- 2) Material loss on localized areas on Subframe was approximately 1/16"


with the exception of a localized area on the driverside tie down which was 3/32"

The following is recommended:

- 1) Localized area on subframe by driverside tie down area to be repaired by weld filling and grinding smooth using sterling weld procedure WP2
- 2) it is recommended that subframe and frame be blasted and repainted to prevent further deterioration

Kova to reinspect following completion

Name: Garfil Gonzales

Signature: 

Name: Jordan Gaucher

Signature: 

Name: Derek Horvath


Signature: 



Tadano Boom Truck Crane




Corrosion sub frame passenger side



Corrosion passenger side



Corrosion passenger side



Corrosion Driverside