|--|

			2.00
		Equipment Hours	
CRN-004 MAINTENANCE HISTORY	Repair Date	at Work Order	Equipment Inspection or Maintenance Notes
			Found the power steering was not working no oil on the system filled steering fluid and it disappeared after ten minutes
			found the steering pump seal was bad putting the steering on in the engine oil. I replaced the steering pump and changed
Replaced power steering pump	7-19-25	316	the engine oil and filter out. It had 20I extra oil in the engine we used pails to measure what came out.
			HVAC blower motor will cut out after an extended period of driving. Has thermal breakers in fuse panel. Found blower motor
		9	breaker spec is 30 amp, 25 amp installed. Obtained 30 amp and replaced original. Terminals in fuse panel seem tight. To
HVAC motor intermittently functions	6-19-25	220	be tested
			Tractor cab ac blowing hot. Hooked up gauges, system is charged and compressor is engaging. Found coolant taps to
Tractor cab AC inop	6-19-25	212	heater core open. Closed and re tested AC, blowing cold
			Front crank seal is not leaking. No boom or crane complaints from operators - asked directly. Still has slower air pressure
			build time. Capped off line from air dryer to compressor. Installed gauge and shutoff on hose. Applied external air - held
		Control of Control	pressure. Unit to be taken away from running engines and checked for air leaks. I will enter a new issue for air compressor
Compressor is really slow to build air Boom with retract u	6-19-25	220	slow build time
			Disabled AUX 1 alarm as it was alarming on the crane smart screen when starting the unit. Changed out the A2B as it
A2B alarming	6-13-25	9551	wasn't stopping the winch. Tested the new one and worked as intended.
			Completed service sheet
			Repaired leaking suction fitting on power steering pump
			Repaired hydraulic leak at selector valve for outriggers.
			Replaced hydraulic line from hydraulic pump to selector valve.
	n	5-10 CONTROL TO	Fixed damaged wiring on 1st differential for temp sensor
A service	4-4-25	152	Replaced 3rd differential temp sensor and wiring.
			Replaced hour meter/tach gauge
			-new due hours are 150, current hours are zero (ecm 9484)
			-set dip switches according to the instructions
			-monitor tach reading vs ET engine speed, matches
Replaced tach/hour meter gauge	3-8-25	0	-run unit for 15 minutes, hour meter matches.
			Dan would not shut off, Todd diagnosed and suspected high resistance in the wiring, I tested all wiring and tested good but
Engine fan not turning off	3-3-25	0	still would not shut off, hooked up et and found a/c high pressure switch failed and was commanding

			Troubleshoot Engine fan light always on//manual fan inopfound a wiring diagram of the circuit, might not be 100% accurate but something to go off of. Attached to WO -found the pressure switch for the fan was wired incorrectly and plumbed in on the wrong side of the air solenoid for the fan. It was always getting pressure and wired to the NO side so the fan light was always lit. Swapped pressure switch to outlet side of the solenoid and wired it to the NC contact so that when there is no pressure on the switch (fan on) that the bulb turns on. The bulb now works properly again -cut back wires to pressure switch and install new terminals, one wire had 1° of bare copper showing
			Troubleshoot inop manual fan switch
	1		monitor inputs on ET,
			-AC high pressure switch/ AC fan input turns on Fan and functions as it should. Was told one of the AC pressure switches was bad causing the AC to come on when it wasn't supposed to, ohm'd out switches OK. They might have had the Defrost turned on which will run the AC. Read somewhere online when the ECM turns on the fan its on a timer so when the AC is turned off it will continue to run for a bit, which tests true.
			-no state change with manual switch -jumped pins 3 and 2b together to bypass the fan switch, fan doesnt come on, also ohm'd out the switch and it is switching those contacts when in manual. Diagram shows its a ground input to ECM, checked connection at pin 2b to ground, OK.
	[Supplied ground to pin 3, no change.
			-turn fan solenoid on/off with ET -Check ECM configuration setting for manual fan override switch was set to j1/P1:41, the diagram says that engine fan
			override is input 7, change to j1/p1:7. Manual fan works again!!!
			-install missing screws in warning light bar
Manual fan not working, fan light on all the time	3-1-25	29805	-ziptie loose wiring on top of rear valve cover
	1		Replaced 3 hydraulic hoses
			-2 for the scope out cylinder, between the valve bank and swivels
Leaking hydraulic hoses	3-1-25	29796	-replaced one hose between the turret swivel and the valve bank
			Troubleshoot inop high beams -checked power and ground, ok. Install a low/high beam bulb and it functions normally. Has LED bulbs, ordered new ones.
			Was told these lights are new, found a date code from 2016, likely have bad High beam circuits, also found pins on the
Inop high beam lights	2-26-25	29796	connector were corroded.
18 - Lamps/Reflectors: Passenger side front clearance light	2-26-25	0	light is working at this time, other mech might have repaired it
10 * Lamps/ reflectors. 1 assembly side from clearance light	 		Replaced headlights replaced the TXV valve and receiver dryer and did a service hour meter not working ECM hoursx as
A Servie, Headlights, txv valve, reciever dryer	2-20-25	9337	are 9337 hrs
			Previously diagnosed as ac pressure switch. I installed the new switch, the fan turned off and worked as normal for an hour then stuck on again. New switch failed or we have other issues. Noticed torn intake boot on top of air to air. Replaced failed
Engine fan not turning off. Dylan diagnosed as as pressure switch	2-15-25	29795	boot.
No start	2-8-25	29781	Had to replace starter motor
Coolant leak	12-28-24	29697	Replaced o-ring on pipe from oil cooler to water pump
	1,,,,,,		removed temporary work around, and existing plug off webasto air top and replaced with Duetsch connector. all tested
Operator Cab Heater connector	11-8-24	29690	okay.
coolant leak at surge tank	11-4-24	2963	coolant leaking at filler neck on surge tank. de soldered neck and soldered in new filler neck, tested for leaks, tested good
TIRES	10-29-24	2000	1 Michelin tire installed and balanced at Kirks
coolant header tank cracked	10-15-24	29661	JB welded the header tank neck again under the rad cap.
			Found power HI, LOW, tested okay at spade connections off the wiper motor. Noticed mounting bolt for motor mounting
	1		plate sheered off. These motors are grounded from their mounting plate direct to chassis so without bolt to hold it in place it
Crane cab front wiper INOP	10-12-24	29658	would not function. drilled out new hole and replaced bolt all tested okay.
"A" service	9-26-24	29638	Completed *A" service
Battery box inspection	8-30-24	29581	Completed Battery box inspection
oil pressure gauge leaking	8-18-24	29545 29493	installed new o-ring on oil pressure sensor
7pin plug	8-5-24	29493	Replaced 7Pin plug to pull jeep from one lease to another as old one was rotten.

crane winch rollers	7-29-24	29474	removed winch rollers and installed bigger rollers so the winch cable wouldn't rub on the brackets.
rear outrigger modification	7-29-24	29474	installed hose reels on back of crane for outriggers, built and installed new hoses for downriggers, tested.
rear ourngger modification	1 2 2 4	20414	CVIP Repairs
			- Replaced tank drain cords
	1 1		- Replaced lower steering shaft u-joint
			, ,
	1 1		- Repaired rear work light circuit
			- Replaced axle 3 shocks
			- Replaced axle 3LH and axle 5RH wheel seals
		*****	- Replaced air dryer cartridge and purge valve
CVIP	7-24-24	29445	- Secured loose CAC mounts
replaced rear D.S downrigger hardline	7-23-24	29462	replaced hardline
]]		Oil on exterior of transmission. Cleaned off. Replaced o ring on plug at side of PTO. Looks like PTO outlet shaft seal is
Transmission oil leak	7-19-24	113801	seaping as well. Topped up transmission oil
Retorque all	7-19-24		Retorqued all. Removed and filed torque tag 001060
			Rear outrigger replace three tubes that are bent.
			MEASURE AND ORDER MATERIAL TO MAKE NEW TUBES, CLEAN AND REMOVE DAMAGED TUBING.
			- MANUFACTURE NEW TUBES AS PER SAMPLES AND INSTALL ONTO OUTRIGGER.
			- PRESSURE TEST CYLINDER AND TUBES TO MAKE SURE WE HAVE NO OTHER ISSUES OR LEAKS.
Replace outriggers	7-17-24		- EVERYTHING TESTED GOOD, CLEAN CAP FITTINGS.
TIRES	7-11-24		Flat repair sent by TYTAN
Driver side rear outrigger, replaced hoses and extension ram	7-9-24	29443	hydraulic hoses twisted steel lines on extension ram
Direct Side rear outrigger, replaced modes and extension rain	- - - 		drivers side mirror lights don't work, found it wired incorrectly, wired it correctly and now there is 12v to the lights but both
drivers side mirror marker lights not wokring	6-22-24	29424	lights are burnt out. Mechanic will get some and replace them.
University Side minror marker lights not working	 		noticed a small wet spit on the ds rear down rigger hard line. as I was inspecting, I had the op function the down rugger up
			and down. I saw hyd fluid pouring out between the first and second stages of the outrigger, removed the inspection plate
	1 1		and saw one of the lines or fitting was leaking on the up function. removed the cylinder and found both line heavily worn,
			routed wrong and leaking. had TME in Killam make new lines, verified proper routing of the lines and verified they wouldn't
l	6-17-24	29411	get hung up.
hyd leak	0-17-24	29411	lots of steam coming from engine comp.
	-		
	1 1		coolant spewing from over flow.
			main belt had broken.
over heat	6-17-24	29396	tensioner bolt eas backed off making the belt slack and snap. tightened the tensioner and installed new belts.
Retorque steers	6-6-24	29393	Retorque both steer axle wheels as per tag 1009
			Transmission input seal leaking. Was advised to take down and inspect clutch. Lifted unit on outriggers. Drained
			transmission, inspected oil, okay. Removed driveshaft, hydraulic pump, pto, transmission air and electrical. Unbolted clutch
			and shift lever. Removed tandem spring mount crossmember. Supported unit with transmission jack, removed bell housing
			bolts, lowered transmission and removed from unit, Removed flywheel, replaced seaping rear main seal. Cleaned flywheel
	i I		housing. Installed new pilot bearing. Re installed flywheel, torqued. Removed and inspected clutch. Inspected pto.
			Dissasembled input shaft, found input bearing spacer missing upon dissasembly Installed new cross shaft bushings, input
	_ j _ l		shaft, input bearing, bearing space bearing plate, clutch brake and release fork. Power washed clutch housing and
			transmission. Replaced worn release bearing grease hose. Re installed clutch and transmission into unit. Torqued clutch
			and bell housing bolts. Re installed driveshaft with new u joints x2 (greased), hydraulic pump, pto, transmission air and
			electrical. Re installed shift lever and tandem spring mount crossmember. Re filled transmission. Had steer tires x4 replaced
			at kirks. One tire saved as spare. Re installed wheels, torqued. Installed torque tag 001009. Replaced pulled out pins in AC
			high pressure switch. Tested AC operation and fan cut in pressure. ABS light for PS front drive modulator open. Found
			Idamaged electrical connector. Parts on order. Test drove unit in yard, verified no leaks. To be test driven fatter and re
Transmission insut and looking	4-25-24	29387	torqued in morning
Transmission input seal leaking	4-24-24	23301	4 New tires installed with stems and wheel balance.
TIRES	4-24-24	29381	r&r PTO and pump, set backlash to .007", refill trans, test and check for leaks
PTO	4-11-24	29383	rear Fire and pump, set backlash to .007, retili trans, test and check for leaks
air bag replaced (middle passenger) / rear outrigger hoses passenger side			
crane cab heater	3-7-24	29351	replaced previously diagnosed crane cab heater. It tested good.

			Operator call diseast heater increasting. Heaterd up with websets coffware in short Locked out for welfage. Heat helbert
			Operator cab diesel heater inoperative. Hooked up with webasto software in shop. Locked out for voltage. Had battery charger on unit, would drop below 10V when fan kicked in. Checked voltage at source in cab, 10.5 volts. Voltage would
	l l		increase when tractor is started. Could not get unit to start with multiple attempts, blew out combustion chamber to no avail.
		00000	
No heat in operator cab	3-2-24	29338	Heater on order. Voltage supply to operator cab should be looked at during breakup
Replaced the bad ac fan switch	2-21-24	29302	- replaced the A/C engine fan switch old one was not letting the fan turn off. working good now
			- checked for engine fan not shutting off found the ac switch was faulty put a jumper wire in to stop the fan till the new sensor comes in.
and the second s		00000	
engine fan not turning off	2-19-24	29292	- call for rad leak removed the fan and pinched off the leak till a new rad can get installed.
coolant diverter solenoid	1-7-24	29281	replaced solenoid on coolant diverter cartridge, tested operation
			Inspect for rough running
			found active codes for IVA number 6 coolant diverter and boost pressure sensor followed diagnostic flow chart found Iva 6
			shorted replaced with used part from spare cat engine tests good orders coolant diverter solenoid
			when testing for boost pressure found sensor unplugged reinstalled and had unit road tested operating with peak
ough running and check engine light	1-6-24	29281	performance at this time
			r&r centre axle lay. torque arm
orque arm	1-6-24	28280	D/S/M Longitudinal torque rod.
			found 1st axle differential temp sensor to be broken. ordered and obtained new temp sensor and installed re crimped new
			end on wiring.
			found d.s leveling valve rod bent from hitting frame when bags dump.
			removed straightened and cut off 1/4"
			reinstalled and leveled properly from side to side.
run through	1-4-24	29279	2nd axle longitudinal torque rod bushing moving out. ordered rod will see tomorrow
			oil pan gasket needed replace
			removed pan and gasket and old silicone.
			cleaned up and block surfaces and applied new silicone to 4 corners of the block where front and rear of blocks mate
			installed new gasket and pan torqued bolts to 20 ft/lbs in proper sequence
			changed oil and fuel filters and refilled oil.
pil pan gasket and new filters	1-3-24	29279	during run up found the oil return line was loose and leaking, tightend up and reran, found no leaks
Repair Damaged tail light wiring	11-21-23	29204	Repair corroded wiring to licence plate lamp and passenger rear clearance lamp, secure with zipties
			- towed unit in shop
	1 1		- checked for no start problem found the ecm not communicating with laptop.
	!		checked all power wiring to ecm everything was good.
			- Replaced ecm with one from 1003 unit started and ran good
			- cut out the front spring bumper bolt and replaced the bumper and bolt.
no start problem	10-28-23	29200	- checked the discharge line from the compressor to dryer didn't see a problem .
out protein	13 23 20		- towed unit in shop
			- checked for no start problem found the ecm not communicating with laptop.
			checked all power wiring to ecm everything was good.
			- Replaced ecm with one from 1003 unit started and ran good
	1 1		- cut out the front spring bumper bolt and replaced the bumper and bolt.
and a stant markland	10-28-23	29200	- checked the discharge line from the compressor to dryer didn't see a problem .
no start problem	10-20-20	20200	cel. Engine coolant diverter current low code. Tested the circuit response by opening and shorting. Circuit did not respond.
and the state of t	10-15-23	29180	Suspect harness issue.
cel	1 10-13-23	23100	purposi numbor isout.

			Greased unit, ordered PS front steer axle suspension bump stop. Rolled through unit. Replaced leaking rear drive axle ds
nspect, replace DS rear abs modulator valve	10-10-23	105615	abs modulator valve.
oolant leak	10-1-23	29147	replaced leaking heater hose at webasto .
nti two block broken	9-16-23	29072	Anti two block broken, got new one installed and tested good.
" service	9-12-23	29064	"A" service completed
A SERVICE	0 12 23	20001	Sensor has been completely broken out of the housing. Parts on order. Have bypassed the alarm until parts can be
2B has been damaged and needs replacement	9-3-23	29032	installed.
letorque	8-31-23		Retorque wheels as per tag 000726. 450 tt/ ibs
ngine fan	8-3-23	28958	Replaced engine fan
nti Two Block not working.	7-27-23	28915	repaired tension ring/spring inside block and rotate clevis eyelet 180° to stop it from catching wiring. All tested okay.
	7-24-23	28902	Replaced hydraulic lines for driver side outrigger.
utrigger hydraulic lines	7-21-23	20002	Retorque wheels as per tag 000597
torque FO leak / cab fan	7-21-23	28889	resealed front cover on PTO and replaced missing fuse for fan in crane cab
TO leak / cap fan	72.25	20000	replaced front drag link and rear drag link ends. replaced main steering box and pitman arm perform air bleed procedure. verify steering wheel is straight-ok. recommend sending out for wheel alignment. inspect leaks and pro shaft cover- found worn groove on shaft. installed speedy sleeve and news seal. refill trans and test for leaks- no leaks.
			test for long air build time. replaced desiccant filter and retest- no change, test air line from compressor to air drier-found perforated, replaced line and retest still has slow build time. inspect and test operation of air drier and found internal check valve leaking.
vip repairs	7-19-23	28871	replaced air drier and retest now build air fast.
			replaced all brakes shoes and drums. removed all scams and replaced seals installed all new wheel seals and filled hubs. replaced failing slack adjuster on right rear drive axle. removed front to middle and middle to rear drive axle shafts. installed 2 new unjoints in front to middle drive shaft, sent middle to rear out to get rebuilt and than reinstalled. removed rear cover from front drive axle refilled front drive axle- resealed due to leaking, replaced clear crane light, replaced left and right rear side marker lights and pigtails, replaced right side upper inner stop light, had redark come in and reeled all suspension chains. Repaired block heater cord and installed new left side step light.
CVIP Repairs	7-16-23	28871	Parts ordered to repair steering and one more step light.
VIP	7-16-23	99300	Completed wheels off CVIP INSP
VII			Remove DS wheels and stairs for access.
			Remove and replace rear steering box and pitman arm. Torque retainer on pitman arm to 350ftlbs, installed antisieze as per manufacturer
			Replace drag link ends between both steering boxes.
			Remove pitman arm off main box.
			Parts is looking for a new drag link tube between pitman arm and steering knuckle, threads are damaged. The end that was
teplace rear steering box, drag links	7-13-23	28873	removed, center of drag link to end of tube was 93mm
	7-12-23	23070	Cut off Axle chains and properly repair.
epair	7-12-23		Annual Crane inspection
spection	7-5-23		Annual Crane Inspection
nspection	7-5-25	-	Hydraulic Swivel Replacement. (Turret Line Swivel.)
			Remove shock mounts, cut and air hammer bolts out, buff and paint frame.
			· · · · · · · · · · · · · · · · · · ·
	0,4500		Repair, Paint and remount shock mounts with new hardware.
Repair	6-15-23		Axle 4 both torque arm bushings and Axle 5 transverse torque arm bushing replaced.

.

			- repaired a bad brake air line on #3 axle right side.
Bad brake air line	6-12-23	28840	- tied up all the loose airlines to the brake pots
			Diagnose Steering box leaks. Found the manual relief plunger leaking. Removed plunger and replaced seal. Still leaks.
Look into steering box leaks, Needs new front box	6-1-23	28828	ordered new manaul 110 steering box.
			ac inspection. clutch would not kick in. hooked up gauges and found 78psi on high/low sides. checked clutch pigtail and
			found erratic 12v source. checked wiring over and found a break on one of the fan switches. installed a new plug and
			tested good.
			testing e-kill. inop. found the air line had been removed, plugged off and ziptied out of the way. I cleaned the threads in the
			rodadeco and installed a new pipe fitting, installed a new air line from the relay to the Roda, tested good. I cannot see why it
			was disabled.
!			inspected fan hub wear, found .041"
			inspected outrigger extension wear pads, no sign of rust jacking, no sign of binding while functioning the stages in and out.
break up list repairs	4-9-23	28798	unit is good to return to service.
Drivers rear outrigger no function	3-11-23		Found failed relay in relay panel on passenger side beside front outrigger. Worked fine afterwards
Diff of our ourigger for furfaction			- repaired the broken tilt steering wheel lock
steering lock	3-8-23	28792	- tighten loose steering hoses
occurry con			- helped the etech diagnose the problem with the no rear throttle problem found the 5v signal was good and the peddle
			signal voltage was good, checked in the electrical panel on passenger side and found a bad 5amp fuse replaced and
no rear throttle	2-24-23	10718	everything was working.
no tour unound			- Replaced the air compressor and tested.
ļ ·			- replaced the air dryer cartridge and purg valve
replaced air compressor	2-20-23	28784	- replaced the fan belt and 2 Idler bearings.
back-up alarm	2-20-23	28784	replaced back up alarm and pigtail attached to it. all tested okay
Repair	2-1-23		
winch line replaced	1-27-23	28759	kink in winch line, needed to be replaced. Dakoda Gackle spooled 500 ft of new line and pull tested.
Times the representation of the representati			-Troubleshoot CRN cab Heater not working
i		l	-unit smokes a bit during start up then cuts out. Faults for code F01 no start.
		ĺ	-check intake and exhaust for blockage, when blowing air into inlet lots of diesel came out so its not a fuel issue.
		ŀ	-remove unit from cm cab.
1			
			-Disassemble airtop, measure resistance of all sensors all in spec.
[l	-glow plug and combustion chamber full of carbon, cleaned up.
		l	-install Heater back in unit
Troubleshoot CRN Cab Heater, Cleaned out carbon	1-18-23	28744	I-test, starts right up and makes good heat. Ran for 3hrs with no issues
Houseshoot Only Can reater, Cleaned out Carbon	1-10-20	20177	took out to fight up with maked good frout. Hair for only this no record

.

			-Replaced down rigger cylinder extention lines from bulkhead to cylinder on passenger side rear outrigger. Function and
	i		leak test, OK
	i		-Removed outrigger ram on DS rear, hoses ripped off bulk head. send ram away to get lines repaired. Replaced damaged
	1		bulkhead
	1		-installed ram with new extension hoses, function test to see if lines would get caught up. Had to shorten hose, hose length
			was 77" not including fittings.
	1		
		1	-install new hoses from down rigger to bulkhead. Replaced leaking steel line on down rigger retract to counterbalance
			valve, replaced oring between CBvalve and cylinder
			-function/leak test down and outrigger, OK
		1	-top up hydraulic tank, below sight glass to half
		1	Look over unit
			-topped up engine oil
			-unit is 78hrs away from service
			-repaired PS tail/license plate wiring at back of unit
	1	1	-replaced axle flange gasket on DS front drive axle, oil level in Diff Good
			-replaced hub cap gasket on ds Rear steer hub. Fill with new oil
Repair leaking outriggers, Look over unit	1-14-23	28730	-secure wiring behind front bumper
wiper on crane cab front	1-9-23	28726	replaced missing wiper arm and blade for front of crane cab
wiper on crane cab from	1-3-23	20/20	Cm 4 boom length alarm remained active. Not sure how it lost its calibration. called Cranesmart and went through re
			calibrating with Jerry operating crane.
	į		Also confirmed Load cell operation by lifting a know weight.
			Confirmed with Jesse and Jerry that they did not want it re calibrated to show block weight.
Boom length Alarming and test load cell	11-19-22		To get into calibration menu i was supplied with code 111 from cranesmart.
la construction	11-15-22	28619	Tested existing switch under seat and it has a wire pulled out of it. Replaced and wired into existing cabling. Tested good.
Seat switch not working			replaced transmission output yolk and ujoint
replaced ujoint and yolk	11-10-22	28634	
Replace air compressor	11-5-22	28601	Air compressor inlet fitting stripped. Removed and replaced compressor. Tested okay
Replace 500 Ft of winch line	10-28-22		Replace winch line
		i	- replaced the blown air bag on #5axle right side and bad one on #4 acre left side
	i		- checked the heater blower current it was pulling 18amp at the motor found the fuse box pins were not making a good
	1	1	condition causing the breaker to get hot and trip after 5 min of run time. I pinched the connection together and it seems to
air bags and heater	10-5-22	28518	have stopped the breaker from tripping.
			- completed A service
	1		- greased unit
			1 groupes arm
			- checked all fluids
			• • • • • • • • • • • • • • • • • • • •
A service	10-3-22	28508	- checked all fluids
A service	10-3-22	28508	- checked all fluids - replaced the air filters - checked over unit
A service	10-3-22	28508	- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve, was leaking so hydraulics could be functioned without button in
A service	10-3-22	28508	- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve, was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctly.
A service	10-3-22	28508	- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve, was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctlyReplaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks, set to 500psi (spec found in
			- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve, was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctly. -Replaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks, set to 500psi (spec found in schematic).
A service Replaced Hydraulic Cartridges	9-28-22	28508 28489	- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve, was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctly. -Replaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks, set to 500psi (spec found in schematic). -pressure no longer drops off 200psi when any circuit is functioned. Can run 4 functions at one time.
			- checked all fluids - replaced the air filters - checked over unit - Replaced Solenoid cartridge for hydraulic blocking valve. was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctly Replaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks. set to 500psi (spec found in schematic) pressure no longer drops off 200psi when any circuit is functioned. Can run 4 functions at one time. Replaced upper wiper motor with Toban.
			- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve. was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctlyReplaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks. set to 500psi (spec found in schematic)pressure no longer drops off 200psi when any circuit is functioned. Can run 4 functions at one time. Replaced upper wiper motor with Tobanswapped shorter drive stud from old motor to new.
Replaced Hydraulic Cartridges	9-28-22	28489	- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve. was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctlyReplaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks. set to 500psi (spec found in schematic)pressure no longer drops off 200psi when any circuit is functioned. Can run 4 functions at one time. Replaced upper wiper motor with Tobanswapped shorter drive stud from old motor to newinstalled a new nut on the wiper arm
			- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve. was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctly. -Replaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks, set to 500psi (spec found in schematic). -pressure no longer drops off 200psi when any circuit is functioned. Can run 4 functions at one time. Replaced upper wiper motor with Tobanswapped shorter drive stud from old motor to newinstalled a new nut on the wiper arm -tested good
Replaced Hydraulic Cartridges	9-28-22	28489	- checked all fluids - replaced the air filters - checked over unit -Replaced Solenoid cartridge for hydraulic blocking valve. was leaking so hydraulics could be functioned without button in run position, the bypass on the cartridge also didn't work. Now everything is working correctlyReplaced pressure reducing valve and am now able to adjust pilot pressure for the joysticks. set to 500psi (spec found in schematic)pressure no longer drops off 200psi when any circuit is functioned. Can run 4 functions at one time. Replaced upper wiper motor with Tobanswapped shorter drive stud from old motor to newinstalled a new nut on the wiper arm

. "

			Troubleshoot blower motor self resetting fuse repeatedly tripping.
	1 1		-replaced blower motor and resistor block, no change, installed original parts
	1		replaced fan speed switch and resettable 30amp fuse. no longer trips the fuse, fuse also doesn't get nearly as hot. 40°C vs
			79°C
			Installed new wiper on front of crane cab, reclocked wiper arm
			troubleshoot inop wiper motor on roof of crane cab.
Troubleshoot Inop Blower motor, troubleshoot wipers	9-16-22	28442	-has good power going to the motor for each speed, ground is good, a new motor has been ordered.
Troubleshoot Inop Blower motor, troubleshoot wipers	9-16-22	20442	-has good power going to the motor for each speed, ground is good, a new motor has been ordered.
•			Troubleshoot Slow hydraulics with etech.
			-found the electronic solenoid for the joystick blocking valve intermittently working after rig moves. Inspected the wiring for
			the blocking valve, didn't see anything other than the connector was a bit corroded. Replaced the din Connector. Keeping
			an eye on it. hasn't failed since it started working two days ago, if it fails again we will have to look at the power side of that
			solenoid.
			When the blocking valve wasn't working correctly the pilot pressure was only reaching 200psi hence the slow hydraulics
			Which the steeling valve mach, working contestly the pilot presents that any reasoning zerper vertex the cloth hydraulise
			When the blocking valve is working 400psi is found, according to the hydraulic schematic it should be at 500psi which is
			controlled by a pressure reducing valve, tried adjusting the pressure and nothing happens when the set screw it adjusted in
			either direction.
			Ordered a new pressure reducing valve as 3000psi is found on the inlet side of the pressure reducing valve which is spec.
			Also noticed the hydraulics still work with the estop button in the stop position, simulating like when the blocking valve isnt
			working. the cartridge must be leaking by allowing flow to the pilot lines on the joy sticks. also ordered a new solenoid
Troubleshoot Slow Hydraulics	9-15-22	28442	cartridge for the blocking valve.
			Diagnosed hvac breaker to a faulty switch on panel. Fuse would overheat on max setting but not others, mechanic grabbing
	ĺ		new switch to install.
	1		Activation button in control cab of crane intermittently seems to be failing. When looking at the time, was working properly
	1 1		but ops have said it was running slower before. Replaced the DIN connector on the solenoid as was in rough condition.
Functions coming on slow, blower motor tripping fuse in tractor.	9-15-22		Power is good at connector and at push button. Monitoring in the mean time.
			Coil of solenoid had wires exposed, cracking the housing. Suggested ops not use it as this was a hazard. Fitted a different
	1 1		style coil until Al sent up proper one. Installed proper and working properly. Went through all other solenoids2, cleaned up
Found very badly damaged solenoid.	9-10-22		cartridges and coils. Working
			Found a DIN connector in center of turret, fixed problem when wiggling around, took apart the din connector, cleaned out
No crane controls inside cab.	9-10-22		pins and cut back wiring a bit. Reconnected, working good.
DS FRNT outrigger	9-9-22		outrigger would not extend, mechanic and I swapped out relays and replaced two, outrigger started working- monitoring
	1 1		- check the unit for no heater blower motor found that the blower motor keeps blowing the auto reset fuse and heating up
	1 1		the circuit when the motor was disconnected everything works good and does not heat up. I ordered a new heater blower
no blower in cab	9-4-22	28381	motor and resistor for this unit.checked all wiring behind the dash could not find a bad wire anywhere.
Replace Damaged Hood signal/marker lamp assembly	9-1-22	28362	Replaced damaged signal/marker lamp assembly on passenger side of hood.

•

•

Replace clutch	8-23-22	28315	Removed transmission from unit, removed old clutch. Cleaned up input shaft. Replaced cross shaft bushings, replaced cross shaft. Replaced flywheel, torqued flywheel bolts to 200 ft lbs. Replaced pilot bearing. Replaced clutch brake. Installed clutch onto input shaft. Installed transmission onto unit, torqued bell housing bolts to 50 ft lbs. Torqued clutch bolts to 50 ft lbs. Hooked up all air fittings and electical connections for transmission. Installed pto and set backlash to .011" Replaced transmission output u joint. Unit needs new transmission output yoke due to stripped threads.
Retorque	8-23-22		Retorque wheels as per tag 000608
Air to Air boot	8-22-22	28317	replaced air to air boot that had a hole in it
			Battery Cable running under oil pan to starter rubbed through and caused a fire on the LHS of the engine. The fire caused damage to the battery cables, engine wiring harness, truck side wiring harness, fuel lines and some air lines. All battery cables Replaced, Rerouted and secured properly to avoid rubbing. Engine wiring harness replaced and tied up. 1 supply and 2 return fuel lines were replaced and secured. Truck side wiring harness repaired and secured with P clamps. slightly rerouted to better spot. Air kill lines replaced. Tied up and secured loose wiring and coolant lines running along the frame. Started engine and ensured all was in proper order. One engine code appeared, calling for 385-3 Intake Valve Actuation System Oil Pressure voltage high (95) Wiring to the head lights and turn signals/markers on hood was in poor condition. Replaced harnesses and plugs to lights, and secured them properly. Wiring for the rear tail lights rubbing on air bags and in poor condition. Repaired wiring and tied up properly.
Major Repairs from Fire.	8-17-22	28315	DUE HOURS: 28523 (Sample Required)
signal flasher	8-7-22	28307	replaced previously diagnosed flasher. lights tested good.
			wheels off inspection replaced blower motor resistor replaced left rear wheel seal replaced right middle hub gasket replaced #1 brake pot repaired left and right fenders replaced mud fap anti sail brackets replaced mud fap anti sail brackets repaired broken bolts in right side of crane frame repaired broken bootstrap in right fender replaced left and right head light assemblies replaced 4 broken rebound clips on the suspension replaced left side 2nd suspension bump stop replaced 2nd steady bearing repaired 3 broken limit chains replaced axle 1 left front brake shoes replaced left rear shoes and drum
cvip	7-26-22	28253	slick inspection completed crane inspection
Angle alarm is constantly on	7-26-22		Replaced low battery and recalibrate the angle, load and reel. Tested good.
Load cell not working	7-26-22		Found that the battery was dead, replaced battery (had to use a flat washer for positive post to make contact)
Control cab fan not working	7-26-22	l	Wiring and 3 position switch are badly damaged. Removed and replaced all. Fan tests good now

A2B not cutting winch out	7-26-22		Troubleshot with cranesmart tech and found that the a2b box itself is bad and needs replacement, new part ordered
			"P Cont" wire in harness broke at connection to plug, fixed. Antenna unplugged from back now plugged back in. Tested and
Sterio not picking up radio station.	7-26-22		working.
			Opened it up the check the battery and board, all good, re installed battery and the system saw the a2b again, needed a
A2B reported to be not working	7-26-22		hard reset
			Organized wiring in crane control panel. Cound outrigger wires in terminal strip inside panel to be in bad shape, cleaned
	1		terminals and replaced ends. Found a bunch of failing relays in the outrigger relay box on the PS, replaced 5. Found bad
			ternimal in the same box, cleaned and now passes voltage. All solenoid tested and clean, turrect ring contact block sprayed
Outrigger wiring overhaul	7-26-22		down. All functions tested after reassembly.
Eront DC quitrieses ant outpoding	7-26-22		Cleaned Din connector and tested voltage to connector. All Good. Replaced coil as it was rusted. Tested Unit. All Good
Front PS outrigger not extending Load cell reading max.	7-26-22		Recalibrated load cell.
Load cell battery dead	7-26-22		Replaced
Driver side rear outrigger would not retract	7-26-22		Verified electrical and controls, unit send home for repair
Anti 2 block needed replacement	7-26-22		Swapped out the A2B and checked the comms, OK
First 2 book noceds replacement	7 20 22		Signal strength good at panel and alarm shows up when battery removed from A2B switch. Checked battery voltage, good.
	į l		Tried another battery, no change. Disassemblied switch, no physical damage to board or wiring. Doug working on getting
Anti two block switch operation not showing up on CraneSmart panel.	7-26-22		replacement switch.
· · · · · · · · · · · · · · · · · · ·			
			New A2B sent from crane smart is for the auxiliary A2B, which is turned off in the display settings. Called crane smart and
			was able to change channel of Main A2B(74 to 75) and Aux A2B(75 to 74) to have A2B function proper. Bringing back failed
			A2B for repair. will be replacing with proper main A2B and sending back Aux A2B after repair is complete to aviod charges.
New A2B not communicating with crane smart head unit.	7-26-22		***settings will have to be changed with crane smart when replacing with proper main A2B
			Signal & battery good. Opened up & tried adjusting spring tension. Working by hand. Installed back on crane but failed
A2B switch not operating.	7-26-22		again. New A2B switch on order.
			Checked signal input for both, nothing. Replaced battery for "Cable Reel", now had good signal for both "Angle Main" and
CraneSmart showing alarms for "Angle Main" and "Cable Reel".	7-26-22		"Cable Reel". Found that the "Cable Reel" tarnsmitter was a 2 in 1 setup, performed both operations.
			A2B Block Aux 1 showing alarm but we only use A2B Block Main. Showing turned off in menu. Also operator losing angle
0	7-26-22		signal at times & it shows up as an alarm. Signal strength good & menu shows OK. Could not locate angle transducer on boom? Left for now, needs tooking at back in Hat.
CraneSmart system showing errors, operator has to use bypass to use. Red light on multi-coloured work light on crane not working	7-26-22		Tightened up terminals in light housing and test good.
ned light on multi-coloured work light on crane not working	7-20-22		Had 10.5VDC to solenoid (2A). Measured resistance of solenoid (6.8 omh for 21W 12VDC coil) good. Pulled apart
			hirschman and found loose terminal. Tightened up and tested good. Clean up all cartridges, solenoids connectors and
Road side rear outrigger extract function not working.	7-26-22		wiring to rear outrigger valve bank. Tested good.
2 way radio in crane cab not programmed for our channels.	7-26-22		Installed used 2 way in cab, with required channels.
a may make in ordine ode not programmed to the entire of the manner.			Pulled on cable reel for indicating boom length, readings were incorrect on cab display (Crane Smart). Slippage on reel,
			removed & reseated reel shaft to spring tensioner & checked electronic connections inside, OK. Checked drum connection
			to shaft, reseated drum on shaft cam & tightened retaining screw. Performed a fully retracted (30.2') & fully extended (96.9')
Boom extension readings out.	7-26-22		calibration on cable reel for boom length. Verified correct operation.
Unit needs 2 way radio	7-26-22		install 15 amp inline fuse harness, install radio and test.
		·	
Unit needs GPS	7-26-22	00000	Install GPS behind far left DS instrumentation panel. Powered up and LED's. Submit paperwork to Dalias for activation
Retorque	7-23-22	28267	Retorque as per tag number 473
B annian	7-1-22	28223	Changed engine oil, oil filter, fuel filter and fuel water separators. Did not have time to complete checklist - Air filters on the way with cross shift. Remainder of B service will need to be completed at shop
B service Replace engine warning light lense	6-15-22	28223	Replaced engine warning light lense on head liner
Inchiace engine waiting light lense	0-13-22	20174	Inspected the winch cable and sheave.
	1 1		Cable had a small bend. No indication of twists, kink, crushing or over loading.
			One sheave had some damage but the cable was in no danger of being damaged.
			Replaced idler Bearings and both belts.
Crane inspection and repairs	6-10-22	28121	Replaced front steer Ps tire. Torque tag tied to the keys.
Orang inspection and repairs	1 0-10-22	20121	I replaced from a too. To the tag hed to the keys.

. .

			unit had no refrigerant in system pressure tested and found bad oring at compressor, replaced orings and put unit on vac
landa.	5-18-22	28070	and tested all good, filled with refrigerant and tested all good.
no a/c	5-6-22	28007	- removed the main engine harness it was full of oil replaced with new harness ad tested unit runs good.
replaced engine harness	5-0-22	20007	wipers, heater and radio inop. found no power on the whole row in the fuse panel, could not find the open in the circuit
	3-21-22	27928	without tearing the entire dash apart. ran a jumper wire in the fuse panel working fine for now.
wipers, heater and radio inop	3-21-22	21920	unit had no power to ign fuses ecm would not power up, diagnosed no power to 85 on ign relay to supply power traced wires
			out and found back connection under passenger side floor mat to e-kill box, replaced wire from ign to e-kill box and tested
	1 1		good had power
	i i		good riad power
	1 1		-oil leak between power steering pump and front structure,
	i i		. removed pump and installed new gasket and re installed, tested good.
			. removed pump and installed new gasket and re installed, tested good.
Level A Service/repairs	3-14-22	27917	replace engine fan
20vol 71 Odi 1000 repullo			Replaced abs modulator valve on p/s # 2 axle
			Replaced driveline between first and second diff
	i I		Replaced output seal on first diff
	! !		Replaced input yoke on second diff
	1 1		Replaced input yoke on first diff
			Replaced input yoke u-joint on first diff
Replace front diff	2-9-22	27646	Replaced # 1 axle differential
retorque	1-26-22	27630	retorque as per tag number 244.
retorque			-replaced axle 2 p/s brakepot
a-service	1-25-22	27614	-completed a-service
			Injector/Jake wiring harness was leaking oil through the pins. Replaced the injector harness' and intermediate plate gasket.
			Cruise control could not be utilized from the crane operator cab. I checked the system with ET and checked electronics in the dash and the crane module beside the passenger seat. Everything seed to act as it should, the ecm was still seeing the
			cruise control and when the pto.
1	1 1		I installed a twist throttle in the crane can, deleting the foot pedal throttle control. I left the foot pedal and wiring ziptied in
Liter Matantau Innovana - Common Marable	1-15-22	27452	place in case the twist throttle fails, the pedal could be hooked back up.
Jake / injector harness.Remote throttle	1-13-22	21432	ps rear out rigger only retracting half way, go's in and out the first half fine, stops solid in the same place every time, the
	1 1		cylinder rod seems a little bent but this unit has had previous problems with the hydraulic valving, next day when it warmed
	1-12-22	27470	up operator was able to cycle and retract it fully, will need further diagnosis.
out rigger not retracting	1-12-22	21410	up operator was able to cycle and retract it range. Will need further diagnosis.
	1		- check the unit for no cab Heat i found bad connection at the heater blower motor it kept blowing the fuse. I clean the
Las and book	12-16-21	27396	connection and reinstalled a new fuse seems to be working good.
no cab heat	12-10-21	2,000	- tested the Webasto found it was air locked at the water pump got the coolant circulating and it seems to be working good.
	12-11-21	27331	- replaced both windshield wiper blades.
repair taillight	12-11-21	27001	Completed A Service check sheet
A Carrier	12-9-21	27325	Topped up Driver side front steer hub oil
A Service	12321	2,020	unit had complaints of boom creeping in.
1			-Set up crane and lifted coil injector off the ground and marked main boom cylinder and stabilizer rams, found boom was
			leaking down. Tightened up main boom counter balance valve 1/4 turn and tested again, unit still doing the same thing.
	1 !		paramag at the state of the sta
			Turned screw to 1/2 turn and let sit for an hour. unit no longer seeps down with main boom.
			Turned screw to 1/2 turn and let sit for an hour. unit no longer seeps down with main boom.
			Turned screw to 1/2 turn and let sit for an hour. unit no longer seeps down with main boom. -Replaced anti-2 reel on side of boom Doug's is going to zero it.

. -

			-Replace Crank Pulley. torque bolts to spec -replaced fan belt
			Postero compressor disaborar line and install subbourses consult analysis of compressor.
Replace Crank Pulley, PS Rear steer wheel seal, Crane Cab lower front window, Crane Cab window turn buttons and for winter front, Voltage and Coolant Gauges	11-18-21	27189	-Replace compressor discharge line and install rubber wrap around coolant line off compressor.
			 Repaired a oil leak on the power steering reservoir found a bad orb fitting on the bottom of the tank. check the engine fan for not cutting in found a bad connection at the solenoid for the air valve. checked the voltage gauge was reading 16 volt on the dash the battery voltage and the power supply to the gauge is only
power steering oil leak	11-14-21	27148	14 volts I have ordered a new volt gauge for the dash.
backup lights	10-20-21	26936	replaced missing backup light and grommet.
isotrov bov ropgie	9-27-21	26733	-LHS Jockey box aluminum ring had riveting break drilled out broken ones and installed self tappers into it all goodRHS jockey box latch mechanism had a broken bolt have a different nut crossed onto stud a couple threads for now untill I can source a new piece.
jockey box repair	9-24-21	26697	-Repaired a loos bearing plate on the back of the transmition checked transmission oil level was good unit got greased
transmission leak	3-24-21	20097	
Install missing reverse lamp, check lights	9-11-21	26607	-Installed missing reverse lamp on driver side at rear bumper. Check operation of reverse lamps and backup alarm, Ok -Check operation of rest of lights, OK
A2B issues	9-6-21	26542	Did a2b troubleshooting with crane smart tech, a2b was communicating but when the hook was raised it wouldn't trip out, tech concluded that the box was damaged and a replacement was needed, parts on order
retorque	8-23-21	26503	retorqued entire unit as per tag number 96.
255542			Completed CVIP
	1 1		Replaced drive axle shock
	1 1		Replaced bump stop
			Installed limiting chains on the drives
			Replaced all steer tires
CVIP	8-17-21	26479	Replaced all serp belt Bearings on the alternator belt
A service	8-5-21	26452	Completed "A" service
			Evacuated AC system and changed out compressor, then charged with nitrogen to look for leaks. No leaks found. Charged system with 3.25lbs of refrigerant and 3 oz of oil in system. At time of test temp was 3 degrees out of vents.
			Changed system with 3.25lbs of reinigerant and 3 oz of oil in system. At time of test temp was 3 degrees out of vents. Changed power steering hose that was sweating from the reservoir to manifold below the tank on the frame rail. Also
1	6-27-21	26323	changed coolant line from tank to water pump old one was leaking and needed changed out.
AC repairs	4-15-21	26081	Replaced/ rewire in new mirror for clearance lights/ mirror heat.
Rewire mirror	3-2-21	25921	Replaced damaged airbag on p.s axle #1, tied up loose wiring that was getting close to the driveshaft-
Damaged airbag	2-20-21	25854	Insplaced damaged alroad on p.s axie #1, tied up loose willing that was getting close to the divestialt-
Completed "B" Service	2-20-21	20004	Removed d/s rear outrigger cylinder. Replace extend and retract hoses. Replace cylinder up and down hoses. Replace
Replacements	2-6-21	25661	outrigger cylinder with spare from the yard. Confirm operation
neplacements			D/S rear outrigger would not retract, we figure issue lies within the electric over hydraulic valve bank. Removed extend/
D/S rear outrigger would not retract	2-1-21		retract hydraulic lines and ended up having to slowly push outrigger back in. Unit will be coming home
570 Total Guinggoi House Hot Fortube			All operations are working at this time. Swapped drivers retract cartridge with p/s extend check ohms of solenoids. 7.2,
Inspect d/s outrigger operation	1-25-21	25596	letting unit sit over night to retest.
mapor de designe per de la companya			D.S rear out rigger will not retract. ETECH verified electrical, valve seems to be operating correctly, suspect damaged
D.S rear out rigger will not retract	1-22-21	25589	cylinder. Unhooked lines and forced in
Completed "A" service.	1-19-21	25539	"A" service. Units needs a "B" service completed next time it's home
			high water temp light and buzzer comes on even though coolant temp is 200° Hooked up and monitored , no problem found,
High water temp light on	1-10-21	25457	turned off water temp buzzer in the dash.
Move crane power	12-29-20	25408	Move crane power to disconnect to prevent two batteries from going dead. Test and confirm repair.
Boom cylinder creeping down	11-17-20	25267	Boom cylinder creeping down, suspended load and tried to adjust counterbalance valve to hold. Boom still creeping down. Valve or piston seals have failed
			Verified complaint of boom creeping down. It is creeping down under load, no external leaks. Either the the boom cylinder lock valve is leaking down or the oil is bypassing the piston seals internally. Will need further diagnostics when it comes
Down accepting down	11-14-20	25257	home.
Boom creeping down	11-14-20	20201	promo.

.

			Belt squeal, removed belts and checked idler pulleys, replaced 2 6203 bearings in main belt idler pulley. Found alternator
Both coursed	11-7-20	25186	chirped. Sourced our new alternator from Mid Plains Diesel and installed, tested. All good, no squeal
Belt squeal	11-7-20	23100	Removed belt and cleaned pulleys and tested seemed ok. Later on acted up again. Will need clutch inspected further at
Pulleys acting up	10-9-20	25050	home
runeys acting up	10020	20000	T/S grinding in transmission, removed auxiliary section. Found worn clutch teeth on bull gear and syncros. Replaced bull
			gear, syncros & output shaft bearing, new seals and shimmed counter shafts. Road tested good. Replaced u joint @ 1st
T/S grinding in transmission, removed auxiliary section	8-16-20	25019	steady bearing
The grinding in transmission, formerod admirary addition			
Drive and check coolant temp, no issues. Grinds sometimes from H-L range. Went through tests and found 54 psi on low			
range line spec is 58-63. Changed regulator and no difference/ high range line tested good at 58psi. Charged A/C	8-2-20	25019	
			Completed CVIP repairs/ adjusted both 2nd steer springs twisted p/s 1st steer and 2nd drive wheel seals & shoes. 2nd & 3rd axle drums replaced, repaired a/c lines and charged. Fix coolant leak @ water pump. D/S air bag 1st drive axle. d/s 2nd steer shock mount broken & replaced. Replaced d/s upper rad mount bushings. 2nd drive diff plug looser and leaked-
Occupational OVID consider	8-1-20	25019	steer shock mount broken & replaced. Replaced as upper rad mount bushings. 2nd drive diff plug looser and leaked- ltightened.
Completed CVIP repairs	7-29-20	25019	ingmened.
Completed CVIP inspection	1-29-20	25019	
Complaint of no A/C	7-25-20	25014	Complaint of no A/C. Found high & low pressure lines were against turbo and burnt through, new lines needed, ordered. Also receiver dry, to be replaced at the same time. Also complaint of grinding between 4 & 5 gear test drove and could not replicate problem. Checked air filter on regulator on transmission. All seemed good. Replaced belt for AC compressor.
Replaced idler bearings that had failed and were squealing	6-12-20	24966	replicate problem. Onecked air litter on regulator on transmission. All seemed good. Replaced bet, for AC compressor.
Replaced fuler bearings that had rane and were squeating	0 12 20	24000	REPAIR P/S FOG LIGHT 19338HRS 214527KMS
REPAIR P/S FOG LIGHT 19338HRS 214527KMS REPLACED 3rd IN DRIVERS MARKER LIGHT	4-25-20	19338	REPLACED 3rd IN DRIVERS MARKER LIGHT
TIEL ARTH TOTAL EIGHT 13000 THE 21302 THE EIGES STATE STATE AND THE EIGES STATE			R&R DRIVERS FRONT STEER WHEEL SEAL - 19338HRS 214527KMS
			R&R P/S REAR STEER TOP SHOCK BOLT
R&R DRIVERS FRONT STEER WHEEL SEAL - 19338HRS 214527KMS R&R P/S REAR STEER TOP SHOCK BOLT RE	4-25-20	19338	REPLACED P/S REAR STEER TIRE
REPLACE AIR DRYER CARTRIDGE/PURGE VALVE - 19338HRS 214527KMS	4-25-20	19338	REPLACE AIR DRYER CARTRIDGE/PURGE VALVE - 19338HRS 214527KMS
A2B not communicating with crane smart head unit. Changed assigned channel to sensor for proper connection with head			A2B not communicating with crane smart head unit. Changed assigned channel to sensor for proper connection with head
unit. Tested good	3-10-20		unit. Tested good
Replaced failed 2 way radio. Tested good	3-8-20		Replaced failed 2 way radio. Tested good
LEVEL A - 24913HRS 39716KMS	3-8-20	24913	LEVEL A - 24913HRS 39716KMS
Start digging into fan not working in auto mode. Monitor all status's and sensors with computer. Sensors and switches seem to be operating normally. Coolant temp gauge in cab not accurate to computer reading – 24875HRS 39681KMS	3-1-20	24875	Start digging into fan not working in auto mode. Monitor all status's and sensors with computer. Sensors and switches seem to be operating normally. Coolant temp gauge in cab not accurate to computer reading. Gauge reads over 210f when computer reads 196f. Fan kicked in normally when ecm read 200f but gauge in cab showing around 220f. System is fine – 24875HRS 39681KMS
Order parts for failed A2B	2-23-20		Order parts for failed A2B
Verified complaint of engine fan not working. Got unit to 200* fan didn't kick in. Works fine in manual setting. Further diagnosis required. 24832HRS 39654KMS	2-23-20	24832	Verified complaint of engine fan not working. Got unit to 200° fan didn't kick in. Works fine in manual setting. Further diagnosis required. 24832HRS 39654KMS
Crane angle & cable reel alarm. Found dead battery in transmitter. Replaced & tested operation, OK	2-17-20		Crane angle & cable reel alarm. Found dead battery in transmitter. Replaced & tested operation, OK
Anti-2-Block not operating. Found defective A2B switch. New switch on order	2-17-20		Anti-2-Block not operating. Found defective A2B switch. New switch on order
Played with counter balance valve some more. Got it to where we had it booked and scoped all the way out for an hour straight and it did not scope in at all- 24742HRS 39274KMS	2-16-20	24742	Played with counter balance valve some more. Got it to where we had it booked and scoped all the way out for an hour straight and it did not scope in at all- 24742HRS 39274KMS
Boom scoped in during operation, adjusted locking valve set screw. Did not scope under our observation - 24645HRS 39055KMS	2-5-20	24645	Boom scoped in during operation, adjusted locking valve set screw. Did not scope under our observation - 24645HRS 39055KMS
A2B block alarm & angle signal being lost at times. Found A2B Aux 1 block alarm was a result of it being set to off. Must confirm if in use or not. Checked angle transducer signal & status, both good at time of inspection	2-2-20		A2B block alarm & angle signal being lost at times. Found A2B Aux 1 block alarm was a result of it being set to off. Must confirm if in use or not. Checked angle transducer signal & status, both good at time of inspection. Will need operator to run to monitor when problem occurs

•

Check unit for the boom creeping down, found that it is the main boom cylinder that is creeping, gone back to medicine hat			Check unit for the boom creeping down, found that it is the main boom cylinder that is creeping, gone back to medicine hat
for repairs - 24336HRS 38388KMS	12-1-19	24336	for repairs - 24336HRS 38388KMS
	j		REPLACE CABINET DOOR HANDLES - 24312HRS 38148KMS
	1 1		WITH NEW ONES
REPLACE CABINET DOOR HANDLES - 24312HRS 38148KMS	10-17-19	24312	MINOR MODIFICATIONS
RECOVER SEAT - SEWLINE	10-9-19		RECOVER SEAT - SEWLINE
			CHANGED TO BOOM IN/OUT AND SWING - HYDRACO
			MOVE BOOM EXTEND CONTROLS FROM FOOT PEDAL ON FLOOR TO JOYSTICK
			TRACE OUT PILOT LINES
	l i		WASH OFF VALVE
			UNHOOK FOOT VALVE AND REMOVE
			FAB FOOT VALVE PEDAL BLANK OFF PLATE, PAINT AND INSTALL
			UNHOOK AND REMOVE LINES (WINCH, FOOT PEDAL SUPPLY AND PILOT LINES)
			CAP OFF UNUSED PORTS ON CONTROL VALVE
			MOVE PILOT LINES TO BOOM EXTEND
			WASH OFF UNIT
			RUN UNIT TO VERIFY CORRECT JOYSTICK OPERATION-GOOD
			VERIFY SWING BRAKE PROPER AND HOLDING
	j !		MAKE AND INSTALL LABELS FOR JOYSTICK
	i i		TIE UP LINES AND ELECTRICAL
	1		RUN UP WITH CUSTOMER
CHANGED TO BOOM IN/OUT AND SWING - HYDRACO	9-30-19		RELEASE UNIT CUSTOMER
			10 YEAR CRANE INSP/REPAIRS - HYDRACO
	l I		CARRY OUT REPAIRS, ORDER NEW TRAVELING BLOCK AND PARTS
	1 1		INSTALL NEW WINCH MOUNT BOLT WITH STOVER LOCK NUT
	, 1		REPLACE PRESSURE LINE FROM LARGE PUMP
			REPAIR LEAK ON PTO
	i I		REPLACE MAIN BOOM LIFT CYLINDER LOAD HOLDING VALVE WITH NEW
	ł I		POLISH ALL OUTRIGGER SHAFT TO REMOVE PITTING TO CLEAN UP SHAFTS
			CARRY OUT WELDING REPAIRS TO BOOM SECTIONS AND HORSES HEAD
	Į I		REPAIR LEAK ON COOLER FITTING
			WRAP COOLER LINES WHERE THEY ARE RUBBING AT PICKER BASE
			REPAIR FAULTY PTO INDICATOR LIGHT
			CLEAN UP BATTERY POSTS
10 YEAR CRANE INSP/REPAIRS - HYDRACO	9-27-19		HAVE NDT CARRIED OUT ON BOOM REPAIRS AND NEW PINS AND BUSHING IRON HORSE HAD REPLACED
			we wired in the oil temp sensor and took outside for test, last thing to look at is volt gauge reading high (says were charging
we wired in the oil temp sensor and took outside for test, last thing to look at is volt gauge reading high (says were charging	9-22-19		at over 15 V but verified 13.8 V at batteries)
at over 15 V but verified 13.8 V at batteries)	2-22-12		calibrate the crane smart - T DILLMAN/D TIBBS
			ran boom in and out for derek tibbs so he can calibrate the crane smart.
Louis to the second T DULMAND TIPES	9-15-19		Engine oil temp gauge is fluttery, will diagnose issue more tomorrow
Calibrate the crane smart - T DILLMAN/D TIBBS TROUBLESHOOT ESPAR-REPLACED WITH WEBASTO HEATER - 24302HRS 38105KMS	9-11-19	24302	TROUBLESHOOT ESPAR-REPLACED WITH WEBASTO HEATER - 24302HRS 38105KMS
I HOUDLESHOUT ESPAR-REPLACED WITH WEDASTO FIRST 24302FIRS 30105NWS	9-11-19	24302	MEASURED CRANE CAB FOR WINDOW COVER - SEWLINE
MEASURED CRANE CAB FOR WINDOW COVER - SEWLINE	9-11-19	24302	LEVEL B - 24302HRS 381058KMS
LEVEL B - 24302HRS 381058KMS	9-11-19	24302	REPLACE A/C BELT - 24302HRS 381058KMS
REPLACE A/C BELT - 24302HRS 381058KMS	9-11-19	24302	INSTALL FIRE EXTINGUISHER/HAZARD ID KIT - 38106KMS
INSTALL FIRE EXTINGUISHER/HAZARD ID KIT - 38106KMS	9-9-19		TIGHTENED NUTS ON HYD COOLER - 38106KMS
TIGHTENED NUTS ON HYD COOLER - 38106KMS	9-9-19		TESTED AIR TO AIR SYSTEM/REPLACED BOOTS WORN DOWN TO FIBERS - 38106KMS
TESTED AIR TO AIR SYSTEM/REPLACED BOOTS WORN DOWN TO FIBERS - 38106KMS	9-9-19		REPLACE BURNT OUT BULBS IN OVER HEAD CONSOLE - 38106KMS
REPLACE BURNT OUT BULBS IN OVER HEAD CONSOLE - 38106KMS	9-9-19		REPLACE HOOD BUSHINGS - 38106KMS
REPLACE HOOD BUSHINGS - 38106KMS	9-9-19		REPLACE CRANE CAB WASHER FLUID HOSE - 38106KMS
REPLACE CRANE CAB WASHER FLUID HOSE - 38106KMS	ן ש-ש-וש		THE LACE OWNER OVER ANOTHER LEGIS HOSE - 30 DOMING

			REPLACE REAR MARKER LIGHTS/TAIL LIGHTS - 38106KMS
REPLACE REAR MARKER LIGHTS/TAIL LIGHTS - 38106KMS	9-9-19		AND HOUSINGS - RED ARC
REPLACE D/S REAR DRIVE AXLE AIR BAG - 38106KMS	9-9-19		REPLACE D/S REAR DRIVE AXLE AIR BAG - 38106KMS
REPLACE WHEEL SEALS FRONT AND REAR STEER AXLE D/S - 38106KMS	9-9-19		REPLACE WHEEL SEALS FRONT AND REAR STEER AXLE D/S - 38106KMS
REPLACE D/S STEP - 38106KMS	9-9-19		REPLACE D/S STEP - 38106KMS
REPLACE STEER STOPS ON REAR STEER AXLE - 38106KMS	9-9-19		REPLACE STEER STOPS ON REAR STEER AXLE - 38106KMS
REPLACE BRAKES AND DRUMS ON REAR AND MIDDLE DRIVE AXLE - 38106KMS	9-9-19		REPLACE BRAKES AND DRUMS ON REAR AND MIDDLE DRIVE AXLE - 38106KMS
			CLEANED UP DIESEL TANK ON CRANE CAB - 38106KMS
	İ		AND HOOKED UP FUEL LINES
CLEANED UP DIESEL TANK ON CRANE CAB - 38106KMS	9-9-19		REPLACED FILTER
REPLACED ALL MUDFLAPS - 38106KMS	9-9-19		REPLACED ALL MUDFLAPS - 38106KM
REPLACE KINGPIN ON D/S FRONT STEER AXLE W/BUSHINGS - 38106KMS	9-9-19		REPLACE KINGPIN ON D/S FRONT STEER AXLE WITH BUSHINGS - 38106KMS
INSTALL LICENSE PLATE LIGHT ON REAR OF UNIT - 38106KMS	9-9-19		INSTALL LICENSE PLATE LIGHT ON REAR OF UNIT - 38106KMS
REPLACED SHOCKS ON REAR STEER AXLE - 38106KMS	9-9-19		REPLACED SHOCKS ON REAR STEER AXLE - 38106KMS
INSTALL BATTERY DISCONNECT - 38106KMS	9-9-19		INSTALL BATTERY DISCONNECT - 38106KMS
			REPLACE BATTERIES - 38106KMS
REPLACE BATTERIES - 38106KMS	9-9-19		CLEANED UP CONNECTIONS
REPLACE DOOR LOCKS AND IGNITION - 24302HRS 38105KMS	9-6-19	24302	REPLACE DOOR LOCKS AND IGNITION - 24302HRS 38105KMS
REPLACED MESH COVER FOR FOG LIGHT - 24302HRS 38105KMS	9-6-19	24302	REPLACED MESH COVER FOR FOG LIGHT - 24302HRS 38105KMS
FILTERED HYD OIL PUT IN NEW FILTERS - 24302HRS 38105KMS	9-6-19	24302	FILTERED HYD OIL PUT IN NEW FILTERS - 24302HRS 38105KMS
ENGINE TEMP/TRANNY TEMP GAUGES REPLACED - 24302HRS 38105KMS	9-6-19	24302	ENGINE TEMP/TRANNY TEMP GAUGES REPLACED - 24302HRS 38105KMS
			REPAIR FAN LIGHT WITH NEW HUB SWITCH - 24302HRS 38105KMS
REPAIR FAN LIGHT WITH NEW HUB SWITCH - 24302HRS 38105KMS	9-6-19	24302	AND FIXED WIRES
REPLACE HOOD BUSHINGS	9-2-19		REPLACE HOOD BUSHINGS
MFG & INSTALL BEARING BRONZE IN PULLEYS	7-26-19		MFG & INSTALL BEARING BRONZE IN PULLEYS & MFG NEW PINS - RED ARC