

| Unit | Model     | Date      | Work Order Details                                                                                                                                                                                                                                 |
|------|-----------|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 7/2/2023  | Edge flip                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 7/2/2023  | Flip edges.                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 7/21/2023 | Took panels off. Found a piece of plastic impeding with the decelerator. Removed plastic plug.                                                                                                                                                     |
| 1700 | D71PXI-24 | 8/13/2023 | Had a AS10KM code. Injector overheating. Got shut down in the middle of a burn. Forced a burn on it.                                                                                                                                               |
| 1700 | D71PXI-24 | 8/15/2023 | Wait for unit to show up and replace busted track pads                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 8/22/2023 | Travel to unit and trouble shoot def injector high temp removed injector and it was plugged did a regen code did not go away had to get Tyler give a hand to figure out how to reset the code until is good to go                                  |
| 1700 | D71PXI-24 | 8/22/2023 | Removed injector, cleaned out ports. Re install. Do regen but code still on. Cleared code later, and sent to work. Wait for lubers to get pulled out. End of day crossover. Diagnostic test-95-f6-f6.                                              |
| 1700 | D71PXI-24 | 8/27/2023 | Replace busted dash                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 8/31/2023 | Pre shift inspections                                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 9/1/2023  | Replace busted track pads                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 9/2/2023  | Repair loose fire extinguisher and mount                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 9/9/2023  | Attend unit at 384 Inspect for headlamp switch push through behind dash. Re&Re dash cover secure switch with zip ties - interim repair. Order new switch. Job ongoing.                                                                             |
| 1700 | D71PXI-24 | 9/11/2023 | Attend unit at 384. Install new headlight switch. Job complete.                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 9/15/2023 | Troubleshoot no air condo. Found compressor failed. Ordered parts. Repair rh track frame carrier mount also                                                                                                                                        |
| 1700 | D71PXI-24 | 9/16/2023 | Unit has failed a/c compressor go back to hcl set up and remove compressor from 1698 drive back out to 1700 and remove the failed compressor and install used one pull vacuum on system and charge to 2.2lbs into system run unit ok send to work. |
| 1700 | D71PXI-24 | 9/22/2023 | Check blade angle cylinder bearings and order parts                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 9/23/2023 | Gouge/grind old skins off. Fit up new skins                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 9/23/2023 | Gouge off blade skins and fit new ones on                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 9/24/2023 | Completed welding on blade                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 9/25/2023 | Build up frog on bottom. Install cutting edges for mechanics( Jorge tightened)                                                                                                                                                                     |
| 1700 | D71PXI-24 | 10/3/2023 | Checked unit over and ordered parts to make repairs                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 10/4/2023 | Split the tracks and pulled them out                                                                                                                                                                                                               |

|      |           |            |                                                                                                                                                                                                                                                               |
|------|-----------|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 10/4/2023  | Crib up unit. Release tension. Split and pull out rails.                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 10/4/2023  | Replace mirror and adjust left door.                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 10/23/2023 | Position and wrap rails. Find zipper bolts. Clean mounting surfaces. Connect tracks. Left zipper was twisted and had to be beat straight.                                                                                                                     |
| 1700 | D71PXI-24 | 10/23/2023 | Install missing track pads                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 10/23/2023 | Get rails and pads moved to unit on pad. Get permit for track install. Wrap and install new rails                                                                                                                                                             |
| 1700 | D71PXI-24 | 10/24/2023 | Weld corks/trimmed grouser bars                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 10/24/2023 | Weld corks in place                                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 10/25/2023 | Repair leak on ripper hose                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 10/29/2023 | Remove cylinder, replace pins and bushings. Re install. Grease assy.                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 10/30/2023 | Flip edges                                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 10/30/2023 | Go out and verify edges being worn and needing change. Called back to inform supervisor. Needed stand plates brought out but they were being used. Had new plates made at yard and sent out. In that time 1709 went down for leak and 1700 needed to be taken |
| 1700 | D71PXI-24 | 10/31/2023 | Went and picked up the steel plates that where left behind                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 12/1/2023  | Go to unit for def codes. Nothing active when we showed up. Send unit back to work                                                                                                                                                                            |
| 1700 | D71PXI-24 | 12/1/2023  | Grab parts at laydown. Remove and replace edges.                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 12/1/2023  | Check out inactive faults. Faults for def heater relay. Ops is running dozer and codes inactive. End of shift.                                                                                                                                                |
| 1700 | D71PXI-24 | 12/1/2023  | Remove and replace cutting edges and hardware                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 12/5/2023  | Diagnose code. Was not active when i got to unit, only service hours needing reset.                                                                                                                                                                           |
| 1700 | D71PXI-24 | 12/11/2023 | Flip edges.                                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 12/11/2023 | Cutting edge                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 12/11/2023 | Started corking machine                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 12/12/2023 | Finish corking                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 12/15/2023 | Cut off corks and start to weld                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 12/16/2023 | Finish welding corks on one track                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 12/17/2023 | Cut corks and weld new ones one roll track and cut corks                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 12/18/2023 | Finish corking machine                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 12/24/2023 | Travel to yard, get edges, travel back and change                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 1/1/2024   | Inspect for leaks, found hose off def injector leaking. Drive to laydown to find new hose but had none in correct size. Grab barb union, drive back to unit and install.                                                                                      |

|      |           |           |                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|------|-----------|-----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 1/2/2024  | Grab corner bits and stands from yard. Travel to unit. Set up and flip edges. New hardware. Return stands and clean up                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 1/7/2024  | Drone to camp pad removed old cutting edges cleaned up blade surface. Found that cutting edges were already flipped once already. Drove back to hcl got edges and installed new edges and corner bits                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 1/10/2024 | Active code for def injector malfunction. Run def pump test and was at 900kpa right away. Remove cover and chip out def tank and pump. Remove lines and blow through with air. Outlet line frozen right into pump. Go get heater and put on def pump, attempt to run pump test after thawing but will not pressure up. Was unable to remove outlet line on pump side from barb fitting to blow through def injector line. Left heater on tank. |
| 1700 | D71PXI-24 | 1/16/2024 | Weld corks on tracks                                                                                                                                                                                                                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 1/17/2024 | Spin tracks, clean track pads and weld corks on                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 1/26/2024 | Replaced horn button. Reassembled cab. Put PANLES on machine and sent to work                                                                                                                                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 2/9/2024  | Split tracks. Put machine on dunnage. Wrapped up tracks. Tracks need to be tired up. Cleaned up at end of day.                                                                                                                                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 2/12/2024 | Tie up old tracks, move to shipping area. Re tie up 1 set as a track pin fell out.                                                                                                                                                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 2/22/2024 | Start disassembling under carriage                                                                                                                                                                                                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 2/22/2024 | Cleaned tar off undercarriage bolts on left side and removed all rollers. Removed sprockets and hardware. Disposed of scrap in bin.                                                                                                                                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 2/23/2024 | Work on under carriage                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 2/23/2024 | Remove broken bolts for bottom rollers from track frame                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 2/23/2024 | Tap out roller bolt holes in frame. Install top carrier rollers. Install front idlers. Install segments.                                                                                                                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 2/24/2024 | Finish all rollers, idlers & segments and hardware j                                                                                                                                                                                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 2/24/2024 | Install bottom rollers. Install new ripper teeth.                                                                                                                                                                                                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 3/11/2024 | Set and wrap tracks for day shift to assemble                                                                                                                                                                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 3/11/2024 | Install under carriage                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 3/12/2024 | Finish connecting/wrapping tracks. Get unit off blocks. Set track tension and clean up area. Park up.                                                                                                                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 4/3/2024  | Load corner bits and hardware and stands, locate unit/ figure out how to get there. Flip edge and replace corner bits.                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 4/9/2024  | Segments coming loose. Started to look for parts and organize but called off. Told to leave for days as per supervisor.                                                                                                                                                                                                                                                                                                                        |

|      |           |           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|------|-----------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 4/10/2024 | Check segments and found segments on left side loose, tighten nuts to move to yard to disassemble check over machine                                                                                                                                                                                                                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 4/11/2024 | Split left track remove segments clean segments,final drive flange,nuts and bolts inspect for cracks and damages and are ok clean all anti seize from nuts and bolts Install segments with red loc-tite as per Ron and Ethan torque all nuts to 450ft/lbs                                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 4/12/2024 | Look up parts and locations. Go to unit and found only 1/4" wear on cutting edge and corner bits. New is 4" from centre of bolt hole to edge. Currently at 3-3/4". Edges not required                                                                                                                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 4/12/2024 | Assemble left track after removing all segments and bolts and inspecting because they were loose cleaned all surfaces properly and assembled with red loc-tite and torqued to 450 ft/lbs as per supervisor Right side Ron David would not let me do it properly he said to remove nuts use red loc-tite and torque to 450 ft/lbs so that is all that was done on the right side segments would not let me disassemble to clean properly and inspect properly Note: his exact words were he does not give a f??k |
| 1700 | D71PXI-24 | 4/14/2024 | Drove to unit, operator said it worked fine, and was no issue. Probably operator error. Drove back to laydown.                                                                                                                                                                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 4/15/2024 | 6692 hr inspect segments make sure still tight, inspect cutting edge as per supervisor.                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 4/18/2024 | 6724hr - pull out broken bolts. Steal 1 hold plate from 1698. Drive back out amd install.                                                                                                                                                                                                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 4/21/2024 | Bring hardware for segments out to hcl job                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 4/21/2024 | Went to unit for LO1 code. Found undercarriage is coming loose on machine. Remove and clean up RH side segments and reinstalled with old hardware (as per supervisor) so unit can come back to yard. Lots of components on undercarriage loose. Lockout. All hardware should be replaced and surfaces cleaned up.                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 4/24/2024 | Bring machine to undercarriage pad. Split LH track and inspect for why it came loose. Bolts were extremely loose. Clean up and inspect.                                                                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 4/24/2024 | Remove broken bolts from missing carrier roller                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 4/26/2024 | Put machine on blocks. Split and pull tracks. Start stripping undercarriage.                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 4/28/2024 | Clean up segments/final. Finals surfaces have some damage from segments coming loose. Reuse hardware as per supervisor and torque to 450ft/lbs with red loctite. Drop rollers on LH side and clean up rollers and frame. Bolts loose. Reinstalled LH side rollers and torque to 315ft/lbs as per service manual. Again reused hardware as per supervisor. Drop rollers on RH start install prep.                                                                                                                |
| 1700 | D71PXI-24 | 4/29/2024 | Install blade angle cylinder. Waiting for hardware to finish installing the sensor and guard.                                                                                                                                                                                                                                                                                                                                                                                                                   |

|      |           |           |                                                                                                                                                                                                                                                                                                                                                                                              |
|------|-----------|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 4/29/2024 | Prep rollers and surfaces for RH side. Install rollers and torque to 315ft/lbs. Reused hardware as per supervisor. Holes and track frame damaged from the rollers that fell off. Welder cleaned them up as best as possible. Torque carriers 400ft/lbs. Need a second person and permit to pull tracks on now.                                                                               |
| 1700 | D71PXI-24 | 4/30/2024 | Wait for permit. Pull both tracks onto machine. Clean master link and pad surfaces. Torque master bolts to 220ft/lbs + 180 degrees as per service manual. LH side track master link has damaged threads from track coming loose. Got it to spec torque but the holes are in bad condition. Get machine off blocks and clean up area. Still missing hardware for blade angle cylinder sensor. |
| 1700 | D71PXI-24 | 4/30/2024 | Wrap tracks. Check over machine. Install blade angle sensor and guard.                                                                                                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 5/3/2024  | Put stand and plate underneath blade and start removing edges                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 5/4/2024  | Cut off reamaining bolts for edge, pick new edges and hardware clean up area                                                                                                                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 5/4/2024  | Install edges tighten plow bolts 3/4" impact. Remove off stand cleanup.                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 5/4/2024  | Help installing edges and clean up area                                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 5/8/2024  | Operator compliant of rides rough. Find front cab mounts leaked out viscous fluid, rear cab mounts broken. C frame pins and bushings worn bad approx 1/4"-3/8" play. Order parts                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 5/10/2024 | Position machine to remove sight glass for unit 1697. 1700 is down for cab mounts. Plug hole with orb plug for now. Parts ordered to replace.                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 5/20/2024 | Reset injector overheat counter. Repair park brake switch wiring.                                                                                                                                                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 5/21/2024 | Hcl                                                                                                                                                                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 5/21/2024 | Find unit on HCL job. LH track loose. Adjuster backed out. Clear out grease. Tighten track adjuster valve. Tension tracks. Notify to watch for rock build up in rails.                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 5/31/2024 | Look at blade cylinder pin retainers missing and loose LH rear bottom roller. This roller fell off previously and trackframe was damaged. Surface was ground to be flush. Order new bolts. Check over rest of rollers and segments, nothing else loose at this time.                                                                                                                         |
| 1700 | D71PXI-24 | 5/31/2024 | Grab edges from HCL and replace at new laydown job.                                                                                                                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 6/1/2024  | Extract broken bolts, clean mating surface and tap holes. Install roller with new hardware and red loctite                                                                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 6/2/2024  | Repair handrail and install                                                                                                                                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 6/8/2024  | New HCL                                                                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 6/8/2024  | 500 hrs service                                                                                                                                                                                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 6/8/2024  | Service 500hrs                                                                                                                                                                                                                                                                                                                                                                               |

|      |           |           |                                                                                                                                                                                                                                                                                                 |
|------|-----------|-----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 6/22/2024 | Install belt fire up and walk to new yard. Drive panels over with service truck and put on track                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 6/25/2024 | Pick up edges and stand bring down to unit. Drop edges off at unit and got pulled away to a downed excavator. Come back to unit and change edges.                                                                                                                                               |
| 1700 | D71PXI-24 | 6/25/2024 | Load up edges and go change out full set.                                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 7/11/2024 | R&R a/c compressor. Vacuum system, add 2oz oil. Charge with 2.5lbs refrigerant. Duct temp good until high side hose blew. Clean up area.                                                                                                                                                        |
| 1700 | D71PXI-24 | 7/20/2024 | Change out one a/c hose off compressor. Other hose was incorrect. Change dryer and charge 2.65 lbs. Test system, blowing 9c. Put return hose in seacan.                                                                                                                                         |
| 1700 | D71PXI-24 | 7/29/2024 | Travel to pinto for L03 code. Unit in use code inactive. Check logged codes has intermittent def injector overheat. Send back to work.                                                                                                                                                          |
| 1700 | D71PXI-24 | 8/1/2024  | Drive to unit. Set up work area. Lock out machine. Take sample of finals and engine oil. Change final oil, engine oil and filter. Change air filters. Check over unit. Tidy up work area. Drive to laydown.                                                                                     |
| 1700 | D71PXI-24 | 8/1/2024  | Drive to unit. Set up work area. Lock out machine. Take sample of finals and engine oil. Change final oil, engine oil and filter. Change air filters. Check over unit. Tidy up work area. Drive to laydown.                                                                                     |
| 1700 | D71PXI-24 | 8/7/2024  | No codes active. Checked logged codes had brake pressure sensor open. Back probed wiring. Had proper 5v and signal was within spec. Push connector to lock properly on sensor. Gave to ops.                                                                                                     |
| 1700 | D71PXI-24 | 8/7/2024  | Head to unit and weld up broken handrail, install back on machine                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 8/8/2024  | Drive to pinto. Line to tilt cyl leaking. Pull off clamps and panels. Pull line, take back to laydown and build a new one. Drive back out and re install components. Top up hyd oil. Went to start unit but would just click. Boost batteries but still nothing. Starter failed, ordered parts. |
| 1700 | D71PXI-24 | 8/9/2024  | Grabbed parts, drove down to machine, rnnr starter, machine still will not run, batteries draw down to 15v starting, draw down from 24V - 20v with key on, suspect batteries are dead or failed , boosted machine to get it running, sent unit to work                                          |
| 1700 | D71PXI-24 | 8/10/2024 | Drive to unit, boost batteries.                                                                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 8/10/2024 | Swap batteries test unit good to go                                                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 8/11/2024 | Diagnose smoke coming out of engine bay. Ac compressor throwing sparks when clutch engaged. Order parts.                                                                                                                                                                                        |

|      |           |           |                                                                                                                                                                                                                                                                                                                       |
|------|-----------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 8/11/2024 | Complaint of machine overheating, drove out to machine, blew out coolers, sent unit to work                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 8/14/2024 | Callout for overheat on 1700 at fahp                                                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 8/15/2024 | Incident. Wait for unit to come into yard. Diagnose coolant leak, found hose damaged at a clamp. Start pulling components off lid to remove for valve set. Got pulled off.                                                                                                                                            |
| 1700 | D71PXI-24 | 8/17/2024 | Set up to pull hood. Follow through and finish disconnecting hood. Lift and set aside. Rig up dpf/scr assembly. Disconnect harness and piping. Lift and set aside. Disconnect wiring harness and clean off valve cover area. Look up and order accessory drive belt. Clean up and cover ports.                        |
| 1700 | D71PXI-24 | 8/18/2024 | Go through pm inspection sheet. Find deficiencies and document                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 8/18/2024 | Pull valve cover and check valve train. Most within 0.002". Couple 0.003 out of spec loose. Check rocker arms, bridges, push rods and slippers. No abnormal wear found. Torque rockers arms to 62nm. Jam nuts to 25nm. Reassemble. Lift and install dpf/scr assembly.                                                 |
| 1700 | D71PXI-24 | 8/18/2024 | Fill cooling system. Found hose behind cylinder head split. Look up and order hose.                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 8/19/2024 | Fill out paperwork. Look up and order parts. Search in seacanns for stocked parts. Clean up and install hood to walk over to wash bay.                                                                                                                                                                                |
| 1700 | D71PXI-24 | 8/20/2024 | Gouge out crack on right side track frame and start welding                                                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 8/21/2024 | Finish welding cracks on track frames, remove two track pads to access 1 crack                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 8/21/2024 | Gouge off 1 corner skins and centre with test holes                                                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 8/21/2024 | Pick kit. Drive to unit. Set up work area. Change all filters. Change all oils. Fill fluids. Test run machine. Left machine for welder to continue working on it.                                                                                                                                                     |
| 1700 | D71PXI-24 | 8/21/2024 | Ran unit for Mike to line up final drives                                                                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 8/21/2024 | Assist welder                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 8/22/2024 | Finish gouging off skins, grind clean fit up and weld on new ones                                                                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 8/31/2024 | Drove back to yard, set up job, removed engine hood , disconnected and removed all related covers and wiring                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 8/31/2024 | Replaced left engine bay door latch Replaced def door latch. Replaced horn. Replaced both nox sensors                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 9/1/2024  | Remove exhaust pipe from dpf to turbo, remove coolant pipe and remove broken thermostat, install new thermostat, reinstall coolant pipe, fill coolant system, install hood and hook up, install electrical connections, install covers, run unit up to temp and check for leaks. Install all panels and clean up area |
| 1700 | D71PXI-24 | 9/1/2024  | Install misc parts and repair items on list.                                                                                                                                                                                                                                                                          |

|      |           |            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
|------|-----------|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 9/1/2024   | Installed front center link for blade                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 9/1/2024   | Helped install hood. Other misc assembly.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 9/2/2024   | Changed hst filter                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 9/2/2024   | Changed hst oil filter                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 9/19/2024  | Left side rear roller fell off machine, drove out to unit, got stuck, checked over unit with forman, unit is in soft sand will need blocking to remove roller to walk machine to a suitable work area, got pulled out, drove back to yard, end of night crossed over to days                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 9/21/2024  | Remove roller from track. Walk machine over to accessible spot. New roller and hardware at machine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 9/21/2024  | Morning safety meeting, drive out to machine with pick up, set up job, extract roller from under machine walk unit out to suitable work area                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 9/22/2024  | Load up blocking and drive to ned. Block unit up so welder can extract broken roller bolts. Once bolts removed replaced left rear roller. Buffed mating surfaces, installed new hardware with red loctite and torqued to spec at 300 ft lbs. waited for welder to weld on roller as this is a reoccurring issue. Load up blocks and return to yard                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 9/22/2024  | Extract broken roller bolts, help mechanic install roller                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 10/15/2024 | Start welding corks                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 10/16/2024 | Finish welding ice lugs                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 10/17/2024 | 250hr service with engine oil and filter changed                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 10/17/2024 | Change engine and left final oil, change outer air filter, get samples                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 10/17/2024 | Service due to 250hrs With changed eng.oil                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 10/19/2024 | Crank case over pressure codes L01 and l03 ca555 and 556. Noticed pressure sensor not fully engaged rectified. Changed out crank case filter. Cleaned housing and check valve ran unit. Only lo1 code came back cleared electrical abnormalities record. ops wanted unit packed up and left location. Lo3 code came back 1/2 hour later Checked turbo inlet and outlet. Checked cartridge ok. Removed valve cover outlet block and cleaned. Tested 5v reference voltage and ground at sensor plug ok. Disconnected 1/2" line between sump and valve cover voltage and pressure drops low. Hook back up and rev in h mode and alarm sounds 5.2 kpa pressure 3.844volts. Came back to yard and grabbed whole kccv assembly from 1712. Installed on unit no change. Unit will push oil up dipstick tube when revved up. Preformed cylinder cut out all cylinders drop the same rpm and increase fuel demand the same. All cylinders sound the same when cut.out. End of day left lock on unit and rh side panels off |

|      |           |            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|------|-----------|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 10/20/2024 | Diag high crankcase pressure.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 10/21/2024 | Continue diag for high crankcase pressure find intake fitting plugged with soot/ carbon. Clean and reinstall test- good. Install panels and swap out leaking oil pipe.                                                                                                                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 10/22/2024 | Drive to fhap. Check codes CA1682 and CA 3559. Pump prime and voltage codes. Visually check components. Removed tank vent filter cleaned and cleared vent tube crystal build up. Codes set during move from yard to site warm up up cycle key, preform pump prime test pressure came to 905kpa, codes cleared. Ran unit up to operational temperature, unit started its own regen. Let it run cycle and cool exhaust temp to 160*c and shut down. Cleared electrical abnormalities record packed up and left |
| 1700 | D71PXI-24 | 11/3/2024  | Pick parts. Load up stand and edges. Drove down to fhap and told to come back at break. Drive back to lay down. Go back to fhap at 10 o'clock break. Replace broken middle edge and corner bits, flip the rest. Put unused parts back on edge racks                                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 11/10/2024 | Drive to location , set up work area, service, clean up and drive back to yard throw the garbage and back fill                                                                                                                                                                                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 11/10/2024 | Pick kit. Drive to unit. Set up work area. Allow unit to warm up. Complete 500 hour service. Check and adjust all levels. Test unit. Call unit up. Drive back to yard                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 11/22/2024 | Diag low power at fhap and install fuel filters.                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 11/23/2024 | CA281 active, repair fuel leak. Repair wiring on fuel bowl so code for water in fuel goes away. Test machine and send to work.                                                                                                                                                                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 11/24/2024 | Complaint of bogging down still. Run unit and could not create symptom. Look in fuel tank and there is some small pieces of ice. Add meltdown. Remove fuel/water separator and add meltdown there as well. Run machine and still no symptoms. Go back later in the day and run again, acted up momentarily.                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 11/27/2024 | Fhap 250hr service with engine oil changed                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 11/27/2024 | Change eng oil. Change inner and outer cab filter. Change oil filter and inspect the machine. Get eng, and both finals sample.                                                                                                                                                                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 11/29/2024 | Fund throwing brake solenoid code, not a tice couldn't get to come active. Need to run more for it to develop so can t/s                                                                                                                                                                                                                                                                                                                                                                                     |

|      |           |            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
|------|-----------|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 12/2/2024  | Drive to fhap. Get unit running and warm up. Operator presence switch intermittent both on and off. Unplugged switch and l03 code pops up. Plug back in and has trouble reading. View current on monitor not consistent. Ordered new switch. Drive unit back and forth to duplicate brake issues once it started was long process of getting back to work area. Removed floor and started testing with DW7EKA CODE found faulty solenoid harness many chafing bare and broken wires ordered new harness. Both rear rollers have broken bolts. Made parts list and let supervisor know |
| 1700 | D71PXI-24 | 12/3/2024  | Removed solenoid harness from 1698.removed some roller bolts. Drive to fhap install harness. Removed both rear rollers. Plug in block heater and get unit going. Test drove for 20 minutes no codes or park brake issues. Unit locked out. And blocked up                                                                                                                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 12/4/2024  | Helped welder with rear roller repairs                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 12/4/2024  | Drive out to fhap, unit wasn't blocked up high enough to remove rollers, had blocking brought down, blocked unit up, removed rollers, extracted broken roller bolts, cleaned up track frame mating surface, assisted mechanic to install rollers, welded rollers to frame because mating surfaces are damaged and rollers keep falling off                                                                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 12/10/2024 | Complaints of intermittent code for def injector over heat. Check out unit and send back to work. Didn't act up for the rest of shift.                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 12/17/2024 | Get eng, hyd, both finals samples. Change eng oil fuel separator, fuel , hyd, inner, outer air. Change inner cab filter. Change eng and both finals oil. Inspect the machine                                                                                                                                                                                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 12/17/2024 | Fhap 1000hr service                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 1/1/2025   | Completed 250 hr service on unit.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 1/1/2025   | 250hr service                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 1/7/2025   | Look up parts and pull from inventory. Unable to locate rh corner bit. Stole from down unit 1698. Drive to fhap. Removed old edges, buffed off mating surfaces. Installed new edges with new hardware. Torqued to 375 ft/lbs. note old edges were worn well into frog. Washers on corner bits don't have enough frog left to make full contact. Took photos and sent to supervisor                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 1/8/2025   | Clean tracks and weld ice lugs                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 1/9/2025   | Finish corking unit                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 1/13/2025  | Check over machine for exhaust leak. Clamp broken on turbo. Replace sensor on fuel bowl.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 1/14/2025  | Removed engine panels to access turbo and exhaust lines and pipes, checked for damage to exhaust system, made up parts list, removed intake piping from air filter, housing removed, exhaust piping, and various lines cover all engine parts.                                                                                                                                                                                                                                                                                                                                        |

|      |           |           |                                                                                                                                                                                                                                            |
|------|-----------|-----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 1/14/2025 | Remove battery protective cover, ordered new cover cleaned out battery box, removed old batteries replaced cable clamps cleaned cable ends, installed new batteries, and clamped down batteries                                            |
| 1700 | D71PXI-24 | 1/15/2025 | Drained, coolant, removed oil, lines, and coolant lines from turbo, heat up turbo mounting bolts and removed turbo, covered up all engine, parts, and turbo parts, cleaned up work area.                                                   |
| 1700 | D71PXI-24 | 1/19/2025 | Round up parts for turbo install, prep parts                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 1/19/2025 | Installed battery cable adaptors                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 1/20/2025 | Assist mechanic with starting unit after reassembly                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 1/20/2025 | Attempt to start machine set up heaters and booster connect battery charger charge attempt to start multiple times start up engine ran engine checked for leaks installed all panels                                                       |
| 1700 | D71PXI-24 | 1/21/2025 | Extract broken bolts from cylinder, chase holes, install new cylinder guard onto cylinder                                                                                                                                                  |
| 1700 | D71PXI-24 | 2/10/2025 | Set heater up on unit. Attempt start. Needs boost. Boost unit. Unit starts                                                                                                                                                                 |
| 1700 | D71PXI-24 | 2/14/2025 | Get all the oil samples. Change eng and both finals oil. Change inner outer cab, eng , hyd, fuel,fuel separator filters                                                                                                                    |
| 1700 | D71PXI-24 | 2/14/2025 | Np2 500hr service                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 2/20/2025 | Tighten tracks                                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 2/20/2025 | Went to unit, inspected sprockets, RH final drive missing one segment, went to yard, got parts, went back cleaned up final drive, installed new segment with hardware, torqued all sprocket bolts to spec 600 ft/lbs, cleaned up work area |
| 1700 | D71PXI-24 | 2/20/2025 | While repairing undercarriage, found engine had active code, checked codes, had active low crank case pressure code, troubleshot, found bad connection at sensor, repaired, checked and cleared code, tested, cleaned up work area         |
| 1700 | D71PXI-24 | 2/26/2025 | Find corners bits. Pick bolts drive to unit flip edges replaced hardware torqued to 375 ft lbs                                                                                                                                             |
| 1700 | D71PXI-24 | 3/4/2025  | Drive to location, set up work area, sample the finals, changed the engine oil and filter Changed fuel filter Clean up Drive back                                                                                                          |
| 1700 | D71PXI-24 | 3/4/2025  | Pick filters. Drive to unit. Complete service to unit.                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 3/7/2025  | Complaint of overheat. Get unit check coolant level and was good. No signs of leaks. Run machine and heat not working and no circulation in rad. Check water pump and is cowbelled. Order parts                                            |
| 1700 | D71PXI-24 | 3/8/2025  | Get engine serial number look up parts for water pump                                                                                                                                                                                      |

|      |           |           |                                                                                                                                                                                                                                                                                                                                                                 |
|------|-----------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 3/8/2025  | Remove pan to access coolant drain, but it's completely packed off. Chip out frozen material. Drain coolant. Remove water pump and impeller had broken clean off. No other chipped pieces missing from retrieved damaged pump. Install pump and reinstall belt/tensioner. Fill coolant and get machine running and check for leaks.                             |
| 1700 | D71PXI-24 | 3/9/2025  | Morning meeting and paperwork. Drive to location. Install missing carrier roller. Get unit running. Work air lock from cooling system. Used up coolant from service truck. Lube truck not able to get to unit. Drive to yard refill jugs. Top up coolant run up to temperature. Leave running for ops.                                                          |
| 1700 | D71PXI-24 | 3/17/2025 | Went to unit, set up, checked seat operation, removed garbage from behind seat, checked wires, all good, seat works, cleaned up                                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 3/19/2025 | Start machine and run. Coolant temp gets to 100 degrees for me. Operator claims it gets to the red. I could not get machine to overheat. Coolant lines going to engine are not hot. Coolant temp sensor reads 100 degrees, hit coolant lines, block and water pump with temp gun and engine runs around 70 degrees. Ordered thermostat and coolant temp sensor. |
| 1700 | D71PXI-24 | 3/21/2025 | Thermostat on order. Remove thermostat and inspect- some scoring suspect jamming, drill 1/8 hole in thermostat, install, test- ok.                                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 3/21/2025 | Remove panels, Remove exhaust, remove coolant piping and thermostat pipe. Tested thermostat, drilled holes in thermostat for temp repair. Installed components.                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 3/21/2025 | Look over seat/undercarriage and overheat complaints.                                                                                                                                                                                                                                                                                                           |
| 1700 | D71PXI-24 | 3/22/2025 | Drive out to unit, jack track up, cut top of carrier pedestal off. Unit was run with no carrier roller so a new pedestal is needed, called for fuel and lube to come tighten the track, returned to laydown                                                                                                                                                     |
| 1700 | D71PXI-24 | 3/22/2025 | Travel to machine, inspect pin walking out. Push pin back in and replace bolts for retainer.                                                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 3/23/2025 | Check edge                                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 3/29/2025 | Drive to fhap. Check coolant level. Blow out rad as best as possible without pulling belly pans. Look up work history. Found thermostat on order. Talked to operator only overheating when working hard or fast. Then cools quickly. Let Forman know.                                                                                                           |
| 1700 | D71PXI-24 | 3/30/2025 | Morning meeting. Drive to fhap install thermostat old thermostat was previously removed. Figure out where parts go. Wait for lube team to fill coolant. Rain up to temp check for leaks. Unit up                                                                                                                                                                |
| 1700 | D71PXI-24 | 3/30/2025 | Find unit at FHAP. Get machine moved to suitable area for repairs. Gain access and remove thermostat. New parts were incorrect. Source correct parts and order. Tidy job and prepair for night shift to install.                                                                                                                                                |

|      |           |           |                                                                                                                                                                                                                                |
|------|-----------|-----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 4/16/2025 | Complete service to unit.                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 4/16/2025 | Drive to location, helped the boys with the service, filled all the oils , grease and drive back                                                                                                                               |
| 1700 | D71PXI-24 | 4/16/2025 | Assisted services                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 4/19/2025 | Called to unit, checked blade, found blade tilt cylinder outside pin snapped, half the pin still in bore holding cylinder in, removed guards, tried getting pin out, jammed in bushing, will order parts, cleaned up work area |
| 1700 | D71PXI-24 | 4/20/2025 | Set up and remove busted pin from blade and split rh track for carrier roller pedestal replacement                                                                                                                             |
| 1700 | D71PXI-24 | 4/20/2025 | Fired unit up, brought to wash bay to have track frame washed out and angle cylinder washed, brought to undercarriage pad                                                                                                      |
| 1700 | D71PXI-24 | 4/21/2025 | Made reference points off of old pedestal, gouged off broken pedestal, found cracks in track frame around the pedestal, gouged out cracks, ground everything clean                                                             |
| 1700 | D71PXI-24 | 4/22/2025 | Drive to unit set up work area inspect c-frame and ripper look up complete parts list for all needed pin and bushings                                                                                                          |
| 1700 | D71PXI-24 | 4/22/2025 | Found some more cracks in the track frame, gouged out and ground clean, welded cracks in frame and ground flush, fit up new carrier pedestal and started welding                                                               |
| 1700 | D71PXI-24 | 4/23/2025 | Finish welding out cracks and pedestal, install carrier roller, bolts still need to be torqued                                                                                                                                 |
| 1700 | D71PXI-24 | 4/24/2025 | Install pin and retainer                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 4/24/2025 | Install blade tilt cylinder pin, tighten carrier roller. Look for hardware to install track master pad.                                                                                                                        |
| 1700 | D71PXI-24 | 4/26/2025 | Set up at unit, performed 3000 hr inspection, made parts and repair list, parked unit, cleaned up work area                                                                                                                    |
| 1700 | D71PXI-24 | 4/26/2025 | Went to unit, set up, assembled RH track, installed new master link bolts, set track tension, cleaned up work area                                                                                                             |
| 1700 | D71PXI-24 | 4/27/2025 | Inspect cutting edge- good                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 4/27/2025 | Lift blade, inspect cutting edge, find that edge is only wore down 3/4 of an inch.                                                                                                                                             |
| 1700 | D71PXI-24 | 4/28/2025 | Demob unit                                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 5/1/2025  | Strip unit to be washed                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 5/2/2025  | Set up work area, walk machine and shop and remove blade off seaframe. I started prepping, for seaframe to be removed off unit                                                                                                 |

|      |           |           |                                                                                                                                                                                                                                                                                        |
|------|-----------|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 5/3/2025  | Started moving lines off cylinders, capping off the lines. Removing grease lines then removed my angle cylinders. Then try to remove the pins for the c-frame. They were seized try heating up, did not remove. So then had to Torch the pin Then finally got one side to stare moving |
| 1700 | D71PXI-24 | 5/4/2025  | cut and press out seized pins                                                                                                                                                                                                                                                          |
| 1700 | D71PXI-24 | 5/4/2025  | Remove c frame and took it to the steam Bay So ends could be line board                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 5/7/2025  | Inspect rails for wear. Repair limit 206.5mm 80% measured at 205-206. 2 stretched links on LH rails. Look through rollers. Research and compare plus vs conventional. Determined that needs full set of undercarriage with rails.                                                      |
| 1700 | D71PXI-24 | 5/10/2025 | Wrap up blade hoses. Bring unit into bay with steel plate. Put unit on stands and remove rails.                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 5/10/2025 | Start 4000hr PM. Disconnect hood to access valve cover.                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 5/11/2025 | Helped Travis remove the hood and DPF filter so he could do the valve set on the unit                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 5/11/2025 | Clean off debris. Use jack and check hardware pins. Outer bearings worn but still usable. Remove panels.                                                                                                                                                                               |
| 1700 | D71PXI-24 | 5/11/2025 | Remove hood and DPF. Clean off Engine and remove valve cover. Check and set valves. #1 Intake and exhaust larger clearance than spec. Adjusted from 0.019 to 0.012" on intake. Replace valve cover. Wait for new seals before reassembly.                                              |
| 1700 | D71PXI-24 | 5/12/2025 | Remove bottom rollers and carrier rollers. Clean area. Look for new parts.                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 5/12/2025 | Cleaning up all the grease and polishing the C-frame                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 5/12/2025 | Brought c frame over to Walding Bay to have the ends line board. And drop the cylinders antonion assembly to the steam bay to be washed and brought it back to the shop                                                                                                                |
| 1700 | D71PXI-24 | 5/13/2025 | Line bore c frame                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 5/13/2025 | Fabricating centre measure bar for line bore set up and build up on faces of bores                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 5/13/2025 | Replace valve cover gasket. Install dpf and hood. Start and run unit. Replace Blade control lever. Replace park brake switch. Need to calibrate once blade is reinstalled. Remove panels and clean out belly pans. Shovel out dirt and debris from unit.                               |
| 1700 | D71PXI-24 | 5/14/2025 | Remove front idlers. Clean up area.                                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 5/14/2025 | Finish building up faces make reference points and start building up bores                                                                                                                                                                                                             |
| 1700 | D71PXI-24 | 5/14/2025 | Remove all the guards from around the final drives and clean all the dirt from around them and clean out all the rocks plus clean all the rest of the dirt from up in the stump pans to inspect hoses                                                                                  |

|      |           |           |                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
|------|-----------|-----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 5/14/2025 | Removed broken bolts for the bottom track rollers plus tapped out all the holes then removed the idlers                                                                                                                                                                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 5/14/2025 | Finish PM checklist. Look up parts for techs                                                                                                                                                                                                                                                                                                                                                                                                                |
| 1700 | D71PXI-24 | 5/14/2025 | Clean and tap frame holes inspected for cracks remove guards off the side of frames cleaned up all the dirt and rocks inspected hoses going to final drives, they had some damage. So I started removing the dirt and cleaning up underneath of unit to further inspect hoses and any other damage noticed, the final drives feed lines had damage and the crims. We're pretty much wore through from the sand so got parts order up and clean up work area |
| 1700 | D71PXI-24 | 5/15/2025 | Helped welder set up linebore and showed how to operate different system                                                                                                                                                                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 5/15/2025 | Finish welding bores and set up line bore and starting cutting bores                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 5/15/2025 | Clean off bottom rollers. Clean off track frame. Lift and install. Torque new hardware to 300 ft. Lbs. Clean up excess parts and put all on one pallet. Clean up area                                                                                                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 5/15/2025 | Cut material for slides. Cut off old slides, welded on new.                                                                                                                                                                                                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 5/15/2025 | Cleaned off where bottom rollers mount cleaned paint off the rollers and mounted them to the unit and torqued them to 300 ft/lb spec                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 5/16/2025 | Cutting bores                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 1700 | D71PXI-24 | 5/16/2025 | Had to do some grinding after the welder installed the wear plates on the track frame on the right side to get the idler to fit plus remove the yoke from the right side track tensioner so the new bushing and seal can be installed when it gets in clean up at the end of the day                                                                                                                                                                        |
| 1700 | D71PXI-24 | 5/16/2025 | Engine service after valve set                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 5/16/2025 | Install LH idler. Torque to 375 ft lbs. Push idler in. Idler gets stuck on built up track frame. Press out and grind down frame. Lift and test fit RH idler. Idler slides freely. Clean up tools and area.                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 5/17/2025 | Straightened up the bent panels installed panels on the hood and the sides of the engine compartment                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 5/17/2025 | Pressed bushings. Broke down and moved c frame                                                                                                                                                                                                                                                                                                                                                                                                              |
| 1700 | D71PXI-24 | 5/17/2025 | Tried to get the pin to take grease with the porta power it would not take had 7500 PSI on it for a bit removed pin it was hard to get out cleaned all the dirt out of the grease holes on the pin cleaned up bushing and bores installed pin and it takes grease know                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 5/17/2025 | Finish cutting bores tear down set up grind tacks and press in bushings                                                                                                                                                                                                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 5/21/2025 | Clean and inspected right side tensioner notice the hole's not lining up for the shaft wait to see if they have a new one to swap out with                                                                                                                                                                                                                                                                                                                  |

|      |           |           |                                                                                                                                                                                                                           |
|------|-----------|-----------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 5/21/2025 | Cleaned up work area before starting then Drain hydraulics and started cleaning the left side of rocks and sand and then crack the lines let oil drain out.And then the same on the other side                            |
| 1700 | D71PXI-24 | 5/22/2025 | It's removed final motor lines. Then had to remove left side, hose bracket that was broke off and get rewelded then cleaned up surface on both sides then installed lines and order parts                                 |
| 1700 | D71PXI-24 | 5/22/2025 | Retake engine oil sample                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 5/23/2025 | Cleaned up right side track adjuster, remove old bushing.Install a new one and new dust seal then replaced seals on shaft. Then installed idler on yolk torque to spec then had install idler and slack adjuster on frame |
| 1700 | D71PXI-24 | 5/24/2025 | Remove the old pins and bushings cleaned up all faces and boars. started pushing new bushes in                                                                                                                            |
| 1700 | D71PXI-24 | 5/24/2025 | Remove old line then clean up surfaces then place it with new                                                                                                                                                             |
| 1700 | D71PXI-24 | 5/26/2025 | change pins and bushings                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 5/26/2025 | Replaced ripper pins and bushings                                                                                                                                                                                         |
| 1700 | D71PXI-24 | 5/27/2025 | Installed grease seal in c-frame and helped installed c-frame on unit                                                                                                                                                     |
| 1700 | D71PXI-24 | 5/27/2025 | reassemble c frame                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 5/28/2025 | Finished ripper repairs and helped with blade                                                                                                                                                                             |
| 1700 | D71PXI-24 | 5/28/2025 | reassemble blade and cylinders                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 5/31/2025 | Remove side frame for seal replacement                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 5/31/2025 | Went to put on drive motor lines seen right side stub shaft seal leaking removed remaining lines and pulled frame to change seal                                                                                          |
| 1700 | D71PXI-24 | 6/1/2025  | Tightened up drive line hoses removed bushings from right side frame installed guarding on left side frame and cleaned up area                                                                                            |
| 1700 | D71PXI-24 | 6/3/2025  | install rh track frame and wrap tracks                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 6/3/2025  | Installed new seal and bushings on right side frame installed frame back onto unit hooked up hoses and installed gaurds brought tracks into the shop and wrapped onto unit                                                |
| 1700 | D71PXI-24 | 6/4/2025  | complete undercarriage and clean work area                                                                                                                                                                                |
| 1700 | D71PXI-24 | 6/4/2025  | Uc                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 6/5/2025  | Travel to unit, start checking a/c components, thinking coolant temp control valve leaking but got shut down due to weather                                                                                               |

|      |           |           |                                                                                                                                                                                                                                                                                                                                                                                                                |
|------|-----------|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 6/5/2025  | Check out why ac quit working. Pressures looked good filters were clean but noticed ac compressor wouldn't cycle. Has good air flow through the cab. Recover and pull vacuum for 30 minutes refill system to the 1150+-50g it calls for. No change. Ran out of time travel back to yard.                                                                                                                       |
| 1700 | D71PXI-24 | 6/5/2025  | Mob in machine. Found one ripper pin that wouldn't take but had to leave.                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 6/10/2025 | Travel to unit, check a/c per ops request. Found a/c worked until unit warmed up then got weak - bad heater valve. Spent time taking apart machine to find valve, r&r valve and reassemble. Ran machine 30 min to verify repair - a/c stays cold. Wrap up and travel back.                                                                                                                                     |
| 1700 | D71PXI-24 | 6/11/2025 | Travel to unit for complaint of 2way not receiving. Found antenna missing - replaced antenna but just getting constant static. Switched power plug from 24v to 12v outlet. Plugged in new coax cable - no change. Replace radio - no change. Run new power wire straight to battery - no change. Removed antenna and radio began working - must be interference from machines other antennas. Released to ops. |
| 1700 | D71PXI-24 | 6/22/2025 | Travel to machine. Wait for service to finish up. Found leak on bottom of pump for hydrostatic system. Replaced blown o-ring. Wait for service to top up levels and test. No further leaks.                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 6/24/2025 | 2 way no range attena broke replace good to go                                                                                                                                                                                                                                                                                                                                                                 |
| 1700 | D71PXI-24 | 6/25/2025 | Inspected unit all levels and functions ok.                                                                                                                                                                                                                                                                                                                                                                    |
| 1700 | D71PXI-24 | 6/26/2025 | Inspection of blade will need a new blade                                                                                                                                                                                                                                                                                                                                                                      |
| 1700 | D71PXI-24 | 6/28/2025 | Travel to unit, R&R front center wiper blade.                                                                                                                                                                                                                                                                                                                                                                  |
| 1700 | D71PXI-24 | 7/1/2025  | Service                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 7/1/2025  | Service                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 7/7/2025  | Troubleshoot and repair fuel issues                                                                                                                                                                                                                                                                                                                                                                            |
| 1700 | D71PXI-24 | 7/11/2025 | Travel to unit. Wait for service and edges. Swapped out edges. Good to go.                                                                                                                                                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 7/16/2025 | Service                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 7/16/2025 | Travel to unit. Checked codes and found a low rail pressure 1 occurrence 3 hours prior then 1 def injector caution high temp occurrence 4 hour's prior. Checked for any leaks all good. Had to take off.                                                                                                                                                                                                       |
| 1700 | D71PXI-24 | 7/16/2025 | Service                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1700 | D71PXI-24 | 7/17/2025 | Low rail pressure code , check fuel system, limiter was leaking to much fuel                                                                                                                                                                                                                                                                                                                                   |
| 1700 | D71PXI-24 | 7/17/2025 | Travel to unit found code on unit for can 2 defective communication deleted code and move unit for service                                                                                                                                                                                                                                                                                                     |
| 1700 | D71PXI-24 | 7/17/2025 | Put outer air filter, outer cab filter and hydraulic/trans filter                                                                                                                                                                                                                                                                                                                                              |

|      |           |           |                                                                                                   |
|------|-----------|-----------|---------------------------------------------------------------------------------------------------|
| 1700 | D71PXI-24 | 7/17/2025 | Continuity service from yesterday Change air filters and hyd/trans filter                         |
| 1700 | D71PXI-24 | 7/19/2025 | Install new fuel regulator sensor as per previous order ran unit for 1/2 hour no codes unit is up |