

Invoice To: 57973

Date: 31/10/2023

Tric Transport
Invoice number: 21126156

PO Box 1484
Swan Hill

Reference:
Contract
Number:

VIC VICTORIA 3585

Your Order No: NSS 131069
Work completed: 27/10/2023
Workorder number: 21145683

Vehicle make: SCANIA TRUCK R 620 A6X4NB
Vehicle model: R 620 A6X4NB
Chassis No: 9259162
Engine No: 1160368

Registration No: TRIC09
Mileage: 741836
Delivery Date: 30/07/2020
Fleet Number

Product	Description	Price/unit	%	Total *
TAKE 5	Complete Take 5 Safety Report ***** DO NOT STAMP TO LINE *****			0.00
REPAIRS CARRIED OUT	This is an information invoice only to advise the repairs requested by you and/or found by our workshop and were carried out on your vehicle at no charge			0.00
FAULT: CHECK AND REPORT - DETECTED BY KEMBLA TRUCK REPAIRS X4 CYLINDERS				
Cause , cracked head gasket cyl 7 Fpn: 1893055 Fras: drfr01034592				
Remedy: Cabbed over , removed sump , found coolant pouring from pistons when turning over. Stripped motor ,found head gasket cyl5, 7 cracked. Removed adblue tank,tail-shaft, gearbox wiring ,sensors , hoses. Removed gearbox ,removed fan assembly, hoses , wiring , air lines. Removed fuel lines , mounts , removed engine ,placed on stand in rebuild area. Fully stripped engine , found all heads , liners , pistons to have excessive damage. Machined block to oversized liners , crank shaft found to have wear. Engine swap was now approved. Swapped over studs, pumps , hoses , fittings. Fitted motor into truck ,clutch realigned , gearbox fitted,mounts tighten. Gearbox wiring , air lines , hoses ,tail-shaft , adblue tanks refitted. Fuel lines , wiring , fan assembly ,hoses , sensors reconnected. Oil and coolant pumped , locked the ecu using spd3. Cabbed down washed truck, road tested, All okay.				
				0.00
[2, 1, 11] because of , [1, 18, 11] because of , SUBCON	Detected by workshop,Engine,Noise - knocking Customer complaint,Cab,Noise - knocking ALPHA TOWING	1.00		0.00
SUBCON [2, 1, 33] because of , 05005211	HM GEM Detected by workshop,Engine,Visual fault Remove and fit gearbox with retarder.	1.00		
Page Total:				0.00

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.

Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney
Lic No: MVRL 449 / MD 615
16-18 Lyn Parade. Prestons. 2170
Telephone: 02 9825 7900
Facsimile: 02 9825 7998

Banking Details
BSB: 013226
Account: 8361-52653
Account Name Scania Australia Pty Ltd - NSW Account

A.B.N. 44000537333
Web: www.scania.com.au

invoiceWV_orig1

Invoice To: 57973

Date: 31/10/2023

Tric Transport

Invoice number: 21126156

Product	Description	Price/unit	%	Total *
Previous page carried forward:				0.00
01005195	Incl. drain and fill coolant.			
01005203	Remove and fit engine. Incl. change engine oil, use Scania Diagnos.			
01005143	Troubleshoot engine prior to decision on reconditioning or engine renewal. Incl. check oil and filter, check bearings, remove and fit various components.			
01005232	Transfer parts to exchange engine when renewing engine. Incl. remove and fit clutch, program using Scania Diagnos.			
01005117	Clean engine assembly.			
2459139	Test drive vehicle.			
2341657	O-RING	2.00		
2966989	FILTER ELE	1.00		
2575780	FLANGE SCREW	8.00		
2058778	O-RING	1.00		
0577403	RETAINING	2.00		
0816135	EXCHANGE DC16 115 L01	1.00		
1943567	HOSE CLAMP 50-70MM	4.00		
0816135	HOSE	1.00		
0812545	HOSE CLAMP 50-70MM	2.00		
2192155	SCREW M10X70	1.00		
0809809	FLEXIBLE HOSE	2.00		
0812502	BOLT	2.00		
0041056	BOLT SUNVISOR HEX	4.00		
2607731	WASHER	2.00		
1796996	PIPE	1.00		
2628672	COVER	1.00		
1896695	OIL LDF4 (1000L IBC) 5W30 - SOLD BY THE LITRE	46.00		
ENV	COOLANT PRE MIXED(1000L IBC) - SOLD BY THE LITRE	65.00		
	ENVIROMENT LEVY	1.00		
				0.00

FAULT: CHECK AND REPORT - CUSTOMER ADVISES LEAK AT DIFF

Cause: dirty drain plug

Remedy: Cleaned diff, test drove, all ok.

[1, 8, 21] Customer complaint,Rear axle,Leakage - Oil/Fuel

because of ,

01005147 Clean with chemicals and high-pressure cleaning equipment.

0.00

231703, 231703 Renew Scania Communicator due to inadequate coverage

Page Total: 0.00

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.

Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney

Lic No: MVRL 449 / MD 615

16-18 Lyn Parade. Prestons. 2170

Telephone: 02 9825 7900

Facsimile: 02 9825 7998

Banking Details

BSB: 013226

Account: 8361-52653

Account NameScania Australia Pty Ltd - NSW Account

A.B.N. 44000537333

Web: www.scania.com.au

invoiceWV_orig1

Invoice To: 57973

Date: 31/10/2023

Tric Transport

Invoice number: 21126156

Product	Description	Price/unit	%	Total *
Previous page carried forward:				0.00
Cause, inadequate coverage				
Remedy: Replaced communicator				
Calibrated/carried out conversion using spd3				
Road tested , no faults found , truck sent off				
				0.00
FAULT: CUSTOMER REQUEST - REPAIR LIGHTS ON RHS REAR ON MIRROR				
Cause: broken wire				
Remedy: tested fuse , inspected lights ,checked wiring				
Found broken wire in door sill , cut , stripped ,crimped wires				
Refitted fuse cover and foot sill cover				
Tested ,all-good ,truck sent off				
[3, ,] Factory-requested campaign,,				
[97, ,] because of Factory-ordered campaign,				
[1, 16, 2] Customer complaint,Electrical system,Loss of function				
because of ,				
3110449	FMS RETROFIT ECU RTC C300	1.00		
16208000	Repair wiring harness			
				0.00
FAULT: DETECTED DURING REPAIRS - CLUTCH WORN AND FORK ROLLERS NOISEY				
Cause: deformed rollers				
Remedy: replace clutch and rebuilt clutch fork with new bushes and rollers				
[2, 4, 50] Detected by workshop,Clutch,Seizing				
because of ,				
04105066	Addition for Opticruise on renewal of clutch disc.			
04055045	Renew release bearing			
2258072	LEVER	1.00		
				0.00
FAULT: DETECTED DURING REPAIRS - BOOST HOSES PERISHED				
Cause: perished rubber				
Remedy: replaced boost hoses				
[2, 1, 33] Detected by workshop,Engine,Visual fault				
because of ,				
02055055	Renew 1 flexible hose on engine charge air system.			
2345957	FLEXIBLE H	2.00		
				0.00
FAULT: DETECTED DURING REPAIRS - ENGINE MOUNTS PERISHED				
Page Total:				0.00

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.

Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney

Lic No: MVRL 449 / MD 615

16-18 Lyn Parade. Prestons. 2170

Telephone: 02 9825 7900

Facsimile: 02 9825 7998

Banking Details

BSB: 013226

Account: 8361-52653

Account NameScania Australia Pty Ltd - NSW Account

A.B.N. 44000537333

Web: www.scania.com.au

invoiceWV_orig1

Invoice To: 57973

Date: 31/10/2023

Tric Transport

Invoice number: 21126156

Product	Description	Price/unit	%	Total *
Previous page carried forward:				0.00
Cause, perished rubber/vibration				
Remedy: replaced engine mounts while engine was removed				
[2, 1, 13] Detected by workshop,Engine,Vibration				
because of ,				
01505078	Renew vibration insulator, 2 off, on engine.			
2611113	VIB INSULATOR	2.00		
3018627	SCREW KIT	2.00		
				0.00
FAULT: DETECTED DURING REPAIRS - ECA RESERVOIR PERISHED				
Cause: perished plastic housing				
Remedy: replaced reservoir , bled with new fluid				
Test driven , no faults				
[2, 10, 2] Detected by workshop,Brakes,Loss of function				
because of ,				
04015079	Renew the fluid reservoir, 1 off, for Opticruise clutch. Incl. change fluid, bleed clutch control, use Scania Diagnos.			
2825405	RESERVOIR	1.00		
0816108	HOSE CLAMP	1.00		
				0.00
FAULT: DETECTED DURING REPAIRS - D/S BLEED PIPE DEFORMED				
Cause, deformed piping				
Remedy , not required as engine was replaced				
[2, 0, 33] Detected by workshop,General,Visual fault				
because of ,				
				0.00
FAULT: DETECTED DURING REPAIRS - FUEL BRACKET CRACKED				
Cause, vibration				
Remedy: not required as engine was replaced				
[2, 3, 33] Detected by workshop,Fuel and exhaust systems,Visual fault				
because of ,				
				0.00
FAULT: DETECTED DURING REPAIRS - EXHAUST BRAKE BOLTS MISSING				
Cause, vibration				
Remedy , not required as engine was replaced				
[2, 10, 47] Detected by workshop,Brakes,Loose				
Page Total:				0.00

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.

Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney

Lic No: MVRL 449 / MD 615

16-18 Lyn Parade. Prestons. 2170

Telephone: 02 9825 7900

Facsimile: 02 9825 7998

Banking Details

BSB: 013226

Account: 8361-52653

Account NameScania Australia Pty Ltd - NSW Account

A.B.N. 44000537333

Web: www.scania.com.au

invoiceWV_orig1

Invoice To: 57973

Date: 31/10/2023

Tric Transport

Invoice number: 21126156

Product	Description	Price/unit	%	Total *
Previous page carried forward:				0.00
	because of ,			0.00
	FAULT: DETECTED DURING REPAIRS - INTAKE PIPE BOLTS MISSING			
	Cause, vibration			
	Remedy , not required as engine was replaced			
	[2, 3, 47] Detected by workshop,Fuel and exhaust systems,Loose			
	because of ,			0.00
	FAULT: DETETED DURING REPAIRS - COMPRESSOR BOLT SNAPPED			
	Cause, seized bolt			
	Remedy , not required as engine was replaced			
	[2, 16, 33] Detected by workshop,Electrical system,Visual fault			
	because of ,			0.00
	FAULT: DETECTED DURING REPAIRS - POWER STEERING HOSES PERISHED			
	Cause: perished rubber			
	Remedy: replaced hose during engine swap ,bled steering oil. Road tested , no faults found.			
	[2, 13, 33] Detected by workshop,Steering,Visual fault			
	because of ,			
13205055	Renew hydraulic pipe, 1 off, between power steering gear and fluid reservoir. Incl. renew filter.			
0816132	HOSE CLAMP	2.00		
1925549	O-RING	1.00		
2998087	HYDR PIPE	1.00		
0807310	WASHER 10MM FLAT	3.00		
0815147	NUT M10 NYLOC	3.00		
				0.00
	FAULT: DETECTED DURING REPAIRS - BELT TENSIONER BOLT MISSING			
	Cause, vibration			
	Remedy , not required as engine was replaced			
	[2, 2, 33] Detected by workshop,Cooling system,Visual fault			
	because of ,			0.00
	FAULT: DETECTED DURING REPAIRS: REAR CAB BUSHES PERISHED			
	Cause, perished bushes			
Page Total:				0.00

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.

Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney

Lic No: MVRL 449 / MD 615

16-18 Lyn Parade. Prestons. 2170

Telephone: 02 9825 7900

Facsimile: 02 9825 7998

Banking Details

BSB: 013226

Account: 8361-52653

Account NameScania Australia Pty Ltd - NSW Account

A.B.N. 44000537333

Web: www.scania.com.au

invoiceWV_orig1

Invoice To: 57973

Date: 31/10/2023

Tric Transport

Invoice number: 21126156

Product	Description	Price/unit	%	Total *
Previous page carried forward:				0.00
Remedy: lifted cab ,removed old bushes , new bushes fitted , lowered cab				
Test driven , all-good ,truck sent off				
[2, 18, 33] Detected by workshop,Cab,Visual fault				
because of ,				
18605141	Renew bush, 4 off, on the link for the rear			
	air spring.			
2773898	BUSH	8.00		
				0.00
FAULT: DETECTED DURING REPAIRS; TORQUE ROD BUSHES WORN				
Cause: End of service life				
Remedy: Removed and replaced torque rod bushes as required				
[2, 13, 2] Detected by workshop,Steering,Loss of function				
because of ,				
12055114	Renew air spring link, 1 off, on front axle.			
2465189	REP KIT	4.00		
				0.00
231703, 231703 Renew Scania Communicator due to inadequate coverage				
Cause, inadequate coverage				
Remedy: Replaced communicator				
Calibrated/carried out conversion using spd3				
Road tested , no faults found , truck sent off				
16155165	Renew Scania Communicator, 1 off, in			
	cab.			
				0.00

Customer Survey Reminder

After your visit to our workshop, you may receive a survey from Scania Australia to share your feedback.

Survey ratings are as follows:

9-10: Positive

7-8: Neutral

1-6: Negative

If you feel unable to provide a positive rating, we encourage you to contact the Branch Manager to discuss how we can enhance your experience during your next visit. We truly appreciate your feedback.

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.

Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney

Lic No: MVRL 449 / MD 615

16-18 Lyn Parade. Prestons. 2170

Telephone: 02 9825 7900

Facsimile: 02 9825 7998

Banking Details

BSB: 013226

Account: 8361-52653

Account Name Scania Australia Pty Ltd - NSW Account

A.B.N. 44000537333

Web: www.scania.com.au

invoiceWV_orig1

Invoice To: 57973

Date: 31/10/2023

Tric Transport

Invoice number: 21126156

Product	Description	Price/unit	%	Total *
**** Scania RTA Licence AU07116 expires 12.12.2027 ****				
Sub Total (Excl. of GST) :				0.00
TOTAL AMOUNT PAYABLE:				0.00

For queries on this invoice, please contact: Kaitlyn Ristevski on 0298257900

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.

Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney

Lic No: MVRL 449 / MD 615

16-18 Lyn Parade, Prestons, 2170

Telephone: 02 9825 7900

Facsimile: 02 9825 7998

Banking Details

BSB: 013226

Account: 8361-52653

Account Name Scania Australia Pty Ltd - NSW Account

A.B.N. 44000537333

Web: www.scania.com.au

invoiceWV_orig1