

Inter-Rail Transport 1405 90th Avenue Edmonton, Alberta, T6P 0C8 CA 7804647046

Work Order Number: Invoice Number: PO Number:

WORK ORDER

WORK ORDER DETAILS

Actual Start Date:

Issue Date:

Mon, Mar 17, 2025

9:45 AM

1035

2013 Kenworth W900

Scheduled Start Date:

Mon, Mar 17, 2025

11:35 AM

VIN/SN:

License Plate:

1XKWD40X3DJ964311

U37644

Operator:

Type:

N/A

Group:

Semi Truck **Heavy Duty**

IRT/

Actual Completion Date:

Expected Completion Date:

Fri, Mar 21, 2025

4:15 PM

4 days 4 hrs 40 mins

Odometer: Secondary Meter: 1,695,385km (voided meter) 32,734.5hr (voided meter)

Repair Priority Class:

Scheduled

Status:

Duration:

Completed

Issued By:

SHOP1

Assigned to:

Kohl Dolph

Vendor:

Labels:

Date on Bill / Invoice:

Repair Type:

LINE ITEMS

Subtotal Parts Labor Item \$0.00 \$1,160.00 \$1,160.00 17 Truck labor

Kohl Dolph (Contact)

29 hrs \$40.00

\$1,160.00

PARTS (not linked to a Service Task)

Par		Quantity	Unit cost	Subtotal
#	3101268 (Part) · Inter-Rail Transport Turbo Drain Gasket	1 ea	\$7.71	\$7.71
===	QWNC1212FP (Part) · Inter-Rail Transport 3/4* STEEL WING COUPLER X 3/4* FEMALE NPT	1 ea	\$36.43	\$36.43
Ħ	QWNN1212FP (Part) · Inter-Rail Transport 3/4" BRASS WING NIPPLE X 3/4" FEMALE NPT	1 ea	\$24.29	\$24.29



Part	:		Quantity	Unit cost	Subtotal
**		2DC (Part) · Inter-Rail Transport ING NUT - DUST CAP	1 ea	\$10.16	\$10.16
Ħ		I 2DP (Part) · Inter-Rail Transport ING NUT · DUST PLUG	1 ea	\$14.50	\$14.50
Ħ		s 59CUM (Part) · Inter-Rail Transport st Outlet Connection Gasket	1 ea	\$16.70	\$16.70
#		975 (Part) · Inter-Rail Transport Stud Nut	1 ea	\$13.57	\$13.57
#		975 (Part) · Inter-Rail Transport Stud Nut	3 ea	\$13.45	\$40.35
#		242 (Part) · Inter-Rail Transport charger Mounting Stud	2 ea	\$21.75	\$43.50
Ħ	1	041CUM (Part) · Inter-Rail Transport ET,TURBOCHARGER	1 ea	\$22.02	\$22.02
Ħ	I	940 (Part) · Inter-Rail Transport ET EXHAUST MANIF	1 ea	\$27.79	\$27.79
Ħ		557 (Part) · Inter-Rail Transport ET,EXHAUST MANIFOLD	4 ea	\$27.04	\$108.16
Ħ		331CUM (Part) · Inter-Rail Transport L COOLER	1 ea	\$756.63	\$756.63
Ħ	- 1	755 (Part) · Inter-Rail Transport oler Housing Gasket	1	\$142.79	\$142.79
Ħ		881 (Part) · Inter-Rail Transport RETAINING	1 ea	\$6.15	\$6.15
## ## ## ## ## ## ## ## ## ## ## ## ##		629CUM (Part) · Inter-Rail Transport 629CUM	1 ea	\$293.83	\$293.83
Ħ		025CUM (Part) · Inter-Rail Transport g ISX 15 Oil Cooler Threaded Plug Thermostat Housing	1	\$18.48	\$18.48
計		409 (Part) · Inter-Rail Transport NECTION WATER TRANSFER	1 ea	\$329.95	\$329.95
Ħ	3683 Seal	607 (Part) · Inter-Rail Transport	1 ea	\$7.01	\$7.01
#		er Pipe O-Ring (Part) · Inter-Rail Transport Pipe O-ring	2 ea	\$7.59	\$15.18
=======================================	5658	098CUM (Part) · Inter-Rail Transport g (Compressor Intake Pipe)	1 ea	\$3.12	\$3.12
Ħ	ł	100 (Part) · Inter-Rail Transport	2 ea	\$9.17	\$18.34



Part	;			Quantity	Unit cost	Subtotal
#	90358B (Part) · Inter- 5" Aluminum Band C	*		2 ea	\$11.17	\$22.34
Ħ	49035 (Part) - Inter-R 5" Stainless Steel Flex			1 ft	\$18.55	\$18.55
#	CC2610XFLG (Part) RESTORE COOLING	·		2 ea	\$23.67	\$47.34
#	FR1044 (Part) · Inter- Battery Disconnect S	· ·	•	1 ea	\$104.95	\$104.95
Ħ	HE5985 (Part) · Inter	-Rail Transport - accordion rings TRP Version)		1 ea	\$50.70	\$50.70
#	G384-125 (Part) - Int	ter-Rail Transport		1 ea	\$9.35	\$9.35
===	561.75250 (Part) · Ir			1	\$46.63	\$46.63
Ħ		Part) - Inter-Rail Transport		1 ea	\$9,495.77	\$9,495.77
Ħ	If14000nnflg (Part)	· Inter-Rail Transport		1 ea	\$44.57	\$44.57
#		00 (Part) · Inter-Rail Transport		1 ea	\$133.89	\$133.89
#	C16-1001 (Part) · In	ter-Rail Transport		1 ea	\$23.28	\$23.28
**	1) · Inter-Rail Transport		1 ea	\$19.68	\$19.68
Ħ	1 -			1 ea	\$31.65	\$31.65
Ħ	Filter Water Precharg 15w40 (Part) · Inter- 15w40 Oil			10 L	\$3.71	\$37.10



oil in coolant inspected and found the oil cooler to be leaking internally, removed all parts, to access cooler removed cooler and inspected the cooling core and found the gaskets are what was leaking, removed and cleaned housing, replaced oil thermostat, still put a new core in. torqued into housing, reinstalled all parts with new seals. the turbo had a crack in it on the turbine side, tried to replace it with a used turbine but wasnt the same once i got it apart, ordered a new one, installed it, and rest of parts torqued them all into place, put a cleaner into coolant system cleaned out oil, then had replace all coolant lines except for bunk cooler lines, put more cleaner in system and cleaned it out again replaced coolant filter. filled with coolant and pressure tested, didnt find any leaks. exhaust leak under unit, relaced flex pipe and u bolt clamps for d/s exhaust pipe gong to stack. battery shut offs were seized, replaced one of them and the other one a i cleaned an freed up works good not, 2 lights out on front bumper, replaced lights and pig tails. tested and works. bunk heater not working said glow pin reset, reset computer cleared codes reset hours and worked after wards and tried several times and ran for an a hour and worked

Subtotal	\$13,202.46
Labor	\$1,160.00
Parts	\$12,042.46
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$13,202.46





Inter-Rail Transport Ltd 1405 - 90 Avenue Edmonton, AB T6P 0C8 Work: 780-464-7046 Fax: 780-464-1148 www.inter-rail.ca

Equipment: 1035

Work Order #: 54272

Date: 6/8/2022

Completed Date: 6/8/2022

Year: 2013 Make: Kenworth Model: W900

Hours: 26,359

Odometer: 1,346,524

Serial Number: 1XKWD40X3DJ964311

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
O1 Assessarios	Labour	Brayden Harper	1.75	40.00	70.00
01 Accessories	Labour	Brayden Harper	4.50	40.00	180.00
07 Engine	Labour	Brayden Harper	1.50	40.00	60.00
07 Engine	Labour	Brayden Harper	3.00	40.00	120.00
07 Engine	Labour	Brayden Harper	1.00	40.00	40.00
07 Engine	Labour	Brayden Harper	1.50	40.00	60.00
07 Engine	Labour	Brayden Harper	3.67	40.00	146.80
07 Engine		Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Brayden Harper	5.75	40.00	230.00
07 Engine	Labour	Brayden Harper	1.50	40.00	60.00
07 Engine	Labour	Brayden Harper	3.83	40.00	153.20
07 Engine	Labour	Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Brayden Harper	4.33	40.00	173.20
07 Engine	Labour	Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Brayden Harper	3.00	40.00	120.00
07 Engine	Labour	Brayden Harper	3.00	40.00	120.00
07 Engine	Labour	Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Brayden Harper	3.50	40.00	140.00
07 Engine	Labour	Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Brayden Harper	4.00	40.00	160.00
07 Engine	Labour	Siayden naipoi			

Parts

i aits	Description	Quantity/Hours	Price/Rate	Amount
3680882CUM, Scr. 3685173CUM, Fro 3685556CUM, Gas 4393089CUM, Gas 5414049CUM, Fro 5484228CUM, Fro 5484229CUM, Res 5484230CUM, Fro	sket Gear Housing	1.00 13.00 1.00 1.00 1.00 1.00 1.00 3.00 3	103.69 7.78 79.07 14.58 87.92 30.85 18.17 131.82 131.82 145.23 140.21	103.69 101.14 79.07 14.58 87.92 30.85 18.17 395.46 395.46 435.69 420.63



Inter-Rail Transport Ltd 1405 - 90 Avenue Edmonton, AB T6P 0C8 Work: 780-464-7046 Fax: 780-464-1148 www.inter-rail.ca

Parts

	Description	Quantity/Hours	Price/Rate	Amount
5658203RXCUM, H	AD CYLINDER	1.00	6,706.83	6,706.83
	LASSIC OVERHAUL	1.00	8,492.02	8,492.02
	OR-160AMP PAD MOUNT 105C	1.00	311.45	311.45
5579417PXCUM, Inc		4.00	1,452.88	5,811.52
05-6224, 24mm 6 po		1.00	37.70	37.70
3963988CUM, Wash		4.00	4.70	18.80
3963991CUM, Wash		4.00	6.15	24.60
3688012CUM, Oil Dr		1.00	50.02	50.02
3688398CUM, TUBE		1.00	86.90	86.90
4307482RXCUM, M	ochanical Fuel Pump	1.00	692.65	692.65
2872513CUM, Fuel F		1.00	27.60	27.60
	ust gas pressure sensor	1.00	168.45	168.45
2679904CUM, GAIR	W HEX FLANGE HEAD CAP	4.00	17.04	68.16
3678506CUM, HEAL		22.00	23.87	525.14
3688089CUM, Tube		1.00	105.00	105.00
3601476CLIM Dum	ny Non Serviceable Crank Case "Filter"	1.00	109.53	109.53
HYDX, Hydraulic Ho		1.00	30.16	30.16
E16 6000031B413S	30, 4.5" - 4" Constant Torque Hose Clamp	4.00	15.74	62.96
WF2127FLG, Filter		1.00	25.53	25.53
561 16400 CAC HO	SE COLD CHARGE AIR	3.00	23.71	71.13
CB12255, Relay	OF OOFD OUVER A SECTION	1.00	17.48	17.48
5298564CUM, Servi	ce Shim () ()20"	6.00	64.17	385.02
5236304COM, GGIV	COOLER DELETE TUBE PIPE Water Transfer Tube	1.00	148.48	148.48
4367122CHM FGR	COOLER DELETE TUBE PIPE Water Transfer Tube	1.00	242.99	242.99
5599284RXCUM, LC	phrication Pump	1.00	851.42	851.42
3688113CUM, Plug		1.00	15.51	15.51
3075658, SEAL O-R		1.00	8.98	8.98
3678846CUM, Seal		1.00	15.75	15.75
HHA-TBR-03, Hose		1.00	18.20	18.20
F69-6003-122, Com		1.00	701.88	701.88
	serviour / Surge Tank	1.00	242.28	242.28
15W-40, Bulk Oil	Solviour / Cargo Faint	48.00	3.58	171.84
3163075, Cummins	Red Paint	5.00	27.29	136.45
Sublet				
Category	Description	Quantity/Hours	Price/Rate	Amount

Task 1

- We had just replaced the A/C compressor as the clutch was seized, now it came in and the A/C clutch would not engage. Using power directly from the batteries the clutch would not engage at all. Ordered a new compressor and will return the other new one for warranty while rebuilding the engine.

Invoice: 48302 Supplier: Dave's Diesel Repair

1.00

600.00

600.00

Task 2

- Operator complaint that he was loosing coolant and had no visual leaks. Pressure tested cooling system and it held pressure, No excessive smoke from the exhaust with pressure on the system. Found evidence of coolant coming out of the pressure valve for the coolant reservoir, we added a line to the pressure valve into a water bottle and took the unit for



Inter-Rail Transport Ltd 1405 - 90 Avenue Edmonton, AB T6P 0C8 Work: 780-464-7046 Fax: 780-464-1148 www.inter-rail.ca

a test drive and nothing came out of the over flow. We left the bottle on the unit and told the operator to go work and after one day of driving it had filled the bottle with coolant meaning the coolant system was pressurizing above 15psi on its own and letting coolant out the over flow. Decision was made to remove the cylinder head to further investigate the cause. Removed all accessories and components necessary to get the cylinder head off. When removing the head bolts two bolt heads were broken off and one bolt was seized in place. Had to drill and use a bur bit to brake the bolt head off the seized bolt. Than lifted the head up over the bolts still threaded into the head and found that the head gasket was blown out where the two head bolts were broken. Cleaned the deck surface and found that the liner protrusion was at minimum spec on cylinder 3 and 4 on the intake side. Decision was made to complete a full in-frame engine over haul and cut the counter bores. Disassembled bottom end of the engine, removed front gear housing as it was leaking on the driver side next to the block, removed hi pressure fuel pump head to inspect rollers and tappets to make sure they were updated and in good working order. Cleaned all components and ordered necessary parts. Cut blocks counter bores to accept service shims and to get liner protrusion up to 0.012"-0.013" across the whole block. Than Cleaned block inside and out extensively to get ready to assemble engine. Completed bottom end bearing rollm checked crank end play with was 0.010" after new bearings. Assembled and installed liners, pistons/connecting rods, new updated oil pump and oil pick up tube. We used belzona to level a wear spot on the front right of the engine block near the coolant port in the block, once the belzona was dried we leveled the added material the best we could, when installing the head gasket we also added some aviation gasket maker to that corner to make sure it seals nicely. Installed cylinder head and torqued into place with all new head bolts as 12 of 26 were bad. installed front cover with all new gaskets and timed the engine. Completed assembling the top end we added all new updated intake and exhaust rockers. we inspected exhaust jake rocker components to confirm no broken springs. Completed valve set. installed 4 new injectors in cylinders 1,4,5,6 than used the old injectors in 2 and 3. Than installed all outside engine components as needed. Replaced blocked off EGR cooler with water transfer tube to connect the water pump back to the rear of the block. All operations were done as per Cummings guidelines. Took unit for drive and it worked perfectly, no leaks or issues.

DAVE'S DIESEL REPAIR
CU510-INJECTOR, COMMON RALL (TEST)
CLEAN/INSPECT/TEST SET OF (6) INJECTORS - INJECTOR(S) #1, #4, #5 FAIL - #2 & #3 ARE OK - #5 IS AT THE
DISCRETION OF THE CUSTOMER TO RE-USE
LABOUR
TECHNICIAN: RG2204 / SERVICE ADVISOR: BB2203