

205-60
SEP

Customer Number:

INVOICE #

329155

DAVLIN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE

Page 1 of 9



LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

Home:

Bus: 780-451-2203

Cell:

Email:

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZADRFD8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS: DLR:263723			
122890	CHG	27AUG26				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A DIAGNOSE & ADVISE - DERATED

12-0000 REPLACED DEF PRESSURE LINE, DOSER RETURN

LINE AND DEF FILTER

2124CPCMS

3068CPCMS

3058CPCMS

1575.00 1575.00

1 0433014185 DEF RETURN 90D3/8-90D5/16.1850

609.36

1 AIR PREMIUM AIR FREIGHT CHARGE

60.94 60.94 60.94

1 0432032180 DEF LINE PRESSURE

353.11

1 0433013080 DEF SUPPLY

546.86

1 GRD GROUND FREIGHT CHARGE

60.00 60.00 60.00

1 FLTFDEF106 FLEETRITE DIESEL EXHAUST FLUID

200.83

4 522-836021C STANDARD TIE ALL WEATHER

0.36

6 522-836029C STANDARD TIE ALL WEATHER

1.20

2 PGDEF946 DEF 9.46L DEF JUG

31.98

PARTS: 1743.70 LABOR: 1575.00 OTHER: 120.94 TOTAL LINE A: 3439.64

71197 BROKEN DEF LINES

CUSTOMER REPORTED THE UNIT WAS DERATED.

CONNECTED DIAGNOSTIC SOFTWARE AND FOUND MULTIPLE DEF SYSTEM

PRESSURE FAULTS. INSPECTED THE DEF TANK AND FOUND IT WAS EMPTY.

INSPECTED THE DEF SYSTEM AND FOUND THE PRESSURE LINE BETWEEN THE

DEF PUMP AND DOSER WAS BROKEN. FURTHER INSPECTION FOUND MULTIPLE

DAMAGED DEF LINES. THE LONG DEF PRESSURE LINE FROM THE PUMP TO THE

DOSER AND THE DOSER RETURN LINE TO THE TANK WERE BROKEN AND REQUIRED

REPLACEMENT. ALSO FOUND THE SHORT DEF SUPPLY LINE FROM THE TANK TO THE

PUMP WAS CRACKED/BROKEN.

REMOVED THE DAMAGED DEF LINES AND ORDERED THE REQUIRED REPLACEMENT

PARTS. QUOTED REPLACEMENT OF THE DEF LINES AND DEF FILTER, FOLLOWED BY

DEF SYSTEM TESTING AND AN SCR SYSTEM TEST.

INSTALLED THE NEW DEF LINES FROM THE TANK TO THE PUMP, PUMP TO

DOSER, AND DOSER RETURN TO THE TANK. REPLACED THE DEF FILTER.

PRIMED THE DEF SYSTEM AND PERFORMED A SYSTEM LEAK/PRESSURE TEST.

VERIFIED THE DEF SYSTEM BUILT PROPER PRESSURE AND NO LEAKS WERE

Thank you! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Visit our website WWW.DIT.CA

CUSTOMER COPY

Customer Number:

INVOICE #

329155



DAVLYN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE

Page 2 of 9

LEDUC

8226 Sparrow Cres.
Leduc, AB T9E 8B7
Phone: (780) 986-9530
GST# 101382109

Home:

Bus: 780-451-2203

Cell:

Email:

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZA DRFD8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS: DLR:263723			
122890	CHG	27AUG26				

LINE OPCODE TECH TYPE HOURS

LIST

NET

TOTAL

PRESENT.

PERFORMED A REGENERATION AND VERIFIED THE DERATE FAULT WENT
INACTIVE. CLEARED ALL RELATED FAULT CODES AND CONFIRMED THE DERATE WAS
REMOVED.

CONFIRMED THE DEF SYSTEM REPAIRS WERE COMPLETED SUCCESSFULLY.

B** AMVIC INSPECTION **FORM ATTACHED**

20-0000 COMPLETED AMVIC INSPECTION FORM

421 CP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

71197 REQUESTED AFTER COMPLETION OF THE CVI, COMPLETED THE REQUIRED
AMVIC INSPECTION FORM AND DOCUMENTED THE VEHICLE INSPECTION
RESULTS.

C** TRUCK - TRCVI COMMERCIAL VEHICLE INSPECTION - With wheels on! (IF
WHEELS REQUIRED TO COME OFF ADD 0.5 HRS PER WHEEL)

TRCVI CV8036334

3068 CP

PARTS: 0.00 LABOR: 275.00 OTHER: 0.00 TOTAL LINE C: 275.00

71197 DUE

275.00

PERFORMED COMMERCIAL VEHICLE INSPECTION (CVI) AND COMPLETED THE
REQUIRED INSPECTION DOCUMENTATION.

VERIFIED THE UNIT MET ALL APPLICABLE CVI REQUIREMENTS.

UNIT PASSED THE COMMERCIAL VEHICLE INSPECTION AND AFFIXED CVI
STICKER **CV8036334**.

D** WHEEL PULL ON ONE AXLE ONLY AND INSTALL (TORQUE TO SPEC). BRING
UNIT BACK AND HAVE WHEELS RETORQUED WITHIN 150KM.

TWP 2 AXLE WHEEL PULL

3068 CP

PARTS: 0.00 LABOR: 264.00 OTHER: 0.00 TOTAL LINE D: 264.00

71197

264.00

PERFORMED A **2-AXLE WHEEL PULL** AS PART OF THE CVI.

REMOVED THE WHEELS ON BOTH AXLES TO ACCESS AND INSPECT THE

Thank you ! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Customer Number:

INVOICE #

329155



DAVLYN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE

Page 3 of 9

Home:

Bus:780-451-2203

Cell:

Email:

LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZADRFD8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS: DLR:263723			
122890	CHG	27AUG26				

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

HYDRAULIC DISC BRAKE COMPONENTS.

INSPECTED THE BRAKE PADS, ROTORS, CALIPERS, WHEEL ENDS, AND RELATED
BRAKE COMPONENTS. MEASURED AND RECORDED THE APPLICABLE BRAKE WEAR
MEASUREMENTS.

REINSTALLED THE WHEELS AND TORQUED ALL WHEEL FASTENERS TO
SPECIFICATION.

E** REPLACE LHS REAR SIGNAL LIGHT

08-0000 INSTALLED NEW LIGHT IN LEFT REAR SIGNAL.

3058 CPI

1 STL43AB LED TAIL LIGHT, AMBER 4" 10LED

66.42 66.42

1 FRT1 STD FREIGHT 4HR <199#

35.16

PARTS:

35.16 LABOR:

66.42 OTHER:

30.00

30.00 30.00

30.00

71197 FAILED LIGHT

TOTAL LINE E: 131.58

FOUND THE LEFT-HAND REAR SIGNAL LIGHT WAS INOPERATIVE.

REMOVED THE FAILED REAR SIGNAL LIGHT AND INSTALLED A NEW LIGHT
ASSEMBLY.

TESTED THE REAR TURN SIGNAL AND VERIFIED IT WAS OPERATING PROPERLY.
CONFIRMED THE REPAIR WAS COMPLETED SUCCESSFULLY.

F** LEFT FRONT FENDER SIGNAL LIGHT NOT WORKING

08-0000 INSTALLED NEW LIGHT IN LEFT FRONT FENDER SIGNAL

421 CPI

3068 CPI

3 568-194NA T-3 1/4 WEDGE W2.1X9.2D

99.63 99.63

PARTS:

1.83 LABOR:

99.63 OTHER:

0.00

TOTAL LINE F:

1.83

71197 FAILED BULB

FOUND THE LEFT FRONT FENDER SIGNAL LIGHT WAS INOPERATIVE.

INSPECTED THE LIGHT AND FOUND THE BULB HAD FAILED.

REMOVED THE FAILED BULB AND INSTALLED A NEW BULB. TESTED THE SIGNAL
LIGHT AND VERIFIED IT WAS OPERATING PROPERLY.

CONFIRMED THE REPAIR WAS COMPLETED SUCCESSFULLY.

Thank you ! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Customer Number:

INVOICE #

329155



DAVLYN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE

Page 4 of 9

LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

Home:

Bus: 780-451-2203

Cell:

Email:

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZADRFD8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS:			
122890	CHG	27AUG26	DLR:263723			

LINE OPCODE TECH TYPE HOURS

LIST

NET

TOTAL

G** REPLACE WIPER BLADES

20-0000 INSTALLED NEW WIPER BLADES

421 CPI

2 FLT26 FLEETRITE WIPER BLADE

0.00

0.00

PARTS: 27.46 LABOR: 0.00 OTHER: 0.00 TOTAL LINE G: 27.46

71197 WORN

FOUND BOTH WIPER BLADES WERE WORN AND REQUIRED REPLACEMENT.
REMOVED THE WORN WIPER BLADES AND INSTALLED NEW WIPER BLADES.
TESTED WIPER OPERATION AND VERIFIED PROPER WINDSHIELD CONTACT AND
OPERATION.

CONFIRMED THE REPAIR WAS COMPLETED SUCCESSFULLY.

H** DASH SWITCHES NOT WORKING: DOOR OPEN/ CLOSE, LIGHTS (X2), HEATERS (X2)

08-0000 REPAIRED IGNITINO POWER WIRE FOR BODY

MODULES

3058 CPI

2 MIN10 FUSE

332.10

332.10

PARTS: 16.12 LABOR: 332.10 OTHER: 0.00 TOTAL LINE H: 348.22

71197 DAMAGED WIRE

CUSTOMER REPORTED MULTIPLE DASH SWITCHES WERE INOPERATIVE,
INCLUDING THE DOOR OPEN/CLOSE SWITCH, TWO LIGHT SWITCHES, AND TWO
HEATER SWITCHES.

CHECKED THE RELATED FUSE AND FOUND NO POWER PRESENT AT THE FUSE.
CHECKED THE BODY POWER RELAY AND VERIFIED MAIN BATTERY POWER WAS
PRESENT; HOWEVER, THE RELAY WAS NOT RECEIVING THE REQUIRED IGNITION
POWER SIGNAL.

REMOVED THE DASH PANELS AND TRACED THE BODY MODULE IGNITION POWER
CIRCUIT. FOUND THE IGNITION POWER WIRE FOR THE BODY MODULES WAS
CHAFED/DAMAGED BEHIND THE DASH, CAUSING THE LOSS OF POWER TO THE BODY
CONTROL CIRCUITS.

REPAIRED THE DAMAGED IGNITION WIRING, SECURED THE HARNESS, AND
REASSEMBLED THE DASH.

TESTED THE DOOR OPEN/CLOSE, LIGHT, AND HEATER SWITCH FUNCTIONS AND

Thank you ! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Customer Number:

INVOICE #

329155



DAVLIN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE

Page 5 of 9

LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

Home:

Bus: 780-451-2203

Cell:

Email:

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4U2ADRFD8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS:			
122890	CHG	27AUG26	DLR:263723			

LINE OPCODE TECH TYPE HOURS

LIST

NET

TOTAL

VERIFIED THE BODY SYSTEMS WERE OPERATING PROPERLY. CONFIRMED THE REPAIR
WAS COMPLETED SUCCESSFULLY.

I** 2 SEAT BELT LATCHES BROKEN, 2 NEED ADJUSTMENT

20-0000 INSTALLED 2 NEW SEATBELT LATCHES,

ADJUSTED 2 SEATBELT LATCHES

3058 CPI

2 27621 AISLE SIDE BUCKLE

99.63

99.63

2 AIR PREMIUM AIR FREIGHT CHARGE

75.00

75.00

106.56

PARTS: 106.56

LABOR:

99.63

OTHER:

150.00

TOTAL LINE I:

356.19

71197 BROKEN SEAT BELT LATCHES

FOUND TWO SEAT BELT LATCHES WERE BROKEN AND TWO ADDITIONAL SEAT
BELT LATCHES REQUIRED ADJUSTMENT.

CUT AND REMOVED THE TWO BROKEN SEAT BELT LATCHES AND INSTALLED NEW
LATCHES.

ADJUSTED THE TWO REMAINING SEAT BELT LATCHES TO ENSURE PROPER
ALIGNMENT AND ENGAGEMENT.

TESTED ALL FOUR SEAT BELT LATCHES AND VERIFIED THEY LATCHED,
RELEASED, AND SECURED PROPERLY.

CONFIRMED THE REPAIRS WERE COMPLETED SUCCESSFULLY.

J** INSPECT AND REPORT UNIT HAS DUAL LEVELING VALVES, ONE SIDE IS

INFLATING AND THE OTHER SIDE IS NOT

03-0000 INSTALLED NEW LEVELING VALVE AND CONTROL

ROD

3068 CPI

1 KD2205 VALVE, HEIGHT CONTROL

166.05

166.05

1 DIAC322 ADJUSTABLE LINKAGE KIT

125.55

PARTS: 137.80

LABOR:

166.05

OTHER:

0.00

TOTAL LINE J:

303.85

71197 FAILED LEVELING VALVE AND CONTROL ROD

CUSTOMER REPORTED THE UNIT HAS DUAL SUSPENSION LEVELING VALVES AND
ONE SIDE OF THE SUSPENSION WAS INFLATING WHILE THE OTHER SIDE WAS NOT.

REMOVED BOTH LEVELING VALVE CONTROL RODS AND MANUALLY TESTED BOTH
LEVELING VALVES. BOTH VALVES RESPONDED DURING TESTING; HOWEVER, ONE AIR

Thank you ! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Customer Number:

DAVLIN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE #

329155

INVOICE

Page 6 of 9



LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

Home:

Bus: 780-451-2203

Cell:

Email:

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZADRF8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS:			
122890	CHG	27AUG26	DLR:263723			

LINE OPCODE TECH TYPE HOURS

LIST

NET

TOTAL

BAG WAS INFLATED WHILE THE OPPOSITE SIDE REMAINED DEFLATED.
DURING DIAGNOSIS, THE LEVELING VALVE CONTROL ROD BROKE OFF AT THE
LEVELING VALVE AND REQUIRED REPLACEMENT.
REMOVED THE AFFECTED LEVELING VALVE AND BROKEN CONTROL ROD.
INSTALLED A NEW LEVELING VALVE AND CONTROL ROD.
ADJUSTED THE LEVELING VALVE ROD TO SET THE SUSPENSION TO THE
CORRECT RIDE HEIGHT. VERIFIED BOTH SIDES INFLATED EVENLY AND BOTH AIR
BAGS MAINTAINED THE CORRECT RIDE HEIGHT.
CONFIRMED THE SUSPENSION LEVELING SYSTEM WAS OPERATING PROPERLY AND
THE REPAIR WAS COMPLETED SUCCESSFULLY.

K** REAR SWAY BAR BUSHINGS WORN OUT.

03-0000 REPLACED REAR SWAY BAR BUSHINGS

3058 CPI

2 AUTM46902 SWAY BAR BUSHING POLY FREIGHTLINER

166.05

166.05

2 AUT AUTOMANN EMR FEE

35.00

35.00

49.04

PARTS: 49.04 LABOR: 166.05 OTHER: 70.00 TOTAL LINE K: 285.09

71197 WORN

FOUND THE REAR SWAY BAR BUSHINGS WERE WORN AND REQUIRED
REPLACEMENT.

REMOVED THE WORN REAR SWAY BAR BUSHINGS AND INSTALLED NEW BUSHINGS.

REASSEMBLED AND SECURED ALL SWAY BAR MOUNTING COMPONENTS.

VERIFIED THE REAR SWAY BAR WAS PROPERLY SECURED AND CONFIRMED THE
REPAIR WAS COMPLETED SUCCESSFULLY.

L** REPLACE 3 RUBBER EXHAUST HANGERS BROKEN

07-0000 FABRICATED 2 NEW EXHAUST STRAPS AND

INSTALLED NEW EXHAUST HANGER

3058 CPI

3 AUTM460419 EXHAUST BUSHING FREIGHTLINER

83.03

83.03

PARTS: 105.63 LABOR: 83.03 OTHER: 0.00 TOTAL LINE L: 188.66

71197 BROKEN HANGER STRAPS

FOUND THREE RUBBER EXHAUST HANGER STRAPS WERE BROKEN, ALLOWING THE
EXHAUST SYSTEM TO MOVE AND REQUIRING REPAIR.

Thank you ! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Customer Number:

INVOICE #

329155



DAVLYN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE

Page 7 of 9

LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

Home:

Bus: 780-451-2203

Cell:

Email:

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZADRF8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS			
122890	CHG	27AUG26	DLR:263723			

LINE OPCODE TECH TYPE HOURS

LIST

NET

TOTAL

THE CORRECT REPLACEMENT HANGERS WERE NOT AVAILABLE. REMOVED THE SEIZED MOUNTING HARDWARE AND REMNANTS OF THE THREE BROKEN EXHAUST HANGER STRAPS.

FABRICATED TWO REPLACEMENT HANGER STRAPS FROM HEAVY-DUTY RUBBER MUD FLAP MATERIAL AND INSTALLED THEM USING NEW MOUNTING HARDWARE. FOR THE THIRD LOCATION, INSTALLED THE REPLACEMENT EXHAUST HANGER THAT WAS AVAILABLE AND SECURED IT WITH NEW HARDWARE.

INSPECTED THE COMPLETED INSTALLATION AND VERIFIED THE EXHAUST SYSTEM WAS PROPERLY SUPPORTED AND SECURE.

CONFIRMED THE REPAIR WAS COMPLETED SUCCESSFULLY.

M** RADIO AND BACK UP CAMERA NOT WORKING

08-0000 RELATED TO LINE H

3058 CPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE M: 0.00

71197 RELATED TO AND REPAIRED ON LINE H

N** POWER MIRRORS NOT WORKING

08-0000 RELATED TO LINE H

3058 CPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE N: 0.00

71197 RELATED TO AND REPAIRED ON LINE H

O** BOTH A/C UNITS NOT WORKING

20-0000 RELATED TO AND REPAIRED ON LINE H

3058 CPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE O: 0.00

71197 RELATED TO AND REPAIRED ON LINE H

P** STORAGE RACK BROKEN OFF FROM WALL / FALLING DOWN

20-0000 REPOSITIONED AND RESECURED THE STORAGE RACK

3068 CPI

2 EUCE9020 FLANGED CAP NUT

116.24 116.24
12.78

Thank you! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Customer Number:

INVOICE #

329155

DAVLYN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE

Page 8 of 9



LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

Home:

Bus: 780-451-2203

Cell:

Email:

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZRFD8KCKT6819		71197 / 71197	T1457
PO NO.	PAYMENT	INV. DATE	OPTIONS: DLR:263723			
122890	CHG	27AUG26				

LINE OPCODE TECH TYPE HOURS

PARTS: 12.78 LABOR: 116.24 OTHER: 0.00 LIST NET TOTAL
71197 DAMAGED MOUNTING POINT TOTAL LINE P: 129.02

FOUND THE STORAGE RACK HAD PULLED AWAY FROM THE WALL AND WAS FALLING DOWN DUE TO DAMAGED WOOD AT THE ORIGINAL MOUNTING LOCATIONS. REMOVED THE EXISTING SCREWS FROM THE STORAGE RACK MOUNTING CHANNEL. DRILLED NEW MOUNTING HOLES FURTHER BACK IN THE CHANNEL TO BYPASS THE DAMAGED WOOD AND PROVIDE SOLID MOUNTING POINTS. REPOSITIONED THE STORAGE RACK AND SECURED THE CHANNEL TO THE WALL USING THE NEW MOUNTING LOCATIONS. VERIFIED THE STORAGE RACK WAS PROPERLY SECURED AND STABLE ALONG THE WALL. CONFIRMED THE REPAIR WAS COMPLETED SUCCESSFULLY.

Q** EMERGENCY DOOR/ WINDOWS NOT SOUNDING ALARM WHEN OPENED
08-0000 RELATED TO LINE H

3058 CPI
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 LIST NET TOTAL
71197 RELATED TO AND REPAIRED ON LINE H TOTAL LINE Q: 0.00

R** BACK 2 EMERGENCY WINDOWS: LEFT IS MISSING ONE LATCH ON BOTTOM AND RIGHT DOES NOT OPEN
20-0000 ADJUSTED RIGHT SIDE WINDOW CATCH

3068 CPI
PARTS: 0.00 LABOR: 166.05 OTHER: 0.00 LIST NET TOTAL
71197 DAMAGED/MISSING MECHANISMS TOTAL LINE R: 166.05

INSPECTED BOTH REAR EMERGENCY EXIT WINDOWS. FOUND THE RIGHT-HAND EMERGENCY WINDOW WOULD NOT OPEN. INSPECTED THE WINDOW MECHANISM AND FOUND THE WINDOW CATCH WAS BENT/ADJUSTED TOO HIGH, PREVENTING PROPER OPERATION. FREED UP THE WINDOW MECHANISM AND ADJUSTED THE CATCH TO THE CORRECT POSITION. TESTED THE WINDOW AND VERIFIED IT NOW OPENS, CLOSES, AND LATCHES PROPERLY. INSPECTED THE LEFT-HAND REAR EMERGENCY WINDOW AND FOUND THE LOWER REAR LATCH/WINDOW CATCH WAS MISSING. ATTEMPTED TO SOURCE THE REQUIRED LEFT-HAND WINDOW LATCH/CATCH; HOWEVER, THE REPLACEMENT PARTS ARE NOT AVAILABLE.

Thank you! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK. I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Customer Number:

DAVLIN CORPORATION
LEASING & SALES O/A AIRWAYS RENTALS

INVOICE #

329155



INVOICE

Page 9 of 9

Home:

Bus:780-451-2203

Cell:

Email:

LEDUC

8226 Sparrow Cres.

Leduc, AB T9E 8B7

Phone: (780) 986-9530

GST# 101382109

SERVICE ADVISOR: 3036 AMANDA ALBERT

UNIT #	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
190041	19	FREIGHTLINER CONVENT	4UZADRF8KCKT6819		71197 / 71197	T1457
PO NO.		PAYMENT	INV. DATE	OPTIONS:		
122890		CHG	27AUG26	DLR:263723		

LINE OPCODE TECH TYPE HOURS

LIST

NET

TOTAL

RIGHT-HAND EMERGENCY WINDOW REPAIR COMPLETED. LEFT-HAND EMERGENCY WINDOW STILL REQUIRES THE MISSING LATCH/CATCH IF PARTS BECOME AVAILABLE.

S** FIRE EXTINGUISHER, SAFETY TRIANGLES AND FIRST AID KIT MISSING
20-0000 INSTALLED ALL SAFETY HARDWARE

3058 CPI

33.21 33.21

1 WBDLABC10WH ABS 10LB EXT. W/WALL BRKT

92.99

1 A10C 10LB CARTRIDGE BKT

101.85

1 OOF04042304 SCHOOL BUS FIRST AID KIT

88.19

1 DIA18223 3 PC. TRIANGLE REFLECTOR W/CAS

26.95

PARTS: 309.98 LABOR: 33.21 OTHER: 0.00 TOTAL LINE S:

343.19

71197 MISSING

FOUND THE REQUIRED FIRE EXTINGUISHER, SAFETY TRIANGLES, AND FIRST AID KIT WERE MISSING FROM THE UNIT.

INSTALLED A FIRE EXTINGUISHER, SAFETY TRIANGLE KIT, AND FIRST AID KIT IN THE CAB AND SECURED ALL ITEMS IN THEIR APPROPRIATE LOCATIONS. CONFIRMED ALL REQUIRED SAFETY EQUIPMENT WAS PRESENT IN THE UNIT.

SHOP SUPPLIES

275.39

WARRANTY

NAV OEM PARTS - 1 YEAR PARTS & LABOR

DIAMOND ALL MAKES PARTS - 1 YEAR PARTS ONLY

DELETED ENGINE PARTS - 30 DAYS PARTS ONLY

CUSTOMER SUPPLIED PARTS - NO WARRANTY

ALL WHEELS REMOVED-MUST BE RETORQUED <100KM

Customer Invoice

Thank you ! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK
I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE
AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

X

Visit our website WWW.DIT.CA

DESCRIPTION	TOTALS
LABOUR AMOUNT	\$ 3442.41
PARTS AMOUNT	\$ 2546.06
GAS, OIL, LUBE	\$ 0.00
SUBLET AMOUNT	\$ 0.00
MISC. CHARGES	\$ 646.33
TOTAL CHARGES	\$ 6634.80
LESS INSURANCE	\$ 0.00
SALES TAX	\$ 331.74
PLEASE PAY THIS AMOUNT	\$ 6966.54

CUSTOMER COPY