B04-1

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3591762**
Invoice Date	05/27/2026
Location:	14
Work Order Number:	537471
Payment Type:	
Page:	1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8400	RW9520P041228	50778M	

Service Reminders:

JSC RADIUS A Retail

COMPLAINT:

01 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS A.

VMC Discount

CORRECTION:

Job Total: $0.00

JHYDDIAG1 JD ALL Retail

COMPLAINT:

02 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS - Oil leak.

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

-Removed SCV oil supply line from stack and from gungeon
-Cut one fitting off to pull line out
-Gave line to customer who took it to bumper to bumper
-Customer wanted me to look at his connections on the claas tractor they moved the harrow to
-Case drain on the harrow was hooked up to the load sense port on the tractor
-Told him that would cause issues and showed him where the drain coupler was
-Fitting for drain was some weird german one so removed it
-Followed customer to bumper to bumper and showed them what he needed for it to work
-They said they'll put everything back on

Miscellaneous Charges:

SERVICE ACCESSORIES $59.68

Labor: $375.78 **Parts: $0.00** **OL&M: $0.00** **Misc: $59.68** **Sub-Total: $435.46**

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3591762**
Invoice Date	05/27/2026
Location:	14
Work Order Number:	537471
Payment Type:	
Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8400	RW9520P041228	50778M	

Service Reminders:

Customer PO No:
Tax Exempt No:
Advisor:

Labor:	$596.78
Parts:	$0.00
OL&M:	$0.00
Misc:	-$161.32
GST:	$21.77
PST:	$0.00
Grand Total:	$457.23

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: ..... Date: .....

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351
Maple Creek, SK (306) 662-2233
Kindersley, SK (306) 463-2683
Kyle, SK (306) 375-2302
Leader, SK (306) 628-3889
Unity, SK (306) 228-2696
North Battleford, SK (306) 446-4468
Humboldt, SK (306) 682-2572
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639
Yorkton, SK (306) 783-9459
Balcarres, SK (306) 334-2492
Moosomin, SK (306) 435-3301
Preeceville, SK (306) 547-2007
Russell, MB (204) 773-2149
Wynyard, SK (306) 554-2536
Kamsack, SK (306) 542-2814
Swan River, MB (204) 734-3466

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	1 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

JGL4WD JD ALL Retail

COMPLAINT:

01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST
****
HOURS: _____
TRACTOR DYNOED AT: _____
****
DOES THIS UNIT GET A VALUEMAX STICKER __ YES __NO
HAS STICKER BEEN INSTALLED __ YES __ NO
CAB HAS BEEN COMPLETELY CLEANED _____(INITIAL)
THIS UNIT HAS HAD A FINAL CHECKOVER _____(INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB _____(INITIAL)
****
THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

REPLACE ENGINE OIL AND FILTER
WASH/BLOW OUT COOLING PACKAGE ALL MACHINES.
REPLACE ENGINE FUEL FILTERS
Some protective wire loom on engine wiring harness is missing. (Install new loom in those areas)
Dozer couplers at the front of the tractor leak. (Replace o-rings)
REPLACE REAR WIPER BLADE.
RH side mirror is cracked. (Replace)

Job Total: $1,922.00

JFCC JD ALL Retail

COMPLAINT:

02 FREE CLEANUP OF CAB

CORRECTION:

-Clean cab

Job Total: $0.00

EXPERT-1000000366122 Retail

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	2 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

COMPLAINT:

04 Engine Mounts, Remove and Replace

CORRECTION:

-Remove engine fan, coolant reservoir and brackets.
-Remove charge air pipe.
-Removed positive batter cable off of starter.
-Removed negative battery cable from frame.
-Removed exhaust pipe.
-Removed air intake pipe.
-Removed engine mount bolts.
-Support and install hydraulic jack under engine to raise engine .
-Used overhead crane with proper lifting support to top of the engine to assist lift.
-After lifting engine enough to remove engine isolators, removed and installed new .
-Assemble in reverse order.
-Measure Clearance between Drive shaft and Dampner
-Loosen Mountings and lift engine
-Insert Shims in front
-Lower engine
-Torque mountings
-Snug drive shaft to dampner
-Loosen drive shaft and measure clearance again
-Clearance in Spec 1.78 mm must not exceed 3 mm
-Fit drive shaft to dampner
-Clean bolts
-Assemble with loctite
-Torque bolts

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
T129538	ISOLATOR	4.00	149.64	$598.56	Y

Labor: $1,785.00 **Parts: $598.56** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,383.56**

JGEN02- Retail

COMPLAINT:

05 Turbo drain line leaking. (Repair)

CORRECTION:

-Remove Feed hose
-Remove Return hose

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3465
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	3 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:
-Clean Gasket landing
-Clean Hoses
-Fit Return Hose
-Fit Feed Hose
-Fit Exhaust Flex hose
-Remove Engine lifting brackets
-Fit Exhaust cover plate
-Fit Hoses Clamp

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R521349	GASKET	1.00	3.79	$3.79	Y

Labor: $420.00 **Parts: $3.79** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $423.79**

JGEN06- Retail

COMPLAINT:

06 Adjust valve clearance.

CORRECTION:

-Adjust valves while doing injector.

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

J01020050 JD 9520 Retail

COMPLAINT:

07 REPLACE VALVE COVER GASKET.

CORRECTION:

No Labour if doing valve clearance adjust.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
DZ120103	GASKET KIT	1.00	260.71	$260.71	Y
R72328	O-RING	3.00	2.06	$6.18	Y

Labor: $0.00 **Parts: $266.89** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $266.89**

J01040101 JD 9520R Retail

COMPLAINT:

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3465
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: . . .

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	4 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

08 REPLACE CYLINDER HEAD INJECTOR WIRING HARNESS.

CORRECTION:

Less labour if doing valve clearance adjust.

-Remove harness from tractor to Head
-Remove harness of injector
-Install new wiring.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE533647	HARNESS KI	1.00	780.83	$780.83	Y

Labor: $0.00 **Parts: $780.83** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $780.83**

J01001200 JD 9520RX Retail

COMPLAINT:

09 ENGINE AUXILIARY DRIVE BELT, REPLACE (Cracked)

CORRECTION:

-Remove Tension
-Remove axillary belt
-Fit Axillary belt
-Fit Fan blade
-Fit Shields

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R199163	V-BELT	1.00	68.94	$68.94	Y

Labor: $75.00 **Parts: $68.94** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $143.94**

JENGDIAG1 JD ALL Retail

COMPLAINT:

11 PERFORM ENGINE DIAGNOSTICS (Coolant leak near water pump)

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:
-Looked all around the water pump.

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351
Maple Creek, SK (306) 662-2233
Kindersley, SK (306) 463-2683
Kyle, SK (306) 375-2302
Leader, SK (306) 628-3889
Unity, SK (306) 228-2696
North Battleford, SK (306) 445-4468
Humboldt, SK (306) 682-2572
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639
Yorkton, SK (306) 783-9459
Balcarres, SK (306) 334-2492
Moosomin, SK (306) 435-3301
Preeceville, SK (306) 547-2007
Russell, MB (204) 773-2149
Wynyard, SK (306) 554-2536
Kamsack, SK (306) 542-2814
Swan River, MB (204) 734-3466

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	5 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:
-There is sweating from the front cover. nothing to worry about at this time.
-Did notice the water pump has not been changed.
-Got parts list together and gave to foreman.
-Advised shop foreman.
-Foreman advised customer.

Labor: $210.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $210.00**

JGEN12- Retail

COMPLAINT:

12 Fuel tank vent replace.

CORRECTION:

-Removed the fuel tank vents.
-Found the new vents and installed.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE255763	CAP	2.00	164.99	$329.98	Y

Labor: $50.00 **Parts: $329.98** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $379.98**

JELECDIAG1 JD ALL Retail

COMPLAINT:

14 PERFORM ELECTRICAL SYSTEM DIAGNOSTICS (Hi/Low lights not working)(Beacon lights also not working)

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

-Test high and low beams.
-Need to look closely but they are working properly.
-The beacon light was not working.
-Removed the cover
-the beacon light was still spinning but the light was not on.
-removed the light from the beacon.
-found the bulb was burnt out.
-replace with new bulb
-beacon light was working again.
-reinstalled beacon cover.

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	6 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
57M7019	H1 BULB 55W	1.00	19.81	$19.81	Y

Labor: $157.50 **Parts: $19.81** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $177.31**

JELECDIAG2 JD ALL Retail

COMPLAINT:

16 PERFORM ELECTRICAL SYSTEM DIAGNOSTICS (PCU controller missing and tractor stuck in park)

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

-Checked all the wiring to the transmission controller.
-All was checking out to be ok.
-Cleaned all the grounds on the tractor.
-Didn't do anything.
-PCU controller would not come up the address list.
-Was told from customer that they wiggled the harness on the back of the tractor and got it working again.
-While the key was on do a wiggle test all the harness that I could reach.
-Could not make the controller come back online.
-Found a test controller at another store for testing.
-Got it shipped to the store.
-Installed test controller onto the tractor for a test.
-After installing the PCU come online.
-Test the unit and everything worked properly.
-Left tractor for couple hours and test again, everything worked properly.
-Left tractor over night and test again, everything working right in the morning.
-Install the old PCU and it was offline, start unit and could not drive. PCU seems to have failed.
-Double check wiring, cannot find any issues.
-Ordered controller.
-Installed test controller again just to double check addresses.
-Installed the new controller.
-Perform the all the calibrations for the new controller.
-Took a while for the oil to get warm because it wouldn't let me drive until calibration was complete.
-Took the tractor for a test drive and all was working good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
YZ502338	Module	1.00	3,180.09	$3,180.09	Y
YZ502338-CR	CORE for:Module	-1.00	282.00	-$282.00	Y

Labor: $1,260.00 **Parts: $2,898.09** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $4,158.09**

9520F901009 Retail

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	7 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

COMPLAINT:

17 HINGE PINS AND BUSHINGS, R&R (Bushings worn) Double check, pins was done not too long ago, if it can go for another season we done do it.

CORRECTION:

-Got the jack
-Jacked the tractor up in the middle
-Found there was play in the bushings but bushings is not worn through yet.
-Unit will be good for a season.
-Customer would need to keen an eye on it.

Labor: $105.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $105.00**

J01020100 JD 9520R Retail

COMPLAINT:

18 REPLACE REAR ENGINE TORSIONAL DAMPER (Cracked)

CORRECTION:

-Remove hood.
-Drain hyd tank.
-Remove tank.
-Remove lines and wiring.
-Remove bracket.
-Disconnect shaft.
-Remove bolts holding damper.
-Remove damper.
-Install new.
-Clean Hydraulic tank
-Clean Hyd tank brackets
-Fit new Hoses on bottom
-Fit to tractor
-Fit hoses to hyd tank
-Fit hood

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R151762	SCREW	12.00	3.06	$36.72	Y
R45693	CAP SCREW	2.00	4.70	$9.40	Y
RE220150	TORSIONAL	1.00	2,715.66	$2,715.66	Y

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	8 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

Labor: $2,100.00 **Parts: $2,761.78** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $4,861.78**

JHYDDIAG1 JD ALL Retail

COMPLAINT:

19 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS (Leak under hydraulic tank)

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

-Find Hose leaking under tank
-Has a crack in on the peace that goes over the fitting where the clamp sits
-Cut cracked peace of
-Get a fitting and extend hose
-Extend hose and connect to Tank
-Install and all looks good.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	4.00	132.16	$528.64	Y
H77698	Tie Band 16" 30/pk	4.00	1.20	$4.80	Y
R206756	HOSE	2.00	66.16	$132.32	Y
RE52702	CLAMP	4.00	29.18	$116.72	Y
TY22466	CLAMP	2.00	1.86	$3.72	Y
TY22469	CLAMP	1.00	1.86	$1.86	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF300	ENVIRO FEE	4.00	3.00	$12.00	Y

Labor: $315.00 **Parts: $788.06** **OL&M: $0.00** **Misc: $12.00** **Sub-Total: $1,115.06**

JELECDIAG3 JD ALL Retail

COMPLAINT:

23 PERFORM ELECTRICAL SYSTEM DIAGNOSTICS (Washer fluid pump does not work)

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

-Removed all the dirt away from the washer tank.
-Tank was about 1/2 full.

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	9 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:
-Checked the wiring.
-Cleaned the connections
-Worked the button from inside the cab.
-Had full voltage to the pump.
-Checked the pump with power probe and had nothing both pumps had failed.
-Made parts list and gave to foreman.
-Foreman advised customer and customer did not want replace pump at this time.

Labor: $315.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $315.00**

JGEN24- Retail

COMPLAINT:

24 Replace RH armrest cover. (Broken)

CORRECTION:

-Removed cover
-Installed new cover.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE151332	Cushion	1.00	176.63	$176.63	Y

Labor: $52.50 **Parts: $176.63** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $229.13**

9520RF1146687 Retail

COMPLAINT:

25 INJECTOR, R&R ONE W/TIER II ENGINE

CORRECTION:

Might need one as the wire on the injector came loose and could have arced the contact surface up. Need to clean it up really good and inspect why the nut came loose and if it will make good connection.

-Clean injector cup landing
-Cover head with valve cover for dust
-Clean all parts removed
-Loosen Hood
-Bring crane to tractor to remove hood
-Remove hood
-Remove valve cover
-Get tools fit injector cup replacement

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	10 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:
-Fit injector cup
-Fit injector
-Fit Rocker arm assembly
-Found one stripped hole holding down rocker arm assembly
-Remove rocker arm assembly
-Tap new treads
-Insert helli coil
-Fit rocker arm
-Adjust valves and injectors as per manual
-Fit wiring harness
-One wire holding bracket broke of half way worn
-Remove rocker arm assembly
-Remove injector
-Remove injector cup
-Fit Valve cover to keep clean

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R136507	SCREW	12.00	6.24	$74.88	Y
SE501957	Elect Unit Injector Reman 12.5L	1.00	2,300.62	$2,300.62	Y
SE501957-CR	CORE for:Elect Unit Injector Reman	-1.00	706.00	-$706.00	Y

Labor: $2,205.00 **Parts: $1,669.50** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $3,874.50**

JPWTRNDIAG2 JD ALL Retail

COMPLAINT:

26 PERFORM POWERTRAIN DIAGNOSTICS (Front and rear yokes on the transmission outputs are leaking but the yokes have play and move up and down so we need to figure out why there is play or they will not seal again.)

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:

-Removed the rear drive shaft in pivot area.
-Set up dial indicator on yoke.
-There was little play on the yoke.
-Removed the yoke.
-Found the yoke had a pretty nasty grove in it where the seal runs.
-Went to the front input from the transmission.
-Had to dig the mud out to get the front drive line cage.
-Took about 2 hours of cleaning to get the cage out.
-Set up the dial indicator.
-Measuring there were to little play.
-Front seal is sweating, no sign of dripping.
-Front seal will be ok for a bit.

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	11 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:
-Reinstalled the cage.
-Made a parts list to advise the customer about the rear output.
-Gave list to shop foreman to advise customer.
-Customer confirmed we can do the repair.

Labor: $630.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $630.00**

JHYDDIAG6 JD ALL Retail

COMPLAINT:

27 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS - SCV 1 sometimes does not work, customer restarts unit and it works again.

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

-Fit Test cylinder and run tractor test inside shop
-Working cylinder almost an hour then started to hear a loud clicking sound once hyd scv is bottomed out
-Remove Logic plate to inspect
-Fund logic plate and Cover plate badly worn at valve location
-Got new Logic plate from parts
-They did not have Cover plate
-Got Sanding paper and polished cover plate until grove is polished out
-Fit new logic plate and polished cover plate
-Refill hyd oil
-Run cylinder test again and sound was not there anymore
-Return cylinder to container

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE220721	PLATE	1.00	941.52	$941.52	Y

Labor: $1,279.19 **Parts: $941.52** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,220.71**

JSC RADIUS B Retail

COMPLAINT:

28 SERVICE CALL TO AND FROM MACHINE LOCATED IN RADIUS B.

CORRECTION:

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4458	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account Nc

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	12 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

Job Total: $472.50

JENGDIAG2 JD ALL Retail

COMPLAINT:

29 PERFORM ENGINE DIAGNOSTICS (Knocking and smoking)

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:_____

-Check oil level, above the min mark but needs to be filled
-Check coolant level, Coolant level very low
-Clean Connection, a bit of oil on connection
-Connect Injector cutoff tool
-Start and test
-Found a mis on injector 5
-Took it out for a run and test again and found the same fault on injector 5
-Park tractor in shop and disconnect cutting tool
-Start again and fault still persisted
-Cleared the ECU fault codes
-Start again and check codes, found code 35
-Check Code 35
-Injector 5 open circuit
-Check For transmission fault codes and controller not found

-Remove Boost pipe
-Remove Breather hose
-Loosen and remove valve cover
-Wire lose on injector 5
-Tighten and check al other injectors found some lose on them also but not as much as 5
-Fit valve cover
-Fit boost pipe
-Fit breather hose
-Start and test
-Runs smooth
-Clear ECU codes
-Start and run test again
-No codes found
-Tractor does not take gears cant test run outside
-Recommend replacing injector wire harness and valve cover gasket

Labor: $660.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $660.00**

J01050051 JD 9520 Retail

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	13 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

COMPLAINT:

30 REPLACE REAR TRANSMISSION OUTPUT SHAFT SEAL.

CORRECTION:

-Remove old seal.
-Install new seal.
-Install yoke ans torque to speck.
-Install drive shaft.
-Fasten all bolts to speck.
-All looks ok.
-Wash engine compartment
-Wash rear transmission area of seal repair
-Clean cab floor

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	2.00	132.16	$264.32	Y
R77978	RING	1.00	12.81	$12.81	Y
R98309	CAP SCREW	1.00	19.29	$19.29	Y
RE158082	SEAL	1.00	110.93	$110.93	Y
YZ501556	UNIVERSAL	1.00	819.25	$819.25	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF300	ENVIRO FEE	2.00	3.00	$6.00	Y

Labor: $462.00 **Parts: $1,226.60** **OL&M: $0.00** **Misc: $6.00** **Sub-Total: $1,694.60**

J01030040 JD 9520 Retail

COMPLAINT:

31 WATER PUMP, R&R

CORRECTION:

-Coolant was drained and put in on another segment.
-Removed shields.
-Removed hose clamps.
-Removed fittings from old pump
-Removed water pump.
-Cleaned
-The bearing were very dry in the water pump removed was very close is failing.
-Installed new water pump

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	14 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:
-Installed fittings
-Installed new hoses
-Checked for leaks after coolant was filled.
-All checked out.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R117080	RADIATOR H	1.00	45.38	$45.38	Y
R121427	RADIATOR HOSE	1.00	31.42	$31.42	Y
RE224072	HOSE CLAMP	1.00	20.99	$20.99	Y
SE501592	WATER PUMP	1.00	1,110.91	$1,110.91	Y
SE501592-CR	CORE for Water Pump Reman	-1.00	141.00	-$141.00	Y
T77932	-10FF O-ring	1.00	2.68	$2.68	Y
TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9.46L	6.00	63.12	$378.72	Y

Labor: $1,365.00 **Parts: $1,449.10** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,814.10**

JDISC JD ALL Retail

COMPLAINT:

33 GREEN LIGHT INSPECTION DISCOUNTS

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
DISC	Parts Discount	-1.00	1,406.59	-$1,406.59	Y

Miscellaneous Charges:

SERVICE ACCESSORIES	$150.00

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: -$1,256.59** **Sub-Total: -$1,256.59**

Credit Card Information

Customer PO No:
Tax Exempt No:
Advisor:

Type: Credit Card
Auth No:
Amount: $30,011.29

Labor:	$16,548.19
Parts:	$14,065.91
OL&M:	$0.00
Misc:	-$2,031.92
GST:	$1,429.11
PST:	$0.00
Grand Total:	$30,011.29

PATTISON AGRICULTURE LIMITED
Box 550
Wynyard, SK S0A 4T0
Phone: (306) 554-2536
Fax: (306) 554-3153
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3559535**
Invoice Date	04/14/2026
Location:	14
Work Order Number:	529833
Payment Type:	Credit Card
Authorization Number:	
Page:	15 of 15

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9520	8364	RW9520P041228	50778M	

Service Reminders:

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: ..... Date: .....