Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30JUN26	114	114501272

SOLD TO: [redacted]

PAGE 1

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89718	[redacted]	114501272	01	26MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	STAN

DESCRIPTION				AMOUNT
REPLACE PUMP TO LCV HOSES & STEEL TUBE				
When preforming run ups on the machine after some other repairs it was noticed that there is a hose routed incorrectly and rubbing on the left-hand steering cylinder rod chrome. Looked into service history and the hose that was installed is a pinch to get the machine operational in the field as the steel tube was leaking and removed at the time that guides around the cylinder. Got approval to supply and install the steel tube and new hoses as req. The Pulled loader into shop, chocked wheels, installed articulation lock, discharged accumulators and hydraulics, and locked out battery disconnect. Installed vacuum transducer onto hydraulic reservoir. Dropped skid plate from underneath pumps. Removed temporary hose. Dropped secondary steer guard from hydraulic tank. Detached and moved secondary steer hard lines. Installed new hard line against frame using new P-clamps. Ordered and installed both connecting hoses using new O-rings and then torqued flange clamps. Reconnected and secured secondary steer hard lines. Installed skid plate under pumps. Installed secondary steer guard. Removed vacuum transducer and lock out. Started machine, ran boom and bucket functions. Discharged accumulators. Topped up hydraulic tank, ran out to wash bay to rinse off residual oil. Machine coded on startup at wash bay with VGT actuator code again. Did run ups and tested for leaks, none found.				
3	T78393	O-Ring	13.05	39.15
1	51M7065	O-Ring	4.03	4.03
1	AT433692	HydrauliCY	1,032.72	1,032.72
1	AT453972	Hose CY	810.67	810.67

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30JUN26	114	114501272

SOLD TO: [redacted]

PAGE 2
SALE TYPE CHARGE
CUSTOMER NO. 14194304
SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89718	[redacted]	114501272	01	26MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	STAN

		DESCRIPTION		AMOUNT
2	T363072	Grommet XY	19.13	38.26
1	AT460175	Oil Line	976.41	976.41
1	T363027	Clamp CY	100.16	100.16
	* LABOR *			1,800.00
1	FREIGHT-TAXABLE		95.00	95.00
	SERVICE ACCESSORIES		162.00	162.00
	ENVIRONMENTAL FEE		18.00	18.00
>>---> SEG# 01	PRT 3,001.40	LAB 1,800.00	MSC 275.00	5,076.40
	* GST/HST *		253.82	

DIAGNOSE & REPAIR FOR TURBO ACTUATOR CODE

During machine run ups the machine the a code for turbo actuator fault. Inspected the harness and electrical connector to find no issues. Hooked up laptop and attempted a VGT actuator re learn to find it failed. Chocked wheels, installed articulation lock, locked out battery disconnect. Placed vacuum transducer on surge tank, removed and capped coolant lines to actuator. Detached VGT linkage from actuator. Tested the actuator to find it slightly hangs up when moving through its range of motion. Swapped coolant fitting with new O-rings to new actuator. Installed new actuator, attached linkage, and connected coolant lines. Removed lock out. Performed VGT re-learn in Service Advisor, successful. Deleted codes, did run ups, parked in wash bay for courtesy wash. Cleaned up bay and work bench. Completed tech report.

1	DZ114560	ActuatorCY	1,684.44	1,684.44
	* LABOR *			1,410.00

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30JUN26	114	114501272

SOLD TO: [redacted]

PAGE 3

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89718	[redacted]	114501272	02	29MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	STAN

DESCRIPTION						AMOUNT
SERVICE ACCESSORIES					126.90	126.90
ENVIRONMENTAL FEE					14.10	14.10
>>---> SEG# 02 PRT	1,684.44	LAB	1,410.00	MSC	141.00	3,235.44
* GST/HST *					161.77	
* TOTAL GST/HST * - GST No. 899544779						415.59

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____
SIGNATURE

_____
DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	4,685.84
TOTAL LABOR	3,210.00
MISC. CHARGES	416.00
SALES TAX	0.00
PLEASE PAY THIS TOTAL ▶	8,727.43

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29MAY26	114	114501059

SOLD TO: [redacted]

PAGE 1

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89717	[redacted]	114501059	01	29APR26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	

DESCRIPTION				AMOUNT
REPAIR FOR LEAKING RIGHT HAND BUCKET CYLINDER				
Park and prepare machine for bucket cylinder removal. Disconnect hydraulic lines from right bucket cylinder and cap hoses and fittings. Support bucket cylinder with crane and remove rod cylinder from z bar. Remove grease lines from barrel pin and remove pin from cylinder. Lift cylinder from machine, move cylinder to wash bay and wash grease from cylinder. Have cylinder sent to a local hydraulic shop for repair / reseal as req. Note: the rod required re chrome, the rod guide required machining and customer seals installed. Install bucket cylinder back onto machine. Pinned barrel end and installed hoses. Went through the bleed procedure and cycle air from cylinder as req. Installed rod end pin. Greased pins. Top up hydraulic oil to proper oil level. Move machine outside and perform run ups to verify there are no more leaks to note.				
	* LABOR *			1,175.00
1	1472211S RESEAL BKT CYL		4,991.00	4,991.00
	SERVICE ACCESSORIES		105.75	105.75
	ENVIRONMENTAL FEE		11.75	11.75
>>--> SEG# 01 PRT	.00	LAB 1,175.00	MSC 5,108.50	6,283.50
	* GST/HST *		314.18	
CHANGE HYD AND AXLE OILS				
The customer requested the hydraulic oil and axle / final drives be changed while the machine is here in the shop. Discussed if they also wanted the case drain and suction				

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

QST # 1226957240

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

LF-1152C

CUSTOMER COPY

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29MAY26	114	114501059

SOLD TO: [redacted]

PAGE 2

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89717	[redacted]	114501059	02	07MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	

DESCRIPTION	AMOUNT
screens removed and replaced as per the service manual. Received approval to move forward. HYDRAULIC OIL : Locked out battery disconnect. Removed secondary steering guarding on bottom of hydraulic tank. Drained hydraulic oil. Removed return filters and housings. Discarded filters, cleaned out housings, and let dry. Detached case drain return hoses from tank, removed and cleaned case drain screens. Reinserted case drain screens and attached hoses with new O-rings. Flushed hydraulic tank with 10 liters of fresh oil. Secured drain plug with new O-ring. Reinserted return filter housings with new cartridge filters. Secured and torqued caps. Filled reservoir with fresh hydraulic oil. Removed lock out and started machine, cycled cylinders to purge air from pilot system. Topped up hydraulic oil. FRONT AXLE FD OILS: Jacked up front of machine using bucket and placed jackstands under front axle. Rotated both front final drives into position by hand with parking brake off. Shutdown machine and locked out battery disconnect. Drained both final drives and sides of front axle. Removed skid plates. Used air chisel and prybar to remove packed dirt and debris from around plumbing and screens. Removed screens and hard lines from front axle. Disassembled screens; found lots of delaminated brake material clogging both screens. Cleaned up screens and hard lines. Reassembled with new O-rings. Used air chisel and shovel to remove packed dirt and debris from front of frame. Removed cover. Changed front axle circulation filters. Filled final drives and both sides of front axle with Hygard. Started machine and topped up oil. Replaced stripped level check plug on right side of front	

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29MAY26	114	114501059

SOLD TO: [redacted]

PAGE 3

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89717	[redacted]	114501059	02	07MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	

DESCRIPTION					AMOUNT
axle. Jacked up front of machine, removed axle stands, moved machine into					
REAR AXLE / FD OILS: position for left rear final drive. Locked out battery disconnect. Drained left rear final drive and axle. Removed both rear skid plates. Used air chisel, prybar and wire brush to clear out packed dirt and debris. Removed left rear screen and cleaned out. Found delaminated brake material in screen. Reassembled screen and installed with new O-rings. Changed left rear axle circulation filter. Filled left rear final drive and axle with Hygard. Ran machine. Topped up oil. Started machine and moved for right rear final drive. Locked out battery disconnect. Drained right rear final drive and axle. Removed right rear screen and cleaned out. Found delaminated brake material in screen. Reassembled screen and installed with new O-rings. Changed right rear axle circulation filter. Filled right rear final drive and axle with Hygard. Ran machine. Topped up oil. Cleaned skid plates in wash bay. Installed both front and rear skid plates.					
4	T78612	O-Ring		1.24	4.96
6	R43750	O-Ring		15.00	90.00
2	R26906	O-Ring		7.45	14.90
4	AT367840	Oil Filt		160.28	641.12
4	T78784	O-Ring		7.72	30.88
3	AT545968	Filter E		228.97	686.91
368	TY27711	Hydrauli		8.42	3,098.56
578	WDF	WASTE DI		.10	57.80
210	6284B	1L - BUL		7.43	1,560.30
	* LABOR *				4,700.00
	SERVICE ACCESSORIES			423.00	423.00

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29MAY26	114	114501059

SOLD TO: [redacted]

PAGE 4

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89717	[redacted]	114501059	02	07MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	

DESCRIPTION						AMOUNT
ENVIRONMENTAL FEE					47.00	47.00
>>--> SEG# 02 PRT	6,185.43	LAB	4,700.00	MSC	470.00	11,355.43
* GST/HST *					567.77	

REPAIR FOR LEAKING LH BUCKET CYLINDER

During final run ups the left side loader bucket cylinder started weeping oil from the rod guide as well. Discussed with the customer and got approval to reseal. Park and prepare machine for bucket cylinder removal. Disconnect hydraulic lines from right bucket cylinder and cap hoses and fittings. Support bucket cylinder with crane and remove rod cylinder from z bar. Remove grease lines from barrel pin and remove pin from cylinder. Lift cylinder from machine, move cylinder to wash bay and wash grease from cylinder. Have cylinder sent to a local hydraulic shop for repair / reseal as req. Note: the rod required re chrome, the rod guide required machining and customer seals installed. Install bucket cylinder back onto machine. Pinned barrel end and installed hoses. Went through the bleed procedure and cycle air from cylinder as req. Installed rod end pin. Greased pins. Top up hydraulic oil to proper oil level. Move machine outside and perform run ups to verify there are no more leaks to note.

4	T78393	O-Ring	13.05	52.20
15	TY27711	Hydrauli	8.42	126.30
15	WDF	WASTE DI	.10	1.50
	* LABOR *			1,175.00
1	1472392S	RESEAL CYL	4,991.00	4,991.00

GST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29MAY26	114	114501059

SOLD TO: [redacted]

PAGE: 5
SALE TYPE: CHARGE
CUSTOMER NO.: 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89717	[redacted]	114501059	03	08MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	

DESCRIPTION						AMOUNT
SERVICE ACCESSORIES					105.75	105.75
ENVIRONMENTAL FEE					11.75	11.75
>>---> SEG# 03 PRT	180.00	LAB	1,175.00	MSC	5,108.50	6,463.50
* GST/HST *					323.18	
CHECK & REPAIR FOR CODES						
000641.07 Turbocharger VGT actuation calibration fault on numerous startups. 6 incidents. Checked wiring and connectors, ok. Connected with service center, attempted re-learn, got engine running fault with engine off. Checked ECU readings, none found. Attempted to re-flash ECU, no communication. Used CAN wizard, unable to connect due to missing Fcode6 module. Followed steps to remedy issue, not successful. Unable to use CAN wizard. Two payload updates for machine. Attempted to update TCU, no communication. Updated VCU, installation successful. Communication with ECU established. Performed VGT re-learn, successful. Cycled ignition on and off to test, fault after 5 cycles. Re-flashed ECU, successful. Cycled ignition on and off to test, no faults after 10 cycles. ECU readings available, TCU readings not available. Updated TCU, installation successful after 4 attempts. Cycled ignition for TCU to learn PIN, active fault stored and cleared. Active articulation calibration fault due to updated TCU. Communicating with all controllers now, no VGT calibration faults.						
** TOTAL LABOR **						470.00
SERVICE ACCESSORIES					42.30	42.30
ENVIRONMENTAL FEE					4.70	4.70

GST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

LF-1152C

CUSTOMER COPY

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29MAY26	114	114501059

SOLD TO: [redacted]

PAGE 6

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89717	[redacted]	114501059	04	12MAY26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15838	

DESCRIPTION					AMOUNT
>>--> SEG# 04 PRT	.00	LAB	470.00	MSC 47.00	517.00
* GST/HST *				25.85	
CHECK AND REPAIR FOR FAILED GREASE SYSTEM HOSE FITTING					
Found major grease leak front manifold attached to inside of front frame. Unmounted manifold and removed hard lines. Fabricated test fitting and pressurized manifolds with mounted hard lines using grease gun. Found crack in pipe thread on 90 degree fitting on lower manifold. Replaced fitting and tested. OK, no leaks. Re-mounted manifolds, connected hard lines and hoses. Started machine and set greaser to purge until grease was evident at pivot points. Shut down greaser and machine. Cleaned area.					
** TOTAL LABOR **					940.00
SERVICE ACCESSORIES				84.60	84.60
ENVIRONMENTAL FEE				9.40	9.40
>>--> SEG# 05 PRT	.00	LAB	940.00	MSC 94.00	1,034.00
* GST/HST *				51.70	
* TOTAL GST/HST * - GST No. 899544779					1,282.68

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	6,365.43
TOTAL LABOR	8,460.00
MISC. CHARGES	10,828.00
SALES TAX	0.00
PLEASE PAY THIS TOTAL ▶	26,936.11

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30JUN26	114	114501489

SOLD TO: [redacted]

PAGE: 1
SALE TYPE: CHARGE
CUSTOMER NO.: 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89800	[redacted]	114501489	01	15JUN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15904	CHAD

DESCRIPTION						AMOUNT
SERVICE CALL/TRAVEL						
HIGHLAND QUARRY, ABBOTSFORD						
* LABOR *						1,012.50
ENVIRONMENTAL FEE					10.13	10.13
>>--> SEG# 01 PRT	.00	LAB	1,012.50	MSC	10.13	1,022.63
* GST/HST *					51.13	
DIAGNOSE & REPAIR 002795.31 TURBO ACTUATOR FAULT CODE						
Diagnose and repair for customer complaint of Turbo Actuator fault code 2795.31. Visually inspected Turbo charger linkage and wiring harness. Both appeared okay. Manually tested VGT linkage for range of travel. Found no sticking or binding in linkage. Noticed above fault code now stored fault but active code 641.13 (VGT calibration error). Followed diagnostic trouble shooting procedure as outlined in service advisor. Suspect internal wear in turbo charger causing out of calibration range during key on. Recommend replacing turbo charger. Removed all turbo charger piping and bellows, removed turbo charger lines to turbo charger, and removed turbo from the manifold. Cleaned all mounting surfaces, installed new turbo, and torqued hardware to spec. Installed all lines, piping, and bellows to turbo. Pre-lubed turbo before starting the engine, performed VGT calibration and started the engine. Codes no longer present.						
1	R528625	Gasket			124.56	112.10
1	DZ114164	O-Ring			46.27	46.27
1	DZ128752	Gasket			37.63	37.63

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30JUN26	114	114501489

SOLD TO: [redacted]

PAGE 2
SALE TYPE CHARGE
CUSTOMER NO. 14194304
SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89800	[redacted]	114501489	02	15JUN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15904	CHAD

		DESCRIPTION		AMOUNT
4	R543924	Washer XY	102.95	411.80
4	R543352	Stud	55.61	222.44
1	T77814	O-Ring	4.27	4.27
1	51M7039	O-Ring	6.47	6.47
1	DZ100375	Gasket	22.82	22.82
4	R539762	Flange N	8.51	34.04
1	DZ104282	TurbochaCY	9,139.42	9,139.42
2	T77814	O-Ring	4.28	8.56
2	51M7039	O-Ring	6.48	12.96
2	TY26576	COOL-GAR	62.87	125.74
20	WDF	WASTE DI	.10	2.00
1	R528035	Gasket	65.61	65.61
1	RE541291	Gasket	38.57	38.57
1	R522023	Gasket	65.98	65.98
		* LABOR *		3,240.00
		SERVICE ACCESSORIES	291.60	291.60
		ENVIRONMENTAL FEE	32.40	32.40
>>--> SEG# 02	PRT	10,356.68 LAB	3,240.00 MSC	324.00	13,920.68
		* GST/HST *		696.03	

DIAGNOSE & REPAIR OIL LEAK FROM CENTER OF MACHINE

Diagnose and repair for customer complaint of oil leak from center of machine. Visually inspected area for leaks. Found oil leaking from bottom jumper hose in loader articulation area. Relieved residual hydraulic oil pressure. Removed mounting bolts and hose. Replaced failed O-Ring. Installed hose and torqued mounting hardware to spec. Verified hydraulic reservoir oil level was within spec. Run machine

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30JUN26	114	114501489

SOLD TO: [redacted]

PAGE 3

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-89800	[redacted]	114501489	03	15JUN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15904	CHAD

DESCRIPTION		AMOUNT
and bled air from hydraulics. Checked for leaks, no leaks. Returned unused parts.		
1 T78393 O-Ring	13.05	13.05
* LABOR *		405.00
SERVICE ACCESSORIES	36.45	36.45
ENVIRONMENTAL FEE	4.05	4.05
>>--> SEG# 03 PRT 13.05 LAB 405.00 MSC	40.50	458.55
* GST/HST *	22.93	
* TOTAL GST/HST * - GST No. 899544779		770.09

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

QST # 1226957240

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	10,369.73
TOTAL LABOR	4,657.50
MISC. CHARGES	374.63
SALES TAX	0.00
PLEASE PAY THIS TOTAL ▶	16,171.95

LF-1152C

CUSTOMER COPY

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
16JUL26	114	114501620

SOLD TO:

[redacted]

PAGE 1

SALE TYPE: CHARGE

CUSTOMER NO.: 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-90211	[redacted]	114501620	01	30JUN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15968	STAN

DESCRIPTION					AMOUNT
TRAVEL TO HIGHLAND QUARRY, ABBOTSFORD					
** TOTAL LABOR **					277.50
ENVIRONMENTAL FEE				2.78	2.78
>>--> SEG# 01 PRT	.00	LAB	277.50	MSC 2.78	280.28
* GST/HST *				14.01	
REPAIR FOR BUCKET PIN NOT TAKING GREASE					
Diagnose and repair for customer complaint of left-hand side bucket pin not taking grease. Visually inspected bucket pin and found it appeared completely dry. Tried forcing grease through grease fitting located on back side of pin but no success. Removed automatic greasing line from base of boom and installed grease fitting. Applied some heat to pin and bottom of boom near grease passage. Manually forced some grease in pin. Worked bucket for a bit and forced some more grease. Purged automatic greasing system and installed fitting and grease to boom. Noticed loose fitting on right hand side so fixed it. Verified all pin taking grease.					
** TOTAL LABOR **					757.50
SERVICE ACCESSORIES				68.18	68.18
ENVIRONMENTAL FEE				7.58	7.58
>>--> SEG# 02 PRT	.00	LAB	757.50	MSC 75.76	833.26
* GST/HST *				41.66	
* TOTAL GST/HST * - GST No. 899544779					55.67

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	0.00
TOTAL LABOR	1,035.00
MISC. CHARGES	78.54
SALES TAX	0.00
PLEASE PAY THIS TOTAL ▶	1,169.21

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30APR26	114	114500248

SOLD TO: [redacted]

PAGE 1

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-88282	[redacted]	114500248	01	28JAN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15848	STAN

DESCRIPTION	AMOUNT
SEE RECENT INSPECTION REPORT/HISTORY 2494512	
>>---> SEG# 01 PRT .00 LAB .00 MSC .00	.00
CHECK & REPAIR FOR FAILED REAR AXLE TRUNNION THRUST PLATE	
BOLTS Bring loader into shop bay, install articulation lock bar. Lift rear of machine off ground and install 20-ton jack stands under machine to support. Disconnect machine batteries, remove counterweight, and saddle from machine. Disconnect fuel tank lines and electrical from tank. Support tank with fork extensions on loader. Remove bolts holding fuel tank to machine and lower tank from machine. Support rear axle with 100-ton bottle jack, while using transmission jack to support rear trunnion support. Remove bolts holding trunnion support to frame, remove support from machine. Place 12-ton stands under axle to support axle. Clean parts and inspect components for wear and damage. Install new bushing and seal into rear trunnion support, install new shims, and retain with snap ring. Install rear trunnion support onto rear axle and tighten hardware to spec. Install thrust plate and cover with new shims and hardware. Tightened to spec. Clean fuel tank of dirt buildup and install fuel tank to frame of machine. Install fuel lines and breather lines to fuel tank. Install side saddles and counterweight onto machine. Install fuel fillers to side saddles and install new battery disconnect switch. Install new batteries into machine frames	

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30APR26	114	114500248

SOLD TO: [redacted]

PAGE 2

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-88282	[redacted]	114500248	02	29JAN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15848	STAN

DESCRIPTION					AMOUNT
and connect battery cables to batteries. Install side saddle cover plates and bolt mud flaps to side saddles. Install battery hold down hardware and secure batteries. Install covers of battery compartments. Lower machine to ground, drive machine back and forth in shop and inspect rear trunnion support. Move machine outside and drive around yard, perform some heavy brake applications. Check that the rear axle is stationary and not clunking around as before. Drive machine around over some uneven ground to allow rear axle to oscillate and listen for noises coming from axle. Bring loader back into shop and inspect rear axle and trunnion support, all ok.					
12	19M7815	Screw	CY	5.82	69.84
1	T295620	Cover	CY	2,160.00	2,160.00
1	AT358357	Seal	CY	109.45	109.45
1	R57050	O-Ring	XY	14.71	14.71
6	19M9152	Cap Scre	CY	21.64	129.84
6	24M7242	Washer		5.96	35.76
1	T408388	Plate		996.80	996.80
6	T295615	Thrust W	CY	200.43	1,202.58
1	T295617	Bushing	CY	667.45	667.45
2	14M7396	Lock Nut		3.49	6.98
2	24M7298	Washer		2.40	4.80
	* LABOR *				9,400.00
1	FREIGHT-TAXABLE			125.26	125.26
(PARTS DISCOUNTED BY $728.08 KK)					
1	1472203S EXTRACT MATERIAL			1,531.25	1,531.25
1	SERVICE ACCESSORIES			500.00	500.00
	ENVIRONMENTAL FEE			94.00	94.00

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30APR26	114	114500248

SOLD TO: [redacted]

PAGE 3

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-88282	[redacted]	114500248	02	29JAN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15848	STAN

DESCRIPTION	AMOUNT
>>--> SEG# 02 PRT 5,398.21 LAB 9,400.00 MSC 2,250.51	17,048.72
* GST/HST * 852.44	

CHECK & REPAIR FOR ENGINE LEAKS

Drained coolant and engine oil. Remove engine hood, side panels, shrouding, and exhaust aftertreatment. Removed all components attached to the engine, removed all fuel lines, air induction piping and hoses, exhaust piping, removed all electrical harnesses, removed all coolant lines, removed driveshaft and engine mounts.
Disconnect engine from machine frame, cap, and cover openings. Use overhead hoist to lift engine from frame of machine. Install engine onto engine rotator stand, remove engine oil pan, and rear main seal from engine. Clean surfaces and put components into parts washer. Install new gaskets and install rear main seal housing and engine oil pan. Install new rear main seal using JD tooling to install rear seal.
Clean engine compartment of built-up dirt and grime. Move engine to wash pad and pressure wash engine of dirt and oil. Wash engine components for installation, i.e. drive damper, driveshaft, mounts.
Use overhead hoist to lift engine into machine frame, tighten engine mounting hardware, install drive damper and driveshaft to engine flywheel. Connect radiator hoses and charge air cooler piping to engine. Connect electrical connectors and connect engine starter wires. Use overhead hoist to lift muffler and intake filter frame onto machine frame, tighten frame down. Install exhaust pipe from engine

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
30APR26	114	114500248

SOLD TO: [redacted]

PAGE 4

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-88282	[redacted]	114500248	03	07APR26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	944K	1DW944KXTHE680319	FMC809	15848	STAN

DESCRIPTION				AMOUNT
turbo to muffler with new clamps and gaskets. Fill fuel tank with fuel that was removed before start of disassembly of machine. Fill engine and invertor cooling system and pressure test systems to check for leaks. Fill engine with new engine oil to proper oil level. Start engine and monitor for leaks, all ok. Run engine and monitor for leaks and codes, all ok. Move machine outside and run machine around at various rpm levels. Check fluid levels and check over machine for signs of leaks. Top up any fluids that are low, install panels that were removed from machine for engine removal.				
4	24M7240	Washer	3.60	14.40
4	19H3836	Cap Scre	13.30	53.20
2	RE537634	Speed Se	64.68	129.36
1	R530785	O-Ring XY	13.49	13.49
1	R530786	Packing CY	64.79	64.79
1	DZ130550	Filter E	214.00	214.00
1	DZ112919	Filter E	176.56	176.56
5	T77613	O-Ring	4.70	23.50
1	AN276328	Clamp XY	59.54	59.54
4	AT116380	Clamp CY	37.60	150.40
1	AT180264	Clamp CY	42.30	42.30
1	RE532183	Clamp CY	117.63	117.63
1	R528625	Gasket	90.69	90.69
1	DZ10556	Clamp	90.95	90.95
1	R529640	Gasket	81.83	81.83
1	T337997	Sleeve XY	116.51	116.51
4	RE52702	Clamp	33.71	134.84
1	T257347	Hose	145.72	145.72
1	R522023	Gasket	68.38	68.38

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C