Service History Report for - P206 Komatsu PC1250LC-8

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
22-Oct-22	Michael		$300.00	Stair damage due to swing with stairs down	
22-Oct-22	Josh	17353	$150.00	Fix broken ladder	
20-Oct-22	Michael		$950.00	Start installation of panel for transport Remove stairs, walkways and handrails start removing counter weight	
19-Oct-22	Jesse		$900.00	4x heel blocks remove & install new one x new cat wear plates Remove damage ones install new ones	
22-Sep-22	Shane	13482	$100.00	Replace worn GET wear plates on bucket	
22-Sep-22	Toddy		$100.00	Replaced 3 GET	
20-Sep-22	Shane	13473	$150.00	Fuel & grease diggers & dozers	
18-Sep-22	Jesse		$100.00	Leak clean up	
18-Sep-22	Shane		$750.00	Machine blown hose 10m from workshop Diagnose & found only 2000psi hose fitted when it should have been 6000psi Found old hose in the bin, couldn't find a problem with it, so cleaned up & fitted Fill with oil & test. OK Then it got about 500m down the track & started leaking from main valve no. 2 Valve has just been resealed Replace u/s orings & test ok	
18-Sep-22	Shane		$900.00	Finish fitting hyd pump in & check over Fix hyd leak	
17-Sep-22	Sean	13452	$1,200.00	Remove & replace water pump Make x2 hose for main pump #1 Fill hydraulic oil Fill coolant Run machine up Repair multiple leaks on main pump #1 due to incorrect seals being used	
17-Sep-22	Shane		$600.00	Refit hyd pump & plumb up all hoses	
17-Sep-22	Toddy		$800.00	Installed valve hydraulic pump and reassemble componds	
17-Sep-22	Michael	13452	$1,200.00	Remove and installation of new water pump Fill coolant tanks Fil hydraulic tanks Hydralic or fitting replace	
16-Sep-22	Shane		$350.00	Continue with hyd leak repairs	
16-Sep-22	Toddy		$700.00	Resealed high pressure pilot lines	
16-Sep-22	Michael	13452	$1,200.00	Remove & reseal control valve #2 Prep area for pump installation pump #3 Remove unwanted bearing for grease pump	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Sep-22	Sean	13452	$1,200.00	Reseal valve #2 & spilt apart Reseal high pressure screens	
16-Sep-22	Shane		$800.00	Reseal hyd pump	
15-Sep-22	Shane		$200.00	Fix oil leaks	
15-Sep-22	Sean	13452	$850.00	Reseal valve #1 & hard pipes	
15-Sep-22	Shane		$450.00	Split pumps & fit new seals	
15-Sep-22	Toddy		$200.00	Cleaned engine oils spill & sorted orings for breakdown of number 1 hydraulic pump	
14-Sep-22	Michael		$1,200.00	Remove LHS hyd cylinder to Grease upper seals Remove hand and pump hoses across door to pump #7 Remove main pump #1	
14-Sep-22	Sean	13452	$1,200.00	Replace dust seals on boom foot pin Remove main pump #1 Remove covers for pump	
13-Sep-22	Michael	13452	$600.00	500hr service	
11-Sep-22	Rhys	13412	$150.00	Check leak from under machine coming from valve and hoses	
10-Sep-22	Michael		$50.00	Fit new teeth Top up coolant Fill hydraulic oil head	
06-Sep-22	Dayle		$1,000.00	R+R radiator	
06-Sep-22	Shane		$300.00	Rear radiator core leaking. Repair	
06-Sep-22	Toddy		$600.00	Repair radiator core	
02-Sep-22	Sean		$300.00	Service	
29-Aug-22	Shane	16342	$150.00	Check over & grease bucket pins Test auto greaser, OK.	
28-Aug-22	Jack	12281	$200.00	Grease leaks	
27-Aug-22	Jack	13281	$100.00	Greased	
27-Aug-22	Harry		$110.00	Take bolts out of ear	
23-Aug-22	Sean	132011	$250.00	A/C freezing over Checked pressure & no leaks	
14-Aug-22	Rhys	13154	$100.00	Replace bucket tooth	
14-Aug-22	Shane	13166	$100.00	Refit LH outer bucket tooth	
10-Aug-22	Shane	16099	$850.00	Diagnose fuel leak as no. 2 injector line Remove covers & filter housings to get acess Make up tool to get to injector end of pipe Remove pipe R&R #2 pipe. Test. OK.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
09-Aug-22	Jack	13059	$800.00	C/O water pump Looked for fuel leak	
09-Aug-22	Jesse		$1,050.00	Bucket repairs Remove four heel blocks Weld on new heel blocks Goug out cracks Remove old CAT wear base Install 25 biz on missing area Prestart & weld out dress welds	
08-Aug-22	Jack	13058	$100.00	Topped up oils & coolant	
07-Aug-22	Shane	13093	$200.00	Search all parts for coolant and oil leaks	
04-Aug-22	Shane		$100.00	Top up coolant & R+R GET	
04-Aug-22	Jesse S		$200.00	Carry out welding repairs on rock guard L/H middle	
04-Aug-22	Shane	13061	$200.00	Check over Track guide stripped bolts and bent up Assist with welding into place Replace bucket wear plates	
03-Aug-22	Jack	13058	$100.00	Broken rock guard	
03-Aug-22	Shane	13662	$100.00	Fix mirror	
02-Aug-22	Jack	13052	$200.00	Repaired horn fault Cleaned out cooler pack	
02-Aug-22	Shane		$300.00	Look at overheating fault Fix horn	
02-Aug-22	Alexander	13052	$82.50	Remove air horn selenoid & clean Install & test	
01-Aug-22	Jack	13046	$200.00	Bucket repairs, teeth C/O	
31-Jul-22	Jack	12987	$165.00	Rock guard Boom to stick pin bolts	
31-Jul-22	Sean Grieve	12998	$110.00	Bucket & chain guide repairs	
31-Jul-22	Shane		$55.00	Make up 3 hyd hoses	
30-Jul-22	Jack		$220.00	Loose stick pin bolt Stair fault Oil leaks	
29-Jul-22	Shane		$55.00	Top up hyd oil	
28-Jul-22	Sean Grieve	12970	$385.00	Change engine cooler out	
27-Jul-22	Jack	12970	$110.00	Stair/handrail modifaction	
27-Jul-22	Shane		$300.00	Fit new stop controller and proxy sensor Adjust and check operation - OK	
26-Jul-22	Sean Grieve	12980	$165.00	Change door out & coolant leaks	
26-Jul-22	Shane		$55.00	Fit new tooth	
25-Jul-22	Alex	12970	$495.00	Replace door on cab Remove guards to inspect coolant leak Repair grease lines	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
25-Jul-22	Shane	12956	$150.00	Engine temp getting warm Top up coolant Run machine Reverse fan and blow out coller pack	
24-Jul-22	Xander	12960	$55.00	Replace lip shroud	
24-Jul-22	Xander	12960	$137.50	500hr service	
24-Jul-22	Sean	12960	$300.00	250hr service & c/o lip shrouds & coolant	
23-Jul-22	Xander	12950	$110.00	Inspect coolant leak Found radiator core leaking & thermostat hose cracked	
23-Jul-22	Sean	12950	$400.00	C/O doors Diagnose coolant leaks	
22-Jul-22	Xander	12960	$330.00	Replace grease dozers on boom X2 Bleed grease system Remove panels to find coolant leak Found LH radiator core leaking Installed guards Fill coolant	
20-Jul-22	Xander	12920	$330.00	Replace bucket wear plates Grease & fuel Check over Fill coolant	
18-Jul-22	Shane	12901	$110.00	Engine running warm Coolant level low Top up & check for leaks. Ok. Start up & check	
16-Jul-22	Shane	12872	$100.00	Fire suppression alarm going off Low pressure Remove power supply from control panel	
14-Jul-22	Jack	12889	$100.00	RH rock guard	
12-Jul-22	Jack	12832	$500.00	Pos 1&3 tooth Chain guard	
11-Jul-22	Jack	12845	$600.00	Chain guide Tooth changed/repaired Grease fault	
11-Jul-22	Sean	12845	$600.00	Weld chain guide Change teeth Grease fault	
08-Jul-22	Sean	12758	$150.00	H link pin	
28-Jun-22	Michael		$100.00	Repairs to grease lines Fit new wear pads	
28-Jun-22	Shane		$100.00	Fix grease line & wear pads	
27-Jun-22	Shane		$100.00	Repair grease lines	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
27-Jun-22	Michael		$100.00	Get bucket change outs	
23-Jun-22	Shane		$200.00	R+R blown hose on hyd pump	
22-Jun-22	Michael		$250.00	Remove and replace blown hydraulic cooler hose	
21-Jun-22	Shane	12669	$200.00	Prestart checks Grease bucket pins Check over machine - over heating Reverse fan and blow radiator out	
20-Jun-22	Shane	12664	$200.00	Finish off repairs Top up hydraulic oil level and check operation Tighten loose track guard bolts	
19-Jun-22	Shane	12664	$600.00	Re-assemble engine and refit all covers	
19-Jun-22	Alex	12664	$206.25	Reseal steel lines on control valve	
19-Jun-22	Shane	12664	$150.00	Hyd oil leaks	
18-Jun-22	Shane	12664	$200.00	Organise parts and driver to pick up	
14-Jun-22	Shane	12664	$850.00	Install EGR cooler	
12-Jun-22	Shane	12664	$600.00	Remove EGR cooler	
12-Jun-22	Lain				
			$247.50	Replaced lip shrouds and side plates on bucket Filled up auto greaser	
11-Jun-22	Shane	12664	$450.00	Check machine Top up with coolant - coolant leaking from exhaust manifold Remove EGR cooler Start to remove cooler	
11-Jun-22	Shane		$400.00	Check out coolant leak	
10-Jun-22	Lain	12640	$82.50	Greased machine Topped up engine oil and hydraulic oil	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
10-Jun-22	Shane	12664	$200.00	Check over machine - blowing a lot of white smoke and running hot	
08-Jun-22	Shane	12636	$150.00	RH outer tooth missing Fit worn tooth with new retainer	
07-Jun-22	Alex	12604	$60.00	Grease and inspect	
06-Jun-22	Alex	12594	$165.00	Replace x6 wear plates Replce x1 bucket tooth	
02-Jun-22	Lain	12555	$123.75	Greased, blew out air filters Machine check over Replaced rear plate on bucket	
27-May-22	Shane	12556	$100.00	Grease bucket pins and check over	
26-May-22	Shane	12498	$400.00	Continue with electrical fault diagnosis Found no power getting to hyd isolator lever switch Check fuses - OK Run new power wire to switch, test - OK Re-assemble machine	
25-May-22	Shane	12496	$900.00	Carry out 500hr service Remove, make and refit CAC fan hoses Tighten loose grease lines on H-link Machine lost hyd's and wait start Fault find problem	
23-May-22	Shane	12486	$200.00	Check over machine Grease bucket pins All machine checks	
20-May-22	Shane	12446	$200.00	Prestart and grease bucket pins	
19-May-22	Shane	12438	$200.00	Machine check over and pre-starts	
18-May-22	Shane	12428	$100.00	Grease Checkover and fit new air solenoid for auto greaser	
16-May-22	Alexander	12405	$206.25	Replace bucket teeth	
14-May-22	Lain	12386	$82.50	Greased machine Topped up hydraulic tank Blew out filter	
13-May-22	Lain		$123.75	Greased, topped up hydraulic oil and blew out air filters	
07-May-22	Shane	11320	$100.00	Dailt check over and grease.	
06-May-22	Shane	11317	$200.00	Daily check over and grease, change out and test faulty grease doser for RH lift cylinder.	
05-May-22	Shane	11308	$100.00	Daily grease and checks.	
04-May-22	John	12255	$660.00	Fit New bottom coolant hose, fill coolant, fit new fuel filters, fill eng oil, put stick in wash bay, remove stick cylinder for reseal	
04-May-22	Shane	11299	$100.00	Daily check over and grease.	
03-May-22	Shane	11294	$100.00	Check over and grease bucket pins	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-May-22	Shane O	11280	$400.00	Machine walked out of RH track on sprocket end. Paperwork, site prep and refit track and adjust.	
29-Apr-22	Shane O	12271	$1,050.00	Move all machines of cut behind digga, finish reverse camera install, diagnose repair wiring for stair alarm. Repair oil leaks at control valve under floor rear engine,	
28-Apr-22	Shane O	12271	$850.00	Fit new valve solenoid assemblies for steps on walk way, wire up solenoids and check	
13-Apr-22	Shane O		$100.00	Manually grease bucket.	
10-Apr-22	Harry F	12257	$176.00	Install tracker	
08-Apr-22	Seb Zumbo		$792.00	Make grease lines for stick/fit sfter getting crimped Reseal grease dosers for stick/spare Fit new grease dosers Hose to stick Load stick auto truck Load counterweight and other machine parts on truck	
08-Apr-22	Jack O'Neil		$1,500.00	Clean up bucket bores Tap holes Install pins, retainers, seals and shims Install throttle position sensor Run/test Remove boom cyl head end and install seals Reinstall boom cyl and shims Install all belly guards Install guards Remove ladder Bolt radiator grill down Load on truck	
08-Apr-22	Jack		$550.00	Clean up bucket bores, tap holes, install pins+retainers+seals+shins, install throttle position sensor, remove boom cyl head end and install seal, re install, install all belly guards, remove ladder, bolt radiator grill down, load on	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Apr-22	John	12255	$522.50	Fit remaining grease dosers, fit new rh lift cyl boom seals, fit new bolts and bushes to high pressure screen plate, fit belly guards.	
07-Apr-22	Jack		$550.00	Install pilot hoses, route hoses, install joysticks and covers, install right hand boom cylinder, diagnose E14 CA132 Code, throttle speed sensor, install covers	
07-Apr-22	Seb Zumbo		$264.00	Install and tension wheels Clean and install H frame bearings Start replacing grease dosers	
07-Apr-22	Jack O'Neil		$1,000.00	Install pilot hoses Route hoses Install joysticks and covers Install right hand boom cylinder Diagnose E14 CA132 code Failed throttle speed sensor Track to wash bay Install covers	
07-Apr-22	Shane	12200	$120.00	Reseal grease doors for stick	
07-Apr-22	John	12255	$572.50	Refit ppc lines under hyd tank, fit rh boom cylinder, start refitting guards and walk ways, fill out paperwork	
06-Apr-22	John	12255	$605.00	Fit new boom plant stickers, remove lh boom cylinder barrell, wash stick, pallet up handrails, refit RH joystick pilot hoses	
06-Apr-22	Jack O'Neil		$1,000.00	Strip and reseal travel valve Install pilot hoses to joysticks in cab Install joysticks	
06-Apr-22	Shane		$700.00	Chase up and sort out bucket bushes Bring stick to w/shed Test all, grease dozers Order extra doses for bucket pins Organise fittings and hose to plumb up all doors Assist with refitting pilot hoses Remove bucket hoses to get spares made	
06-Apr-22	Jack		$550.00	Strip and re seal travel valve, install pilot hoses in cab, install joysticks	
05-Apr-22	Harry H		$275.00	Clean wheel motor housing, put guards for wheel motor, clean belly, put all guards on.	
05-Apr-22	Jack O'Neill		$550.00	Remove front windscreen, remove glass, clean up, install new glass, reinstall fron window, adjust latch, remove joysticks, remove panels, remove and mark hoses, clean hoses	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
05-Apr-22	Jack O'Neil		$1,000.00	Remove front windscreen window Remove glass Clean up window frame Install new glass and let set Re-install front window Adjust window latch Remove left and right joystick Remove panels Remove and mark all pilot hoses Clean hoses	
05-Apr-22	Shane		$600.00	Reseal and refit stick cylinder rod Remove LH lift cylinder to reseal rod and barrel damaged Assist with pilot hoses under cabin Tidy up greaser and fix grease leaks	
05-Apr-22	John	12255	$577.50	Reseal stick cylinder, remove lh lift cylinder, check over bucket, check over stick, remove boom plant numbers.	
04-Apr-22	Shane		$320.00	Check over stick and bucket and organise missing parts Bring stick assembly to wash bay to get washed Remove stick cylinder rod to get resealed	
01-Apr-22	John	12255	$550.00	Reseal leaking valve spool caps Fit new bottom radiator hoses Repair harness Reseal valve relief valves Clean up under machine	
31-Mar-22	Craig	12255	$385.00	Relocate fire suppression actuator on engine cowling Connect grease pump to external air supply Carry out audit on grease system	
31-Mar-22	Jackson	12255	$495.00	Repair electrical wiring Re-seal leaking valves 250hr service	
31-Mar-22	Harry		$79.75	Fix top hinge Put new one on	
31-Mar-22	John	12255	$522.50	Repair electrical harness Remove guards Start to remove high pressure screen hose	
30-Mar-22	Jackson	12255	$165.00	Replace turbo pipe gasket Remove bracket for repair	
30-Mar-22	Craig	12255	$467.50	Clean work area Remove hoses from RH boom cylinder Remove barrell end Set up and remove retainers, seals and bearing Install new bearing Decommission fire suppression to relocate engine bay actuator Remove 1/4" signal line from bottle to engine bay	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
29-Mar-22	John	12255	$577.50	Repair electrical harness around main valves, under engine and cab	
29-Mar-22	Harry		$55.00	Had to fix stand that held stick on	
29-Mar-22	Craig	12255	$357.50	Set up and remove LH boom cylinder head end pin Clean up pin bores and bearing for reusability evolution Clean out block grease holes in bearing install new pin only Remove pin from RH boom cylinder	
28-Mar-22	Craig	12255	$82.50	Locate and clean PTO breather Remove hoses between jumbo 3 & 4 Remove fittings from jumbo 4 Reseal, remove covers from travel motors	
28-Mar-22	John	12255	$577.50	Fit new pto pump hoses Clean out horn solenoid Get horn working Fix all air leaks around air tank	
18-Feb-22	Jackson		$247.50	Remove 1250 bucket, disconnect bucket hoses.	
17-Feb-22	Jackson		$110.00	start disassembling machine.	
17-Jan-22	John C	12167	$55.00	Grease, hyd oil	
09-Jan-22	John	12108	$110.00	Blow out evap and blow out condensor	
08-Jan-22	John	12102	$82.50	Gas AC	
07-Jan-22	John	12086	$55.00	Fill hyd oil and check oils	
10-Dec-21	Jackson	11993	$110.00	Grease machine, top up hyd oil	
09-Dec-21	John	11983	$165.00	grease, prestart.	
09-Dec-21	Jackson	11983	$82.50	Grease, Prestart	
07-Dec-21	Jackson	11963	$165.00	Fit new compressor, replace coolant over flow hose.	
07-Dec-21	John	11963	$165.00	Fit new compressor	
05-Dec-21	J Ciappara	11963	$82.50	try to get compressor working	
04-Dec-21	J Ciappara	11963	$330.00	Diagnose air compressor failure	
03-Dec-21	J Ciappara	11961	$110.00	Fit new top radiator hoses	
30-Nov-21	J Ciappara	11961	$247.50	Diagnose coolant leak	
29-Nov-21	Jackson	11946	$82.50	fill auto greaser, clean out grease actuator	
22-Nov-21	JohnCiappara	11914	$110.00	Fit horn button	
21-Nov-21	Jackson	11906	$55.00	Fill hyd oil	
19-Nov-21	Jackson	11891	$55.00	Grease machine	
19-Nov-21	JohnCiappara	11891	$55.00	Grease	
16-Nov-21	Jackson	11862	$110.00	Pre-start Grease Fill hydraulic oil	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Nov-21	JohnCiappara	11862	$110.00	Pre-start Grease Fill hyd oil	
11-Nov-21	JohnCiappara	11848	$55.00	Fill auto greaser	
10-Nov-21	JohnCiappara	11848	$220.00	Fit new horns Grease	
10-Nov-21	Greg Mills	11828	$220.00	Fit new horns Grease machine 3 times during the day	
09-Nov-21	JohnCiappara	11828	$82.50	Grease Pre-start	
24-Oct-21	JohnCiappara	11720	$275.00	Repair hydraulic leak	
22-Oct-21	JohnCiappara	11694	$137.50	Fit horn	
21-Oct-21	JohnCiappara	11685	$55.00	Swap bolts around track guides	
19-Oct-21	JohnCiappara	11668	$110.00	Adjust tracks Get auto greaser working	
03-Oct-21	John C	11591	$55.00	Repair air leak	
02-Oct-21	Greg Mills	11580	$55.00	Repair lights Replace travel alarm	
01-Oct-21	Greg Mills	11580	$110.00	Fill auto greaser Grease machine	
30-Sep-21	Greg Mills	11580	$165.00	Fit bucket Repair auto greaser fault	
30-Sep-21	John C	11579	$192.50	Fit bucket	
29-Sep-21	John C	11579	$632.50	Fit new stick bushes Diagnose ladder problem Try to fit bucket	
29-Sep-21	Greg Mills	11580	$660.00	Fit bushes to stick Diagnose & repair ladder fault Diagnose air leak Start to fit bucket - had to cut off spacer	
28-Sep-21	John C	11579	$165.00	Fit stick	
17-Jul-21	Duncan	11296	$357.50	Fit A/C compressor Fit new plug to harness Fit fan belt Replace receiver dryer Attempted to charge system. No power to compressor Found melted fuse. Attempted to remove fuse. Broken off in there Will need external one wired in # Noticed crack in boom	
15-Jul-21	Duncan	11296	$55.00	Completed FFP inspection	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
12-Jul-21	Duncan	11288	$247.50	Completed Pre-start & grease Replaced broken grease nipple on bucket pin Attempt to start - flat batteries. Jump started. Checked charge rate. Only 22V. Checked alternator. No belt. Found seized HC Compressor. Ordered compressor Use dumpy to charge batteries to keep working machine	
09-Jul-21	Duncan	11271	$165.00	Cut off old bass on RH lip shroud Welded new boss in and fitted lip shroud	
01-Jul-21	A Mills	11257	$55.00	Prestart machine grease and check over machine.	
30-Jun-21	A Mills	11248	$55.00	Pre start digger grease and check over	
29-Jun-21	John C	11234	$137.50	Grease Pre-start Fit new pin to goanna bar Assist with fire suppression	
28-Jun-21	John C	11224	$55.00	Pre-start Grease	
27-Jun-21	John C	11214	$55.00	Grease Pre-start	
26-Jun-21	Duncan	11203	$110.00	Pre-start Grease Remove step for repair	
25-Jun-21	Duncan	11192	$220.00	Pre-start Grease Auto greaser not working Check air pressure. No air pressure Traced air lines. Found blown hose from air tank to govenor valve Replaced hose fittings Checked auto grease. Ok	
24-Jun-21	Duncan	11182	$55.00	Pre-start Grease	
23-Jun-21	Duncan	11171	$55.00	Pre-start Grease	
22-Jun-21	Duncan	11162	$55.00	Pre-start Grease	
19-Jun-21	Duncan	11161	$55.00	Pre-start Grease	
18-Jun-21	Duncan	11151	$55.00	Pre-start Grease	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
17-Jun-21	Duncan	11149	$522.50	Blown hose top of bench Remove floor next to engine bay Remove blown hose from pump bay to rear main valve Remove 2 Pilot lines & PTO hose in pump bay as well (Known leaks) Sent hose to town Replaced o-ring on rear main valve Resealed T piece top of solenoid valves Measured bolts in solenoids Fitted pilot hoses, PTO hose & main pressure hose to main valve Top up hyd oil. Washed down machine. Fitted floor.	
16-Jun-21	Duncan	11137	$55.00	Pre-start Grease	
15-Jun-21	Duncan	11130	$440.00	Replaced pilot hoses x 3 from pump to under 2 front main valves Replaced hose top of solenoid valves Replaced 3 link pilot hoses between 2 front main valves Replaced 4 relief valve o-ring on LH worn valve	
14-Jun-21	Duncan	11122	$55.00	Pre-start Grease	
13-Jun-21	John	11115	$82.50	Fit old tooth to bucket repair Seat belt	
12-Jun-21	B Swan		$55.00	Pre start machine	
11-Jun-21	B Swan		$55.00	Pre start machine	
10-Jun-21	B Swan	11093	$412.50	Complete 1000hr Service Reseal x 5 relief valves under lower walkway floor Weld on x 1 CAT wear plate adapter Change out x 2 wear plates	
10-Jun-21	John	11093	$302.50	1000hr service Weld on CAT wearplate adapter	
09-Jun-21	B Swan		$110.00	Pre-start machine R/R x 1 wear plate Refit tooth & top greaser	
07-Jun-21	B Swan		$55.00	Pre-start machine Grease etc	
01-Jun-21	Duncan S	11005	$55.00	Prestart and grease	
31-May-21	Duncan S	10995	$110.00	Prestart and grease. Oxy out broken retainer on wear plate on bucket. Fitted new wear plate	
30-May-21	Duncan		$55.00	Pre-Start Grease	
29-May-21	John	10975	$55.00	Grease Pre-start	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
28-May-21	Duncan	10965	$55.00	Pre-start Grease	
27-May-21	Duncan	10955	$82.50	Investigate oil leaks Complete Pre-start, grease	
26-May-21	Duncan	10945	$82.50	Complete Pre-start & grease Replaced 2 wear plates on bucket	
23-May-21	Duncan	10926	$357.50	Remove floor plates next to engine Replaced o-ring on return back on main valve next to engine Resealed 2 relief valves top of main valve block Resealed 2 relief & pilot fitting on LH side of RH main valve block. Cleaned arouind all 3 main valve blocks Clean & investigated leaks on front of excavator - ordered seals Replaced broken grease fitting on bucket pin Greased bucket	
20-May-21	Duncan		$55.00	Complete pre-start Grease	
16-May-21	B Swan	10859	$55.00	Pre start machine	
16-May-21	John	10873	$55.00	Fit new CAT wear plate.	
15-May-21	B Swan	10870	$55.00	Pre start machine	
14-May-21	B Swan	10864	$110.00	R/R air control valve. Fix up mount and tidy up harness. R/R x2 wear plates on buckets.	
14-May-21	B Swan	10860	$55.00	Pre Start machine and grease.	
13-May-21	John	10845	$55.00	Test starter motors.	
13-May-21	B Swan	10845	$110.00	Test poor start. Test both starters. Check earths.	
13-May-21	B Swan	10842	$55.00	Pre start machine and grease.	
12-May-21	B Swan	10830	$55.00	Pre start machine and grease	
11-May-21	B Swan	10849	$55.00	Pre start and grease.	
11-May-21	B Swan	10854	$75.00	Re adjust grease injectors.	
10-May-21	B Swan	10840	$55.00	Drop oil out of drop box to level (engine oil leaking into drop box.)	
08-May-21	Duncan Steve	10814	$220.00	Check operation of auto greaser in morning. OK. Made 2 bolts and drilled out mounting holes for hyd steel line bottom LH of pump housing. Fitted 2 bolts to secure line Greased bucket	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
07-May-21	Duncan Steve	10814	$440.00	Replaced leaking hyd hose from bottom of pump housing to top pump. Replaced O-Ring on load sensing/pilot lines in pump area. Filled auto greaser. Removed air water/regulator/oiler. Cleaned and re-assembled. Reoplaced air lines on auto greaser. Tested auto greaser. OK.	
06-May-21	Duncan	10809	$55.00	Performmed pre start and grease.	
05-May-21	Duncan	10800	$192.50	Blown o-ring. Replaced o-ring bottom left of pump area. Filled hyd tank. Walked down from bench.Top up OT. Performed pre start and greased.	
05-May-21	J.Ciappara	10800	$165.00	Fit new bolts to hyd pump pressure line. Fill hyd oil.	
04-May-21	J. Ciappara	10800	$110.00	Fit o-ring to pump pressure line.	
04-May-21	Duncan Steve	10797	$137.50	Complete pre-start & grease Battery light on. Check charge rate. Ok. 27V Repaired broken wire on alternator. Light out.	
03-May-21	Duncan	10791	$55.00	Complete pre start and grease	
02-May-21	Duncan	10781	$137.50	Pre-start & grease Removed cab over bucket croud pin. Tap out threads 1 ….. Stripped. Cleaned up Skin cap and fitted	
01-May-21	Duncan	10771	$165.00	Pre-start & grease Low engine oil to full mark Replace bucket teeth	
30-Apr-21	Duncan	10761	$55.00	Pre-start & grease	
29-Apr-21	Duncan	10751	$55.00	Pre-start & grease	
28-Apr-21	Duncan	10791	$165.00	Pre-start & grease Auto greaser fault. Remove tap. Fill auto greaser. Stir grease Pump working & completing cycles	
27-Apr-21	Duncan	10731	$55.00	Prestart & Grease	
18-Apr-21	Duncan	10690	$82.50	Complete Prestart, grease & top up hyd oil	
17-Apr-21	Duncan	10679	$137.50	Complete Prestart & grease Removed snapped retaining bolts from bucket pin Tapped out threads Fitted new bolts and tightened.	
16-Apr-21	Duncan	10668	$55.00	Complete Prestart & grease	
15-Apr-21	Duncan	10656	$165.00	Complete Prestart & grease Replaced O-ring on hose to front slew motor. Top up slew motor hyd oil	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
14-Apr-21	John	10646	$110.00	Grease Pre-Start Quarterly	
12-Apr-21	John	10653	$165.00	Weld on lip shroud boss	
12-Apr-21	A Mills		$220.00	Cut off old weld Unable to read the rest	
08-Apr-21	A Mills	10625	$55.00	Grease & clean tracks off Top up oils	
07-Apr-21	A Mills	10619	$27.50	Grease bucket & top up coolant	
06-Apr-21	A Mills	10608	$110.00	Tooth retainer missing Clean tooth and fit new Tighten retainer cap on bucket pin Chase up lip shroud for digger	
05-Apr-21	John	10605	$82.50	Check a/c Reverse cooler fan	
04-Apr-21	A Mills		$13.75	Pre-start	
04-Apr-21	John	10592	$55.00	Fit new bucket wear	
04-Apr-21	A Mills		$27.50	A/C not working Blew out cooler	
02-Apr-21	A Mills		$55.00	Grease bucket & check	
30-Mar-21	A Mills		$55.00	GET missing off bucket ……Fit new one	
27-Mar-21	A Mills	10531	$632.50	Weld grease pot back on platform Replace 3 bucket - stick lines Clean & adjust various injectors. Down day Inspect top fluids Reseal x 3 solenoids on valve block Replace x 2 coolant lines, 2 compress on Weld grease line mounts on day bono Repair boom lift hyd fault	
16-Mar-21	A Mills		$220.00	Joy stick hoses leaking Pull out hoses, took to town & got new ones made	
11-Mar-21	A Mills		$165.00	A/C evap blocked Pulled out seat and b…. Cleaned out and fitted again	
11-Mar-21	John	10511	$55.00	Grease bucket, clean ear plugs	
09-Mar-21	John	10493	$55.00	Gas a/c	
09-Mar-21	A Mills		$82.50	Gas A/C	
08-Mar-21	John	10488	$55.00	Check pilot leak in cab	
08-Mar-21	A Mills	10488	$55.00	Seat belt stuck & pilot hose leeks	
07-Mar-21	A Mills		$110.00	Fuel leak on filte3r hose	
05-Mar-21	John	10461	$220.00	Check codes, check egr wiring Check general wiring	
05-Mar-21	A Mills		$137.50	Electricla problems test Pumps & solenoid	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Mar-21	A Mills		$165.00	Electrical wiring Top up oils	
04-Mar-21	John	10435	$192.50	Repair electrical wiring Top up oils	
03-Mar-21	A Mills		$467.50	Repair electrical wiring on machine Elec fault finding codes	
03-Mar-21	John	10435	$412.50	Chase fault codes Repair electrical wiring	
02-Mar-21	John	10435	$55.00	Fill hydraulic oil Check for leaks	
02-Mar-21	A Mills		$55.00	Check hyd hoses for leaks Run up machine	
26-Feb-21	A Mills		$275.00	Fit hand rails Plumb up grease line Purge system	
25-Feb-21	A Mills		$385.00	Assemble digger	
25-Feb-21	John	10456	$550.00	Assemble	
23-Feb-21	Connor		$137.50	Pick up paint and paint hand rails	
23-Feb-21	DaveMarshall		$82.50	Fabricate and install handrails	
23-Feb-21	Ted Van		$27.30	Clear NPM FFP & HV Actions	
22-Feb-21	Ted Van	10450	$55.00	Clear NPM HVA FFP Actions	
19-Feb-21	ClayBennett		$55.00	Take belly plate off & drop coolant	
18-Feb-21	ClayBennett		$27.50	Hydraulic hoses	
18-Feb-21	Zumbo	10451	$330.00	Change hyd hoses Fit counter weight Move and wash oil mess. Clean up	
18-Feb-21	Ted Van		$27.50	Fit counterweight	
17-Feb-21	Zumbo	10451	$522.50	Install all rocker covers with new gaskets Install cover & guards Start and run engine. Check oilo pressure Drain & fill engine oil Replace oil filters, replace leaking hyd hoses	
17-Feb-21	ClayBennett		$13.75	Put new hydraulic hoses on	
15-Feb-21	Kyle M		$137.50	Excavator bucket rebuild	
15-Feb-21	Zumbo	10451	$165.00	Clean up mess Install fitting into pump	
12-Feb-21	Kyle M		$82.50	Excavator bucket rebuild	
12-Feb-21	Zumbo		$522.50	Remove rocker covers. Clean top of engine Clean & assemble oil coolers Clean rocker covers Clean & install sump & pick up Fill with coolant Remove & drain oil filters	
11-Feb-21	Kyle M		$137.50	Bucket rebuild	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
11-Feb-21	Zumbo		$357.50	Troubleshoot test & inspect using camera to find water leak Order parts.	
10-Feb-21	Kyle M		$82.30	Excavator bucket rebuild	
10-Feb-21	Zumbo		$412.50	Install lower rock guard bolts Remove sump from under engine. Make plates & pressure test engine oil coolers Remove oil thermostats & install oil coolers. Pressurize cooling system & inspect. Leak. Measure hosing & check fittings to be made	
09-Feb-21	Ted Van		$27.50	Remove counterweight	
09-Feb-21	Kyle		$357.50	Bucket Rebuild	
08-Feb-21	DaveMarshall				
			$302.50	Repair underan guard mounts Repair bucket	
08-Feb-21	Kyle M		$330.00	Guard repairs Exc bucket rebuild (206/237)	
08-Feb-21	Zumbo		$522.50	Install all handrails & covers Install rock guards Install extra bolts into guards	
06-Feb-21	Connor		$82.50	Put belly guards on	
06-Feb-21	Clay		$275.00	Fit belly plates	
06-Feb-21	Ted Van	10450	$220.00	Refit covers	
05-Feb-21	Zumbo		$220.00	Move ladder over & weld miounts Fill hyd tank Remove remaining hand rails for paint Mark all mounting points	
04-Feb-21	Zumbo		$357.50	Fit rock guard RHS pump up track Install decals. Replace pilot hyd lines Drain & fill final drives Fill grease tank Breather hose to ground level on hyd tank	
04-Feb-21	Kyle M		$275.00	Hand rail Modification/Repair	
04-Feb-21	Ted Van	10450	$467.50	Complete NPM FFP & HV Inspections Fit site required stickers Clear FFP actions	
03-Feb-21	Zumbo		$412.50	Fit counter weight, boom cyl, repair deisel leak Repair operators seat.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
03-Feb-21	Clay	10450	$247.50	Replace split tube on wiring harness	
03-Feb-21	Ted Van	10449	$206.25	NPM FFP Report Assist with fitting boom cylinders Fit counterweight	
03-Feb-21	Kyle M		$412.50	Counter weight install Hand rails repairs Soft ladder repairs	
02-Feb-21	Ted Van	10448	$192.50	Rig up to fit boom Fit cover & reconnect fire supression system Fit boom	
02-Feb-21	Zumbo		$412.50	Clean boom bushes Install & shim boom, connect hoses Install decals Estop & fill with coolant	
02-Feb-21	Jackson		$55.00	Remove fire supression bottle Fix excelerator, arm / boom	
02-Feb-21	Clay		$55.00	Clean shims, boom rail Hand rails	
01-Feb-21	Ted Van	7268	$110.00	Strip water pump	
01-Feb-21	Brad Smith	42318	$220.00	Locate oil leak Re torque oil filters Refil engine oil Wash out radiator & belly plates	
29-Jan-21	Will Paull	10448	$357.50	Replace hoses Reseal fittings Remove water pump and clean	
29-Jan-21	Ted Van	10448	$288.75	Fit power…… & diagnose not operating Repair slew ring transducer wiring Check power to motor - Found motor not working Refit track motor covers Drop boom cylinders for boom fitting	
28-Jan-21	Will Paull	10448	$440.00	Chase oil leaks Replace fuel line - order parts	
21-Jan-21	Connor		$110.00	Croc sleeved blow off lines	
21-Jan-21	Will Paull	10488	$275.00	Find leak Order parts Assist sparkie - conduit wires Sleeve hoses Start check levels Take to wash bay	
20-Jan-21	Connor		$110.00	Split fuel line	
20-Jan-21	Will Paull		$591.25	Secure hoses Change fuel hose & hydraulic hose Prime fuel Trouble shoot no stacking (auto elec) Top up hydraulic oil - change engine oil	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
19-Jan-21	Connor		$536.25	Installed boom pivot hoses Checked all oils Installed P clamps Started getting ready for wash bay Washed belly guards & filled hydraulic oil tank	
19-Jan-21	Ted Van	10448	$110.00	Reconnect lines to swivel	
19-Jan-21	John C	12186	$110.00	Grease fill auto greaser, get auto greaser working	
18-Jan-21	Connor		$453.75	Hydraulic hoses	
18-Jan-21	Ted Van	10448	$550.00	Remove broken steps bolts from LH undercarriage Continue with replacing u/s hydraulic hoses Reseal leaking fittings	
18-Jan-21	Will Paull		$591.25	Replace u/s hoses Clean area Fit P clamps Start to fit swivel	
17-Jan-21	Lindsay		$27.50	Assist Connor with croc sleeving hoses	
16-Jan-21	Will Paull	10488	$302.50	Fit new hoses - assemble swivel	
16-Jan-21	Connor		$275.00	Replaced 2 hydraulic lines	
15-Jan-21	Ted Van	10448	$522.50	Identify hydraulic hoses for replacement Remove RH track motor hoses & clean out cavity Dismantle LH console & identify hose for replacement Repair wiring to autogreaser module	
15-Jan-21	Will Paull	10488	$591.25	Identify & mark u/s hoses Remove guards Remove u/s hose to be made & install new	
15-Jan-21	Connor		$302.50	Marked hoses & replaced with new ones	
14-Jan-21	Ted Van	10448	$522.50	Replace missing RH bucket cylinder Retract pipe assembly & refit stick cylinder hose Replace missing clamp. Reseal stick cylinder piping & check valve assembly on boom. Remove broken bolts from retainer Secure check valve assembly Fit croc sleeve to PTO cooler hoses Repair wiring & starter motors - fit insulation covers Replace heater hoses Remove machine - boom hose for replacement	
14-Jan-21	Connor		$522.50	Removed remaining fuel lines Put croc sleeve over fuel lines Put fuel lines back & P clamps	
14-Jan-21	Will Paull	10488	$591.25	Reseal fittings & pipes - sleeve hyd fan hoses Assist Connor with fuel hoses	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
13-Jan-21	Connor		$385.00	Remove fuel lines ready for sleeve Put sleeve on fuel line	
13-Jan-21	Ted Van	10448	$275.00	Continue resealing & assemble boom cylinders Kievlar sleeve boom cylinder hoses	
13-Jan-21	Will Paull	10488	$495.00	Reseal swivel Start to reseal bottom pump - fit flex coupling Fit fuel primer pump Assist Ted with boom cylinders Assist Connor with fuel lines	
12-Jan-21	Will Paull	10488	$605.00	Reseal main valve Start to reseal bottom pump (1) Start to reseal relief valves on main valves (need O-rings) Assist Ted with boom cylinder Assist Connor with fuel lines Remove swivel valve to reseal	
12-Jan-21	Ted Van	10448	$522.50	Reseal boom cylinders	
12-Jan-21	Connor		$357.50	Checked oil Take off belly guards Put new O-rings in pilot valve Took P clamps off Took fuel line out	
12-Jan-21	KyleMusgrave		$137.50	Fabricate a plate	
11-Jan-21	Ted Van	10448	$522.50	Remove broken track guide Re-tap threads - grind back old welds Organise new bolts Start strippind RH lift cylinder for reseal	
11-Jan-21	Connor		$137.50	Top up oil and check over	
11-Jan-21	Will Paull	10488	$605.00	Reseal valves Assist Ted with boom cylinder	
09-Jan-21	Ted Van	10448	$165.00	Remove front screen for glass replacement Free up & lubriate screen cable Replace air filter inductor Remove broken bolts & repair covers Start repairing threads for rock guard	
08-Jan-21	Will Paull		$577.50	Remove fuel primer pump Reseal pilot valve fittings Remove flex coupling Assist Connor - Assist Ted Drain Hyd oil	
08-Jan-21	Ted Van	10448	$467.50	Remove / replace front & rear manifold segments	
08-Jan-21	Connor		$357.50	Fuel pump problem Drained & refilled oil Resolve a minor oil leak / topped up	
07-Jan-21	Will Paull	10448	$247.50	Replace PTO oil & filters Replace hyd filter Reseal hyd fittings Remove old a/c hose Replace RH carry roller	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
06-Jan-21	Will Paull	10448	$165.00	1000hr Service	
06-Jan-21	Ted Van	10448	$165.00	Update repairs list for site spec Set up in shed Start removing broken exhaust manifolds	
11-Dec-20	Ted Van	10448	$165.00	Organise parts	
10-Dec-20	Ted Van	10448	$605.00	Fit new engine/ELR wiring harness taken for another machine Replace batteries - Check now power fault to St… Terminals & Isolator & E-Setup Start machine & cary out checks Diagnose leaks. Organise parts.	
10-Dec-20	Dave Marshal		$275.00	Bucket 5 - Repair bucket, replace wear plates	
09-Dec-20	Dave Marshal		$302.50	Repair bucket	
03-Dec-20	Dave Marshal		$27.50	Inspect excavator bucket	
25-Nov-20	Ted Van		$55.00	Chase up parts	
24-Nov-20	Ted Van		$55.00	Inspect manifolds & organise parts	
02-Nov-20	Duncan	41879	$82.50	Adjusted trcks Blew out Air filters	
21-Aug-20	Ted		$55.00	Remove engine/fuel pump wiring harness off to send to site	
11-Aug-20	Lindsay		$137.50	Jump start, Put in washbag, Remove belly plates, take photos of leaks	
05-Dec-19	B Swan		$877.50	Sticks Buckets Rails Accessories Counter weights	
14-Apr-18	Brad	10283	$363.00	250hr service.	
09-Apr-18	Brad	10254	$45.00	R+R bucket grease nipples and grease.	
04-Mar-18	Brad		$363.00	Monitor engine temps, lift fan speeds and recheck. Blow out rads.	
23-Feb-18	Brad	19981	$544.50	1000hr service, R+R final oils and slew oils, incorrect oil filter supplied.	
21-Feb-18	Brad	9960	$272.25	find and fix wiring fault causing missfire and derate, inf earth rub through.	
10-Feb-18	Swanling	9917	$137.50	Find & repair electrical fault in engine harness Test & run machine	
06-Feb-18	Swanling	9902	$272.00	Diagnose shut down fault as broken wire Machine has 1 semi seized top roller	
03-Feb-18	Brad	9870	$226.88	Idle fault diagnosis. R&R Leakinghose.	
02-Feb-18	Brad Smith	9865	$136.12	Replace leaking o-rings.	
31-Jan-18	Swanling	9840	$136.12	Fit new travel hoses.	
20-Jan-18	Brad smith	9786	$65.00	Coolant leak repair and refil.	
17-Jan-18	Brad	9760	$136.13	clean and reseal hyd screens	
17-Jan-18	Brad	9760	$90.75	Clean and reseal hyd screens.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
13-Jan-18	Brad Smith	9746	$162.50	R&R hyd sight glass, machine check over.	
10-Jan-18	Brad Smith	9725	$227.50	R&R craked hyd hard line. Replace weeping O-ring nearby.	
03-Jan-18	Brad Smith	9676	$65.00	Remove broken track guard,pump up RH track.	
21-Dec-17	Brad Smith	9660	$97.50	Replace broken nipple on dipper manifold, unblock, purge grease lineto dipper pin.	
14-Dec-17	B Swam	9595	$162.50	R/R x2 wear plates. Check oil leak and tighten. Lines in slew area control blocks.	
12-Dec-17	Brad Smith	9562	$32.50	replace bolt in rear stairs	
10-Dec-17	Brad Smith	9562	$292.50	500hr service	
07-Dec-17	Brad Smith	9562	$32.50	Remove split/broken grease hose.	
28-Nov-17	Brad Smith	9484	$97.50	Braze and refit leaking hyd pipe behind boom.	
21-Oct-17	Brad Smith		$97.50	Check hyd system for leaks, found many around value bank, topped up hyd tank and monitor leaks.	
25-Sep-17	Webb		$288.75	Air compressor spilling out engine oil, a/c not cold, leaking a/c hose	
23-Sep-17	Webb	9117	$226.88	Blown hose off boom lift cylinder, removed, fixed and refitted	
22-Sep-17	Webb	9113	$272.25	power grease machine and replace line off compressor to tank and auto	
21-Sep-17	Swanling	9105	$90.75	Remove split air line off air compressor	
12-Sep-17	webb	9064	$90.75	repair a/c earth wirse @ a/c compressor	
01-Sep-17	Swanling	9001	$363.00	Service, check over and find pump faulty - circuit breaker and wiring heavily corroded	
29-Jul-17	B Swan	8801	$130.00	Check auto stair clean slew sensor. Check + clean harness on stairs. Retest ok. Tighten loose inspection pannel + isolater manafolds	
23-Jul-17	S Webb	8786	$195.00	Look over digger + replace refil line in pump bay. Tighten up bolts on bucket /stick.	
07-Jul-17	B Swan	8710	$162.50	Shut down inspection + grease. Inspect water pump tell tail no leaks. Not blocked. (slight stain) will keep check on it when hot.	
26-Jun-17	Swanling	8635	$226.00	Grease snapped bolts Removed pump Got one broken bolt out, had to hei coil another Refitted pump Leaking coolant Found loose hose on EGR	
25-Jun-17	Swanling	8635	$136.00	Check over Found coolant leak Grease broken bolts Also had a look at start, couldn't fault Fixed up leak off shaft motor	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
11-Jun-17	Swanling	8521	$272.00	Reseal/replace orings on adjuster at valve block Top up fluids & inspect machine	
04-May-17	Swanling	8328	$272.00	Fit new starter motor A/C not cold, checked gas Found clutch not holding	
03-May-17	Swanling		$136.00	Check over machine Tighten up loose grease feed line Recheck oil & grease bucket	
02-May-17	Swanling	8319	$363.00	Machine wouldn't start Check battery, isolator & e-stop, found top start shorting Fixed up Grease line on bucket & got running on one starter Run up top hyd oil	
28-Apr-17	G Wykes		$93.00	Repair handrail	
22-Apr-17	Swanling	8317	$181.00	Site inspections Test operations etc	
21-Apr-17	Swanling	8317	$363.00	Fit stick & bucket Pump up hydraulics & fit walkways Battery light on charge rate, fit alt wires (found out cancels charge) Jump start	
18-Apr-17	Swanling	8317	$544.00	Assemble boom, counterweight & stick	
10-Apr-17	T Van	8313	$211.00	Clean up bay Secure cooler door after wash Fit new heater core & test for leaks Reassemble cab, fit seat Complete prehire paperwork	
10-Apr-17	J Seymour		$32.00	Re-tagged fire extinguisher	
08-Apr-17	J Ciappara		$97.00	Put 20L grease gun back together	
08-Apr-17	James Mills		$260.00	Reseal Hyd spools, remove broken boltfrom hydraulic support, check seal in H frame.	
08-Apr-17	T Van	8313	$260.00	Assist with slew control valve & pivot valve reseal Join up new heater hoses to existing hose beneath PTO Refit bottom covers	
07-Apr-17	T Van	8313	$260.00	Wash down residual leaks from engine Start reseal slew control valve	
06-Apr-17	T Van	8313	$682.00	Remove U/S heater core Fit taps at engine for heater hoses Replace leaking PTO cooler hose running past engine Replace heater hose from egnine to beneath PTO Free up seized access door hinges & refit door Inspect stick & boom	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
06-Apr-17	J Ciappara	8313	$260.00	Refill auto greaser Diagnose 20L greaser pump	
05-Apr-17	T Van	8313	$195.00	Check over Remove covers Remove seat assembly	
29-Mar-17	A Warren	8313	$715.00	Drove to Orange from Dubbo Changed over hitorque to a bigger one Drove to Guanna Hill Remove counter weight bolts Removed side rails/steps Removed counter weight & loaded onto float Removed boom cylinders & boom & loaded onto float Return tools to Orange Drove back to Dubbo & unloaded	
29-Mar-17	J Ciappara	8313	$536.00	Remove side rails Remove counter weight/load on float Remove boom/load on float	
28-Mar-17	A Warren	8313	$947.00	Drove to Guanna Hill Completed site induction & prestart JHA Remove stick & bucket assemblys Tried to remove counter weight bolts, too tight Drove to Orange, hired small hitorque wrench Drove back to Guanna Hill, tried to remove bolts, couldn't crack them. Removed boom hoses & capped Drove back to Dubbo	
28-Mar-17	J Ciappara	8313	$650.00	Diassemble bucket Diassemble stick Remove top handrails Remove hydraulic hoses from boom	
05-Dec-16	Greg Mills		$32.50	Check over swap around bucket teeth	
24-Nov-16	Greg Mills	8247	$162.50	Fill auto greaser.	
11-Nov-16	Greg Mills		$130.00	Disassemble manual greaser, fit new seals assemble and test - OK	
08-Nov-16	Greg Mills		$65.00	Repair manual greaser	
08-Nov-16	Greg Mills	8180	$130.00	Cut out heater hoses and join, fill with coolant and test for leaks	
02-Nov-16	Greg Mills	8144	$130.00	Fill hydraulic tank, fill tracker to finish filling tank	
27-Oct-16	Greg Mills	8122	$552.50	Replace EGR cooler, test.	
26-Oct-16	Greg Mills	8122	$65.00	Diagnose coolant in exhaust	
13-Oct-16	G Wykes		$156.00	Repair boom	
29-Sep-16	Greg Mills	8009	$65.00	Repair manual greaser	
21-Sep-16	Greg Mills		$65.00	Fit new grease fitting.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Sep-16	Greg Mills		$812.50	Assemble machine. Repair and replace grease lines. Check out fire supression. Top up hydraulic oil.	
14-Sep-16	D.Lundholm		$65.00	assist load	
13-Sep-16	A Warren	7936	$965.00	Escorted Russell to site Completed site induction & paperwork Unloaded bucket, steps & stick from truck Started to assemble stick onto boom Fitted new seals Travelled to Dubbo	
13-Sep-16	DMR	7936	$877.50	Escorted russell to site, completed site induction and paperwork, unloaded bucket/steps and stick from truck, started to assemble stick onto boom, fitted new seals.	
13-Sep-16	Ted Van		$65.00	Remove power stairs off walkway and guard up truck for transport.	
12-Sep-16	Hedgy		$32.50	Fit step and stand	
12-Sep-16	G Wykes		$31.00	Fit step to stand	
09-Sep-16	Dane.L	7936	$292.50	Clean cab. Remove stairs. Organise safe lifting points	
08-Sep-16	A. Warren	7936	$71.50	Repaired leaking fire supression	
25-Aug-16	Kevin.M		$390.00	Fit and straighten belly guards repair bracket and threads for belly guards.	
25-Aug-16	Jacob Seymor	7936	$406.25	tapped thread holes out clean dirt out of machine, straightened belly guards. Cleaned brackets up to be welded assisted fordy with guides fitted all belly plates.	
24-Aug-16	acob Seymor	7936	$195.00	Cleaning and fitting belly guards to machine	
24-Aug-16	C Ford		$437.00	Weld repairs	
24-Aug-16	D.Lundholm	7936	$130.00	Assist fordy with track guides	
24-Aug-16	Kevin.M		$341.25	Fit belly guards. Straighten guards and brackets.	
23-Aug-16	acob Seymor	7936	$471.25	Dug dirt out and washed	
19-Aug-16	Jacob.S	7936	$178.75	wash	
18-Aug-16	Jacob.S	7936	$471.25	Dug dirt out of tracks and fitted two clamps onto hose started to wash	
18-Aug-16	Ted Van		$32.50	Replace Get	
18-Aug-16	C Ford		$218.00	Make & fit stairs	
16-Aug-16	Crank	7933	$601.25	Fit plunger in solenoid and test swings OK, check wiring to access ladder, change around proxies and connections and test - works well, ladder still needs to be re-welded and strengthened, clean up surfaces track guides to get bolted to and bolt up LHS guides, fit grommet in front windscreen, straighten RHS bent guide - might need remaking.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Aug-16	RLW		$618.00	Repair fault in slew Remove broken bolts in track frame & tap out Fit track guides & tension Straighten track guides in press	
16-Aug-16	Crank Mechan	7933	$814.00	Fit plunger in solenoid & test, swings ok. Check wiring to access ladder Change around proxies & connections & test, works well. Ladder still needs to be re-welded & strengthened. Cleaned up surfaces, track guides get bolted & bolt up LHS guides. Fit grommet in front windscreen Straighten RHS bent guide, might need re-making	
15-Aug-16	Crank	7933	$162.50	Machine wouldn't swing, checked solenoids/plugs and wiring, will check book and figure out tomorrow, could not be to do with stairs.	
15-Aug-16	Dane.L	5975	$48.75	Assist remove out of shed, assisted drop final oil levels.	
15-Aug-16	Crank Mechan	7933	$220.00	Machine wouldn’t swing Checked solenoids/plugs/wiring Will check book & figure out tomorrow Could be to do with stairs	
15-Aug-16	RLW		$433.00	Move stick out of wash bay Start & check all levels & top up Replace final drive oils Remove belly guards Find fault in slew, machine would not slew	
12-Aug-16	Crank Mechan	7933	$858.00	Pick up return hose from Stevensons Fit to machine Fit stairs & test Need to get schematic on wiring Fit piston rings to piston on stick cylinder & reassemble stick cylinder. Fit to machine & clean up	
12-Aug-16	Dustin Eade		$75.00	Assist with stick cyliner assembly and fitment.	
12-Aug-16	Crank	7933	$633.75	Pick up return hose from Stevos and fit to machine, fit stairs and test, need to get schematic on wiring, fit piston rings to piston on stick cylinder and reassemble stick cylinder - fit to machine and clean up.	
11-Aug-16	RLW		$825.00	Replace & refit hose on boom pump drive Replace No. 3 tappet cover gaskets Fit fire extinguishers Fit swivel in under carriage Fit hand rails & repair Remove all belly guards	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
11-Aug-16	Crank Mechan	7933	$880.00	Removed return hose to filter to get remade Reassemble swivel valve & refit to machine Fit other hoses that were remade Still waiting on a few clamps Removed last of broken bolts out of track guides Cleaned up surfaces	
11-Aug-16	Colin Ford		$359.49	Continued weld repairs	
11-Aug-16	Crank	7933	$650.00	remove return hose to filter to get remade, reassemble swivel valve and refit to machine, fit other hoses that were remade, still waiting on a few clamps, removed last of broken bolts out of track guides.	
10-Aug-16	Crank Mechan	7933	$313.00	Service 1250, fuel, oil, hydraulic air filters, slew oils Scraped all dirt & grease off belly guards Finish washing stick off 1250	
10-Aug-16	RLW		$763.00	Reseal stick ram, carry out 1000hr service Remove all hoses that need replacing	
10-Aug-16	A. Warren	7935	$89.38	Fit up boom, stick cylinder hoses with Wyksy.	
10-Aug-16	Colin Ford		$109.41	Weld repairs	
10-Aug-16	Crank	7933	$568.75	Remove swivel valve from machine, disassemble valve, remove hoses that need replacing, resealed brake release solenoid and swing priority solenoid, dropped hoses to stevos to get them made first thing in the morning.	
10-Aug-16	Crank Mechan	7933	$770.00	Remove swivel valve from machine Disassemble valve Removed hoses that needed replacing Resealed brake release solenoid & swing priority solenoid. Dropped hoses to Stevensons to have made first thing in the morning	
09-Aug-16	A. Warren	7935	$232.38	Removed and stripped stick cylinder with Wyksy.	
09-Aug-16	Colin Ford		$156.30	Continue making steps	
09-Aug-16	RLW		$825.00	Reseal boom ram's & remove stick ram to reseal	
09-Aug-16	Crank Mechan	7933	$880.00	Reassemble RH boom lift cylinder Remove LH boom lift cylinder, refit & reassemble Start removing broken bolts in LH track guide Organise list of parts & order	
09-Aug-16	Crank	7933	$650.00	Reassemble RH boom lift cylinder, remove LH boom lift cylinder rebuild and reassemble, start removing broken bolts in LH track guide, organise list of parts and order.	
08-Aug-16	Kevin		$52.50	Assist to assemble and fit rams	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Aug-16	Crank Mechan	7933	$880.00	Check over machine Remove belly guards Write list of problems on machine Clean down areas where needs work on. Remove RH boom lift cylinder & refit ready to assemble	
08-Aug-16	A. Warren		$286.00	Assisted Wyksy in cylinder assembly	
08-Aug-16	Crank	7933	$650.00	Check over machine, remove belly guards, write list of repairs for machine, clean down areas that need to be worked on, remove RH boom lift cylinder and rekit ready to assemble.	
08-Aug-16	Colin Ford		$109.41	Make Steps.	
08-Aug-16	RLW		$701.00	Reseal bucket ram Remove boom ram & reseal	
03-Aug-16	RLW	5975	$247.00	Strip ram & clean Clean stick & parts to reassemble	
02-Aug-16	RLW	5975	$639.00	Remove ram from stick & fit seal kit Remove other ram & strip	
30-Jul-16	C Ford		$359.00	1250 Stand	
29-Jul-16	Ted Van	7973	$325.00	Strip bucket and stick, walkway handrails ready for transport	
29-Jul-16	Dane.L	7973	$455.00	Disassemble stick and bucket, exhaust, air mushrooms, handrails and side stairs.	
26-Jul-16	Ted Van	7923	$195.00	Replace GET repair damaged wear plate adaptors, replace p3 wear plates quick check over.	
14-Jul-16	Westrac		$1,115.30	Track pin broken Travelled to site, align track, fit seal washers & spacers Set up track press, freeze fown pin, press in pin. Fit grouser plates	
30-Jun-16	Ted Van	7904	$650.00	Continue prep for track rejoin, return travel to condoblin for replacement oxy bottle line track up and push new pin in with westrac refit grousers and pump up track.	
29-Jun-16	Ted Van		$195.00	Recover broken LH track and align back under machine, start prepping for rejoining.	
28-Jun-16	Ted Van		$97.50	Inspect and report on broken LH track	
16-Jun-16	Ted Van	7810	$65.00	chech ladder wire raise and rescewe	
31-May-16	Ted Van		$32.50	Replace GET	
23-May-16	G Wykes		$187.00	Repair hydraulic pipe	
20-May-16	Ted Van	7720	$520.00	Remove same hose off P205 and take to fit to machine found bolts broken attempt to remove remove covers remove hydraulic pipe with broken bolt still cant remove bolt remove same pipe off p205 and fit fit hose and covers check hydraulic oil	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
19-May-16	Ted Van	7214	$292.50	Continue power stair fault diagnosing. Check all transducer wiring and operation, change stair wiring to operate stairs only, no lock. Test operation, okay. Clear blocked grease lines and grease stairs.Adjust main relief pressure up.	
19-May-16	Ted Van	7720	$65.00	Remove covers inspect oil leak organise parts	
18-May-16	Ted Van	7214	$390.00	Walk unit to tip head, diagnose faults with power stairs. Chase info from williams engineering. Check solenoids and trasducers	
06-May-16	Ted Van	7676	$422.50	Modify new bolts for grease distriutor, weld on retaining plate, refit distriutor and hoses. Replace broken fitting refill and test auto greaser investigate coolant usage no coolant used dor week.	
05-May-16	Ted Van	7676	$455.00	Reseal leaking fittings, clean up grease off stick, remove grease distributor, remove mounting plate remove broken bolts and repair mount plate, remove broken fittings from ditriutor and replace	
04-May-16	Ted Van	7673	$97.50	Replace GET, Check operation faults. Top up front slew box and pump drive box repair leaking grease lines	
03-May-16	Ted Van	7671	$260.00	Return to travel to Albert to pick up parts fit batteries and link cable replace sml wear plate clear blocked air reciever	
02-May-16	Ted Van		$32.50	Organise parst	
22-Apr-16	Ted Van	7664	$195.00	Replace u/s fan hoses top up hydraulic oil reseal valve fittings	
21-Apr-16	Ted Van	7660	$260.00	Reseal leaking cartridge from LHS of main control valve number 1 remove covers and diagnose oil leaks. Organise more parts	
21-Apr-16	Ted Van	7660	$260.00	Reseal leaking cartridge from LHS of main control valve #1 remove covers and diagnose oil leaks. Organise more parts	
20-Apr-16	Ted Van	7654	$97.50	Broken grease fitting @ boom knuckle bleed air from system	
20-Apr-16	Ted Van	7654	$97.50	Replace broken grease fitting @ boom knuckle bleed air from system	
18-Apr-16	Ted Van	7654	$227.50	Inspect oil leak and organise parts. Remove seat, replace seat base and refit.	
18-Apr-16	Ted Van	7654	$227.50	Inspect oil leak and organise parts. Remove seat. Replace seat base and refit.	
07-Apr-16	Ted Van	7623	$32.50	Change out blocked outer air filter	
05-Apr-16	Ted Van	7595	$32.50	Secure stairs and bypass alarm.	
04-Apr-16	Ted Van	7589	$32.50	Replace G.E.T	
24-Mar-16	Greg Mills		$65.00	Diagnose and repair power stair fault	
23-Mar-16	Greg Mills		$65.00	Repair wiring to powerstairs	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
22-Mar-16	Greg Mills		$65.00	Diagnose powerstart fault	
09-Mar-16	Greg Mills		$32.50	Fuel and grease	
08-Mar-16	Greg Mills	7531	$195.00	Jump start and move out of pit. Replace leaking hose.	
24-Feb-16	Ted Van	7516	$260.00	Replace u/s engine dipstick tube, find leaking grease fitting and reassemble remove broken grease hose make new one at pybar and fit resecure loose grease hoses	
22-Feb-16	Ted Van	7516	$97.50	Replace bolts with gennuine and pump 1 to pump 2 block	
08-Feb-16	Ted Van	7504	$520.00	Clean up maiting surfaces and fit hydraulic pipe, obtain replacement bolts from Pybar. Replace hose, reseal 2nd pipe, top up hydraulics and test. Refit covers. Walk out of pit and carry out 500hr service as manufacturer recommends	
27-Jan-16	Ted Van	7560	$325.00	Removed damaged hose from pump 2 to pump 1 and block remove pipes, remove broken bolts, organise parts	
22-Jan-16	Greg Mills	7501	$260.00	Fill auto greaser repair grease leak. Replace hyd hose between boom and stick. Repair grease line to h-link Grease machine	
21-Jan-16	Greg Mills	7491	$65.00	Fill hyd oil. Repair leak on hyd hose.	
21-Jan-16	Greg Mills		$65.00	Repair oil leakon slew motor	
20-Jan-16	Greg Mills	7491	$390.00	Fill coolant Fit fuel hose Fit hyd hose and pipe	
19-Jan-16	Greg Mills	7491	$325.00	Remove and replace water pump. Replacxe coolant hose.	
18-Jan-16	Greg Mills	7491	$195.00	Fit grease reel. Clean out battery box. And reel	
14-Jan-16	Ted Van	7488	$32.50	Replace fuel filters and bleed.	
12-Jan-16	Ted Van	7488	$357.50	Cap off hoses to LH bucket cylinder, top up hydraulic oil and move to safe location. Remove broken bolts from damaged cylinder, organise parts. Check over for coolant leak. Found water pump leaking from tailgate. Organise parts	
11-Jan-16	Ted Van	7488	$65.00	Top up coolant check boom damage	
22-Dec-15	Greg Mills	7420	$65.00	Repair power stair wiring.	
14-Dec-15	Ted Van		$32.50	Check noise in hydraulics.	
10-Dec-15	Greg Mills	7342	$130.00	Repair a/c	
09-Dec-15	Greg Mills		$195.00	Remove manual greaser hose reel, replace bucket teeth.	
07-Dec-15	Greg Mills	7308	$130.00	Swap bucket teeth around, replace 2x small wear plates.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
25-Nov-15	Greg Mills	7235	$195.00	Fill auto greaser, repair power stair fault.	
24-Nov-15	Greg Mills	7220	$65.00	Fuel, grease, fill auto greaser.	
23-Nov-15	Greg Mills		$97.50	Tighten grease fitting, repair broken grease line. Fuel machine.	
11-Nov-15	Greg Mills	7117	$130.00	Finish off 1000hr service.	
10-Nov-15	Greg Mills	7107	$325.00	Replace bucket teeth. Pump up track. Change slew oil, filters and lip protector.	
06-Nov-15	Ted Van	7090	$65.00	Remove broken/damaged RH track guide and pump up tracks.	
30-Oct-15	Greg Mills	7002	$195.00	Carry out service, change eng oil, filter, fuel filters, inner and outer air cleaners, repair power stairs.	
29-Oct-15	Greg Mills	6988	$97.50	Repair grease line & auto greaser.	
28-Oct-15	Greg Mills	6955	$195.00	Replace wear plate. Weld up track guide, repair grease lines. Replace bucket teeth; wear plate.	
27-Oct-15	Greg Mills	6945	$130.00	Repair grease leak on boom fill auto greaser.	
23-Oct-15	Ted Van		$65.00	Blow out air filter check codes.	
22-Oct-15	Ted Van	6915	$520.00	Replace sml wear plate, swap outside teeth with inside. Top up engine oil. Ws isolate, clean up and repair leaking. Auto greaser main feed line on top of stick. Refill auto greaser and bleed. Found auto greaser not pumping, Found plunger not connected. Strip clean and reassemblebleed. Found leaking fitting broken. Replace and retest.	
08-Oct-15	Greg Mills	6804	$292.50	Repair hose to air compressor, blow out air cleaner, a/c filters, check a/c due to fault reported. Repair a/c controller, had no power to controller.	
07-Oct-15	Greg Mills	6792	$65.00	Check over machine.	
06-Oct-15	G Wykes		$63.00	Repair handrails and steps	
30-Sep-15	A Warren		$214.50	Replaced bucket teeth, checkover & grease. Inspected electrical smell in cab, found no	
29-Sep-15	A Warren	6774	$143.00	Completed 250hr service. Replaced air filters	
27-Sep-15	G Wykes		$62.00	Repair handrails & power	
24-Sep-15	Ted Van	6680	$65.00	Swap teeth. Replace wear plates.	
24-Sep-15	Greg Mills		$32.50	Fuel and grease machine	
23-Sep-15	Greg Mills	6709	$195.00	Fuel and grease. Fit wear plate, repair manualgrease handle after it got wrapped around the slaw.	
22-Sep-15	Greg Mills		$32.50	Check over	
22-Sep-15	Ted Van	6694	$32.50	Grease blow out air filters.	
20-Sep-15	Greg Mills	6662	$195.00	Replace coolant hoses at front of engine.	
17-Sep-15	Greg Mills		$32.50	Fuel and grease	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Sep-15	Greg Mills		$32.50	Fuel and grease machine	
16-Sep-15	A Warren	6608	$214.50	Replaced grease hoses. Checked over machine. Refitted & tightened track guide. Full checkover	
15-Sep-15	Greg Mills	6604	$195.00	Fuel, grease fill auto greaser. Repair manual grease pump.	
15-Sep-15	A Warren		$53.63	Top up oils, checkover & grease	
14-Sep-15	Greg Mills		$32.50	fuel and grease	
11-Sep-15	Ted Van		$65.00	fill up and grease replace wear plates	
11-Sep-15	Ted Van		$32.50	Fuel up, grease and wear plate.	
10-Sep-15	Ted Van	6546	$130.00	Fuel up and grease also. Replace wear plates on bucket.	
09-Sep-15	Greg Mills		$32.50	Fuel and grease	
08-Sep-15	Greg Mills	8519	$97.50	Check hydraulic leak, fuel and grease.	
07-Sep-15	Greg Mills	6508	$97.50	Fuel and grease. Fill auto greaser.	
07-Sep-15	Ted Van	6468	$162.50	Broken adaptor, remove bucket and fit B2 bucket remove obstructing wear plates, change over wand swap RH outsid tooth with middle. Grease.	
03-Sep-15	Greg Mills	6488	$195.00	Carry out eng service. Eng oil filters fuel filters and air cleaner. Blow out cab filter	
02-Sep-15	A Warren	6493	$143.00	change out air filter. Check & inspected noise coming from front of engine. Noise came & went. Change out bucket teeth.	
02-Sep-15	G Wykes		$125.04	Repairs to track frame	
02-Sep-15	Greg Mills	6474	$195.00	Repair auto greaser, fit track guide. Grease and fuel.	
01-Sep-15	Greg Mills	6452	$227.50	Fill auto greaser, grease machine, top up eng oil.	
01-Sep-15	A Warren	6418	$143.00	Change out teeth, greased & checkover. Tightened belts	
31-Aug-15	Greg Mills	64440	$260.00	Remove track guide. Pump up track. Weld end of bucket pin. Grease machine	
21-Aug-15	A Warren	6339	$71.50	Replaced teeth. General checkover & grease. Adjusted tracks	
20-Aug-15	Greg Mills	6332	$32.50	Blow out air cleaner	
19-Aug-15	Greg Mills	6320	$65.00	Top up eng oil. Fuel up machine. Swap around wear plates.	
19-Aug-15	A Warren	6300	$286.00	Inspected autogreaser, tested, diagnosed & ordered new pressure switch. Full machine checkover. Adjusted tracks. Greased bucket, replaced grease fittings.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
18-Aug-15	Greg Mills	6307	$325.00	Replace grease line. Fill auto greaser, diagnose fault. Fuel up machine. Grease machine.	
13-Aug-15	Greg Mills	6264	$227.50	Replace 6 wear plates (large) 2x small wear plates. Fit coolant level sensors. Top up coolant in radiator. Fit new bucket teeth.	
12-Aug-15	Greg Mills	6263	$260.00	Swap bucket teeth around. Fill Hyd tank.	
10-Aug-15	Greg Mills	6255	$682.50	Fit new sensor to stairs, still no go, swap sensors around dozens of times, different part of stairs would work each time. Found that new sensors are sending wrong signal to stair control. Replace pilot hose to LH joystick.	
07-Aug-15	Greg Mills		$32.50	Clean out air cleaner after air filter restruction light came on.	
06-Aug-15	Greg Mills	6220	$65.00	Prime up fuel, replace 2 x wear plates	
05-Aug-15	Greg Mills	6209	$65.00	Prime up fuel after machine ran out.	
05-Aug-15	Greg Mills	6198	$32.50	Replace 2 x wear plates	
04-Aug-15	Greg Mills	6184	$65.00	Fit bucket teeth and wear plates	
03-Aug-15	Greg Mills	6177	$130.00	Check out power stair fault, bypass switches to lock stair in.	
31-Jul-15	A Warren		$107.25	Inspected oil leak & ordered parts	
30-Jul-15	A Warren		$643.50	Commission digger for site	
29-Jul-15	A Warren		$607.75	Commission digger for work	
22-Jul-15	Kevin		$308.75	Replace D2 valve repair air leaks replace signal line to compressor.	
21-Jul-15	Kevin	6156	$341.25	Overhaul air grease gun. Test air compressor, blown hose,	
20-Jul-15	Dustin Eade		$260.00	Replaced air hose from compressor to vavle and fittings. Replaced hydraulic hose. Refited all belly guards	
20-Jul-15	Kevin		$48.75	Dismantle grease unit pump.	
17-Jul-15	Greg Mills		$195.00	Fit boom cylinder hoses fit window check out air compressor not unloading. Found hole in hose from unload valve to compressor	
14-Jul-15	Greg Mills		$195.00	Finish rebuilding water pumps. Fit water pump to machine start to fill with coolant	
13-Jul-15	Greg Mills		$65.00	Remove hoses for P205	
11-Jul-15	Andrew		$150.00	Removed hose on boom in yard.	
09-Jul-15	Andrew		$225.00	Unload stick, handrails & load up trailer & tyre onto float.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Jul-15	Kevin	6156	$97.50	Remove water pump.	
02-Jul-15	Dustin Eade	6156	$585.00	Refitted auto greaser and secured. Refitted hose to left control handle in cab to valve block under body. Checked for other leaks. Fitted hydraulic tank breather hose.	
01-Jul-15	Dustin Eade	6156	$455.00	Straightened steps and fitted to tracks. Replaced globe on boom light. Re-aired air tanks. - Relief valve/air hose and fittings. Checked all oil levels. Removed auto greaser to repair floor. Tightened all clamps on main feed hoses from hrydraulic pump. Re-paired floor for auto greaser	
30-Jun-15	Dustin Eade	6156	$503.75	Check over. Re-tag extinguishers. Diagnose oil leaks. Remove hose from control to tank. Re-thread step mounting holes RH side.	
18-Jan-15	Ted Van	7488	$390.00	Clean, strap and overhall waterpump, set up impeller offset (8.44 + 1.55) and reassemble package up and ready for freight.	
07-Jan-15	Greg Mills		$65.00	Remove power stairs from walkway and load onto trailer.	
07-Nov-14	Dave O'Leary		$65.00	Clean and cover stick pin holes	
06-Nov-14	Dave O'Leary		$260.00	remove stick/walkways/handrails/exhaust stacks and fire supression bottles from machine.	
06-Nov-14	Greg Mills	6149	$227.50	Disassmeble machine for transport	
05-Nov-14	Dave O'Leary		$260.00	Remove bucket, remove stick cylinder pin, prep stick for removal, prep walkway for removal.	
05-Nov-14	Greg Mills	6149	$97.50	Remove bucket	
29-Oct-14	Greg Mills	6149	$65.00	Check over machine and make up repairs list.	
15-Oct-14	Greg Mills	6143	$65.00	grease, fill auto greaser	
15-Oct-14	Greg Mills	6133	$65.00	Grease machine and check over.	
11-Oct-14	Ted Van		$32.50	Grease bucket and stick	
11-Oct-14	Ted Van		$65.00	Grease bucket and stick and refill autogreaser	
10-Oct-14	Ted Van	6083	$325.00	No A/C found belt had thrown - organise and pick up parts from Gunnedah go back to site and fit belt and jump start machine.	
10-Oct-14	Ted Van	6083	$32.50	Grease bucket and stick.	
09-Oct-14	Ted Van	6070	$195.00	Grease bucket and stick, refill autogreaser, top up hyd oils, tighten loose fitting under cab, refit tooth and replace missing lock.	
30-Sep-14	Dave O'Leary	6060	$76.05	take fuel filter to machine, different filter fitted, return to container and look for filter - none there.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
29-Sep-14	Dave O'Leary	6055	$568.75	Continue 2000hr service, grease bucket pins, inspect oil leak under cab, joiner fitted in pilot hose - hose to small from joiner may need to be replaced.	
29-Sep-14	G Wykes		$1,137.50	repair bucket.	
27-Sep-14	Ted		$65.00	inspect & report broken tooth adaptor on bucket. Grease bucket & stick.	
26-Sep-14	Ted	6027	$162.50	top up engine oil. Replace fuel/water separators & bleed fuel system. Replace fallen off tooth. Grease bucket & top up autogreaser.	
24-Sep-14	Ted	6012	$325.00	grease bucket. Refill autogreaser. Replace inner & outer air filters. Inner & outer cab filters. Replace hydraulic filters.change engine oil & filters.	
20-Sep-14	Millsy	5970	$65.00	Autogreaser fault, grease was empty, pump some grease into greaser, try to bleed, told operator to press button to get pump working. Fill auto greaser, grease.	
19-Sep-14	Millsy	5969	$35.00	Grease.	
17-Sep-14	Millsy	5950	$35.00	Grease.	
12-Sep-14	Ted Van		$32.50	Grease bucket and top up autogreaser	
10-Sep-14	Ted Van	5893	$32.50	Grease bucket and stick	
09-Sep-14	Ted Van	5881	$130.00	Fit new pipe and hose, top up hyd oil	
08-Sep-14	Ted Van	5881	$65.00	refill autogreaser, organise parts, organise EWP, remvoe damaged LH bucket cylinder pipe, add 100L of hyd oil	
06-Sep-14	Greg Mills	5853	$32.50	Grease machine	
05-Sep-14	Greg Mills	5845	$32.50	Fit bucket tooth	
04-Sep-14	Greg Mills	5843	$32.50	Top up oil, grease machine	
03-Sep-14	Greg Mills	5833	$130.00	Grease machine, weld up auto greaser mount, fit lip protector	
03-Sep-14	Greg Mills	5821	$65.00	Repair auto greaser air supply valve	
02-Sep-14	Greg Mills	5816	$65.00	grease, fit bucket tooth	
01-Sep-14	Greg Mills	5806	$130.00	check oil leak, start machine, operate machine but unable to find leak, send back to work	
01-Sep-14	Greg Mills	5813	$32.50	Grease machine	
26-Aug-14	Ted Van		$292.50	remove covers for Pirtek, refit after hose repair, secure hose and bleed off tap for stairway, chase parts for pritek and grease bucket and refill autogreaser.	
24-Aug-14	Greg Mills	5774	$65.00	Replace new set of teeth due to teeth falling off	
24-Aug-14	Greg Mills	5773	$65.00	Replace 2 x missing teeth	
23-Aug-14	Greg Mills	5768	$32.50	Grease machine	
22-Aug-14	Greg Mills	5759	$32.50	Grease machine	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
22-Aug-14	Greg Mills	5752	$422.50	Track down oil leak, travel to Gunnedah to get joiner, travel back and fit joiner, test and refit panels.	
21-Aug-14	Greg Mills	5780	$32.50	Grease machine	
20-Aug-14	Millsy	5740	$195.00	fit hoses. Fill with hyd oil, test. Straighten guards. Test.	
19-Aug-14	Millsy		$390.00	Remove guards. Remove blown hose, take to Gunnedah & get new ones made. Travel back to site.	
14-Aug-14	Ted Van	5724	$32.50	Grease bucket	
13-Aug-14	Ted Van	5714	$97.50	Fill autogreaser and grease bucket	
13-Aug-14	Ted Van	5705	$65.00	Fill autogreaser, grease bucket	
12-Aug-14	Ted Van	5696	$81.25	Replace extinguisher, refill autogreaser and grease bucket and stick	
09-Aug-14	Greg mills	5876	$32.50	Grease machine	
08-Aug-14	Greg Mills	5867	$65.00	Grease machine, fit new wear plate	
07-Aug-14	Greg Mills	5658	$32.50	Grease machine, fit bucket tooth	
06-Aug-14	Greg Mills	5698	$65.00	Blow out air cleaner.	
06-Aug-14	Greg Mills	5651	$65.00	Grease machine, cut and fit lip protector	
05-Aug-14	Greg Mills	5692	$32.50	Grease machine, try to fit lip protector	
04-Aug-14	Greg Mills	5633	$32.50	Fit one lip protector	
01-Aug-14	Ted Van	5626	$130.00	inspect bucket and refill autogreaser, replace tooth on bucket	
31-Jul-14	Ted Van	5626	$32.50	Grease bucket and stick.	
30-Jul-14	Ted Van	5611	$130.00	Refill autogreaser pod, replace missing tooth off bucket, grease bucket and stick	
29-Jul-14	Ted Van	5608	$32.50	Grease bucket and stick	
29-Jul-14	Ted Van	5602	$65.00	Replace missing tooth on bucket	
28-Jul-14	Ted Van	5596	$65.00	Refill auto greaser and grease bucket	
25-Jul-14	Greg Mills	5587	$130.00	Grease machine, diagnose power steer fault, found broken sensor, bypassed sensor, adjusted releif valves on control valve.	
24-Jul-14	Greg Mills	5578	$32.50	Grease machine	
23-Jul-14	Greg Mills	5569	$32.50	Grease machine	
23-Jul-14	Greg Mills	5569	$32.50	Grease machine	
22-Jul-14	Greg Mills	5559	$32.50	Grease machine	
21-Jul-14	Greg Mills	5550	$130.00	Replace fuel primary pump and control box.	
18-Jul-14	Ted Van	5550	$32.50	Grease bucket pins	
16-Jul-14	Ted Van	5546	$32.50	Grease bucket pins and stick	
14-Jul-14	Ted Van	5538	$97.50	Refill autogreaser tub, assist GB auto with power stair fault adjust sensors.	
13-Jul-14	Greg Mills	5525	$97.50	Check alarm, check greaser, no grease in pot, hook up air greaser to fill auto greaser and grease machine	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
12-Jul-14	Greg Mills	5519	$32.50	Grease machine	
11-Jul-14	Greg Mills	5509	$390.00	Oil leak, remove belly guard, find hose, hose was spiral wrapped with two other hoses, remove cover up top, remove all clamps, remove spiral wrap, remove hose pirtek made new hose, fit hose, fit cover, fit belly guards, carry out 500hr service, change engine oil and filters/fuel filters, priming pump controller shorted out - had to prime with hand pump, grease machine.	
10-Jul-14	Greg Mills	5491	$65.00	Grease machine, go to container and get service trailer, top up engine oil.	
08-Jul-14	Greg Mills	5474	$32.50	Grease machine	
04-Jul-14	Ted Van	5444	$32.50	Grease bucket pins and stick	
02-Jul-14	Ted Van	5429	$65.00	Grease bucket pins and stick, refill autogreaser pot	
01-Jul-14	Ted Van	5421	$32.50	Grease bucket and top up auto greaser	
30-Jun-14	Ted Van		$16.25	Grease bucket pins	
29-Jun-14	Greg Mills	5405	$32.50	Greased machine	
29-Jun-14	Greg Mills	5398	$65.00	Replace air cleaner due to filter light coming on	
27-Jun-14	Greg Mills	5392	$32.50	Grease machine	
27-Jun-14	Greg Mills	5383	$32.50	Grease machine	
25-Jun-14	Greg Mills	5376	$130.00	Check auto greaser fault and manual grease, found blown air line at rear of machine, replace air line, grease bucket pins.	
24-Jun-14	Greg Mills	5367	$97.50	Fill service trailer, top up engine oil, fill auto greaser.	
20-Jun-14	Ted Van	5361	$390.00	Replace 4 hoses in pump drive box cooler circuit, top up pump box oil, replace grease pipe to stick pin to bucket.	
19-Jun-14	Ted Van	12490	$130.00	Grease stick and bucket - top up autogreaser	
17-Jun-14	Ted Van	5343	$97.50	Refill autogreaser pod, grease bucket and stick, check autogreaser operation, replace handgreaser coupler.	
12-Jun-14	Greg Mills		$130.00	Escort GB's to machine and back off site when finished.	
10-Jun-14	Greg Mills	5302	$65.00	Remove panels in cab, check wiring to A/C, fit panels	
10-Jun-14	Greg Mills	5299	$32.50	Check A/C - started working before I got to machine	
06-Jun-14	Ted Van	5294	$292.50	Dig off excess clay and mud and replace GET, replace damaged grease line, refit grease pod, change out mt hand grease pod, check oil leak at back of engine, grease stick and bucket.	
05-Jun-14	Ted Van	5289	$65.00	Blow out air filter	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
02-Jun-14	Ted Van	5274	$130.00	Replace 2 x missing wear plates off bottom of bucket	
28-May-14	Jono Pittin	4528	$178.75	Fit rear belly plates and fit mirrors and fill auto greaser and fire supression bottle.	
28-May-14	Greg Mills	5241	$97.50	Fill auto greaser, change around bucket teeth	
21-May-14	Ted Van	5228	$65.00	Check oil leaks, grease bucket and stick	
19-May-14	Ted Van	5216	$162.50	Refill empty autogreaser pod, replace and set autogreaser dryer/regulator up, grease machine	
15-May-14	Dave O'Leary		$65.00	Fill hyd oil and coolant	
14-May-14	Dave O'Leary		$97.50	Inspect economy setting, change to EO setting from E4 and test OK..	
13-May-14	Ted Van		$162.50	Chase parts for autogreaser, remove old u/s air dryer/oiler and fit new one, package up assembly for transport to boggabri	
13-May-14	Dave O'Leary		$65.00	Check P/E switching OK	
09-May-14	Ted Van	5130	$325.00	Replace cracked coolant lines to compressor, reseal air lines, bypass autogreaser dryer, run and test, grease machine	
08-May-14	Ted Van	5130	$455.00	Remove compressor and inspect no fault found, remove unloader valve clean and lubricate, refit compressor, reattach loose lines	
08-May-14	Ted Van	5128	$195.00	Refit repaired grease lines, grease machine, top up engine oil.	
07-May-14	Ted Van	5124	$292.50	Bypass damaged grease lines and grease machine, pick up parts from gunnedah and repair grease lines.	
07-May-14	Ted Van	5119	$325.00	Grease machine, check air system, chase parts	
06-May-14	Ted Van	5119	$227.50	Check autogreaser and horn fault, reconnect loose grease hose, found air compressor not working, grease machine pot empty	
01-May-14	Dave	5038	$97.50	repair wiring to stairs sensor.	
29-Apr-14	dave	5079	$130.00	top up auto greaser. Temp repair air reg leak. Test, still slight leak. Take photos to chase up parts.	
17-Apr-14	Dave O'Leary		$65.00	Fill auto grease	
14-Apr-14	Dave O'Leary	5036	$97.50	Add grease to auto greaser, repair air leak from valve, dig tracks	
12-Apr-14	Ted Van	5014	$195.00	Top up grease pod, replace blown o-ring in No 1 boom hose	
11-Apr-14	Ted Van	5006	$97.50	Check charge rate - OK, check autogreaser fault - found blown hose organise hose with pirtek, change coupling on handgreaser and ensure bucket and h-link pins taking grease.	
08-Apr-14	Ted Van	4983	$65.00	Replace blown globe in revolving light	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Apr-14	Ted Van	4983	$357.50	Fit and shim bucket, wire up and test power ladder, remove GET from bucket and take to container, purge grease line and grease bucket cylinders.	
04-Apr-14	Josh Hewett	4982	$747.50	Assemble all handrails/steps, assemble stick and connect all hoses.	
04-Apr-14	Dave O'Leary	4982	$747.50	Assemble machine - still need to pin bucket, grease pins and check over machine.	
02-Apr-14	Dave oleary	4982	$48.75	Review SWMS	
02-Apr-14	Dave O'Leary	4982	$195.00	Remove broken bolts from bucket pin	
22-Mar-14	G Wykes		$130.00	repair handrails. Repair bucket.	
21-Mar-14	Josh Hewett	4982	$195.00	Check over machine and complete pre-hire checks and paperwork, clean up tracks and clean cab.	
20-Mar-14	RLW		$48.75	unload from float.	
20-Mar-14	Shane	4980	$750.00	remove hoses & pins. Remove stick ass. Cap all hyd hoses & grease lines. Remove walkway handrails & exhaust stack. Fit new dipstick tube & clamp. Clean dirt out of tracks.	
19-Mar-14	Greg Mills	4980	$65.00	Remove bucket form machine.	
19-Mar-14	Shane	4980	$150.00	remove bucket.	
15-Mar-14	Greg Mills	4968	$130.00	Finish slew motor, top up oils, test slew	
14-Mar-14	Greg Mills	4968	$520.00	Fit front slew motor and all hoses	
13-Mar-14	Greg Mills		$260.00	Assemble slew drives	
12-Mar-14	Greg Mills	4968	$130.00	Fit piston into housing	
12-Mar-14	Shane		$187.50	Re-assemble slew pinion & housing assembley.	
07-Mar-14	Shane	4968	$187.50	repair hyd oil leak at main control valve in front of engine.	
07-Mar-14	Greg Mills	4968	$195.00	Repair oil leak on pipes to control valve	
06-Mar-14	Shane	4968	$450.00	remove front slew motor & take to w/shop & dis assemble.	
06-Mar-14	Greg Mills	4968	$357.50	Remove and disassemble slew motor	
06-Mar-14	Greg Mills	4968	$65.00	Try to get slew drive apart - unable to press apart	
05-Mar-14	Greg Mills	4968	$325.00	Change final drive oils, diagnose front slew motor problem oil won't drain	
04-Mar-14	Greg Mills	4968	$585.00	Carry out 1000hr service, change engine oil and filter, change fuel filters, change air cleaner, change rear slew motor oil, repair electric fuel primer, change PTO oil.	
22-Feb-14	Shane	4937	$75.00	fit new bucket teeth. Check out movement in boom, stick & bucket. Just bearing wear.	
14-Feb-14	Shane	4878	$75.00	Rotate bucket teeth.	
10-Feb-14	Andy William	4830	$65.00	Replace cutting edges	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
09-Feb-14	Greg Mills	4823	$97.50	tighten bucket pin retainer, repair power stairs, put emergancy stairs up.	
09-Feb-14	Andy William	4812	$48.75	Rotate bucket teeth	
08-Feb-14	Greg Mills	4811	$65.00	Fill with hyd oil, fit rubber behind hose to stop hose rubbing	
07-Feb-14	Greg Mills	4791	$195.00	Change out blown hyd hose	
29-Jan-14	Shane	4689	$337.50	pick up new alternator. Travel to site & fit to machine. Check charge - U/S. remove exciter wire & check 28volts, OK. Leave wires off & send back to work. Investigate fault later.	
29-Jan-14	Shane	4698	$112.50	Swap Diode in charge circuit. Alt good. Check wiring for slots. No good.	
28-Jan-14	Greg Mills	4689	$195.00	Fill hyd oil to the correct level, diagnose fault with swing - found to have low battery voltage which is causing the fault.	
28-Jan-14	Jono Pittin		$195.00	Refit new hose in pump room clamp up remove alternator	
28-Jan-14	Andy William	4030	$195.00	Oil leak at pressure hose off pump 2, removed hose from spare machine and fitted to this machine.	
27-Jan-14	Greg Mills	4680	$260.00	Repair hyd oil leak - found bolts snapped on pipe, remove block and remove broken bolts, fit block and pipe, fill with oil.	
26-Jan-14	Andy William	5677	$97.50	Alt light coming on check alternator not charging	
25-Jan-14	Greg Mills	4000	$32.50	Change bucket teeth	
22-Jan-14	Dave O'Leary	4641	$227.50	Complete 500hr service	
22-Jan-14	G Wykes		$65.00	Repair broken handrails.	
22-Jan-14	Jono Pittin		$227.50	Engine service, check finals, drain PTO oil.	
21-Jan-14	Greg Mills	4630	$32.50	Connect greaser alarm, change air cleaner	
17-Jan-14	Shane	4584	$75.00	check bucket teeth & rotate to get more	
16-Jan-14	Andy William		$97.50	Refit hydraulic hose and belly plates	
16-Jan-14	G wykes		$65.00	repair hydraulic pipe.	
16-Jan-14	Greg Mills	4568	$130.00	Pick up pipe in dubbo, fit pipe to machine and test.	
15-Jan-14	Ted Van	4568	$162.50	Remove split and leaking hydraulic pipe for welding repairs	
15-Jan-14	Jono Pittin		$227.50	Check over for oil leaks, remove steel hose from control valve to boom arch and bring back to workshop for welder to fix.	
13-Jan-14	Dave O'Leary		$16.25	Clean air filter	
12-Jan-14	Andy William	4491	$97.50	6 x bucket teeth	
08-Jan-14	G Wykes		$97.50	fab handrails & fit.	
07-Jan-14	Shane	4491	$75.00	repalce LHS bucket wear block.	
07-Jan-14	Andy William	4481	$118.95	Repalce o-ring on pump 3 pressure lines	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Jan-14	Greg Mills	4458	$130.00	Greaser fault, fill auto greaser	
02-Jan-14	Greg Mills	4734	$130.00	Remove broken piece and replace grease fitting.	
01-Jan-14	Greg mills	4422	$32.50	Blow out air cleaner	
31-Dec-13	Greg Mills	4411	$32.50	Change bucket teeth	
28-Dec-13	Greg Mills	4376	$32.50	Top up hyd oil	
20-Dec-13	Greg Mills	4330	$65.00	repair power stairs	
20-Dec-13	Greg Mills	4325	$32.50	Check to see if noise had gone out of slew.	
19-Dec-13	Greg Mills	4325	$130.00	Diagnose noise in slew - found no grease in slew ring remove plate and pump in 20kg grease and refit plate.	
19-Dec-13	Shane	4325	$115.00	noise coming from slew area. Check auto greaser & bleed all grease lines, OK. Manually grease slew area. Noise still there but goes away when does full revdution at slew. Check inside slew ring for grease, low & teeth dry. Remove cover & pump 30kg of grease into inside slew ring, check OK.	
18-Dec-13	Greg Mills		$65.00	Clean up control valve - diagnose where oil leak is coming from.	
18-Dec-13	Shane	4308	$75.00	check hyd leak above slew area, found leaking from main control valve. Send back to work & investigate at lunch.	
13-Dec-13	Shane	4305	$300.00	fit electrical horn & wire up, test, OK. Segegrate wiring around washer bottles. Repalce fuel fitters.	
12-Dec-13	G Wykes		$325.00	Handrails.	
12-Dec-13	Shane	4305	$525.00	adjust up tracks, grease all bucket pins. Fit retainer to bucket pin. Start to segegrate wiring.	
11-Dec-13	G Wykes		$845.00	Fab & fit handrails.	
11-Dec-13	Shane	4305	$150.00	remove bucket pin & shim, refit. Loosen tracks & sit chain guides in place, clean threads. Tried to bolt up in place but wouldn't line up with holes. Wrong guides supplied. Lift machine back up & remove guides. Fit new bucket teeth. Fit all bolts & tighten walkway. Fit handrails.	
10-Dec-13	Jono Pittin		$682.50	Fit grouser plate tighten up, reshim boom, clean up bucket pins and load on trailer.	
10-Dec-13	G Wykes		$1,137.50	repair bucket. Fab handrails.	
10-Dec-13	Dave Oleary	4297	$1,186.25	Fit grousers, shim boom, grease pins, tension tracks, repair LHS boom light, fit stick and bucket, fit walkway	
10-Dec-13	Josh Hewett	4297	$227.50	Help Dave remove boom pins and fit shims	
10-Dec-13	Greg Mills	4305	$357.50	Fit stick/bucket and walkways	
09-Dec-13	Ted Van		$162.50	Assist with track link assy.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
09-Dec-13	Jono Pittin	4297	$682.50	Check all accumulators, continue with Tomingley checklist and clean up track pins and replace with new links.	
09-Dec-13	Dave Oleary	4297	$725.00	Remove broken rock guard bolt, finish building new track section, fit rock guard, fit UHF and aerial, tighten panel bolts, remove u/s section of track.	
09-Dec-13	Josh Hewett	4297	$195.00	Help press new chain links in place	
07-Dec-13	Ted Van	2860	$227.50	Reseal leaking fittings on hyd pump, remove rock guard for broken bolt removal.	
07-Dec-13	Dave Oleary	4297	$422.50	Tighten counterweight bolts, refit grease line and clamp to slew ring, loosten LHS track, start removing broken bolt from rock guard, fit UHF aerial.	
07-Dec-13	Jono Pittin	4297	$97.50	Oil leak in pump room, place reflective tape on digger.	
06-Dec-13	Ted Van	2860	$650.00	Assemble new track links, assist with boom cylinder fitting, diagnose oil leak on control valve of hydraulic pump.	
06-Dec-13	Steve Grant	4296	$195.00	Segregated wires	
06-Dec-13	Josh Hewett	4297	$487.50	Prepare for boom to be fitted, fit boom.	
06-Dec-13	Dave Oleary	4297	$725.00	Press together track links and fit pins, assist with fitting boom and counterweight, fit boom cylinders and plumb up boom.	
06-Dec-13	RLW		$650.00	repair oil leaks on rear pump, replace 2 hoses, & Oring on fitting. Fit boom & counter weight to machine.	
06-Dec-13	Jono Pittin	4297	$325.00	Repair hydraulic leak on control valves, replace top pilot lines in pump room, separate electrical wiring from hyd hose.	
05-Dec-13	RLW	4297	$227.50	clean pins, bushes on boom ready to fit. Clean counter weight surfaces.	
05-Dec-13	Ted Van	4297	$682.50	Remove pins from bucket and dress up bushes, fit new bushes and seals into stick end and bucket link end, start assembling tracks.	
05-Dec-13	Jono Pittin	4297	$390.00	Electrical and hydraulic hose separation around swing boxes, hydraulic oil leak on control valves x 4.	
05-Dec-13	Josh Hewett	4297	$617.50	Segregate all wiring from hoses, help dave remove grouser plates, clean up counterweight matting surface. Clean up boom pins.	
05-Dec-13	Dave Oleary	4297	$790.00	Remove grousers, replace cracked track plate, refit 1 x cracked track plate, start assembly of new track section.	
04-Dec-13	Ted Van	4297	$585.00	Remove stick end and bucket link end bushes and clean up, assist with machine checkover.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Dec-13	Dave Oleary	4297	$725.00	Check over, inspect tracks, organise parts, start removing grouser plates, assist with stick bush removal.	
04-Dec-13	Jono Pittin	4297	$325.00	Remove fir supression bottles, make up rubber bushes for mounting, tidy up electrical wires around engine, remove track grousers.	
03-Dec-13	G Wykes		$35.00	clean threads in track frame.	
28-Nov-13	WMS - T		$400.00	strip & load onto float.	
27-Nov-13	WMS - T		$600.00	Demob at Sweetmans yard.	
27-Nov-13	WMS - A		$400.00	Demob machine.	
26-Nov-13	WMS - T		$800.00	Strip down for transit.	
26-Nov-13	WMS - A		$300.00	Demob machine.	
25-Nov-13	WMS - A		$400.00	Demob Machine.	
24-Nov-13	WMS - A		$100.00	jumpstart machine & move to a suitable position for demob.	
19-Nov-13	WMS - A		$200.00	completed paperwork to strip machine.	
27-Oct-13	WMS - A	4295	$200.00	inspect & repair bucket pin retainer bolts.	
13-Oct-13	WMS - T		$200.00	do off hires.	
02-Oct-13	WMS - T	4230	$300.00	change out belly guard broken bolts.	
29-Sep-13	WMS	4226	$200.00	Replaced 2 bucket teeth. Adjusted track tension.	
20-Sep-13	WMS	4196	$300.00	Cut down lip guard to fit and fitted to excavator.	
14-Sep-13	WMS		$100.00	Fill up battery fluid levels as they were low.	
07-Sep-13	WMS		$100.00	Jump start machine	
30-Aug-13	WMS - A	4832	$350.00	replaced Oring on hyd hose. General checkover.	
17-Aug-13	WMS - Tom		$200.00	inspect for no greaseing, blown fuse.	
16-Aug-13	WMS - Tom	4052	$200.00	change out unserviceable grease injector.	
13-Aug-13	WMS - Tom	4030	$600.00	4000 hr service. Note: crack in bucket.	Note: crack in bucket.
05-Aug-13	WMS	3969	$100.00	repaired fault with steps. Tightened loose bucket pin bolts.	
03-Aug-13	WMS		$600.00	removed & replaced hyd hose for boom.	
31-Jul-13	WMS	3923	$400.00	repaired starting fault. Cleaned terminals. Checked & cleaned all earths.	
26-Jul-13	WMS	3909	$100.00	tighten belts.	
23-Jul-13	WMS		$300.00	fit up bucket G.E.T.	
22-Jul-13	WMS		$350.00	change out leaking drive box Orings & hose.	
19-Jul-13	WMS	3870	$200.00	repair fuel leak - banjo fitting.	
30-Jun-13	WMS	3730	$100.00	repaired broken air line to horn.	
20-Jun-13	WMS		$100.00	fit up earth harness that I made to bypass ECM earth.	
19-Jun-13	WMS	3658	$300.00	chagne out bucket teeth & test no start.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
17-Jun-13	WMS	3641	$200.00	diagnose starting problems, not found fault yet.	
16-Jun-13	WMS	3643	$300.00	starting problem. Carry out test for no starting. Bridged out starter for time bean.	
07-Jun-13	WMS	3536	$200.00	measured pins (bucket), adjusted tracks, inspected oil leak at valve body.	
04-Jun-13	WMS	3564	$400.00	shimmed bucket. Checked autogreasing operation. Tightened belts.	
31-May-13	WMS	5236	$90.00	Inspect greasing system. Brease up bucket	
28-May-13	WMS	3521	$540.00	Change out GET. Cutting sdges, weld on buttons and side wings.	
27-May-13	WMS		$180.00	Shim up main bucket pin.	
25-May-13	WMS	3495	$360.00	Change out blown hose & carry out 500 hour service.	
22-May-13	WMS	3483	$90.00	Fit up new fabbed up banjo bolt for auto greaser.	
30-Apr-13	WMS		$360.00	Chage out 3 o rings in slew centre area.	
29-Apr-13	WMS	3405	$180.00	Change 2 cat wear tyres.	
17-Apr-13	WMS	3338	$90.00	Fit up tilt cly hose that got repaired.	
16-Apr-13	WMS	3338	$270.00	Removed hose.	
13-Apr-13	WMS	3333	$360.00	repaired leaking oring on A/C system. Recharged A/C system	
06-Apr-13	WMS	3315	$360.00	Replaced blown oring on main valve block, filled with oil.	
02-Apr-13	Tom		$360.00	250 hour service & change leaking hose in pump room.	
29-Mar-13	WMS		$100.00	inspect for oil leak.	
21-Mar-13	WMS		$100.00	inspection of digger.	
19-Mar-13	WMS	3197	$300.00	change out bucket teeth.	
10-Mar-13	WMS		$100.00	move spare bucket to borrow pit.	
08-Mar-13	WMS	3167	$200.00	repalced A/C belt. Assisted in fire suspression check/service.	
01-Mar-13	WMS		$100.00	change out air cleaner & check over.	
21-Feb-13	WMS	3073	$100.00	inspection & changed air filters.	
10-Feb-13	WMS	3017	$600.00	installed track & tensioned. Machine check over.	
09-Feb-13	WMS	3017	$800.00	installed 2 of 3 track link pins. 3rd pin picked up & seized. Removed link assembly's put in press & removed seized pin. Assembled link assembly's & installed onto track.	
08-Feb-13	WMS	3017	$800.00	fitted new links & bushes. Drove to Mackay & picked up link pins & dropped off broken track press.	
07-Feb-13	WMS	3017	$950.00	pick up track press. Completed JHA & paperwork to do the job. Pressed out & removed track link assemblings.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Feb-13	WMS		$400.00	order parts & organise press for broken track.	
03-Feb-13	WMS		$300.00	inspect & move digger after snapping the track.	
02-Feb-13	WMS	3011	$200.00	refit up belly guard as bolts rattled loose.	
28-Jan-13	WMS	2982	$400.00	finish off 1000 hr service. Oil, fuels, airs, drive oil & checks.	
27-Jan-13	WMS	2982	$600.00	fire suspression fault, low on gas. Charge up & check for nitro leak, end up finding a leak at the gauge @ main bottle, discharge gas & reseal guage & charge back up to speck & test, OK for leak. Change out 2 small wear tyles. Change final drive oils.	
21-Jan-13	WMS		$100.00	inspect bucket & organise parts.	
18-Jan-13	WMS		$300.00	repalced leaking fuel fuilters. Inspected low power problem. Replaced blocked air filter.	
12-Jan-13	WMS	2913	$200.00	diagnosed & repaired steps inoperatable. Replaced fuse & repaired wiring.	
09-Jan-13	WMS	2803	$200.00	machine checkover & recharge fire suspression.	
21-Dec-12	Mark Unwin	2903	$190.00	checked fire suspression alarm as low on charge. Aquired nitrogen & returned to site with kit. Charge fire suppresion system & tape up exhaust.	Note: starter isolator handle missing.
16-Dec-12	WMS	2879	$99.00	change out broken bucket tyle.	
13-Dec-12	WMS	2856	$99.00	grease fault, had an air lock in main pump.	
11-Dec-12	WMS	2834	$99.00	change up fire suspression system. Spray soapy water everywhere no leak found.	
05-Dec-12	mark unwin	2792	$140.25	inspection & grease.	
28-Nov-12	WMS	2757	$360.00	Full machine inspection, topped up engine/hydraulic/swing motor oils, tightened track guides.	
22-Nov-12	WMS	2713	$90.00	Check over machine	
22-Nov-12	Mark unwin	2712	$380.00	fit bucket to stick. Clean worn out bolts & retaining caps & cleaned out broken threads. Quick steel & loctite bolts into pin & tensioned by hand only.	Note: grease system still has 'fault'.
22-Nov-12	WMS	2713	$270.00	Fit up bucket.	
21-Nov-12	WMS	2713	$135.00	Unload bucket and clean pins and bushes.	
13-Nov-12	Mark Unwin	2710	$255.00	Remove bucket pins and carry out inspection, replace air filters, anti seize LH front track guide bolt on outside and retension.	Front slew motor low on oil, LH front handrail cracked, alternator belt cracked badly.
13-Nov-12	WMS		$198.00	remove bucket to go into town for welding.	
06-Nov-12	WMS		$135.00	Machine inspection - tighten belts, top up swing motor oil.	
05-Nov-12	WMS		$180.00	Repair grease system	
03-Nov-12	WMS	2677	$45.00	Clean out fuel tank breather.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-Nov-12	Mark Unwin	2658	$380.00	Still diagnosing not starting - checked all earths, checked batteries & found joiner lead hot & losing volts when starting. Relays behind seat faulty. Fixed coolant leak on bypass hose at front of engine. Re-assembled & started to move bucket, fit grease nipple & grease.	
01-Nov-12	WMS	2660	$270.00	Finish off repairing starter wire, assemble all panels/guards and covers that were removed.	
31-Oct-12	Mark Unwin	2658	$237.50	Diagnose why starter motor's would not engage to start engine, as relays on starters not engaged from additional relays fitted to starters. Repalced lower starter relay & attempted to start. Bad earth from key signal.	
31-Oct-12	WMS	2660	$360.00	Repaired wiring to starter motor solenoid after fault finding and diagnosis.	
27-Oct-12	WMS		$90.00	Powerstair wouldn't operate - cleaned all sensors and took all paint off where the sensors pickup from.	
26-Oct-12	Mark Unwin	2622	$297.50	Fit grease hose and secure other hoses, return to workshop and make up new grease hoses, stairs sticking up adjusted sensors until light came on - still stuck, released pressure ontop of stair bank ram and trimmed lockdown. Raised and lowered stairs, tom tight with bent stairs, checked grease hose on tiller and bucket pins found dry, greased injectors.	
25-Oct-12	Mark Unwin	2612	$170.00	Power stair repairs, checked boom grease supply and found dry filler hose looked wet, checked over rest of digger and tightened bucket pin bolts.	
25-Oct-12	Mark Unwin	2620	$170.00	checked grease hose ontop of tiller after manouvering it to boom, removed broken hose and sourced in town.	
25-Oct-12	WMS	2612	$225.00	Repair bent steps	
24-Oct-12	WMS	2612	$90.00	Repair bent steps	
23-Oct-12	WMS	2604	$90.00	Check over machine and fit up belly guards	
20-Oct-12	WMS	2570	$360.00	500hr service	
19-Oct-12	Mark Unwin	2873	$170.00	500hr service and complete most of checklist.	
19-Oct-12	Mark Unwin	2873	$190.00	500hr service and complete most of checklist.	
14-Oct-12	Mark Unwin	2530	$166.25	LH track guide bolt missing, RH track ladder missing, Tightened loose bucket retaining pin bolts, grease bucket and adjust injectors.	
12-Oct-12	Mark Unwin	2515	$47.50	Bucket pin bolts stripped pre start check, tightened other two bolts.	
11-Oct-12	WMS	2513	$45.00	Machine Inspection	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Oct-12	WMS	2490	$90.00	Inspect for stairway damage and e-mail photos to Dom.	
05-Oct-12	Mark Unwin	2468	$85.00	Inspection - drive belt worn out LH, grouser plates bent out RH grouser plates bent badly and guides blue.	
02-Oct-12	Mark Unwin	2449	$85.00	Changed primary air filter and inspected engine for leaks OK, manouvered to turkeys nest.	
26-Sep-12	Mark Unwin	2407	$85.00	Fitted RH bucket side G.E.T with sledge hammer and bolted in.	
24-Sep-12	Mark Unwin	2397	$85.00	Take boilermaker to bucket.	
22-Sep-12	WMS		$90.00	Step won't go up, faulty terminal - fixed terminal.	
21-Sep-12	WMS	2380	$135.00	Loose pin retainers, replaced grease fittings.	
18-Sep-12	Mark Unwin	2375	$47.50	change engine oil.	
17-Sep-12	WMS	2375	$225.00	Serviced machine.	
16-Sep-12	WMS	2370	$90.00	Inspect missing bucket G.E.T.	
06-Sep-12	WMS		$47.50	reset power stairs.	
03-Sep-12	WMS	2280	$95.00	digger inspection - LH step torn off.	LH step torn off.
01-Sep-12	WMS		$95.00	digger inspection.	
25-Aug-12	WMS	2214	$380.00	grease leak. Change out grease output pump fitting. Reset power steps.	
11-Aug-12	WMS		$380.00	Cont 1250 build.	
10-Aug-12	wms		$1,140.00	Cont. with 1250 build.	
09-Aug-12	WMS		$712.50	Cont with 1250 build.	
09-Aug-12	Graham W		$97.50	Take handrails etc to site.	
07-Aug-12	Graham W		$455.00	Fit up machine.	
07-Aug-12	WM S	2114	$855.00	Fit up counter weight & boom @ sweetmans yard.	
03-Aug-12	Graham W		$195.00	Unload Truck	
02-Aug-12	Lance		$1,248.00	De mob machine and organise cranes at late notice, remove boom, remove counterweight, load trucks unload machine at scottys quarry, finish loading trailers escort off site.	
02-Aug-12	Graham	2114	$312.00	Chase up scotts quarry, so to park machine off wiggins island, escort machine off site onto quarry unload machine escort truck offsite.	
02-Aug-12	Max		$1,248.00	Remove boom cyl from boom, remove pivot pins and lift off boom and counterweight, load excavator and parts onto trucks, work in with cranes.	
01-Aug-12	Lance		$260.00	Loosten counterweight bolts remove retainer plates for boom cyl + boom foot pins, remove and cap boom arch hose, pick up chain for boom cyls.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-Aug-12	Max		$312.00	Disconnect and cap boom hoses and wiring, start remove pins.	
31-Jul-12	Max		$1,196.00	Clean and fit remaining belly plate bolts, move walkways and handrails to storage area, weld missing foot to handrail and paint, relocate machine away from wash pad, place pin seals and shims in tool box.	
30-Jul-12	Max		$988.00	Remove walkways, fit handrails, remove exhaust and air cleaner tops, fit carrier and body belly plates, prime grease through stick hoses.	
29-Jul-12	Noel Fitzsim		$660.00	Paint handrails for site delivery on Monday morning.	
27-Jul-12	Max	2112	$522.50	Remove body and carrier belly plates, remove hand rails for painting.	
25-Jul-12	Max		$418.00	Off hired, assist removing hand rails	
24-Jul-12	Max		$418.00	Help bleed grease lines and test fire supression.	
23-Jul-12		2112	$418.00	Assist boilermaker fitting steps and handrails	
20-Jul-12	Lance		$104.50	Fit lhand walk way	
17-Jul-12	Max	2110	$522.50	Disconnect and cap hoses, remove pins and lift off stick from boom and wash.	
17-Jul-12	Lance	2111	$1,045.00	Remove stick from boom, pick up capping plates from Becher.Assist with auto lube fitout, organise new grease seals and O rings for assembly	
16-Jul-12	Lance	2111	$522.50	Assist to fit auto lube system and fire supression.	
12-Jul-12	Max	2110	$332.50	Demobilision. Remove bucket & rear walkway.	
12-Jul-12	Lance	2110	$332.50	remove bucket & rear section of walkway. Clean pins & retainer caps.	
07-Jul-12	Graham		$940.50	Assemble slew box, fit new bearings, pins and gears and fit to machine. Fill oils and test ok.	
07-Jul-12	Max		$285.00	fit rebuilt front slew drive assy. Fill with oil & test OK.	
06-Jul-12	Graham		$522.50	Strip and clean slew box, order parts	
04-Jul-12	Lance	2098	$1,092.50	dissassemble swing machinery (front). Take photo's. remove front swing machinery housing from calbody. Put on flat bed & sent to beecher. Had to wait for transport.	
03-Jul-12	Lance	2098	$760.00	noise found in front slew, found no oil in slewbox. Dissassemble front slew machinery case top planetry gear set u/s. not checked by operator at pre starts.	
23-Jun-12	Max		$418.00	Set up dozer and new track. Walk onto track and pull inot position on rear idler.	
12-Jun-12	Lance		$104.50	Carry out prestart inspection.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Jun-12	Lance	1922	$418.00	C/O H-link pin as we didn't have a replacement retainer plate to suit pin, clean up pins and wait for forklift.	
04-Jun-12	Max	1977	$313.50	Check retainers for bucket pins, spares and different, replaced pin and restrainer assy until new retainer made.	
01-Jun-12	Lance	1977	$992.75	200 hour service	
17-May-12	Lance		$104.50	Rotate bucket teeth + grease machine.	
27-Apr-12	Chris		$455.00	repair grease pump & refit. Fit service tail.	
16-Apr-12	Lance		$142.50	grease bucket circuit.	
12-Apr-12	Lance		$95.00	dry pins - operator reported sqeeking at bucket, grease machine.	
10-Apr-12	Lance		$570.00	fit bucket, grease machine, clean up & walk machine to pit.	
10-Apr-12	Graham F		$665.00	complete machine assy. Grease, top up fluids.	
05-Apr-12	Lance		$1,092.50	Assemble machine.	
05-Apr-12	Graham F		$1,092.50	Assemble machine.	
04-Apr-12	Lance		$237.50	Unload machine & fit stickers.	
04-Apr-12	Graham F		$237.50	Unload machine. Start assy.	
02-Apr-12	Chris		$195.00	Demobilisation.	
02-Apr-12	Greg M		$715.00	Wash down. Fit guards. Remove stick, counterweight & boom. Remove handrails.	
01-Apr-12	Chris		$747.50	Demobilisation.	
01-Apr-12	Greg M		$292.50	Cleaned machine. Remove bucket.	
31-Mar-12	Merv		$440.00	Fit new quick fill and pipes	
31-Mar-12	Chris		$487.50	Clean & dismobilisation. Fit new quick fill hose. Overflow hose.	
28-Mar-12	Merv		$82.50	Quick fill	
26-Mar-12	Merv		$192.50	Steps	
23-Mar-12	Merv		$247.50	Steps.	
23-Mar-12	Merv		$55.00	Change teeth	
23-Mar-12	Chris		$130.00	Site compliance work.	
22-Mar-12	Chris	1660	$65.00	R & R bucket teeth.	
20-Mar-12	Chris		$65.00	check bucket cracks * oil leaks.	
19-Mar-12	Merv		$55.00	Remove plates for quick hitch fill and elect fitting housings	
19-Mar-12	Merv		$330.00	New steps	
16-Mar-12	Jeff R		$97.50	fit handle to manual grease line. Fit grease bucket & hook up hoses. Top up hyd oil tank.	
16-Mar-12	Chris B	1616	$195.00	Finish service, check over, rotate teeth.	
15-Mar-12	Jeff R	1250	$585.00	clean up grease spill. Remove grease cylinder. Change hyd filters & fuel filters. Clean up grease unit.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
15-Mar-12	Chris B	1610	$390.00	Service - R&R new water pump clean.	
14-Mar-12	Chris B	7788	$422.50	Check oil leak & overheating fault. R &R new pilot hose. Check fan shuttle valve. Service. Repair pilot oil filter housing oil leak.	
14-Mar-12	Jeff R	1250	$227.50	change engine oil & filters. Repair grease.	
12-Mar-12	Jeff R		$65.00	check engine oil level. Top up, put cover back on.	
12-Mar-12	Merv		$437.50	Make up new steps.	
10-Mar-12	Chris		$65.00	fit new bucket retainer bolts.	
10-Mar-12	Jeff R		$195.00	500hr service.	
07-Mar-12	Merv		$70.00	fit step.	
06-Mar-12	Merv		$280.00	make up step.	
02-Mar-12	Chris		$65.00	R & R air filters, check over for service.	
16-Feb-12	Merv		$245.00	Replace belly plate. Make up step.	
16-Feb-12	Graham W		$285.00	Fabricate step & fit. Repair belly plate.	
13-Feb-12	Merv		$140.00	Steps.	
30-Jan-12	Ted	1308	$162.50	Remove and replace bucket.	
30-Jan-12	Merv		$0.00	Wear package	
14-Jan-12	Merv		$35.00	Check air cleaner	
04-Jan-12	Shane	1144	$178.75	Diagnose electrical fault code lifting power. Carry out diagnostic checks for active code, all Ok. Found electrical system over ride switch on. Turn off.	
02-Jan-12	Merv		$630.00	Wear package.	
02-Jan-12	Jed		$840.00	Weld wear package & cracks on bucket.	
31-Dec-11	Merv		$840.00	Wear package	
31-Dec-11	Jed		$70.00	Cut tracks 1250.	
30-Dec-11	Jed		$840.00	Cut tracks 1250	
30-Dec-11	Merv		$840.00	Cut tracks 1250.	
29-Dec-11	Merv		$840.00	Cut Grouser plates	
29-Dec-11	Jed		$840.00	Cut track plates 1250.	
23-Dec-11	Merv		$490.00	Cut Grouser Plates.	
20-Dec-11	Red		$0.00	Change out full set of teeth.	
19-Dec-11	Red		$0.00	check out worn lip shrouds & cracks in bucket.	
08-Dec-11	Red		$55.00	Check out oil leak	
03-Dec-11	Red	1039	$0.00	Do 1000 hr service as per manual. Change oils in finals, swing boxes PTO and engine, change hydraulic filters, oil filter and air filter	
24-Nov-11	Merv		$0.00	Wear package bucket	
16-Nov-11	Merv	941	$0.00	Repair oil leak at control valve.	
15-Nov-11	Merv	932	$0.00	Check out oil leak & report bucket wear.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
10-Nov-11	Red		$0.00	Swap line relief valves to try to find problem swap pilot lines to chase problem.	
22-Oct-11	Red	745	$0.00	Refit front windscreen and adjust frame to suit. Tighten loose tub guard bolts	
13-Oct-11	Red		$0.00	Get digger back to worshop	
12-Oct-11	Red		$0.00	Change out 5 teeth	
28-Sep-11	Red		$0.00	swap teeth on bucket	
24-Sep-11	Red	639	$0.00	Grind up damage on stick and fit armour base plate	
20-Sep-11	Red	631	$0.00	Change out bucket on 1250 with bucket out of shed	
09-Sep-11	Red		$0.00	Remove pin from bucket (spare), remove bush and wear ring, move bucket for weldig, measure up powerlink pin. Seal leaks in container and update serviceboard	
07-Sep-11	Red	563	$0.00	Gouge and weld crack in moveboard on bucket. Do 500hr service	
06-Sep-11	Red	563	$0.00	Gouge cracks on inside of bucket and weld	
01-Sep-11	Red	525	$0.00	Swap outside teeth for centre ones.	
01-Sep-11	Red	520	$0.00	Blow out air cleaner and check out bucket crowd problem. Clean cab filter	
31-Aug-11	Red		$0.00	Move bucket from erection pad to shed and position in shed	
26-Aug-11	Red		$55.00	change bucket teeth.	
01-Aug-11	Red	369	$165.00	Fit isolators, fire extinguishers and fill oil for hydraulics.	
31-Jul-11	SCOTT	359	$1,182.50	Installed boom & cylinder & lines. Installed stick & cylinders & lines. Installed bucke. Fitted all panels & walkways back on machine. Fitted counterweight.	
31-Jul-11	Red		$522.50	Assemble 1250 Excavator.	
30-Jul-11	Red		$825.00	Assemble Excavator.	
06-Feb-01	WMS	3017	$150.00	organise track press & parts.	
	John	10514	$110.00	Remove hoses (leaking)	
	WMS	2806	$247.50	fire alarm going off, end up being low on gas, change up to spec.	