Work Order History Report

Transmission rebuild at 15964 hours

Asset	W/O No	Description	Finished	Done Reading	
P0294		Cat 773F Dump Truck			
	59358	HME Inspection - Rigid Dump Truck Quote #: 434 Tub lock bent Oil leak at filter RH side engine (top steer) Suction hose for trans squashed Window washers Mirror rubbers Drivers door not sealing well Leak at filters LH side drop box Wash/ inspect hyd pump Leak at hoist control Wash out radiator for side (BOTTOM) 250 Hour service	4/12/2025	16799	Hours
	58080	October R & M Monthly WO USO: - Fan belts U/S, replace belts 16741hrs 17/10	27/10/2025		Hours
	57638	September R & M Monthly WO: - park brake stuck on, repair broken wire 16547hrs 09/09 - Inspect truck for slow tub lowering and not locking in first with tub up - Inspect switch operation - Connect ET and found transmission configured to 3rd when tub up, reset to 1st - Inspection/ Fix headlight 27/09	27/09/2025		Hours
	56021	JULY R&M -A frame pin falling out, damaging harness and hosing, 16302hrs 04.07 - faults on dash 11.07 - investigate intake pressure sensor codes, inspect sensor supply, ground and return voltages. 14.07 - swap sensor from another machine , no good - carry out wiggle test, found fault in harness. - inspect engine speed sensor code, inspect sensor and harness - unable to locate fault - work with GB auto to repair codes on dash 21/07 - tub not coming all the way down, adjusted proxy. 25/07 - Repair transmission harness, repair brackets & try to install pin for transport chain up A frame - Fit hydraulic hardlines and hoses R+R orings, fit pins to dog bone, fit clamps to hoses, grease machine - Fit dog bone bolt	18/09/2025		Hours

Asset	W/O No	Description	Finished	Done Reading	
		- Gas struts, replace AM/FM radio and aerial, charge brake accumulators (brake fault) - Order gas bottle for struts			
	55011	Fuel tank breathers not working when fueling up. Supply vent kits.	18/09/2025		Hours
	56710	August R&M Monthly: - hoist fault sometimes doesn't come down, bad connection in control panel 16373hrs - Fabricate rock ejector wear plates - Fuel leak cause breather - Fit UHF aerial - Replace fuel tank breather - Horn button damaged ordered new one - Checked over lights Leaking tyre - send replacement.	18/09/2025		Hours
	57335	Rigid Dump Truck - 500hr Service and to do repairs 16540hrs - service and repair horn button	8/09/2025	16540	Hours
	54052	Charge front struts. Flip access steps.	5/08/2025		Hours
	55326	June USO R&M - Line Bore & repair A frame - Attempt to set speed limit - Change out faulty turbo inlet sensor. Lock out speed in truck - Daily grease - Fix am/fm radio, replace halogen lights with LED - Hoist leaver fault. Test leaver inputs and outputs will require replacement. - Order parts - Replace hoist/ trans lever unit - Top up coolant - Grease - Wouldn't select all gears, stopped on haul road found A frame pin had warped, damaging harmed, Got back to workshop organise repairs test.	30/07/2025		Hours
	55555	Rigid Dump Truck - 250hr Service 16196hrs 16304.5 11.07.2025 completed in Dubbo with A frame	10/07/2025		Hours
	55574	12 Month fire suppression and fire extinguisher service	13/06/2025		Hours
	54710	May USO R&M. Swap out mine radio unit, test, ok Mount new mine radio unit, put cab back together Top up trans oil, fit UHF Remove and replace blown trans cooler hose Grease, set speed limit and gear Check tyre pressure	31/05/2025		Hours

Asset	W/O No	Description	Finished	Done Reading	
		Top up hyd oil, top up coolant Organise parts for jobs Check a/c - cab was fogging up Trucks breaking down/asset fitter over the place. Collect parts for site P1137 Electrical faults. Remove Alt circuit breaker earth. Clear and re-fitted. P0292 Coasting in neutral fault. Checked input/output sensor. Test drive with operator. Checked gear lever through ET. P0301 Some fault/repairs at P1137 - sent back to work all good. P0935 Cannon direction not working. Remove/cleaned ... tested good. P0237 Dry pin removed and greased manually. P1136 Remote shutdown fault. By passed switch until new one arrives. Steer oil level low, fill up 20L drum and top up steer oil A1-502 .5hrs Organise service kit. P0301 .5hrs. P1136 .hrs. P1201 .5hrs Organise parts for repair Collect parts and road up for site Trans cooler hose rubbed through and leaking			
	50923	Capital Repairs Pre hire repairs as per HME inspection and installation of hungry boards. w/o 49052 Fab and install tub hungry boards Defect repairs. Fire suppression system audit, RA, repairs and service. Rim removal, NDT. Installation. Pressure vessel inspections. Sepura radio install. ITS Ulan. Electrical Ulan spec. USO OIL CHARGE OUT	28/03/2025		Hours
	49052	HME Inspection - Rigid Dump Truck Quote #: 213 Hrs: 15987 09.10.24	10/10/2024		Hours
	21194	Missed invoice from work order 15268 and work order 15282 - Wade Earthmoving Hours: 15953 25/06	12/09/2024		Hours
	21018	Replace transmission hose	6/08/2024		Hours
	21065	Remove panels check battery’s and jump start machine	30/07/2024	15947	Hours
	15268	Truck is riding rough, charged accumulator and struts have gone down. Need to order new valve for rear. Hours: 15890 No WER invoice. Possible PWE labour	30/06/2024		Hours
	12581	Rigid Dump Truck - 250hr Service PWE labour hrs - 15727	30/06/2024		Hours
	17437	Repair transmission after failure. Remove transmission at Tynong. Fab transport stand - send transmission to Dubbo. Strip transmission, found 1 x destroyed planetary group due to sheared spring pin. Assess all iron, replace as required. Measure all frictions and steel plates, replace any outside CAT spec. Replace all seals and bearings.	21/06/2024	15914	Hours

Asset	W/O No	Description	Finished	Done Reading	
		Send Transmission to Tynong. Remove and overhaul transmission pump at Tynong. Install transmission. Callibrate transmission after install - check pressures after callibration - all in spec. 15961hrs.			
	15282	Pulled thread out of cap on steering cylinder. Hours: 15914 No WER labour invoice. Possible PWE labour.	29/04/2024		Hours
	14914	Rigid Dump Truck - 16000 Hour service Hours: 15877 15914 26/04/ Load up oils for service Set machine up for 16000hr service Change engine oil, transmission oil Front hub oils, and rear diff oils Change all filters supplied Check over machine front to back Clean out transmission screen Found metal in screen Take photos of screen and metal Complete service Clean up area machine Complete paper work and service report Fill out oil samples	26/04/2024	15914	Hours
	14031	Adjust front and rear strut pressures Adjust ride height and test machine	8/04/2024	15818	Hours
	13467	Replace reverse camera Hours: 15706 Reports of Camera monitor showing blue screen. Assess monitor inputs. Find it to be ok. Check over the camera cable, and find it to be ok. Plug in a test camera & find it to now be working. Diagnose camera as faulty & speak to Bryce on rectification.	25/03/2024		Hours
	10047	@Wade Earthmoving FAULT- Rock ejector has bent pin and will require following parts to get truck back going, will also need to weld block back into place as it's bent so far it allows the bar to hit the hub, all parts please be sent to wade earthmoving repairs, REPAIRS - 26/02/2024 Load up ute Travel to site Drill out broken bolts Install new airline Install new cover Remove rock ejector bar Organise new parts Pump up tyre Pack up ute. Load up truck Travel to site Cut off bar Clean up eyes Straighten eyes Weld in new bar Install ejector bar with new washers pin and clips Paint mount Pack up truck Travel back Unload truck. Wheel assembly taken off so rock injector can be removed. Position 5 - valve extension and protector plate replaced. Wheel assembly replaced. Hours: 15666	9/03/2024		Hours
	9679	Diagnose body coming down hard Notice body sensor not working as it should Adjust sensor till body soft closes Notice tyre valve damaged from ejector bar jumping hub Organise tyre fitter	24/02/2024	15643	Hours

Asset	W/O No	Description	Finished	Done Reading	
	8477	250hr service & prehire repairs Replace transmission fill tube and cap Torque up wheels & fit wheel nut indicators Replace brake cooling hose Replace camera Remove old fish plates, repair cracks, replace fish plates Fulcrum photos	22/01/2024	15638	Hours
	4695	Capital Expenditure - Gouge off old wear plates on tail of tipper, cut out damaged rib under rear end, have new section bent up to shape, dog down and align new piece in place, cut and place new wear plates, weld out all new works. Patch wear holes on inside walls of tray both sides Remove & repair damaged front panel on truck Repair Broken walkway platform mounting plate Rim inspections	17/08/2023	15631	Hours
	1265	Start and load machine onto float	2/05/2023		Hours
	556	Check over and do up defect list. Chase up walkways & hungry boards. Drive out to quarrie to inspect hungry boards to see if still useable.	23/03/2023	15404	Hours
	17299	Hours 15032 - 1000 Hour service	9/10/2022		Hours
	17300	Broken step - Removed and replaced step rubbers as required. Left hand hungry board damaged, to be assessed by boilmaker Right hand rear tyre damage - inspected. ok to return to work	29/09/2022		Hours
	17302	Replace rubber on front steps, remove and replaced as required.	24/09/2022		Hours
	17303	Transmission oil low - top up oil	22/09/2022		Hours
	17307	Remove dog bone pin bolt from P1205 & fit to P294	14/09/2022		Hours
	17308	Hours 11634. Replaced rock injector. Fit new rock ejector & remove rock	5/09/2022		Hours
	17309	Hours 14629. Remove rack from between POS 3&4. Pump tyres up.	4/09/2022		Hours
	17310	Hours 14564 - 500 hr service	26/08/2022		Hours
	17304	Hours 14522 - 500 Hour service	24/08/2022		Hours
	17312	Finish installing rod	23/08/2022		Hours
	17315	Hours 14522 Electrical fault with lights	22/08/2022		Hours
	17314	Strip and clean brake calipers, assemble with new seals	22/08/2022		Hours
	17313	Strip & clean brake calipers assemble with new seals	22/08/2022		Hours

Asset	W/O No	Description	Finished	Done Reading
	17316	Broken rock injector. Fab & install new rock injector from 25mm biz (all we have)	13/08/2022	Hours
	17306	Pre start defects Reverse camera not working, checked at service interval. Unserviceable. Noted for replacement. Tyre side wall damage, noted on service interval checks. Headlight casing, damage noted. OK to return to work. Fire extinguishers to be tagged - removed and replaced fire extinguisher as required.	5/08/2022	Hours
	17317	Hours 14275 - 250 hour service. Defects, oil leaks and grease lines.	3/08/2022	Hours
	17318	Hours 12980 - fill coolant	27/07/2022	Hours
	17319	Hours 14072 - fuel and grease. check over machine.	22/07/2022	Hours
	17320	Hours 14056 Stair repairs on mount to front Remove weld at mounting cable replaced	21/07/2022	Hours
	17321	Hours 14056 - 1000 hr service & defects	19/07/2022	Hours
	17322	Hours 14056 Repairs to hungry board due to accidental damage. Hungry board weld out after repairs	18/07/2022	Hours
	17323	Hours 14024 - Tighten LHR and RHR wheel nuts	7/07/2022	Hours
	17324	Hours 14001 250 hour service and defects. Topped up all oils.	1/07/2022	Hours
	17325	Hours 13935 - fixed hydraulic leak on steer cylinder. Filled up steer oil. Blew out air filters.	24/06/2022	Hours
	17327	Hours 13909 - Inspect seat air leak - found loose fitting. Resealed and installed all air lines and tested. Resolved steering cylinder hose.	19/06/2022	Hours
	17328	Hours 13745 - Check engine oil light on, diagnose and test, dicky e-stop connections. Access platform loose, tighten and fit new bolts, tidy and repair wiring under platform	6/05/2022	Hours
	17330	Hours 13516 - Lifted body of machine then secured it at the rear points. Tested solenoid with pressure gauge. Removed top of transmission, removed solenoid 6&7. Put gearbox back together and tested	16/03/2022	Hours
	17339	Hours 13516 - Removed steps, walk ways and steps from the back of the vehicle. Lifted walk ways up with the crane then bolted to the vehicle, also lifted and bolted roof guards to the body of the truck.	14/03/2022	Hours
	18024	Hours 13242 Remove RH steer cylinder, won't go full lock, clean ball stud bores on new cylinder and fit ball studs, refit cylinder to machine and test, ok, take to boilermaker for repairs. Weld up cracks underneath cab on both sides, weld up cracks on shoulders, weld wear plates in tub.	3/03/2022	Hours
	18023	Hours 13242 Remove RH steer cylinder, wrong one fitted, won't go to full lock. Clean up ball studs bores on new cylinder and sit ball studs, refit cylinder to machine and test - OK. Take to boiley bay for repairs. Help harry with cracks under cab and new support plates.	3/03/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	18025	Install seat covers, assist mechanic.	1/03/2022	Hours
	18027	Hours 13242 Chack and top up all oil levels, had to jump start again, order new battery, not steering properly to right, found new cylinder must not be correct one, bring back to w/shop to remove cylinder.	28/02/2022	Hours
	18026	New battery.	28/02/2022	Hours
	18028	Hours 13242 Remove broken bolt from accumulator mount and fit new one. Weld new nut to bonnet and refit front grill. Find missing mirror, remove broken bolt from handrails and refit mirror.	26/02/2022	Hours
	18031	Hours 13242 Fit 2 new ball struts and refit drag link. Fit new fitting to ball crank pin, grease and fit grease lines. Grease all pins, blades and ball studs that have been removed, refit all grease hoses and tie up. Remove ladder platform.	25/02/2022	Hours
	18030	Helped unbolt walkway platform.	25/02/2022	Hours
	18032	Hours 13242 Remove steering bell crank and fit new bushes and pin. Found RH draglink had movement in both ball studs. Remove drag link and ball studs. Fill with oils, lower tub and check and top up all levels. Straighten and weld RH head lists surround. Clean up A frame housing and thread. Fit new bearing and Mt Pull axel assembly back into place and fit A frame pin. Connect all hoses etc. Clean outer section of hydraulic tank and fit new sight gauge seals. Re-assemble hyd tank. Clean up strut bearings and pins and refit. Nut very tight, tried welding but kept breaking welds. Cut nut out and remove bearing.	24/02/2022	Hours
	18764	Hours - 13242 Clean up A frame housing and thread. Fit new bearing and mount. Pull axel assembly back into place and fit A frame pin. Connect all hoses etc. Clean outer section of hydraulic tank and fit new sight gauge seals. Re-assemble hydraulic tank. Clean up strut bearings and pins and refit.	23/02/2022	Hours
	18766	Hours - 13242 Remove A frame pin and pull axel assembly back. Clean up around bearing to remove. Nut very tight, tried welding but kept breaking welds. Cut nut out and remove bearing.	22/02/2022	Hours
	18906	Assist with ball stud removal, help fit steer cylinder	21/02/2022	Hours
	18902	Hours 13242 - Clean tank gasket surface. Take tank to boilys to get pick up welded back in place. Remove RH steer cylinder to reseal, chrome on rod. Find spare steer cylinder and fit ball studs and refit to machine. Rig up rear axel ready for A Frame bearing removal.	21/02/2022	Hours
	18907	Took hyd tank off	19/02/2022	Hours
	18911	Remove everything for A frame bearing replacement, hoses, wiring, drive shaft, strut pins, dog bone etc 500hr service	18/02/2022	Hours
	18909	500hr Service. Dropped hyd tank.	18/02/2022	Hours
	18908	Hours - 13242 - 500hr service - Remove everything for a-frame bearing replacement, hoses, wiring, drive shaft, strut, pins, dog bone etc.	18/02/2022	Hours
	18921	Check over for repairs	17/02/2022	Hours
	18919	Check over machine do up defect list and order parts. Bring into shed and set up for rear A Frame bearing replacement.	17/02/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	18916	Pop ball studs on tie rod. Steer cyl.	17/02/2022	Hours
	18914	Hours 13242 - Check over machine, do up defect list and order parts. Bring into shed and set up for rear a-frame bearing replacement.	17/02/2022	Hours
	18923	13512 Hours Demob	22/01/2022	Hours
	18924	Hours 13418 - Clamp up brake lines	14/11/2021	Hours
	18927	Hours 13411 - replace o-ring on brake hose	6/11/2021	Hours
	18928	Hours 13333 Fit new hydraulic cooling hose	20/10/2021	Hours
	18929	Hours - 13245 - fit new LH hand rail bolts. Reweld LH hand rails.	2/10/2021	Hours
	18930	Mobilise	30/09/2021	Hours
	18949	Hours 12819 - FFP instructions & repairs. Fit new steps.	9/09/2021	Hours
	18931	Hours 12940 - Complete FFP Inspection. Replace step.	14/07/2021	Hours
	18934	12876 Hours - Tighten bolts on stairs & walk way to cab. Replaced step rubbers.	9/07/2021	Hours
	18933	Hours 12876 Tighten bolts on stairs & walkway to cab. Replaced step rubbers.	9/07/2021	Hours
	18937	Hours 12881 Repair fire supression pressure wires.	28/06/2021	Hours
	18938	Hours 12861 Machine stopped on haul road. Checked over machine, reset fire suppression, check fire suppression. OK.	24/06/2021	Hours
	18941	Hours 12856 - Fit LH mirror & wheel chocks	21/06/2021	Hours
	18943	Hours 12834 - pump up tyres	14/06/2021	Hours
	18947	Hours 12826 - repair LH rock ejector. Remove rock from ducts.	11/06/2021	Hours
	18945	Hours 12826 - 250 hr service. Check over, fit new light bulbs. Repair rock ejector.	11/06/2021	Hours
	18952	Hours 12822 - remove broken rock ejector and tighten walkway & fix up. Stairway mount all come lose.	8/06/2021	Hours
	18954	Check tyres POS 4 down. Unable to get air in. Telescope & repair.	30/05/2021	Hours
	18957	Pump up tyres	18/05/2021	Hours
	18959	Hours 12594 - Carry out diagnostic checks and change all machines to 40km p/h	10/05/2021	Hours
	18960	Hours 12535 - 500hr service. Check over	29/04/2021	Hours
	18970	Hours 12472 Tighten bolts RH mirrors. Reconnect UHF plug antenna. Blew out a/c filters and turn taps off.	18/04/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
		~~Tighten bolts RH mirror. Reconnect UHF plug antenna. Blow out a/c filters and turn taps on.~~		
	18972	12465 Hours - Grease	17/04/2021	Hours
	18973	Check LHF strut seal - sponge. Check height and pressure was good. Pumped up tyre	31/03/2021	Hours
	18974	Hours 12317 - Grease, grease hoses, adjust camera, fit window wiper	24/03/2021	Hours
	18975	Hours 12246 - Repair remote shut down wiring, elec fault, remove, shut down wiring.	7/03/2021	Hours
	18976	Hours 12246 - try to find engine faults	5/03/2021	Hours
	18977	Hours 12195 - Check over. Grease	22/02/2021	Hours
	18979	Grease & change, remount stop switch	10/02/2021	Hours
	18981	Hours 12127 - fill transmission oil and hydraulic oil	9/02/2021	Hours
	18982	Grease check over. Fit new horn contact assembly. Assemble steer column, fit to machine.	7/02/2021	Hours
	18985	Inspect wheel nuts	4/02/2021	Hours
	18987	Remove steering column on machine.	3/02/2021	Hours
	18988	Gas rear struts, diagnose a/c compressor.	2/02/2021	Hours
	18990	North Parkes FFP - inspect strut mount bolts, reflective taping.	27/01/2021	Hours
	18993	Hydraulic sleeving	22/01/2021	Hours
	18992	Defects	22/01/2021	Hours
	18996	Hours - 12083 Finish fitting exhaust, remove & fit new muffler, finish off lagging all hyd hoses in engine area	15/01/2021	Hours
	19004	North Parkes FFP. Burst protection, paint tow points, install decals.	8/01/2021	Hours
	19000	Hours 12083 - North Parkes FFP. Fitted fire extinguisher. Fitted boots to wiring terminals. Replace cooling hose, sleeved hosing.	8/01/2021	Hours
	19006	12083 Hours - Remove & sheath hyd hoses around engine. Remove P clamps from hoses.	7/01/2021	Hours
	19010	Put hand rail on. Mud flaps/guards. Insulate fuel lines on RHS of truck. Tap bolt holes - remove broken bolts. Fit guards & lights.	22/12/2020	Hours
	19008	Fit hand rails/guards. Put sleeve on fuel lines. Fuel lines. Handrails. Lights.	22/12/2020	Hours
	19013	Start installing guards and rails.	21/12/2020	Hours
	19014	Repairs to truck tub	11/12/2020	Hours
	19015	Repairs to truck guards and tub	10/12/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	19016	Put truck on stands. Wash front grill.	28/11/2020	Hours
	19018	Remove old wear lines	27/11/2020	Hours
	19017	Replace broken line/fitting on fire suppression line. Try and charge	27/11/2020	Hours
	19019	Wear plate, cut out, prep. Wash. Change final drive oils. Put cab back together. Install trans filter tube.	26/11/2020	Hours
	19020	Install HMU. Remove 7 broken bolts. Drain transmission, remove torque converter fill tube. Cut off/weld on panel bracket. Grease. Try charging fire suppression system. Charge batteries. Tag extinguishers.	25/11/2020	Hours
	19024	Hours 12081 -Remove HMU. Try to reseal - damage inside. Remove radiator shroud.	24/11/2020	Hours
	19023	Remove grill/radiator guard. Remove broken bolts.	24/11/2020	Hours
	19111	Hours 12081 Replace secondary steer magnetic switch. Reseal RH steer cylinder. Replace brake block. Drain & fill diff.	23/11/2020	Hours
	19025	Hours 12081 - replace secondary steer magnetic switch, reseal RH steer cylinder, replace brake block. Drain & fill diff.	23/11/2020	Hours
	19112	Hours 12081 - Diagnose electrical faults 1000hr service	20/11/2020	Hours
	19113	12080 Hours- Start to remove handrails	1/09/2020	Hours
	19115	12064 hours - Not going into reverse, checked trans oil, checked harness and plugs, used ET and found no codes. All ok.	3/12/2019	Hours
	19118	11122 hours - Replace RH steer cylinder ball end at wheel	2/12/2018	Hours
	19122	10693 Hours - Fit new tipper switch	20/10/2017	Hours
	19123	10648 hours - fit and adjust mirrors, pump up front struts, fit strut guards	29/09/2017	Hours
	19132	10648 Hours - Fit steps and eyebrow to tipper body	27/09/2017	Hours
	19133	10611 hours - Fit new tranny hose LHS	6/09/2017	Hours
	19137	Hours 10684 - remove broken screen, replace u/s fuel sender and secure wiring. Replace missing reverse alarm, remove LH steer cylinder for bearing/pin replacement. Repair exhaust tip.	5/09/2017	Hours
	19134	10617 hrs - remove LHS steer cylinder. Fit new pins and bearings to steer cylinder. Refit LHS steer cylinder. Remvoe tranny hose.	5/09/2017	Hours
	19145	10648 hours - finish fitting new batteries. replace stair light switch @ bumper. Remove fuel sender and check - found u/s organise replacement.	4/09/2017	Hours
	19143	c/o blow bulbs. Check wiring and repair harness.	4/09/2017	Hours
	19140	10648 Hours - Remove LHS steer cylinder.	4/09/2017	Hours
	19147	10592 hours - check fleet for first day back	9/01/2017	Hours

Asset	W/O No	Description	Finished	Done Reading
	19152	Chair air conditioning. Add gas & advise.	13/12/2016	Hours
	19149	10559 hours fit new steer pressure sensor. Pick up oils for service tonight.	13/12/2016	Hours
	19148	10563 hours - Perform 500hr service, have AC check, dispose of waste oil and filters.	13/12/2016	Hours
	19154	Hours 10334 - pump and load oil/filters. Travel to machine. Perform 250hr service. Dispose of oils & filters	4/11/2016	Hours
	19155	10270 hours - inspect torn off tread block on POS 4 seems ok, will monitor. Replace failed grease nipple.	25/10/2016	Hours
	19156	10132 hours - Diagnose steer pressure sensor failure. Order new one.	7/10/2016	Hours
	19157	10125 hours - Adjust front strut heights	6/10/2016	Hours
	19159	10112 hours - Unload tub, fit walkways, stairs, tub wings, mudguards. Charged front struts	20/09/2016	Hours
	19160	Find fault for wipers, clean cab, tyre and rim check. bolted mudguard back for float, filled radiator with coolant, filled steer tank with oil, ready for work.	17/09/2016	Hours
	19164	Put handrails on machine, test all lights/alarm/aircon etc, remove covers of steer column and fit new strut assembly to steer column, remove dirt under machine with bar, fit rubber over batteries, bend muffler back - panel beated, find fault to wipers they operate themselves, remove stickers on tub, blow out air filter and replace other one, removed stair case and platform out of tub.	16/09/2016	Hours
	19162	Crack repairs	16/09/2016	Hours
	19169	Helped welder panel beat RHS front step, checked all over machine for cracks and signage, check for wear and tear, fit mudguard to LHS front wheel, tensioned all suspension strut bolts 700ft/pound, replaced a bolt in strut, complete asset inspection report.	15/09/2016	Hours
	19170	10110 hours - finish off 1000hr service as manufacture specifies, change diff oil. Change pilot and brake filter. Repairs. Remove walkway and eyebrows.	13/09/2016	Hours
	19172	Hours 10110 - Carry out transmission service	12/09/2016	Hours
	19174	Carry out engine service as manufacturer recommends/check over.	26/08/2016	Hours
	19175	Hours 10017 - replace hose and top up oil	25/08/2016	Hours
	19177	Weld up hungry boards	19/08/2016	Hours
	19178	Line up hungry board for welding.	18/08/2016	Hours
	19179	Complaint: brake warning alarm on, brake accumulator charge valve malfunction causing low charge pressure. Travelled to site, connected pressure gauge to brake accumulator charge valve & tested pressure. Charge pressure only at 600 PSI. Found bad oil leak at brake change filters. Removed filters and inspected. Filters looked clean. Removed filter housings for resealing. Remove accumulator charge valve for inspection. Packed up & travelled back to workshop. Inspected accumulator charge valve for inspection. Packed up & travelled back to workshop. Inspected accumulator charge valve, found some wear on spools, ordered new charge valve, resealed filter housings and all fittings on & between the two housings. Changed over fittings from old to new accumulator charge valve & filter housings. Tested charge pressure, all	27/07/2016	Hours

Asset	W/O No	Description	Finished	Done Reading
		found to be ok. Topped up oil & packed up. Travelled back to workshop, completed service report.		
	19203	9906 - Fit bolt into strut check camera wiring.	26/07/2016	Hours
	19190	Harsh shifting into gear, failed modulation valve. Travel to the machine & inspect the transmission & torque converter screen & found no material. Cut open the transmission filter & found no metal or debris in the system. Tested all transmission pressures, found all to be within spec. Tested modulation valves on transmission, found possible faulty valve swapped over the forward & reverse modulation valves to see if the problem would transfer into reverse. Tested again to find that the problem has transferred to reverse.	26/07/2016	Hours
	19207	Fitted up new modulating valve. Warmed up transmission, carried out full calibration. Completed full calibration 3 times to get a successful calibration. Tested truck. Fault repaired. Minor movement in rear A frame bearing.	8/07/2016	Hours
	19193	9865 Diagnose noise in driveline when put into drive from park. Found modulating valve in transmission faulty. Checked over the rest of the truck and greased. Ordered parts.	7/07/2016	Hours
	19211	Hours 9865 - Loaded up tooling and parts needed for repair	6/07/2016	Hours
	19212	Hours 9811 - Check over and grease	21/06/2016	Hours
	19213	9807 Hours - Repair tub. Replace fuel tank e-stop, replace left outside guard light, turn mirrors in for transport.	31/05/2016	Hours
	19215	9735 Hours - Continue brake fault diagnosing clean check valves and diverter valves. Working again.	17/05/2016	Hours
	19217	Chase brake accumulator, pressure test brake accumulators. Swap dump solenoid with P30I check wiring to and test brake pressure switches.	16/05/2016	Hours
	19226	Hours 9625 - Reported brake failure. Test braking system all within seoc. Demonstrate testing procedure to Murray.	22/04/2016	Hours
	19727	9505 hrs Check, charging faults. Check, wiring and connections, calibrate transmission and test drive ok.	4/04/2016	Hours
	19728	10328 - Diagnose brake pressure fault	21/03/2016	Hours
	19729	Replace step rubber	18/02/2016	Hours
	19730	Diagnose brake pressure fault, pressure OK. Possible dirty plug.	17/02/2016	Hours
	19732	9325 - repair isolator switch	16/02/2016	Hours
	19733	9326 Hours - Repair isolator switch	10/02/2016	Hours
	19734	9230 hrs Diagnose brake pressure accumulator fault. Check pressures - found sensor faulty.	23/12/2015	Hours
	19736	Reseal leaking brake filter assy, still leaked, remove brake filter assy off P0301 and fit. Order parts.	17/12/2015	Hours
	19737	9230 hrs - Remove broken bolt from fan hub. Wash up parts, repack bearings, reassemble and refit fan.	16/12/2015	Hours
	19738	9160 hrs - Repair air con. Replace steer hose, top up steer oil. Replace O-ring and order parts. Inspect oil leaks.	9/12/2015	Hours
	19739	9023 Hours - Change rear diff and final drive oils.	20/11/2015	Hours

Asset	W/O No	Description	Finished	Done Reading
	19741	9023 hrs - Carry out 1000hr service as manufacturer recommends.	19/11/2015	Hours
	19742	Repair hungry boards	14/11/2015	Hours
	19743	8792 hrs - Replace trans hose repair oil leak at pilot filters.	29/10/2015	Hours
	19810	Check out seat dropping, couldn't find a problem.	26/10/2015	Hours
	19745	Check out seat dropping, couldn't find a problem.	26/10/2015	Hours
	19813	Hours 8725 - Replace LH mirror	23/10/2015	Hours
	19812	Hours 8734 - Check connection to transmission	23/10/2015	Hours
	19815	Installed new mirror glass into housing	8/10/2015	Hours
	19817	Repair tank brackets	7/10/2015	Hours
	19819	8504 hours - Complete 500hr service. Replaced O-ring on several transmission hoses. Brittle O'Rings weeping. Cleaned out cab.	29/09/2015	Hours
	19821	Check over for defects	24/07/2015	Hours
	19822	8043 Hours - Diagnose wiring fault for lights, Light relays, check all wiring to lights, found pin in plug on side of cab burnt. Ran new wire around plug.	19/05/2015	Hours
	19823	8031 Hours - Check out lights, got high beam working only.	18/05/2015	Hours
	19831	Washed machine, completed pre hire paperwork, fitted safety stickers, topped up oils. Gassed and oiled rear struts.	16/05/2015	Hours
	19830	8009 Hours - Remove old plant stickers and fit new stickers. Wash machine.	16/05/2015	Hours
	19833	Organised parts & pressure washer to do repairs & wash machine.	15/05/2015	Hours
	19824	8024 Hours - Repaired transmission fault, Checked over machine, replaced fuel level sensor	13/05/2015	Hours
	19826	8024 Hours - Inspected transmission fault. Diagnose fault. Ordered parts.	12/05/2015	Hours
	19835	Complete pre hire site paperwork/checks	11/05/2015	Hours
	19839	8009 Hours - Finish off injector seals, complete valve and injector clearances, replace worn tie rod ends.	8/05/2015	Hours
	19857	Fit rear strut	3/05/2015	Hours
	19859	Assemble struts with new seal kit, fit new bearings.	2/05/2015	Hours
	19828	Pump up front struts and replace left hand steer cylinder	20/04/2015	Hours
	19837	Fit hungry boards	11/04/2015	Hours
	19848	8009 Hours - Completed remainder of injector re-seal.	8/04/2015	Hours

Asset	W/O No	Description	Finished	Done Reading
		Completed valve set & injector set. Removed & replaced worn tie rod ends. Replaced blown headlight globes. Repaired brake filter oil leak.		
	19855	8009 Hours - Organise parts, started machine. Repaired lights, repaired front step mount. Carried out injector re-seal	7/04/2015	Hours
	19853	8009 Hours Reseal starter motor, remove all rocker gear, remove injectors and replace o-rings, check over machine. Gather parts to complete for all four trucks.	7/04/2015	Hours
	19861	Drain hydraulic tank, replace all O-Rings in drain. fill hyd tank, plumb up steer cyl, fit front strut cover.	11/12/2014	Hours
	19890	Replace bearings in strut, fit RH strut	10/12/2014	Hours
	19893	8005 Hours - Straighten RH Mudguard, pop out ball joints	5/12/2014	Hours
	19895	8005 Hours - Replace LH & RHF brake pads, fit steer ram.	3/12/2014	Hours
	19897	Remove LH steer cylinder, remove both rear struts	27/11/2014	Hours
	19902	8005 hrs - check over machine	16/10/2014	Hours
	19905	7990 hrs - Prime up fuel and get machines started	13/10/2014	Hours
	19904	7990 hrs - carry out engine service, change engine oil/filters /fuel filters/ inner and outer air cleaners	13/10/2014	Hours
	19918	Change trans/torque converter oil & filter & check screen. Check diff bung, replace front hub oils. Replace hyd filters. Replace steer oil & filters. Replace inner & outer cabs.	26/09/2014	Hours
	19920	7765 - replace bent rock ejector	2/09/2014	Hours
	19922	Check code coming up	10/08/2014	Hours
	19924	7698 Top up engine oil	30/07/2014	Hours
	19926	Low steer oil alarm, check steer system - all OK. Alarm cleared itself.	28/07/2014	Hours
	19928	Hours 7634 - fit fuse to flashing light working	21/07/2014	Hours
	19933	7607 Hours - Let truck go for 2 loads, check wheel nuts, let truck go for another 2 loads, recheck and tighten	13/07/2014	Hours
	19934	7607 Hours - Stay with tyre fitters while 4x new rear tyres were fitted.	12/07/2014	Hours
	19935	Stay with tyre fitters, fit 2x U/S tyres to rims. Fit rim back onto truck.	10/07/2014	Hours
	19936	7591 Hours - Fab flashing light to brackets. Fit flashing light to machine.	7/07/2014	Hours
	19938	7518 Hours - 500hr service. Change engine oil and filters/fuel filters/air cleaners/ clean cab filters/check over machine.	23/06/2014	Hours
	19942	Fit mirrors and gas struts	29/05/2014	Hours
	19940	7430 Hours - Fit steps and mirrors, pump up struts.	29/05/2014	Hours

Asset	W/O No	Description	Finished	Done Reading
	19963	7429 Hours - Replace bearings in rear lift strut and refit to truck, replace horn relay and refit cover.	22/05/2014	Hours
	20000	7479 Hours - Fix light out on stairway, got rubbish out of cab and help Josh tighten up steering ball joint. Help Wykesy replace tie rod end.	20/05/2014	Hours
	19965	7429 Hours - Replace LH inner & outer tie rat ends, straighten exhaust, carry out paperwork.	20/05/2014	Hours
	20002	7429 Hours - Remove hungry boards, replace bolt in fan hub. Remove LH steering tie rat end outer. Check over truck, top up oils, grease, remove right hand rear strut.	19/05/2014	Hours
	20001	7429 Hours - Replace the rod end, remove hungry boards	19/05/2014	Hours
	20003	Move trucks off site to load onto float.	17/05/2014	Hours
	20004	Clean out tub & disassemble ready for transport.	16/05/2014	Hours
	20005	Replace step rubbers	13/05/2014	Hours
	20006	7383 - Check low steer pressure, bypass switch alarms went out, connected switch back up. All OK.	10/05/2014	Hours
	20007	Do JHA. Move truck to workshop and fit new tyres to POS 1 & 2	6/05/2014	Hours

Service History Report for - P294 Caterpillar 773F Rigid DT

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
14-Sep-22	Shane		$100.00	Remove dog bone pin bolt from P1205 & fit to P294	
05-Sep-22	Toddy	11634	$200.00	Replaced rock injector	
05-Sep-22	Shane		$100.00	Fit new rock ejector & remove rock from	
04-Sep-22	Sean	14629	$300.00	Remove rack from between pos 3&4 Pump tyres up	
26-Aug-22	Jack	14564	$200.00	500hr service	
23-Aug-22	Sebastian		$55.00	Finish installing rod	
23-Aug-22	Sebastian		$65.00	Finish installing rod	
22-Aug-22	Sebastian		$55.00	Strip & clean beake calipers assemble with new seals	
22-Aug-22	Sebastian		$330.00	Strip & clean brake calipers assemble with new seals	
22-Aug-22	Sean	14522	$350.00	Electrical fault with lights	
18-Aug-22	Sean	14371	$250.00	Electrical faults	
13-Aug-22	Jesse		$150.00	Broken rock injector Fab & install new rock injector from 25mm biz (all we have)	
03-Aug-22	Jack	14275	$400.00	250hr service Defects, oil leaks and grease line	
27-Jul-22	Sean Grieve	12980	$55.00	Fill coolant	
22-Jul-22	Xander	14072	$55.00	Fuel & grease Check over machine	
21-Jul-22	Michael	14056	$250.00	Stair repairs on mount to front Remove weld at mounting cable replaced	
19-Jul-22	Rhys	14056	$400.00	1000hr service & defects	
18-Jul-22	Rhys	14056	$1,050.00	1000hr service & defects	
18-Jul-22	Michael	14056	$550.00	Repairs to hungry board due to accidental damage Hungry board weld out after repairs	
07-Jul-22	Jack	14024	$400.00	Tighten LHR and RHR wheel nuts	
07-Jul-22	Sean		$300.00	Tighten LHR and RHR wheel nuts	
01-Jul-22	Rhys	14001	$400.00	250hr service and defects	
01-Jul-22	Jack	14001	$400.00	250hr service and defects Topped up all oils	
01-Jul-22	Sean	13937	$200.00	250hr service Top all oils	
24-Jun-22	Lain	13935	$82.50	Fixed hydraulic leak on steer cylinder Filled up steer oil Blew out air filters	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
19-Jun-22	Alex	13909	$330.00	Inspect seat air leak - found loose fitting Resealed and installed all air lines and tested Resolved steering cylinder hose	
06-May-22	Shane	13745	$300.00	Check engine light on, diagnose and test, dicky E-stop connections. Access platform loose, tighten and fit new bolts, tidy and repair wiring under platform.	
16-Mar-22	Lain	13516	$247.50	Lifted body of machine then secured it at the rear points Tested solinoids with pressure gauge Removed top of transmission, removed solinoid 6 & 7 Put gearbox back together and tested	
14-Mar-22	Lain	13516	$442.50	Removed steps, walk ways and steps from the back of the vehicle Lifted walk ways up with the crane then bolted to the vehicle, also lifted and bolted roof guards to the body of the truck	
05-Mar-22	Jim		$137.50	Washed.	
03-Mar-22	Shane	13242	$233.75	Remove RH steer cylinder, wrong one fitted, wont go to full ock. Clean up ball studs bores on new cylinder and sit ball studs, refit cylinder to machine and test - OK. Take to boiley bay for repairs.	
03-Mar-22	Dave M		$120.00	Help harry with cracks under cab and new support plates.	
03-Mar-22	Shane	13242	$220.00	Remove rh steer cyinder, wont go full lock, clean ball stud bores on new cylnder and fit ball studs, refit cylinder to machine and test, ok, take to boilermaker for repairs	
03-Mar-22	Harry D		$522.50	Weld up cracks underneath cab on both sides, weld up cracks on shoulders, weld wear plates in tub.	
01-Mar-22	Lleyton		$137.50	install seat covers, assit mechanic.	
28-Feb-22	Lleyton		$82.50	New battery.	
28-Feb-22	Shane	13242	$110.00	Check and top up all oil levels, had to jump start again, order new battery, not steering properly to right, found new cylinder must not be correct one, bring back to W/shop to remove cylinder.	
28-Feb-22	Shan	13242	$110.00	Check and top all oils, jump start, order new batterie, not steering to right, found new cylinder and remove	
26-Feb-22	Shane	13242	$352.00	Remove broken bolt from accumulator mount and fit new one. Weld new nut to bonnet and refit front grill. Find missing mirror, remove broken bolt from handrails and refit mirror.	
25-Feb-22	Harry		$55.00	Helped unbolt walkway platform	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
25-Feb-22	Shane	13242	$616.00	Fit 2 new ball struts and refit drag link. Fit new fitting to ball crank pin, grease and fit grease lines. Grease all pins, blades and ball studs that have been removed, refit all grease hoses and tie up. Remove ladder platforom.	
24-Feb-22	Shane	13242	$508.75	Remove steeing bell crank and fit new bushes and pin. Found RH draglink had movement in both ball studs. Remove drag link and ball studs. Fill with oils, lower tub and check and top up all levels. Straighten and weld RH head list surround.	
23-Feb-22	Shane	13242	$792.00	Clean up A Frame housing and thread. Fit new bearing and Mt. Pull axel assembly back into place and fit A Frame pin. Connect all hoses etc. Clean outer section of hyd tank and fit new sight gauge seals. Re assemble hyd tank. Clean up strut bearings and pins and refit.	
22-Feb-22	Shane	13242	$396.00	Remove A Frame pin and pull axel assembly back. Clean up around bearing to remove out. Nut very tight, tried welding but kept breaking welds. Cut nut out and remove bearing.	
21-Feb-22	Shane	13242	$352.00	Clean tank gasket surface. Take tank to boilys to get pick up welded back in place. Remove RH steer cylinder to reseal, chrome on rod. Find spare steer cylinder and fit ball studs and refit to machine. Rig up rear axel ready for A Frame bearing removal.	
21-Feb-22	Clay		$55.00	Assist with ball stud removal, help fit steer cylinder	
19-Feb-22	Jim		$110.00	Took hyd tank off	
18-Feb-22	Shane	13242	$467.50	Remove everything for a-frame bearing replacement, hoses, wiring, drive shaft, strut pins, dog bone etc 500HR SERVICE	
18-Feb-22	Jim		$550.00	Fire tags 500HR SERVICE Dropped hyd tank	
18-Feb-22	Shane		$748.00	Remove everything for A Frame bearing replacement, hoses, wiring, drive shaft, strut pins, dog bone etc 500hr service	
17-Feb-22	Shane	13242	$55.00	Check over machine Do up defect list and order parts. Bring into shed and set up for rear a-frame bearing replacement	
17-Feb-22	Clay		$55.00	Pop ball studs on tie rod Steer cyl	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
17-Feb-22	Shane		$176.00	Check over machine do up defect list and order parts. Bring into shed and set up for rear A Frame bearing replacement.	
17-Feb-22	Zumbo		$88.00	Check over for repairs	
22-Jan-22	John C	13512	$82.50	Demobe	
14-Nov-21	Greg Mills	13418	$55.00	Clamp up brake lines	
06-Nov-21	Jackson	13411	$137.50	Replace o-ring on brake hose	
20-Oct-21	JohnCiappara	13333	$137.50	Fit new hydraulic cooling hose	
02-Oct-21	John C	13245	$220.00	Fit new LH hand rail bolts Reweld LH hand rail	
30-Sep-21	John C	13245	$137.50	Mobilise	
14-Jul-21	Duncan	12940	$110.00	Completed FFP Inspection Replace Step	
09-Jul-21	Duncan	12876	$110.00	Tighten bolts on stairs & walk way to cab. Replaced step rubbers	
28-Jun-21	John C	12881	$55.00	Repair fire sup pressure wires	
24-Jun-21	Duncan	12861	$110.00	Machine stopped on haul road Checked over machine Reset Fire suppression Check fire suppression. Ok	
21-Jun-21	Duncan	12856	$82.50	Fit LH mirror & wheel chocks	
14-Jun-21	John	12834	$110.00	Pump up tyres	
11-Jun-21	John	12826	$275.00	250hr Service, Check over Fit new light bulbs Repair rock ejector	
11-Jun-21	B Swan	12826	$137.50	Repair LH rock ejector Remove rock from ducts	
09-Jun-21	B Swan	12819	$55.00	FFP Instructions & repairs	
08-Jun-21	John	12812	$55.00	Fit new steps	
08-Jun-21	B Swan	12822	$137.50	Remove broken rock ejector and tighten walkway & fix up Stairway mount all come loose.	
30-May-21	Duncan		$55.00	Check tyres Pos 4 down Unable to get air in. Telescope & repair	
19-May-21	John	12665	$55.00	Pump up tyres	
18-May-21	John	12656	$55.00	Pump up tyres	
11-May-21	John	12595	$55.00	Pump up tyres.	
10-May-21	B Swan	12594	$55.00	Carry out diagnostic checks and change all machines to 40km p/h	
29-Apr-21	John	12535	$110.00	500hr service Check over	
28-Apr-21	John	12535	$55.00	500hr Service	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
18-Apr-21	Duncan	12472	$137.50	Tighten bolts RH mirrors Reconnect UHF plug antenna Blew out a/c filters & turn taps off	
17-Apr-21	John	12465	$27.50	Grease	
01-Apr-21	John	12347	$27.50	Grease	
31-Mar-21	A Mills		$110.00	Check LHF strut seal - spongie Check height and pressure was good Pumped up tyre	
24-Mar-21	John C	12317	$110.00	Grease, grease hoses, adjust camera, fitr window wiper	
07-Mar-21	A Mills		$165.00	Elec fault Remove Shut down wiring	
07-Mar-21	John	12246	$165.00	Repair remote shut down wiring	
05-Mar-21	John	12246	$137.50	Try to find engine fault	
22-Feb-21	John	12195	$41.25	Check over Grease	
18-Feb-21	John	12159	$55.00	Grease - check over	
10-Feb-21	A Mills		$55.00	Grease & change Remount stop switch	
09-Feb-21	John	12127	$55.00	Fill transmission oil and hydraulic oil	
09-Feb-21	A Mills	11755	$82.50	Fill hyd oil, trans oil	
07-Feb-21	A Mills		$27.50	Grease & check over	
07-Feb-21	John		$27.50	Grease Check over	
05-Feb-21	Greg Mills		$110.00	Fit new horn contact assembly Assemble steer column Fit to machine	
04-Feb-21	A Mills		$55.00	Inspect wheel nuts	
03-Feb-21	Greg Mills		$55.00	Remove steering column on machine	
02-Feb-21	John		$123.75	Gas rear struts Diagnose a/c compressor	
30-Jan-21	John		$55.00	Set up	
27-Jan-21	Jackson	12083	$137.50	North Parks FFP Inspect strut mount bolts, reflective taping	
22-Jan-21	Greg		$165.00	Defects	
22-Jan-21	Lindsay		$110.00	Hydraulic sleeving	
20-Jan-21	Will Paull		$577.50	Defectsw	
15-Jan-21	Zumbo	12083	$27.50	Finish fitting exhaust	
14-Jan-21	Zumbo	12083	$82.50	Remove & fit new muffler	
08-Jan-21	Shane	12083	$275.00	Finish off lagging all hyd hoses in engine area	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Jan-21	Jackson	12083	$192.50	North Parkes FFP Fitted fire extinguisher Fitted boots to wiring terminals Replace cooling hose Sleeved hosing	
08-Jan-21	Zumbo	773	$110.00	North Parkes FFP Burst protection, paint tow points, install decals	
07-Jan-21	Shane	12083	$481.25	Remove & sheath hyd hoses around engine	
07-Jan-21	John		$82.50	Remove P clamps from hoses	
06-Jan-21	Shane	12083	$206.25	Test Fire Supression & remobe bottle for testing Start to remove & fit burst sleeves to hyd hoses	
22-Dec-20	Will Paull		$522.50	Fit hand rails / guards Put sleeve on fuel lines	
22-Dec-20	Zumbo		$220.00	Fuel lines Handrails Lights	
22-Dec-20	Jack L		$412.50	Put hand rails on Mud flaps/guards Insulate fuel lines on RHS of truck Tap bolt holes - remove broken bolts	
22-Dec-20	John		$247.50	Fit guards & lights	
21-Dec-20	Jack L		$178.75	Start installing guards & rails	
11-Dec-20	Dave Marshal		$302.50	Repairs to truck tub	
10-Dec-20	Dave Marshal		$192.05	Repairs to truck guards and tub	
28-Nov-20	Jack L		$55.00	Put truck on stands Wash front grill	
27-Nov-20	Jack L		$110.00	Replace broken line/fitting on fire supression line Try and charge	
27-Nov-20	Dave Marshal		$330.00	Remove old wear liners	
26-Nov-20	Greg Mills	12081	$55.00	Change wheel end oil	
26-Nov-20	KyleMusgrave		$110.00	Wear plate Cut out Prep	
26-Nov-20	Jack L		$467.50	Wash Change final drive oils Put cab back together Install trans filter tube	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
25-Nov-20	Jack L		$536.25	Install HMU Remove 7 broken bolts Drain transmission Remove torque converter fill tube Cut off/ weld on panel bracket Grease Try charging fire supression system Charge betteries Tag extinguishers	
24-Nov-20	Jack L		$330.00	Remove grill/radiator guard Remove broken bolts	
24-Nov-20	Greg Mills	12081	$385.00	Remove HMU Try to reseal - damage inside Remove radiator shroud	
23-Nov-20	Greg Mills	12081	$330.00	Replace secondary steer magnetic switch Reseal RH steer cylinder Replace brake block Drain & fill diff	
20-Nov-20	Greg Mills	12081	$495.00	Diagnose electrical faults Start 1000hr service	
17-Nov-20	Greg Mills	12081	$55.00	Check over	
02-Nov-20	Kyle M		$412.50	Dump Truck Repairs	
30-Oct-20	Kyle M		$385.00	Dump Truck Repairs	
29-Oct-20	Kyle M		$522.50	Dump Truck Repairs	
01-Sep-20	Will	12080	$165.00	Start to remove handrails	
31-Aug-20	Will	12080	$27.50	Start to remove handrails.	
15-Mar-20	Duncan	12080	$55.00	Started truck & check over	
03-Dec-19	D Stevens	12064	$97.50	Not going into reverse Checked trans oil Checked harness and plugs Used ET and found no codes All ok	
02-Dec-18	Duncan	11122	$363.00	Replace RH steer cylinder ball end at wheel.	
20-Oct-17	Swanling	10693	$90.75	Fit new tipper switch	
29-Sep-17	Swanling	10648	$181.50	Fit and adjust mirrors, pump up front struts, fit strut guards	
27-Sep-17	Swanling	10468	$363.00	Remove and fit catwalk and steps, mount rock guard to tuts, charge struts	
27-Sep-17	Swanling	10648	$317.63	Fit steps and eyebrow to tipper body	
06-Sep-17	J Ciappara	10611	$130.00	Fit new tranny hose LHS.	
05-Sep-17	J Ciappara	10617	$422.50	Remove LHS steer cylinder. Fit new pins and bearings to steer cylinder. Refit LHS steer cylinder. Remove tranny hose.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
05-Sep-17	Ted Van	10684	$195.00	Remove broken screen. Replace u/s fuel sender and secure wiring. Replace missing reverse alarm. Remove LH steer cylinder for bearing/pin replacement. Repair exhaust tip.	
04-Sep-17	J Ciappara	10648	$195.00	Remove LHS steer cylinder.	
04-Sep-17	James Mills		$130.00	C/O blown bulbs. Check wiring and repair harness.	
04-Sep-17	Ted Van	10648	$325.00	Finish fitting new batteries. Replace stair light switch @ bumper. Remove fuel sender and check - found u/s organise replacement	
09-Jan-17	RAM Diesel	10592	$41.00	Check fleet for first day back	
13-Dec-16	RAM Diesel	10563	$288.00	Perform 500hr service Have AC check Dispose of waste oil & filters	
13-Dec-16	RAM Diesel	10559	$82.00	Fit new steer pressure sensor Pick up oils for service tonight	
13-Dec-16	Stephen Cook		$98.00	Chair air conditioning Add gas & advise	
04-Nov-16	RAM Diesel	10334	$165.00	Pump & load oil/filters Travel to machine Perform 250hr service Dispose of oils & filters	
25-Oct-16	RAM Diesel	10270	$82.00	Inspect torn off tread block on POS 4 Seems ok, will monitor Replace failed grease nipple	
07-Oct-16	RAM Diesel	10132	$82.00	Diagnose steer pressure sensor failure Order new one	
06-Oct-16	RAM Diesel	10125	$41.00	Adjust front strut heights	
20-Sep-16	RAM Diesel	10112	$206.00	Unload tub, fit walkways, stairs, tub wings, mudguards Charge front struts	
17-Sep-16	brandon		$292.50	find fault for wipers, claen cab, tyre and rim check, bolted mudguard back for float, filled radiator with coolant, filled steer tank with oil, ready for work.	
16-Sep-16	Fordy		$325.00	Crack repairs	
16-Sep-16	Jacob		$260.00	Dug dirt out and washed machine	
16-Sep-16	C Ford		$312.00	Crack repairs	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Sep-16	Brandon		$763.75	Put handrails on machine, test all lights/alarm/aircon etc, remove covers of steer column and fit new strut assembly to steer column, remove dirt under machine with bar, fit rubber over batteries, bend muffler back - panel beated, find fault to wipers they operate themselves, remove stickers on tub, blow out air filter and replace other one, removed stair case and platform out of tub.	
15-Sep-16	C Ford		$500.00	Truck repairs	
15-Sep-16	Brandon		$601.25	Helped welder panel beat RHS front step, checked all over machine for cracks and signage, check for wear and tear, fit mudguard to LHS front wheel, tensioned all suspension strut bolts 700ft/pound, replaced a bolt in strut, complete asset inspection report.	
15-Sep-16	Fordy		$520.00	Truck repairs	
13-Sep-16	Greg Mills	10110	$715.00	Finish off 1000hr service as manufacture specifies. Change diff oil. Change pilot and brake filter. Repairs. Remove walkway and eyebrows.	
12-Sep-16	Greg Mills	10110	$65.00	Carry out transmission service.	
26-Aug-16	Greg Mills		$130.00	Carry out engine service as manufacturer recommends./ check over.	
25-Aug-16	Greg Mills	10017	$195.00	Replace hose and top up oil.	
19-Aug-16	Greg Mills		$260.00	Weld up hungry bpoards	
18-Aug-16	Greg Mills		$130.00	Line up hungry board for welding	
27-Jul-16	Westrac		$3,584.17	Complaint: brake warning alarm on, brake accumulator charge valve malfunction causing low charge pressure Travelled to site, connected pressure gauge to brake accumulator charge valve & tested pressure. Charge pressure only at 600PSI. Found bad oil leak at brake charge filters Removed filters & inspected Filters looked clean Removed filter housings for re sealing Remove accumulator charge valve for inspection. Packed up & travelled back to workshop. Inspected accumulator charge valve, found some wear on spools. Ordered new charge valve, re sealed filter housings & all fittings on & between the two housings. Changed over fittings from old to new accumulator charge valve & filter housings. Tested charge pressure, all found to be ok. Topped up oil & packed up. Travelled back to workshop, completed service report	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
26-Jul-16	Westrac		$728.00	Harsh shifting into gear, failed modulation valve. Travel to the machine & inspect the transmission & torque convertor screen & found no material. Cut open the transmission filter & found no metal for debris in the system. Tested all transmission pressures, found all to be within spec. Tested modulation valves on transmission, found possible faulty valve swapped over the forward & reverse modulation valves to see if the problem would transfer into reverse. Tested again to find that the problem has transferred to reverse	
26-Jul-16	Greg Mills	9906	$65.00	Fit bolt into strut check camera wiring.	
08-Jul-16	A Warren	9865	$286.00	Fitted up new modulating valve Warmed up transmission, carried out full calibration Completed fulled callibration 3 times to get a successful calibration. Tested truck Fault repaired Minor movement in rear A frame bearing	
07-Jul-16	A Warren	9865	$250.00	Diagnose noise in driveline when put into drive from park Found modulating valve in transmission faulty Checked over the rest of the truck & greased Ordered parts	
06-Jul-16	A Warren	9865	$71.00	Loaded up tooling & parts needed for repair	
27-Jun-16	Ted Van		$32.50	Talk with Westrac Canberra.	
21-Jun-16	A Warren	9811	$71.00	Checkover & grease	
31-May-16	G Wykes		$281.00	Repair tub	
31-May-16	Ted Van	9807	$130.00	Replace fuel tank E-stop, replace left outside guard light, turn mirrors in for transport.	
30-May-16	G Wykes		$218.00	Repair tub	
25-May-16	G Wykes		$125.00	Repair tub	
24-May-16	G Wykes		$781.00	Repairs to tub	
23-May-16	G Wykes		$125.00	Repair hungry boards & tub	
17-May-16	Ted Van	9735	$162.50	Continue brake fault diagnosing clean check valves and diverter valves. Working again.	
16-May-16	Ted Van	9735	$130.00	Chase brake accumulator	
03-May-16	Ted Van	9657	$195.00	Pressure test brake accumulators. Swap dump solenoid with P301 check wiring to and test brake pressure switches	
22-Apr-16	Ted Van	9625	$65.00	Reported brake faliure. Test braking system all within soec. Demonstart testing brocedure to Murray.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Apr-16	Ted Van	9505	$130.00	Check, charging faults. Check wiring and connections calibrate transmission and test drive ok.	
21-Mar-16	Greg Mills	10328	$195.00	Diagnose brake pressure fault.	
18-Feb-16	Greg Mills		$32.50	Replace step rubber	
17-Feb-16	Greg Mills		$195.00	Diagnose brake pressure fault, Pressures ok. Possible dirty plug.	
16-Feb-16	Greg Mills	9325	$32.50	Repair isolator switch	
10-Feb-16	Ted Van	9326	$32.50	Check over and start	
23-Dec-15	Greg Mills	130	$130.00	Diagnose brake pressure accumulator fault check pressures, found sensor faulty	
17-Dec-15	Ted Van		$262.50	Reseal leaking brake filter assy, still leaked remove brake filter assy off P301 and fit order parts	
16-Dec-15	Ted Van	9230	$260.00	Remove broken bolt from fan hub. Wash up parts, repack bearings, reassemble and refit fan	
09-Dec-15	Greg Mills	9160	$65.00	Repair a/c	
08-Dec-15	Greg Mills	9140	$65.00	Repair a/c.	
07-Dec-15	Greg Mills	9127	$65.00	Replac steer hose, top up steer oil/.	
04-Dec-15	Tec Van	9127	$65.00	Replace o-ring and order parts	
03-Dec-15	Tec Van	9127	$32.50	Inspect oil leak	
20-Nov-15	Greg Mills	9023	$130.00	Change rear diff and final drive oils.	
19-Nov-15	Greg Mills	9023	$520.00	Carry out 1000hr service as manufacturer recommends,	
14-Nov-15	G Wykes		$125.04	Repair hungry boards	
13-Nov-15	Greg Mills	8991	$130.00	Repair hungray board	
29-Oct-15	Greg Mills	8792	$97.50	Replace trans hose repair oil leak at pilot filters	
26-Oct-15	Greg Mills		$32.50	Check out seat dropping. Couldn't find a problem.	
23-Oct-15	Ted Van	8734	$32.50	Check connection to transmission	
23-Oct-15	Ted Van	8725	$32.50	Replace LH mirror.	
08-Oct-15	A Warren		$71.50	Installed new mirror glass into housing	
07-Oct-15	G Wykes		$63.00	Repair tank brackets	
29-Sep-15	A Warren	8504	$429.00	Completed 500hr service. Replaced oring on several transmission hoses. Brittle orings weeping. Cleaned out cab	
24-Jul-15	Andrew		$35.00	check over for defects.	
19-May-15	Greg Mills	8043	$130.00	Diagnose wiring fault for lights. Light relays, check all wiring to lights, found pin in plug on side of cab burnt. Ran new wire around plug.	
18-May-15	Greg Mills	8031	$65.00	Check out lights, got high beam working only	
13-May-15	Andrew	8024	$225.00	repaired transmission fault. Checked over machine. Replaced fuel level sensor.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
12-May-15	Andrew	8024	$150.00	inspected transmission fault. Diagnosed fault. Ordered parts.	
20-Apr-15	Greg Mills		$130.00	Pump up front struts and replace left hand steer cylinder	
16-Apr-15	Josh Hewett	8009	$130.00	Remove old plant stickers and fit new stickers, wash machine.	
16-Apr-15	Andrew W		$150.00	Washed machine. Completed pre hire paperwork. Fitted safety stickers. Topped up oils. Gassed & oiled rear struts.	
15-Apr-15	Andrew W		$25.00	organised parts & pressure washer to do repairs & wash machine.	
11-Apr-15	Andrew W		$35.00	complete prehire site paperwork / checks.	
11-Apr-15	G Wykes		$211.25	fit hungry boards.	
10-Apr-15	Josh Hewett		$65.00	Fit hungry boards to machine	
10-Apr-15	Andrew W		$75.00	fitup hungry boards.	
08-Apr-15	Josh Hewett	8009	$617.50	Finish off injector seals, complete valve and injector clearances, repalce worn tie rod ends.	
08-Apr-15	Andrew W	8009	$693.75	completed remainder off injector re-seal. Completed valve set & injector set. Removed & replaced worn tie rod ends. Replaced blown headlight globes. Repaired brake filter oil leak.	
07-Apr-15	Josh Hewett	8009	$552.50	reseal starter motor, remove all rocker gear, remove injectors and replace o-rings, check over machine, gather parts to complete all four trucks.	
07-Apr-15	Andrew W	8009	$637.50	organise parts. Started machine. Repaired lights, repaired front step mount. Carried out injector re-seal.	
03-Mar-15	Greg Mills	8009	$130.00	Fit rear strut	
02-Mar-15	Greg Mills		$178.75	Assemble struts with new seal kit, fit new bearings.	
11-Dec-14	Greg Mills		$130.00	drain hyd tank, replace all o-rings in drain, fill hyd tank, plumb up steer cyl, fit front strut cover	
10-Dec-14	Greg Mills		$97.50	Repalce bearings in strut, fit RH strut	
05-Dec-14	Greg Mills	8005	$130.00	Strighten RH mudguard, pop out ball joints.	
03-Dec-14	Greg Mills	8005	$227.50	Repalce LH & RHF brake pads, fit steer ram.	
27-Nov-14	Greg Millls		$260.00	Remove LH ster cylinder, remove both rear struts	
16-Oct-14	Greg Mills	8005	$32.50	check over machine	
13-Oct-14	Greg Mills	7990	$97.50	Carry out engine service, change engine oil/fielters/fuel filters/inner and outer air cleaners.	
13-Oct-14	Greg Mills	7990	$32.50	Prime up fuel and get machine started	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
26-Sep-14	Ted		$292.50	change trans/torque convertor oil & filter & check screen. Check diff bung. Replace front hub oils. Replace hyd filters. Replace steer oil & filters. Replace inner & outer cab filters.	
02-Sep-14	Greg Mills	7765	$65.00	repalce bent rock ejector	
10-Aug-14	Greg Mills		$32.50	Check code coming up	
30-Jul-14	Ted Van	7698	$32.50	Top up engine oil	
28-Jul-14	Ted Van	7680	$130.00	Low steer oil alarm, check steer system - all OK, alarm cleared itself.	
21-Jul-14	Greg Mills	7634	$32.50	Fit fuse to flashing light wiring.	
13-Jul-14	Greg Mills	7607	$162.50	Let truck go for 2 loads, check wheel nuts, let truck go for another 2 loads, recheck and tighten.	
12-Jul-14	Greg Mills	7607	$357.50	Stay with tyre fitters while 4 x new rear tyres were fitted.	
10-Jul-14	Greg Mills	7107	$162.50	Stay with tyre fitters, fit 2 x u/s tyres to rims, fit rim back onto truck.	
07-Jul-14	Greg Mills	7591	$32.50	Fit flashing light to machine.	
04-Jul-14	G Wykes		$20.00	fab flashig light brackets.	
23-Jun-14	Greg Mills	7518	$97.50	500hr service - change engine oil and filters/fuel filters/air cleaners, clean cab filters, check over machine.	
29-May-14	Greg Mills	7430	$97.50	Fit steps and mirrors, pump up struts	
29-May-14	Dave O'Leary		$130.00	Fit mirrors and gas struts	
22-May-14	Ted Van	7429	$162.50	Replace bearings in rear lift strut and refit to truck, repalce horn relay and refit cover.	
20-May-14	RLW	7429	$276.25	Replace LH inner & outer tie rat ends, straighten exhaust, carry out paperwork.	
20-May-14	Jono Pittin	7479	$390.00	Fix light out on stairway, got rubbish out of cab and help Josh tighten up steering ball joint.	
20-May-14	Josh Hewett	7429	$97.50	Help Wykesy replace tie rod end.	
19-May-14	Josh Hewett	7429	$195.00	Replace the rod end, remove hungry boards	
19-May-14	RLW	7429	$390.00	Remove hungry boards. Replace bolt in fan hub. Remove LH steering tie rat end outer.	
19-May-14	Jono Pittin	7479	$195.00	Check over truck top up oils, grease, remove right hand rear strut.	
17-May-14	Shane		$112.50	Move trucks offsite to load onto float.	
16-May-14	Shane		$225.00	Clean out tub & disassemble ready for transport.	
13-May-14	Greg Mills	7414	$32.50	Replace step rubbers	
10-May-14	Greg Mills	7383	$32.50	Check low steer pressure, bypass switch alarms went out, connected switch back up all OK	
06-May-14	Shane	7354	$262.50	Do JHA. Move truck to w/shop & fit new tyres to pos 1 & 2.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
06-May-14	Greg Mills	7354	$195.00	Move machine, change out POS 1 & 2 wheels, load up wheels onto trailer	
05-May-14	Shane	7354	$150.00	Pos 1 tyre blown at top of ramp. Move machine to safe area & secure machine & area.	
05-May-14	Greg Mills	7354	$65.00	Front tyre blew out, got authorisation to unload and move truck off haul road	
02-May-14	Shane	7325	$187.50	Replace pos 1 tyre.	
01-May-14	Shane		$225.00	Slew pressure code active intermittantly. Check pressures with new gauge & ET all OK.	
29-Apr-14	Shane		$75.00	Straighten front steps.	
25-Apr-14	Greg Mills	7208	$97.50	tighten up handrails. Check product link not working. Check wiring, connect computer, found it wasn't registered. Fit cover, register product link.	
14-Apr-14	Greg Mills	7053	$390.00	Finish 1000hr service, change steer oil and filters/brake filters/trans oil and filters, check both trans screens, check plugs on finals and diff, check front hub oil.	
13-Apr-14	Shane	7047	$337.50	complaints of A/C not blowing hard. Found filters blocked, due for 1000 hr service. Replaced A/C filters & start 1000 hr service. Changed engine oil & filters, fuel filters, fuel filter & air filters.	
08-Apr-14	Shane	6988	$150.00	fit body up alarm.	
08-Apr-14	Greg Mills	6988	$65.00	Check over and straighten front steps	
31-Mar-14	RLW	6898	$150.00	reports of tranny fault light coming on, sol 1 return wire code inactive. Check wiring harness & measure resistance, OK. Remove tranny cover & swap sol 1 & 3. send back to work & monitor.	
31-Mar-14	Greg Mills	6898	$162.50	Diagnose trans alarm fault, check wiring and test wiring circuits, swap solenoids in trans	
22-Mar-14	Shane	6845	$300.00	replace fan belts.	
18-Mar-14	Greg Mills	6800	$32.50	Change front steps	
17-Mar-14	Greg Mills	6790	$65.00	Fit Alt/A/C belt	
17-Mar-14	Greg Mills	6790	$32.50	Check alternator light, belt missing from alternator	
10-Mar-14	Shane	6700	$112.50	remount RH headlight & adjust.	
09-Mar-14	Shane	6692	$75.00	reports of wipers working intermittantly when switch off. Investigate problem but could not fault system.	
12-Feb-14	G Wykes		$422.50	Fit hungry boards.	
12-Feb-14	Shane	6480	$262.50	carry out 500 hr service & assist with fitting hungry boards.	
11-Feb-14	G Wykes		$89.40	Fab hungry boards.	
10-Feb-14	G Wykes		$81.25	Fab hungry boards.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Feb-14	Greg Mills	6458	$195.00	Diagnose trans fault, check solenoid in top of transmission	
07-Feb-14	G Wykes		$30.00	Fab hungry boards.	
06-Feb-14	Greg Mills	6438	$32.50	Change out front steps	
06-Feb-14	G Wykes		$75.00	Fab hungry boards.	
05-Feb-14	Shane	6416	$112.50	steer pressure warning lights coming on. Test pressure, found sensor faulty. Fit new sensor & check, OK.	
05-Feb-14	G Wykes		$90.00	Fab hungry boards.	
04-Feb-14	G Wykes		$95.00	Fab hungry boards.	
31-Jan-14	G wykes		$146.25	Fab hungry boards.	
30-Jan-14	Shane	6360	$150.00	repair lock hinge assemble on door window.	
23-Jan-14	Greg Mills		$65.00	Replace front steps	
23-Jan-14	G Wykes		$10.00	fab hungry boards.	
22-Jan-14	G Wykes		$30.00	fab hungry boards.	
17-Jan-14	G Wykes		$81.50	fab hungry boards.	
16-Jan-14	G Wykes		$81.50	fab hugnry boards.	
15-Jan-14	G Wykes		$81.50	fab hungry boards.	
14-Jan-14	G Wykes		$81.50	fab hungry boards.	
13-Jan-14	G Wykes		$32.50	Fab hungry boards.	
02-Jan-14	Andy William	6078	$32.50	LH rock ejector bent removed and straightened and refit.	
10-Dec-13	Greg Mills	5967	$130.00	Grease line segregation throughout machine	
09-Dec-13	Greg Mills		$65.00	Pump up struts, repair front step	
08-Dec-13	Greg Mills		$227.50	Fit walkway/stairs/mudflaps and eyebrows.	
03-Dec-13	Jono Pittin	5466	$97.50	Finish off checklist and running checks, fit new stickers.	
02-Dec-13	Jono Pittin	5466	$357.50	Remove old camera cables, tidy up electrical wire go though checklist for Tomingley.	
12-Oct-13	WMS - T		$1,200.00	strip down for transport.	
18-Sep-13	WMS	5964	$300.00	Remove rock stuck in dual wheels.	
03-Sep-13	WMS	5893	$300.00	Carry out 250 hour service	
16-Aug-13	WMS - Tom		$200.00	change out unserviceable batteries.	
15-Aug-13	WMS - Tom	5782	$300.00	250 hr service.	
08-Aug-13	WMS		$200.00	clear eng speed sensor.	
22-Jul-13	WMS	5722	$400.00	carry out 250 hr service.	
15-Jul-13	WMS	5596	$400.00	carry out 250 hr service.	
29-Jun-13	WMS	5489	$300.00	repair broken hand rail bolts. Repaired oil leak at filter head for transmission.	
08-Jun-13	WMS	5318	$200.00	repair oil leak at transmission filter hsg.	
30-May-13	WMS	5306	$360.00	Inspect & test steering system dut to alarm coming on.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
19-May-13	WMS	5245	$270.00	250 hours service APS	
19-Apr-13	WMS	5361	$90.00	Repair damaged steps	
30-Mar-13	WMS	5010	$800.00	carry out 250 hr service.	
27-Mar-13	WMS	4997	$200.00	remove rock jam in dull wheels.	
23-Mar-13	WMS		$200.00	check & listen & go for drive with operator to listen for noise. All OK.	
22-Mar-13	WMS		$100.00	check & listen for noise in front end.	
25-Feb-13	WMS	4856	$300.00	carry out 250 hr service.	
14-Feb-13	WMS		$100.00	fitted wheel chock. Check machines.	
19-Jan-13	WMS		$100.00	inspected vibration in driveline. No vibration felt.	
12-Dec-12	Mark Unwin	4593	$760.00	make up hoses & grease nipple manifolds. Make & fit grease hoses to steering system. Secure with zip ties.	
07-Dec-12	WMS	4565	$396.00	speed sensor fault, clear come back on , so change sensor & all OK.	
05-Dec-12	mark unwin	4554	$46.00	inspection. Rear & front strut boots need replacing.	rear & front strut boots need replacing.
01-Dec-12	WMS	4532	$180.00	Finish off 500hr service.	
30-Nov-12	WMS	4532	$450.00	Service as per sheet.	
26-Nov-12	WMS	4500	$90.00	Inspect and test for driveline vibration removed rock jammed behind cab.	
18-Nov-12	WMS	4459	$198.00	removal of bent rock ejector.	
24-Oct-12	JohnCiappara	13356	$110.00	Fit new bolts to LH walkway	
15-Oct-12	Mark Unwin	4337	$95.00	Recert fire extinguishers, inspection needs strut boots.	
05-Oct-12	WMS	4267	$540.00	Carry out 250hr type of service - oil/fuel/air and inspections.	
03-Oct-12	Mark Unwin	4259	$191.25	Start 250hr service changed primary air/fuels/A/C filters, greased, seat belt due with fire extinguisher.	
27-Sep-12	Mark Unwin	4244	$127.50	Fit wheel chock bracket.	
08-Sep-12	wms	4142	$95.00	Diagnose engine speed sensor fault. Removed, cleaned & installed sensor.	
08-Sep-12	WMS	4142	$95.00	Diagnose engine speed fault. Removed cleaned sensor & reset to spec.	
31-Aug-12	WMS	4081	$95.00	Eng speed sensor, require file flash upgrade.	
21-Aug-12	WMS		$95.00	fit up fast fill kit.	
21-Aug-12	Hast/Deering		$900.00	250hr service.	
19-Aug-12	Hast/Deering		$150.00	New fuel filters, updated ECM's, cleared codes, drained sediment from tank.	
08-Jul-12	WMS	3844	$180.00	Codes on dash, hook up ET scanner show engine speed sensor, clear code and take for run OK.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
06-Jul-12	WMS	3829	$90.00	Change out fuel sender.	
05-Jul-12	WMS	3820	$135.00	Fit up fast fill + test operation fuel sender.	
03-Jun-12	Josh		$65.00	Stamp rims	
02-Jun-12	WMS		$255.00	Continue to put truck together as day before.	
01-Jun-12	Josh		$390.00	Dry assemble, fit safety stickers, apply all mud flaps.	
01-Jun-12	WMS		$510.00	Unload 773f off truck, Slowly drive up driveway as was a wet day, assemble truck guards, stairways, footsteps etc, pump up all struts on truck.	
24-May-12	WMS		$531.25	Fit up rear wheels, fit up handrails.	
23-May-12	WMS		$510.00	Weld in isolation front grill and paint, fab up e-stop bracket for fuel tank, fab up e-stop bracket for incab, fab up pos id rear sign, fit rear wheels.	
20-May-12	WMS		$340.00	Fit up product link and sink to truck, stamp inner rear wheels, fit up rock ejectors.	
	J. Ciappara	12317	$137.50	Service, repair grease lines, grease	
	WMS	4894	$100.00	replaced 2way hand piece.	