Work Order History Report

Asset	W/O No	Description	Finished	Done Reading	
P0302		**Cat 773F Dump Truck**			
		Final Drive Pos 4 removed and replaced at 15474 hours			
	58146	October R&M - Replace RH door/window assembly (superseded part, weld mods required for install). - Fit door seal - jumpstart - Fit window plate - fit trans output speed sensor - Secure RH mirror and rails - Fit new wheel chocks - Replace fire extinguisher	12/02/2026		Hours
	57784	Rigid Dump Truck - 4000hr Service and to do list 15946hrs	6/02/2026	15946	Hours
	60377	February R&M - 6 MONTHLY FIRE SUPPRESSION TEST/INSPECTION - Demob	28/01/2026		Hours
	60004	January R&M prep for transport	28/01/2026		Hours
	59418	December R&M Pump up both rear struts with nitrogen Check AC functions Repair step Bring truck to workshop	11/12/2025		Hours
	58764	November R&M Window repairs Fit trans input speed sensor, fit guards run up and check fluids Fire system fault Bleed fuel & start Repair trans oil leak Fit C27 sump bolts and spacers Adjust mirrors	22/11/2025		Hours
	58805	Rigid Dump Truck - 250hr Service 15846 hrs - 15852 hrs	1/11/2025		Hours
	57296	September R&M - repair hyd leak 21/09	28/09/2025		Hours

Asset	W/O No	Description	Finished	Done Reading	
		- inspect door, order parts 23/09 - window seal and door glass 28/09			
	52158	Pre-Hire Repairs - Ward Kelly. HME - Dubbo. Report any required repairs. #Refer to Wards handover notes - in cab of truck or see Pete. Ward: Replace batteries, replace pinot pin and bushes, was for transport 09/02: Hard to start, had to prime 3 times, fuel pressure in spec 20/02: Replace ball joints on Y frame drag link for steering, 2 x swapped fuel transfer pump with -- truck to see if problem starts to move 21/02: Find cap screw, fit L/H arm rest Dawson: Assist replacing pivot pin and bushes USO OIL CHARGE OUT	9/09/2025		Hours
	54975	Pre hire repairs-FFP Lake Cowal. Continuation from WO52158.	4/09/2025		Hours
	56801	August Monthly R&M - Fit mirror - 12 Monthly fire suppression and fire extinguisher service - repair rear struts- overfilled with oil 26/08 - c/o starter, repair not power/start, move off ramp 27/08 - replace batteries, fit panels, check over truck, re-clamp hoses 28/08	28/08/2025		Hours
	57426	SOS engine	22/08/2025		Hours
	56458	July Monthly R&M- Lake Cowal Drop off UHF For programming, Pick up nitrogen for struts. Find & print strut charge procedure for 772 dump trucks. Fuel system fault Put nitrogen in 2x 773's	21/07/2025		Hours
	18412	Prepare for sale of Machine Chek over Jump Start Drain Fuel	25/06/2024		Hours
	15430	Inspection Westwood Quarry	20/05/2024	15511	Hours
	9892	De-Mobilisation	23/02/2024		Hours
	9044	Right hand rear wheel nuts loose. Retorq and send to work. **No labour or parts on job April 2024 - closed.	25/01/2024		Hours
	8329	Rigid Dump Truck - 500hr Service	15/01/2024	15497	Hours
	8194	Remove final drive from P1136 in Dubbo. Fab transport stand. Dispatch with mount O'ring and planetary cover o'ring. Remove internally leaking final from P0302 (Pos 4). Fit Replacement unit, bleed brakes. Clean all mounting surfaces, fit final drive assembly tension mount bolts as per oem spec's. Fit tyres + tensioned Filled final drive oil + diff	14/01/2024	15474	Hours

Asset	W/O No	Description	Finished	Done Reading	
		Prep removed core and dispatch to Dubbo. Disassemble and repair final as required Fit wheel group to P1136. Filled final drive oil & diff			
	8232	Refitted step that had been removed. Fitted new belt tensioner. Had been removed and used on another machine to get it mobile. Order/Fit new Solenoid valve	21/12/2023	15474	Hours
	8011	Diagnosing park brake release issue Replaced park brake solenoid with U/S unit, to get P292 back into service. Removed blanking plates from brake cooling circuit. Replaced U/S o-rings. Topped up hydraulic, diff and final drive. Diff is making oil- wheel end fault. Replace UHF	14/12/2023	15474	Hours
	7957	Investigate park brake issue. Park brake will not release. Checked accumulator pressures all seem to be correct. Testing all electrical circuits related to park brake fault. Tested accumulator charge circuit, would not work as per SIS Believe to be faulty valve, pulled apart and found damage on spacer but would still build up. Swapped valve off another truck, still same issue. Swapped back valves and tidied up Fitted park brake solenoid and tested. Dropped charge pressure instantly Fabricate blanking plates to assist in diagnosis of park brake issues. Blocked off right hand wheel end and it built charge pressure. Swapped over and blocked off left hand wheel end, would not build above 100PSI *indicative of a fault with right hand wheel end Blocked off brake cooling ports to see if we could get brakes off Tested service brake line to check for no bypass. Could not get brakes to release Continue investigating park brake fault. Remove solenoids and inspect. Found small particles in valve. blocked off brake cooling hoses. fault still there. Removed drain plug on final drive and found to overfull with oil. Possible wheel end failure. Removed blanking plates from brake cooling circuit. Replaced U/S o-rings. Topped up hydraulic, diff and final drive. Diff is making oil- wheel end fault.	12/12/2023	15474	Hours
	7533	Carried out machine check over as required. Checked starting issue. Found poor connection on isolator wiring. Cleaned and re-tested ok. Trans temp code coming up. Removed J plugs, cleaned and checked all wiring to and from sensor. Found sensor to be faulty. Order replacement sensor. Trans temp low voltage. Shut engine down and restart machine. Re-check and seems ok.	3/12/2023	15444	Hours
	7299	Blew out cabin and engine air filters as required, pre-shift. Fitted new battery isolator as required. Tested- all OK. Replaced mirror as required. Tidied up wiring	26/11/2023	15444	Hours
	7053	Minor R&M: parts supply only	19/11/2023		Hours
	6808	Inspect isolator fault. Found battery isolator to be faulty. Ordered replacement unit.	4/11/2023	15346	Hours
	6106	Rigid Dump Truck - 250hr Service	15/10/2023	15312	Hours
	6076	Check and repair oil leak Follow up from park brake issues- o-ring failed. Replaced with genuine article. Tested- Ok.	15/10/2023	15312	Hours

Asset	W/O No	Description	Finished	Done Reading	
		Top up hydraulic oil, wash and test operation			
	5468	Continued fitting fuel hose clamps and bracket Refitted front cover and plates Replaced some missing bolts Refitted battery isolator, starter isolator Removed old cooler pack and replaced Refitted hoses, fitting and tidied up Replaced missing cooler mounting bolts Checked for park brake not releasing. Operator error.	28/09/2023	15184	Hours
	5326	Brake Fault Fuel hose leak	14/09/2023		Hours
	5084	Carry out brake test Carry out park test Cheak accumulator pressures	5/09/2023	15155	Hours
	4612	Pre-hire work	18/08/2023		Hours
	2557	Off hire repairs #3850 - broken hungry board - removed. Reseal rear RH strut. Brake filter oil leak. Fuel up. Replace batteries. Reseal lift cylinder hoses. RH Mirror repaired. Replace top bearings in both LH & RH lift cylinders. Reseal hoist valve and associated hoses. Reseal torque convertor output shaft. Replace RH steer cylinder ball studs. Diagnosed hard to start - replace fuel transfer pump and reseal hoses in fuel pressure ciruit. Rewire horn circuit and replace horn. A/C issue - not blowing cold air. Clean out evaporator, clean out system, clean filters. Window washers not working - cleaned out bottle and replaced hose. Shim body pads. Check and charge accumulators. Weld up cracks for fire suppression bottle mount. Service fire suppression system. Test rims. Replace a-frame bearing. Checked electrical fault with park brake drag. Straighten body pad mount under tub. Straighten wheel chock holder. Straighten front right light holder and fit lights. Replace dog bone bearings. Wash. Site requirement checks and paperwork. Replace air filter covers. Reseal Brake/Hoist tank sight glass. Reseal accumulator valve and associated hoses/fittings.	20/07/2023	15155	Hours
	3914	Take strut to Morrison's for repair.	30/06/2023		Hours

Asset	W/O No	Description	Finished	Done Reading	
		Fit new batteries. Clean out battery box.			
	3913	Press out seized strut pin, hoist, lube o-rings, various leaks.	29/06/2023		Hours
	9725	Re-seal strut	19/06/2023		Hours
	9693	Dog Bone Bearings J#2810	16/06/2023		Hours
	2168	Organize boom lift and Franna to remove eyebrows and put in tub. Load on float.	27/05/2023		Hours
	2165	Drop struts	26/05/2023		Hours
	2303	Carried out repairs to machine preparing machine for transport	13/05/2023		Hours
	1892	Demobe - Get franna and boom lift to remove all cat walks and put in tub	6/05/2023		Hours
	2378	Fitted secondary steering solenoid	26/04/2023		Hours
	1078	Gouge R/H side strut crack out. Weld up and fish plate cracked area. Cat yellow paint and prime	17/04/2023		Hours
	716	EWP use to weld out underside of beaver tail. Move machine to start repair on RH strut	16/04/2023	15142	Hours
	830	Replace lift cylinder hoses	10/04/2023	15142	Hours
	2366	Diagnosed secondary steering fault. New soildnoid on order	6/04/2023		Hours
	723	Finish off welding beaver tail out	5/04/2023	15142	Hours
	721	Tub weld out and wear strips install. install 6 100 biz strips	4/04/2023	15142	Hours
	719	Cut and install biz plate weld out plate	3/04/2023	15142	Hours
	814	Cut and prep steel for bin repairs. Replace fan belts, hood lining and door stop	2/04/2023	15142	Hours
	668	Carried out repairs to machine, assisted boiler maker doing repairs to machines body. Fitted new parts like cabin roof lining.	2/04/2023	15142	Hours
	647	Tub repairs	26/03/2023	15142	Hours
	643	Remove floor back to main frame and clean out all the dirt. Prep for new floor	25/03/2023	15142	Hours
	625	Remove rest of wear package on beaver tail.	24/03/2023	15142	Hours
	623	Tub repairs clean tub of larger rock, Remove wear plate on beaver tail	23/03/2023	15142	Hours
	621	Inspect cracks on chassis	22/03/2023	15142	Hours
	607	Carried out repairs to machine, drained and refill front strut oil and tested. All ok.	20/03/2023	15142	Hours
	606	Commenced repairs to this machine started disassembling LH rear body strut and preparing it to be reassembled. Completed repairs to this machine, completed cleaning LH rear strut. Reassembled strut using new seal, then topped up	19/03/2023	15142	Hours

Asset	W/O No	Description	Finished	Done Reading	
		with new oil and adjust it to correct height. Carried out repairs to RH rear strut, drain old oil and topped up with new oil and adjust it to correct height.			
	604	Carried out inspection and testing on this machine. Carried out repairs on this machine, repaired oil leaks and commenced repairs to rear strut tower.	18/03/2023	15142	Hours
	1214	Carried out running checks/movement checks/ defects list	6/02/2023		Hours

Service History Report for - P302 Caterpillar 773F Rigid DT

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
23-Sep-22	Shane	14664	$200.00	Machine shut down at digger bunch. Check over. Ecams not communication. Start diagnosing, other machines were priorty	
30-Aug-22	Sean	14295	$500.00	1000hr service & machine checks	
30-Aug-22	Jack	14295	$1,200.00	1000hr service	
21-Aug-22	Sean	14189	$100.00	Injector fault	
19-Aug-22	Shane		$100.00	R+R pos 6	
02-Aug-22	Shane	13914	$100.00	Fix mirror	
02-Aug-22	Jack	13921	$100.00	Repaired FSI fault	
02-Aug-22	Rhys	13914	$100.00	Broken mirrors	
01-Aug-22	Jack	13921	$50.00	Accident damage	
29-Jul-22	Jack	13864	$110.00	Rock injector	
28-Jul-22	Shane		$220.00	Repair flat tyre	
28-Jul-22	Rhys	13163	$55.00	Replace steps	
27-Jul-22	Jack	13855	$165.00	Broken wiring FSI fault Damaged estop	
21-Jul-22	Xander	13972	$55.00	Fill engine oil	
20-Jul-22	Xander	13792	$165.00	250hr service Fuel & grease	
07-Jul-22	Jack	13674	$100.00	C/O horn and broken wire on FSI system	
07-Jul-22	Sean	13674	$200.00	Horn pad changeout and broken wire FSI bottle	
02-Jul-22	Rhys	1365	$300.00	500hr service	
02-Jul-22	Jack	13635	$300.00	500hr service Defects	
30-Jun-22	Rhys	13629	$250.00	Warning light on dash loss off power	
30-Jun-22	Sean	13629	$250.00	Warning light engine and lost all power to dash and vims	
09-Jun-22	Lain	13488	$82.50	Greased Blew out filters Diagnosed computer fault	
23-May-22	Harry F	13318	$176.00	Diagnose A/C - no fault found	
12-May-22	Alex	13278	$288.75	Tighten up all walkway mounting bolts Install rock guards and run harness	
12-May-22	Lain	13270	$330.00	Torqued up walkways and hand railings Gassed front and rear shocks Bolted up body wirings	
06-May-22	Harry D		$330.00	Cut off plate on side of truck and cut a new one, finish welding floor in, weld cracks up on walk way.	
04-May-22	Jim N		$66.00	Took rock guards off.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-May-22	Zumbo		$112.50	Load tub with tyres, walkway and bucket.	
04-May-22	Craig P	13277	$563.75	Clean up rear suspension cylinder bores, fit new bearings, fit cylinders, lower machine from stands, remove body rock deflectors for (tilt?) on hire paperwork, tp up fluids, fit missing bosy t(tool?) clean work area, on hire paperwork, load components.	
04-May-22	Clay B	13277	$357.50	Fit exhaust elbow, fit light brackets, fit plant ID bracket, fit suspension pad, replace check valve, remove engine covers, fit bucket, tyres, access steps / walkway in back of tub, paint blue rail on side of head board.	
03-May-22	Harry D		$591.25	ut out wear floor and grind up in tub, cut out holes in sheet and weld new sheet in.	
03-May-22	Craig P	13277	$96.25	Remove LH access for (tilt?) and fit safety decals.	
29-Apr-22	Clay B	13277	$412.50	Fit tranny hoses, reseal RHS brake cooling pipe, fit UHF hand piece, remove old strut bearings, clean dogbone ears / buff pins, fit dogbone, cut exhaust bolt heads off and assist removing it, top up hydraulic oil.	
29-Apr-22	Craig P	13277	$495.00	Remove rusted exhaust elbow, remove 4x siezed bolts, fit brake cooling return tube to tank, repair damaged flange on brake cooling return hose, fit brake cooling return hoses, fit dog bone, remove both lower strut bearings.	
29-Apr-22	Harry D		$82.50	weld up crack on back of dump truck.	
28-Apr-22	Clay B	13277	$508.75	Remove hoses for A-frame bearing removal, split machine.remove old bearing, clean bores up, install new bearing, torque locking nut, pull machine together, fit tranny hoses, fit drive shaft / driveshaft cover, clean work area.	
28-Apr-22	Craig P	13277	$536.25	Remove hoses, driveshaft, wiring harness, remove rear axle lock, remove A-frame bearing, clean up parts, fit new bearing and nut, move axle forward, fit hoses and driveshaaft (waitig on new pin) clean area.	
27-Apr-22	Clay B	13277	$440.00	Remove old armrest / fit new one. Pop steer cylinder ball studs, remove old ball studs, clean cylinder / bores fit new studs, fill with grease, run grease lines, tidy grease lines, steer cylinder hoses, clean work area.	
27-Apr-22	craig P	13277	$178.75	C/O RH and LH inner steer cylinder ball stands, check light operation, disconnect hoses for A-Frame bearing C/O, clean area.	
20-Apr-22	David M		$280.00	Cut wear plate Fit pallet rack in yard	
14-Apr-22	Jim N		$412.50	Smashed out ball joints, took tranny hoses off.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
14-Apr-22	Connor M		$508.75	Ball joints, fited new hose to hydraulic tank suction line, unbolted tranny, diff drive shaft, knocked bottom suspension strut pins out, cleaned up grease around suspension struts, removed rear dog bone and cleaned up.	
13-Apr-22	Harry D		$55.00	weld up sock under cab and weld up crack.	
13-Apr-22	Connor M		$339.12	Assisted greg with machine check over, removing strut tower for crack to be welded up. Started on ball joints.	
13-Apr-22	Jim N		$343.75	Fire tags, filled washer bottle, fitted spray nozzle, installed shocks, put tyre back on, torque bolts, cleaned up and started to knock out steer cylinders.	
07-Mar-22	Jim N		$55.00	Pulled off back tyres.	
07-Mar-22	Zumbo		$110.00	Jack up and remove rear wheels.	
02-Mar-22	Harry D		$96.25	Put hanger board on and grind out cracks.	
16-Oct-21	Harrison F		$110.00	Install TFO tracker Remove NPM tracker	
13-Jul-21	Duncan	12843	$137.50	Complete FFP inspection Repaired step rubbers Top up steering oil	
20-Jun-21	Duncan	12744	$247.50	Complete 250hr Service Fit wheel chocks Repaired step	
13-Jun-21	John	12706	$55.00	Adjust mirrors	
11-Jun-21	B Swan	12699	$55.00	FFP checks & repairs	
01-Jun-21	John	12596	$55.00	Remove broken grease line Fit new UHF Perform park brake test	
27-May-21	Duncan	12546	$55.00	Check tyre pressures. Pump up Pos 3 & 5	
26-May-21	Duncan	12545	$275.00	Complete 500hr service Remove step rubbers Trimmed, drilled new holes Refitted step	
10-May-21	B Swan	12410	$55.00	Carry out diagnostic checks and change all machines to 40km p/h	
02-May-21	Duncan	12394	$110.00	Hyd leak. Replace on brake charge hose at accumulator Repaired grease lines on starring joints	
20-Apr-21	John C	12319	$192.50	Fit new reverse light relay Fit new strut bolts	
19-Apr-21	John C	12319	$220.00	250hr service - check over	
17-Apr-21	John	12393	$27.50	Grease	
01-Apr-21	A Mills	12234	$55.00	Missing trans cap replaced Greased	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
31-Mar-21	John	12209	$357.50	Fit new hoist cylinder hose Clean trany electric plug Clean engine position sensor Fit new LHF blinker Fit new reverse light FFP paperwork	
08-Mar-21	A Mills	12152	$55.00	Fire suppression mounts - bolts missing	
08-Mar-21	John	12152	$110.00	Remount fire suppression bottle Swap mirrors	
08-Mar-21	A Mills		$55.00	Change out mirror - smashed	
22-Feb-21	John	12072	$41.25	Check over Grease	
17-Feb-21	John	12041	$55.00	Check oils	
10-Feb-21	A Mills	12043	$55.00	Grease & check over	
09-Feb-21	A Mills	12043	$55.00	Grease & tidy up elec wiring	
09-Feb-21	John	12043	$55.00	Grease	
07-Feb-21	A Mills		$110.00	Gas struts, strut cover, fit mirrors, move together	
07-Feb-21	John		$107.25	Gas struts, fit strut covers, fit mirors, mobilise	
05-Feb-21	Clay		$495.00	Replace old light bulb with new one Scrape old MAAS stickers and replace with new ones Stick reflective stickers around machine Re attach P clamps on hoses. Go over machine Wipe down cab and blow it out Replace cab filters Re attach rock guard Drain and replace final drive oil Clean up underneath machine Fill auto greaser, clean up grease Clean bolt heads for marking	
04-Feb-21	Zumbo	12042	$165.00	Fit trans cooler hose Fill trans oil Inspoect fault code with ET pressure wash	
04-Feb-21	Ted Van		$27.50	Clear FFP actions	
03-Feb-21	Ted Van		$137.50	Clear NPM FFP & HV defects	
03-Feb-21	Zumbo	12042	$55.00	Check over final defects. Remove tranny cooler hose	
02-Feb-21	Clay	12042	$220.00	Change hydraulic hose	
02-Feb-21	Jackson	12042	$82.50	North Parkes FFP Check all critical fasteners, safety stickers Replace cooling hose	
01-Feb-21	Clay	12042	$247.50	Replace O-rings Put hydraulic hose on Shovel dirt into loader bucket	
01-Feb-21	Zumbo	12042	$192.50	Repair defects NPM FFP	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-Feb-21	Jackson	12042	$165.00	North Parkes FFP Replace globe in interior light Lower front step Replace axle cooling hoses	
29-Jan-21	Jackson	12042	$247.50	North Parkes FFP Sleeve hosing Fit reflective tape Replace x 3 globes in front lights Secure hosing Safety stickers	
29-Jan-21	Connor		$96.25	Handrails	
21-Jan-21	Ted Van		$302.50	NPM - FFP	
14-Jan-21	Zumbo	12041	$82.50	Fit side cab handrail & repair bolt threads	
12-Jan-21	Zumbo	12041	$137.50	Install handrails & mirrors	
08-Jan-21	Lindsay		$440.00	Finish hydraulic sleevings Clamp up all hoses Start & clutch Diagnose steering code Test batteries	
08-Jan-21	Jackson	12040	$192.50	North Parkes FFP Sleeve hosing with burst protection Secure hosing Replaced grease nipples Fitted seatbelt buckle	
08-Jan-21	Zumbo	773	$220.00	North Parkes FFP Burst protection & hose clamps	
07-Jan-21	Lindsay		$220.00	Hyd sleeving	
07-Jan-21	Jackson	12040	$261.25	North Parkes FFP Sleeve hosing with croc sleeve	
06-Jan-21	Shane	12040	$27.50	Test Fire Supression & remobe bottle for testing	
05-Jan-21	Connor		$220.00	Remove hand rails / take to paint bay	
17-Dec-20	Zumbo		$27.50	Cover missed fuel lines in burst protection	
17-Dec-20	ack Lovemor		$275.00	Insulate fuel lines	
16-Dec-20	ack Lovemor		$371.25	Insulate fuel lines	
16-Dec-20	Zumbo		$330.00	Cover fuel lines in burst proction & repair front grill bolts	
07-Dec-20	KyleMusgrave		$247.50	Buub repairs Tube repairs	
04-Dec-20	Dave Marshal		$385.00	Repairs to 773 truck	
03-Dec-20	Dave Marshal		$412.50	Repair bumba bar	
01-Dec-20	Dave Marshal		$82.50	Fold and fabricate bumpa bar	
28-Nov-20	Will Paull	12038	$110.00	Fit steer pin and tighten Check levels	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
27-Nov-20	Will Paull	12038	$371.25	Checks Remove RH Steer cylinder pin & bearing Remove seat base Remove replace rear dog bone bearings - grease	
27-Nov-20	Ryan Morris		$330.00	Pre hire repairs	
26-Nov-20	Dave Marshal		$27.50	Measure and draw bumper bar	
25-Nov-20	KyleMusgrave		$110.00	Mud guard repairs	
30-Sep-20	Greg M	11999	$192.50	Finish 1000hr service.	
29-Sep-20	Greg M	11999	$82.50	Begin 1000hr service	
01-Sep-20	Greg Mills	11837	$110.00	Replace broken exhaust section.	
07-Jul-20	Greg	11720	$82.50	Carry out service	
25-May-20	Greg Mills		$55.00	Repair step.	
05-Mar-20	Greg	11522	$110.00	Gas fire suppression Find leak & repair	
04-Mar-20	Greg	11522	$82.50	Carry out engine services	
21-Feb-20	Greg	10522	$55.00	Charge up fire supression	
08-Feb-20	Lindsay		$55.00	Diagnose isolator issue Remove cover Disconnect & tape up isolator	
07-Jan-20	Zumbo	773	$247.50	North Parkes FFP Paint tow & lift points Replace battery isolator	
15-Jun-19	Kyle		$0.00	Fix trailer mud guard bracket holder x2	
06-Feb-18	Swanling		$272.00	Remove & replace hydraulic hose from tranny to front of engine	
08-Oct-17	Swanling	10309	$317.63	Fit walk way, eyebrows, mirrors, hook up wiring	
28-Sep-17	J Ciappara		$65.00	Fit wheel chock bracket. Put new wheel chock bracket and wheel chocks in tub.	
11-Sep-17	Ted Van	10309	$422.50	Remove RH lift cylinder. Replace bearings in top and bottom of spare cylinder and fit.	
08-Sep-17	Ted van	10309	$97.50	Remove top pin from Rh lift cylinder - organise parts	
07-Sep-17	Ted Van	10309	$195.00	Repair wiring and replace globe to access light. Tag supression system and extinguishers. Swap out batteries with spare.	
02-Aug-17	J Ciappara		$195.00	Reseal brake filter housing lines. Refit brake filter housing. Check tyre pressures.	
01-Aug-17	J Ciappara		$325.00	Assist with checkover. Fill window washer. Remove brake filter housing. Reseal brake filter housing lines.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
27-Jul-17	ake Seymour		$65.00	Assist fordy with hungry boards	
26-Jul-17	ake Seymour		$81.25	Assist fordy fitting hungry boards	
09-Jan-17	RAM Diesel	10252	$41.00	Check fleet for first day back	
13-Dec-16	RAM Diesel		$41.00	Adjust mirrors General check	
08-Dec-16	RAM Diesel	10203	$41.00	Inspect hyd leak & tighten fittings around accumulators	
26-Nov-16	RAM Diesel	10131	$288.00	Jack machine & remove failed RHR lower failed strut bearing/pin Repair base of damaged strut & circlip groves Fit new bearing & pin Pack up	
25-Nov-16	Childs Earth	10131	$732.00	Jacked & chocked Stripped & fitted spare runout 24.00R35 tyre to POS 2 & inflated	
25-Nov-16	RAM Diesel	10131	$82.00	Swap out truck with P283 Assist with strip & refit of POS 2 tyre Escort handler back to workshop	
11-Nov-16	RAM Diesel	10040	$41.00	Check burning smell of rubber reported by operator Seems to be coming from POS 2 tyre No visible sign of failure Temps slightly higher than other trucks Pumped tyre up to 100 PSI Will monitor - returned to work	
04-Nov-16	RAM Diesel	9994	$206.00	Pump & load oils/filters Travel to machine Perform 1000hr service Dispose of oils & filters	
20-Oct-16	RAM Diesel	9894	$371.00	Leaking brake hose Remove & take to Gympie to have new one made Return to site & fit Remove belts from P301 & fit to P302 Top up oil	
17-Oct-16	RAM Diesel	9868	$82.00	Replace rubber step strap & straighten bent step piece	
20-Sep-16	RAM Diesel	9776	$206.00	Organise franna, JHA lift plan Unload & assemble walkways, stairs, tub wings etc Charge front struts, set mudguards	
17-Sep-16	Fordy		$292.50	Weld repairs	
17-Sep-16	C Ford		$281.00	Weld repairs	
17-Sep-16	D.Lundholm	9772	$308.75	Wash. Replace snapped LH strut bolt.	
16-Sep-16	Ted van	9775	$487.50	Complete pre-hire paperwork, drop front struts, replace Lh lift cylinder with new bearings and re-hose, finish repairing guards and handrails.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Sep-16	D.Lundholm	9772	$585.00	Pull apart for transport. Clean cab. Assist fit LH lift cylinder and bottom bearing. Complete machine to site specs. Tension front strut bolts. Get parts. UHF aerial fitted,	
16-Sep-16	jacob	9774	$97.50	Started to dig dirt out and wash machine	
16-Sep-16	Dustin		$130.00	Assist with removing stairs	
15-Sep-16	Ted Van	9775	$487.50	Replace reverse camera, recover spare lift cylinder from spare tub down back of yard, remove LH hoist cylinder and cap off lines, replace front brake control switch and reassemble dash, continue with front right quarter/bumper repair.	
15-Sep-16	Jacob	9772	$97.50	Removed old hydraulic filter and replaced, bent exhaust back into place.	
14-Sep-16	D.Lundholm	9772	$520.00	Replace fuel tank E-stop. Repair front E-stop. Remove steer filter seal. Tag extinguishers. Wheel chocks. Start removing lift cylinder pin.	
14-Sep-16	C Ford		$187.00	Remove hungry boards	
14-Sep-16	Ted Van	9775	$487.50	Replace P2 brake pads, remove damaged front 1/4 bumper on RHS and start repairing step.	
14-Sep-16	Fordy		$195.00	Remove hungry boards	
14-Sep-16	Kevin.M		$97.50	Help Dane remove LH top tub ram pin.	
13-Sep-16	D.Lundholm	9772	$162.50	250 hr service. Change eng oil and filters and eng air cleaners blew out. Replaced cab filters and fuel filters.	
13-Sep-16	Ted Van	9775	$227.50	Empty tub, order parts, replace fuel tank cap breather, reconnect wiper linkage weld in place, diagnose wiper wiring fault to faulty switch - replace switch.	
09-Sep-16	Ted Van		$65.00	Drive out and load on float.	
06-Sep-16	Ted Van	9772	$130.00	Check over condition report.	
06-Sep-16	Ted Van		$130.00	Wash and load with parts.	
03-Jun-16	Ted Van	9202	$65.00	Remove wiper motor assembly and reconnect linkage and refit.	
17-May-16	Ted Van	9641	$227.50	Check and clean all connections in transmission temp sensor circuit from sensor to ecm. Check wires for breaks and resistance all good fault cleared	
16-May-16	Ted Van	9641	$195.00	Chase electrical fault with transmission temp sensor	
20-Apr-16	Ted Van	9573	$65.00	Replace faulty transmission sensor output speed sensor number 2 and test drive ok.	
20-Apr-16	Ted Van	9573	$65.00	Replace faulty transmission output speed sensor #2 test drive ok.	
07-Apr-16	G Wykes		$187.00	Repairs to hungry boards	
07-Apr-16	Ted Van	9564	$130.00	Carry out 500hr service per spec.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
05-Apr-16	Ted Van	9560	$195.00	Replace faulty wiper motor. Calibrate transmission. Reseal leaking fitting at control valve.	
14-Mar-16	Greg Mills	9418	$162.50	Replace hyd hose replace step rubbers.	
22-Feb-16	Ted Van	9333	$130.00	Replace a/c fan motor, top up a/c gas. Reassemble air box and refit covers.	
16-Feb-16	Greg Mills		$130.00	Disassemble a/c hosing	
15-Feb-16	Greg Mills		$162.50	Check a/c fault, fan not working, remove fan, replace fitting on compressor.	
10-Feb-16	Ted Van	9328	$65.00	Check over and start. Top up a/c gas and a.c check ok.	
28-Jan-16	Ted Van	9328	$292.50	Remove and replace u/s muffler	
27-Jan-16	Ted Van	9328	$162.50	Remove u/s muffler	
19-Jan-16	Greg Mills	9294	$130.00	Diagnose trans fault. Clean all plugs. Check wiring.	
14-Jan-16	Ted Van	9271	$32.50	Replace steps/	
04-Jan-16	Greg Mills	9158	$97.50	Fit pos 6 tyre	
22-Dec-15	Greg Mills	9158	$390.00	Remove POS 3,4,5 and 6. Fit POS 3,4 and 5	
17-Dec-15	Ted Van	9144	$130.00	Change flat POS 3 tyre	
16-Dec-15	A Warren		$214.50	Removed parts for Ted for Mineral Hill	
11-Dec-15	Greg Mills	9098	$195.00	Replace fan hub bolt.	
09-Dec-15	Greg Mills	9084	$65.00	Repair a/c	
08-Dec-15	Greg Mills	9070	$195.00	Diagnose trans sensor fault, clean out all plugs in harness, load machine and test.	
03-Dec-15	Tec Van	9048	$162.50	Replace P3 tyre, reseat and inflate spare.	
02-Dec-15	Tec Van		$32.50	Set up for P3 changeout	
27-Nov-15	Greg Mills	9008	$65.00	Fit transmission hose.	
26-Nov-15	Greg Mills	9008	$325.00	Carry out 1000hr service, Change engine oil, change engine oil filters, change fuel filters, change inner and outer air filters, change cab filters, change transmission oil and filter, Change pilot filters, Check transmission screens, Change front hub oil, Check final drive oil and bungs, check diff bung.	
14-Nov-15	G Wykes		$125.04	Repair hungry boards	
06-Nov-15	Ted Van	8928	$195.00	Change out POS 3 tyre flat	
04-Nov-15	Ted Van	8910	$195.00	Chase parts, repalce faulty tranny speed sensors. Replace tranny temp sensor. Replace faulty lock up clutch moudlating valve. Repair wiring to madulating valve and temp sensors.	
03-Nov-15	Ted Van		$65.00	Chasing parts	
27-Oct-15	Greg Mills		$227.50	diagnose trans temp fault. Lock up clutch fault.	
21-Oct-15	Ted Van	8787	$292.50	Replace blown P4 and P5 tyres. Take all tyres to 90psi.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
20-Oct-15	Ted Van		$227.50	Replace u/s a/c compressor.	
09-Oct-15	Greg Mills		$65.00	Repair reverse camera	
07-Oct-15	Greg Mills	8690	$130.00	Repair hydraulic oil leak. Top up hydraulic oil.	
07-Oct-15	G Wykes		$63.00	Repair tank brackets	
06-Oct-15	Greg Mills	8678	$390.00	Replace bolt in fan hub. Updated bolt fitted. Replace brake loading hose. Check and repair fuel levelsensor.	
21-Sep-15	Greg Mills	8539	$227.50	Change out broken fan bolt.	
21-Sep-15	Ted Van	8530	$32.50	Blow out cab and cab filters. Check weeping hydraulic hose.	
17-Sep-15	A Warren	8503	$429.00	completed 500hr service. Attempted to straighten r/h guard. Replaced oring on brake cooler hose.	
14-Sep-15	A Warren	8482	$500.50	Removed tyres from truck. Removed tyres off transport. Loaded up tyres to return to yard. Fitted four new rear tyres. Checked over truck & topped up oils	
14-Sep-15	Greg Mills	8459	$130.00	Replace fan hub bolt	
11-Sep-15	Ted Van		$32.50	Check pos3 tension	
11-Sep-15	Ted Van		$32.50	Inspect oil leak	
10-Sep-15	Greg Mills	8444	$260.00	Replace pos3 and 4 wheels, repair lights	
09-Sep-15	Ted Van		$32.50	Tighten clamps on radiator hose.	
21-Aug-15	A Warren		$250.25	Removed & installed POS 5 tyre	
19-Aug-15	Greg Mills	8148	$130.00	Repair grease lines, make up and fit new lines. Repair lights.	
17-Aug-15	A Warren	8092	$71.50	Topped up hyd oil. Checked over	
14-Aug-15	Greg Mills	8087	$325.00	Carry out 2000Hr service as manufacturer specifies. Change eng oil, filters, fuel filters. Change inner and outer air cleaners. Change cab filters. Change front hub oil. Change trans oil and filter. Change brake filters. Check diff and find drive bungs. Repair grease lines. Radio.	
28-Jul-15	A Warren	7847	$286.00	Removed & fitup POS 3 tyre	
22-Jul-15	Greg Mills	7801	$487.50	Repair oil leak, fit bolt to hungray board. Top up hyd oil. Test brake pressures and check tyre pressures.	
08-Jul-15	Andrew		$262.50	Changed out pos 3 tyre.	
03-Jul-15	Andrew	7570	$35.00	check over & grease.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
02-Jul-15	Andrew	7560	$525.00	repaired/diagnosed park brake fault. Swapped sensors. Stripped brake valve block found white backup Oring material jammed /stuck in spools. Cleaned & re-assembled. Greased & checked over machine.	
30-Jun-15	Andrew	7560	$225.00	diagnose & find fault in park brake circuit. Park brake wouldn't apply. Repaired wiring to reverse camera. Organised parts.	
29-Jun-15	Andrew	7553	$75.00	repaired door window latch.	
25-Jun-15	Andrew	7501	$150.00	removed rock ejector & rock wedged in tyres. Fitted up, rock ejector from P281 & ordered parts.	
23-Jun-15	Andrew	7492	$525.00	assembled fan hub & fitted to machine. Fitted new belts. Chekced over machine.	
22-Jun-15	Andrew	7492	$450.00	removed & stripped fan hub.	
19-Jun-15	Andrew W.	7492	$65.00	Removed and replaced alt / a/c belts	
05-Jun-15	Andrew		$225.00	installed hungry boards & bolted down. Installed bucket into tub. Completed paperwork for onsite.	
05-Jun-15	Dustin Eade		$130.00	Finished off, filled with fuel, coppied paper work	
04-Jun-15	Dustin Eade	7484	$341.25	Re-fitted starter motor, re-fitted rocker covers, Re-fitted intake pipe, Topped up oils and fuels. Pre hire	
03-Jun-15	Andrew	7484	$656.25	assisted in tie rod end tensioning. Finished off remainder of vavle set. Completed pre hire pwperwork. Fitted rock ejector. Assisted in pos 3 tyre fitment. Gassed up struts.	
03-Jun-15	Dustin Eade	7484	$585.00	Torque all wheels to 1500ft/lbs, Refitted Pos 8 rim and tyre, Tighten all tie rod ends to 1000ft/lbs, Refit LH mirror assembly, Refit all grease lines to steering, Refit hydraulic tank, Refilled hydraulic tank	
03-Jun-15	Kevin		$65.00	Assisted dusto	
02-Jun-15	Andrew	7484	$656.25	repaired guards. Fitted mudflap. Completed vavle set.	
02-Jun-15	Dustin Eade	7484	$585.00	Resealed starter motor, Split hydraulic tank after emptying and catching oil. Replaced sight glass seals, Removed all rocker covers, removed ecm, removed turbo intercooler pipe.	
01-Jun-15	Andrew	7484	$150.00	completed machine checkover & ordered parts.	
07-Jan-15	Greg Mills		$325.00	Replace tie rod ends on steer link, pop other joints, had to heat to get them to pop.	
11-Dec-14	Greg Mills		$65.00	Remove POS 3 wheel, load onto trailer, take to marathon tyres	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
10-Dec-14	Greg Mills		$162.50	Repalce 2 x ball joints in steering link, fit to machine	
05-Dec-14	Greg Mills	7482	$32.50	Strighten Rh mudguard	
06-Nov-14	Greg Mills	7482	$32.50	Drop struts	
16-Oct-14	Greg Mills	7483	$65.00	Tighten up POS 3 wheel	
15-Oct-14	Greg Mills	7483	$162.50	Carry out service, change engine oil and filter/fuel filters and only one air cleaner.	
14-Oct-14	Greg Mills	7482	$32.50	check over machine and make up jobs list.	
09-Aug-14	Greg Mills	7263	$32.50	Top up engine oil	
07-Aug-14	Greg Mills		$32.50	Turn RH step upside down and fit chain across handrail.	
22-Jul-14	Greg Mills	7176	$65.00	Replace drivers side mirror, try to remove broken bolt	
21-Jul-14	Greg Mills	7176	$32.50	Replace step rubbers, fit fuse to flashing light wiring	
07-Jul-14	Greg Mills	7106	$32.50	Fit flashing light to machine.	
04-Jul-14	G Wykes		$20.00	fab flashing light brackets.	
29-Jun-14	Greg Mills	7068	$32.50	Replace inner and outer air filters	
26-Jun-14	Greg Mills	7053	$65.00	Repalce oil line in seat	
23-Jun-14	Greg Mills	7030	$195.00	Finish 1000hr service, change cab filters/trans oiland filter/brake filter/steer filters, check wheel end plugs, check front hub plugs and level, check screens.	
13-Jun-14	Greg Mills	7003	$97.50	Carry out engine service, change engine oil/filter and fuel filters.	
12-Jun-14	Greg Mills	6995	$32.50	Replace broken steps, bent brackets and step rubbers.	
29-May-14	Dave O'Leary	6928	$32.50	Inspect tranny overheat problem - wiring fault	
21-May-14	Ted van	6905	$32.50	Connect ET - check speed limit and retarder settings.	
07-May-14	Ted Van	6835	$97.50	Replace faulty transmission temp sensor	
06-May-14	Ted Van	6818	$130.00	Check wiring and connections to trans temp sensor	
05-May-14	Ted Van	6818	$130.00	Check fault code for transmission fault and organise parts	
28-Apr-14	Josh H		$260.00	Help Dave get machine ready to go to work. Check oils, pump up struts, pump up tyres etc.	
28-Apr-14	Dave		$210.00	Oil & gas front & rear struts as required. Check lights. Replace Estop. Top up oils. Check over ready for work.	
27-Mar-14	RLW		$245.00	swap tyres between P282 & P302 & P281.	
21-Mar-14	RLW	6789	$178.75	check over. Tighten bolts fire supression. Straighten wheel chock bracket. Find faultin 2 head lights RHS.	
17-Mar-14	Greg Mills		$65.00	Remove walkways/eyebrows/stairs	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Mar-14	Shane		$35.00	refit LH access steps to machine.	
07-Mar-14	Greg Mills		$32.50	Replace rubber on front steps	
21-Feb-14	Greg Mills		$162.50	Change out POS 1 brake pads	
15-Feb-14	Shane		$112.50	Replace broken step rubbers. Check Estop wiring to compare with P293.	
11-Feb-14	G Wykes		$89.40	Fab hungry boards.	
10-Feb-14	G Wykes		$81.25	Fab hungry boards.	
07-Feb-14	G Wykes		$30.00	Fab hungry boards.	
06-Feb-14	G Wykes		$75.00	Fab hungyr boards.	
05-Feb-14	G Wykes		$90.00	Fab hungry boards.	
04-Feb-14	G Wykes		$95.00	Fab hungry boards.	
24-Jan-14	Greg Mills	6516	$65.00	Fit window	
23-Jan-14	G Wykes		$10.00	fab hungry boards.	
22-Jan-14	G Wykes		$30.00	fab hungry boards.	
17-Jan-14	Andy William		$585.00	Service oil leak at RH cooler pipe replace o-ring, top up steering oil and front hubs, oil leak at RHF brake cooler hose,	
17-Jan-14	G Wykes		$81.50	fab hungry boards.	
16-Jan-14	G Wykes		$81.50	fab hungry boards.	
15-Jan-14	G Wykes		$81.50	fab hungry boards.	
15-Jan-14	Greg Mills	6453	$65.00	Check light on dash - trans sensor fault checked wiring to sensor	
14-Jan-14	G Wykes		$81.50	fab hungry boards.	
13-Jan-14	G Wykes		$32.50	Fab hungry boards.	
31-Dec-13	Greg Mills	6301	$97.50	Change POS 6 tyre	
13-Nov-13	Shane	6040	$225.00	replace batteries. Check, OK.	
10-Nov-13	Greg Mills	6024	$65.00	Check amp voltage out of alterator, check battery size, check codes.	
10-Nov-13	Shane	6027	$75.00	check alt charge- OK. Order new batteries.	
31-Oct-13	Greg Mills	5992	$162.50	Gas front struts	
31-Oct-13	Ian Miller	5991	$32.50	Change front RH high beam and check - OK	
30-Oct-13	Greg Mills	5992	$130.00	Gas up struts	
30-Oct-13	Ian Miller		$260.00	Change starter motor	
29-Oct-13	Ian Miller	6156	$260.00	Repair wiring and deutsh plugs, remove camera cables, bolt up stairs, blow out rear engine radiators due to excess dirt and seeds.	
28-Oct-13	Ian Miller		$65.00	Fit new fuel/water separator filters and check lights	
28-Oct-13	Shane	5992	$375.00	fit rock guards, walkways, stair & mudguard. Check faulty wiring to head lights. Segregate electric & hyd. Fit stickers.	
26-Oct-13	Ian Miller		$65.00	R&I fuel/water filter metal bowl	
14-Oct-13	WMS - T		$600.00	strip down for transport.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
07-Oct-13	WMS - T		$600.00	strip down for transport.	
23-Sep-13	WMS	5969	$200.00	Jump started truck. Checked alternator operation and wiring as well as earth points.	
25-Aug-13	WMS - A	5837	$300.00	changed out pos 1 tyre.	
22-Aug-13	WMS -A	5837	$500.00	change out pos 2 & 5 tyres.	
06-Aug-13	WMS	5747	$300.00	250 hr service.	
31-Jul-13	WMS	5697	$300.00	completed transmission, pressurer, fill & clutch adjustment.	
27-Jul-13	WMS	5696	$400.00	repaired trans harness wiring for temp sender.	
15-Jul-13	WMS	5606	$400.00	carry out 250 hr service.	
15-Jun-13	WMS	5513	$100.00	fitup rock ejector.	
13-Jun-13	WMS	6444	$1,000.00	p3/4 duo seal rebuild.	
12-Jun-13	WMS		$600.00	strip down p5/p6 duo seal hub.	
07-Jun-13	WMS	5420	$300.00	inspected truck wheel seal leaking. Cleaned hub assembly ordered parts.	
18-May-13	WMS		$360.00	250 hour service APS	
13-Apr-13	WMS	5116	$360.00	Repair wiring to windscreen wipers, intermited operations.	
08-Apr-13	WMS		$170.00	Tighten up loose fitting & replace oring on hydraulic filter housing, fill with oil.	
16-Mar-13	WMS	4976	$100.00	checked tyre pressures. Adjusted tub speed. Machine check over.	
23-Feb-13	WMS	4894	$300.00	finish off exhaust repairs.	
22-Feb-13	WMS	4893	$200.00	repair hole in exhaust until new one turns up & charge up fire suspression.	
17-Feb-13	WMS	4891	$450.00	escorted Pana from Wormald. Repaired fire suspression system. Muffler burnt through pyro line. Carried out 6 monthly inspection.	
15-Feb-13	WMS	4883	$300.00	top up fire suspression system inspected system for leaks.	
14-Feb-13	WMS	4880	$150.00	replaced front step rubber. Fitted wheel chock. Check machine.	
04-Feb-13	WMS	4824	$100.00	window wipers inop, test, there is back feed in power through stick, bypass.	
30-Jan-13	WMS	4792	$200.00	charge up fire suspression & look for leaks, non found.	
29-Jan-13	WMS	4781	$200.00	carry out 250 hr service as per service sheet.	
11-Jan-13	Mark Unwin	4720	$49.50	fit repaired rock ejector to Pos 5/6.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
10-Jan-13	Mark Unwin	4720	$427.50	levered, hammered chiseled at rock stuck in between pos 5 & 6, let pos 6 tyre down to 5psi. Turned bent rockejector around. Slung rock & winched back towards braced rock ejector. Moved truck & winched towards front cross member. Used Andrews ute to pull rock out. Pumped up tyre. Removed rock ejector & have straighten.	
10-Jan-13	WMS		$100.00	removed jammed rock in pos 3 & 4 tyres.	
14-Dec-12	Mark Unwin	4664	$760.00	make up grease manifolds, make up cut hoses, drill manifold bracket & fit fittings to steering joints. Assemble manifolds & hoses to truck steering system & secure hoses & bracket to chassis.	
14-Dec-12	WMS		$445.50	fit up grease systems hose on steering.	
03-Dec-12	Mark unwin	4608	$70.00	adjust rear camera. Inspect pos 6 tyre tread damage. Check a/c. recertify ext. chock missing & bent.	
12-Nov-12	Mark Unwin	4482	$255.00	250hr service on truck less cab and engine air filters, greased truck, replaced secondary fuel filters & bled system, checked hydraulic/coolant/fuel hoses OK, checked intake hoses, performed brake/light/horn tests and checked exhaust system.	No 6/8 head still leaking coolant but level not low so leak is slow, cab filters and fresh air filters due now.
09-Nov-12	Mark Unwin	4465	$255.00	replace steering and hydraulic filters, took engine oil sample, replaced fuel filters and bled system, checked hub and final drive oils OK, checked drive/tensioner pulleys and drive belts OK, checked and adjusted tyre pressures, coolant less from no 6/8 head gasket leaking, checked and regassed air conditioner and cleaned out cab filter.	
08-Nov-12	Mark Unwin	4455	$21.25	Pre-start inspection - low coolant topped up radiator, NO 6/8 head leaking coolant slowly, POS 6 tyre tread damaged slightly.	
04-Nov-12	WMS	4428	$90.00	Repair broken window hinge.	
19-Oct-12	WMS	4353	$45.00	Fit up 2 new wheel chocks	
13-Oct-12	Morgan		$130.00	weekly service. Grease & check noise in drive line, found uni joint out put side of drop box & artic.	
02-Oct-12	WMS	4264	$360.00	Finish off 250hr service	
02-Oct-12	Mark Unwin	4265	$170.00	Changed hydraulic oil and cleaned breather, started and checked fluid levels, adjusted diff oil and swept floor.	
02-Oct-12	Mark Unwin	4265	$255.00	Changed diff oil, left and right final drive oils, drained torque converter, transmission screen cleaned, changed trans filter and refilled with oil, cleaned diff and transmission breathers, replaced small steering filter.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-Oct-12	WMS	4264	$180.00	Carry out 250hr service, oil/fuel/airs and full 250hr service.	
01-Oct-12	Mark Unwin	4265	$531.25	Started 2000hr service eng oil sample, eng oil and filter changed, air filter for engine changed, filled washer bottle, changed fresh air filter for cab, cleaned cab recirculation filter, changed parkbrake release filter, drained torque converter/transmission fluids, changed park brake release filter and cleaned torque converter screen, checked hydraulic hoses/fire extinguishers and fluid levels.	
30-Sep-12	WMS	4264	$90.00	Inspection for hissing sound out of tyre - blown tyre - damage cause unknown.	
27-Sep-12	Mark Unwin	4247	$85.00	Repalced primary fuel filter bay.	
25-Sep-12	Mark Unwin	4237	$170.00	Locate sensor under cab on chassis, fit new o-ring and install a checked fuel tank quick fill breather, filters OK, lubricated and reassembled.	
19-Sep-12	WMS	3851	$135.00	Check brake accumulator fault, check pressures no codes active.	
31-Aug-12	WMS	4104	$95.00	Inspectin, RH bumper damage. Both front tyres have slices. Brake pressure switch weap.	
21-Aug-12	WMS		$95.00	fit up fast fill kit.	
19-Aug-12	Hast/Deering		$150.00	New filters, updated ECM's, cleared codes, drained sediment from tank, replaced steering sensor, fitted step to RHS.	
17-Aug-12	Hast/Deering		$525.00	Reflash all ecm's test machine for fault codes all OK.	
06-Aug-12	WMS		$190.00	Colant leak @ engine, tracked down to heater core hose clamp. Remove, clean & refit new clamp.	
07-Jul-12	WMS		$360.00	Cont 773 build for work.	
06-Jul-12	WMS		$720.00	Assemble 773 ready for work.	
04-Jul-12	WMS		$90.00	Remove of truck + escort truck out.	
07-Jun-12	WMS		$477.50	Load up foot steps, put any other items in rear of tub.Fit up product links	
06-Jun-12	WMS		$170.00	Fit up painted hand rails	
05-Jun-12	WMS		$255.00	Prepare hand rails and paint	
04-Jun-12	WMS		$170.00	Fit up camera rear and in cab and cables.	