Work Order History Report

Asset	W/O No	Description	Finished	Done Reading	
P1259		**Komatsu PC850-8 Excavator**			
	192462	HME Inspection - Excavator Quote #: 8808 hrs	10/04/2026	8808	Hours
	56025	FFP Lake Cowal, - install fire extinguisher in cab - tag and install external extinguisher - replace plant ID LHS of machine- replace carrier rollers x 6 - repair step LHS of machine at rear - fit decals, fuel, 3pt contact - repair rack?cap on exhaust - order parts for stick and bucket - get window washers working - remove stick H link bushes - fit stick and change up - hook up hoses - fit belly guard bolts - start paperwork - zip tie lagging over hoses - Carry out 12 monthly fire suppression and fire extinguisher service on Komatsu PC850 ID P1259	12/02/2026		Hours
	60395	February R&M. Lake Cowal - Tighten bottom A frame bolts - Repair fuel rail switch wiring - Remove stick pins	9/02/2026		Hours
	60026	January R&M - Repair step - 6 MONTHLY FIRE SUPPRESSION TEST/INSPECTION Inspect + Diagnose starting fault, fuel issue Replace fuel filters Replace outer air cleaner Replace leaking engine oil hoses	28/01/2026		Hours

Asset	W/O No	Description	Finished	Done Reading	
		Fill up grease Starting issues, replace fuel rail sensor, prime/test Repair wiring to sensor Remove bucket - Demob			
	59814	Excavator - 250hr service 8808hrs	22/01/2026	8808	Hours
	59432	December R&M Ac fault blocked condensor AC not cold Fuel system pressure malfunction Wash tracks and rollers	17/12/2025		Hours
	58781	November R&M Hand rail repairs Reset fire suppression fault Alternator belts Replaced all belts and tested Diagnose starting fault, remove batteries from P0291 and swap, move digger from bench, replaced all belts and test Replaced batteries	27/11/2025		Hours
	59194	GET - In preparation to change not yet due	18/11/2025		Hours
	58810	Excavator - 500hr service 8429 hrs - 8558 hrs Replace air filter Replaced hydraulic filters Replaced all belts	15/11/2025	8558	Hours
	58172	October R&M - engine re-sample, grease block 02/10 - replace grease injectors, repair grease leaks/faults 08/10 - re-fit grease bank to H-link 11/10 - Hand rail and mirror - Data link error	31/10/2025		Hours
	57312	September R&M: - investigate start fault and repair 09/09 - repair grease leaks 16/09 - fire supp slow leak, top up. Electrical fault 20/09 - fire supp fault 21/09 - grease manually 28/09	28/09/2025		Hours
	57391	Excavator - 4000hr service 8000 hrs - 8127 hrs	14/09/2025	8127	Hours

Asset	W/O No	Description	Finished	Done Reading	
	53275	Excavator - 500hr service 7557hrs	11/06/2025		Hours
	54809	Excavator - 250hr service 7750hrs	13/05/2025		Hours
	53064	Hours: 7313 Attend to starting fault, assess and determine that machine will not crank. -Test start signal and battery supply at starter motor and find present. -Test power at starter primary solenoid in DT2 and find pin 2 from alternator R terminal powered with 24v via IGN inhibiting cranking. -Extensively test and trace back to cabin. -Disassemble cabin trim, locate diode pack 1 and identify faulty diode between pins 2&6 causing power to flow to alternator R terminal. -Replace faulty diode, re-assemble cabin trim. -Test starting and charging, all now OK.	4/03/2025		Hours
	53083	Diagnose grease fault and repair diagnose grease fault pump grease into point remove line and make sure not blocked adjust injector up tell Matt to run system on test mode regularly to see if pin stays greased	21/02/2025	7358	Hours
	51927	Repair bucket. Replace 12 x heel blocks. Use PH stock where possible. (180w x 40mm thick) Gouge off 5 x wear strips, second from the lip working back toward the heel. Weld on CAT GET adapters. #Use PH stock where possible. Fit CAT GET.	1/02/2025		Hours
	51070	Missed invoice from work order 20205** 02/09/2024 Travel to FH Tynong Remove belly plates Loosen of pulleys Tighten alternator belt on engine Check over engine Install belly’s plates back up Change hydraulic filters Travel back to workshop to get oils as I couldn’t get to workshop in morning due to storms Load up oils Travel back to FH Tynong Drain damper drive oil Fill oil back up Start machine and line up final drives Top up oil Pack up from service	2/09/2024		Hours

Asset	W/O No	Description	Finished	Done Reading	
		Clear service codes			
	20205	Excavator - 1000hr service Check over machine Drain all oils for service Change all filters Fill all components with oil Still need to tighten belts	12/08/2024	7071	Hours
	20452	Radio fault - Diagnose and repair -Access machine in pit, wait for machine to stop and make work area accessible - Diagnose faulty AM/FM radio. Remove and replace. Modify mounts and wiring to suit new radio. Test all OK	31/07/2024	7005	Hours
	20203	Easy-out snapped grease fitting on H link. Install new fittings and test Check over machine and top up engine oil Install new nuts on U bolts for stick cylinder pipes Check out belts Check out grease unit and see if it has an overflow	29/07/2024	6974	Hours
	17460	Repair A/C system after compressor failure	14/06/2024		Hours
	50355	Reimbursement of expenses relating to service and repairs completed by PWE Quarry services on equipment hired from MAAS Plant hire Invoice : 00000176	31/05/2024		Hours
	15233	Repaired broken grease lines at the h link pin. Replaced lines and fitting.	22/04/2024	6563	Hours
	14035	Excavator - 500hr service Hours: 6461 Yarra Valley Quarry	13/04/2024		Hours
	13965	Diagnose electrical fault at fuel rail pressure sensor. Removed plug and cleaned Tested ok	5/04/2024	6445	Hours
	12082	Grease unit stopped working, need to travel up & diagnose fault / Inspection of bucket Clean and prep bucket Gouge and grind up cracks Weld cracks and pad weld low wearing area Clean up bucket and pack up area Inspection of excavator found grease lines to be modified or changed	28/03/2024	6347	Hours
	15883	Test grease unit, no pressure at lines Check hydraulic pressure, had pressure on pressure side and no oil returning through motor Remove covers to start disassembling unit Found solenoid was hanging of coil, clean up and brake clean components Install solenoid and nut, test grease unit All working good now, put panels back over grease unit	14/03/2024	6347	Hours
	12627	Visited Site: Yarra Valley Quarries. -Escorted to machine. Assess lighting fault, tests and inspection found wiring harness to be	14/03/2024		Hours

Asset	W/O No	Description	Finished	Done Reading	
		-Escorted to machine. Assess lighting fault, tests and inspection found wiring harness to be damaged on the boom circuit. Repaired wiring - all tested okay. Hours - ??			
	10433	Parts only - bucket teeth. Shipped to Phil Wade Yarra Valley Quarries	5/03/2024		Hours
	9689	Excavator - 250hr service (Parts only)	16/02/2024	6213	Hours
	9258	6000 Hour Service	18/01/2024	6032	Hours
	3695	Disassemble for transport, replace stick pin and bushes	16/11/2023		Hours
	6616	Repair grease lines Recharge fire suppression system	15/11/2023	5768	Hours
	5330	Excavator - 5500Hour service 14.09.2023	14/09/2023		Hours
	4840	Assemble machine onsite	4/09/2023	5340	Hours
	15513	Make new steps and straighten out old steps. Make new handrail and weld up crack on handrail.	5/06/2023		Hours
	1744	Excavator - 1000hr service Defect repairs as listed	3/06/2023	5033	Hours
	1941	Check over defect list, carry out 1000hr service and repair defects	30/05/2023		Hours
	15514	Carry out full checkover.	27/02/2023		Hours