Service History Report for - P205 Komatsu PC1250LC-8

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Sep-22	Shane		$350.00	Fit new injector pipe & re-assemble engine	
02-Sep-22	Shane		$450.00	Continue with repairs to get machine running	
01-Sep-22	Shane		$250.00	Continue with reassembly for more of machine	
31-Aug-22	Shane		$400.00	Fit cooler pack & plumb up	
30-Aug-22	Shane		$400.00	Clean out & flush open hoses & pipes, Start fitting new radiator core to cooler pack	
06-Aug-22	Shane		$350.00	Look up parts for repairs	
04-Aug-22	Jack		$400.00	Fit new bucket teeth	
04-Aug-22	Shane		$550.00	Remove bucket	
04-Aug-22	Shane		$100.00	Remove bucket	
30-Jun-22	Sean	12781	$300.00	R&I pilot pump. C/O fan pump	
30-Jun-22	Rhys	12781	$300.00	R&I pilot pump. C/O fan pump	
28-Jun-22	Sean	12781	$1,000.00	C/O EGR cooler Fit EGR and hoses C/O cooler fan hoses and seal Degrease and wash machine to remove as much dirt and oil as possible Wash down pumps to start removing pilot pump	
28-Jun-22	Shane		$300.00	Hyd fault repairs continued	
27-Jun-22	Sean	12781	$1,200.00	C/O fan motors Remove broken bolts x2 Remove all broken or damaged hoses Reseal fan valves Remove fan and cooler for support frame	
26-Jun-22	Shane	12871	$200.00	Remove cooler pack	
26-Jun-22	Sean	12781	$1,200.00	C/O cooler fan motors	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
11-Jun-22	Lain		$206.25	Filled up hydraulic tanks, after 2 trips to refill our own tanks, refitted hydraulic lines from pumps	
02-Jun-22	Lain		$495.00	Bled up hydraulic pumps Pumped more oil into it	
31-May-22	Shane		$800.00	Continue cleaning lines, hoses, filter housing, tank etc Fit new pumps and plumb up	
29-May-22	Shane		$200.00	Continue cleaning hyd tank	
28-May-22	Shane		$450.00	Flush out / clean hyd tank and suction pipes	
24-May-22	Shane		$100.00	Check over and grease bucket pins Finalise parts orders and organise freight	
20-May-22	Shane		$400.00	Ordering hydraulic system parts Chasing info for hydraulic system repairs	
			$150.00	Continue with hyd diagnosis. Order parts	
18-May-22	Shane		$250.00	Hydraulic system faults	
15-May-22	Lain		$82.50	Refit new GET pin from tooth Tension pin bolts on bucket	
15-May-22	Lain		$82.50	Greased Machine inspection Topped up hydraulic oil tank	
02-May-22	Shane		$250.00	Remove panels and set up for testing pumps.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
12-Apr-22	Shane O		$100.00	Check over machine for oil leaks, oil leaking from several different hyd connections, need O'ring kits to repair. Check cooler pack for signs of over heating. Hosed it down and clened off the remaining oil.	
09-Apr-22	Harry D		$110.00	Cut down wear plates to 210mm	
08-Apr-22	Lain	12782	$82.50	Messure GET, inspected machine for site repairment.	
03-Apr-22	Lain		$660.00	Fitted bucket to the stich of the machine then fitted steps, railings,exhaust, grease lines and hooked up trimbel wiring	
02-Apr-22	Lain		$701.25	Unloaded stick, bucket and counter weight fom transport vehicle Installed counter weight to machine Went down to site to help unload Hilux and crew van. Went back and lifted cross member beams onto transport float then fitted stick and hoses to machine	
01-Apr-22	Lain	12771	$288.75	Helped unload machine off transport and inspected	
28-Mar-22	Harry		$63.25	Welded buttons onto tooth holder	
01-Mar-22	Zumbo		$467.50	diagnose hyd fault for boom creep to boom low spool, Remove spool and inspect no major signs of damage, remove counter weight from rear for transport.	
18-Feb-22	Zumbo		$88.00	Fit guards and covers.	
17-Feb-22	Zumbo		$88.00	Set up to charge batteries Set up container fork to hold boom for testing	
27-Jan-22	Zumbo		$44.00	Set up clams to hold boom	
18-Jan-22	Sebastian		$88.00	Fit guards & covers	
06-Dec-21	Zumbo		$176.00	remove air compressor, clean and package.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
17-Sep-21	Zumbo		$220.00	Install harmonic balance Electrical fault Install counterweight Fill coolant Move fire suppression bottle	
17-Sep-21	Connor		$82.50	Fitted counterweight	
17-Sep-21	Komatsu		$0.00	Check & adjust the control pressure after the new valve was installed.	
17-Sep-21	Komatsu		$0.00	Press the oil seal into the front housing Press the dust seal in Install the balancer - tighten to spec	
17-Sep-21	Greg Mills		$55.00	Fit counterweight	
16-Sep-21	Harry H		$151.25	Gave Zumbo a hand to put track guide on Did not end up fitting Replaced mirror	
16-Sep-21	Connor		$453.75	Scrapped old MAAS stickersw off counter weight Check all guard bolts had antisieze on them Fitted gauge to fire extinguisher cylinder Put new connectors to grease unit Fitted fire extinguisher (9kg) Assisted Zumbo with changing water pump hose	
16-Sep-21	Komatsu		$0.00	7.5 hours all up (2 days) Remove the balancer from the front of the engine Remove the dust seal & remove the oil seal Clean the front cover	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Sep-21	Ted Van		$27.50	Pre-Hire Inspection	
15-Sep-21	Greg Mills		$55.00	Remove counterweight	
15-Sep-21	Connor	12754	$536.25	Assisted loading stick & bucket on float to go to site Tapped out bolt holes for track guide to be mounted Re-wired auto greaser from constant power to power when ignition is engaged Filled up greaser	
14-Sep-21	Harry H		$137.50	Removed bucket and stick	
14-Sep-21	Clay Bennett	12754	$137.50	Assist removing bucket & stick from boom	
14-Sep-21	Greg Mills		$110.00	Remove bucket & stick	
14-Sep-21	Zumbo		$55.00	Cut gusset & start to heat to bend track guide	
14-Sep-21	Komatsu		$0.00	16.50 hours all up (3 days) Remove covers Install testing equipment Bring the machine up to working temp Carry out PM inspection Adjust pressures that were low and bring them up to spec The control pressure could not be brought up to spec and the valve was fully adjusted Look up and order a replacement valve Remove testing equipment	
13-Sep-21	Zumbo		$467.50	Assemble stick & bucket Install counterweight Install guards & covers Install track guide	
13-Sep-21	Connor	12754	$398.75	Assisted Greg & Zumbo putting stick on Collected all guards & doors Assisted with installing counterweight Fitted all guards	
13-Sep-21	Clay Bennett	12754	$343.75	Assist putting bucket & stick on Fit guards to machine	
13-Sep-21	Greg Mills		$550.00	Fit stick, bucket and counterweight Fit guards	
10-Sep-21	Clay Bennett		$316.25	Wash machine	
10-Sep-21	Zumbo		$357.50	Remove & replace 2 leaking hoses Rewire boom lights, make new harness Pressure wash	
09-Sep-21	Zumbo		$302.50	Install track guides and tension tracks Move to wash bay. Try to fix electrical faults Tidy up	
08-Sep-21	Greg Mills		$275.00	Fit boom to machine Check stick bushes Clean up burrs	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Sep-21	Zumbo		$577.50	Install boom & shim Install boom arch housing Clean out cab & install UHF Install track guide & start thread repair	
06-Sep-21	Zumbo	12754	$55.00	Replace batteries	
01-Sep-21	Connor M		$82.50	Change fuel filter Assisted Zumbo with hydraulic tank leak	
31-Aug-21	Clay Bennett	12754	$68.75	Sand repair work Work on counterweight Prime & paint	
31-Aug-21	Connor M		$55.00	Painted repair work on boom	
18-Aug-21	HarryDimmock		$467.50	Bucket 7 weld numbers and letters on bucket (MAAS B7) Found more cracks in bucket Welded shin guard brackets on bucket	
17-Aug-21	HarryDimmock		$591.25	Bucket B7 started to weld up crack on floor plates Bucket B7 - finish off welding up cracks on floor and sides Welded on new chock bars	
06-Aug-21	DaveMarshall		$55.00	Repairs to stick	
13-May-21	Sebastian	12754	$55.00	Remove air horn valve.	
10-May-21	Sebastian	12754	$137.50	Mount stick on frame Inspect grease system and repair Bleed grease lines Clamp & zipties lines	
03-May-21	Sebastian	12754	$522.50	Install PTO pump drive & tension. Install new front & rear engine mounts Install firewall & some hosing. Install grease reel to battery bay.	
23-Apr-21	Connor	12754	$522.50	Fitted grease drum / tested to see if worked Scrapped of existing reflective stickers on boom for painting	
23-Apr-21	Sebastian	12754	$247.50	Install harmonic balancer and tension. Install flywheel and tension. Install drive plate and coupler and tension.	
22-Apr-21	Sebastian	12754	$165.00	Remove front crank seal and clean crank front and rear.	
21-Apr-21	Harry		$275.00	Finish putting solenoid on Putt batteries back Hand rails on, stickers on, painted tow points	
21-Apr-21	Sebastian	12754	$110.00	Tap and repair thread, install and torque frame bolt with torque multiply.Remove plant ID decal front of cab.	
20-Apr-21	Harry		$522.50	Removed solenoid Put stickers on Cleaned battery box Re-crimped electrical wires	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
20-Apr-21	Sebastian	12754	$550.00	Straighten panels Finish mounting & paint isolator panel Mount isolators and e-stops Remove broken bolt main frame.	
20-Apr-21	DaveMarshall		$385.00	Repair counter weight and boom Remove broken bolts	
19-Apr-21	DaveMarshall		$220.00	Side of counter weight	
19-Apr-21	Harry		$247.50	Cleaned battery box Started to take a solenoid off near battery box	
19-Apr-21	Connor	12754	$110.00	Tidy up wiring Clean battery box	
19-Apr-21	Sebastian	12754	$275.00	Replace seals in swing valve as required. Replace O-rings in solenoid block. Remove clean & reseal metal screens in hyd valves. Straighten belly guards Straighten lower rock guards Make new mount for isolators & e-stop.	
17-Apr-21	Connor	12754	$82.50	Put reflective stickers on	
16-Apr-21	Connor	12754	$467.50	Covered wires with conduit Identified fuel hose leak	
16-Apr-21	Clay Bennett	12764	$481.25	Sand & paint handrails / steps green Do P clamps up around conduit Fit stairs on	
16-Apr-21	Zumbo	12754	$275.00	Reseal relief valves Finish installing rocker covers & guards on top of engine Mix paint for hand rails & steps	
15-Apr-21	Zumbo	12754	$550.00	Assemble cylinder extension housings Install extension housing & overhead gear Carry out valve set Clean up around machine	
15-Apr-21	Connor	12754	$522.50	Covered wires in conduit Identified any wiring that needed repairing Topped up front swing box Fitted fuel cooler Assisted Zumbo fitting fly wheel for valve set	
15-Apr-21	Clay Bennett	12764	$68.75	Tighten P clamps up.	
14-Apr-21	Clay Bennett	12764	$110.00	Fit hydraulic hose & fill front swing box	
14-Apr-21	Zumbo	12754	$522.50	P-Clamp fuel lines & tighten fittings Install swing box drain Remove fuel cooler for repair Install & hose hyd tank	
14-Apr-21	Connor	12754	$522.50	Covered wires with conduit Topped up rear swing box Filled up front swing box Removed return swing box hydraulic hose Fitted hydraulic tank (Assisted Zumbo) Clamped up remaining fuel lines	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
13-Apr-21	Greg Mills		$385.00	Reseal & assemble boom cylinders	
13-Apr-21	Connor	12754	$522.50	Fitted new hydraulic hoses from Stevo's Re-fitted air intake line Fitted air intake mounts Filled up engine with engine oil Filled up radiator	
13-Apr-21	Zumbo	12754	$522.50	Install boom cylinder rods Finish cleaning extension housing Try removing broken butts Install air intake	
12-Apr-21	Clay Bennett	12764	$192.50	Replace filters, 3 seals on tank, clear suction hydraulic screen. Fill rear swing box	
12-Apr-21	Zumbo	12754	$522.50	Mark off freight Remove valve covers Remove overhead gear Remove valve extension covers & clean Look up parts	
12-Apr-21	Connor	12754	$247.50	Went through parts received Changed fuel filters Changed engine oil filters Changed inner & outer air filters Changed cab air filters	
10-Apr-21	Connor	12754	$110.00	Seg tied hoses from wiring	
08-Apr-21	Zumbo		$522.50	Remove broken bolts track frame Remove damaged hyd hoses for replacement Clean up rear engine mounts	
08-Apr-21	Clay Bennett		$495.00	Refit filter housings on hydraulic tank & reseal Pull fuel hose out Sleeve and reseal Assist Zumbo with broken undercarriage bolt Clear around undercarriage bolts Pull old hydraulic hose off Refil cat cap kit	
07-Apr-21	Zumbo	10754	$522.50	Lift hyd tank & move for cleaning Clean of hyd tank & internal Remove balancer Order parts Assemble & install oil cooler housing	
06-Apr-21	Zumbo	10754	$440.00	Remove pump drive Remove water pump Remove & clean oil cooler housing Try to remove harmonic balancer Supervision	
06-Apr-21	Clay Bennett		$426.25	Disconnect everything of hydraulic tank for cleaning	
01-Apr-21	Connor	12754	$467.50	Wired up E-Stops Sleeved hoses Put new starter isolator in	
01-Apr-21	Clay		$316.25	Sleeve & fit fuel lines	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-Apr-21	Zumbo	10754	$481.25	Remove firewall from pump housing Remove pump drive housing hoses Seal all pumps for cleaning Make supports for engine to remove pump drive Supervise apprentices	
31-Mar-21	Clay		$440.00	Take out boom cylinder Sleeve fuel hoses	
31-Mar-21	Connor		$481.25	Removed second lifting cylinder for re-sealing Removed damaged boom hoses to be replaced Crock sleeved remaining boom hoses Crock sleeved lifting cylinder hoses Helped Clay with fuel lines	
31-Mar-21	Zumbo	10754	$522.50	Remove LHS lift rod Mark & remove all hyd hosing to pumps Remove all pumps	
30-Mar-21	Connor	12754	$330.00	Inspect for any leaks Removed travel motor cover Drained final drives Removed boom hoses to be replaced Removed lifting cylinder to be resealed Charged batteries	
30-Mar-21	Clay		$275.00	Inspect any leaks, take or travel cover motor, drain & fill final drive Take out boom cylinder	
30-Mar-21	Zumbo	10754	$192.50	Check over when running Order more parts Remove travel motor covers Remove RHS lift cylinder rod	
25-Mar-21	Zumbo	10754	$275.00	Complete parts & defect list	
24-Mar-21	Zumbo	10754	$522.50	Remove covers, guards ready for cleaning Try to diagnose electrical problem Start repair list & parts list	
23-Mar-21	Zumbo	10754	$247.50	Remove boom	
23-Mar-21	Clay		$220.00	Disconnect hydraulic boom lines	
18-Dec-20	Ted Van		$82.50	Unload stick & bucket	
11-Dec-20	Greg Mills	12750	$220.00	Remove bucket, Stick & handrail	
25-Nov-20	Will Paull		$82.50	Layout engine harness (wrong one) Fit EGR valve	
30-Sep-20	Greg M	12507	$55.00	Diagnose greaser fault.	
29-Sep-20	Greg M	17565	$110.00	Fit goanna bars, fit tooth, weld up lip shroud retainer, fit lip shroud. Fit fuel primer switch.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Sep-20	Greg Mills	12456	$55.00	Repair hyd leak	
03-Sep-20	Greg Mills	12450	$82.50	Carry out engine service.	
26-Aug-20	Ted		$55.00	Organise parts.	
24-Aug-20	Ted		$82.50	Assist with diagnosis of electrical fault.	
21-Aug-20	Ted		$247.50	Assist with diagnosing electrical fuel solenoid fault	
14-Jul-20	Greg	12305	$302.50	Replace bucket cylinders	
08-Jul-20	Greg		$440.00	Disassemble & assemble cylinders with new seals	
07-Jul-20	Greg	12261	$82.50	Carry out service	
19-Jun-20	Greg M		$275.00	Disassemble bucket cylinder - couldn't get piston off.	
25-May-20	Greg Mills	12003	$110.00	Carry out engine service, check hyd fault.	
01-Apr-20	Greg		$165.00	Replace bottom lift cyl pins	
31-Mar-20	Greg		$165.00	Replace LH idlre Fit lip shroud retainers	
20-Mar-20	Greg	11608	$467.50	Find leak in ac system Remove hose try to get new one Replace o rings on boom piping	
18-Mar-20	Greg	11608	$467.50	Guards Fit bucket Repair A/c	
17-Mar-20	Greg	11608	$550.00	Replace & repair broken grease lines Fit all belly guards	
16-Mar-20	Greg	11608	$247.50	Presss in stick & h link bushes	
05-Mar-20	Greg		$467.50	Get machine runnings Cut out & replace stick & H-link bushes	
04-Mar-20	Greg	11608	$577.50	Finish off manifold Replace hyd hoses	
03-Mar-20	Greg	11608	$715.00	Replace exhaust manifold Replace hyd hoses	
02-Mar-20	Greg	11608	$440.00	Remove exhaust manifold	
28-Feb-20	Ted		$27.50	Complete assembly of swivel valve	
26-Feb-20	Ted		$165.00	Clean , strip & reseal swivel valve/block Match up o-rings for fitters & replace Order end cap o ring	
21-Feb-20	Greg		$385.00	Fit remaining hoses Fit new suction lines	
20-Feb-20	greg		$577.50	Continue removing & replacing hoses Remove swivel from machine	
18-Feb-20	Greg	11608	$687.50	Replace leaking hoses	
13-Feb-20	Greg Mills		$323.00	Sorting out parts for the following week	
08-Mar-19	Matt		$363.00	check coolant levels. Blow out radiater and coolers	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
02-Dec-18	Duncan	10709	$453.75	250hr service.	
26-Jun-18	Matt	10389	$408.38	Check wiring on auto grease.	
12-Jun-18	Matt		$181.50	Repair wires on valve.	
30-May-18	Matt	10268	$272.25	Remove and replace teeth .	
17-Apr-18	Matt		$90.75	Find hyd leak	
29-Mar-18	Swanling		$544.00	Change oil in engine Change hydraulic hoses in pump	
09-Mar-18	Matt	9868	$266.88	R+R	
08-Mar-18	Matt	9864	$363.00	Blow out radiator and coolers.	
07-Mar-18	Matt	9859	$816.75	Replace hoses on motors. Remove and replace 6 hoses on left hand joy stick.	
07-Mar-18	Matty	9859	$816.75	Replace 6 loses on left hand joy stick. Refit belly plates	
06-Mar-18	Matt		$181.50	Remove belly plate to remove hydraulic hose.	
15-Jan-18	Matt	9526	$952.88	Carry out 500hr service. Assist boil maker in replacing tooth retainer.	
19-Dec-17	Mathew	9450	$195.00	Find oil leak under cab. Remove guards, remove hose, replace hose. Refit guards.	
13-Dec-17	Swanling	9406	$130.00	Tighten bolts on bucket. Reattach GPS cable on stick.	
07-Dec-17	Swanling	9341	$130.00	Fit wear plate to bucket. Top up auto greaser.	
01-Dec-17	Swanling	9334	$97.50	Remove and replace 4 teeth on bucket.	
22-Nov-17	Swanling		$130.00	Remove and replace hydrolic hose on boom arm.	
20-Nov-17	Swanling		$65.00	Grease bucket. Tighten bolts on bucket.	
27-Oct-17	Swanling	9187	$816.75	Remove and replace CAR cooler	
25-Oct-17	Swanling	9167	$272.25	Digger wont start. Remove engine, check fluid leaks	
24-Oct-17	Swanling	9162	$272.25	remove and replace hydraulic hose	
22-Oct-17	Swanling	9155	$136.13	Change wear platefrom left of bucket to right, fit 2 new wear plate to bottom of bracket	
18-Oct-17	Swanling	9122	$363.00	Remove belly plates, remove hydraulic hose, refit hose and belly plate	
30-Sep-17	Swanling	9083	$589.88	Fit boom stick and bucket to digger	
30-Sep-17	Swanling	9083	$544.50	Ìnstall stick to boom, stick to C/C and buck to stick	
29-Sep-17	Swanling	9082	$45.38	Fit hand rails, fit exhaust stack	
23-Sep-17	Swanling	9082	$226.88	Remove hand rail near cab, reposition across gate	
14-Sep-17	Greg Mills	9079	$355.50	Repair lights. Help load machine. Check over machine.	
14-Oct-16	Greg Mills		$65.00	Weld pin on bucket	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
22-Sep-16	Greg Mills	8824	$552.50	Remove stick, remove lift cylinders, remove hoses from boom, repair grease leak on stick	
21-Sep-16	Greg Mills	8824	$195.00	Remove bucket wash down bucket	
15-Sep-16	Greg Mills	8770	$130.00	Swap around bucket teeth. Carry out 250hr service as manufacturer recommends.	
14-Sep-16	Greg Mills	8766	$130.00	Replace greaser, pick up parts for greaser.	
09-Sep-16	Greg Mills		$130.00	Repair greaser.	
08-Sep-16	Greg Mills	8732	$195.00	Fit new wear plates. Repair greaser.	
07-Sep-16	Greg Mills		$65.00	Grease and check over.	
26-Aug-16	Greg Mills	8651	$65.00	Replace bucket teeth	
25-Aug-16	C Ford		$531.00	Weld repairs	
19-Aug-16	Greg Mills	8600	$97.50	Replace grease pot repair grease lines	
18-Aug-16	Greg Mills		$130.00	Repair greaser replace wear plates	
18-Aug-16	Greg Mills	8597	$130.00	Finish off service, weld up grease block	
10-Aug-16	Greg Mills	8529	$32.50	Replace hyd hose.	
09-Aug-16	Greg Mills	8524	$32.50	Replace 3x lip protectors.	
08-Aug-16	Greg Mills		$32.50	Replace fuel filters, air cleaner, cub filters. Fill auto greaser, fit 2x wear plates.	
05-Aug-16	Greg Mills	8491	$65.00	Replace bucket teeth	
03-Aug-16	Greg Mills		$195.00	repair manual greaser.	
21-Jul-16	Greg Mills		$35.00	Repair auto greaser pressure switch	
21-Jul-16	Greg Mills		$35.00	Replace leaking hyd hoses.	
16-Jul-16	Power Intern		$2,274.49	Replace faulty compressor & service air con system as required	
06-Jul-16	A Warren	8302	$429.00	Changed out bucket teeth Changed out bucket side shroud, had to cut down shroud to fit properly Greased & checked over machine Replaced grease nipples that wouldn't take grease	
02-Jul-16	Power Intern		$294.80	Check air con system & trace fault to leak on high side fitting on rear of compressor	
21-Jun-16	A Warren		$71.00	Top up hyd oil Replaced grease handle Greased machine	
14-Jun-16	A Warren	8148	$107.00	Complete site paperwork Unload remaining tooling, caps & slings & clean	
11-Jun-16	A Warren	8148	$71.50	Unload & clean tooling Removed escort sign from ute	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
10-Jun-16	A Warren	8148	$1,072.00	Drove to site Reassembled digger Changed out old perished hoses on boom, stick & pump room Had to drive to ENZED to pick up hose Tested machine Drove back to Dubbo	
10-Jun-16	Dane.L	8148	$650.00	Assemble, replace hoses. Watch operation. All, Ok.	
09-Jun-16	Dane.L	8148	$877.50	Travel, unload. Start assembly.	
09-Jun-16	A Warren	8148	$965.00	Escort Russell to site Remobilise P205 on site Travel to accommodation	
08-Jun-16	A Warren	8148	$715.00	Escort Russell from Condobolin to Canberra	
07-Jun-16	A Warren	8148	$929.00	Drive from Dubbo to Mineral Hill Demobilise P205 Escort Russell to Condobolin from Mineral	
07-Jun-16	Dane.L	8148	$617.50	Disassemble machine, load on to trucks.	
06-Jun-16	A Warren	8148	$143.00	Get tooling & equipment ready for repairs at Mineral Hill & Canberra	
01-Jun-16	C Ford		$62.00	Weld repair	
01-Jun-16	A Warren	8148	$286.00	Repaired grease system Made up new steel lines	
31-May-16	A Warren	8148	$71.50	Look up parts seals for stick & 'h' link Found parts in shed	
30-May-16	G Wykes		$312.00	Repair & remount steps	
30-May-16	Ted Van		$260.00	Swap buckets	
27-May-16	A Warren	8148	$71.50	Make up & paint stick frame with Fordy & Dan e	
26-May-16	Dane.L	8148	$455.00	Continue disassemble clean look for weeping hoses.	
26-May-16	A Warren	8148	$160.00	Lookup & order parts/hoses Clean up tooling & put back on shelf in workshop	
25-May-16	Dane.L	8148	$390.00	Dissasmble. Fit hoses.	
25-May-16	A Warren	8148	$500.00	Remove bucket, stick, guard rails, GPS, exhaust & intake hats Remove all centreweight bolts Fitup 4 bolts with 3/4 bar Checkover & report faults	
24-May-16	A Warren	8148	$482.00	Organise parts & tooling for repairs Replaced hoses & pipes in pump room Started machine & walked to stripdown site Removed bucket	
23-May-16	Ted Van		$162.50	Remove broken bolt and clean up pipe ready for re-use. Organise parts for mineral hill.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
19-May-16	Ted Van		$292.50	Walk machine to stock pile set up boom/stick for blown hoses change out. Replace cab filters top up gas in a/c system order parts	
18-May-16	Ted Van		$32.50	Bleed fuel systen	
17-May-16	Ted Van	8130	$130.00	Reseal leaking fittings at pump bay cap off broken grease line and fit nipple	
16-May-16	Ted Van	8129	$325.00	Walk back to compound, remove seat, replace seat base cushion, repair broken seat riser replace inner air filter replace faulty gps bucket sensor cable.	
11-May-16	Ted Van		$97.50	Locate spare GPS bucket sensor, make up new bucket sensor cable	
06-May-16	Ted Van	8094	$32.50	Remove GPS cable	
04-May-16	Ted Van	8084	$520.00	Walk digger back. Change final drive oils, change slew box oils. Change pump drive box oil. Replace 3 small wear plates. Remove front pin due to broken tear drop. Reseal leaking hoses.	
03-May-16	Ted Van		$32.50	Check GPS cables and sensor	
22-Apr-16	Ted Van	8020	$162.50	Top up hydraulic oil top up coolant drain excess coolant from over flow bottles. Remove broken hose from autogreaser circuit at boom/stick knuckle, make new hose at pybar and fit.	
21-Apr-16	Ted Van	8020	$32.50	Clean contacts on auto greaser solenoid and start refilling with grease.	
21-Apr-16	Ted Van	8020	$32.50	Clean contacts on auto greaser solenoid and start refilling with grease	
20-Apr-16	Ted Van	8014	$292.50	Change engine oil and filters. Out and inner air filters, fuel filters and replace leaking fitting at auto greaser. Repair auto greaser wiring.	
20-Apr-16	Ted Van	8014	$292.50	Change engine oil, filters. Outer air filter and fuel filters, replace leaking fitting in auto greaser circuit repair auto greaser wiring.	
19-Apr-16	Ted Van	7996	$162.50	Repair broken/damaged grease lines, Replace GET	
19-Apr-16	Ted Van	7996	$162.50	Repair broken/damaged grease lines, replace GET	
18-Apr-16	Ted Van	7995	$130.00	Clean airways in cab, replace both blocked cab filters, top up a/c gas. Check for leaks.	
18-Apr-16	Ted Van	7995	$130.00	Clear airways in cab, replace both blocked cab filters, top up a/c gas. Check for leaks. Repair leaking auto greaser fitting.	
07-Apr-16	Ted Van	7960	$97.50	Replace leaking hoses at pump bay	
04-Apr-16	Ted Van	7960	$292.50	Remove cover, tighten hose clamps @ leaking suction hose, refit fallen LH track and adjust. Walk to compound for boily work.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
23-Mar-16	Greg Mills	7917	$130.00	4x wear plates replace teeth turn cheak protectors had to be cut to make fit.	
22-Mar-16	Greg Mills	7913	$130.00	Replace hyd hose	
21-Mar-16	Greg Mills	7896	$65.00	Swap around bucket teeth and change wear plates.	
16-Mar-16	Greg Mills		$130.00	Auto greaser fault. Found no air going to greaser. Puller apart electronic shut off valve. Found to be very dirty. Cleaned out and assembled and fitted to grease tested ok.	
11-Mar-16	Greg Mills		$130.00	Repair grease leak. Fit wear plates and lip protectors.	
07-Mar-16	Greg Mills	7817	$32.50	Fit wear plates	
03-Mar-16	Greg Mills		$487.50	Clean out a/c evaporator replace grease nipples replace bucket teeth	
29-Feb-16	Greg Mills		$65.00	Repair grease handle	
25-Feb-16	Ted Van	7744	$162.50	Repair GPS bucket sensor cable and swap out	
24-Feb-16	Ted Van	7726	$32.50	Blow out filters and bleed grease system	
22-Feb-16	Ted Van	7706	$195.00	Resecure bucket sensor GPS cable. Still intermittentl dropping out, clean connections no good. Replace with spare cable. Resecure cables (work between loads.)	
19-Feb-16	Greg Mills		$65.00	Remove track guide	
17-Feb-16	Greg Mills	7684	$97.50	Replace blown hose, top up hydraulic oil.	
16-Feb-16	Greg Mills	7682	$32.50	Replace wear plate and grease nipple	
16-Feb-16	Greg Mills	7864	$97.50	Remove blown hose.	
12-Feb-16	Ted Van	7640	$32.50	Replace 2x wear plates	
12-Feb-16	Ted Van	7639	$65.00	Replace cab filters and top up a/c	
12-Feb-16	Ted Van	7636	$32.50	Replace wear plate	
09-Feb-16	Ted Van	7629	$260.00	Replace fuel return hose, replace worn alt/ A/c belt.	
21-Jan-16	Greg Mills	7614	$32.50	Replace wear plate	
21-Jan-16	Greg Mills	7641	$32.50	Replace bucket teeth	
20-Jan-16	Greg Mills	7597	$32.50	Fit lip protector.	
19-Jan-16	Greg Mills	7595	$65.00	Fit new batteries	
18-Jan-16	Greg Mills	7585	$162.50	Jump start machine on bench. Top up gas in a/c. clean cab filters and air cleaners. Join fuel hose. Hose to hard.	
15-Jan-16	Ted Van	7551	$390.00	Replace GET, Travel to Albert to pick up new compressor return and fit. Replace recever dryer blow out lines Vac down and charge.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
14-Jan-16	Ted Van	7550	$390.00	Blow out a/c filters. Check pressures. Top up gas. Return to check again, found a/c belt u/s remove belt off	
11-Jan-16	Ted Van	7484	$357.50	Remove covers, check for oil leaks. Make up and replace 3 hoses to PPC valve reseal travel motor pipe at rotating valve	
11-Jan-16	Ted Van	7478	$65.00	Jump start replace GET	
08-Jan-16	Greg Mills	7481	$130.00	Carry out 500hr service as manufacturer recommends	
07-Jan-16	Greg Mills	7461	$32.50	Swap bucket teeth around	
06-Jan-16	Greg Mills	7441	$390.00	Replace lip shroud plate replace 2x lip shrouds. Fit new grease gun handle check over machine	
23-Dec-15	G Wykes		$187.56	Fit new steps	
22-Dec-15	G Wykes		$390.75	Fabricate new steps	
16-Dec-15	Ted Van	7404	$65.00	Check no a/c. Clean out cab filters. Check pressures	
15-Dec-15	Ted Van	7387	$65.00	Replace worn GET. Replace blocked air filter.	
14-Dec-15	Ted Van		$32.50	Replace shin guard pin and retainer	
11-Dec-15	Greg Mills	7353	$130.00	Trying to repair GPS	
09-Dec-15	Ted Van		$32.50	Repair GPS cable.	
07-Dec-15	Greg Mills	7288	$130.00	Check a/c. Diagnose GPS fault.	
04-Dec-15	Tec Van	7287	$162.50	A/c reports to have failed, check all ok. Blow out evaporator replace missing adaptor on bucket replace GET.	
04-Dec-15	Tec Van	7284	$65.00	Check a/c system regas blow back coolers clean out cab filters	
04-Dec-15	Tec Van	7282	$32.50	Replace GET.	
27-Nov-15	G Wykes		$62.52	Repair handrails	
27-Nov-15	Greg Mills		$65.00	Gas up a/c diagnose fault with a/c.	
27-Nov-15	Greg Mills		$162.50	Fit new track motor hoses, fit covers.	
26-Nov-15	Greg Mills	7190	$325.00	Remove final drive hoses, clean out track frame.	
25-Nov-15	Greg Mills		$260.00	Repair GPS, Diagnose blown hose, blank off hose, pump 200L of hydraulic oil into machine, move machine away from blast area.	
24-Nov-15	Greg Mills	7171	$65.00	Replace circuit breaker, diagnose and repair GPS, take to pit.	
23-Nov-15	Greg Mills	7171	$390.00	Fit front slew motor, grease machine, replace bucket teeth, replace 5x wear plates.	`
21-Nov-15	Ted Van		$130.00	Rebuild front slew drive box assy. Clean up	
21-Nov-15	Ted Van		$130.00	Rebuild front slew drive box assy. Clean up bay	
20-Nov-15	Ted Van		$390.00	Rebuild front slew drive box	
20-Nov-15	Ted Van		$390.00	Rebuild front slew drive box.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
18-Nov-15	Greg Mills		$617.50	Disassemble slew motor, clean up all parts	
18-Nov-15	C Ford		$62.52	Remove bearing off shaft	
17-Nov-15	Greg Mills		$520.00	Diagnose slew fault found front slew motor to have metal on the dip stick, take machine from pit to go line, remove front slew motor disassemble slew motor found planetry failed assemble slew motor load up dravel to dubbo	
16-Nov-15	Greg Mills		$32.50	Swap bucket teeth around.	
12-Nov-15	Greg Mills	7127	$32.50	Replace bucket teeth	
11-Nov-15	Greg Mills	7095	$487.50	Continue with diagnosing electrical fault, snapped realys. Found faulty circuit breaker. Jump started machine, all codes went away. Put panels back onto cab.	
10-Nov-15	Greg Mills	7095	$390.00	Repair wiring to horn, machine wouldn't start. Diagnose fault with start circuit.	
09-Nov-15	Greg Mills	7067	$130.00	Replaced hoses for stick cylinder.	
06-Nov-15	Ted Van	7066	$97.50	Repair wiring to horn. Check a/c- top up gas.	
06-Nov-15	Ted Van	7067	$162.50	Build up pad next to boom, remove 2x u/s hydraulic hoses ro dipper cylinder.	
05-Nov-15	Ted Van	7053	$162.50	Refit EGR pipes, guards. Run ant test, top up coolant. Refit Belly plates.	
04-Nov-15	Ted Van	7052	$227.50	Replace o-rings on thermostat connecting pipe, reclean surfaces and refit thermostat. Fill coolant and check for leaks start refitiing EGR pipes and covers	
03-Nov-15	Ted Van	7052	$520.00	Refit EGR pipes and supports, refit cooling pipes, remove broken bolts. Refill coolant. Thermostat leaking. Remove EGR pipes and supports, remove thermostat found connector pipe. u/s o-rings, organise parts.	
02-Nov-15	Ted Van	7052	$617.50	Remove covers, Remove water pump and thermostat housing, clean up parts, replace thermostats and seals, refit thermostat housing and water pump.	
30-Oct-15	Greg Mills	7043	$65.00	Check coolant leaks, clean cab filters.	
29-Oct-15	Greg Mills	7040	$260.00	Diagnose GPS fault, found broken cable	
28-Oct-15	Greg Mills	7040	$357.50	Carry out 1000hr service, replace engine oil, filters, fuel filters, inner and outer air cleaners, pilot filters, hydraulic filters, clean cab filters and check over.	
27-Oct-15	Greg Mills	7035	$227.50	Clean out plugs on gps cables. Wash out radiator, adjust fan, test.	
26-Oct-15	Greg Mills	7023	$65.00	Wash out radiator.	
26-Oct-15	D.O'leary	7017	$130.00	Change out wear plates, Check GPS.	
23-Oct-15	Ted Van	7003	$214.50	Replace pins on side get, replace small wear plates remove small plates off spare bucket	
23-Oct-15	Ted Van	7003	$32.50	Replace small wear plate	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
23-Oct-15	Ted Van	7003	$65.00	Replace GET	
19-Oct-15	Ted Van	6919	$162.50	Replace GET. Clean engine breather. Clean mud/dust from engine bay floor. Check auto greaser operation.	
10-Oct-15	josh Hewett		$32.50	Adjust up park brake	
09-Oct-15	Greg Mills	6844	$32.50	Gas up a/c	
09-Oct-15	Greg Mills		$32.50	Replace wear plates.	
07-Oct-15	Greg Mills	6820	$260.00	Find leak in a/c, tighten up bolts in bucket pin. Check seat, check over machine.	
07-Oct-15	G Wykes		$125.00	Repair track frame guides	
06-Oct-15	Greg Mills	6799	$65.00	Gas up, check a/c	
02-Oct-15	A Warren	6790	$286.00	Weld up lip shroud retainer. Fuel up & grease. Top up a/c system & test	
01-Oct-15	A Warren	6804	$214.50	Weld up lipshroud retainer	
30-Sep-15	A Warren	6756	$143.00	Checkover & grease. Completed 250hr service, Replaced air filters	
30-Sep-15	Josh Hewett		$32.50	5th to 6th gear slipping go for run	
28-Sep-15	A Warren		$71.50	Checkover & grease. Top up oils	
25-Sep-15	Ted Van		$325.00	Fuel/grease. Reverse blow coolers, blow out filters. Recharge a/c system.	
24-Sep-15	Greg Mills		$32.50	Fuel and grease machine	
24-Sep-15	Ted Van	6680	$195.00	Check + clean all gps connections	
23-Sep-15	Greg Mills		$32.50	Fuel and grease machine.	
22-Sep-15	Greg Mills		$65.00	Change out bucket teeth, change out grease pot.	
22-Sep-15	Ted Van	6636	$65.00	Grease and replace missing/broken GET, refill auto greaser, blow out engine air filter.	
21-Sep-15	Ted Van	6622	$97.50	Tie back gps screen pole with cable ties. Repair faulty wiring to auto greaser. Blow out cab and cab filters. Check a/c. Top up gas	
21-Sep-15	Greg Mills	6628	$195.00	Clean up and weld on new lip protector mount. Remove GPS screen pole weld up and refit.	
20-Sep-15	Greg Mills	6616	$195.00	Swap over buckets and grease machine.	
19-Sep-15	Josh Hewett		$162.50	Complete engine service, change hyd filters, check finals and diffs, didn't have tranny oil to complete trnas and drop box service	
18-Sep-15	A Warren	6600	$143.00	change out bucket teeth. Tightened loose track guides, checkover & grease.	
17-Sep-15	Greg Mills		$32.50	Check over machine	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
16-Sep-15	Josh Hewett		$65.00	Hose from hyd pump to hoist valve bank weeping - hose yet yet to be fitted when machine down	
16-Sep-15	Greg Mills	6586	$130.00	Fit bolts to track guid. Replace 1x wear plate. Fuel machine.	
16-Sep-15	A Warren	6582	$214.50	Checked low power. Drained fuel filter, cleared air filters. Got specs on machine. Tested & checked machine. All ok	
15-Sep-15	Greg Mills		$65.00	Fill auto greaser	
15-Sep-15	A Warren		$53.63	Top up oils, checkover & grease	
14-Sep-15	A Warren		$268.13	Organised franna. Loaded up parts inside bucket. Fitted pin into bucket to lift from. Lifted bucket onto truck. Strapped down bucket. Inflated tyres on truck	
14-Sep-15	Greg Mills		$32.50	fuel and grease	
14-Sep-15	Josh Hewett		$162.50	Hyd hose return to tank leaking, went and got made (hose from hyd pump to hoist block weeping didn't have fittings ordered from westrac)	
11-Sep-15	Ted Van		$32.50	Fuel up and grease.	
10-Sep-15	Ted Van	6516	$65.00	Out of fuel, Fuel up and bleed.	
10-Sep-15	Greg Mills		$32.50	Fit grease pot and fuel and grease machine.	
09-Sep-15	Ted Van	6502	$780.00	Remove a/c compressor, weld up clutch, refit and gas up, still no good. Park machine in the compound remove and replace a/c compressor. Remove and replace dryer vac down and charge a/c test ok.	
09-Sep-15	Greg Mills	6505	$65.00	Walk digger to pit.	
08-Sep-15	Ted Van	6487	$32.50	Check a/s fault.Remove covers to change a/c compressor wrong part. Organise new parts fit covers	
08-Sep-15	Greg Mills	6501	$195.00	Grease and fuel machine. Replace dip stick tube, replace hydraulic hose, fill auto greaser.	
07-Sep-15	Greg Mills	6480	$32.50	Fuel and grease	.
07-Sep-15	Greg Mills	6480	$65.00	Check a/c fault. Regas a/c	
07-Sep-15	Ted Van	6460	$32.50	Locate, clean. Refit engine oil cap. Top up eng oil.	
04-Sep-15	A Warren	6452	$178.75	Change out wear parts, checkover & grease. Change out teeth	
02-Sep-15	Greg Mills		$32.50	Fuel up machine	
01-Sep-15	Greg Mills	6382	$32.50	Fit lip protector.	
31-Aug-15	Greg Mills	6382	$65.00	Fuel and grease machine.	
31-Aug-15	Greg Mills	6370	$65.00	Fit one lip protector and one wear plate	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
20-Aug-15	A Warren	6192	$286.00	Repaired temp coolant bleed lines. Topped up coolant	
20-Aug-15	Greg Mills	6234	$130.00	Weld new lip protector mount onto bucket, fat lip protector.	
20-Aug-15	Greg Mills	6229	$65.00	Replace coolant hose. Blow out air cleaner.	
19-Aug-15	Greg Mills	6211	$130.00	Fit wear plates. Swap around plates, replace bulb in cab light. Fuel up machine. Check coolant leak.	
18-Aug-15	Greg Mills		$65.00	Fill up fuel tracker, fill machine grease	
18-Aug-15	A Warren	6187	$393.25	Greased machine, replacing damaged grease nipples. Full machine checkover. Topped up hyd oil. Organised parts. Removed & replaced stick cylinder return hose.	
14-Aug-15	Greg Mills	6153	$195.00	Swap around wear plates. Check out a/c, top up gas. Find fault in auto greaser, repair broken wire.	
13-Aug-15	Greg Mills	6136	$32.50	Change bucket teeth	
10-Aug-15	Greg Mills	6071	$32.50	Electrical fault with ustop, found tripped circuit breakers	
07-Aug-15	Greg Mills	6052	$260.00	Repalce hyd filters/slew oil/fuel filter/eng oil filter	
06-Aug-15	Greg Mills	6052	$130.00	Fit wear plates, change final drive oil	
05-Aug-15	Greg Mills	6052	$65.00	Fit wear plates, load up truck	
04-Aug-15	Greg Mills	6052	$487.50	Carry out service as per manufacturers recommendations, change eng oil/filters/fuel filters/air cleaners, remove step, get broken bolts out of track frame, fit steps, check out A/C. make up grease line and fill.	
04-Aug-15	Greg Mills	6052	$130.00	remove bucket wear plates	
31-Jul-15	A Warren	6018	$500.50	change out tiles on bucket. Change hyd oil. Inspected a/c, cleaned cab filters. Inspected machine, tightened belts.	
30-Jul-15	A Warren		$143.00	Change out tiles, grease, replace teeth	
29-Jul-15	A Warren	5962	$143.00	Grease up, change bucket teeth	
28-Jul-15	A Warren	5948	$71.50	Replaced teeth & changed out grease pod	
27-Jul-15	A Warren	5933	$196.63	Checked out outer l/h bucket wear pad, missing. Fitup r/h wear pad upside down to get machine going. Checked over machine	
24-Jul-15	Greg Mills	5910	$65.00	Charge up fire suppression, Clean track frame. Grease machine.	
22-Jul-15	Greg Mills	5868	$162.50	Replace 2x wear plates. Remove and repair manual grease pump.	
21-Jul-15	Greg Mills	5844	$65.00	Replace bucket teeth.	
20-Jul-15	Greg Mills	5821	$32.50	Top up hyd oil.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
19-Jul-15	Greg Mills	5821	$390.00	Travel to site. Remove and replace blown pilot hose	
17-Jul-15	Andrew	5782	$375.00	Cut off & weld up new lip guard mount. Cut down cheek protectors. Cut down & fit lip guard. Diagnose & ordered parts for blown hose.	
16-Jul-15	Andrew	5765	$225.00	Changed out cheek guard with old guard. Changed out teeth. Changed out wear plates.	
15-Jul-15	Andrew	5759	$150.00	Checked over machine. Adjusted tracks. Changed out 2 x teeth.	
14-Jul-15	Andrew		$300.00	Cut off & weld on new lip shroud guard retainer. Cut down lip shroud. Changed out teeth x 4.	
13-Jul-15	Andrew		$150.00	checked over machine. Replaced worn teeth x 4.	
12-Jul-15	G Wykes		$65.00	Remove & repair steps.	
11-Jul-15	G Wykes		$260.00	Repair handrails, fire suspression bracket, repair bucket.	
10-Jul-15	Andrew		$112.50	Check over machine. Grease. Top up oils.	
09-Jul-15	Andrew		$300.00	Change out water pump. Change out manual grease pump. Fit up autogreaser fill point fittings.	
08-Jul-15	Andrew		$600.00	Inspected machine topped up engine oil. Removed fire suspression bottle & bracket as it broke off. Hooked up GPS & got operating. Calibrated bucket. Removed / diagnosed water pump failure. Installed new water pump. Inspected A/C operation & topped up gas.	
07-Jul-15	Andrew		$35.00	Checked over machine & bucket.	
06-Jul-15	Andrew	5618	$150.00	repaired broken grease hose pump fittings. Checked travel motor operation. Hooked up GPS wiring for top pole.	
03-Jul-15	Andrew	5604	$318.75	inspected bucket. Organise parts. Checked & diagnosed A/C compressor failure. Ordered parts. Checked oil leak & ordered parts. Chased up bucket teeth.	
02-Jul-15	Andrew	5599	$225.00	Inspected bucket & showed welder what needs to be repaired. Setup & diagnosed G.P.S with Dominic. Greased & check over.	
01-Jul-15	Andrew	5587	$300.00	cut down & replaced lip shroud. Ordered parts.	
30-Jun-15	Andrew	5562	$75.00	check over machine. Checked bucket. Repaired aerial.	
29-Jun-15	Andrew	5541	$150.00	tried to fit glam in cab. Wrong part supplied. Organise parts. Greased link & bucket pins & bushes due to bucket change out. General checkover.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
26-Jun-15	Andrew	5529	$225.00	changed out buckets due to cracks.	
25-Jun-15	Andrew	5508	$375.00	repaired grease lines. Broken fittings on main boom. Found pins & retainers from another controller onsite. Fitted up bucket shrouds. Cut down pins & installed pins & locks. Inspected bucket several times over the day as bucket was cracking.	
24-Jun-15	Andrew	5496	$150.00	organise teeth, pick up teeth. Removed & replaced teeth. Inspected bucket. Changed out 2 wear plates.	
23-Jun-15	Andrew	5482	$35.00	inspected lever sticking. Couldn't fault lever.	
22-Jun-15	Andrew	5463	$75.00	repaired grease lines on main bucket pin.	
20-Jun-15	Andrew W.	5439	$65.00	Organised parts from stevensons to carry out repairs on auto greaser system.	
19-Jun-15	Andrew W.	5439	$97.50	Required damaged grease hoses. General chek over of machine.	
18-Jun-15	Andrew W.		$65.00	Made up light bracket to be linked into button.	
17-Jun-15	Andrew W.	5428	$292.50	Re-paired oil leak ar R/H track motor. Directional control spool broke bolts. Repaired oil leak at pilot control bank.	
16-Jun-15	Andrew W.	5421	$211.25	Fitted steps and handrails. Repaired grease hoses and fittings. Primed up bucket pins and manually greased all points.	
11-Jun-15	Andrew	5421	$600.00	completed site requirements. Fitted stick & bucket.	
05-Jun-15	Ted Van	5409	$455.00	Prep gps sensor brackets and weld onto short stick, fit sensors, run cable, fit staff clamps. Prep stick for transport. Load bucket.	
04-Jun-15	Ted Van	5409	$260.00	Reseal sunction pipe on pump 3. Reseal PPC filter housing, replace filter housing, replace filter. Wash down pump bay. Replace hydraulic tank breather and cap filter. Top up hydraulic oil. Check bucket and complete pre hire paperwork. Remove gps sensors, cables, and brackets off 206. Remove bucket cylinder pipe support off 206 and replace p205 stick broken one. Check stick bearings for play and order new seals	
03-Jun-15	Ted Van	5408	$568.75	Fuel up, Paint new fire suppression support and fit. Fit holder and secure bottle charge fire supression system. And remove bypass. Test machine.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
02-Jun-15	Ted Van	5408	$422.50	Repair oil leak solenoid under stairway LHS. Repair oil leak at pilot line on RHS of pump. Repair oil leak at pilot line on top LHS of control valve1. Remove fire supression bottle bracket and support for repair. Remove broken grouser bolt from RH track. Replace U/S wiperblade. Check and re stamp extinguishers Mount gps radio bracket. Clean out cab of rubbish.	
01-Jun-15	Ted Van	5408	$650.00	Condition report, order parts. Replace blown globe in RHS light. Replace cab filters, blow out air filter, top up engine oil. Remove broken bolts from RH track for step carriers, Drill out damaged holes. Remove fire suppression bottle neck, Inspect refit refill bottle with 70.5LTS water and 4.5LTS (6%) of agent. Connect GPS screen, Remove faulty cable frm RHS mushroom and secure new cable.	
24-Nov-14	Greg Mills	5405	$32.50	Clean off track frame.	
07-Nov-14	Dave O'Leary		$65.00	Clean and cover stick pin holes	
06-Nov-14	Dave O'Leary		$260.00	remove stick/walkways/handrails/exhaust stacks and fire supression bottles from machine.	
06-Nov-14	Greg mills	5405	$227.50	Disassemble machine for transport	
05-Nov-14	Dave O'Leary		$65.00	Remove bucket from machine.	
05-Nov-14	Komatsu		$790.00	diagnose hydraulic pump, surging & possible failure, check plugs on pumps, no metal. Test pump pressures, front pump 4600psi, rear pump 4600psi, swing pump 4300psi. All in spec, no noise. Cycle times in spec. watch machine work, retest pressures, all OK. Recommend to recheck filters after 8hrs of work.	
05-Nov-14	Greg Mills	5405	$97.50	Remove bucket	
29-Oct-14	Greg Mills	5405	$65.00	Check over machine and make up repairs list.	
15-Oct-14	Greg Mills	5361	$97.50	Grease machine, repair grease line, fill auto greaser	
11-Oct-14	Ted Van		$32.50	Grease bucket and stick	
11-Oct-14	Ted Van		$65.00	Grease bucket and stick and refill autogreaser	
10-Oct-14	Ted Van	5302	$32.50	Grease bucket and stick	
30-Sep-14	Dave O'Leary	5295	$32.50	Repair bucket pin grease lines, grease bucket.	
27-Sep-14	Ted	5271	$35.00	grease bucket & stick.	
24-Sep-14	Ted	5257	$130.00	grease bucket & refill autogreaser. Remove broken fitting from back bucket pin & replace. Grease.	
20-Sep-14	Millsy	5221	$35.00	fill auto greaser. Grease.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
19-Sep-14	Millsy	5207	$97.50	listen to machine while working, noise in machine OK. Grease.	
17-Sep-14	Millsy	5201	$35.00	repaire grease line. Fit grease nipple. Grease.	
12-Sep-14	Ted Van	5197	$65.00	Remove damaged autogreaser components from stick, cap off hose and top up autogreaser, organise parts to manually grease.	
12-Sep-14	Ted van	5194	$32.50	Grease bucket and top up autogreaser	
10-Sep-14	Ted Van	5177	$65.00	Repalce hydraulic filters	
10-Sep-14	Ted Van	5174	$32.50	grease bucket and stick	
08-Sep-14	Ted van	5152	$97.50	Fill autogreaser/grease bucket, refill hyd oil	
06-Sep-14	Greg Mills	5135	$65.00	Grease, replace broken grease line	
06-Sep-14	Greg Mills		$32.50	Top up engine oil	
06-Sep-14	Greg Mills	5126	$97.50	Fit hose and covers	
05-Sep-14	Greg Mills	5126	$97.50	Remove blown hose and replace	
05-Sep-14	Greg Mills	5121	$260.00	Help Komatsu walk digger into cut, let machine work for a while, recheck pressures	
03-Sep-14	Greg Mills	5120	$65.00	Weld up fire supression bracket	
02-Sep-14	Greg mills	5120	$162.50	replace hyd filters, cut filters open, test machine	
02-Sep-14	Greg Mills	5120	$130.00	remove blown hose, get new hose made and fit hose.	
01-Sep-14	Greg Mills	5120	$195.00	Top up hyd oil and test - pump noisy, pull all magnetic plugs in pumps, tighten up all suction lines	
26-Aug-14	Ted Van	5114	$162.50	Refill autogreaser and grease bucket/stick, swap outside teeth with inner teeth, replace damaged tooth retainer.	
25-Aug-14	Ted Van	5101	$65.00	Load/unload and check GET	
23-Aug-14	Greg Mills	5086	$65.00	Grease, replace elbow for grease line	
23-Aug-14	Greg Mills	5085	$65.00	Remove guards, try to find filler cap	
22-Aug-14	Greg Mills	5078	$32.50	Grease machine	
21-Aug-14	Greg Mills	5160	$32.50	Grease machine	
21-Aug-14	Greg Mills	5160	$32.50	Remove broken step	
20-Aug-14	Millsy	5153	$65.00	fit side cutters to bucket.	
14-Aug-14	Ted Van	5047	$357.50	Change engine oil and filters/fuel filters/outer air filter, blow out coolers, top up autogreaser and grease bucket, remove bucket sidelink GET and clean up.	
14-Aug-14	Ted Van	5043	$97.50	Grease bucket and fill autogreaser	
12-Aug-14	Ted Van	5022	$48.75	Grease bucket and stick and refill autogreaser	
10-Aug-14	Greg Mills	5009	$32.50	Top up engine oil	
09-Aug-14	Greg Mills	5002	$32.50	Grease machine	
08-Aug-14	Greg Mills	4993	$65.00	Grease machine, fit new wear plate	
07-Aug-14	Greg Mills	4983	$32.50	Grease machine	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
06-Aug-14	Greg Mills	4974	$32.50	Grease machine	
05-Aug-14	Greg Mills	4964	$65.00	Fit grease line, grease machine	
01-Aug-14	Ted Van	4928	$422.50	Escort franna and maas truck to machine, unload/reload buckets on truck, fit repaired bucket to machine and grease, replace worn wear plate.	
31-Jul-14	Ted Van	4924	$227.50	Check overheating, blow back coolers, check levels, remove bucket.	
29-Jul-14	Ted Van	4912	$130.00	Grease bucket and stick, repair grease line on end of stick cylinder.	
28-Jul-14	Ted Van	4902	$65.00	Inspect bucket, refill autogreaser and grease bucket, fit flexi hose and new coupling to hand greaser.	
25-Jul-14	Greg Mills	5889	$32.50	Grease machine	
24-Jul-14	Greg Mills	5879	$32.50	Grease machine	
24-Jul-14	Greg Mills	5576	$65.00	Replace bucket teeth, took wrong teeth to machine had to go back and get other teeth	
23-Jul-14	Greg Mills	5871	$32.50	Grease machine	
23-Jul-14	Greg Mills	5871	$32.50	Grease machine	
22-Jul-14	Greg Mills		$32.50	Grease machine	
19-Jul-14	Ted Van	4827	$32.50	No start - E-stop (operator error)	
18-Jul-14	Ted Van	4827	$32.50	Grease bucket pins	
17-Jul-14	Ted Van	4812	$390.00	Fit bucket, clean and tap out retaining bolt holes, remove GET ready for replacement, refit GET and grease bucket and stick	
15-Jul-14	Ted Van	4809	$725.00	mole board broken off bucket, organise machine to be taken to clear area, remove bucket pins, remove solenoid collar, escort franna to and from site to unload/reload exchange bucket clean up damaged/rusty sliding collar, clean up bucket bushes, fit collar, clean up pins and position in bucket.	
15-Jul-14	Ted Van	4807	$65.00	Grease bucket pins and stick	
14-Jul-14	Ted Van	4807	$65.00	Refill autogreaser tub, clean out bucket and inspect break/cracks in adaptors and mole board	
13-Jul-14	Greg Mills	4796	$32.50	Grease machine	
12-Jul-14	Greg Mills	4790	$32.50	Grease machine	
11-Jul-14	Greg Mills	4781	$32.50	Grease machine	
10-Jul-14	Greg Mills	4763	$32.50	Grease machine	
07-Jul-14	Greg Mills		$65.00	Replace 2 cooler hoses	
04-Jul-14	Ted Van	4745	$97.50	Replace u/s o-ring on travel motor hose, diagnose weep and organise parts for pump drive box cooler circuit	
02-Jul-14	Ted Van	4738	$65.00	Grease bucket pins and stick, refill autogreaser pot.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-Jul-14	Ted Van	4729	$32.50	Grease bucket, top up autogreaser	
30-Jun-14	Ted Van		$16.25	Grease bucket pins	
29-Jun-14	Greg Mills	4714	$32.50	Greased machine	
28-Jun-14	Greg Mills	4706	$162.50	Try to remove bucket pin - unable to do so, removed grease line from H-link, fitted grease nipple, greased pin no worries, pumped grease through grease line, fitted grease line - very slow to get grease through need bigger line	
27-Jun-14	Greg Mills	4700	$32.50	Grease machine	
27-Jun-14	Greg Mills	4692	$32.50	Grease machine	
20-Jun-14	Ted Van		$130.00	Organise Pirtek and replace grease line to bucket pin and grease	
10-Jun-14	Greg Mills		$65.00	Replace 3 x wear plates on bucket	
06-Jun-14	Ted Van	4568	$65.00	Check autogreaser adjustment, refill autogreaser, change out mt hand grease pod.	
04-Jun-14	Ted Van		$97.50	Top up grease pod and adjust H-link bucket pin and greaser.	
03-Jun-14	Ted Van	4549	$65.00	Grease H-Link bucket pin, check auto greaser	
02-Jun-14	Ted Van	4547	$227.50	Replace bucket teeth	
30-May-14	Greg Mills	4534	$65.00	Clean up stick pins and holes	
30-May-14	Greg Mills	4534	$325.00	Assemble machine	
29-May-14	RLW	4532	$130.00	replace bushes in basket. Load stick & bucket on truck.	
29-May-14	Dave O'Leary		$162.50	Assemble handrails and prep stick for fitting	
29-May-14	Greg Mills	4534	$325.00	Unload machine/stick/bucket and handrails, fit walkway/handrails/exhaust stack, fit seal to stick	
29-May-14	Josh Hewett	4532	$292.50	Help other fitter with bucket bearings, load truck.	
29-May-14	G Wykes		$65.00	weld brackets to stick over grease lines.	
29-May-14	Shane	4528	$393.75	remove front section of platform & load digger onto float. Fit new bushes to bucket ears. Make new grease lines, fit extra grease dosers. Clean up work area.	
28-May-14	WMS - Andrew	4538	$885.50	fitted up water pump. Filled cooling system. Checked fluid levels. Fitted guards. Removed & installed stick bushes. Startup & checked all fluid levels.	
28-May-14	Josh Hewett	4532	$162.50	Help other fitter press in bearings to stick, help welder with steps, remove fire supression bottle	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
28-May-14	Shane	4528	$881.25	replace all covers around pump housing. Replace leaking hose & Orings at boom area. Fit new alt belt idler & replace belt & adjust. Re-wire flashing light. Fill hyd tank & check for leaks. Refit all belly guards. Fill auto greaser. Bleed hyd system, start machine & check for leaks. Check all systems for operation & check all fluid levels. Replace stick & H link bearings.	
28-May-14	G Wykes		$585.00	Fab & fit new stairs.	
27-May-14	WMS - Andrew	4538	$731.50	removed guards. Removed coolant & waterpump. Removed idler pulley. Resealed leaking relief valves. Assisted in pump fitment. Machine checkover as per site checksheet. Repaired GPS aerial. Fitup swivel valve bank.	
27-May-14	G Wykes		$357.50	Fab step for track frame.	
27-May-14	Shane	4528	$562.50	finish removing pumps & replace input shaft seals. Refit pumps & re-hose. Fit new suction hoses to pumps.	
26-May-14	Shane	4528	$675.00	inspect machine for defects. Drain hyd oil & remove all panelling from around pump housing. Start to remove hyd pumps. Load stick onto float, tram franna to Agriweld & unload stick off float.	
26-May-14	Greg Mills	4534	$585.00	Fit walkway, check rollers, remove swivel, disassemble, clean, fit new seals, assemble and pack up.	
23-May-14	G Wykes		$32.50	Remove Bushes.	
22-May-14	Greg Mills		$552.50	Disassemble machine for transport	
17-May-14	Shane	4528	$187.50	Carry out 500 hr service.	
02-May-14	Shane	4457	$262.50	Diagnosis oil leak, hose U/S. Remove hoses & take to town & get new ones made. Travel back to site & refit tomachine. Check, OK.	
24-Apr-14	Greg Mills	4423	$35.00	check over & check levels.	
23-Apr-14	Greg Mills	4403	$35.00	tighten bolts in bucket pins, check oil leak.	
19-Apr-14	Shane	4393	$112.50	refit check protector to RHS of bucket.	
29-Mar-14	Greg Mills	4360	$65.00	Prime up fuel after machine	
19-Mar-14	Shane		$112.50	refit all GPS gear that was fitted to P370 the night before.	
06-Mar-14	Greg Mills	4269	$32.50	Check over and create job list	
06-Mar-14	Shane	4269	$112.50	check over machine & do up defect list.	
26-Feb-14	Shane	4269	$150.00	repair U/S lights. Check fire extinguishers. Adjsut LH track.	
13-Feb-14	Shane	4209	$75.00	Fit new bucket teeth.	
11-Feb-14	Shane	4198	$75.00	chase electrical fault with GPS. Found fuse blown under console.	
08-Feb-14	Greg Mills	4150	$32.50	Pull apart GPS plugs and check wiring	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
07-Feb-14	Greg Mills	4148	$32.50	Check out GPS cables	
03-Feb-14	Greg Mills		$32.50	Change bucket teeth	
28-Jan-14	Greg Mills	4030	$65.00	Repair oil leak, found crack in pipe, replace pipe	
24-Jan-14	Shane	3992	$187.50	Rotate bucket teeth.	
22-Jan-14	Shane	3960	$225.00	Organise parts & start 500 hr service.	
22-Jan-14	Jono Pittin	3968	$195.00	Engine service, check finals, drain PTO oil.	
22-Jan-14	Dave O'Leary	3968	$260.00	Complete 500hr service, 1000hr service due.	
22-Jan-14	G Wykes		$97.50	repair broken handrails & GPS bracket.	
21-Jan-14	Greg Mills	3957	$130.00	Repair auto greaser, fit new cut out valve.	
19-Jan-14	Shane		$187.50	replace bucket teeth & air cleaner. Boom pins squeaky, found auto greaser not working. Found greaser pumps but not cutting out when it gets to 3000psi, causing a fault in system. Clean pressure sensor & adjust. Check, OK. Order new sensor.	
17-Jan-14	Shane	3902	$187.50	replace bucket teeth. Replace worn wear pads under teeth adaptors.	
13-Jan-14	Dave O'Leary		$16.25	Clean air filter	
11-Jan-14	Shane	3833	$75.00	replace bucket teeth.	
07-Jan-14	Andy William	3807	$65.00	Check over fit GPS	
06-Jan-14	Andy William	3807	$910.00	Stick and bucket	
06-Jan-14	Shane	3807	$750.00	remove bucket & stick & handrails from machine. Transport to other side of site & put back together. Do all necessary paper work for job.	
05-Jan-14	Shane	3807	$150.00	start removing bucket pins.	
05-Jan-14	Andy William	3807	$97.50	Remove bucket pins	
02-Jan-14	Greg Mills	3767	$195.00	remove broken piece and replace grease fitting, put new wear plate on bucket, check auto greaser, check A/C	
01-Jan-14	Greg Mills	3769	$32.50	Change bucket teeth	
01-Jan-14	Andy William	3749	$65.00	Change out cuting edges	
29-Dec-13	Greg Mills	3722	$32.50	Swap around bucket teeth	
23-Dec-13	Greg Mills	3697	$65.00	Grease bucket pins, check greaser.	
23-Dec-13	Andy William	3692	$32.50	Grease all bucket pins and stick pins.	
19-Dec-13	Shane	3651	$35.00	fit new bucket teeth.	
19-Dec-13	Greg Mills	3651	$32.50	Change bucket teeth	
09-Dec-13	Greg Mills		$130.00	Check greaser fault	
09-Dec-13	Greg Mills	3605	$130.00	Greaser fault, check all plugs, adjust air flow, system came good.	
06-Dec-13	Shane	3567	$75.00	change bucket teeth.	
04-Dec-13	Greg Mills	3555	$195.00	Change out 4 x wear plates on bucket, swap around 6 x wear plates, swap around teeth.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Dec-13	Shane	3555	$300.00	carry out 500 hr service. Adjust tracks, fill auto grease. Replace worn wear plates & rotate teeth.	
04-Dec-13	G Wykes		$130.00	remount fire suspression bottle.	
30-Nov-13	Shane	3502	$75.00	fit new GET.	
30-Nov-13	Andy William	3502	$130.00	Replace bucket teeth	
28-Nov-13	Andy William	3478	$130.00	Loose fire supression bracket	
25-Nov-13	Shane	3451	$75.00	rotate bucket teeth & replace work wear plate.	
25-Nov-13	Greg Mills	3451	$32.50	Swap around teeth , fit new wear plate under adaptor.	
24-Nov-13	Shane	3432	$206.25	checked out squeaking noise in machine. Monitor machine, found noise gradually went away as machine warmed up. Just a relief valve when machine cold.	
24-Nov-13	Greg Mills	3440	$32.50	Check noise in machine	
23-Nov-13	Shane	3421	$187.50	pick up GET from tamex depot. Travel to site & fit to machine.	
23-Nov-13	Greg Mills	3425	$32.50	Change bucket teeth	
22-Nov-13	Greg Mills	3421	$32.50	Grease all front nipples	
20-Nov-13	Shane	3395	$75.00	rotate teeth.	
17-Nov-13	Greg Mills	3364	$32.50	Change bucket teeth	
12-Nov-13	Shane	3310	$150.00	fit new a/c belt & adjust.	
11-Nov-13	Shane		$150.00	a/c not working. Found a/c belt missing, remove belly guards & check all bearing. OK. Order new belts.	
09-Nov-13	Shane	3278	$115.00	replace bucket teeth.	
02-Nov-13	Andy William		$325.00	Fit turbo heat shield, fit grease leak at grease pump, segregation of wiring.	
01-Nov-13	Shane	3254	$225.00	carry on with defect list. Change fule filters. Organise turbo swapping. Segregate elect & hyd.	
31-Oct-13	G Wykes		$325.00	prepare for mine spec.	
30-Oct-13	G Wykes		$325.00	prepare for mine spec.	
30-Oct-13	Shane	3254	$170.00	check over machine for defects. Assist Hedgy measure up for handrails. Fit required reverse quaka. Sticker up machine with required stickers.	
28-Oct-13	Ian Miller		$65.00	Install drill and mount new fire extinguisher.	
15-Oct-13	Shane		$620.00	finish off pump reseal. Clamp all hoses etc. refit all panels. Finish off 1000 hr service. Replace all hyd filters & a/c filters. Replace engine dipstick tube. Fill auto greaser. Adjust RH track.	
14-Oct-13	Shane		$506.25	ermove pumps no 1 & no 2 & replace input shaft seals.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
14-Sep-13	Shane	3241	$300.00	remove all guards, doors & panel from around pump hosing ready to reseal pumps.	
13-Sep-13	Shane	3241	$262.50	repair coolant leak. Fit 2 set of steps to machine. Fit new E stop.	
29-Aug-13	Shane	3202	$150.00	check operation of auto greaser. OK. Manually grease up all bucket pins.	
12-Jul-13	Shane	3141	$140.00	fit new bucket teeth.	
11-Jul-13	Shane	3138	$35.00	swap bucket teeth.	
09-Jul-13	Shane	3141	$35.00	R & R bucket teeth with 2nd hand teeth.	
04-Jul-13	Shane	3068	$65.00	Swap outside bucket with middle teeth.	
21-Jun-13	Shane	3011	$143.00	R & R fuel filters & bleed up fuel system.	
20-Jun-13	Shane	3002	$360.00	start 1000 hr service. Change engine oil & filters. Couldn't change fuel filters because tank was to full.	
19-Jun-13	Shane	2984	$196.00	coolant level light staying on. Top up coolant & check wiring, OK.	
06-Jun-13	Shane	2985	$146.25	Fit new GET & fit auto greaser.	
29-May-13	Shane	2935	$162.50	Swap teeth bucket & top up auto greaser. Grease bucket pins & adjust grease dozers. Top up engine oil level.	
21-May-13	Shane	2910	$65.00	Fill auto greaser.	
20-May-13	Shane	2902	$130.00	Travel to machine to check oil leak. Found oil leaking from pump drive housing breather. Pump drive overfill. Check operation for faults, OK	
17-May-13	Shane	2875	$130.00	Fill auto greaser & check operation.	
16-May-13	Shane	2865	$178.79	Disconnect auto greaser from beeping until fitting to fill arrives. Grease up all pins. Fit new bucket teeth & grease pins.	
15-May-13	Shane	2858	$97.50	Check over machine for engine oil leak. Found hose had come off air compressor. Refit hose & check over.	
10-May-13	Shane	2832	$65.00	Swap outside bucket teeth with middle teeth.	
07-May-13	Shane	2808	$97.50	Grease up boom & bucket pins & check GET.	
06-May-13	Shane	2788	$65.00	Fit new bucket teeth.	
01-May-13	Shane	2760	$130.00	Fit shims to bracket pin & fit retainer.	
01-May-13	Greg Mills	2760	$162.50	Fuel machine, top up hyd oil, fit shims to bucket pin.	
29-Apr-13	Shane	2738	$65.00	fit new bucket teeth.	
26-Apr-13	Shane		$487.50	oil leak from slew motor pilot hose leaking hose spiral wrapped with 2 other pilot hoses. Remove all 3 hoses together & take to stevo's & got 3 new hoses made & wrapped. Drive back to site & refit & clmap hoses to machine.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
24-Apr-13	Shane	2720	$562.50	replace bushes & pin on H link to bracket. Mount up grease dosers. Make hose & fit & clamp to frame.	
24-Apr-13	Greg mills	2720	$585.00	Remove pin in H-link using spare excavator, cut out bearings, shrink new bearings and fit to H-link, fit new pin, weld on bosses for clamps and bracket for greaser, weld stopper for pin, fit grease lines to all bucket pins.	
19-Apr-13	Shane	2670	$75.00	rotate bucket teeth for better wear.	
15-Apr-13	Shane	2644	$187.50	refuel machine & grease bucket pins.	
08-Apr-13	Shane		$75.00	swap bucket teeth around & manually grease up bucket.	
04-Apr-13	Shane	2569	$281.25	rotate corner bucket teeth with middle ones. Replace 2 outside CAT wear plates. Organise more CAT GET.	
28-Mar-13	Shane	2565	$265.00	remove blown hose & measure up & get new one made. Fit new hose & refill hyd tank level. Check operation, OK.	
25-Mar-13	Shane	2530	$300.00	EOE fault code active & macine won't run. Carry out diagnostics for that code. No problem found but code still active. Pull apart Estops & check, found one with corroded terminals. Bypass code gone, check operation, OK. Fit new bucket teeth.	
22-Mar-13	Shane		$360.00	carry out 500 hr service. Change engine oil & filters. Change fuel & air filters. Check all oil levles. Clean A/C filters. Grease all points.	
18-Mar-13	Shane	2490	$150.00	refuel machine.	
14-Mar-13	Shane	2454	$170.00	refuel machine & grease bucket pins.	
13-Mar-13	Shane	2445	$135.00	investigate engine oil leak. Found filters loose. Tighten filters.	
12-Mar-13	Shane	2436	$210.00	remove worn bucket teeth & fit new ones. Grease bucket pins & check operation of greaser. Top up coolant.	
11-Mar-13	Shane	2428	$210.00	refuel, check bucket teeth & fit maas sticker to rear of machine. Rotate teeth at lunch break to finish off the day.	
07-Mar-13	Shane	220	$65.00	repair steps & tried to fit to machine, but all holes don't line up, needs modifying. Grease bucket pins.	
06-Mar-13	Shane	2390	$165.00	fit new grease pump to auto greaser. Test, OK.	
05-Mar-13	G Wykes		$260.00	repair step on exc.	
05-Mar-13	Shane	2380	$276.25	top up fuel & hyd levels & grease bucket pins. Fit helicoils to access step mounts. Heat & straighten bottom step. Grease & refuel machine at end of shift.	
04-Mar-13	Shane	2380	$877.50	continue cutting off grouser plates.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Mar-13	G Wykes		$942.50	cut grousser plates.	
01-Mar-13	Greg Mills	2389	$812.50	Travel to Tomingly - Could not get into machine due to rain, escort truck to digger via highway, fit up stick onto digger, pull crane out of bog with moxy and PC1250, fit bucket onto digger, repair autogreaser.	
01-Mar-13	Shane	2380	$715.00	fit stick & bucket to machine. Plumb up all hoses. Check all systems & levels & do prehire inspection. Diagnose faulty greaser. Found power wiring cut in conduit. Clean out air supply solenoid. Got greaser to cycle, but after a few cycles grease started coming out air vent & pump hyd locked. Need new pump.	
28-Feb-13	Greg Mills	2381	$97.50	Check around machine, drop off trailer, park up tooling, take out regulators for Shane.	
28-Feb-13	Shane	2380	$373.75	plumb up grease lines. Assist hedgy cutting off grouser plates.	
27-Feb-13	Greg Mills	2385	$747.50	Fit up boom and counter weight, fit handrails and walkways, fit exhaust stack and intake hats, cut off some grouser plates.	
27-Feb-13	Josh Newbigg		$585.00	Unloaded 2 trucks, fitted boom to the 1250 excavator, fitted counter weight, fitted side rails, hooked hydraulic hoses up.	
27-Feb-13	Shane	2380	$270.00	assist with machine assembley.	
22-Feb-13	EOS - Grant		$1,188.00	demobilise & load excavator.	
22-Feb-13	D Burgess		$1,470.00	Demobe. Remove bucket (had to get boily to make a pin pusher). Remove stick & removed hose to boom remove boom, load boom & steps on to float & bucket. Removed counter weight. Load excavator & counter weight onto float.	
22-Feb-13	Lance		$1,365.00	Demobe. fill out required permits for job. Pick up screw compressor & hose. Carry out prestart with all personal involved, loosen counter weight bolts & remove bucket while crane set up. Carry out dis-assemble of excavator.	
21-Feb-13	D burgess		$210.00	start removing bucket & steps.	
21-Feb-13	Lance		$1,155.00	complete all paper work for site. Carry out assessments for test operations & W.A.H. prep work area. Start removing bucket btu A-link pin was worn & had little grease. Pick up drill rod to make pin pusher.	
21-Feb-13	EOS - Grant		$836.00	compliance & begin demobilisation.	
20-Feb-13	EOS - Grant		$264.00	begin paperwork, SWMS, certification, VOC.	
14-Feb-13	Outcall		$285.00	oil leak from hyd valve block needs machining.	
07-Feb-13	outcall	2320	$95.00	changed out batteries & checked change rate.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
01-Feb-13	Outcall		$285.00	resealed hyd pump suction hose & jump started.	
23-Jan-13	Outcall		$380.00	installed auto greaser.	
23-Jan-13	Outcall		$142.50	rebuild grease pump.	
22-Jan-13	Outcall		$380.00	completed 250 hr service.	
21-Jan-13	outcall		$380.00	fixed fule filter leak. Re-sealed suction hose. Started 250 hr service.	
14-Jan-13	Outcall	2209	$570.00	stripped down pump & find parts to order. Greased.	
11-Jan-13	Outcall		$332.50	removed grease pumps & stripped.	
10-Jan-13	Outcall		$285.00	replace Oring on hyd pump. Auto lube pump failure.	
09-Jan-13	Outcall	2180	$332.50	inspect hyd leak at pump.	
17-Dec-12	outcall	2098	$1,235.00	2000 hr service. Remove hyd block that was leaking & have machined flat & refit.	
13-Dec-12	outcall	2075	$190.00	inspect leak on hyd block. Top up rear slew.	
12-Dec-12	outcall	2058	$95.00	inspect oil leak.	
07-Dec-12	Outcall	2011	$570.00	repair hyd leak on pump.	
02-Nov-12	Outcalll	1893	$42.50	manually grease bucket.	
01-Nov-12	Outcall		$85.00	grease bucket	
01-Nov-12	Outcall		$170.00	Noisy pins - grease bucket manually	
31-Oct-12	Outcall	1878	$170.00	tightened grease pump fittings	
22-Oct-12	Trevor Huth	1866	$297.50	Cahnge out H-link pin, inspection + risk assessment.	
19-Oct-12	Graham F		$210.00	water pump - strip & inspect pump, order parts. Clean & assemble. Fit new shaft, seals & bearings. Seal pump & paint.	
19-Oct-12	Outcall		$285.00	change out bucket & pins.	
15-Oct-12	Outcall		$190.00	weld step on & modify bucket retainer pin.	
13-Oct-12	Trevor Huth		$765.00	Fit up stick hoses/handrails/walkway.	
12-Oct-12	Max Yates	1861	$470.25	Remove handrails and exhaust, fit belly plates, loading parts on transport float change over bucket.	
12-Oct-12	Lance		$1,097.25	refit panels. Give last wash down, remove walkways, exhaust & handrails. Organise watercart to wash tracks. Load on float z& was down. Escort to gate. Move stick & bucket to wash pad, had to wait for crane, assist with rigging, wash stick & bucket, load on float. Unload bucket & sent spare as found cracked out adaptor - escort to gate, clean up.	
12-Oct-12	Noel		$880.00	attach nelly plates to machine. Remove hand rails, tie machine down to float. Continue to remove excess grease from stick. Finish washing stick & bucket. Load bucket to truck.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
12-Oct-12	Graham		$731.50	fit covers, check over for cleaniness. Remove walk ways. Escort float onto site, load machine & wash. Escort to front gate. Held up on permit. Wait for float to return, have bucket & stut loaded.	Note bucket has cracked adaptor bay - Rob + swapped buckets.
12-Oct-12	Dan Burgess	1861	$261.25	Refit all belly plates and finish cleaning.	
11-Oct-12	Max Yates	1861	$418.00	Trace and repair wiring to radiator fan.	
11-Oct-12	Lance		$418.00	inspect faults found rectrify headlight faults. c/o Orings on boom manifold start removing u/s wiring harness near can. Organise cranes for Friday.	
11-Oct-12	Dan Burgess	1861	$470.25	Clean excavator and bucket	
11-Oct-12	Noel		$880.00	complete cab cleaning. Air chiesel out bucket from mud & dirt. Continue washing machine when machine was moved back to wash pad.	
10-Oct-12	Noel		$880.00	continue with high pressure cleaning of machine. Ran out of water so cleaned interier of cab. After water was refilled continued to high pressure clean machine.	
09-Oct-12	Lance		$1,045.00	prep for removal of stick, organise Orings, pick up JLG from arch 10. carry out permits for wah barricade area. Move machine, remove stick assy & refit pins. Drop off ewp & clean up.	
09-Oct-12	Noel		$880.00	high pressure wash the stick. Stick was heavily soiled with grease as such with the use of cold water was hard to remove. Stick was removed with crane during this time, belly plates were washed.	
09-Oct-12	Dan Burgess	1861	$627.00	Clean ready to be taken offsite, remove stick from excavator.	
09-Oct-12	Max Yates	1861	$783.75	Set up for demobilisation, disconnect hoses and pins, lift off stick from boom - work in with cranes.	
08-Oct-12	Max Yates		$418.00	removing bucket and belly plates, cleaning.	
08-Oct-12	Dan Burgess	1861	$418.00	Remove belly plates and buckets.	
08-Oct-12	Lance		$1,045.00	carry out inspection for damage & oil leaks. Remove bucket, chisel mud off tracks. Remove guards & panels for cleaning, found broken bolt at carbody to trackflange behind guard. Parts ordered. Fix oil leak on spool bank & test OK. Use water cart to wash off truck frames. Start scraping off grease & degreasing for washing.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Oct-12	Noel		$484.00	remove bucket from machine. Shovel off excess dirt from trash frames & machine body. Scrape pff excess grease from stick z& around pins. Scrape off excess grease from around grease pad. Walk machine o wash pad to start high pressure cleaning.	
28-Sep-12	Dan Burgess	1803	$712.50	refit bucket.	
28-Sep-12	Max		$760.00	fitting bucket to excavator. Remove pins & debar bushes in bucket. Fit new seals 7 Orings. Align hole & push in pins. Weld on extra pin retainer plates. Grease pins, clean up area. Return blocks & forklift etc.	
07-Sep-12	Max		$416.00	Remove bucket and refit pins to bucket.	
07-Sep-12	Daniel		$104.00	Remove bucket pins and bucket.	
06-Sep-12	Daniel		$156.00	Clean bucket pins and ready for disassembly.	
27-Aug-12	Max	1798	$617.50	help with 750hr service. Repalce leaking fuel fill hose. Tighten bolts in hyd flanges on control valve.	
27-Aug-12	Lance		$0.00	250 hr check over. Hi flow fuel hose replaced due to leaks. Machine off hire as of 22/08/12.	
16-Jul-12	Lance	1565	$522.50	Change over bucket, purge pins and shim H Link.	
16-Jul-12	Max	1565	$522.50	Remove pins and bucket, refit bucket from P206 and secure pins	
10-Jul-12	Lance		$95.00	get 90 degree elbow from pirtek for H. flow fuel hose.	
30-Jun-12	Lance		$126.50	oil leak in Eng bay, try to organise wash down Monday morning.	
26-Jun-12	Lance	1504	$52.25	Measure bucket as requested by rob.	
25-Jun-12	Lance	1504	$365.75	Carry out 500hr service had to level area first.	
21-Jun-12	Lance		$104.50	Grease injector bank broken off.	
29-May-12	Lance		$209.00	Clunking noise found to be loose idlers. Tighten up.	
17-May-12	lance		$52.25	Rotate bucket teeth	
15-May-12	Morgan		$32.50	fit 2 way hand bracket, tighten mirror head.	
03-May-12	Lance		$285.00	investigate cause of engine sump over filling. No fault found yet.	
03-May-12	Graham F		$190.00	inspect machine. Change oil in both pto & engine. Top up to correct levels. Pto oil dark - suggest slighty burnt (hot) Over filled. Did oil test, levels appear to be staying correct. May have been over filled.	
21-Apr-12	Lance		$380.00	Fit bucket to machine & clean up.	
20-Apr-12	Lance/Max		$427.50	rotate bucket teeth. Remove bucket & clean pins.	
18-Apr-12	Lance		$95.00	Replace bucket teeth.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
18-Apr-12	Lance		$95.00	Rotate teeth.	
12-Apr-12	Lance		$95.00	stick to bucket. Grease line broken off. Fit line. Report broken injectors on H link.	
11-Apr-12	Graham F		$760.00	carry out 500hr service.	
30-Mar-12	Graham		$190.00	blown oring in bucket circuit under boom.	
30-Mar-12	Lance	1059	$190.00	C/O blown orings, fit belly guards. Top up oil. Clean up.	
29-Mar-12	Graham		$190.00	check over machine auto grease working correctly.	
29-Mar-12	Lance		$95.00	Blown O ring on steer pipe for bucket cyl around screw motor. Find leak - clean up & crack bolts, did not have correct size.	
29-Mar-12	Lance		$95.00	pump extra grease in to bucket pins.	
27-Mar-12	Lance		$142.50	Carry out inspection on grease systems, hydraulic hoses & walking gear.	
23-Mar-12	Max		$332.50	pick up thread, tap out worn bolts, clean threads, fit end cap & bolts.	
22-Mar-12	Lance	991	$570.00	fit bucket & new grease seals, perge pins & lines. Move old bucket for boilermaker to repair. Tap hlink grease hole & fit new fitting. Held up at times due to heavy rain. Had minor difficulty due to uneven ground & mud.	
22-Mar-12	Max		$665.00	working in mud, rain delays. Setup bucket, clean pins & bushes, align bucket & boom, fit seals & pins.	
20-Mar-12	Max		$97.50	Work with fitter, grind off locky tubs, unbolt end caps. Draw out bucket pins, & remove bucket.	
20-Mar-12	Lance		$427.50	carry out bucket inspection with brad. Tap out grease line fitting in H link. Fit new fittings, grease injectors. Tighten RH step on track, & hand rails on LH side. Remove bucket for welding repairs.	
14-Mar-12	Lance	987	$47.50	check teeth, carry out bucket inspection. Cracking badly at adaptors & lars.	
13-Mar-12	Max	955	$190.00	Prepare & carry out 500hr service part of 1000hr	
13-Mar-12	Lance	955	$332.50	prep filters for service.carry out 500hr part of 1000hr service. Make parts list for servicing. Look up filter numbers & order.	
12-Mar-12	Lance	950	$47.50	C/O leaking wiggins fitting for hi flow fuel.	
05-Mar-12	Max		$95.00	Inspect bucket teeth adaptors. Cracking at welds.	
02-Mar-12	Lance		$47.50	Refit grease line to stick to bucket pin.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
29-Feb-12	Lance	852	$855.00	remove bucket C/O seals in stick & H Link, clean pins & new bucket. Remove burrs in seal recess on H link - had to wait for forklift & operator to install new pins. Make & fit new grease line to H link stick - bucket pin purge pins & lines.	
29-Feb-12	Max	852	$665.00	remove large coal bucket, fit smal rock bucket. Clean up pins & bushes. Work with forklift availability. Wet & muddy. Replace bucket control spool springs with spacer.	
29-Feb-12	Graham		$332.50	Remove bucket pins, clean up BRGS & photograph. Bushes are worn but will go again. Fit new seals to stick & dog bone - make sure auto greaser is working correctly. All OK.	
28-Feb-12	Graham		$190.00	Chase up & pick up parts that have arrived.	
27-Feb-12	Lance		$285.00	remove bucket pin for inspection of pins & bushes - All OK. Order grease seals before removing bucket.	
27-Feb-12	Max		$285.00	Work with availability of forklift - R & R bucket pin to check boom bushes for waer. OK>	
22-Feb-12	Max	836	$95.00	Fit & bleed recon grease pump.	
22-Feb-12	Lance	873	$95.00	Refit lube pump - perge system.	
21-Feb-12	Lance		$475.00	Remove grease pump & sent to coopers for repairs - pick up parts from Gladrock & beecher. Drop roller wheel at Rabco yard.	
21-Feb-12	Max		$95.00	work with Lance - check & remove failed grease pump.	
20-Feb-12	Lance		$475.00	Grease system fault. Pot ran out of grease. Fill pot - test system but pump would not pick. Unable to rectify fault. No book on site to refer to.	
15-Feb-12	Graham		$380.00	Trace lines & valves on machine using project plant rentals, workshop manual found spare spool (bucket speed) had springs both ends of spool tex from wrench tool desk explained this had been corrected prior to shipment. But has not been done to this machine, email factory of fault found.	
15-Feb-12	Lance		$95.00	Check spools in bucket circuit.	
13-Feb-12	Graham		$380.00	Remove auto grease pump, transport to Coopers fluid at Boyne island. Mike striped pump - found plunger valve shaft missing. Rebuild under warranty. Travel to pick up pump, bring back to site.	
13-Feb-12	Graham		$47.50	Rotate bucket teeth.	
10-Feb-12	Lance		$95.00	Grease bucket circuit.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
03-Feb-12	Max		$95.00	work in with operator, pump extra grease into bucket pins.	
31-Jan-12	Graham		$142.50	Remove pins & inspect for ware, all pins & brushes worn. Reinstall pins, grease & send back to work.	
19-Jan-12	Lance	830	$617.50	Change out bucket. No Orings fitted as directed by Barney. Old worn pins used as good pins did not fit bucket. Had to wait for new retainer bolts, grease hose & new injectors for bucket circuit & fit. Clean up Perge all pins. Orings for bucket damaged. Worked RDO as directed by Barny.	
19-Jan-12	Lance	835	$190.00	Blown boom hose. Take to pirtek to get new one made deliver to site & fit to excavator.	
19-Jan-12	Max	667	$332.50	Contain oil leak, locate & remove split hose at base of boom, cap hoses, fit new hose & clean up oil etc.	
19-Jan-12	Max	665	$190.00	Changing over bucket to spare one, needed to use pins out of spare.	
19-Jan-12	Graham		$570.00	Cut tab retaining pins on new bucket so to remove pins. Bucket pins Off machine are larger & won't fit new bucket.Grease seals U/S. Pins worn. Fitted as per instructed. Fit grease injector & grease line.	
18-Jan-12	Lance		$237.50	C/O Bucket main stick to bucket pin seized.	
18-Jan-12	Graham		$190.00	Start to remove bucket pins, pins shred.	
07-Jan-12	Max	610	$285.00	adjust grease injectors for flow to bucket & tilt. Injector on bottom of digger arm working but rock damaged.	
05-Jan-12	Max	592	$237.50	Check machine. Tighten bolts in bucket pivot pin bush.	
02-Dec-11	Lance	480	$522.50	Prep service kit for service on Saturday, make parts list - form spreadsheet for machines on site with unit numbers, serial numbers, hours & defect listings - (MAAS equipment only) check for electrical fault in boom bucket circuit. At end of shift.	
01-Dec-11	Lance	479	$902.50	Read operations book test & discuss possible cause for bucket leveling while booming up. Plan for servicing excavators.	
01-Dec-11	Max	479	$902.50	Check for bucket leveling when booming up.	
30-Nov-11	Lance	440	$190.00	Test machine & play with settings to try & find out why bucket dumps when lifting boom up. No fault found, Read manual for answers.	
30-Nov-11	Max	471	$95.00	Monitor coolant leak , all OK.	
29-Nov-11	Max	464	$95.00	Check coolant overflow tubes.	
04-Nov-11	Lance	335	$47.50	Fit fire ext & bracket to machine.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
31-Oct-11	Max	319	$190.00	Check for low power. Filter all OK. Fuel low by gauge & sight. Fuel truck, added 1100l. Test OK.	
30-Oct-11	Outcall		$170.00	repaired faulty grease pump	
27-Oct-11	Graham	308	$285.00	repair ware holes in adaptor, weld on choc blocks over holes & position to prevent ware to adaptors. Welded on whole box of ware pad buttons.	
27-Oct-11	Max		$427.50	Weld on wear pads to bucket.	
26-Oct-11	Max	313	$570.00	Hot work permit & weld on wear pads to bucket adapters.	
14-Oct-11	Graham	302	$1,045.00	Nake machine ready for site. Fit ground level stop boxes & isolation points. Log mufflers & pipes. Sent photos for quotes to do proper job. Fit 2way & revolving light. Refit all covers for auto electrican. Test all system. Test auto greaser. Travel to town, sort out wheel nuts for float. Unload hitch for 336 excavator (no pins).	
13-Oct-11	Lance		$220.00	Start mounting 2way & beacon.	
04-Oct-11	Lance		$427.50	tighten counter weight bolts. Fit laging to exhaust.	