BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2951216***
Document Date:	4/08/2023
Repair Order No.:	852641
RO Creation Date:	26/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	520000
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	1 of 3

K046 Fuel gaugeerratic

Couldn't fault on road test. Inspectedwiring, wriggled wiring at sender and the wiring let go with little to no force. Replaced terminals, cleaned up studs for terminals. Road tested again, no issues. ***$120.01***

Part Number	Part Description	Quantity	Total Cost
M866	Contact Cleaner	1.00	19.40
	Parts Totals:	***1.00***	***$19.40***

K046-2 Check enginelight on. Code 1852

Connected laptop, found code relatingtowater in fuel. Drained water separator bowl into clear bottle, found heavy amounts of dirty water in there. Removed fuel tank capsand found LHS tank completely filled with dirty water/fuel. Sucked out all contaminated diesel. Applied fuel doctor to tank andreplaced both filters. Ran truck and cleared inactive code. ***$369.03***
Note - left remaining container of fueldoctor in cab for customer

Part Number	Part Description	Quantity	Total Cost
FF5776	FUEL FILTER	1.00	66.90
K37-1004	FILTER-FUEL/WATER PACCAR	1.00	34.04
9265	FUEL FIX 1LTR	1.00	37.14
	Parts Totals:	***3.00***	***$138.08***

K024 Air bag pressure gauges not working.

Found RH air bag gauge N/W, LHwasdeleted for a load scale gauge, pulled dash panels out, found for some reason they had the air bag gauge lines running throughanaftermarket switch on the dash, removed switch and re ran air lines to gauges, had to extend lines and add a joiner to reach,fitted new LH gauge and placed load scale gauge in cab (Customer request), gauges now reading ok. ***$360.01***

Part Number	Part Description	Quantity	Total Cost
150077020	GAUGE-PRESSURE,BRASS BEZEL	1.00	113.86
B SP2312	FITTING-NUT	1.00	6.14
SP2336	FITTING-OLIVE	1.00	3.27
164PTC-4	FITTING	2.00	36.82
31887	PHD TX25 M5X20 BZN	3.00	0.51
134126	WSH BLK NYLN 5.5X11X1 MOQ 250	3.00	0.81
	Parts Totals:	***11.00***	***$161.41***

K002 Front diff temp gauge not working

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2951216***
Document Date:	4/08/2023
Repair Order No.:	852641
RO Creation Date:	26/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	520000
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	2 of 3

Disconnected sensor. Undone p clamp. Bridge harness and found temp gauge working. Removed and replaced sensor. Also found pins at plug bent. Pulled pins out and straightened up. Connected all back up. Road tested, all ok. ***$341.86***

Part Number	Part Description	Quantity	Total Cost
P21-1039	SENDER-AXLE TEMP	1.00	86.98
	Parts Totals:	***1.00***	***$86.98***

K011 Air leak fromthe yellow/red button area

found red button leaking. ***$450.00***
Correction: removed and replaced trailer air release button .spend time because other air leaks from dash. Removed dash panels and found multiple air leaks from manifolds. Need approval because can be big job to fix all.

Part Number	Part Description	Quantity	Total Cost
287280N	VALVE TRAILER CONTROL	1.00	255.80
	Parts Totals:	***1.00***	***$255.80***

K031-1 Customer reports of a banging noise under the cab

Found Heat Shrouds not secured andplate missing. Drilled old rivets out and re fitted plate and riveted both sides of Heat Shroud back on. Road tested and no more sound. ***$309.01***

K039-3 Set engine brakes to 0.7 second delay

Changed engine brake delay to 0.7 sec as per customer request. ***$57.01***

k031-2 Supply andfitgrille

Removed and replaced grille. FixedKWlogo cover flap bracket, all ok. ***$199.35***

Part Number	Part Description	Quantity	Total Cost
R45-1016-B	GRILLE - ASSEMBLY	1.00	3,748.96
Comments: HASNT BEEN GIVEN OUT YET			
	Parts Totals:	***1.00***	***$3,748.96***

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2951216***
Document Date:	4/08/2023
Repair Order No.:	852641
RO Creation Date:	26/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	520000
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	3 of 3

Warranty Repairs/Service At No Charge

Inspected under truck for leaks, found power steering oil leaking. Inspected lines, found leaking out of top reservoir lid gasket and suction hose. Drained power steering oil. Removed and replaced lid seal. Removed and replaced hose. Refilled and bled system. Adjusted oil level. Washed down and road tested, couldn't find any leaks.

Service Reminders Advisor:
0447015911 Use Premium blue oil.

Workshop Trading Hours: Mon-Fri 6:30am to 9:15pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

PART S	$4,410.63
LABOUR	$2,206.28
MISC. CONSUMABLES	$20.00
ENVIRONMENTAL LEVY	$10.00
SUBLET	$0.00
OTHER CHARGES	$0.00
TOTAL GST CHARGED	$664.69
TOTAL Incl. GST	$7,311.60

Customer's Signature

Bank Account Details for Direct Payments:
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd