BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3145527***
Document Date:	8/03/2024
Repair Order No.:	878057
RO Creation Date:	27/02/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	646938
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	1 of 5

k057 A/C fan inopDriver reported that the fans did cut back in when he hit a huge bump.

Drove truck in, a/c not working. Foundno power to fan, checked fuses all ok, checked relay found intermittently dropping in and out removed and found burnt out. Replaced relay and found the power supply to blower fan extremely hot, suspect fan drawing high current or resistor is. Replaced both as a pair and tested again all ok a lot less hot. Put all back together and let operate for a while and all ok. ***$193.17***

Part Number	Part Description	Quantity	Total Cost
1-1414687-0	RELAY-MINI,12V	1.00	70.08
25189003	FAN ASSEMBLY-BLOWER-12V	1.00	426.21
25189004	CONTROLLER-FAN SPEED	1.00	191.33
	Parts Totals:	***3.00***	***$687.62***

kwcsl KW C - Service Labour;

$1,271.15

Download Carry out download Insite
Check Ultra-Shift Latest Software In TECU
Carryout Ultra-Shift Grease Procedure
Reset Ultra-Shift Grease Interval
Reset Ultra-Shift Grade Sensor Calibration
Sample Engine Oil Sample
Change Engine Oil
Change Engine Oil Filter
Change Fuel Filters
Change SCR Air Filter & Carry out airside flush as per QSOL E5
Change Crankcase Breather If EGR Engine
Change Power Steering Oil & Filter
Check Ad-Blue System for Leaks, (Air & Ad-Blue)
Check Exhaust System & Report
Check or Change"Gearbox Oil Level, Take SOS
(Change 400,000kms for Synthetic Oil)"
Change Gearbox oil filter, Take SOS (Every 100,000kms)
Check or Change Auxiliary Transmission Oil Level (where applicable)
Change Diff Oils & Filter Remove & Clean Screen (Don't Change Oil If Synthetic But Change Filter)
Clean Combo Sensor (Cummins EGR Engines Only)
Sample If Diff Oil Is Synthetic Take Oil Sample
Change Power Steering Oil, Filter & Gasket
Change All Fan Belts & Check Pulleys & Idlers
Check Transmission Breathers (Remove & Clean If Required)
Check Diff Breathers (Remove & Clean If Required)

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3145527***
Document Date:	8/03/2024
Repair Order No.:	878057
RO Creation Date:	27/02/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	646938
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	2 of 5

Check Air Cleaner Element
Check Engine Oil Level after Starting
Check Radiator Coolant Level
Check & Record Coolant Antifreeze Concentration
Check Battery Electrolyte Level & Tighten Terminals
Check Front Wheel Bearings Play & Adjust
Change Steer Hub Oils, & Check For Contamination
Check Bell Housing Bolts
Change Clutch Fluid Level (DOT 4 ONLY)
Check Free Play in Steering & All Components
Lube All Grease Points, Replace Nipples Not Taking Grease
Fill Auto Greaser
Check Clutch Linkage Bolts
Check Driveline for Movement & Report
Change Air Dryer Filter
Check Tension Cab & Sleeper Mount Bolts
Check Tension U-Bolts
Check Tension Rear Suspension Bolts
Check Tension Steering Draglink Pinch Bolts
Check Tension Engine Mount Bolts - Front & Rear
Check Tension Radiator Mount Bolts - incl. Upper Stabilizer
Alignment. Centralize Steering Wheel
Top Up Windscreen Washer Bottle & Test Washers
Drain Air Tanks
Check Condition of All Air & Electrical Lines & eliminate Rubbing
Report Any Oil Leaks
Check Tension Radiator Hoses With Torque Wrench
Check Tension C.A.C Hoses with Torque Wrench
Lube Door Locks, Latches & Wedge Blocks with Silicon
Check Operation of All Lights, Gauges, Wipers & Horns
Check & Adjust Clutch
Check & Adjust Brakes
Check Interior Appointments
Check Retract Seatbelts For Operation & Fraying.
Clean Down Vehicle
Fit service sticker
****

Part Number	Part Description	Quantity	Total Cost
P182000	AIR FILTER ELEM	2.00	141.52

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3145527***
Document Date:	8/03/2024
Repair Order No.:	878057
RO Creation Date:	27/02/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	646938
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	3 of 5

K37-1004	FILTER-FUEL/WATER PACCAR	1.00	36.29
1324	PREMIUM BLUE 8600 BULK OIL	47.00	381.17
SOS3	Single Sample Kit (o	4.00	151.80
A3380W1687	FILTER ALLCOOL-MAINTENANCE	1.00	32.63
ALLC00L-WF	FILTER FUEL/WATER	1.00	40.46
FS19764	SEPARATOR CARTRIDGE AIR	1.00	39.89
T224P	DRYER	1.00	231.25
LF637	LUBE FILTER	1.00	39.40
AS2474	AIR/OIL SEPARATOR	1.00	17.14
TRPCAF000	TRP KW CAB AIR FILTER	1.00	25.78
1 17237	FILTER ELEMENT	1.00	51.14
FF5776	FUEL FILTER	1.00	61.38
LF14000NN	LUBE FILTER	1.00	56.66
BBC4	BRAKE CLEANER	1.00	4.99
3430285	TRANS DYNADRIVE LL 80W90	2.00	525.26
G	20L GREASE	1.00	15.00
	Parts Totals:	***68.00***	***$1,851.76***

K039-ETCUM — Engine Tune Cummins, Complete download, print and attach download to job card, complete top end set to specifications inspect intake system, exhaust system, cooling system and fuel system, complete general check over.

Completed Cummins Engine Tune, completed download and upgrade with latest file, completed top end set to specifications, inspected intake system, exhaust system and fuel system, completed general checkover. ***$475.00***

Part Number	Part Description	Quantity	Total Cost
3104392	GASKET VALVE COVER	1.00	159.70
BBC4	BRAKE CLEANER	1.00	4.99
	Parts Totals:	***2.00***	***$164.69***

misc — Fill out annualNHVR inspection sheet.

Fill out annual NHVR inspection sheetas required.

K031 — Reported thatthe intake pipe clamp has broken.

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3145527***
Document Date:	8/03/2024
Repair Order No.:	878057
RO Creation Date:	27/02/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	646938
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	4 of 5

Removed and replaced broken intake pipe and rubbers. ***$190.00***

Part Number	Part Description	Quantity	Total Cost
K077-445	CLAMP-AIR INTAKE	2.00	191.54
K161-3477-470	LINING-AIR INTAKE BAND	2.00	23.24
	Parts Totals:	***4.00***	***$214.78***

k031-1 Replace thewiper blades.

Removed and replaced wiper bladesand unblocked and adjusted washer jets all ok. ***$123.50***

Part Number	Part Description	Quantity	Total Cost
WW600B8B	WIPER BLADE 600x8MM B-FIX	2.00	55.58
	Parts Totals:	***2.00***	***$55.58***

K031-2 Cab will notlift.

Began service went to jack cab upandfound it would not lift above the cab locks more then 15 cms. ***$1,520.00***
Thought this was an issue with thepump, rechecked - noticed large amount of ATF coming out of the RHS ram. Tried to find the issue by bleeding lines and bungingthem. Conclusion was ram was seized. Was put on another job after this.
Attempt to assist single ram to tilt cabwith forklift, vehicle twisting on mounts.
Dropped cab, remove grill and wheel.cut ram, with ram unloaded was able release pin and unbolt from chassis. Removed ram in pieces, swapped over fittings and refitted ram while cab down.
Bleed system and tilt cab.
Refit wheel and torque, refit grill and pack away all lifting equipment.

Part Number	Part Description	Quantity	Total Cost
33X1/4	BSP CAP	1.00	2.46
20620-4-4	FITTING	1.00	11.58
639F-4	FLARE-SEAL-PLUG	2.00	5.26
K113-92	CYLINDER-ASSEMBLY CAB TILT	1.00	1,747.24
58F	5/8 UNF GR8 NYLOC NUT	1.00	0.66
	Parts Totals:	***6.00***	***$1,767.20***

K038 repair left sidelower radiator mount as temp repair, will repair properly next service.

Carried out repair on bottom radiatormount as required. ***$313.50***

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3145527***
Document Date:	8/03/2024
Repair Order No.:	878057
RO Creation Date:	27/02/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	646938
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	5 of 5

K046 Repair rooflights inop.

Checked for power and earth, foundno power and earth, rear lights clearance not working, front ones working, could not find fuse. Found fuse in overhead console behind a panel, fitted new light and light not working, roof light were wired in reversed, silicon and fitted lights, got vehicle checked over and washed down and parked up. ***$570.00***

Part Number	Part Description	Quantity	Total Cost
5000KLED	LAMP-ROOF MARKER LED,AMBER	1.00	72.85
56350-1	TERMINAL-ADHESIVE LINED	3.00	3.57
	Parts Totals:	***4.00***	***$76.42***

Service Reminders Advisor: Ryan Date
0447015911 Use Premium blue oil.

Workshop Trading Hours: Mon-Fri 6:30am to 9:15pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

PART S	$4,818.05
LABOUR	$4,656.32
MISC. CONSUMABLES	$50.00
ENVIRONMENTAL LEVY	$25.00
SUBLET	$0.00
OTHER CHARGES	$0.00
TOTAL GST CHARGED	$954.94
TOTAL Incl. GST	$10,504.31

Customer's Signature

Bank Account Details for Direct Payments:
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd