CRESTVIEW
CHRYSLER DODGE JEEP RAM

601 Albert St Regina SK CA S4R 2P4 www.crestviewchrysler.ca
+1(306) 525 - 5411

Customer Pay Invoice
$1,850.89

RO# : [redacted] Tag# : [redacted]
Check-in: Mon Oct 26, 2026 | 3:27 PM

Customer
[redacted]

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2019 Ram 2500 Diesel (6.7L)
3C6UR5TL2*KG598415*
166,408 Km In / 166,410 Km Out
In Service Date: 07/15/2019

Service Advisor
Kevin Brooks
84

1.	MPI	MULTIPOINT INSPECTION	Internal Pay	$0.00

1. INSP

Op.1 MPI -MULTIPOINT INSPECTION

Labor: $0.00

1. MULTI-POINT INSPECTION COMPLETED.

2.	DSLDIAG	Mill light on no drive ability issues	Customer Pay	$0.00

1. AS PER CUSTOMER REQUEST

Op.1 DSLDIAG -INSPECT/DIAGNOSE DIESEL CONCERN

Labor: $0.00

1. see section 4

3.	MISCTRM	Customer states drivers side running board is getting stuck in down posistion	Customer Pay	$0.00

1. AS PER CUSTOMER REQUEST - PLEASE NOTE MINIMUM DIAGNOSTIC FEE OF $265 WILL APPLY TO ANY NON WARRANTABLE ITEMS NOT COVERED BY THE MANUFACTURER OR THIRD PARTY WARRANTY COMPANIES.

Op.1 MISCTRM -INSPECT/DIAGNOSE TRIM CONCERN

Labor: $0.00

1. see section 5

4.	MIL	Replace particulate matter sensor, update pcm and replace air filter	Customer Pay	$1,590.45

Tags: Recommendation

1. mil light on. codes p2002 and p227f. found that air filter is plugged causing p227f and particulate matter sensor is causing code p2002. pcm needs to be flashed to latest software level

© Tekion Corp 2026

Op.1 MIL -INSPECT/DIAGNOSE CHECK ENGINE LIGHT (MIL)

Labor: $959.96

1. replaced particulate matter sensor, updated pcm and replaced air filter. found particulate matter sensor had been previously damaged and they had connector siliconed onto particulate matter sensor (no corrosion or no issues just was siliconed on). I resiliconed on the connector onto the new particulate matter sensor. if there is ever any issues with the connector side of things in the future the particulate matter sensor connector will need to be replaced. cleared codes and test drove vehicle. no codes returned at this time.

Parts $630.49

53034051AB - FILTER AIR 1 - $72.79

68354201AB - SENSOR PARTICULATE MATTER 1 - $557.70

5. RUNNINGBOARD LUBE AND CLEAN POWER RUNNING BOARDS Customer Pay $79.95

Tags: Recommendation

1. AS PER REQUEST

Op.1 RUNNINGBOARD -LUBE AND CLEAN POWER RUNNING BOARDS

Labor: $79.95

1. LUBED AND CLEANED RUNNING BOARDS AS REQUIRED IN OWNERS MANUAL. VERIFIED PROPER OPERATION

Additional Fees	Sale Amount
HAZ - HAZARDOUS MATERIAL	$5.00
FUEL - Fuel charges	$0.00

Labor	$1,039.91
Parts	$630.49
Sublet	$0.00
Sublet Labor	$0.00
Sublet Parts	$0.00
Fees	$5.00
Discounts	$0.00
Tax - GST	$79.77
Tax - PST	$95.72
Deductible	$0.00
Invoice Total	**$1,850.89**

Recommendation Approval Details

[redacted].

© Tekion Corp 2026

CRESTVIEW
CHRYSLER DODGE JEEP RAM

Customer Pay Invoice
$1,850.89

RO# : [redacted]

Recommendation Approval Details

Mode Of Communication	Approver Phone Number	Previous Estimate	Revised Estimate
Call	[redacted]	$1,424.23	$3,269.58

Date and Time	Note
Tue Oct 27, 2026 at 12:09 PM	[redacted]

TERMS: Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Any warranties on the product sold hereby are those made by the manufacturer.

DISCLAIMER OF WARRANTIES: The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Mopar parts warrants 24 months on defects and workmanship for parts & labour on dealer installed retail date of purchase or the installation date by installer. Any limitation contained herein does not apply where prohibited by law.

X
Customer Signature

Date

© Tekion Corp 2026