BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	1 of 12

K031 L/H CAB SCREEN AND R/H WINDSCREEN CRACKED (SUPPLY GLASS FIXER TO FIT)

Sublet The Fixer ***$397.73***
PO W464898
Invoice FIX-11930
Fit own RH windscreen to suit K200
Fit own LH Sleeper screen to suit K200

Part Number	Part Description	Quantity	Total Cost
R44-1065	GLASS - SLEEPER WINDOW	1.00	427.78
TRP257-2	WINDSCREEN CURVED RIGHT HAND	1.00	201.60

Comments: Coming from bris BPDC

Parts Totals: ***2.00*** ***$629.38***

K022 WALK PLATEMISSING

Marked up, drilled and mounted andsecured the new chassis walk plate. Alll plates needed to be tapped out and threads cleaned. ***$270.00***

Part Number	Part Description	Quantity	Total Cost
K350-1857-1200050050	PLATE-FRAME WALKWAY	1.00	866.08

Comments: 6 WEEK LEAD TIME

W16-1009	CLAMP-WALKWAY	4.00	240.68
16710005	3/8 X 2 UNC COUNTERSUNK	4.00	4.20
2	FREIGHT	1.00	60.00
FREIGHT			

Parts Totals: ***10.00*** ***$1,170.96***

K046-1 ELECTRIC HORNS INOPERATIVE

Checked the power and earth for thehorn, traced fault to the electric horn, removed and replaced the electric horn. ***$180.00***

Part Number	Part Description	Quantity	Total Cost
P49-1005-100	ELECTRIC HORN-12V	1.00	109.88

Parts Totals: ***1.00*** ***$109.88***

K015 GEARBOXOIL LINES LEAKING

Drained the transmission oil, removedthe hoses clamps and p-clamps and removed the all oil hoses, Cut new oil hoses to length and fitted hose ends, fitted the new hoses and secured all, and refilled the transmission with oil. ***$720.00***

Part Number	Part Description	Quantity	Total Cost
20620-10-10	FITTING	4.00	49.60

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	2 of 12

639F-10	FLARE-SEAL, PLUG	2.00	15.28
640F-10	ADPT CAP 450 FLARE 7/8-14	2.00	15.28
201-10/1	HOSE-125M ROLL	17.00	163.98
23920-10-10	SWIVEL ELBOW	1.00	37.10
9X3874	Coupling	2.00	75.62
P14362-092	CLAMP-CUSHIONED 1-1/2"ID	10.00	38.90
K275-7149	BRACKET-STAND OFF	3.00	13.47
12HTW	WASHER 1/2 GR8 H/T FLAT Z	2.00	0.28
P14362-002	CLAMP-CUSHIONED 1-1/8"ID	2.00	6.12
P14362-040	CLAMP-CUSHIONED 7/8" ID	3.00	12.06
P14362-080	CLAMP-CUSHIONED 2-1/2"ID	1.00	4.39
A11-1501	BRACKET-STANDOFF	2.00	41.06
	Parts Totals:	***51.00***	***$473.14***

K051 POWER STEERING RESIVOUR LEAKING

Cleaned the reservoir and found to beleaking at return side hose. Drain oil and inspected, found oil leaking form a failed hose and from a leaking fitting. Found the o-ringon the fitting to have gone hard and split. Replace failed o-ring and resecured the fitting. Removed and replaced the failed hose.Refilled the system with oil and ran up and bled the power steering. ***$270.00***

Sublet: Pirtek WA-T00086259 ***$546.84***

PO: W469987

Power Steering Hose

Part Number	Part Description	Quantity	Total Cost
3381101	ATF DEX III 3X4L	2.00	80.40
Q66250	WASHER	1.00	9.65
	Parts Totals:	***3.00***	***$90.05***

K031-2 PASSENGERSEAT BELT NOT RETRACTING

Inspected and found the seat belt frayed and unserviceable, removed and replaced the seat belt. ***$180.00***

Part Number	Part Description	Quantity	Total Cost
SB2700	SEAT BELT-554B L/H	1.00	447.48
	Parts Totals:	***1.00***	***$447.48***

K015-2 GEARSHIFTCABLES EXTREMELY TIGHT

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE
A.B.N. 66 010 732 966
2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	3 of 12

Inspected and found the gear cables tight and unserviceable, disassembled and removed and replaced both cables, reassembled all and adjusted. ***$720.00***

Part Number	Part Description	Quantity	Total Cost
E92-1044-130	CABLE-TRANSMISSION	1.00	563.23
E92-1044-149	CABLE-TRANSMISSION	1.00	643.75
4305294 161-087-009	GASKET U-BOLT	1.00	19.34
		2.00	49.46
	Parts Totals:	***5.00***	***$1,275.78***

K032 L/H FUEL TANK CRACKED (EPOXY REPAIRED) REMOVE SEND TO ARROWS

Removed the tank and refitted the tank in conjunction with repairs on K032-1

K032-1 FUEL TANKSTRAP RUBBERS R/H/S and LHS SPLIT

Inspected, found multiple J-Bracketsbent and straps unserviceable on the RHS and LHS fuel tanks. Found a number of fuel tank straps needing to be cut to allow removal. Drained and removed the fuel tank that was to be sent away for repairs. Straightened the bent J-Brackets, and refitted the repaired fuel tank once returned, replaced the unserviceable straps and rubbers and reassembled all and secured. ***$900.00***

Part Number	Part Description	Quantity	Total Cost
K231-524P0L	STRAP SQUARE FUEL TANK	3.00	1,194.12
K161-4819-1	LINING-FUEL TANK STRAP	11.00	394.13
K231-496P0L	FUEL TANK STRAP SQUARE	2.00	633.24
K231-497P0L	STRAP-SUARE FUEL TANK	2.00	975.52
1/2HDWASHZP	WASHER 1/2 x 27.00 x 3.0mm	32.00	21.76
K161-3477-470	LINING-AIR INTAKE BAND	1.00	11.16
FREIGHT	FREIGHT	1.00	10.00
	Parts Totals:	***52.00***	***$3,239.93***

K039-2 ENGINE REBUILD REQUIRED, RECORDED 24INCH MECURY MAX ALLOWABLE 18INCH

Disassembled the engine, cleaned and inspected all, fitted the new cylinder liners and carried out liner protrusion measure, found liner heights in spec and no need for a counter bore. Fitted the new liners and reassembled the engine with overhaul kit, carried out main bearing roll, fitted the pistons and connecting rods and new big end bearings. Fitted replacement cylinder head, oil pump and water pump. Found the idler pulley bearings noisy and rough, removed and replaced the idler pulley bearings. Replaced oil and coolant with new. Replaced the unserviceable CAC hoses and clamps. Completed the engine reassembly and ran up the engine. ***$8,549.99***

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	4 of 12

Found coolant leak from engine after road test, inspected and found coolant leak from the coolant bypass, removed the turbo and removed and replaced the bypass pipe orings. Reassembled all and checked for further leaks.

Part Number	Part Description	Quantity	Total Cost
1324.20	PREMIUM BLUE 8600 20L OIL	3.00	445.83
5680039RX	RECON LUBE PUMP ISX	1.00	1,727.39
90-0013	CLAMP-5" V-BAND	2.00	117.04
ELC40-20M	PACGEN ELC40 PREMIX 20L	3.00	350.46
BBC4	BRAKE CLEANER	6.00	27.90
L0C30013	LOCTITE 609 MED / HIGH STRENGT	2.00	33.28
WF2127	ES WATER FILTER (NON CHEM) (CU	1.00	50.91
L0C39145	LOCTITE 598 BLACK MAXX SILICON	1.00	16.81
5658203RX	RECON CYL HEAD ISXE5	1.00	8,760.92
639F-8	FLARE-SEAL-PLUG	1.00	3.89
640F-8 6303-	CAPNUT	1.00	3.07
2RSH	BEARING	2.00	10.80
3391271	LUBRIPLATE 105 GREASE 10OZ TBE	2.00	37.40
3680781	SCREW HEXAGON FLANGE HEAD CAP	10.00	303.60
3678506	SCREW HEXAGON FLANGE HEAD CAP	7.00	705.81
3102651	SCREW HEXAGON FLANGE HEAD CAP	4.00	72.92
5693737	KIT OVERHAUL	1.00	12,018.74
3685173	SEAL OIL	1.00	297.16
FREIGHT	FREIGHT	1.00	150.00
3163075	"PAINT ""300 APEX RED"" 12.05OZ"	2.00	132.24
5575513	SCREW HEXAGON FLANGE HEAD CAP	1.00	45.15
4101451	SCREW HEX HEAD CAP	4.00	59.44
4907447	GASKET EXHAUST MANIFOLD	4.00	168.04
4907448	GASKET EXHAUST MANIFOLD	1.00	54.30
4026884	GASKET TURBOCHARGER	1.00	50.25
3679139	SEAL O RING	2.00	54.18
2866337CU	GASKET 5"	5.00	180.35
M HE8761XL	HOSE-HUMP,4"X 4.5"X7" TRP	1.00	76.26
HE8699 848-	HUMP HOSE 4" to 4"	2.00	130.72
66X 848-74	CLAMP-HOSE,105-113MM	9.00	192.06
4795399	CLAMP-TORQUE 41/2"	2.00	28.94
5719759	Paint-Black	1.00	24.76
	CORE WATER PUMP	1.00	1,240.89

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	5 of 12

3684384	SEALO RING	1.00	52.07
P14362-030	CLAMP-CUSHIONED 1-3/8"ID	4.00	16.72
1600366	HOSE	2.00	877.22
1675741	HOSE CLIP	2.00	169.34
3066211	O-RING	1.00	40.49
3067979	CLAMP V BAND BYLAW	1.00	251.10
34HTW	WASHER 3/4 GR8 H/T FLAT Z	4.00	1.36
34F	3/4 UNF NYLOC GR8 NUT	2.00	3.20
34-300F	3/4 X 300 UNF GR8 BOLT	2.00	4.18
	Parts Totals:	***105.00***	***$28,987.19***

K011 MAXI-BRAKEBUTTON JAMMING WHEN RELEASED

Unable to fault at this time.

K025 FIT NEW GREASELESS TURNTABLE JSK37CW

Removed and replaced the turntableas requested. ***$360.00***

Part Number	Part Description	Quantity	Total Cost
JSK37C-D6GF-WFC/1P	5W37C PED+PLATE18516MM FLATDP-1PCASTLOW.	1.00	3,892.00
Comments: EX JOST			
BK-0020	BOLT KIT	1.00	142.61
	Parts Totals:	***2.00***	***$4,034.61***

K031-1 FIT NEW MATTRESS, SECURE BACKBOARD (LOOSE AND RATTLING)

Removed and replaced the mattressas per customers request. ***$90.00***

Part Number	Part Description	Quantity	Total Cost
U12-1046	MATTRESS-KING SINGLE	1.00	1,074.38
	Parts Totals:	***1.00***	***$1,074.38***

K031-4 REPAIR INTERIOR TRIMS, OVERHEAD CONSOLE LOOSE, DOOR CARDS MISSING TRIM PIECE, SECURE HEAD UNIT INTO PLACE.

Repairs carried out by Protruck in conjunction with charges on K031-5

Part Number	Part Description	Quantity	Total Cost

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE
A.B.N. 66 010 732 966
2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	6 of 12

S18-	BEZEL-INSIDE DOOR RELEASE	1.00	71.25
1033R	BEZEL-INSIDE DOOR RELEASE	1.00	71.25
S18-1033	PLUG-DOOR PULL REAR	1.00	0.44
S67-1025	PLUG-DOOR PULL FRONT SCREW-	1.00	5.86
S67-	STEEL,6X40MM BLK 2N XREC	4.00	1.52
1024R	SCREW STEEL 10-32X1 UNF PAN XR	6.00	1.80
38089	***Parts Totals:***	***14.00***	***$152.12***
38993			

K024 REPAIR RIDEHEIGHT, BOTH CONTROL VALVES ON REAR DRIVE LOOSE, RESET RIDE HEIGHT.

Removed the suspension ride heightvalves and removed and replaced the worn linkage ball joints, set up the new valves and adjusted the suspension ride heightstospec. ***$405.00***

Part Number	Part Description	Quantity	Total Cost
H00500C	VALVE-UNIVERSAL HEIGHT CONTROL	2.00	461.40
VF5G-8	BEARING-ROD END	4.00	172.60
L0C56747	LOCTITE 567 HI TEMP CONTROLLED	1.00	29.56
	Parts Totals:	***7.00***	***$663.56***

K038 REMOVE INTERCOOLER AND RADIATOR, SEND TO WESTERN SUBURBS (CUSTOMER PAYING DIRECT)

Recovered the a/c refrigerant. Removed the radiator package, and sent to vendor for repairs as requested, refitted the radiator package once returned from the vendor, and reassembled all. Removed and replaced the receiver drier, vacuumed and recharged the system with refrigerant. ***$720.00***

Part Number	Part Description	Quantity	Total Cost
201-4/1	HOSE REEL (140 METRES O	1.00	8.04
20620-4-4 K251-571	FITTING	2.00	17.42
K363-390	FILTER-FREON, RECEIVER/DRYER	1.00	139.70
58C	WASHER-RADIATOR MTG	2.00	23.92
K363-284 40012	5/8 UNC NYLOC GR8 NUT	2.00	1.34
R134A	WASHER	2.00	8.48
A/C OIL AND ORINGS	CLAMP-HOSE SIZE 14-32MM	4.00	19.48
	A/C GAS AND DYE	1.00	85.00
	A/C Oil AND ORINGS	1.00	15.00
	Parts Totals:	***16.00***	***$318.38***

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	7 of 12

K031-5 REPAIR BUNK COOLER AND CARRY OUT SERVICE & MULTIPLE DASH LIGHTS INOPERATIVE (PRO TRUCK ELECTRICAL)

Sublet: Protruck Electrical PT-11622 ***$1,687.35***
PO: W464901
Replace mattress in bunk. fix back wall loose. Fix roof console loose. Replaced missing screws and bolts in cab. Fit radio properly. Replaced missing interior trims. Replaced dash globes and holders as required. Service custom air. Replaced custom air engine mount. Tune custom air valves. Run custom air, test ok. Diagnose horn not working

Part Number	Part Description	Quantity	Total Cost
S67-1024	PLUG-DOOR PULL FRONT	1.00	6.81
800005002	HOLDER-GLOBE	6.00	39.54
47504	GLOBE-WEDGE,12V3W,T-10(BOX 10)	1.00	6.01
W122	GLOBE,WEDGE BASE 12V2W	2.00	3.00
PX49450	SUPER GLUE 28G	1.00	18.14
HWC02452	NUT-CLIP,100 DEGREE C/SUNK	2.00	6.78
	Parts Totals:	***13.00***	***$80.28***

KWCSL KW C - Service Labour;

Download Carry out download Insite ***$1,170.00***
Check Ultra-Shift Latest Software In TECU
Carryout Ultra-Shift Grease Procedure
Reset Ultra-Shift Grease Interval
Reset Ultra-Shift Grade Sensor Calibration
Sample Engine Oil Sample
Change Engine Oil
Change Engine Oil Filter
Change Fuel Filters
Change SCR Air Filter & Carry out airside flush as per QSOL E5
Change Crankcase Breather If EGR Engine
Change Power Steering Oil & Filter
Check Ad-Blue System for Leaks, (Air & Ad-Blue)
Check Exhaust System & Report
Check or Change"Gearbox Oil Level, Take SOS
(Change 400,000kms for Synthetic Oil)"

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	8 of 12

Change Gearbox oil filter, Take SOS (Every 100,000kms)
Check or Change Auxiliary Transmission Oil Level (where applicable)
Change Diff Oils & Filter Remove & Clean Screen (Don't Change Oil If Synthetic But Change Filter) Clean Combo Sensor (Cummins EGR Engines Only)
Sample If Diff Oil Is Synthetic Take Oil Sample
Change Power Steering Oil, Filter & Gasket
Change All Fan Belts & Check Pulleys & Idlers
Check Transmission Breathers (Remove & Clean If Required)
Check Diff Breathers (Remove & Clean If Required)
Check Air Cleaner Element
Check Engine Oil Level after Starting
Check Radiator Coolant Level
Check & Record Coolant Antifreeze Concentration
Check Battery Electrolyte Level & Tighten Terminals
Check Front Wheel Bearings Play & Adjust
Change Steer Hub Oils, & Check For Contamination
Check Bell Housing Bolts
Change Clutch Fluid Level (DOT 4 ONLY)
Check Free Play in Steering & All Components
Lube All Grease Points, Replace Nipples Not Taking Grease
Fill Auto Greaser
Check Clutch Linkage Bolts
Check Driveline for Movement & Report
Change Air Dryer Filter
Check Tension Cab & Sleeper Mount Bolts
Check Tension U-Bolts
Check Tension Rear Suspension Bolts
Check Tension Steering Draglink Pinch Bolts
Check Tension Engine Mount Bolts - Front & Rear
Check Tension Radiator Mount Bolts - incl. Upper Stabilizer Alignment.
Centralize Steering Wheel
Top Up Windscreen Washer Bottle & Test Washers
Drain Air Tanks
Check Condition of All Air & Electrical Lines & eliminate Rubbing
Report Any Oil Leaks
Check Tension Radiator Hoses With Torque Wrench
Check Tension C.A.C Hoses with Torque Wrench
Lube Door Locks, Latches & Wedge Blocks with Silicon
Check Operation of All Lights, Gauges, Wipers & Horns

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	9 of 12

Check & Adjust Clutch
Check & Adjust Brakes
Check Interior Appointments
Check Retract Seatbelts For Operation & Fraying.
Clean Down Vehicle
Fit service sticker
****

Brake lining condition
LHF 1st 14mm RHF 1st 14mm
LHFD 12mm RHFD 12mm
LHRD 12mm RHRD 12mm
Road test.

Part Number	Part Description	Quantity	Total Cost
FS19764	FUEL/WATER SEPARATOR	1.00	34.55
P182000	AIR FILTER ELEM	2.00	125.26
A3380W1687	FILTER	1.00	31.08
3430302	TRANS AXLE AP 85W-140 20L	2.00	301.48
WF2071	WATER FILTER (DCA IV)	1.00	26.29
T224P	CARTRIDGE AIR DRYER	1.00	231.25
TRPCAF0001	TRP KW CAB AIR FILTER	1.00	25.78
LF637	LUBE FILTER	1.00	38.63
AS2474	AIR/OIL SEPARATOR	1.00	16.03
3415488-1	TRANSMAX MANUAL E 40 LONGLIFE	15.00	632.10
17237	FILTER ELEMENT	1.00	51.14
4304023	O'RING - FILLER PLUG	1.00	27.75
K37-1004	FILTER-FUEL/WATER PACCAR	1.00	34.04
G	GREASE	1.00	15.00
	Parts Totals:	***30.00***	***$1,590.38***

k031-6 Both rear cabmounts

Removed and repalced the rear cabmounts and pads. Reassembled all and secured. ***$270.00***

Part Number	Part Description	Quantity	Total Cost
R85-1185	SUPPORT - REAR ASSY C.O.E CAB	2.00	1,007.04
78F	7/8 UNF NYLOC GR8 NUT	2.00	1.72
7/8HDWASHZP	WASHER 7/8 x 44.00 x 3.5mm	4.00	5.80
78-512F	7/8 X 5 1/2 UNF GR8 BOLT	2.00	15.38

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	10 of 12

K274-166	PAD-WEAR	2.00	169.1
K163-311	CAB-LATCH ASSEMBLY	2.00	0
			404.9
Comments: OTHER 1 IS COMING FROM YATALA			
	Parts Totals:	***14.00***	***$1,604.02***

k038-1 Replace allcooling hoses

Removed and replalced the hoses andclamps, and removed and replaced the leaking heater tap. ***$185.00***

Part Number	Part Description	Quantity	Total Cost
V404P-10-6	TAP-HEATER	2.00	33.66
B9228-0275B	CLAMP	8.00	86.64
80-062T	HOSE-SILICON 5/8" (PER FOOT)	21.00	158.13
P14362-058	CLAMP-CUSHIONED 2" ID	1.00	5.29
	Parts Totals:	***32.00***	***$283.72***

K031-7 Cab tilt not working, hoses leaking

Inspected and found the cab tilt pumpleaking internally, removed and replaced the cab tilt pump, refilled and bled the cab tilt. ***$225.00***

Part Number	Part Description	Quantity	Total Cost
AU1540422	PUMP ASSY-AIR ASSIST CAB TILT	1.00	2,241.14
	Parts Totals:	***1.00***	***$2,241.14***

K046-3 REPLACE BATTERY CABLES.

PRO TRUCK

Sublet: Protruck PT-11681 ***$1,781.00***
PO: W468692
Inspect starting and charging battery cables. Remove cables as required. Make and fit 2 positive starter cables and 2 negative starter cables and both alternator cables.

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	11 of 12

Truck starts ok. Charge rate tested ok

K038-2 REKIT HORTON

Disassembled and removed the Horton, disassembled the Horton, cleaned and inspected all, re-kitted and overhauled the Horton. Found also leak coming from fittings, removed and replaced the leaking fittings, had to also replace the filter due to the fittings being seized. Refitted the Horton and built up air pressure, checked operation and checked for leaks. ***$540.00***

Part Number	Part Description	Quantity	Total Cost
F250130B	FAN DRIVE KIT CONVERSION K200/	1.00	1,208.08
F100724	KIT-DMA-2 SPEED MAGNETS	1.00	631.66
716-100F	7/16 X 1 UNF BOLT	8.00	7.12
716F	7/16 UNF NYLOC GR8 NUT	8.00	2.64
84103	JOINER FITTING 5/32 (PUSH)	3.00	67.32
	Parts Totals:	***21.00***	***$1,916.82***

k011-1 REPAIR AIRLEAKS

Inspected and checked over the airsystem for leaks, removed and replaced a leaking pass through connector and fitting near the transmission. Removed and repairstwoother airline connection near the transmission. Removed and replaced leaking air tank drain valve and removed and replacedaleaking air hose. Found multiple P-Clamps broken, twisted and unserviceable, replaced with new. Found air leak from connectorbehind the driver seat, repaired leak and secured. Removed and replaced the leaking air tank drain valve. FItted the missing silencer to the air drier. ***$450.01***

Part Number	Part Description	Quantity	Total Cost
62PTC-8	FITTING PUSH TO CONNECT	2.00	29.16
62PLBH-4	FITTING-PUSH TO CONNECT	1.00	6.86
62PTC-6	FITTING - PTC JOINER 3/8"	1.00	12.45
3182-56-00	FITTING-90 DEG PUSH IN	1.00	5.39
K299-814	CLIP-AIR BRAKE HOSE VALVE-	2.00	21.08
K295-75-815	DRAIN,CABLE RELEASE CLAMP-	3.00	130.59
P14362-020	CUSHIONED 1/4" ID SILENCER-	2.00	7.98
EM50	1/2NPT SINTERD BRONZE CLAMP-	1.00	12.75
P14362-052	CUSHIONED 3/8" ID SWITCH-	2.00	6.54
FD20-2111-4PS1	PRESSURE 4PSI NC HOSE-ASSY	1.00	66.79
K342-934-965		1.00	217.00
	Parts Totals:	***17.00***	***$516.59***

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***2945432***
Document Date:	28/07/2023
Repair Order No.:	849731
RO Creation Date:	3/07/2023
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	12 of 12

COI1 Complete Roadworthy Inspection as per inspection sheet for vehicles between 4.5T and 16T

Completed Roadworthy Inspection asper inspection sheet for vehicles between 4.5T and 16T

Part Number	Part Description	Quantity	Total Cost
COI MORE THAN 16T	COI more than 16t	1.00	144.55
	Parts Totals:	***1.00***	***$144.55***

Misc Vehicle has just been bought. Carry out inspection of unit and note all defects.Carry out download and blowby test and then discuss with elliott. (Line Brought over for RO 849420)

Carried out inspection and reported findings to customer. (Line Brought over for RO 849420) ***$180.00***

Service Reminders Advisor: Allan Mungai
0447015911 Use Premium blue oil.

Workshop Trading Hours: Mon-Fri 6:30am to 9:15pm, Sat 8am to 12pm *** Refrigerant trading authority number: AU13435 ***

PART S	$51,044.34
LABOUR	$16,380.00
MISC. CONSUMABLES	$505.68
ENVIRONMENTAL LEVY	$50.00
SUBLET	$4,412.92
OTHER CHARGES	$5.00
TOTAL GST CHARGED	$7,239.79
TOTAL Incl. GST	$79,637.73

Customer's Signature

Bank Account Details for Direct Payments:
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd