EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	WorkType	WorkState	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1034	Woodongs - Workshop	Impl/Truck dec	remove mtdata		MT data removed and dash put back together	28/07/2026	1276141	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Woodongs Workshop	P/MOVER
1034	Woodongs - Workshop	Tyres/WORN OUT	Tyres WORN OUT POS 1 + 5-6 + 7-8 + 9-10 + 11-12			16/07/2026	1276141	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	BORDER BANDAG PTY LTD	P/MOVER
1034	Myrtleford - Workshop	Body/DAMAGE	CHECK UNDER TRUCK FOR DAMAGE THE DRIVER RAN OVER A SIGN LAYING ON THE ROAD		CHEK OVER UNDER 1034 FOR DAMAGE ALL OK	25/06/2026	1276141	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS	KLM AT TIME OF SERVICE 1.277.778	20/06/2026	1276141	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Body/ELECT P&W	NO PARK LIGHTS ON TRAILER (CHIP)		FOUND PARK LIGHT WIRE TO BE PULLED OUT OF PIN (NO?) REFITTED AND TESTED ALL GOOD (CALL OUT)	18/06/2026	1276141	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS	KLM AT TIME OF SERVICE 1.269281	04/06/2026	1259201	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			TRU SHAFT SEAL STARING TO LEAK													
1034	Myrtleford - Workshop	DriveLine/OIL LEAK	THERE IS SOME MOVEMENT IN THE HTRU SHARP BEARINGS			27/05/2026	1258200	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS		27/05/2026	1258200	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Woodongs - Workshop	Tyres/TP5+6	Tyres(TP5+6			22/05/2026	1258200	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	BORDER BANDAG PTY LTD	P/MOVER
1034	Woodongs - Workshop	Tyres/TP7+8	Tyres(TP7+8			22/05/2026	1258200	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	BORDER BANDAG PTY LTD	P/MOVER
			VehService/@1 Svc B 1 Service,													
			Jack up steer axle check bearings and king pins.													
1034	Myrtleford - Workshop	VehService/@1 Svc	Replace cabin filter.	VehService/@1 Svc	KLM AT TIME OF SERVICE 1.262007	20/05/2026	1257100	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Woodongs - Workshop	Tyres/Punct	Tyres(Punct POS 9			19/05/2026	1212050	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	BORDER BANDAG PTY LTD	P/MOVER
			REPLACE FRONT DRIVE TIRES X4													
1034	Myrtleford - Workshop	Tyres\TP03	HOOK UP TO T534			13/05/2026	1257100	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	DONE AT 255306KMS	08/05/2026	1212050	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Steering/OIL LEAK	REPLACE POWER STEERING BOX INPUT SHAFT SEAL KIT			07/05/2026	1212050	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG		07/05/2026	1212050	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Elect/BATTERY	CHANGE BATTERIES OUT OF 1031 INTO 1034			28/04/2026	1212050	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG		28/04/2026	1212050	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Woodongs - Workshop	Tyres\TP9+10	Tyres\TP9+10			09/04/2026	1212050	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	BORDER BANDAG PTY LTD	P/MOVER
1034	Woodongs - Workshop	Tyres\TP11+12	Tyres\TP11+12			09/04/2026	1212050	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	BORDER BANDAG PTY LTD	P/MOVER
			REPLACE ALL 4 DRIVE TYRES ON REAR AXLE OF 1034													
1034	Myrtleford - Workshop	Tyres\FITMENT	DONE AT			08/04/2026	1212050	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/@S	VehService/@S B Service	VehService/@S	DONE AT 1.240693 KMS	08/04/2026	1212050	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			REPLACE COOLANT PIPE O RINGS BEHIND TURBO													
			REPLACE BOTH HEATER TANK													
1034	Myrtleford - Workshop	Engine\COOL LEAKS	TOP UP COOLANT & ROAD TEST & RECHECK FOR LEAKS			19/03/2026	1212050	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	KLM AT TIME OF SERVICE 1.234725	17/03/2026	1212050	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS		06/03/2026	1211850	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Engine\ENG FAN	REPLACE DAMAGED ENGINE FAN (CRACKED MOUNT FACE)		KLM AT TIME OF REPAIR 1.225200	20/02/2026	1211850	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					REPLACED DUE TO BEEN CRACKED ON UNDER SIDE											
1034	Myrtleford - Workshop	Cooling\COOL LEAKS	REPLACE LEAKING SURGE TANK		KLM AT TIME OF REPAIR 1.225200	20/02/2026	1211850	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					KLM AT TIME OF SERVICE 1.224850											
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS	KLM AT TIME OF SERVICE 1.224850	20/02/2026	1211850	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			VehService/@1 Svc B 1 Service,													
			Jack up steer axle check bearings and king pins.													
1034	Myrtleford - Workshop	VehService/@1 Svc	Replace cabin filter.	VehService/@1 Svc	REPLACED LH FRONT DRIVE SHOCKER	11/02/2026	1202213	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			VehService/AS A Service													
1034	Myrtleford - Workshop	VehService/AS	SERVICED AT 215482 KMS	VehService/AS	REPAIR WIRING IN LH HLIGHT	04/02/2026	1202213	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Engine\LNG TUNE	TUNE UP ENGINE		ENGINE TUNE UP DONE AT 213895 KMS	30/01/2026	1202213	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
					Pressure test and inspect radiator assembly											
					Found leaking from rubbed tube											
					Open tube, clean and aluminium 2pak glue											
					Allow glue to set, repressure test											
1034	Myrtleford - Workshop	Cooling\RADIATOR	REPAIR LEAKING RADIATOR CORE		Extend sleeve pipe - Re-seal weld	16/01/2026	1202213	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS	KLM AT TIME SERVICE 1208958	16/01/2026	1208958	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					KLM AT TIME OF SERVICE 1.202213											
					TRANS FITTER CHANGED BUT NOT OIL DUE TO IT BEEN DONE AT											
1034	Myrtleford - Workshop	VehService/CS	VehService/CS C Service	VehService/CS	1.125256	10/12/2025	1202213	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	DriveLine/DIFF OIL	DriveLine/DIFF OIL Replace Diff oils	DriveLine/DIFF OIL	CARRIED OUT ON C-SERVICE AT 1.202213	10/12/2025	1202213	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					KLM AT TIME OF SERVICE 1.196345											
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	PLUS HOOK UP	26/11/2025	1196345	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Hydraulic/HYD LEAKS	REPLACE HYD COUPLINGS REAR OF TRUCK			20/11/2025	1185003	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS	KLM AT TIME OF SERVICE 1.189075	11/11/2025	1189075	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Elect/ELECT P&W	7 PIN ELE PLUG NEEDS REPLACING			11/11/2025	1185003	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			VehService/@1 Svc B 1 Service,													
			Jack up steer axle check bearings and king pins.													
1034	Myrtleford - Workshop	VehService/@1 Svc	Replace cabin filter.	VehService/@1 Svc	KLM AT TIME OF SERVICE 1185003	31/10/2025	1185003	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	KLM AT TIME OF SERVICE 1180417	22/10/2025	1180417	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			REPLACE LH & RH STEER KING PINS													
			REPLACE LH & RH STEER WHEEL BEARINGS													
1034	Myrtleford - Workshop	DriveLine/KING PIN	REPLACE SECAM SEALS		KLM AT TIME OF REPAIR 1.175627	10/10/2025	1175627	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Woodongs - Workshop	Tyres\TP1+2	Tyres\TP1+2			10/10/2025	1175627	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	BORDER BANDAG PTY LTD	P/MOVER
					ADJUST T/TABLE JAWS & GREASE											
					TOP UP HYD OIL											
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG		08/10/2025	1169424	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS	KLM AT TIME OF SERVICE 1.169424	24/09/2025	1169424	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					REPLACED X2 UNIS											
1034	Myrtleford - Workshop	DriveLine/UNI JOINTS	REPLACE JACK SHAFT UNIS		KLM AT TIME OF REPAIR 1.164761	12/09/2025	1155807	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/@S	VehService/@S B Service	VehService/@S	KLM AT TIME OF SERVICE 1.164761	12/09/2025	1155807	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					MAKE UP TOW PIN FOR FRONT OF TRUCK TO FIT TOWING POINT											
					KLM AT TIME OF SERVICE 1.161069											
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	HOOK UP ON AFTER SERVICE	05/09/2025	1151807	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG		01/09/2025	1147807	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	DriCab/wip\WIPERS	wiper blades need replacing			01/09/2025	1147807	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			REPLACE DOSER PUMP & HOSES													
1034	Myrtleford - Workshop	Engine\ADBLUE	CLEAR ALL CODES & TEST ALL OK			28/08/2025	1147807	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	TWIN CITY TRUCK CENTRE - 3 - OLD	P/MOVER
1034	Myrtleford - Workshop	Elect\ELECT P&W	NO TRAILER LIGHTS AT ALL		CALL OUT TO NO LIGHTS ON TRAILER FOUND PROBLEM IN 7 PIN ELE PLUG REPAIR WIRING AND TESTED ALL GOOD	28/08/2025	1150807	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Engine\FAULT CODE	CHECK AND REPAIR AFTER TREATMENT LIGHT ON		CHECK FAULT CODE CLEARED 42 BLUE INJECTOR AND CARRIED OUT SYS FLUSH FAULT CODE THEN WENT OUT (KLM AT TIME OF REPAIR 1.143507)	21/08/2025	1143507	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Chassis\GUD COIL	REPLACE SUZI COIL LEADS AND REPAIR ELE 7 PIN PLUG		KLM AT TIME OF REPAIR 1.147807	02/08/2025	1147807	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			VehService/@1 Svc B 1 Service,													
			Jack up steer axle check bearings and king pins.													
1034	Myrtleford - Workshop	VehService/@1 Svc	Replace cabin filter.	VehService/@1 Svc	KLM AT TIME OF SERVICE 1.145777	29/07/2025	1145777	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	KLM AT TIME OF SERVICE 139073	12/07/2025	1134894	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					KLM AT TIME OF SERVICE 1.134893											
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	REPLACED DRIVERS SIDE WEATHER SHIELD	02/07/2025	1134894	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			CHECK FOR DRIVE LINE VIBRATION UNDER LOAD													
			INSPECT ALL UNIS DIRTY & ALL SLIP COMPONETS (ALL OK)													
1034	Myrtleford - Workshop	DriveLine/DRIVES	CHANGE FRONT DIFF OIL & FILTER ALL OK IPOWER DIVIDER MAY HAVE BEEN LEFT IN !			25/06/2025	1129100	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					replaced bonnet rest											
					repained RH indicator											
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	KLM at time of service 1130850	18/06/2025	1134831	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Body/FUEL TANK	FRONT "J" BRACKETS CRACKED BOTH SIDES.		inspected and still ok	17/06/2025	1129100	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Susp\HCV	replace both ride height control valves			16/06/2025	1129100	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Brakes\YEL VALVE	yellow button leaking air and hard to release			13/06/2025	1129100	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Impl/ANN INSP	Annual Inspection	Impl/ANN INSP	KLM at time of inspection 1124557	30/05/2025	1124557	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/CS	C Service	VehService/CS	KLM at time of service 1124557	30/05/2025	1124557	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			RELINE LH & RH STEER BRAKES FIT DRUMS													
			REPLACE INNER & OUTER WHEEL BEARING ON BOTH SIDES		carry out reline retention wheels road tested and check over top up oils all good											
1034	Myrtleford - Workshop	Brakes\BRK RELINE	REPLACE LH & RH SCOMI BUSHES & SEALS		KLM at time of reline 1.122778	23/05/2025	1122778	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Elect\BATTERY	jump start truck		jump started truck found one battery s/s leaking fluid bottom out side replaced with a half good one	20/05/2025	1122054	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					REPLACED LH REAR DRIVE AIR BAG											
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	KLM AT TIME OF SERVICE 1.119706	14/05/2025	1119706	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AS A Service	VehService/AS	4lm at time of service 1.114577	25/04/2025	1114577	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					replaced lower steer shocker absbers											
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	KLM at time of service 1100277	09/04/2025	1100277	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Chassis/10TH WHEE	REPLACE T/TABLE FOOT BUSHES & PINS			08/04/2025	1100393	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/@1 Svc	VehService/@1 Svc	VehService/@1 Svc		08/04/2025	1100393	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AS	VehService/AS A Service	VehService/AS	KLM at time of service 1100393	14/03/2025	1100393	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService/AG	VehService/AG A Service	VehService/AG	KLM at time of service 1096616	05/03/2025	1096616	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			inspect for air leaks and repair													
1034	Myrtleford - Workshop	Body/AIR LEAK	replace exverior valve			05/03/2025	1100393	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Brakes\ABS	REPLACE ABS LEAD TO CONNECT TO TRAILERS			05/03/2025	1100393	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Chassis\10TH WHEE	MOVE T/TABLE FORWARD 100mm TO PUT MORE WEIGHT FORWARD ON STEER AXLE			05/03/2025	1096616	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	DriveLine/DIFF OIL	DriveLine/DIFF OIL	DriveLine/DIFF OIL	carried out on a-ser # 194296	19/02/2025	1091335	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Body/MOUNTS	remove and replace front bonnet mount rubbers			19/02/2025	1091335	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Prevent\WHEEL ALIGN	Wheel Alignment	Prevent\WHEEL ALIGN	inspected on a-ser # 194296 all good	19/02/2025	1091335	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Prevent\STEER W/B	Steer wheel bearings	Prevent\STEER W/B	carried out on a-ser #194296	19/02/2025	1091335	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			VehService/AS													
1034	Myrtleford - Workshop	VehService/AS	A Service	VehService/AS	inspected brakes same as he ads to move it forward	19/02/2025	1091335	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE CAB SHOCKS.		inspected shocks and unable to fault all good	19/02/2025	1091335	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Prevent\BELTS/TENS	Belts & Tensioners	Prevent\BELTS/TENS-deactivated 27/5/2024 7:46:17 pm utc	carried out on a-ser #194296	19/02/2025	1091335	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	DriveLine/GEARBOX	RECALIBRATE AUTO TRANSMISSION.		inspected opp of trans and unable to fault at the time	19/02/2025	1091335	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	DriveLine/OIL LEAK	reseal throw shaft housing and fit new seal and bearings			19/02/2025	1091335	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	DriveLine/DRV LIN SER	remove and replace P/D o-rings			19/02/2025	1091335	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Prevent\SHOCK ABS	Shock Absorber	Prevent\SHOCK ABS-deactivated 13/5/2024 7:23:13 pm utc	carried out on a-ser # 194296	19/02/2025	1091335	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
					KLM at time of service 3083334											
1034	Myrtleford - Workshop	VehService/@S	VehService/@S	VehService/@S		18/02/2025	1083144	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			FIT PTO & PUMP & FILTERS & VALVES TO OPPERATE WALKING FLOOR													
			CHANGE HYD OIL IN TANT													
			FIT CAB CONTROLS													
			MOVE T/TABLE BACK TO SUIT RESIN TRAILER													
1034	Myrtleford - Workshop	Hydraulic/PUMP				05/02/2025	1083144	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Body/WOUSEKEEP	wash and clean inside of cab			29/01/2025	1083144	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
			ARKON AUTO ELECTRICAL													
			Removed dash panels to gain access to wiring behind dash. Found no													
			factory pto wiring. Removed panels under steering wheel and ran wires													
			through firewall through to pto. Wire in pto as per diagram. Located 10 pin													
			and 6 pin plug behind dash cluster. Wired in missing parts of diagram.													
			Mounted and wired in led light on dash with pto switch to warn driver when													
			pto is on. Secured wires and tested. Pto works. Put all panels back and													
			cleaned out truck													
1034	Myrtleford - Workshop	Elect\ELECT P&W				21/01/2025	1083144	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	ARKON AUTO ELECTRICAL - 3	P/MOVER
1034	Myrtleford - Workshop	DriCab/wip\HOUSEKEEP	SUNVISOR NUT MISSING TOP RIGHT HAND SIDE.			10/12/2024	1078887	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Engine\EXHAUST	remove and replace exh pipe dump rubbers			07/12/2024	1078887	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Prevent\TRANS OIL	Transmission Oil Change	Prevent\TRANS OIL	Changed oil and filter	07/12/2024	1078887	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	VehService\TRANS OIL	VehService\TRANS OIL	VehService\TRANS OIL		07/12/2024	1078887	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford	MTK	XV94FI	Myrtleford Workshop	P/MOVER
1034	Myrtleford - Workshop	Engine\MOUNTS	REPLACE REAR ENGINE MOUNTS.

				TRANSMISSION CUSTOMER REPORTS TRANS WILL GET STUCK IN ONE GEAR AND WONT SELECT ANY OTHERS UNTIL STOPPED AND RESET TRUCK. * Removed walkways, drive shaft assembly, air lines, wiring looms, A/C unit & relevant components * Excess time taken to removed blower * Install transmission ballast & remove bell housing fittings & supports * Removed transmission complete * Remove all clutch assembly components * Clean all components * Removed transmission inspection cover * Install replacement rear main seal * Installed transmission * Installed replacement clutch assembly, plate, lever, bearings, seals, gaskets & components * Installed drive shaft assembly, air lines, wiring looms, A/C unit, walkways & components * Excess time taken to install blower * Align & tension components to specification * Removed all weight ballasting * Check clutching & adjust to specification * Overlooked all wiring * Found multiple faults * Repaired wiring faults as required * Lubricate & adjust all components as required												
1034	Wodonga - Workshop	DrivLine/GEARBOX	AUTOSHIFT CODING UP. (TCTC P/O: WWO889612)		* Road test. confirm & quality check reasir	28/09/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
					ENGINE BRAKE REPORTS ENGINE BRAKE WON'T SWITCH OFF UNLESS TRUCK IS TURNED OFF * Test operations & confirmed fault * Test all wiring - All ok * Test switch & found to be faulty * Removed & replaced switch												
1034	Wodonga - Workshop	Engine\JAKE BRAKE	JAKE REMAINING ON EVEN WITH MAIN SWITCH OFF. (TCTC P/O: WWO889912)		* Test operations - All ok. fault no lonwr arevent	28/09/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	TWIN CITY TRUCK CENTRE - OLD	P/MOVER		
1034	Wodonga - Workshop	DrivLine/GEARBOX	PTO GASKET LEAKING.		Pto gasket looks new not leaking	12/08/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	Check Drive Line For Any Oil Leaks, Repair, Wash & Recheck.		No leaks to be found looks OK	12/08/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Body\WIPERS	Replace Wiper Blades & Check Washers.		Wiper blades seem fine	12/08/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Chassis\FIFTH WHEE	Check Turn Table Adjustment & Grease.		Adjust was made but it no movement	12/08/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Chassis\AIR LEAK	Chassis\AIR LEAK			06/08/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	RAPID HYDRAULICS	P/MOVER		
1034	Wodonga - Workshop	DrtCabRep\ST Wheel	STEERING WHEEL.		New Steering Wheel Replaced/	06/08/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	VehService\AS	A Service	VehService\AS	New exhaust mount bushes. New push fitting for PTO box that was leaking air. REPLACED A/C BELT AND IDLER.	06/08/2024	839150	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Engine\FAULT CODE	ENGINE LIGHT ON.		Dan checked on computer and engine light was off, couldn't fault anything	06/08/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Unknown	A SERVICE DUE.		Completed	06/08/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/GEARBOX	NOISE UNDER THE BACK OF GEARBOX. BAD NOISE WHEN PTO IS ON HIGH RDV Hoses made and supplied SB Sales Order ref: 168796 KM labour for welding etc plus consumables and AF9983DD x 2 to be invoiced. Weld BSP alloy sockets into hyd oil tank and supply sight glasses.		Air leak was found in PTO box, exhaust mount bushes were severely worn, have been replaced	06/08/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/PTO	Supply breather			29/07/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	RAPID HYDRAULICS	P/MOVER		
1034	Wodonga - Workshop	Brakes\BRAKE ADJ	NEED BRAKES ADJUST.			03/07/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
					1048283ks 1.108,160 next B and C Major Air leak in Dash Stacks to be replaced												
1034	Wodonga - Workshop	VehService\AS	B Service	VehService\AS		03/07/2024	839150	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Tyres\STEER TYRE	RIGHT HAND STEER WHEEL TREAD IS SPLIT.		Has new steer tyres on it	03/07/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Body\EXHAUST	CHANGE EXHAUST STACKS (RICHARD OK IT)			03/07/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabRep\ST Wheel	NEW STEERING WHEEL.			03/07/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Hydraulics\GREASEDOWN	PTO Won't Engauge Inland Truck Centre Orange P/O: WWO886878			21/06/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	PACCAR PARTS FLEET SERVICES	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			08/06/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	BEAUREPAIRES	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			08/06/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	BEAUREPAIRES	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		KM's 1027960	08/06/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	BEAUREPAIRES	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			08/06/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	BEAUREPAIRES	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			08/06/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	BEAUREPAIRES	P/MOVER		
1034	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES ADJUST.			17/05/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Elect\INDICATORS	LEFT BACK INDICATOR NOT WORKING.		REPAIRED WIRING AT TAIL LIGHT ASSEMBLY.	17/05/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	VehService\AS	A SERVICE.			17/05/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Prevent\SEAT	Seat & Seat Belt	Prevent\SEAT-deactivated 27/5/2024 7:50:03 pm utc	New seat fitted by Shane McCabe	17/05/2024	839150	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabRep\ST Wheel	CHANGE STEERING WHEEL.			17/05/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP1+2	sublet Old Unit: 419003949 New unit: 469001636 new tags: 004895 & 004896 Old Tags: 022136 & 022133 vin: GF3000000KA464921 build date: 2010 Phone number: 0409653494 Will pin: 7607 Spokesperson: Jack Located unit in the overhead. Removed old antennas, passenger side trims and leather panels. Checked wirings and old unit operation (tablet wasn't setup with the old unit so paired it to check if the engine data was working). Mounted new antennas and ran cables to the unit.			23/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabInct\GPS	Cabed MT Data and finish setup and checked mdvr cameras.			18/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Albury Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabRep\WINDSCREEN	DROPPED OFF ALBURY AUTO SCREENS.			14/04/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS		11/04/2024	839150	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Cooling\ENG FAN	REBUILD HORTON CLUTCH FAN.			11/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	DIFF LEAK.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabInct\INST/GAUGE	ENGINE LIGHT IS ON THE DASH.			11/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	OIL LEAK BETWEEN MOTOR AND GEARBOX	REPLACED HYDRAULIC PUMP		11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Air Con\AIR CON	AC STOPS WORKING. NO FAN OR COOLER.	RAN A/C FOR ½ AN HOUR. IT DIDN'T TURN OFF OR CHANGE.		11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Susp\SHOCK ABS	CAB SHOCKERS ARE STUFFED.			11/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	STILL LEAKING OIL UNDER GEARBOX.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine\PTO	LEAKING PTO.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP3+4	FLAT LEFT SIDE DRIVE.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Hydraulics	HYDRAULIC NOT WORKING.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Body\MOUNTS	BONNET SAFETY LATCH.	REPLACED.		11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Susp\SHOCK ABS	CAB SHOCKERS.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Engine\JAKE BRAKE	JAKE BRAKE WON'T TURN OFF ON CE TURN ON .			11/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabRep\WINDSCREEN	WINDSCREEN CRACK.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Susp\ECV	HIGH CONTROL LEAKS LEFT SIDE LEAKING AIR.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabRep\SEAT	DRIVER SEAT WORN OUT-REPLACE-RG.			11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrtCabRep\ST Wheel	STEERING COLUMN NEED FIXING-RATTLES.	COULDN'T FAULT.		11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Susp\SHOCK ABS	LEFT HAND SIDE FRONT SHOCK - CLUNKS & BANGS.	CHECKED. OK.		11/04/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Insp\ANN INSP	To Complete R/W within 12 months	Insp\ANN INSP		11/04/2024	839150	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Body\WINDSCREEN	Replace Windscreen (Albury Autoscreen P/O: WWO885161)			05/04/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Tyres\RUN OUT	4			03/04/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Albury Workshop	P/MOVER		
1034	Wodonga - Workshop	Engine	TOO MUCH ENGINE OIL.			25/03/2024	839150	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Elect\HEAD LIGHT	r/h HEADLIGHT FLICKERS. CHECKED. OPEN POWER CIRCUIT.			23/03/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Air Con\AIR CON	TRUCK AIR CON STOP WORKING AFTER A FEW HOURS.			23/03/2024		Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Body\EXHAUST	FIX RIGHT HAND EXHAUST STACK.			23/03/2024		Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine\PTO	CHECKED PTO FUSES AND HYDRAULIC OIL LEVEL. DIAGNOSED AND REPLACED BROKEN AIR FITTING. TESTED. hydraulic pump not working			20/03/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Hydraulics\PUMP	Elite Diesel to attend P: BREAKDOWN LOSS OF OIL PRESSURE C: OIL PRESSURE SENSOR R: TRAVEL TO VEHICLE NORTH OF GTM, CONNECTED LAPTOP AND CHECK FAULT CODES, ACTIVE CODE FOR OIL RIFLE PRESSURE (0435) CHECK OIL LEVEL AND CONDITION OK, REMOVED ECM PLUGS AND FUEL LINE TO GAIN ACCESS TO SENSOR, TRAVEL BACK TO GTM TO COLLECT SENSOR, FIT AS REQUIRED REFIT FUEL LINE AND ECM PLUGS START ENGINE AND CHECK ENGINE OIL PRESSURE NOW READING.			20/03/2024	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Engine\GREASEDOWN	TRANS BACK TO CTM			06/03/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Albury Workshop	P/MOVER		
1034	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			02/03/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Albury Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine\PTO	Check For Oil Leaks		CHECKED AND TIGHTENED MOUNT BOLTS. CHECKED G/BOX OIL LEVEL.	21/02/2024	980766	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Hydraulics\HYD LEAKS	Check For Leaks		TIGHTENED HYDRAULIC FITTING AT PUMP. ADDED 2SL OIL	21/02/2024	980766	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/02/2024	968465	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Susp\SHOCK ABS	CAB SHOCKERS ARE STUFFED.			03/02/2024	968465	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Hydraulics\OIL/FILTER	HYDRAULIC OIL LOW =PLEASE FIL=		Topped up 10L	03/02/2024	968465	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	VehService\AS	B Service As Per Attached Checklist	VehService\AS		03/02/2024	968465	Service	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Unknown	B SERVICE.			03/02/2024	968465	Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	OIL LEAK BETWEEN MOTOR AND GEARBOX			18/01/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES ADJUST.	182565		18/01/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Air Con\AIR CON	SLEEPER AIRCON. BAG NEEDS REPLACING.			18/01/2024		Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Engine\FAULT CODE	ENGINE LIGHT ON.			18/01/2024		Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Engine\ADBLUE	NOT USING ADBLUE.			18/01/2024		Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Air Con\AIR CON	Fit New Vieva Cover			13/01/2024	957675	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjust Brakes			13/01/2024	957675	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Hydraulics\PUMP	hydraulic pump not working			10/01/2024		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	oil leak near gear box			06/01/2024	952732	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Cooling\ENG FAN	PLEASE CHECK HORTON CLUTCH FAN.	CHECKED. REQUIRES REBUILD.		21/12/2023		Fault	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
				CHECK RH HEADLIGHT FLICKERING travel to yard check headlight found rh highbeam not working until you open bonnet then cuts out when you move headlight harness check wiring found broken wire in headlight harness repair harness												
1034	Wodonga - Workshop	Elect\HEAD LIGHT	r/h HEADLIGHT FLICKERS	test ok move onto next job		21/12/2023		Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	Engine\GREASEDOWN	Breakdown			15/12/2023	946574	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV64R	Albury Workshop	P/MOVER		
1034	Wodonga - Workshop	Body\EXHAUST	NO EXHAUST CLAMP ON FLEX & EXHAUST NEEDS TO BE TURNED TO FIT CLAMP.			13/12/2023	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
					* Inspected all torque rod bushes * Found all required replacement * Unbolted & removed torque rods * Pressed out bushes * Cleaned down surfaces * Pressed in new bushes * Refit torque rods												
1034	Wodonga - Workshop	Susp\Torque Rod	REPLACE FRONT TORQUE ROD BUSHES. R&R TORQUE ROD BUSHES AS REQUIRED		* Aligned & tensioned all as required * Test operations - All ok	13/12/2023	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
					* Inspected turntable * Found footbushes worn * Removed turntable pins, bushes & components * Removed turntable top * Cleaned down all components * Removed & replaced foot bushes * Replaced turntable top * Greased as required												
1034	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACE TURNTABLE TOP. REPLACE TURNTABLE TOP		* Aligned & tensioned all to specifications * Checked jaw hitch mechanism * Test operations - All ok * Removed tailshaft assembly * Undo yoke nut & removed yoke * Removed seal * Cleaned down all surfaces * Installed replacement seal * Refit yoke with new nut & tensioned to specifications * Refit tailshaft	13/12/2023	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	INPUT SHAFT SEAL LEAKING. REPAIR OIL LEAK AT INPUT SHAFT SEAL TO FRONT DIFF		* Aligned & tensioned all as required * Test operations - All ok * Removed jackshaft * Undo yoke nut & removed yoke * Removed seal * Cleaned down all surfaces * Installed replacement seal * Refit yoke with new nut & tensioned to specifications * Refit jackshaft with new bolts * Aligned & tensioned all as required	13/12/2023	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		
1034	Wodonga - Workshop	DrivLine/OIL LEAK	THROUGH-SHAFT SEAL LEAKING. REPAIR OIL LEAK AT THROUGH SHAFT SEAL TO FRONT DIFF		* Test operations - All ok	13/12/2023	839150	Repair	Completed	Greenfreight Logging Vic	KW01SLOG	Myrtleford MTK	XV94H	Wodonga Workshop	P/MOVER		

| | | |

1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					01/12/2022	718413	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT LEAKING.					01/12/2022	718413	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT SEAL LEAKING.					01/12/2022	718413	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS				01/12/2022	718413	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					15/11/2022	707210	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT LEAKING.					15/11/2022	707210	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT SEAL LEAKING.					15/11/2022	707210	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	B Service As Per Attached Checklist	VehService\AS	REPAIRED SERVICE SUZI LINE.			15/11/2022	707210	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Tyres\TPX=2	Tyre Position 1 = 2					01/11/2022		Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					30/10/2022	696562	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Chassis\SWTH WHEE	TRUNION BUSHES WORN.		Not Required			30/10/2022	696562	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Air Con\AIR CON	AIR CONDITIONER NOT BLOWING PROPERLY.		Could not fault			30/10/2022	696562	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS				30/10/2022	696562	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					07/10/2022	681401	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS				07/10/2022	681401	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT SEAL LEAKING.					07/10/2022	681401	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					21/09/2022	669128	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS				21/09/2022	669128	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT LEAKING.					24/08/2022	648938	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					24/08/2022	648938	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Air Con\AIR CON	AIR CONDITIONER NOT BLOWING PROPERLY.					24/08/2022	648938	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\INDICATORS	RIGHT HAND INDICATOR COMES ON BY ITSELF.		COULDN'T FAULT.			24/08/2022	648938	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\INDICATORS	INDICATOR COMING ON BY ITSELF. R/H.					24/08/2022	648938	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\WIPERS	WINDSCREEN WIPERS NEED REPLACING.					24/08/2022	648938	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	B Service As Per Attached Checklist	VehService\AS	Engine Oil Sample SF ##3270559			24/08/2022	648938	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Chassis\AIR LEAK	EXHAUSTING OUT OF AIR DRYER CONTINUOUSLY.		REPLACED UNLOADER VALVE. TESTED.			24/08/2022	568413	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes\AIR LEAK	PLEASE CHECK FOR AIR LEAKS. LOOSING AIR WHEN PRESSING BRAKE PEDAL. (COULD BE TRAILERS)		REARED AIR LEAKS IN CAB AND TAPED UP WIRING AT RH BONNET.			09/08/2022	640186	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Cooling\ENG FAN	HORTON FAN COMING ON AUTO & NOT SWITCHING OFF. STAYS ON LONGER THAN USUAL.					09/08/2022	640186	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\AIR LEAK	TROUBLE BUILDING AIR UP. AIR LEAK UNDER DASH. AIR LINE HOSE NEEDS REPLACING. LEAKING.					09/08/2022	640186	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\DOOR LOCK	FIT WEATHER SHIELDS BOTH SIDES.					04/08/2022	636434	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\HOUSEKEEP	replace matress					22/07/2022	790345	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\HEAD LIGHT	L/S PARK LIGHT NOT WORK.					18/07/2022	622919	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\FAULT CODE	G.I.		INSPECTED. FLUSHED ADBLUE SYSTEM AND REPLACED INJECTOR. PERFORMED CLICK AND OVER-RIDE TESTS. CLEARED CODES. GREASED AND PARKED.			15/07/2022	621541	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\FAULT CODE	SEEK SERVICE IMMEDIATELY.					15/07/2022	621541	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\FAULT CODE	SCR SYSTEM ALTERED OR FAULT.					15/07/2022	621541	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
			Repair Tyre Puncture.																		
1034	Woodongs - Workshop	Tyres\TPX0	Beaumaxis POWWW072929					14/07/2022	62034	Repair	Completed	Greenfreight Loxmine Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\INDICATORS	NO LEFT HAND INDICATORS.		TRAVELLED TO AND FROM 1ST REST AREA NORTH OF HOLBROOK. FOUND TRAILER PLUG PINS NEEDED TO BE SPREAD. TESTED.			11/07/2022	619236	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
			Full Windscreen replacement.																		
1034	Woodongs - Workshop	Body\WINDSCREEN	Alburs Autoscreens POR WW072836					09/07/2022		Repair	Completed	Greenfreight Loxmine Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\WINDSCREEN	Cracked Windscreen		Refer Job# 385828			09/07/2022		Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\WINDSCREEN	Chipped windscreen in the middle.		Refer Job# 385828			09/07/2022		Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					09/07/2022	617969	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN CHIPPED.					09/07/2022	617969	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\HOUSEKEEP	NO FIRE EXTINGUISHER. (IS THERE, BUT OUT OF DATE)					09/07/2022	617969	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\DOH&S	FIRE EXTINGUISHER OUT OF DATE.					09/07/2022	617969	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS				09/07/2022	617969	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\SEAT	Driver seat back rest not working		Change Seat Over			29/06/2022	610574	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	Rear thru shaft sweating.					04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT LEAKING.					04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\TAIL SHAFT	FRONT UNI MOVEMENT		NO MOVEMENT.			04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT SEAL LEAKING. PTO LEAKING.					04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabElect\INSTGAUGE	NO DASH LIGHTS					04/06/2022	592337	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\TAIL LIGHTS	TRAILER PLUG ON PRIME MOVER NEEDS ATTENTION OR REPLACING. KEEPS HOOKING ON BLOWER PIPE AND BREAKING.					04/06/2022	592337	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\FAULT CODE	TRUCK LACKING POWER. DERATED. ENGINE LIGHT ON.		ENGINE LIGHT NOT ON.			04/06/2022	592337	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CLUTCH	CLUTCH SLIPPING UNDER LOAD (WHEN RAINING)					04/06/2022	592337	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Air Con\AIR CON	AIR CONDITIONER NOT BLOWING PROPERLY.					04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabElect\INST/GAUGE	DASH LIGHTS NOT WORKING.					04/06/2022	592337	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	B Service As Per Attached Checklist	VehService\AS	TIGHTENED PITMAN ARM. REPLACED LH STEER HUB SEAL. RELINED FRONT DRIVES.			04/06/2022	592337	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Unknown	B SERVICE DUE					04/06/2022	592337	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Chassis\SWTH WHEE	TRUNION BUSHES WORN.					04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\DOH&S	FIRE EXTINGUISHER OUT OF DATE.					04/06/2022	592337	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Tyres\TPX=4	supply and fit 8 tyres					04/06/2022		Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Tyres\TPX=6	Tyre Position 5 = 6					04/06/2022		Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Tyres\TPX=8	Tyre Position 7 = 8					04/06/2022		Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Tyres\TPX=10	Tyre Position 9 = 10					04/06/2022		Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\TAIL LIGHTS	BREAKDOWN. BROKEN TRAILER PLUG.		TRAVELLED TO AND FROM HUME HIGHWAY PAST OLYMPIC HIGHWAY TURNOFF. REPLACED BROKEN TRAILER PLUG.			02/06/2022	591162	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\PAINT/REST	FIX HOLE BACK OF CAB.		PUT CHECKER PLATE OVER HOLE IN BACK OF CAB.			02/06/2022	591132	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\HEAD LIGHT	REPAIRED FAULT IN L/HS HEADLIGHT. REPLACED HALO HEADLAMP AND LOW BEAM NOT WORKING. TRACED BACK, FOUND BROKEN WIRING. REPAIRED WIRES. TESTED.					28/04/2022	202197	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\HEAD LIGHT	TCTC supply Headlight					27/04/2022	839150	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\HEAD LIGHT	L/S HEADLIGHT NOT WORKING. (FLASHES SOMETIMES)					27/04/2022	839150	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
					[illegible]																
					* Codes active for clutch slipping																
					* Put clutch into open position to adjust																
					* Adjuster seized - Clutch unserviceable																
					* Put truck on hoists to remove transmission																
					* Removed passenger seat and floor to gain access																
					*Removed drive shaft and blower shaft																
					*Cable tied all wiring and hoses out of the way for access																
					*Removed exhaust section that is required																
					*Removed 4 over pipe and hoses																
					*Unbolted clutch and secured trans to jack																
					* Unbolted bell housing and remove trans from engine																
					* Removed clutch and inertia brake from input shaft and replaced both with new parts																
					* No install kits available to be filled																
					* Removed flywheel and had it ground flat																
					* Refit flywheel and torque bolts as required																
					* Replace spigot bearing																
					* Install transmission onto rear of engine																
					* Torqued bell housing to engine																
					* All removed parts re fitted and tensioned as required																
					*Torque clutch to flywheel																
					*Cleaned PTO surfaces and sealed PTO to box																
					* Refit drive and PTO shaft																
					* Fill trans with oil																
					*Install all interior that was removed																
					*Lower truck and test drive																
					*Check over truck - Repair complete																
1034	Woodongs - Workshop	DriveLine\CLUTCH	INVESTIGATE CLUTCH - CUSTOMER REPORTS SLIPPING		[illegible]			06/03/2022	537944	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	PACCAR PARTS FLEET SERVICES	P/MOVER			
1034	Woodongs - Workshop	Tyres\TPX=2	supply and fit 2 tyres					04/03/2022	537933	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
			PTO will not engage.																		
			Bayswater Truck Centre																		
1034	Woodongs - Workshop	Elect\BREAKDOWN	POR WW072830					14/02/2022		Repair	Completed	Greenfreight Loxmine Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\FUEL TANK	High pressure fuel pump sweating.					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	Rear thru shaft sweating.					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN CHIPPED.					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\HOUSEKEEP	NO FIRE EXTINGUISHER.					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT LEAKING.					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Cooling\COOL LEAKS	COOLANT LEAKS AT HEAD OF TANK.		*Check over truck - Repair complete			12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\TAIL SHAFT	FRONT UNI MOVEMENT					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\HOUSEKEEP	WAITING FOR NEW FIRST AID KIT TO FIT.					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\CHL LEAK	THROUGH-SHAFT SEAL LEAKING. PTO LEAKING.					12/02/2022	523584	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
					Engine Oil Sample SF # 42629656																
					Gearbox Oil Sample SF # 42629655																
					Front Diff Sample SF # 42629627																
1034	Woodongs - Workshop	VehService\CS	C Service As Per Attached Checklist	VehService\CS	Rear Diff Sample SF # 42629662			12/02/2022	523584	Service	Completed	Greenfreight Loxmine Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					16/01/2022	506040	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\EXHAUST	EXHAUST LEAK AT MUFFLER					16/01/2022	506040	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\HOUSEKEEP	WAITING FOR NEW FIRST AID KIT TO FIT.					16/01/2022	506040	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS	REPLACED STEER WHEEL SEALS			16/01/2022	506040	Service	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\FAULT CODE	SEEK SERVICE IMMEDIATELY COMING UP ON DASH		CHECKED GEARBOX PLUGS FOR WATER AND CORROSION. ALL SEEMED OK.			16/01/2022	506040	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Unknown	SERVICE ADVISED.					16/01/2022	506040	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
			Perform Vesa service, flush system and reset																		
1034	Woodongs - Workshop	Engine\COMPRESSOR	parameters. Check and repair any faults					11/01/2022	496659	Repair	Completed	Greenfreight Loxmine Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
			Viesta Fault																		
1034	Woodongs - Workshop	Cooling\WARRANTY	Seat to LEFT for Clearance and repair					04/01/2022	838505	Repair	Completed	Greenfreight Loxmine Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Susp\SHOCK ABS	LHF, LHR shocks leaking.					12/12/2021	484988	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\ADBLUE	EXHAUST LEAKING ADBLUE IN FRONT OF SCR.		PIPE REPLACED BY LAVINGTON TYRE AND EXHAUST. INSPECTED.			10/12/2021	484988	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Body\AIR LEAK	Repair air leak under right side cab		DIAGNOSED AND REPLACED LEAKING FITTING UNDER CAB.			10/12/2021	484988	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\EXHAUST	Secure new section of exhaust pipe with clamp, reroute AdBlue injector line as it is mounted badly.		FITTED BY LAVINGTON TYRES & EXHAUST			10/12/2021	484988	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Workshop\MOVE ASSET	PICKUP FROM LAVI EXHAUST CENTRE. TOOK 12 ATTEMPTS TO START WITH INTERLOCK. INTERLOCK WENT OFF ALONG THURGOONA DRIVE AND WAS UNABLE TO PASS AFTER 6 ATTEMPTS. PARKED O					09/12/2021	484972	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Brakes	Record Check Results As Attached To This Job					09/12/2021	484953	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\HEAD LIGHT	Driver side Headlight surround broken.					09/12/2021	484953	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DriveLine\GEARBOX	GEAR BOX FAULT. NEEDS SERVICE (FLASHING ON SHIFTER, ONLY CAME ON THE ONCE).					09/12/2021	484953	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Elect\ELECT PROV	TRAILER PLUG CONNECTION NEEDS REPLACING.					09/12/2021	484953	Fault	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	Engine\FAULT CODE	diagnose and repair fault codes		FLUSHED AND CLEANED DOSER SYSTEM. DIAGNOSED, PICKED UP FROM TCTC AND REPLACED CORRODED FITTINGS.			09/12/2021	484953	Repair	Completed	Greenfreight Logging Vic	KW91SLOG	Myrtleford MTK	XV94FI	Woodongs Workshop	P/MOVER			
1034	Woodongs - Workshop	DrCabRep\HOUSEKEEP	NO FIRE EXTINGUISHER.					09/12/2021	484953	Repair

				Park trailers and unhook.																											
1034	Wodonga - Workshop	Workshop|MOVE ASSET	Park truck back in front of trailers for driver to hook us.																												
			Elbow required for new exhaust modification.																												
			Bridgestone Exhaust Lavington.																												
1034	Wodonga - Workshop	Engine|EXHAUST	POWYW007109																												
1034	Wodonga - Workshop	Engine|EXHAUST	Fabricate exhaust pipe.																												
1034	Wodonga - Workshop	Cooling|COOL LEAKS	seal up radiator																												
1034	Wodonga - Workshop	Engine|EXHAUST	repair exhaust leak																												
1034	Wodonga - Workshop	Cooling|RADIATOR	Inspected leak found radiator leaking need back to replace.																												
			Inspected exhaust leak. Need to order exhaust pipe for in front of SCR.																												
1034	Wodonga - Workshop	Engine|EXHAUST	Hose fitted hand clamps on temp fix																												
			Keeps Dumping Air!!																												
			Found splitter housing on back of gearbox head bolts loose and leaking.																												
			Tightened 4 x bolts, LHR head bolt snapped.																												
1034	Wodonga - Workshop	Chassis|AIR LEAK	Consulted with Grahame & TCTC on Gearbox warranty. parts on order.																												
			Check Coolant leak found RH bottom of radiator core leaking.																												
			Refilled coolant.																												
1034	Wodonga - Workshop	Cooling|COOL LEAKS	Inspected radiator leak is aettine worse. recommend removine and replacine ASAP.																												
1034	Wodonga - Workshop	Workshop|MOVE ASSET	Moved combination to trailer shed for trailers to be serviced.																												
1034	Wodonga - Workshop	Workshop|I/O	Includes leading hand duties.																												
			Keeps Dumping Air!!																												
			Found splitter housing on back of gearbox head bolts loose and leaking.																												
			Tightened 4 x bolts, LHR head bolt snapped.																												
1034	Wodonga - Workshop	Chassis|AIR LEAK	Consulted with Grahame & TCTC on Gearbox warranty. parts on order.																												
			Check Coolant leak found RH bottom of radiator core leaking.																												
1034	Wodonga - Workshop	Cooling|COOL LEAKS	Refilled coolant.																												
1034	Wodonga - Workshop	Elect|SUZI COIL	Fit new trailer plug.																												
			NOT STARTING.																												
			F ON DASH FOR TRANSMISSION																												
			PROCEED TO MANILDRA, INSPECT FOR NOT STARTING.																												
			CONNECT ELECTRONIC SERVICE TOOL, FOUND CODE RELATING TO START ENABLE RELAY.																												
			RAISE CAB, INSPECT CONTROL MODULE AND HARNESS, OK.																												
			DISCONNECT BATTERIES, RE CONNECT, TRUCK STARTING NOW.																												
			RECOMMEND START RELAY FOR TRANSMISSION BE REPLACED.																												
1034	Wodonga - Workshop	DriveLine|GEARBOX	RETURN TO WORKSHOP.																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	Engine|EXHAUST	exhaust has 3 tiniest little cracks in it ad blue leaking out slightly																												
1034	Wodonga - Workshop	Engine|EXHAUST	Leaking Add Blu in front of muffler.																												
			Small Crack in front of muffler.																												
1034	Wodonga - Workshop	Engine|EXHAUST	Ad Blu leakine from crack.																												
1034	Wodonga - Workshop	Engine|EXHAUST	Ad Blu coming out of the exhaust near muffler.																												
1034	Wodonga - Workshop	Chassis|SIXTH WHEE	Replaced worn turntable bushes.																												
1034	Wodonga - Workshop	Susp|SHOCK ABS	LHF, LHR shocks leaking.																												
1034	Wodonga - Workshop	Engine|TURBO	Replaced and replaced top intercooler rubbers																												
1034	Wodonga - Workshop	VehService|AS	A Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	DriCabRep|BREAKDOWN	Repair air leaks in driver's seat.																												
1034	Wodonga - Workshop	Workshop|MOVE ASSET	Drop off at TCTC for light issue in trailer plug and fuel ute																												
1034	Wodonga - Workshop	Elect|LECT P&W	No Clearance lights to trailers.																												
1034	Wodonga - Workshop	DrCabElec|I/AP	IAP not tracking																												
1034	Wodonga - Workshop	Workshop|MOVE ASSET	Drop off at TCTC for repairs																												
			Lighting issue.																												
1034	Wodonga - Workshop	Elect|BREAKDOWN	Novara Truck and Trailer WW064997																												
1034	Wodonga - Workshop	Hydraulics|CONSUMABLE	top up hydraulic oil																												
1034	Wodonga - Workshop	Hydraulics|CONSUMABLE	Top up with hydraulic fluid.																												
1034	Wodonga - Workshop	Brakes|BRAKE ADJ	Adjust brakes and inspect underside of truck.																												
1034	Wodonga - Workshop	Workshop|MOVE ASSET	Pick up from TCTC																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	Chassis|AIR LEAK	Keeps Dumping Air!!																												
1034	Wodonga - Workshop	Tyres|FITMENT	Needs a full set of drive tyres.																												
1034	Wodonga - Workshop	Brakes|BRK RELINE	Rear Axle requires reline.																												
1034	Wodonga - Workshop	DriveLine|UNI JOINTS	Blower shaft Uni's U/S																												
1034	Wodonga - Workshop	Engine|EXHAUST	Ad Blu coming out of the exhaust near muffler.																												
			REPLACE WORN ENGINE BELTS.																												
			* Removed old drive belt and a/c belt.																												
			* Inspected tensioners/pulleys , all good.																												
			* Replaced with new belts.																												
1034	Wodonga - Workshop	Engine|BELTS/TENS	* Reese completed.																												
1034	Wodonga - Workshop	VehService|AS	A Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Workshop|MOVE ASSET	pick up TCTC																												
			SUZI COILS SNAPPED OFF AT 7 PIN PLUG.																												
			REPLACE SUZI COILS AND END FITTINGS.																												
			REUSE OLD FITTING ON TRAILER END DUE TO BEING SHAWFER FITTING.																												
			THREAD TAPE ALL FITTINGS.																												
			REINSTALL POGO STICK TO CORRECT POSITION.																												
			REPLACE 7 PIN PLUG.																												
1034	Wodonga - Workshop	Chassis|SUZI COIL	DUE TO NO TRAILER ON TRUCK ADVISE DRIVER TO INSPECT SUZI COILS FOR ANY AIR LEAKS																												
1034	Wodonga - Workshop	Tyres|TYR>4	AND CHECK TRAILER LIGHTS WORKING PROPERLY WHEN TRAILER IS CONNECTED.																												
1034	Wodonga - Workshop	Tyres|TYR>6	Supply and fit 4 tyres																												
1034	Wodonga - Workshop	Brakes|BRK RELINE	Tyre Position 5 + 6																												
1034	Wodonga - Workshop	Brakes	need reline																												
1034	Wodonga - Workshop	Tyres|FITMENT	Record Check Results As Attached To This Job																												
			Needs a full set of drive tyres.																												
1034	Wodonga - Workshop	Engine|EXHAUST	Small Crack in front of muffler.																												
1034	Wodonga - Workshop	Engine|BELTS/TENS	Ad Blu leakine from crack.																												
1034	Wodonga - Workshop	VehService|AS	Need to check bearings in pulleys as there is slight squeak.																												
			A Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Brakes|BRAKE ADJ	BRAKE ADJUSTMENT																												
1034	Wodonga - Workshop	Tyres|TYR>8	CARRY OUT BRAKE ADJUSTMENT																												
1034	Wodonga - Workshop	Tyres|TYR>10	Supply and fit 4 tyres																												
1034	Wodonga - Workshop	Engine|BREAKDOWN	Tyre Position 9 + 10																												
			truck shut down on Mt Dusley no warning or engine lights																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	Brakes|BRK RELINE	need reline																												
1034	Wodonga - Workshop	VehService|AS	B Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Hydraulics|PUMP	Rear PTO uni has excessive play.																												
1034	Wodonga - Workshop	Tyres|FITMENT	Needs a full set of drive tyres.																												
1034	Wodonga - Workshop	DriveLine|OIL LEAK	Tighten oil return line /filter to DIFF/ Front diff.																												
1034	Wodonga - Workshop	Body|HOUSEKEEP	Refit bonnet rubber at top.																												
1034	Wodonga - Workshop	Body|LIGHTS	Change RH head Lights.																												
1034	Wodonga - Workshop	Engine|EXHAUST	Tighten exhaust clamps under bonnet.																												
1034	Wodonga - Workshop	Body|WIPERS	Adjust position of windscreen washer jet on arm and test.																												
1034	Wodonga - Workshop	Workshop|MOVE ASSET	Park truck and trailers back in their previous positions.																												
1034	Wodonga - Workshop	Engine|EXHAUST	Inspect exhaust leak and repair.																												
1034	Wodonga - Workshop	Brakes|BREAKDOWN	brake coming on and not releasing																												
1034	Wodonga - Workshop	Hydraulics|OIL/FILTER	PROCEED TO MANILDRA LOADING DOCK AND CHECK HYDRAULIC OIL, TOP UP AS REQUIRED.																												
1034	Wodonga - Workshop	Elect|BATTERY	change batteries																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	Chassis|AIR LEAK	Keeps Dumping Air!!																												
1034	Wodonga - Workshop	Engine|EXHAUST	Leaking Add Blu in front of muffler.																												
1034	Wodonga - Workshop	DrCabRep|WINDSCREEN	Chipped windscreen in the middle.																												
1034	Wodonga - Workshop	VehService|CS	C Service As Per Attached Checklist		VehService|CS																										
			Clear Ad Blue faults. Replace dose pump filter fitting & flush out hoses.																												
			Test drive to logic and back. Park on tyre pad. Trailer supply valve fault.																												
1034	Wodonga - Workshop	Engine|ADBLUE	Consult Ash about service sticker & finish paperwork.																												
1034	Wodonga - Workshop	Cooling|COOL LEAKS	Low Coolant.																												
1034	Wodonga - Workshop	Tyres|TYR>2	Supply and fit 2 tyres																												
1034	Wodonga - Workshop	Hydraulics|BREAKDOWN	Hydraulics wont allow tank to come down.																												
1034	Wodonga - Workshop	Engine|BATTERY	Battery Issues																												
			Unblock after treat system.																												
1034	Wodonga - Workshop	Engine|ADBLUE	Check adblue to coolant heat sensor																												
1034	Wodonga - Workshop	Elect|BATTERY	Jump Start with 976																												
1034	Wodonga - Workshop	Engine|BATTERY	Flat Batteries																												
1034	Wodonga - Workshop	DriveLine|GEARBOX	Fault Codes																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Workshop|MOVE ASSET	travel to TCTC to pick up parts																												
1034	Wodonga - Workshop	Chassis|SUZI COIL	remove and replace one way valves on susi leads as required																												
1034	Wodonga - Workshop	Chassis|AIR LEAK	find air leaks																												
1034	Wodonga - Workshop	Brakes|VALVES	Job Added From Invoice																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	Engine|FAULT CODE	adblue coming out of exhaust																												
1034	Wodonga - Workshop	Engine|BELTS/TENS	Replace idler bearings + tensioners																												
1034	Wodonga - Workshop	Chassis|AIR FITTIN	removed and replaced air couplings both on prime mover and trailer, parked up vehicle																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Engine|FAULT CODE	adblue coming out of exhaust																												
1034	Wodonga - Workshop	Brakes|BRK RELINE	need reline																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	DrCabRep|HOUSEKEEP	chrome plate missing above adblue tank - hasn't been on truck since it was pulled off not long after getting truck																												
1034	Wodonga - Workshop	Tyres|STEER TYRE	steer tyres need flipping on the rims																												
1034	Wodonga - Workshop	Engine|EXHAUST	exhaust has 3 tiniest little cracks in it ad blue leaking out slightly																												
1034	Wodonga - Workshop	VehService|AS	A Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Workshop|MOVE ASSET	move trailers 251/533 into top shed for repairs by Aldongo Eng. It took 15 minutes to build air up to move. I also found them very difficult to reverse into shed																												
1034	Wodonga - Workshop	Tyres|TYR>2	fit 2 run outs																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	DrCabRep|HOUSEKEEP	replace																												
1034	Wodonga - Workshop	Tyres|STEER TYRE	steers scalloped																												
1034	Wodonga - Workshop	Workshop|MOVE ASSET	unlock workshop and move truck																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Workshop|MOVE ASSET	move truck																												
1034	Wodonga - Workshop	Cooling|RADIATOR	delay intercooler and radiator																												
1034	Wodonga - Workshop	Workshop|MOVE ASSET	test drive with loaded trailer, temp got to 95°																												
1034	Wodonga - Workshop	Engine|BREAKDOWN	diagnose engine derate and shutdown																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
1034	Wodonga - Workshop	Elect|BREAKDOWN	elec plug damaged																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	Tyres|STEER TYRE	steer tyres need flipping on the rims																												
1034	Wodonga - Workshop	DriveLine|UNI JOINTS	uni's on power divider s/s																												
1034	Wodonga - Workshop	Engine|EXHAUST	exhaust has 3 tiniest little cracks in it ad blue leaking out slightly																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
			fix drivers seat																												
1034	Wodonga - Workshop	DrCabRep|SEAT	reconnect air lines under seat																												
1034	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job																												
1034	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist		VehService|AS																										
			R/H mounting rubbers on cac perished																												
1034	Wodonga - Workshop	Body|EXHAUST	Mount shine on tail shaft exhaust rubbers loos, bolt missing in exhaust shroud																												
1034	Wodonga - Workshop	Tyres|STEER TYRE	steer tyres need flipping on the rims																												
1034	Wodonga - Workshop	Chassis|SUZI COIL	suzzy coil pole needs to be replaced																												

1034	Woodonga - Workshop	Chassis\FIFTH WHEE	turntable bushes next service					29/11/2020	223345	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\UNI JOINTS	uni's on power divider u/s					29/11/2020	223345	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\EXHAUST	exhaust has 3 tiniest little cracks in it ad blue leaking out slightly					29/11/2020	223345	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job			Carry out A Service		08/11/2020	348188	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		Carry Out A Service		08/11/2020	348188	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\STEER TYRE	steer tyres need flipping on the rims					08/11/2020	348188	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	DrkCabRep\HOUSEKEEP	chrome plate missing above adblue tank - hasn't been on truck since it was pulled off not long after getting truck					08/11/2020	348188	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Elect\SUB COIL	replace sus's ant light plug					27/10/2020	230993	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	pick up from HTT and take to TCTC					13/10/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	drop off Hume techniques					13/10/2020	333903	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\WHEEL ALIGN	PERFORM LASER WHEEL ALIGNMENT ON T610 PM					13/10/2020	195892	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Chassis\Rego	replaced missing pops stick					12/10/2020	195889	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\FAULT CODE	lumpy cam and nos needed slower than sweteeer					03/10/2020	328685	Fault	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job			checked and adjusted brakes		03/10/2020	328685	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	Through shaft seal starting to weep			carried out through shaft seal repair		03/10/2020	328685	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Steering\WHEEL ALGN	steering pulls to the left fairl hard			straightened steering		03/10/2020	328685	Fault	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Steering\SUSPENSION	massive clunk turning right to left			couldn't fault		03/10/2020	328685	Fault	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS		TCTC Powe058705 carried out service as per sheet		03/10/2020	328685	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\EXHAUST	R/H mounting rubbers on car perished blower rubbine on tail shaft. exhaust rubbers lose. bolt missine in exhaust shroud					03/10/2020	328685	Repair	Completed	Greenfreight Loxmine Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\GEARBOX	REMOVE TRANSMISSION AS REQUIRED. REMOVE BRONZE BUSH THAT THE INPUT SHAFT RUNS IN BUT DRIVE YESTERDAY WE COULD SELECT GEAR BUT TRUCK WOULD NOT MOVE. DRIVER THINKS DEE TRUCK SA			* Connected service power. * Found no faults, updated program. * Started truck selected gears with no issues. * Inspected all power cables and earths. * Inspected clutch. * Found to be slipping severe. * Attempted		03/10/2020	312403	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					27/09/2020	324630	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\CLEANSION	Job Added From Invoice					27/09/2020	324630	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					22/09/2020	324630	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		carry out A Service		22/09/2020	324630	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	pick up from TCTC and parts from Aldonga					16/09/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	drop clown at Arbon Electrical			straightened steering		16/09/2020	328685	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	picked 1034 up from TCTC					16/09/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Elect\BATTERY	travelled to workshop, then drove to breakdown at above location. Removed and replaced batteries started and ran trunch. Travelled back to workshop. Carried out battery report sheet					11/09/2020	293686	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	pick up from TCTC					22/08/2020	304630	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	drop truck at TCTC					21/08/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	hook up to t446/447 test drive to chck gear changing					20/08/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					14/08/2020	292908	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	Through shaft seal starting to weep			Under warranty		14/08/2020	292908	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	DrkCabRep\WINDSCREEN	Windscreen chipped			Previously completed		14/08/2020	292908	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Chassis\FIRE EXTIN	Expired none in stock			Replaced with new one		14/08/2020	292908	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	Rear thru shaft seal blown			As per #300634		14/08/2020	292908	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\FUEL TANK	Tank needs straightening			J bracket was previously fitted to straighten as best as possible. Fitted new step		14/08/2020	292908	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				14/08/2020	292908	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\STEER TYRE	Job Added From Invoice					14/08/2020	293686	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					14/08/2020	293686	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\FUEL TANK	repair damage to Ad Blu tank and J brackets					08/08/2020	292486	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\FUEL TANK	Tank needs straightening					08/08/2020	292486	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\CLEAN	Clean workshop					08/08/2020	292486	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	DrkCabRep\SEAT	Repair Drivers seat airleak					08/08/2020	292486	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\FUEL TANK	RH fuel tank and ad blue tank brackets damaged need replacing			as per #297889		08/08/2020	292486	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	Hook up to T647/360					08/08/2020	292486	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					23/07/2020	305279	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				23/07/2020	305279	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Chassis\FIRE EXTIN	expired none in stock					23/07/2020	305279	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	rear thru shaft seal blown					23/07/2020	305279	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\FUEL TANK	RH fuel tank and ad blue tank brackets damaged need replacing					23/07/2020	305279	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Hydraulics\HOUSEKEEP	top up hydraulic oil					18/07/2020	280550	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Hydraulics\HOUSEKEEP	tighte up hydraulic fittings					18/07/2020	280550	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice					09/07/2020	265556	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					09/07/2020	265556	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\CLEANSION	Job Added From Invoice					09/07/2020	265556	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\BREAKDOWN	engine lacking power and using fuel			TCTC Powe055928		01/07/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\FILTERS	Job Added From Invoice					17/06/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					14/06/2020	253869	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				14/06/2020	253869	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\Punct	Job Added From Invoice					13/06/2020	244134	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					13/06/2020	240926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					31/05/2020	104926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	CompQ\Truck Safe	Trucksafe sticker has expired			Replaced		31/05/2020	104926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	CompQ\Truck Safe	Truck safe sticker out of date			As per #288570		31/05/2020	104926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	DrkCabRep\WINDSCREEN	Windscreen chipped					31/05/2020	104926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	DrkCabRep\WINDSCREEN	Windscreen got chip			As per #288751		31/05/2020	104926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	Through shaft seal starting to weep					31/05/2020	104926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				31/05/2020	104926	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	park truck & trailers					29/05/2020	104926	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	move truck					19/05/2020	95191	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					16/05/2020	93352	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\HOUSEKEEP	2cts engine oil					16/05/2020	93352	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	CompQ\Truck Safe	Truck safe sticker out of date					16/05/2020	93352	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	DrkCabRep\WINDSCREEN	Windscreen got chip					16/05/2020	93352	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	through shaft seal start to weep					16/05/2020	93352	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				16/05/2020	93352	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					02/05/2020	80598	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	Gearbox output leaking			previously completed		02/05/2020	80598	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Hydraulics\HYD LEAKS	Blower & PTO leaking			previously completed		02/05/2020	80598	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\EXHAUST	Hole in exhaust needs welding			Previously completed		02/05/2020	80598	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				02/05/2020	80598	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					12/04/2020	63169	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\EXHAUST	Hole in exhaust needs welding					12/04/2020	63169	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	CompQ\Truck Safe	Trucksafe sticker has expired					12/04/2020	63169	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				12/04/2020	63169	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\AIR LEAK	fix PTO airleaks & test hydraulic operation					26/03/2020	44660	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\AIR LEAK	breakdown (campbellfield truck)			D. TRAEL TO VICH COOLAROO AND INSPECT FOR HYDRAULIC PTO NOT ENGAGING. ON ARRIEL LOOKED FOR CONTROL BOX AND REMOVED PTO LINES FOUND NO AIR GOING TO THAT PTO. CHECKED WITCHES V					26/03/2020	44660	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Hydraulics\CONSUMABLE	Repair air leak at Hydralic PTO			Rapid Hydraulics to supply parts P/OMWW052768		21/03/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					19/03/2020	4884	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Hydraulics\HOSES	Pto wiring outsourcing to sublet			new switch fitted by workshop correct switch supplied by CTT		19/03/2020	4884	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS		carried out kenworth first service as per service sheet. grease, clutch: disconnect red lightat clutch pedal, disconnected the power supply to red light above clutch pedal as required. Brakes customer reports out text drive and inspected brake operations. all ok.		19/03/2020	4884	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\AIR CLNR	Job Added From Invoice					17/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Steering\WHEEL BRGS	Job Added From Invoice					17/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Steering\WHEEL SEAL	Job Added From Invoice					17/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\WHEEL BRGS	Job Added From Invoice					17/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\FUEL TANK	Job Added From Invoice					13/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\FILTERS	Job Added From Invoice					13/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService	Job Added From Invoice					13/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\DIFF OIL	Job Added From Invoice					13/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\GEARBOX	Job Added From Invoice					13/03/2020	0	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					06/03/2020	164137	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS				06/03/2020	164137	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Drive Line\OIL LEAK	Gearbox output leaking					06/03/2020	164137	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Hydraulics\HYD LEAKS	Blower & PTO leaking					06/03/2020	164137	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\DING	Put walk plate back on					29/02/2020	31526	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\STEER TYRE	Job Added From Invoice					29/02/2020	26955	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					29/02/2020	26955	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\BALANCE	Job Added From Invoice					29/02/2020	26955	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Tyres\Air Callout	Job Added From Invoice					29/02/2020	26955	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Workshop\MOVE ASSET	drop 1034 at twincity					26/02/2020		Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Elect\FAULT CODE	service light on gearbox coming on with fault (transmission fault)					18/02/2020	59618	Fault	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					15/02/2020	147819	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Engine\EXHAUST	Exhaust pipe before muffler leaking AdBlu					15/02/2020	147819	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\EXHAUST	Hole near muffler					15/02/2020	147819	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS				15/02/2020	147819	Service	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Hydraulics\OIL/FILTER	removed 30 L hyd oil					14/02/2020	17373	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job					31/01/2020	138021	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	Body\DING	NO PARK BRAKE ALARM STICKER			Not required - Flour tanker		31/01/2020	138021	Repair	Completed	Greenfreight Logging Vic	KW015\LOG	Myrtleford MTK	XV94\FI	Woodonga Workshop	P/MOVER				
1034	Woodonga - Workshop	DrkCabRep\WINDSCREEN	windscreen chipped					31/01/

1034	Woolongo - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	moved turntable back 1 adjustment	09/09/2019	25719	Service	Completed	Greenfreight Logging Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshop	P/MOVER
1034	Woolongo - Workshop	Body\EXHAUST	Inspect adBlue tank issue with Paul and Twin City			14/08/2019	7135	Repair	Completed	Greenfreight Logging Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshop	P/MOVER
1034	Woolongo - Workshop	Workshop\MOVE ASSET	Took 1034 to Twin City Truck Centre			09/08/2019		Repair	Completed	Greenfreight Logging Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshop	P/MOVER
1034	Woolongo - Workshop	Workshop\MOVE ASSET	Picked up from TCTC			09/08/2019		Repair	Completed	Greenfreight Logging Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshop	P/MOVER
1034	Woolongo - Workshop	Hydraulics\BREAKDOWN	P.T.O. not staying on unless button held down		Nowra Truck and Tractor attended P/O number WW46SSB7	07/08/2019		Repair	Completed	Greenfreight Logging Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshop	P/MOVER
1034	Woolongo - Workshop	Body\HOSES	Make up blower hose			04/08/2019		Repair	Completed	Greenfreight Logging Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshop	P/MOVER
1034	Woolongo - Workshop	Hydraulics\HOSES	Fabricate hydraulic hose line bracket			03/08/2019		Repair	Completed	Greenfreight Logging Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshop	P/MOVER
			warranty items found													
			Drive shaft hitting pipe work for blower		taken photos avised TCTC pick up truck and repair.											
1034	Woolongo - Workshop	DriveLine\WARRANTY	trailer brake panel pulled away from dash		Thomas from TCTC none to sav rubber inserts have pulled throuath dash & CT&T are on there way over to reapir drive line.	02/08/2019	500	Reapir	Completed	Greenfreight Lowrine Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshoo	P/MOVER
					First aid kit, fire extinguisher, grease turntable, rewire light plug, test fit hydraulic hoses & make mount.											
1034	Woolongo - Workshop	Body\HOUSEKEEP	Commission truck		Insoect clearances.	02/08/2019		Reapir	Completed	Greenfreight Lowrine Vic	KWIX15LOG	Myrtleford	MTK	XV94FI	Woolonga Workshoo	P/MOVER