EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
1008	Colac - Colac	Brakes\BREAKDOWN	TRAVEL TO BELLS REEF RD SAILORS FALLS TO DIAGNOSE & REPAIR LOW AIR ISSUE. GOVERNOR VALVE WAS REPLACED.		26/08/2026	1353306	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\HEAD LIGHT	DIAGNOSE & REPAIR R/H LOW BEAM WIRING FAULT		14/08/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Body\EXHAUST	RECTIFY BENT L/H EXHAUST STACK		14/08/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Colac - Colac	VehService\AS	VehService\AS A Service		01/08/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Colac - Colac	Cooling\ENG FAN	FIT NEW HORTON FAN SWITCH		31/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Cooling\ENG FAN	SUPPLY HORTON FAN SWITCH		29/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	QT DIESEL SERVICES - 3	P/MOVER
				Carry out Engine Tune including : - Download ECM data & print out vehicle trip information - Inspect engine for oil & coolant leaks - Carry out valve & injector adjustment to specification (including engine brakes) - Check & inspect camshafts. - Pressure test charge air cooler system - Change out In-tank SCR system Adblue filter - Carry Out SCR system Doser air-side flush - Check air filter element(s) & advise. - Inspect & adjust belts - Check turbo wastegate adjustment - Test Coolant & check level. - Fill out service sticker - Steam clean engine & check over. - Return Vehicle to service. Additional : - Fan belt was found squealing, removed and replace fan belt							
1008	Myrtleford - Workshop	Engine\ENG TUNE	Engine\ENG TUNE L134990	with new belt.	27/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1008	Colac - Colac	Cooling\ENG FAN	DIAGNOSE HORTON FAN FAULT, SWITCH REQUIRED.		23/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\DOOR LOCK	SWAP DOOR CONTROL MODULE FROM TRUCK 1033 TO ELIMINATE FAULT WITH WINDOW , REPAIUR FAULTY WIRING BETWEEN DOOR & CAB		21/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\RWC COMP	CHECK ABS FAULT IN TRAILER ABS LEAD.		21/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Steering\CONSUMABLE	REPLACE STEERING COLUMN LOCKING STRUT		15/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Tyres\STEER TYRE	Tyres\STEER TYRE 1-2	CALL OUT	13/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\ELECT P&W	REPAIR COURTESY LIGHT		09/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\DOOR LOCK	DIAGNOSE & REPAIR DOOR LOCK WIRING		09/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Brakes\ABS	DIAGNOSE & REPAIR TRAILER ABS FAULT IN TRUCK HARNESS, REPLACE FAULTY ABS WIRE NEAR TURNTABLE.		09/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REPLACE 2X DASH GLOBES		09/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\COOL LEAKS	REPLACE THERMOSTAT, REPLACE LEAKING TURBO OIL DRAIN GASKET, REPLACE CXOOLOANT LEVEL SENSOR & MODULE.		04/07/2026	1353306	Completed	Myrtleford	GTK	XO01AE	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\ELECT P&W	ADJUST PTO CONTROL BOX AWAY FROM THE SEAT		22/06/2026	1353306	Completed	Myrtleford	GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12		20/06/2026	1353306	Completed	Myrtleford	GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		20/06/2026	1353306	Completed	Myrtleford	GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		20/06/2026	1353306	Completed	Myrtleford	GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		20/06/2026	1353306	Completed	Myrtleford	GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\HOUSEKEEP	DrCabElect\HOUSEKEEP	ADJUST CABIN RIGHT HEIGHT Drive to Ballan truckstop Inspect truck for not building air Checked over hoses to air dryer and governor Found air dryer choofing off randomly Removed air dryer Changed over fittings to new air dryer Fitted air dryer Replaced governor as well Tested truck multiple times and was good Drive back to shed	04/06/2026	1353306	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	Frid Serv\AIR DRYER	Frid Serv\AIR DRYER VehService\AS A Service		04/06/2026	1353306	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	L134198 VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		30/05/2026	1353306	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		09/05/2026	1353306	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	Susp\HCV	Susp\HCV VehService\AS A Service	Remove and replace cab filter & cover. Replace cabin right height valve 340,472 Km's 28,797 Hrs FULL SERVICE & SAFETY CHECK - TRUCK Carry out full A service and safety check as per check list. Tightened clamp on suction hose to hydraulic hose - to be rechecked Needs: Power steering hoses leaking Steering box leaking Turbo drain leaking	09/05/2026	1353306	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	L133304 Brakes\BOOSTER	Gearbox cooler hoses leaking	10/04/2026	1328336	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	Brakes\BOOSTER	L133308	Remove and replace leaking booster hose from quick release valve to maxi brake valve. DIAGNOSE FAULTY BATTERIES REMOVE AND REPLACE BATTERIES DIAGNOSE FAULTY ALTERNATOR TERMINAL, LOOKS TO HAVE BURNT OUT FROM GETTING HOT REMOVE AND REPLACE ALTERNATOR TERMINAL	07/04/2026	1328336	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\BATTERY	Engine\BATTERY VehService\BS B Service		12/03/2026	1328336	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\BS	L132969		28/02/2026	1328336	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
				Diagnose after treat fault. Inspect after treat fault, find to be a fuel delivery pressure code. Remove and replace fuel water separator, clean codes and test drive. All okay.								
1008	Myrtleford - Workshop	Engine\ADBLUE	DIAGNOSE & AFTER TREAT FAULT.		26/02/2026	1322156	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
				Diagnose & repair right weigh scale power issue. Replace blown fuse.								
1008	Myrtleford - Workshop	DrCabElect\SCALES	DIAGNOSE & REPAIR RIGHT WEIGH SCALE POWER ISSUE.		26/02/2026	1322156	Completed	Myrtleford	GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 8	CALL OUT TRAVEL TO BREAKDOWN AT WARRENHEIP	19/02/2026	1313760	Completed	Myrtleford	GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
				PLUGGED SCAN TOOL IN AND FOUND TO HAVE A HEAP OF FUEL CODES AGAIN DRIVER BROUGHT TRUCK BACK TO THE WORKSHOP FOR REPAIRS DRAINED COOLANT REMOVED GOVERNOR AND POWER STEERING PUMP REMOVED COMPRESSOR REMOVED ALL FUEL LINES THAT WERE ATTACHED TO THE FUEL PUMP REMOVED FUEL PUMP SWAPPED A COUPLE OF FITTING ON TO THE SUPPLIED FUEL PUMP FIT NEW FUEL PUMP ACTUATOR AS THE ONE THAT CAME OFF CUSTOMERS WAS BROKEN AND MISSING A BOLT REFITTED FUEL PUMP WITH NEW GASKET REFITTED FUEL LINES WITH NEW WASHERS REFITTED COMPRESSOR WITH NEW GASKET REFITTED GOVERNOR WITH NEW GASKET REFITTED POWER STEERING WITH NEW GASKET REFILLED COOLANT TOOK TRUCK FOR A TEST DRIVE AND GOT TO THE PYKES CREEK EXIT AND BROKE DOWN PLUGGED SCAN TOOL IN AND FOUND TO HAVE LOW COOLANT, TOPPED UP COOLANT KEPT GOING WITH TEST DRIVE AND MADE IT TO THE BOTTOM OF PYKES ON THE WAY BACK TO THE SHED AND BROKE DOWN AGAIN, TRUCK THEN WOULDNT START								
1008	Myrtleford - Workshop	Body\FUEL TANK	Body\FUEL SYSTEM	CLEARED CODES AND GOT IT STARTED, DROVE TO THE TOP OF PYKES TO THE PARKING BAY AND	17/02/2026	1328336	Completed	Myrtleford	GTK	XO01AE	MM DIESEL	P/MOVER

1008	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	Diagnose and repair heater fan fault, replace relay and terminals. Diagnose and repair short in PTO wiring. Test, all okay. Diagnose secondary issues with heater fan. Replace blower fan and high-speed relay in behind dash, replace terminals. Test okay	07/02/2026	1322156	Completed	Myrtleford GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\AIR CON	DIAGNOSE & REPAIR A/C - FAN FAULT. VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		04/02/2026	1322156	Completed	Myrtleford GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		30/01/2026	1313760	Completed	Myrtleford GTK	XO01AE	MM DIESEL - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	VehService\AS		08/01/2026	1306278	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Cooling\COOL LEAKS	REPLACE COOLANT FILTER & TOP UP COOLANT		07/01/2026	1297713	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\SCALES	REPLACE TURNATBLE, BALL RACE & LOAD CELLS WITH DONOR FROM 999. CHL 1 SCALES ISSUE.		07/01/2026	1297713	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	ElecLab\ELECT P&W	CHECK TRAILER CONNECTION FOR TURN TABLE LOCK, FIT NEW MILITARY PLUG TO SCALES.		07/01/2026	1297713	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
				Repairs Carried Out: Travel to site. Inspect for leak, cut cable ties to header tank hose and inspect. Hose was damaged but no obvious leaks. Inspect for any other leaks, no luck. Replace hose and begin filling coolant, found coolant was leaking from water filter. Turn tap off and fill again. Found coolant filter was still leaking. Remove filter and re seat o ring. Refit filter and test for leaks, all good. Fill with rest of the 40 litres of coolant, not quiet full. Return to Heywood to collect more coolant. Fill the rest of the coolant. Cable tie hoses up and run engine. Check for leaks, all good. !!!							
			CALLOUT TO BREAKDOWN WITH COOLING SYSTEM @ HEYWOOD. COOLANT FILTER GASKET SPLIT.	Further Work Required: Water filter needs replacing. Coolant top up necessary							
1008	Myrtleford - Workshop	Cooling\BREAKDOWN	L098480	Heater taps require turning on.	06/01/2026	1297713	Completed	Myrtleford GTK	XO01AE	COOKY'S DIESEL MECHANIC REPAIRS - 3	P/MOVER
1008	Myrtleford - Workshop	Tyres\FITMENT	Tyres\FITMENT FLIPPED ON RIMS 5-12		06/01/2026	1297713	Completed	Myrtleford GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	Chassis\FIFTH WHEE	CHECK QRTT FOR SERVICEABILITY		15/12/2025	1297713	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	Cooling\ENG FAN	HORTON NEEDS REPLACING		15/12/2025	1297713	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\AIR CON	REPAIR CAB FILTER BRACKET HOUSING	Found on service filter bracket broken. Remove and replace bracket as required, all ok. KW25185926 COVER-POLLEN FILTER	18/11/2025	1292820	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\TRL LIGHTS	NUMBER PLATE LIGHT N/W	Inspect number plate light, found to working all ok. Wriggle and inspect wiring, unable to fault.	18/11/2025	1292820	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\HOUSEKEEP	DRAIN COOLANT / WATER MIX AND FILL WITH FRESH COOLANT FROM BREAKDOWN	Drain coolant and water mix. Filled with fresh coolant and replaced filter. KWELC40-20M PACGEN ELC40 PREMIX 20L 3 353.64 KWWF2077 WATER FILTER DCA4 REP.WF2064	18/11/2025	1292820	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\OIL LEAK	RH sump leak - recheck next service	Remove all bolts and brackets, lower sump, remove u bracket and remove sump. Clean sump and surface, remove gasket and fill cracks with epoxy. Fit new gasket then refit sump. Tension all bolts to spec. CU4026684 GASKET OIL PAN 1 809.15 CU3164067 SEALANT SILICONE ADHESIVE GREY	18/11/2025	1292820	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Steering\PWR STEER	Steering\PWR STEER LEAK	Inspect and found washer leaking. Clean off and monitor leak. To be rectified next service							
1008	Myrtleford - Workshop	Steering\PWR STEER	RECHECK STEER U BOLTS	Tension all u-bolts to spec, all ok	18/11/2025	1292820	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Chassis\BULLBAR	replace steel washers on bullbar bolts with nylon	5/11/25 WD OK	18/11/2025	1292820	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\WORK LIGHT	LH REAR WORK LIGHT MISSING VehService\BS B Service	Found LH rear work light missing. Replace as required and check operation, all working as should.done on 5/11/25 401725	18/11/2025	1289985	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\BS	L097681		13/11/2025	1289982	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\RADIATOR	Engine\RADIATOR VehService\AS A Service	TRAVEL TO CAMBERDOWN & RETURN TO COLAC FIT NEW RIATOR HOSE ON TOP OF THERMOSTAT HOUSING TOP UP WITH WATER	07/11/2025	1287835	Completed	Myrtleford GTK	XO01AE	QT DIESEL SERVICES - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	L097433		24/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\BREAKDOWN	GO TO YARD & JUMP START TRUCK	Travel out to GF yard and jump start truck. Disconnect trailers and drive truck to BMG workshop. Put truck on charge while windscreen is being replaced.	20/10/2025	1276263	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\WINDSCREEN	REPLACE PASSENGER SIDE WINDSCREEN	Carried out by Weston Tinting and Windscreens KWR44-1123 GLASS-WINDSHIELD TWO PC 1 213.47Sublet 1511534 WINDSCREEN INSTALLATION	20/10/2025	1276263	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Body\AIR LEAK	AIR DRIER LEAKING	nspect and found air dryer leaking from housing. Remove air dryer and rekit as needed. Swap over fittings and refit air dryer. Check for leaks, all ok	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Cooling\COOL LEAKS	SIGHT GLASS FOR RADIATOR TANK	Found sight glass for radiator tank was leaking. Removed sight glass and replaced with new. Washed down area from leak. KWSS-500B GLASS-SIGHT,RADIATOR TOP TANK	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Susp\SHOCK ABS	STEER SHOCKER BUSHES	RH and LH steer shockie bushes worn. Remove and replace all 8 bushes as required, all ok	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Susp\Torque Rod	torque rods rear - monitor CHECK OVER REAR SUSPENSION - TRUCK CRAB WALKING DOWN ROAD	Check over all rear suspension components. All looked ok - no bushes badly worn DONE ON 22/9/25 AT 11.50PM INVOICE 400004	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\RADIO	HANDS FREE MIC HANGING OUT OF DASH - BROKEN CLIPS	Did not have new clips in stock. Glue clips back together, will replace at later date if brake again	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\DAMAGE	BROKEN WIND DEFLECTOR	Remove and replace wind deflector, all ok KWKW1001DR WIND DEFLECTOR-DAYLITE DOOR RH	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Body\WIPERS	REPLACE WINDSCREEN WIPER PIVOT	LH wiper arm and stud need replacing. Remove windscreen trim and cut old wiper arm off as was glued on. Remove x2 e-clips off stud then removed stud. Fit new stud then refit e-clips. Fit new arm and put windscreen panel back on. Check operation, all ok KWGS3821 IDLER-WIPER ASSY LH 1 216.49KWS2280-1 SLEEVE-ARM DRIVING KNURL 1 7.75KW908.028 CAP	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Brakes\SLACK ADJ	Repalce s-cams on drive when brakes are low DONE AT 20/10/25 AT 280883 KMS ON INVOICE 401133 VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.	Inspect s-cams for movement, found LH rear and RH front axle s-cams were out of spec. Jacked up axles as needed, backed off brakes. Remove slack adjusters, remove boosters, s-cam tubes. Put tubes in parts washer. Removed CTI line, wheels drums and brake assemblies. Hit out s-cam bushes, removed s-cams and installed new. Refit brakes and wheels. Reconnect booster and slack adjuster. Adjust brakes and tensioned wheel nuts. KWK1T8042 KIT - CAMSHAFT REPAIR 1 37.57KW2210V7536FWPZ S-CAM 28S 11.6' R/H TRP EQUIVALENT CS966	15/10/2025	1280529	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\B1 Svc	L097163 Body\WIPERS T097237		13/10/2025	1272126	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Albury - Workshop	Body\WIPERS		REMOVE & REPLACE WIPER REFILLS	02/10/2025	1260690	Completed	Myrtleford GTK	XO01AE	MM DIESEL - 4	P/MOVER
1008	Myrtleford - Workshop	Tyres\Rims	Tyres\Rims POS 1		29/09/2025	1260690	Completed	Myrtleford GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	Body\WIPERS	Body\WIPERS PASSENGER SIDE N/W	PASSENGER SIDE WIPER N/W - CHECK AND REPAIR AS NEEDED Inspect and found threads and teeth stripped. Remove arm, centre punch and reattach. Temporary fix until truck in next.	18/09/2025	1260690	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Susp\Torque Rod	drive is walking all over the place. suggest torsion rod bushes stuffed ?	Check for rear suspension issue truck leaning into corners Check over all components of suspension all okay. Test drive, was not able to fault. Check issue when truck is loaded next.	05/09/2025	1260690	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Elect\INDICATORS	Elect\INDICATORS	Might be due to new drive tyres. INDICATOR FLASHING TOO FAST Remove flasher unit alter settings on switches. Refit flasher unit, all ok	02/09/2025	1260690	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER

1008	Myrtleford - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEEL RECHECK FOOT BUSHES	RECHECK TURNTABLE FOOT BUSHES Split truck and A trailer. Check and found foot bushes worn. Remove turn table top, remove and replace bushes as required. Fit turn table top and install pins and lock bolts	02/09/2025	1260690	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Chassis\WINCH/STRP	Chassis\WINCH/STRP FIRST BINDER HOOK NEEDS WELDING BACK ON	First binder weld hook back on Grind off old weld, measure and cut new hook then weld back on	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Body\BOLSTER	Bolster keeps falling down, needs to be welded or resecured	Bolster keeps falling down Inspect bolster, found not secure. Install bolt through eye to stop from falling out	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Body\MUDGUARDS	mudguard to be adjusted down	Adjust mudguard down as required Remove dash cluster, replaced blown globes as required. Check operation, all okay, refit dash cluster.	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\INST/GAUGE	4X DASH LIGHTS N/W	KW800005002 HOLDER-GLOBE INCLUDE GLOBE	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Brakes\BRK O/HAUL	CHECK S-CAM MOVEMENT AND ADVISE ON DRIVE BRAKE S/CAMS	Inspect s-cams for movement, found LH rear and RH front axle s-cams were out of spec. Jacked up axles as needed, backed off brakes. Remove slack adjusters, remove boosters, s-cam tubes. Put tubes in parts washer. Removed CTI line, wheels drums and brake assemblies. Hit out s-cam bushes, removed s-cams and installed new. Refit brakes and wheels. Reconnect booster and slack adjuster. Adjust brakes and tensioned wheel nuts. KWK1T8042 KIT - CAMSHAFT REPAIR 1 37.57KW2210V7536FWPZ S-CAM 28S 11.6' R/H TRP EQUIVALENT CS966	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\INDICATORS	L/H front indicator flashing faster than others	Inspect and test wiring, all okay. Check lights, could not fault.	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\TRL LIGHTS	Elect\TRL LIGHTS CLEARNACE LIGHTS OUT	LH AND RH 2 x CLEARANCE LIGHTS OUT LH and RH rear lights not working. Inspect LH light found to be broken, replace light as required. Test power and earth to RH light found nothing. Inspect and found broken wire, joined wiring and test, still not working. Inspect further and found fault at plug. Cut plug and repaired wiring. Plugged trailer light back in, check operation, all working ok.	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\RADIO	REPLACE UHF MIC HOLDER WITH MAGNET TYPE AS ADVISED BY W.D. Work order # 201289	Remove and replace UHF clip as requested. Mount with new bolts, checked all secure.	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Steering\OIL LEAK	CHECK POWER STEERING LEAK	Inspect for power steering oil leak, tightened all fittings and lines. washed down from leak	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\SCALES	NO SCALE	Inspect scales, found ride height valve on side of trailer was not fully engaged, changed ride height handle, all okay	02/09/2025	1283272	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	VehService\AS A Service L096533	GREENFREIGHT A SERVICE Carry out service as per Greenfreight checklist.	28/08/2025	1260690	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\ADBLUE	Engine\ADBLUE AFTER TREATMENT LIGHT CAME ON	CHECK AFTER TREATMENT LIGHT, WAS ON BUT NOW IS OFF Plugged into truck and check fault codes. Found codes for over temp but no codes for after treatment. Cleared all codes, all ok Carried out Greenfreight B service as required. Customer Instructions: Completed paperwork & Cleaned area TOOK ENGINE OIL SAMPLE & ECU DOWNLOAD	13/08/2025	1249991	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	Disconnect truck and trailer. Check over turntable and king pin. Greased all components, all within spec. Reconnect.	12/08/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Tyres\Punct	Tyres\Puncture 2S	CALL OUT	08/08/2025	1240823	Completed	Myrtleford GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	Engine\RERATE	Engine\RERATE BROKEN DOWN ON SEA COAST HILL RD. OILY SUBSTANCE FROM RH SIDE OF ENGINE AND RED STOP ENGINE	Travel to breakdown and inspect system, found coolant very low. Inspect under truck and found filter dripping, coolant filter needed replacement. Top up coolant to get truck back to workshop to fit new filter. Truck did not make it back to workshop due loss of coolant. Travel back out to truck, replace filter and top up with coolant.	05/08/2025	1240823	Completed	Myrtleford GTK	XO01AE	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1008	Myrtleford - Workshop	Cooling\BREAKDOWN	LIGHT ON	start and check over all okay	04/08/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Tyres\Punct	Tyres\Puncture POS 8	CALL OUT CAMPERDOWN COLAC REPLACE RH FRONT MUD GUARD Work order 199043	04/08/2025	1240823	Completed	Myrtleford GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	Body\MUDGUARDS	FR drive guard pole DONE BY B/M 29/7/2025 INVOICE 397859	Upon inspection found right hand guard pole loose. Removed deck plate and tighten pole, re check, all ok	01/08/2025	1240823	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	SLIGHT WEAR REAR ENGINE MOUNT Work order # 199043	31/07/2025	1240823	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\MOUNTS	Slight wear rear engine mount (monitor)	Inspect engine mounts, all okay. Continue to monitor.	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Steering\OIL LEAK	Power steering slight oil leak	POWER STEERING OIL LEAK Work order # 199043 Inspect power steering oil leak. Tightened loose fittings as required.	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\DAMAGE	PTO line rubbing, but no leaks	SLIGHT WEAR REAR ENGINE MOUNT Work order # 199043 Inspect engine mounts, all okay. Continue to monitor.	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Steering\PWR STEER	Power steering weeping		31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\OIL LEAK	Trans oil lines weeping from filler to cooler	TRANS OIL LINES WEEPING FROM FILLER TO COOLER Work order # 199043 Inspect trans oil lines. Found lines were sweating but okay. Truck would need to be pulled off road and have all new trans lines made up. Okay for now. Will continue to monitor on services.	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\RADIO	other operators having trouble understanding drivers through uhf hand piece.	OTHER OPERATORS CANT HEAR DRIVER THROUGH UHF Checked operation of UHF hand piece, found to be unserviceable. Removed hand piece and replaced with new. Tested operation, all okay	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\AIR LEAK	Left air intake pipe rubbing on guard	LH AIR INTAKE PIPE RUBBING ON GUARD Work order # 199043 Inspect air intake, found to be all okay	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\DRV LIGHT	Elect\DRV LIGHT	REMOVE x2 DRIVING LIGHTS AND GIVE TO JB **PRIORITY** Disconnected 2nd set of driving lights. Tidied up all wiring and covered plugs, all ok	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Hydraulics\OIL LEAK	PTO slight oil leak	PTO SLIGHT OIL LEAK & LINE RUBBING BUT NO LEAKS Work order # 199043 Check over and tightened fittings at PTO	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Brakes\BRAKE ADJ	All drive S-Cam bushes, slight movement (monitor)	ALL DRIVE S-CAM BUSHES HAVE SLIGHT MOVEMENT Work order # 199043 All drive s-cams have slight movement but all okay. Will replace s-cams when brakes are low.	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Cooling\RADIATOR	Rh inter cooler hoses starting to wear	RH INTER COOLER HOSES STARTING TO WEAR Work order # 199043 Undo clamps and replaced worn inter cooler hose. Refit clamps, tightened, all okay.	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Cooling\ENG FAN	Horton fan clutch starting to get low	HORTON FAN CLUTCH STARTING TO GET LOW Work order # 199043 Inspect horton fan, found to be okay. Will continue to monitor.	31/07/2025	1250087	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE RH FRONT MUD GUARD		29/07/2025	1240823	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\OIL LEAK	USING OIL REAR AIR TEMP GAUGE LIGHT N/W		29/07/2025	1240823	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\INST/GAUGE	TEMP GAUGE N/W PROPERLY		29/07/2025	1240823	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\MOUNTS	RH REAR ENGINE MOUNT LOOSE		29/07/2025	1240823	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrivLine	CALLOUT TO CAMPERDOWN TO REPLACE BROKEN CTI ROTATOR & HOSE, ALSO TYRES OFF BEAD.		29/07/2025	1260690	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER

				Tested EBS. Turned ignition on and all warning lights illuminated including ESC. Started truck and all light turned off. Turned on off road switch and ESC and ABS warning lights flashed to indicated they were turned off.as they should turned off off road switch and lights turned off. as they should.							
1008	Myrtleford - Workshop	Brakes\EBS FAULTS	test EBS		24/07/2025	1237926	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH	ADJUST CLUTCH Found on service clutch brake took time to engage. Adjusted clutch and pedal free play then cleaned clutch brake.	22/07/2025	1229666	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\WINDOW REG	Window has fallen down and wont go back up	Window has fallen down and wont go back up Test window operation, no good. Test and check fuses, all seem ok. Removed top and bottom door cards. Test LH switch in LH door, all working fine. Changed out RH switch with a test switch, still no good. Found window module to have power but not register. Replaced window module and test operation, window went up halfway then stopped. Found when door was fully open it wouldn't work, suspect rubbing wiring, to be further investigated next service. Inspect and found all door functions to not be working. Removed door card and panel, inspect wiring, suspect broken wire in between door and cab. Test wiring power and found the earth wire was broken. Ran new earth, was able to supply power back to door. Test and refit door panel, all ok	22/07/2025	1229666	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\WIPERS	ADJUST WIPERS	Inspect and found RH wiper was hitting cab causing hole in fibreglass. Removed old stalk and fit new one. Found LH wiper to be worn out and scratching windscreen. Removed, adjusted and fit new one. Adjusted wiper washer nozzles and test operation, all ok	22/07/2025	1229666	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\ST Weel	STEERING WHEEL HORN N/W	Test and check all working well, driver needs to push down hard on wheel to activate horn	22/07/2025	1229666	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Tyres\Punct	Tyres\Puncture POS 5		18/07/2025	1234371	Completed	Myrtleford GTK	XO01AE	BORDER BANDAG PTY LTD -3	P/MOVER
1008	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.		18/07/2025	1231431	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrivLine\CTI Drive	DrivLine\CTI Drive	Air CTI spinner has come off axle and hose is damaged truck on Jubilee hwy near crouch street Travel to breakdown, inspect to find out what parts need to be gathered. Received parts and took to breakdown. Fit CTI spinner, new hose and one new fitting. Trident pumped up tyres and put beads on. Turn CTI taps on, all ok	14/07/2025	1228797	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
				oolant Overfull Leaking Air Compressor Head Leaking Heater Taps Thermostat Binding Up Correction: Hrs: 26550 Klms: 1225162 Fuel Burn: 829991 - Connect laoptop & download - Carry out pressurizing checks; ok - Road test to get hot & recheck; ok - Found coolant level too high in header tank - During road test noticed thermostat late to open & coolant leaks at air compressor head & heater taps - Discuss findings with customer - Drain coolant & remove intake pipe, plumbing, p/steer pump & air compressor - Drop belts & remove turbo pipes, air con compressor & thermostat housing - Clean & inspect all parts - Install new thermostat & seal - Refit housing, air con & air pipes - Upfit & install new air compresor - Refit plumbing, p/steer pump & new governor - Replace leaking heater taps & refill with coolant - Steam clean & road test; ok							
1008	Myrtleford - Workshop	Engine\COMPRESSOR	REPLACE AIR COMPRESSOR & GASKETS (leaking coolant at head) replace thermostat & seal fit heater tap check cooling system for pressurising all ok at this stage replace top rad hose clamps		11/07/2025	1223455	Completed	Myrtleford GTK	XO01AE	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\WIPERS	Repair wiper blade fallen off		05/07/2025	1223456	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\OIL LEAK	SUSPECTED COOLANT LEAK DIAGNOSED TO BE OIL LEAK	Travel to Greenfreight yard, pressure tested cooling system on truck, found pressure didn't drop.Completed dropped liner test for the cooling system and was all fine, not able to fault the cooling system. Connect cummins computer to truck, found oil pressure sensor fault. Got truck to workshop, found pressure sender and switch broken off T piece. Remove and replace T piece, sender and switch. Check engine light still on, Remove and replace cummins pressure sensor, check engine light went out. Cleared all codes, all ok	05/07/2025	1222882	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		28/06/2025	1220560	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Chassis\AIR TANKS	Chassis\AIR TANKS	Order replacement compressor hose Removed compressor air supply and disconnect hose. Fit new compressor hose and secured, check operation, all okay	27/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrivLine\WHEEL ALGN	DrivLine\WHEEL ALGN	WHEEL ALIGNMENT AT TRIDENT	24/06/2025	1211513	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Hydraulics\HYD LEAKS	connections from truck to A trailer leaking every time used	Inspect and found Suzi fittings to be leaking. Removed and replaced all leaking fittings with new. Check over, all ok	24/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\ST Weel	Steering column wont unlock to adjust	Removed steering cover, found cable had fallen off. Put cable back on and cable tied neatly into place so would'nt fall off again. Put covers back on, all ok	24/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Chassis\FIFTH WHEE	CHECK AND ADJUST TURNTABLE JAWS	Disconnect truck from trailer, check tow adjustment, all was fine. Check king pin, ball race and all other components, all looked ok. Check over further, found movement in the first booster that could be causing driver to think its the turn table. Tighten booster so no more movement, all ok	24/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\FUEL TANK	D/S FUEL TANK LEAKING - CHECK BREATHERS	Checked over both breathers, blew them both out with air. Check over fittings and found RH pick up line thread was broken. Fix up broken section of hose as best as could and check over, all ok for the moment until new one arrives. New hose arrived, installed, all ok	24/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\DRV LIGHT	REPLACE FOG LIGHT FOR SPOT LIGHTS	Remove fog lights and fit 2 new LED driving lights and wire into fog light wiring. Remove relay box and change wiring to fog light relay. When fog light relay comes on, so will driving light circuit. KWRAP120DLV2/P	24/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\WORK LIGHT	HEAD BOARD LIGHTS N/W	RH clearance light at top N/W. Found wires corroded at light. Removed old light and replaced with new. Check operation, all ok	24/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE BUSHES	Found all shocker bushes to be worn, removed and replaced all 8 bushes	24/06/2025	1220562	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER

				WORK LIGHTS NOT TURNING ON TRAILERS ONLY LIGHT BAR OF TRUCK. WORK LIGHTS ON TRAILER DO COME ON WHEN IN REVERSE Work order # 197904 Inspect work lights for fault. Checked power at trailer plug in reverse, all okay. Removed plug cover and found wire for work lights was in wrong pin, move wire into spare pin for work lights. Check operation all okay. LH rear tail light out. Removed light and traced wiring, found damaged section. Cut out section. Run new wiring and joined to light, refit light. Also found clearance light							
			work lights not turning on trailers only light bar of truck.	was faulty due to damaged wiring. Cut out and joined new								
1008	Myrtleford - Workshop	Elect\WORK LIGHT	work lights on trailers do come on when in reverse	section, secure wiring and test, all okay.	19/06/2025	1211148	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				HORN ON STEERING WHEEL NOT WORKING ALL THE TIME Work order 197904 Check operation of horn, found to be dull, cleaned out horns								
1008	Myrtleford - Workshop	DriCabRep\ST Weel	Horn on steering wheel not working all the time	and re test all okay.	19/06/2025	1211148	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				ADJUST CLUTCH								
1008	Myrtleford - Workshop	DrivLine\CLUTCH	DrivLine\CLUTCH	Carried out clutch adjustment as required, all okay.	19/06/2025	1211148	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				REPLACE DRIVE AIR BAG - FLR AIRBAG Disconnect air lines, unbolt and removed air bag. Change over fittings and installed new air bag. Connect air lines,								
1008	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG	checked over, no further leaks.	19/06/2025	1211148	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP		13/06/2025	1211148	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	Engine\ENG TUNE	Engine\ENG TUNE	ECM SETTINGS GF B SERVICE Carried out B service as per Greenfreight checklist DISCONNECT TRUCK & TRAILER Disconnect truck and trailer. Check over turntable and king pin. Greased all components, all within	13/06/2025	1204960	Completed	Myrtleford GTK	XO01AE	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER	
1008	Myrtleford - Workshop	VehService\BS	VehService\BS	spec. Reconnec	10/06/2025	1211148	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				Travel to yard and inspect issue for truck not starting, check batteries and connections all okay, check starter motor and diagnose faulty starter. Travel to Greenfreight yard. Lift bonnet, disconnect batteries and wires on starter motor. Remove starter motor bolts, then remove starter motor. Swap over plug, fit new starter motor to truck. Tighten starter motor bolts and fit all wires to new starter motor. Zip tie wiring. Connect								
1008	Myrtleford - Workshop	Engine\START MOTR	Truck wont start at yard	batteries and start truck. All ok.	05/06/2025	1210568	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				REPLACE HOT LINE FROM PIPE TO AIR DRIER Work order 197225 Remove both ends of hose, remove all clamps and zip ties. Remove hose, take to GWH to get new hose made. Fit new hose and tighten all fittings. Refit all clamps and new zip ties. Tested and found governor valve leaking. Remove and								
1008	Myrtleford - Workshop	Engine\HOT PIPE	REPLACE HOT LINE FROM PIPE TO AIR DRYER.	replace governor valve with new. Tested, all ok	28/05/2025	1203559	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				INTERIOR LIGHT COVER MISSING Work order 197225								
1008	Myrtleford - Workshop	DriCabRep\DAMAGE	interior light cover missing	Fit new globe and cover to interior light.	28/05/2025	1203559	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				WIPER BLADES COMING OUT Work order 197225 Put wiper blade back in, crimped tabs to hold in place better. Checked for movement, all ok. truck returned with further wiper issue. Removed wiper head								
1008	Myrtleford - Workshop	Body\WIPERS	wiper blades coming of possible need new head	and replaced with new.	28/05/2025	1203559	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				HOSE AT BOTTOM OF RESERVOIR LEAKING Work order 197225 Cleaned over hose and found fitting loose tighten and check level, all ok. Turned wheel								
1008	Myrtleford - Workshop	Steering\HOSES	hose at bottom of reseviour leaking	left to right. Checked all fittings were tight all okay	28/05/2025	1203559	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				UHF mounting screws come out Check over UHF screws and dash pane. Found all to be in								
1008	Myrtleford - Workshop	DrCabElect\RADIO	DrCabElect\RADIO	place and tight	28/05/2025	1203559	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		27/05/2025	1201726	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		27/05/2025	1199685	Completed	Myrtleford GTK	XO01AE	BEAUREPAIRES - 3	P/MOVER	
1008	Myrtleford - Workshop	Engine\ADBLUE	replace ad blue cap		19/05/2025	1192745	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				Found steering lock not working, had locked itself in the down position. Remove covers, found release wire had come out, and lock was tight and dry. Lubed lock up, mounted								
1008	Myrtleford - Workshop	DriCabRep\ST Weel	STEERING WHEEL TILT LOCKED ALL THE WAY FORWARD AND WONT MOVE	cable, put covers back on, checked operation, all ok	09/05/2025	1192745	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				ADJUST CLUTCH								
1008	Myrtleford - Workshop	DrivLine\CLUTCH	DrivLine\CLUTCH	Carry out clutch adjustment, adjusted free play, all ok.	08/05/2025	1191038	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				Inspected and found UHF unit fallen back. Pull dash panel off. Secure into sleeve with bolts from sleeve to UHF.								
1008	Myrtleford - Workshop	DrCabElect\RADIO	DrCabElect\RADIO	Securely in place wont fall out, refit panel.	08/05/2025	1191038	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				Remove side trim and seat base. Moved seat around until locked in. Removed the rest of the side trim. Found spring was worn and stretched. Ordered new spring. Fit trim back together. Fit seat back together. Was able to get seal to lock into a position driver was happy with. Part arrived, removed side panel and fit new spring. Found seat still not locking in position. Needed to replace seat. Unbolt floor mounts, disconnect all lines and removed seat. Installed new seat, secured. *used GF spare seat* will need								
1008	Myrtleford - Workshop	DriCabRep\SEAT	DRIVERS SEAT BACK WONT LOCK IN POSITION	to be sent back for repairs.	06/05/2025	1192745	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	DrCabElect\BATTERY	LOAD TEST AND CHECK BATTERIES	Disconnected 4 batteries and load tested, all ok. Check every cell for levels, all ok. Reconnected batteries.	29/04/2025	1188134	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc		25/04/2025	1188013	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	CTILab\CTI Drive	MAKE UP CTI BREAK DOWN TOOL BOX FOR 1008		17/04/2025	1186311	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER	
1008	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		11/04/2025	1181406	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				Found LHR wheel seal leaking. Backed brakes off and jacked up LH side of axle the removed axle and hub assembly. Removed bearings from assembly. Cleaned hub and bearings. removed linings from axle, and removed drum from hub assembly. Replaced components, fitted bearings and new seal to hub assembly. Refit hub assembly to axle, and tensioned.								
1008	Myrtleford - Workshop	DrivLine\WHEEL SEAL	DrivLine\WHEEL SEAL	Check movement, all ok	11/04/2025	1181404	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				GUSSET BEHIND GEARBOX CRACKED Found gusset on RH cracked. Disconnected mounting bolts from chassis and DPF. Pried cracked gusset out. Fit new								
1008	Myrtleford - Workshop	DrivLine\GEARBOX	DrivLine\GEARBOX	gusset, put bolts back in, tightened, all ok.	11/04/2025	1181404	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				8.4.25 DIAGNOSE TRUCK OVERHEATIN BLOW OUT RADIATOR CHECK WITH INSITE ACTUAL ECM READ TEMP COMPARED TO DASH GAUGE								
1008	Myrtleford - Workshop	Cooling\RADIATOR	Cooling\RADIATOR	FOUND TO BE OK TOP UP COOLANT RUN TEST OK	09/04/2025	1181404	Completed	Myrtleford GTK	XO01AE	Unknown	P/MOVER	
				Remove kick panel, found coolant residue on heater core. Crimped hoses and unbolted. Removed heater core and replaced with								
1008	Myrtleford - Workshop	Cooling\COOL LEAKS	occasional coolant smell	new. Reconnect hoses and kick panel.	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
				Remove dash, unplug engine idle timer and remove unit. Removed piggy back plug, and installed new unit. Tested all								
1008	Myrtleford - Workshop	Engine\TURBO	turbo timer doesnt work	ok. Reassembled dash.	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	
1008	Myrtleford - Workshop	DriCabRep\WIPERS	wiper blades need replacing	Removed old wiper blades and replace with new.	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER	

				Inspected and tested lights, found no operation at lights. Test fuse, all ok. Test and found relay switching but no light operation. Test at bulk head and found terminal not contacting correctly. Replaced relay block, secured and refit relay panel. Test operation, all ok. Current draw ok							
1008	Myrtleford - Workshop	Elect\DRV LIGHT	DRIVE LIGHTS N/W	at time of testing, if re fault occurs, may need re wiring.	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\DAMAGE	CHECK FLOOR HUMP, CAB FILLS WITH DUST WHEN ENGNE FAN COMES ON	Found on service that firewall dust cover was pushed into the cab. Pushed back into position, all okay	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\SCALES	Fit Bluetooth right weigh scales	Mount and wire in new right weigh scales as requested. Locate and repair faulty power wire. Run air lines and secure, tested all ok.	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
				Test and found Elphinstone scales reading erratic. Stood on scale, found to be reading correct. Unplug one load cell and check plug etc, all ok. Inspect other cell, all ok.							
			Channel One Is Out By 6 To 8 Ton possible load cell	Individually plugged one load cell at a time, found one cell reading and one stuck on 6300kg. Load cell needs							
1008	Myrtleford - Workshop	Chassis\SCALES		replacing. (Or drivers just use new right weigh scales)	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\ELECT P&W	centre dash light	Inspected and found x2 pyro globes out. Replaced both globes, all ok.	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	DriCabRep\RADIO	UHF AERIAL BROKEN	Removed snapped aerial piece and replace with new	02/04/2025	1185225	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
				1 01KWGREENMINIB MINI B SERVICE Tech(s): 8091 8101 8099 225.00MINI B SERVICE Jack up steer axle, check bearing & king pin. Replace cab filter Carried out Mini B Service as per Greenfreight checklist Customer Instructions: Greased and Adjusted Brakes Checked all Fluid Levels Completed paperwork & Cleaned area						
			BRAKES NOT HOLDING ON TRUCK WHILE LOADDING ON HILL								
1008	Myrtleford - Workshop	Brakes\BRAKE ADJ	ALL BRAKES WERE ADJUSTED ON B1 SERVICE AT 188013KMS BY B/M MT GAMBIER 29/4/25 W/O 196383 INVOICE 393895	Replaced cabin air fil Driver advised steering went tight and released again. Turned steering wheel and visually inspected, all moving okay, no damages. Jack up and check king pins, all okay.	02/04/2025	1188134	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
1008	Myrtleford - Workshop	Steering\PWR STEER	CHECK STEERING, LOCKED UP	Topped up power steering oil. LOOSE BOLTS ON HEAD BOARD PASSENGER SIDE Tighten loose headboard bolts, tighten turntable bolts and skid plate bolts. Check over all bolts and tighten, all ok.	27/03/2025	1176148	Completed	Myrtleford GTK	XO01AE	BARRY MANEY - 3	P/MOVER
			cab mount s may need looking at logg rack mounts were loose causing noise	Disconnect B trailer and lift turntable to access bolts.							
1008	Myrtleford - Workshop	DriCabRep\MOUNTS	kms 172937	Tighten and reattach as required. Trailer taken for repairs TAIL LIGHT FALLEN OUT Removed broken tail light from truck. Cut and wire in plug.	26/03/2025	1174004	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\ELECT P&W	loose rear tail lights drivers side	Mount in light plug, test operational, all ok. LOOSE BOLTS ON HEAD BOARD PASSENGER SIDE Tighten loose headboard bolts, tighten turntable bolts and skid plate bolts. Check over all bolts and tighten, all ok. Disconnect B trailer and lift turntable to access bolts. Tighten and reattach as required. Trailer taken for repairs	26/03/2025	1170754	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\DAMAGE	Body\DAMAGE	- J.D metal.	26/03/2025	1170754	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\CS	VehService\CS engine was tuned also	resample both diffs at next B 1 service	08/03/2025	1166323	Completed	Myrtleford GTK	XO01AE	QT DIESEL SERVICES - 3	P/MOVER
1008	Myrtleford - Workshop	DrivLine\OIL LEAK	REPLACE FRONT DIFF INPUT SHAFT BEARINGS & OIL PUMP HOUSING & SEAL DONE AT 166323KMS		08/03/2025	1170754	Completed	Myrtleford GTK	XO01AE	QT DIESEL SERVICES - 3	P/MOVER
1008	Myrtleford - Workshop	Engine\FAULT CODE	CHECK FAULT CODES FIT NOX FLUSH DOSER PUMP CHECK POWER SUPPLY FROM BATTERIES TO BACK OF G/BOX & CLEAN ALL CONECTORS REMOVE DOSER PUMI		04/03/2025	1170754	Completed	Myrtleford GTK	XO01AE	QT DIESEL SERVICES - 3	P/MOVER
1008	Myrtleford - Workshop	DrivLine\DRV LN SER	TIGHTEN LOOSE INPUT AND THROUGH-SHAFT YOKES ON FRONT DIFF. DONE AT 251057KMS REPAIR DRIVING LIGHTS &REPLACE 12V RELAY		20/02/2025	1164578	Completed	Myrtleford GTK	XO01AE	QT DIESEL SERVICES - 3	P/MOVER
1008	Myrtleford - Workshop	Elect\DRV LIGHT	161202KMS		16/02/2025	1166226	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	VehService\AS		06/02/2025	1158516	Completed	Myrtleford GTK	XO01AE	JF MECHANICALS - 3	P/MOVER
1008	Wodonga - Workshop	VehService\B1 Svc	VehService\B1 Svc		11/01/2025	1149760	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
				ENGINE BRAKE * Inspected all components * Found interior lights & steering wheel buttons also inoperative * Inspected fuses & found fuse to be missing * Installed replacement fuse							
1008	Myrtleford - Workshop	Brakes\BREAKDOWN	Engine Brake Won't Turn Off.	* Test drove & test operations - All ok, fault no longer present	11/01/2025	1149760	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\GEARBOX	Gearbox lost direct gears both bottom & top box.	FIT NEW G/BOX & CLUTCH BRAKE TRANSMISSION GRINDING UNDER LOAD & STRUGGLING TO SELECT LOW GEARS $2,875.19 . ** REPAIRS CARRIED OUT 9-10TH JAN 2024 ** . * Test operations & confirmed fault * Unbolted & removed toolbox for access * Disconnected & removed all lines & wiring as required * Removed gearstick * Hoisted truck * Unbolted & removed driveshaft, crossmembers & all components * Unbolted & removed gearbox * Disassembled gearbox & inspected all components * Found countershaft in auxiliary to be broken & caused further damage to gears in auxiliary * Report findings to customer who request to replace transmission * Removed clutch & inspected - All ok * Inspected rear main seal - No leaks evident * Inspected rear engine mounts & gear stick isolator bushes - All ok * Inspected all clutch linkages & found washer to be missing - replaced as required * Sourced replacement gearbox * Swapped all components to replacement gearbox * Refit clutch & gearbox * Refit all components * Refit driveshaft with replacement bolts * Replaced transmission filter & oil * Aligned, adjusted & tensioned all components	11/01/2025	1149760	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
			FIT NEW GEARBOX & CLUTCH BRAKE (CHECK CLUTCH ITS IN GOOD CONDITION) CHECK REAR ENGINE MOUNTS ALL OK								
1008	Myrtleford - Workshop	DrivLine\GEARBOX	148194KMS Engine\DAMAGE	* Test operations - All ok, fault no longer present	11/01/2025	1149760	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Engine\DAMAGE	ACCIDENT REPAIR		09/01/2025	1149734	Completed	Myrtleford GTK	XO01AE	ROYANS WODONGA - 4	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10		13/12/2024	1146916	Completed	Myrtleford GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4		13/12/2024	1146916	Completed	Myrtleford GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6		13/12/2024	1146916	Completed	Myrtleford GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8		13/12/2024	1146916	Completed	Myrtleford GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Engine\JAKE BRAKE	Engine Brake Not Working Properly. (Cummins Wodonga P/O: T090800)		12/12/2024	1149760	Completed	Myrtleford GTK	XO01AE	CUMMINS SOUTH PACIFIC P/L - 4	P/MOVER
			Steering\OIL LEAK BREAKDOWN . The following breakdown repair for Greenfreight Logging Pty Ltd, to a T909, Chassis#6F5000000HA459713, Rego XO01AE & Fleet number#1008 included: . * Customer contacted dealership to report breakdown * Customer advised that truck had a fuel leak * Technician already at depot * Inspect & confirmed power steering oil leak - no fuel leak * Checked leaking fitting & tensioned * Start, action & monitor for further leak - no leak evident now * Cleaned down oil contamination * Returned truck to service * Follow up possibly - new hydraulic line to be replaced								
1008	Albury - Workshop	Steering\OIL LEAK			11/12/2024	1145106	Completed	Myrtleford GTK	XO01AE	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1008	Wodonga - Workshop	Engine\ENG TUNE	Engine Brake Not Working To The Full Properly A Service.	Duplicate job	10/12/2024	1145106	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Serviced @ 1143392 Klms		10/12/2024	1145106	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER

				Ride height is at a normal position									
1008	Wodonga - Workshop	Susp\HCV	Ride Height Needs to be looked at.	Ran the bags flat and pumped them up twice ride was the same both times	10/12/2024	1145106	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\DAMAGE	Engine Brake Not Working %100	Duplicate job	10/12/2024	1145106	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\ELECT P&W	Truck Scales Not Working.		10/12/2024	1145106	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Tyres\RETREAD	Needs New Drive Tyres.		10/12/2024	1145106	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\DRV LIGHT	Driving Lights Not Working.	Job Completed Saturday 7 12 24	10/12/2024	1145106	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Myrtleford - Workshop	Hydraulics\HYD LEAKS	HYD oil leak at tank		10/12/2024	1170754	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
			ALL READY AT SITE CHECK LIGHTS CHECK LH LOW BEAM WORKING INTERMITANTLY FOUND BROKEN WIRE NEAR PLUG FOUND HI BEAM FLICKERING DUE TO BAD CONNECTION IN PLUG REPAIR TO SUIT OPERATION OK RERUN AND TIDY UP HARNESS UPON INSPECTION FOUND DRIVING LIGHTS N/W FOUND FAULTY DRIVING LIGHT RELAY REMOVE AND REPLACE									
1008	Albury - Workshop	Elect\HEAD LIGHT	OPERATION OK Headlights [LOW BEAM] Flickering.		08/12/2024	1147085	Completed	Myrtleford	GTK	XO01AE	HAGANS AUTO ELECTRICAL SERVICE	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	REPAIRED WIRING FOR HIGH BEAM. FURTHER REPAIRS REQUIRED.	Hagans auto elec coming to finish	07/12/2024	1144236	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\DAMAGE	Hydraulic Tank Leaking Oil.	Topped up	06/12/2024	1143874	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		03/12/2024	1141031	Completed	Myrtleford	GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Wodonga - Workshop	Tyres\ALIGNMENT	Needs Wheel Alignment	Checked by tyre person	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\COOL LEAKS	Heavy Coolant Smell In Cabin	Duplicate job	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\JAKE BRAKE	JAKES 'MISSING' ABOUT 1700RPM.	Duplicate job	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT ON INTERMITTENTLY.	Previously completed	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\SCALES	Scales Unit Not Working Bay 2&3	Duplicate job	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\COOL LEAKS	Heavy Coolant Smell In Cabin	Duplicate job	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	CH1 SCALES NOT WORKING- WEIGHT IS ALL OVER THE PLACE. (SEE HOW THEY GO, TRIED CALIBRATING THEM)	Channel 1 scales now operational	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\IAP	TABLET NOT WORKING- NO CONNECTION.	Issue for James	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\COOL LEAKS	Heavy Coolant Smell In Cabin	Checked heater core for any leakage checked clamps no leaking is apparent internally	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ENG TUNE	Jake Brakes "MISSING" Under 1500 RPM	Completed by ruby	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	VehService\AS		02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\SCALES	scales not reading right	Duplicate job	02/12/2024	1141030	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	CTI\CTI Drive	Turn Off all CTI Taps		16/11/2024	1131614	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				506 loaded on back of 506								
1008	Wodonga - Workshop	Chassis\FIFTH WHEE	Disconnect T381 Off T380 & Connect T506 To T380	Trl 283 loaded on to 380	16/11/2024	1131614	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	VehService\AS		06/11/2024	1139472	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP02	Tyres\TP02		02/11/2024	1128794	Completed	Myrtleford	GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Air Con\AIR CON	Air Con\AIR CON #1008 909 Kenworth *Aircon nw properly *May need regas *Onsite at GF *Ring Shaun Before going Travel to Green Freight. Pressure test ac system. Inspect for leaks. Found one leaking hose at the condenser. Remove hose and make a new hose. Fit new hose and pressure test again. Inspect for leaks and diagnose another leak. Charge system with trace gas. Inspect the cabin with trace gas and sniffer. Found a leak inside of cabin coming from the evaporator. Remove surrounding dash panels. Disconnect the TX valve from the pass through hoses on the fire wall. Clamp off the coolant hoses and disconnect the heater core. Unbolt the heater box assembly. Remove the evaporator. Inspect the evaporator and found that it was leaking. Replace the evaporator. Refit the heater box. Pressure test the ac system. The ac system is not holding pressure. Refit all dash panels and surrounding components. Vacuum the ac system down for 45 min's. Held vacuum, ok. Charge the ac system with R134a refrigerant. Start the truck to test. Ac system was not working. Inspect power at the pressure switch, ok. Inspect power down at the clutch on the compressor, ok. Compressor had failed. Remove compressor and contact customer. Customer supplied new compressor and a new belt. Flush the ac system. Mount the new compressor and fit the new belt. Recharge the system with R134a refrigerant. Start truck and test the ac system. Ac system		30/10/2024	1127382	Completed	Myrtleford	GTK	XO01AE	ARKON AUTO ELECTRICAL - 4	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	AIR CON NOT WORKING. CH 1 SCALES NOT WORKING.		29/10/2024	1125567	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NOT WORKING.	REPLACED BLOWN FUSE.	29/10/2024	1125567	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	Air Con Not Working		29/10/2024	1125567	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Air Con\AIR CON	Air Con Not Getting Cold. (Parts Supplied By TCTC P/O: T089841)		26/10/2024	1164578	Completed	Myrtleford	GTK	XO01AE	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
				Tightened exhaust flex Replaced coolant tap Tightened clamp coolant leak Tightened bolts around PTO leaking Changed fuel pro filter Washed down batteries checked fluid level								
1008	Wodonga - Workshop	VehService\AS	VehService\AS	Replaced guard hanger	24/10/2024	1126033	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\B1 Svc	VehService\B1 Svc		24/10/2024	1126033	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Myrtleford - Workshop	Hydraulics\OIL LEAK	hyd oil leak at tank	inspected oil leaks found plastic filter top cover out of shape replaced and tested all good recheck oil le	15/10/2024	1119832	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	Check & Adjust Clutch		09/10/2024	1117650	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	Adjust Clutch (Please)		09/10/2024	1117650	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	VehService\AS		08/10/2024	114558	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\HYD LEAKS	Hydraulic leak out of PTO box side of truck		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	VehService\AS		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	Speed limiter not accurate		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ENG FAN	Horton Fan Switch Not Working Properly		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\DRV LIGHT	Driving Lights Keep Melting Relay		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	Driving lights (spotties) not working!		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	VehService\BS		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRAKE ADJ	Vibration In Steering When Brakes Applied		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	Make up adaptor for light		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\SCALES	Truck scales not working speedo reads 110kmph		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\RERATE	GPS reads 104kmph		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\SCALES	No scales		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	rear shocks also		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	cab shocks stuffed		14/09/2024	1115737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabRep\WIPERS	R/H windscreen wiper U/S blade	Cherysh completed	29/08/2024	1098707	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\WIPERS	Replace Wiper Blades	Replaced driver side wiper arm	29/08/2024	1098336	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	Speedo Reads 110 Km Ph GPS 104 KM Ph	Arkon	26/08/2024	1096570	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\HYD LEAKS	HYDRAULIC LEAK OUT OF ALUMINUM BOX (PTO FILTER)		26/08/2024	1096570	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	Cab Shocks Stuffed	Cab shocks inspected. Not damaged or leaking in anyway	26/08/2024	1096570	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	No Scales VehService\AS Serviced @ 1095689 Klms		26/08/2024	1096570	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS			26/08/2024	1096570	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	CHANNEL ONE FOR SCALES NOT WORKING.	Arkon	26/08/2024	1096570	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\TRL LIGHTS	Make Up Adaptor For Lights	Called Into Yard as Trailer Had No Lights, Made Up New Heavy Duty To Light Duty Adaptor, Tested All Lig	21/08/2024	1092947	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	REPLACE IAP TABLET CRADLE WITH UPDATED VERSION.		09/08/2024	1090946	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	VehService\AS	87389ks	06/08/2024	1088092	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6		01/08/2024	1085524	Completed	Myrtleford	GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8 Insp\RWC COMP		01/08/2024	1085524	Completed	Myrtleford	GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Insp\RWC COMP	RWC INSPECTION		30/07/2024	1085503	Completed	Myrtleford	GTK	XO01AE	CMV TRUCK & BUS - 4	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 Wheel Alignment (Hume Truck Technics P/O: T087783)		30/07/2024	1085503	Completed	Myrtleford	GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN			30/07/2024	1085500	Completed	Myrtleford	GTK	XO01AE	HUME TRUCK TECHNICSP/L-4	P/MOVER

					RUBY 1½ HOURS LABOUR							
1008	Wodonga - Workshop	VehService\AS	VehService\AS		DAN 1½ HOURS LABOUR	19/07/2024	1084836	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WINDSCREEN	Chip in screen in field of view		AUTOSCREEN	19/07/2024	1084836	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Insp\RWC COMP	RWC Inspection (CMV Wodonga P/O: T087490)			19/07/2024	1085494	Completed	Myrtleford GTK	XO01AE	CMV TRUCK & BUS - 4	P/MOVER
			Tighten All Drive Shockers Upper & Lower Nuts									
1008	Wodonga - Workshop	Susp\SHOCK ABS			All drive shocks were tight very tight had leading hand check them first	13/07/2024	1083470	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
			Replace Left Rear Brake Booster									
1008	Wodonga - Workshop	Brakes\BOOSTER			Left rear brake booster wasn't leaking replaced anyway had leading hand check it	13/07/2024	1083470	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\HOUSEKEEP	Give Chassis, Engine & Drive Line A Good Wash To Get Rid Of Any Oil Leaks/Residue			13/07/2024	1083470	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
			Fit Seat Belt Alarm (Hagan's Auto Electrical P/O: T087335)									
1008	Albury - Workshop	DriCabRep\SEAT				13/07/2024	1083469	Completed	Myrtleford GTK	XO01AE	HAGANS AUTO ELECTRICAL - 4	P/MOVER
1008	Albury - Workshop	Chassis\FUEL TANK	Fuel Lines Leaking (Rapid Hydraulics P/O: T			12/07/2024	1121204	Completed	Myrtleford GTK	XO01AE	RAPID HYDRAULICS & PNEUMATICS -4	P/MOVER
1008	Albury - Workshop	Elect\DRV LIGHT	Driving Lights Not Working (Hagan's Auto Electrical P/O: T087257)			10/07/2024	1081982	Completed	Myrtleford GTK	XO01AE	HAGANS AUTO ELECTRICAL SERVICE	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	HEADLIGHT OUT.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\ABS	Trailer ABS Light Is On		Only when trailer is connected problem in trailers	09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\FUEL TANK	REPLACE LH FUEL RETURN TUBE.		Has been previously completed "	09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\CONSUMABLE	WE NEED A BROOM ON TRUCK.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO READING 10KM OUT. NEED CALIBRATION 100KM READING 110KM.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO JUDDERS & READS FAST- DOESN'T WORK SOMETIMES.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\HCV	RIDE HEIGHT ADJUSTMENT.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO PLAYING UP- STOPS WORKING OCCASIONALLY.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	Check engine light on			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	HEADLIGHT OUT L.H.S.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	CALIBRATE SCALES.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	Check Engine Light Is On			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	scales need calibrating			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\Oil Pump	Low oil pressure			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	Low Oil Pressure			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\OIL LEAK	Diff Front Leaking			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\DRV LIGHT	No Driving lights		Driving lights are working. This was previously repaired	09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\DRV LIGHT	Driving Lights Flicking On & Off & Not Working		Previously completed. The relay wasn't working, lights are now fixed	09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Tyres\ALIGNMENT	Wheel Alignment - Steering Tyres Dropping Shoulder			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\ABS	Trailer ABS light on			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\MUDGUARDS	Out Riggers On Drive Guards Loose		three out riggers tightened	09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP		Check engine light on no adapter for computer to check it our computer doesn't connect only Shaun's c	09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
					Cherish and Doug completed this svc							
1008	Wodonga - Workshop	VehService\BS	VehService\B/S		Russell carried on with rnrs on trailers and truck	09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	RHS LOW BEAM WENT OUT AGAIN- POSSIBLE SHORT.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO OUT. READING 110KM. TRUCK ONLY DOING 100KM.			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\WHEEL ALGN	Wheel alignment needed			09/07/2024	1088390	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	CHECK CAB SHOCKS.			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\HYD LEAKS	LEAKING HYDRAULIC OIL.			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\HOUSEKEEP	NEED NEW RNR BOOK LAST PAGE.			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\Torque Rod	REPLACE FRONT TORQUE ROD BUSHES.			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	VehService\AS			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MUDGUARDS	DRIVE GUARD L.H. SIDE REAR LOOSE.			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	SERVICE DUE.			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\OIL LEAK	LEAKING FRONT DIFF.			09/07/2024	1072336	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			28/06/2024	1074908	Completed	Myrtleford GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			28/06/2024	1074908	Completed	Myrtleford GTK	XO01AE	BEAUREPAIRES - 4	P/MOVER
1008	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6			28/06/2024	1074908	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			28/06/2024	1074908	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\DRV LIGHT	Diagnose electrical light problem.		Broken wiring and burnt relay	28/06/2024	1074721	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUST.			18/06/2024	1042805	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	SPRING ON CLUTCH PEDAL SNAPPED			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\FIRE EXTIN	FIRE EXTINGUISHERS NOT UP TO DATE.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\HYD LEAKS	HYDRAULIC LEAK WHEN PTO ENGAGED.		Previously complete	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO NOT WORKING!		Duplicate entry	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALE CALIBRATION.		Driver to calibrate	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\GEARBOX	GEARBOX WORN. NOTCHY GOING IN TOP BOX.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	SERVICE DUE.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	SCALE CALIBRATION.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\AIR CON	SCALES		Duplicate entry	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\DOOR LOCK	DOOR RUBBER ON LHS NEEDS TO BE RE-GLUED.		Previously done	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	SERVICE DUE.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRK O/HAUL	FRONT BRAKES DRUMS MUST BE WORN OUT. CAN FILL BRAKEFADE/PULSE.		There is a lip but brakes are good no hubseal leak monitor for now	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	SERVICE.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRK O/HAUL	FRONT BRAKE DRUMS NEED TO BE CHECKED. WORN OUT POSSIBLY.		Brakes are good minor lip in drum monitor	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	L.H. HEADLIGHT.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
					Shane McCabe started this service and dud most of it							
1008	Wodonga - Workshop	VehService\BS	8 Service			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\TURBO	WASTE GATE STICKING. NOT OPENING ALL TIME TO FULL BOOST.		Previously completed	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO CALIBRATION		Previously completed	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO STOPS WORKING.		Previously completed	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES.		Duplicate entry	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRK O/HAUL	FRONT BRAKES GROANING WHEN PULLING UP. SOMETHING IS NOT RIGHT WITH THEM. DOESN'T STOP LIKE THET SHOULD EITHER.		Brakes are good no need to change	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	SERVICE A OVERDUE 7000KM.			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\PANELS	BOLT L.H.SIDE NEAR HYDRAULIC TANK LOOSE ON COVER PLATE.		Previously done	14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	OVERDUE FOR SERVICE			14/06/2024	1060916	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	VehService\AS			06/06/2024	1051861	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc			06/06/2024	1053881	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service		TOPPED UP HYDRAULIC OIL. REPLACED STEER SHOCK RUBBERS, LH STEER WHEEL STUD. REPAIRED HYDI	06/06/2024	1053881	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Engine\BREAKDOWN	Customer contacted dealership to report breakdown * Customer advised that drain tank cock had been ripped out after hitting wombat * Technician sourced add			24/05/2024	1042805	Completed	Myrtleford GTK	XO01AE	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	HEAD LIGHTS ARE FLICKERING.		DIAGNOSED AND REPAIRED RUBBED WIRING. REPLACED FUSE. TESTED. OK.	09/05/2024	1031652	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	Replaced Tilt Dampener			07/05/2024	1028831	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATING.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\COOL LEAKS	HAS COOLANT LEAKING FROM FLEXI HOSE.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	WORK LIGHTS HAVE A SHORT- FLICKER ON & OFF, CAUSES SCALES TO TURN OFF.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	PLEASE ADJUST CLUTCH (NO CLUTCH BRAKE)			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine	TRUCK HAS DRIVELINE VIBRATION.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\OIL LEAK	TRUCK HAS HYDRAULIC LEAK AT TANK.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\INDICATORS	FRONT L/H INDICATOR NOT WORKING.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATING- NEED EMPTY.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\WHEEL ALGN	TRUCK PULLS TO THE LEFT.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATING.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\WHEEL ALGN	TRUCK PULLS TO THE LEFT.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATION.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	STEERING COLUMN LOCK MALFUNCTIONING.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\BRK LIGHT	R/H BRAKE LIGHT NOT WORKING.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	HAS A SQUEAK IN STEERING COLUMN.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\WHEEL ALGN	TRUCK PULLS TO THE LEFT.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	fit LEDhead lights			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BACK PLATE	REPLACE RR BACKING PLATE.			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		DIAGNOSED AND REPAIRED HORN WIRING. TIGHTENED LOOSE CTI LINES.	03/05/2024	1028802	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	fit guardian system			15/04/2024	1076799	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine	DOWN ON POWER- FULL GEAR SLOWER IN THE HILLS THAN IT USED TO BE.			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	CAB GUARD LIGHTS NOT WORKING.			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WINDSCREEN	REPLACE L/H WINDSCREEN WIPER THAT HAS BEEN REMOVED.			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine	DOWN ON POWER- ½ A GEAR ON HILLS.			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	CAB GUARD LIGHTRS DON'T WORK.			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	Clutch Has Too Much reeplay			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\DRV LIGHT	L/H Fog Light Needs Refitting To Bull Bar			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	truk safe sticker out of date			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\RADIATOR	Radiator mounts worn			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
			number plate light N/W									
1008	Wodonga - Workshop	Elect\TAIL LIGHT	Left rear side marker light N/W			22/03/2024		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER

			*GF #1008 * @ Royans *MT DATA UPGRADE (Parts here, GF supplied) Remove and replace the tracking unit with the 4g unit. Replace the damaged ignition pug on the unit. Fit new high gain antenna. Ring mt data to set up the unit. Carry out the final test and checks ok. OLD TAGS: 020163 020164 NEW TAGS: 002863 002864 NEW UNIT 419005063 NEW UNIT 469001611									
1008	Myrtleford - Workshop	DrCabElect\GPS	Phone# 0456953119		14/03/2024	1020906	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Body\DAMAGE	TRAVEL TO ROYANS WODONGA AND REMOVE REAR STRUCTURE. ASSESS DAMAGE AND REPAIR AS REQUIRED	These are extras not covered under the insurance claim (warn out parts)	21/02/2024		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Engine	DOWN ON POWER- FULL GEAR SLOWER IN THE HILLS THAN IT USED TO BE.		21/12/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WINDSCREEN	REPLACE L/H WINDSCREEN WIPER THAT HAS BEEN REMOVED.		21/12/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\COOL LEAKS	HAS COOLANT LEAKING FROM FLEXI HOSE.	JOBS RAISED FOR INVESTIGATION ONLY.	21/12/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	CAB GUARD LIGHTS NOT WORKING.		21/12/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Engine	DOWN ON POWER- ½ A GEAR ON HILLS.		07/12/2023	1025369	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	WORK LIGHTS HAVE A SHORT- FLICKER ON & OFF, CAUSES SCALES TO TURN OFF.		07/12/2023	1025369	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	CAB GUARD LIGHTRS DON'T WORK.		07/12/2023	1025369	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/12/2023	1025369	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	VehService\CS	Service As Per Attached Checklist		07/12/2023	1025369	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				* Washed down area * Removed rear walkway & torque rods * Removed jackshaft from rear diff * Drained diff oil * Removed axles * Unbolted & removed diff * Cleaned down diff housing * Ballast axle * Removed hubs & knocked out bearings * Cleaned down hub * Fit new bearings & assembled hub with new hub seal * Removed old yoke and fit to new diff * Fit new diff with new gasket * Tensioned all bolts to specifications * Refit hubs * Adjusted all bearings as required * Refit all other components * Refilled diff oil & topped up front diff * Adjusted brakes * Aligned & tensioned all to specifications								
1008	Albury - Workshop	DrivLine\DRV LN SER	MOVEMENT IN REAR DIFF INPUT & METAL PRESENT IN OIL	* Test all operations - All ok, fault no longer present	01/12/2023	1020218	Completed	Myrtleford	GTK	XO01AE	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1008	Albury - Workshop	Steering\PWR STEER	diagnose steering fault,after steering box was replaced.		01/12/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	Clutch Has Too Much reeplay		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL STUD	Broken L/H/S Wheel Stud On Steer		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\DRV LIGHT	L/H Fog Light Needs Refitting To Bull Bar		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Comp\Truck Safe	truk safe sticker out of date		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Cooling\RADIATOR	Radiator mounts worn		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER. number plate light N/W		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\TAIL LIGHT	Left rear side marker light N/W		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist (TCTC)		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	VehService\BS	Puirchase Order Number: T082220		14/11/2023	1020218	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		07/11/2023		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		07/11/2023		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRAKE ADJ	PLS ADJUST BRAKES TRUCK AND TRAILERS.		28/10/2023	1014147	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\OIL LEAK	LEAKING HYDRAULIC TANK.		28/10/2023	1014147	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	truk safe sticker out of date		28/10/2023	1014147	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\RADIATOR	Radiator mounts worn		28/10/2023	1014147	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		28/10/2023	1014147	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/10/2023	1014147	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		28/10/2023	1014147	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjust Brakes		21/10/2023	1008428	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				REPLACE HYDRAULIC FILTER CAP O-RING								
1008	Wodonga - Workshop	Hydraulics\HYD LEAKS	Leaking @ Hydraulic Tank number plate light N/W	TOPPED UP HYDRAULIC OIL - 25LTS APPROX	21/10/2023	1008428	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\TAIL LIGHT	Left rear side marker light N/W		18/10/2023	1006609	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	truk safe sticker out of date		18/10/2023	1006609	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\RADIATOR	Radiator mounts worn		18/10/2023	1006609	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		18/10/2023	1006609	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/10/2023	1006609	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		18/10/2023	1006609	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	fit LEDhead lights		12/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				* Removed bottom radiator hose clamp * Fit new clamp * Re-secured pipe * Topped up coolant								
1008	Albury - Workshop	Engine\RADIATOR	WHILST CARRYING OUT SERVICE, FOUND BOTTOM RADIATOR HOSE LEAKING	* Test operations - All ok, fault no longer present * Released brakes * Removed and replaced slack adjuster * Aligned, tensioned & shimmed as required * Greased & adjusted	07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes\SLACK ADJ	WHILST CARRYING OUT SERVICE, FOUND SLACK ADJUSTER WORN	* Test operations - All ok Removed and replaced steer shock bushes as required * Aligned & tensioned all as required	07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Susp\Torque Rod	WHILST CARRYING OUT SERVICE, FOUND STEER SHOCK BUSHES WORN	* Test operations - All ok	07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Engine\BELTS/TENS	WHILST CARRYING OUT SERVICE, FOUND BELTS WORN / FRAYED . * Removed and replaced belts as required * Aligned & tensioned all to specifications * Test all operations - All ok		07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				* Whilst carrying out service, found aftertreatment fault present and globe blown for light * Removed adblue injector * Carried out system flush - found all ok * Test adblue - All ok * Carried out high Nox reset * Found truck failed test * Carried out troubleshooting procedures * Found Nox sensor faulty * Removed walkways for access * Removed and replaced Nox sensor * Carried out high Nox reset again and carried out ECM calibration								
1008	Albury - Workshop	Engine\ADBLUE	AFTERTREATMENT LIGHT ON	* Test all operations - All ok, fault no longer present	07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Susp\SUSPENSION	replace steer shock bush's mext service number plate light N/W		07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\TAIL LIGHT	Left rear side marker light N/W		07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	VehService\BS	Service As Per Attached Checklist	Carried out 40,000klms interval B service and suspension check on 6/10/2023 as per service sheet prov	07/10/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	Clutch needs adjusting please.		05/10/2023	1002988	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	truk safe sticker out of date		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	replace steer shock bush's mext service		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\RADIATOR	Radiator mounts worn		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	PASSENGER DOOR LOCKS ITSELF.		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	EBS MAJOR FAULT- LOCKS UP ON SLIGHTEST CORNERS & BUMPS.		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Wheel	STEERING COLUMN LOCK MALFUNCTIONING.		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\WORK LIGHT	CABGUARD LIGHTS NOT WORKING.		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\ELECT P&W	Passenger door locks by itself.		28/09/2023	1000367	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER

1008	Wodonga - Workshop	DriCabRep\ST Weel	Steering column loack faulty wont lock tilt at lowest point of extension. Trailer ABS Fault - Unplugged		28/09/2023	1000367	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\ABS	Trailer ABS light U/S Probably removed.		28/09/2023	1000367	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/09/2023	1000367	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		28/09/2023	1000367	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2 number plate light N/W		23/09/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\TAIL LIGHT	Left rear side marker light N/W		22/09/2023	999668	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/09/2023	999668	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
				Bled steering box Add 12lts of coolant							
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist Steering Box Refirb ABS Wodonga	Add 3 lts engine oil	22/09/2023	999668	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\PWR STEER	PO# T081161 Approved by Dean Salmon.		21/09/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/09/2023	994357	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		13/09/2023	994357	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		06/09/2023	990529	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\TAIL LIGHT	L/H TAIL LIGHTS ASSEMBLY IS LOOSE.	LH OK. TIGHTENED RH SIDE. REPLACED RH REVERSE LIGHT.	06/09/2023	990529	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	CLUTCH BRAKE NEEDS ADJUSTING, HARD TO GET IN GEAR.		06/09/2023	990529	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		06/09/2023	990529	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	Service As Per Attached Checklist	REPAIRED POWER STEERING LEAK. FILLED RESERVOIR. DIAGNOSED AND REPLACED STEER SHAFT UNIS.	06/09/2023	990529	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		29/08/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		29/08/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	PLEASE ADJUST CLUTCH (NO CLUTCH BRAKE)		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine	TRUCK HAS DRIVELINE VIBRATION.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\OIL LEAK	TRUCK HAS HYDRAULIC LEAK AT TANK.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\INDICATORS	FRONT L/H INDICATOR NOT WORKING.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATING- NEED EMPTY.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\WHEEL ALGN	TRUCK PULLS TO THE LEFT.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATING.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\WHEEL ALGN	TRUCK PULLS TO THE LEFT.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATION.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	STEERING COLUMN LOCK MALFUNCTIONING.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\BRK LIGHT	R/H BRAKE LIGHT NOT WORKING.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	HAS A SQUEAK IN STEERING COLUMN.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	SCALES NEED CALIBRATING.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\WHEEL ALGN	TRUCK PULLS TO THE LEFT.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER. ON ORDER.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BACK PLATE	REPLACE RR BACKING PLATE.		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		26/08/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	Replaced Blown Fuse For Lift Axle Operation		23/08/2023	981689	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	Tightened Bonnet Hinge Bolts		23/08/2023	981689	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\INDICATORS	Trace And Repair Broken Wiring check D/S brake light found broken wire for brake lights repaired wire test ok		23/08/2023	981689	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\BRK LIGHT	travel back home		13/08/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	DRIVER'S SIDE WIPER BLADE STUFFED. NEEDS REPLACING.		09/08/2023	972149	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Tyres\TP08	HAS A FLAT DRIVE TYRE L/H REAR INSIDE.		09/08/2023	972149	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	ADJUSTABLE STEERING COLUMN IS FAULTY.		09/08/2023	972149	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	NO TOWN HORN. PARTS ORDERED.		09/08/2023	972149	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		09/08/2023	972149	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BACK PLATE	REPLACE RR BACKING PLATE. CHECK FUSES KEEPS POPPING. TRAVEL TO JOB TEST AND FOUND PTO FUSE WOULD BLOW WHEN UNLOADING TRAILER LIFT AND FOUND SHORTING OUT ON TRUCK TRACE WIRING AND FOUND SHORT TO EARTH NEXT TO SOLINOID, REPAIR AND TEST FOUND TO BE WORKING FINE.		09/08/2023	972149	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	PACK UP TRAVEL BACK.		09/08/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Body\WIPERS	Replaced RH Wiper Head		01/08/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	WASHER ON R/H WINDSCREEN WIPER BLOCKED. L/H WINDSCREEN WIPER NEEDS TIGHTENING.		01/08/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
				CHECK COMPLAINT OF DEMISTOR NW							
1008	Albury - Workshop	Air Con\HEATER	HEATER MODE NOT WORKING. (DEMISTER NOT WORKING)	CHECK TEMPS AND CHECK OPERATION COULD NOT FAULT	30/07/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect	TCTC supply Actuator TEST FAN POSITION NO TOP VENT . FOUND ACCUATOR MOTOR NOT HOOKED UP TO VENT POSITION SHIFTER RETEST VENTS ALL WORKING OKAY LOCATE SCREEN VENT POS JAMMED. FREE UP AS REQUIRED AND FIT NEW ACCUATOR MOTOR FIT NEW CABIN FILTER. REASSEMBLE DASH PANELS ETC RETEST ALL VENTS OPERATIONS ALL OK		27/07/2023	1076615	Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\ENG FAN	NEEDS 3 NEW VENT COVERS		27/07/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE DRIVE SHOCKS.		25/07/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	FRONT R/H BUMP STOP MISSING/ FRONT DIFF.		25/07/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		25/07/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		25/07/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE DRIVE SHOCKS.		19/07/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	TIGHTEN DRIVE SHOCKS.	ATTEMPTED TO REPLACE RUBBERS. SEIZED.	19/07/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	NO TOWN HORN. PARTS ORDERED.		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BACK PLATE	REPLACE RR BACKING PLATE.		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Unknown	TRUCK PULLS TO THE LEFT.	HTT.	13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\THROTTLE	ACCELERATOR PEDAL STICKING.		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\DOOR LOCK	DRIVER'S DOOR OUTER HANDLE FAULTY.		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	REPLACVE LH WINDSCREEN WIPER HEAD.		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	WASHER ON R/H WINDSCREEN WIPER BLOCKED. L/H WINDSCREEN WIPER NEEDS TIGHTENING.		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	POWER STEERING RESERVOIR LEAKING.	WASHED AND TIGHTENED FITTINGS.	13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		13/07/2023	962346	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	Throttle Sticking	REMOVED PEDAL AND REPAIRED BASE PLATE.	11/07/2023	962344	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\WIPERS	Replaced LH Wiper Head Balance of Tyre Position 1.	REPLACED MISSING NUT.	11/07/2023	962344	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\BALANCE	Beaurepairs PO# T079532 CHECK SPOT LIGHTS N/W TRAVEL TO GREENFREIGHTS YARD test and found driving light not working test fuses and found all ok test relay and diagnose as faulty remove and replace test and found all working fine		11/07/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	pack up and travel back		11/07/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	Perform laser wheel alignment		06/07/2023	959766	Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
				TRAVEL TO JOB TEST AND FOUND NO POWER TO EBS LEAD TEST FUSES AND FOUND OK CHECK FOR POWER OUT OF CAB AND FOUND POWER REMOVE CHASSIE PLATES AND FOUND INLINE PLUG BURNT OUT REMOVE AND REPLACE PLUG AND SOCKECT AS REQUIRED TEST AND FOUND ALL OK DROP AXLE NOW WORKING						
1008	Albury - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON ALL THE TIME.	PACK UP AND TRAVEL BACK	01/07/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/06/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
				- Drain differential oil - Removed/replaced differential oil filter - Removed/cleaned & replaced differential screens - Installed differential lubricant levels to specification							
1008	Albury - Workshop	DrivLine\DIFF REPMN	DRAIN DIFFERENTIAL LUBRICANT, REPLACE FILTER, CLEAN OUT DIFFERENTIAL SCREENS & REPLACE LUBRICANT	- Re torque all fittings & fixtures	28/06/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\WIPERS	L/H WINDSCREEN WIPER LINKAGES NEED TIGHTENING.		28/06/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\WIPERS	R/H TOP WINDSCREEN WASHER BLOCKED.		28/06/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\BRK LIGHT	R/H BRAKE LIGHT NOT WORKING.		28/06/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
				- Tightened loose sway bar bolts							
			Service As Per Attached Checklist	- Power steering hose weep - Monitor							
1008	Albury - Workshop	VehService\BS	CARRY OUT 40,000KMS INTERVAL B SERVICE & SUSPENSION CHECK AS REQUIRED.	- Bonnet blocks worn - Require replace	28/06/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	Slide Locks Not Working - Reconnect Lead To Trailer		24/06/2023	956017	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER

1008	Wodonga - Workshop	Chassis\MUDGUARDS	Tighten drive guard.	Refer Job # 413245	23/06/2023	954952	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MUDGUARDS	L/H MUDGUARDS ARE LOOSE.		23/06/2023	954952	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\Re-Tor	WHEEL RE-TENT STTEL ALLOY WHEEL POS 1-2		17/06/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		16/06/2023	950399	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/06/2023	950399	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist	COMPLETED A SERVICE AND REPLACED CAB FILTER.	16/06/2023	950399	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	WASHER ON R/H WINDSCREEN WIPER BLOCKED. L/H WINDSCREEN WIPER NEEDS TIGHTENING. SPEEDO ALL OVER THE PLACE & SOMETIMES DON'T WORK. FLEET 1008 CHECK TURBO TIMER N/W & SPEEDO JUMPING GREENFREIGHT HAS CHANGED SPEED SEN SENSOR TRAVEL TO GREENFREIGHT YARD greenfreight diagnose turbo timer faulty and would keep truck running bypass turbo timer and could not get new turbo timer. rebook to the weekend to check speedo	GREENFREIGHT CHANGED SPEED SENSOR. travel to greenfreight yard, greenfreight disgnose turbo timer faulty adn would keep truck running. bypass turbo timer and could not get new turbotimer. rebook to the weekend to check speedo, pack up and travel back return back to depot check truck not turning off. speedo not working, batteries wouldent take charge replaced batteries, checked engine harness, found several rubs and pinchs. repair to suit, run new wires from speedo sensor to speedo operation all okay.	16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	pack up and travel back. SPEEDO ALL OVER THE PLACE & SOMETIMES DON'T WORK.	HAGANS.	16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	TRUCK SOMETIMES WON'T TURN OFF.	HAGANS.	16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO NOT WORKING.	HAGANS.	16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	POWER STEERING RESERVOIR LEAKING.		16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.	HAGANS.	16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist		16/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		15/06/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\HOUSEKEEP	NEW R&R BOOK.		15/06/2023	949649	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	STEERING WON'T LOCK.	INSPECTED. FOUND TILT SHOCK IS WEAK. ADDED COMPRESSION SPRING TO ASSIST LEVER TEMPORARI	15/06/2023	949649	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\HOUSEKEEP	Replaced Steer Column Cable		14/06/2023	949043	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MUDGUARDS	MUDGUARDS GOT HOLES IN THEM.		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	WASHER ON R/H WINDSCREEN WIPER BLOCKED. L/H WINDSCREEN WIPER NEEDS TIGHTENING.		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO ALL OVER THE PLACE & SOMETIMES DON'T WORK. fleet 1008 check turbo timer n/w and speedo jumping.		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	TRUCK SOMETIMES WON'T TURN OFF.		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO NOT WORKING.		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	POWER STEERING RESERVOIR LEAKING.		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		09/06/2023	947694	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Workshop\HD	hook up airhoses, hydraulic lines, load trailers then park		03/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRAKE ADJ	truck brakes need adjusting		01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\TAIL LIGHT	L/H/S rear clearance light not working		01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	R/H Low beam not working		01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	POWER STEERING RESERVOIR LEAKING.	unable to complete due to truck dirty	01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO NOT WORKING. DIAGNOSED AS PLUGS AT SPEED SENSORS NEED REPLACING.		01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/06/2023	942985	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	Replaced RH Hi/Low Beam Globe		01/06/2023	941510	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\TRL LIGHTS	HOOKED UP T547/548. REPAIRED LH INDICATOR WIRING AT PLUG.		01/06/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/05/2023	939077	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	POWER STEERING RESERVOIR LEAKING.		28/05/2023	939077	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		28/05/2023	939077	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\HUBCAP	BOTH FRONT WHEEL SEALS WERE LEAKING, ALL BOLTS WERE LOOSE.		28/05/2023	939077	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES NEED ADJUSTING.		28/05/2023	939077	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO NOT WORKING.	SWAPPED SENSOR AND TESTED. WORKING. REPLACED SENSORS. NOT WORKING. REPOSITIONED WIRII	28/05/2023	939077	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist DURING SERVICE FOUND SEVERE FUEL LEAK FROM FUEL PUMP AREA - Inspect and found fuel leaking from fuel pump actuator. - Remove and replace sctuator as required with new sealing washers as required. - Wash and recheck for leaks, all	ADDED 4L ENGINE OIL.	28/05/2023	939077	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Engine\FUEL TANK	ok.- Engine exclusion		20/05/2023	928456	Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	L/H WINDSCREEN WIPER LINKAGES ARE LOOSE.		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Serviced By TCTC		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	LH Windscreen wiper linkages loose.		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\DRV LN SER	Bad clunk in front end when going around corners.		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	FRONT DIFF TEMP GAUGE NOT WORKING.		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\WHEEL SEAL	L/H STEER WHEEL SEAL LEAKING.		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	L/H CLEARANCE LIGHT ON BACK LIGHT BAR NOT WORKING.		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	R/H TOP WINDSCREEN WASHER BLOCKED.		17/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\OIL LEAK	LEAKING HYDRAULIC OIL WHILE DRIVING.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	BAD CLUNK IN FRONT END WHEN CHANGING DIRECTION OR DROPPING INTO POT HOLES.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	TRUCK RIDES ROUGH. NO RUBBERS OR CAB MOUNTS LIKE YOU HAVE STEEL WHEELS.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	AC NOT BLOWING ON WINDSCREEN & NO VENTS & CAN'T TURN FACE VENTS.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ADBLUE	ADBLUE LEAKING AT PUMP.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	LOW COOLANT FAULT CODE WITH COOLANT LEVEL FULL.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	FITTING AT POWER STEER RESERVOIR LEAKING.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AT FIREWALL. OIL LEAK AROUND FUEL PUMP.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\OIL LEAK	FUEL LEAK. REPLACE OUT OF DATE TRUCKSAFE STICKER.		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	On Order		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		11/05/2023	1076615	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		05/05/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		05/05/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		05/05/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		05/05/2023		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\VALVES	Hydraulic Tank Pressurising (Rapid Hydraulics) Purchase Order Number: WW078063	oil blowing out of filter housing of log truck Drove to site. Had truck moved into shed over the pit, removed covers, hooked up gage, checked and set pressure 180 bar removed and replaced breather and O-ring on filter element. Found out that vehicle had Been driven with P.T.O engaged. fault cause by driving with PTO engaged recommend replacing oil and inspecting PTO for damage and wear	02/05/2023		Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\PTO	REPLACED MELTED AIR LINE AND FITTING FOR P.T.O.		28/04/2023	916409	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	LOW COOLANT FAULT CODE WITH COOLANT LEVEL FULL.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	L/H CLEARANCE LIGHT ON LIGHT BAR BROKEN.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	FUEL GAUGE LIGHT NOT WORKING.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT ON BACK LIGHT BAR BROKEN.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\AIR LEAK	HOSE ON CROSS LOCKS LEAKING AIR.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE OCCASIONALLY FLASHING ON.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ALWAYS ON.	HAGANS.	25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	BAD CLUNK IN FRONT END WHEN CHANGING DIRECTION OR DROPPING INTO POT HOLES.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	TRUCK RIDES ROUGH. NO RUBBERS OR CAB MOUNTS LIKE YOU HAVE STEEL WHEELS.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	AC NOT BLOWING ON WINDSCREEN & NO VENTS & CAN'T TURN FACE VENTS.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ADBLUE	ADBLUE LEAKING AT PUMP.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	FITTING AT POWER STEER RESERVOIR LEAKING.		25/04/2023	915804	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER

1008	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AT FIREWALL.		25/04/2023	915804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\OIL LEAK	OIL LEAK AROUND FUEL PUMP. REPLACE OUT OF DATE TRUCKSAFE STICKER.		25/04/2023	915804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	On Order		25/04/2023	915804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/04/2023	915804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	REPLACED MISSING CAB FILTER COVER AND DISLODGED FILTER. REPLACED LR BOOSTER.	25/04/2023	915804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering	STEERING HAS GOT A LOT OF PLAY IN IT.	Checked movement at pitman arm, drag link and bushes.	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	DIFF TEMP GAUGE NOT WORKING.	Replaced gauge + checked connections at both diffs.	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\OIL LEAK	FRONT DIFF OIL HOSE LEAKING.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Cooling\COOL LEAKS	COOLANT DRAIN FITTING LEAKING.	Tightened fitting driver to monitor	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE OCCASIONALLY FLASHING ON.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\AIR BAG	AIRBAGS OUT OF BALANCE. (RHS LOW)		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	BAD CLUNK IN FRONT END WHEN CHANGING DIRECTION OR DROPPING INTO POT HOLES. New Seat is starting to do what old one did.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\SEAT	Locking up not bouncing.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	CAN'T TURN FACE AIR VENTS.	Refer job # 408145	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	NO WINDSCREEN AIR VENTS.	Refer job # 408145	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	A.C. AIR NOT BLOWING ON WINDSCREEN.	Refer job # 408145	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	CTI\CTI Drive	REPLACE LEAKING SPINNER ON THE FRONT RIGHT SIDE.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\HEATER	TURN HEATER TAPS ON.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	TRUCK RIDES ROUGH. NO RUBBERS OR CAB MOUNTS LIKE YOU HAVE STEEL WHEELS.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	CAN'T TURN FACE AIR VENTS.	Refer job # 408145	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	NO WINDSCREEN AIR VENTS.	Refer job # 408145	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	A.C. AIR NOT BLOWING ON WINDSCREEN. AC NOT BLOWING ON WINDSCREEN & NO VENTS & CAN'T TURN FACE VENTS.	Refer job # 408145	18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	ORDER VENTS		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	TRUCK SOMETIMES WON'T TURN OFF.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ADBLUE	ADBLUE LEAKING AT PUMP.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	FITTING AT POWER STEER RESERVOIR LEAKING.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AT FIREWALL. TRAILER ABS LIGHT ALWAYS ON.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	DIAGNOSED POWER FAULT AT PLUG. AUTO ELEC MAY BE REQUIRED.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\OIL LEAK	OIL LEAK AROUND FUEL PUMP. REPLACE OUT OF DATE TRUCKSAFE STICKER.		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	On Order		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist BRAKE RELINE CHECK ALL BRAKES AND RELINE AS REQUIRED - Inspect brakes and found rear drive axle low both sides. - Raise and support axle. - Remove wheels, drums and shoes. - Inspect s-cams and found excessive movement. - Remove hubs and s-cams. Found s-cams and bushes worn. - Replace s-cams and bushes. - Clean and inspect hubs and bearings, all ok. - Refit hubs withnew seals and adjust bearings. - Fit new brake shoes. - Measure drums and found over spec, replace. - Refit wheels and lower axle. Tension wheel nuts and adjust		18/04/2023	911153	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes\BRK RELINE	brakes. -Billable. PS hoses on 1008 drove to site removed and replaced hoses with new ones found two more that had rubbed throw		14/04/2023	865049	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Hydraulics\HOSES	spoke with shawn and got told to replace them aswell		12/04/2023		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	TRUCK RIDES ROUGH. NO RUBBERS OR CAB MOUNTS LIKE YOU HAVE STEEL WHEELS.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	R/H REAR CLEARANCE LIGHT NOT WORKING.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	AC NOT BLOWING ON WINDSCREEN & NO VENTS & CAN'T TURN FACE VENTS.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	TRUCK SOMETIMES WON'T TURN OFF.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ADBLUE	ADBLUE LEAKING AT PUMP.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\OIL LEAK	OIL LEAK AROUND FUEL PUMP. CAN'T TURN FACE AIR VENTS.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	ORDERED. NO WINDSCREEN AIR VENTS.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	ORDERED.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist	CLEANED UP WHILST WAITING FOR TRUCK.	07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	A.C. AIR NOT BLOWING ON WINDSCREEN.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\OIL LEAK	FITTING AT POWER STEER RESERVOIR LEAKING.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AT FIREWALL.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE OCCASIONALLY FLASHING ON.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ALWAYS ON.	DIAGNOSES POWER FAULT AT PLUG.	07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\AIR BAG	AIRBAGS OUT OF BALANCE. (RHS LOW)		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	BAD CLUNK IN FRONT END WHEN CHANGING DIRECTION OR DROPPING INTO POT HOLES. New Seat is starting to do what old one did.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\SEAT	Locking up not bouncing.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	CAN'T TURN FACE AIR VENTS.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	NO WINDSCREEN AIR VENTS.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	A.C. AIR NOT BLOWING ON WINDSCREEN.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	CTI\CTI Drive	REPLACE LEAKING SPINNER ON THE FRONT RIGHT SIDE.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\HEATER	TURN HEATER TAPS ON.		07/04/2023	904804	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP08	runout New Seat is starting to do what old one did.		29/03/2023		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\SEAT	Locking up not bouncing.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				FUEL LEAK RECTIFY FUEL LEAK AT HIGH PRESSURE FUEL PUMP AREA Inspect and found fuel leaking from banjo bolt fitting on high pressure pump Remove intake pipe and compressor hotline for access Remove and replace banjo bolt washers and refit bolt Wash and recheck for leak, all ok							
1008	Wodonga - Workshop	Engine\OIL LEAK	OIL LEAK AROUND FUEL PUMP.	Engine exclusion	25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	CAN'T TURN FACE AIR VENTS.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	NO WINDSCREEN AIR VENTS.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	A.C. AIR NOT BLOWING ON WINDSCREEN.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	CTI\CTI Drive	REPLACE LEAKING SPINNER ON THE FRONT RIGHT SIDE.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\HEATER	TURN HEATER TAPS ON.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				SUSPENSION CUSTOMER REPORTS FRONT END FEELS LIKE ITS ALL OVER THE PLACE AND KNOCKS Inspect all suspension and steering components, no faults Test drive and check operation Found seat suspension to be worn causing seat to bounce and knock Customer request to replace seat with customer supplied part							
1008	Wodonga - Workshop	Susp\SUSPENSION	TRUCK RIDES ROUGH. NO RUBBERS OR CAB MOUNTS LIKE YOU HAVE STEEL WHEELS.	Remove and replace seat. Test drive, all ok	25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	CAN'T TURN FACE AIR VENTS.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	NO WINDSCREEN AIR VENTS.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	A.C. AIR NOT BLOWING ON WINDSCREEN.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				LIGHTS REPAIR VARIOUS DAMAGED AND INOPERATIVE LIGHTS Replace both rear lightbar clearance lights and brackets as were damaged							
1008	Wodonga - Workshop	Elect\ELECT P&W	R/H REAR CLEARANCE LIGHT NOT WORKING.	Remove and replace n/w number plate light	25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	AC NOT BLOWING ON WINDSCREEN & NO VENTS & CAN'T TURN FACE VENTS.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	TRUCK SOMETIMES WON'T TURN OFF.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ADBLUE	ADBLUE LEAKING AT PUMP.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER

1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				BRAKE CHECK REPLACE BROKEN LHR BACKING PLATE								
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Remove and replace backing plate	25/03/2023	895742	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Chassis\DAMAGE	TOW PIN BENT.	CUT OUT AND REPLACED PIN.	23/03/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	L/H LOW BEAM LIGHT CRACKED.		18/03/2023	891372	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	REPLACED LH LOW BEAM LENSE.		18/03/2023	891372	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con	INSPECTED VENTS. TCTC TO REPAIR.		18/03/2023	891372	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\PANELS	REMOVED AND REPAIRED BROKEN CROME PANEL BRACKET.		18/03/2023	891372	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Comp\Truck Safe	REPLACE OUT OF DATE TRUCKSAFE STICKER.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	CTI\CTI Drive	REPLACE LEAKING SPINNER ON THE FRONT RIGHT SIDE.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	TRUCK RIDES ROUGH. NO RUBBERS OR CAB MOUNTS LIKE YOU HAVE STEEL WHEELS.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	CAN'T TURN FACE AIR VENTS.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	NO WINDSCREEN AIR VENTS.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES NEED ADJUSTING.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	A.C. AIR NOT BLOWING ON WINDSCREEN.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	R/H REAR CLEARANCE LIGHT NOT WORKING.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\AIR CON	AC NOT BLOWING ON WINDSCREEN & NO VENTS & CAN'T TURN FACE VENTS.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	TRUCK SOMETIMES WON'T TURN OFF.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ADBLUE	ADBLUE LEAKING AT PUMP.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	ENGINE CHECK & STOP LIGHT COMING ON. TEMPORARILY REPAIRED. REQUIRES NEW PLUG FOR COOLANT SENSOR.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Air Con\HEATER	TURN HEATER TAPS ON.		18/03/2023	891371	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\WHEEL STUD	REPLACED ALL STEER WHEEL STUDS ON L/H STEER HUB.		16/03/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	ENGINE CHECK & STOP LIGHT COMING ON.		16/03/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE & STOP ENGINE LIGHTS ON MOST OF THE WAY HOME AND ALSO DERATED.		16/03/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE AND STOP ENGINE LIGHTS COMING ON AND OFF.	DIAGNOSED AND REPAIRED WIRING.	16/03/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		16/03/2023		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CLEARED CODES. REPARED WIRING SHORT. REPLACED RF SPINNER.		13/03/2023	888034	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	Checked Codes: Water In Fuel		11/03/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\SEAT	SEAT IS STILL STUFFED.		09/03/2023	885307	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\SEAT	SEAT NEEDS REPLACING.		09/03/2023	885307	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\HOUSEKEEP	NEED A NEW BROOM PLEASE.		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FUEL TANK	FUEL PUMP BANJO BOLT LEAKING.		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ELECT P&W	Engine won't turn off (turbo timer?)		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\AIR CON	AIR VENTS ONLY BLOW ON FACE.		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\SEAT	SEAT IS STUFFED. DOESN'T BOUNCE.		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WIPERS	R/H WIPER U/S.		01/03/2023	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				Hydraulics issue on log trailer Drove to site Turned PTO on to see if it was engaging (OK) Checked oil level (OK) Bypassed valve, pump directly to tank (OK) Caped off valve to dead head system, to check pressure (only reading 18.6 bar) Hooked flow meter in to test pressure and flow between pump and valve (PTO pump good) Removed relief valve cartridge to inspect (OK) Tried to over ride the valve felt like spool was not shifting, seized							
			P.T.O. NOT WORKING. (Rapid Hydraulics)									
1008	Wodonga - Workshop	DrivLine\PTO	Purchase Order Number: WW076924. P.T.O. NOT WORKING.	Swapped out with new one and tested - all good	24/02/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Workshop\MOVE ASSET	DROPPED OFF TCTC.		21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FUEL TANK	FUEL PUMP BANJO BOLT LEAKING.		21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	*CHECK ENGINE/ STOP ENGINE LIGHT ON- DERATING.	REPLACED COOLANT LEVEL SENSOR.	21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\TAIL SHAFT	DRIVELINE VIBRATION ON COAST- CHECK TAIL & JACK SHAFT UNI'S.		21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	ENGINE WILL NOT TURN OFF- (TURBO TIMER SWITCH)?	COULDN'T FAULT.	21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\HOUSEKEEP	NEED A NEW BROOM PLEASE.		21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	REPAIRED RF INDIACATOR.	21/02/2023	875232	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\Re-Tor	Re-Torque		17/02/2023		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	CHECK SHOCKS. DOESN'T TURN IN CORNERS WHEN GOING RIGHT- FEELS LIKE IT'S DRIVING ON EDGE OF LH STEERING TYRE.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\START MOTR	GETTING A BIT HARD TO START.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering	TOO MUCH PLAY IN STEERING. WONDERS ON THE ROAD.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\HOUSEKEEP	NEED A NEW BROOM PLEASE.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\WHEEL BRGS	CHECK STEER WHEEL BEARINGS.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\TIE ROD	BOTH TIE ROD ENDS NEED REPLACING.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\ABS	ESC AND ABS LIGHTS ON.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	REPLACE BONNET SPRING.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WINDSCREEN	RH WINDSCREEN NEEDS REPLACING.		16/02/2023	874117	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				Connect laptop and take ECM download Remove vent tube from radiator and remove fan belt Start engine and engine was pushing water out of vent tube with water pump disconnected Put cooling system pressure tester on vehicle Start engine and watch cooling system pressure Pressure climbed to 90kpa from engine running for 20 seconds with water pump disconnected Remove cooling system pressure tester Disconnect and plug off water feed/return to air compressor Start engine and engine was pushing water out of vent tube with water pump disconnected and air compressor bypassed Steam clean engine Remove radiator, intercooler and A/C condenser Remove rocker cover Remove valve rockers and wiring for Jake brakes and mi ectors Remove front cover Remove idler gears and valve camshaft gear Found idler gear bearings had excessive wear Remove valve camshaft Remove cylinder head Inspect cylinder head and cylinder head gasket Found head gasket hadn't failed Found 0.004" fretting on cylinder 6 fire ring on cylinder head							
			R&R Cyl Head & Upper Gask Kit									
1008	Wodonga - Workshop	Engine\ENG REBLD	Pressurizing cooling system.	Strip cylinder head	20/01/2023	874043	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Engine	R&R Cylinder Head & Upper gasket Kit		20/01/2023	874043	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Steering	TOO MUCH PLAY IN STEERING. WONDERS ON THE ROAD.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	CHECK SHOCKS. DOESN'T TURN IN CORNERS WHEN GOING RIGHT- FEELS LIKE IT'S DRIVING ON EDGE OF LH SEERING TYRE.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\START MOTR	GETTING A BIT HARD TO START.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\HOUSEKEEP	NEED A NEW BROOM PLEASE.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\WHEEL BRGS	CHECK STEER WHEEL BEARINGS.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\TIE ROD	BOTH TIE ROD ENDS NEED REPLACING.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\ABS	ESC AND ABS LIGHTS ON.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	REPLACE BONNET SPRING.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WINDSCREEN	RH WINDSCREEN NEEDS REPLACING.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\WHEEL BRGS	CHECK STEER WHEEL BEARINGS.		14/01/2023		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS FAULT.	CHECKED FUSES. DIAGNOSED AND REPAIRED CABLE. REPLACED PLUG.	10/01/2023	865552	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	BRAKE PEDAL ACTIVATING CLEARANCE LIGHTS- BRAKE LIGHTS STUCK ON WHEN LIGHTS ON.		10/01/2023	865552	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\HOUSEKEEP	NEED A NEW BROOM PLEASE.		10/01/2023	865552	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	SWITCH FOR FOLDING AND UNFOLDING NOT WORKING		10/01/2023	865552	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\SCALES	callibrate scales	DRIVER TO COMPLETE.	10/01/2023	865552	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	RH HEADLIGHT OUT.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	RH HEADLIGHT OUT.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	FRONT AXLE OIL TEMP NOT WORKING.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	REPLACE CRACKED BONNET RESTS.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\CONSUMABLE	REPLACE BROKEN RR SHACKLE PIN GREASE NIPPLE.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER

1008	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	REPLACE BONNET BUSHES.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE DRIVE SHOCK BUSHES.		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				Checked the tablet, found 0 satelite on MT Data, plugged the new antenna in and got 8 satellites, removed the roof console and passenger side panel and removed the old antenna, mounted the new antenna and ran wires down to IAP unit, plugged in and tied in cables, put panels back								
			*Not tracking									
1008	Albury - Workshop	DrCabElect\IAP	*Receiver on roof is cracked.	on and rang MT Data to get a health check, truck is now tracking.	23/12/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\OIL LEAK	FRONT DIFF PINION SEAL LEAKING.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\MOUNTS	ENGINE MOUNTS SQUASHED.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\JAKE BRAKE	CHECK ENGINE BRAKE.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SWAYBAR	REPLACE SWAYBAR BUSHES AND REQUIRED TORQUE ROD BUSHES.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SPRNG PACK	FRONT SHACKLE PINS LOOSE.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\HOUSEKEEP	MISSING BONNET SPRINGS.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MUDGUARDS	MUDGUARD OUTRIGGERS LOOSE/ BROKEN BOLTS		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SPRNG PACK	LH SPRING KEEPER LOOSE/ BROKEN.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\GEARBOX	GEARBOX OUTPUT SHAFT MOVEMENT.		22/12/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\MOUNTS	ENGINE MOUNTS SQUASHED.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\JAKE BRAKE	CHECK ENGINE BRAKE.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SWAYBAR	REPLACE SWAYBAR BUSHES AND REQUIRED TORQUE ROD BUSHES.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SPRNG PACK	FRONT SHACKLE PINS LOOSE.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\HOUSEKEEP	MISSING BONNET SPRINGS.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MUDGUARDS	MUDGUARD OUTRIGGERS LOOSE/ BROKEN BOLTS		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SPRNG PACK	LH SPRING KEEPER LOOSE/ BROKEN.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\GEARBOX	GEARBOX OUTPUT SHAFT MOVEMENT.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\OIL LEAK	FRONT DIFF PINION SEAL LEAKING.		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\B1 Svc	Service As Per Attached Checklist		14/12/2022	861306	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\GOV VALVE	AIR PRESSURE TOO HIGH.	DIAGNOSED AND REPLACED GOVERNOR VALVE.	25/11/2022	835674	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\CLUTCH	CLUTCH ADJUSTMENT.	ADJUSTED.	18/11/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		18/11/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		18/11/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP3+4	fit 2, 4 bolt ons		18/11/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Body\WINDSCREEN	Replace LH & RH windscreen		11/11/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		11/11/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LR.		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\CONSUMABLE	REPLACE BROKEN RR SHACKLE PIN GREASE NIPPLE.		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	REPLACE BONNET BUSHES.		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	REPLACE CRACKED BONNET RESTS.		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE DRIVE SHOCK BUSHES.		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	FRONT AXLE OIL TEMP NOT WORKING.		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
			SWITCH FOR FOLDING AND UNFOLDING NOT WORKING									
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	REPLACED SWITCH. STILL HAS ISSUE.		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist		04/11/2022	841445	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\CLUTCH	CLUTCH ADJUSTMENT.	ADJUSTED CLUTCH.	26/10/2022	836644	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\GOV VALVE	AIR PRESSURE TOO HIGH.	DIAGNOSED AND REPLACED GOVERNOR VALVE.	25/10/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Rosewood - Workshop	Elect\BATTERY	HARD TO START.	REPLACED BROKEN TERMINAL.	20/10/2022	833623	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\HEAD LIGHT	REPLACED RH HIGH BEAM GLOBE.		17/10/2022	1076615	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\TIE ROD	BOTH TIE ROD ENDS NEED REPLACING.		14/10/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
			LH HEADLIGHT OUT									
1008	Wodonga - Workshop	Elect\HEAD LIGHT	RH HEADLIGHT OUT.		14/10/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				REPLACED RH HEADLIGHT GLOBE.								
1008	Wodonga - Workshop	Elect\HEAD LIGHT	RH HEADLIGHT OUT.	CHECKED FRONT END.	14/10/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	A SERVICE AS PER TCTC CHECKLIST.	REPAIRED 3 DASH LIGHTS AND WIRING TO LH TAIL LIGHT.	08/10/2022	829824	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\ABS	ESC AND ABS LIGHTS ON.		08/10/2022	829824	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\MOUNTS	REPLACE BONNET SPRING.		08/10/2022	829824	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\WINDSCREEN	RH WINDSCREEN NEEDS REPLACING.		08/10/2022	829824	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
			BRAKE % 60 90									
			90 30									
1008	Wodonga - Workshop	Brakes	10 30		08/10/2022	829824	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Body\DAMAGE	TCTC supply parts for damage repairs caused by driver		19/09/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\RADIO	UHF NOT TRANSMITTING.	REPLACED HAND PIECE.	15/09/2022	820574	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes\SLACK ADJ	LR ADJUSTER OFF CAM.	DISASSEMBLED LR BRAKES. REFIT S-CAM. ASSEMBLED.	13/09/2022	866162	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Wodonga - Workshop	Steering	SLOP IN STEERING BOX- TRUCK WONDERS ALL OVER THE ROAD.		17/08/2022	807405	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DriCabRep\ST Weel	NO TILT ADJUSTMENT IN STEERING WHEEL.	INSPECTED. FOUND CABLE NOT ATTACHED. ATTACHED CABLE. WON'T RETURN TO LOCK. ADJUSTED CA	17/08/2022	807405	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	ENGINE BRAKE REVERTS TO STAGE 1 WHEN CHECK ENGINE IS ON.		17/08/2022	807405	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMES ON RANDOMLY.		17/08/2022	807405	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering	LOT OF SLACK IN STEERING. HARD TO KEEP IN OWN LANE. (STEERING WHEEL LOCK FOR ADJUSTING POSITION WILL NOT UNLOCK.)	INSPECTED STEERING. REPLACED PITMAN ARM BOLT. TEST DROVE.OK.	17/08/2022	807405	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMES ON & OFF FREQUENTLY. JAKE BRAKES 3 CYL WHEN ON, 6 CYL WHEN OFF.	FAULT 2182. ENGINE BRAKE ACTUATOR DRIVER 1 CIRCUIT. CHECKED ALL WIRING AND SOLONOIDS. IN !	17/08/2022	807405	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
			chain guide under 2nd bolster broken									
1008	Wodonga - Workshop	Body\CHN/RLR/MN	use loader to slide back	INCORRECT ASSET.	17/08/2022	807405	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMES ON. WHEN IT'S ON ENGINE BRAKE ONLY WORKS ON LOW.	CODE FOR 1ST JAKE SOLONOID. FOLLOWED TROUBLE SHOOTING DIRECTIONS. REPLACED BOTH SOLON	12/08/2022	804353	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ELECT P&W	check engine codes		12/08/2022	804353	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ELECT P&W	check engine codes	code 2182 short in jake brake	09/08/2022	802579	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	SWITCH FOR FOLDING AND UNFOLDING NOT WORKING	REPLACED SWITCH. STILL HAS ISSUE.	06/08/2022	501075	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\SEAT	TCTC supply		05/08/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Workshop\MOVE ASSET	UNHOOKED TRAILERS. DROPPED OFF TCTC. NOTIFIED TCTC OF FAULTS.		30/07/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/07/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\TAIL SHAFT	GEARBOX OUTPUT YOKE LOOSE. SPEEDO ERRATIC.		29/07/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\MOUNTS	ENGINE MOUNTS NEED REPLACING.		29/07/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SUSPENSION	SPRING KEEPERS BENT AND BREAKING FREE OF RIVETS.		29/07/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist		29/07/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\CLEANSKIN	no pos given		26/07/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\FAULT CODE	ENGINE BRAKE REVERTS TO STAGE 1 WHEN CHECK ENGINE IS ON.		26/07/2022	772677	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMES ON RANDOMLY.		26/07/2022	772677	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				Engine brake poor & noisey engine. Rocker shaft detent holes elongated. Cylinder #1 detent spring to have broken & caused the master piston to seize. Remaining 5 engine brake rocker levers to have severe fretting in the spool valve top hat seating surface. Ril pump housing to be scored & pumping gears to be pitted Connect laptop and download ECM image. Inspect vehicle for an engine knock and poor engine bakes. Test drive vehicle and find one cylinder to not be activating on engine brakes. Find engine to have a severe gear train related knock. Remove rocker cover and inspect engine brakes. Find rocker shaft detent holes elongated. Find Cylinder #1 detent spring to have broken and caused the master piston to seize. Find remaining 5 engine brake rocker levers to have severe fretting in the spool valve top hat seating surface. Replace both rocker shafts and all engine brake rocker levers. Remove and inspect vibration damper. Find Vibration damper swollen and to measure 0.0013 Maximum thickness is 0.0010 Fit new vibration damper. Inspect camshaft timing. Find Camshaft idler gear to have moved due to excessive vibration. Retime engine. Adjust all overheads. Test drive vehicle to verify repair. Find engine Knock to be better but still present.							
1008	Albury - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT COMES ON & OFF FREQUENTLY. JAKE BRAKES 3 CYL WHEN ON, 6 CYL WHEN OFF.	Remove oil filter and cut open for inspection.	26/07/2022	772677	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	supply and fit 2tyres		21/07/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\TRL LIGHTS	CHECKED TRAILER LIGHT PLUG AND SUPPLY. REPAIRED WIRING AND REPLACED TRAILER PLUG. HAD 2 VOLT DROP.		14/07/2022	793345	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
			Tyre Fitting									
1008	Rosewood - Workshop	Tyres\TP1+2	Beaurepairs PO# R072927		14/07/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\THROTTLE	CALLED OUT TO VEHICLE, NO THROTTLE RESPONSE.	TEST DROVE VEHICLE. COULDN'T REPLICATE.	29/06/2022		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER

			REPAIRS Check and service A/C system Conect Gauges and found no gas in system Visual check for leaks, found none. Charge sysytem with nitrogen and leak test Located damaged hose from compressor to Condensor. Remove hose and make new hose and refit Vac down system and check for leaks - All Ok Charge with oil and vac down for 20 min Charge system with 134a gas Check system operation when running. Tie up all hoses and wrap them where required and re-route wiring loom as was rubbing on the hoses									
1008	Albury - Workshop	Air Con\AIR CON	Final check - All OK		28/06/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		08/06/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\INST/GAUGE	Replace dimmer switch		24/05/2022	768159	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	supply and fit 2tyres		14/04/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\OIL LEAK	Re Seal Oil Pan		12/04/2022	763159	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Body			28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body			28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body			28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	ENGINE WARNING LIGHT ON. STOP ENGINE LIGHT ON. INSPECTED AND RECORDED BY GORDO.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\INDICATORS	No Blinkers		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\ELECT P&W	no PTO rev up engine switch		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\WORK LIGHT	Worklights keep blowing fuses.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	Dim/Bright switch for dash lights do not work.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\HEATER REP	Demister does not work.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\TAIL SHAFT	VIBRATION IN DRIVE LINE, DIFF YOKE ON FRONT DIFF INPUT POSSIBLY LOOSE.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO JUMPS AROUND.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\MOUNTS	REAR ENGINE MOUNTS WORN.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Susp\SPRNG PACK	left front spring twisted		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	replace boost gauge light bulb (blown)		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	diff gauge inaccurate		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\OIL LEAK	some engine oil leaks and lots of blow by		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\COOL LEAKS	heater tank sight glass weaping coolant, was tighten need new		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\OIL LEAK	some oil leaks, various sway bar bushes need replacement		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\SUSPENSION	RHF torque rod, rear bush need replacing		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\AIR LEAK	air dryer gasket leaking		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\PANELS	battery cover step loose		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	PTO idle up needs wiring up		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\KING PIN	Slight knock in King pin, Monitor.		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist		28/03/2022	1075785	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\TAIL SHAFT	GEARBOX OUTPUT YOKE LOOSE, SPEEDO ERRATIC.		08/03/2022	750795	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\MOUNTS	ENGINE MOUNTS NEED REPLACING.		08/03/2022	750795	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Susp\SUSPENSION	SPRING KEEPERS BENT AND BREAKING FREE OF RIVETS.		08/03/2022	750795	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	TCTC A SERVICE	REPLACED NO. PLATE LIGHT. REPLACED FAN BELT AND TENSIONER. TIGHTENED LOOSE STEER SHOCK M	08/03/2022	750795	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		04/03/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		04/03/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	supply and fit 6 tyres		04/03/2022		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\TAIL SHAFT	VIBRATION IN DRIVE LINE, DIFF YOKE ON FRONT DIFF INPUT POSSIBLY LOOSE.		23/02/2022	741187	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	SPEEDO JUMPS AROUND.		23/02/2022	741187	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	TCTC A SERVICE.	TOPPED UP HYDRAULIC OIL AND ADBLUE. TOPPED UP 5L ENGINE OIL.	23/02/2022	741187	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\MOUNTS	REAR ENGINE MOUNTS WORN. A SERVICE. CHECKED RIDE HEIGHT, GUAGE IMBALANCE AND FLUCTUATIONS. REPLACED FAULTY HCV'S. TIGHTENED LOOSE TURBO OUTLET CLAMP. REPLACED P-CLAMP ON		09/02/2022	731155	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	DRAW DOWN HOSE.		09/02/2022	731155	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT ON. CHECKED BASICS. CHECKED WIRING HARNESS VISUALLY. COULDN'T IDENTIFY FAULT. ORGANISED TCTC TO REPAIR.		01/02/2022	726168	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Engine\BREAKDOWN	CALLED OUT TO SHELLEY. DIAGNOSED AND ORGANISED BLOWN TURBO REPLACEMENT. DROPPED DRIVER TO GF WODONGA DEPOT TO PICK UP TRUCK. RETURNI	* Customer contacted dealership to report breakdown * Customer advised technician of turbo failure * Technician travelled to dealership to stock service vehicle with additional parts * Breakdown technician travelled to breakdown location, Shelley/Walwa Rd, Shelley, Vic * Removed all hoses, pipes & components * Removed CAC & components * Removed exhaust & turbo mounting fixtures * Removed turbo complete * Oil contaminated catalyst * Clean all components - wiped catalyst as best as possible * Installed replacement turbo, gaskets, seals & components * Installed hoses, piping, fittings & fixtures * Installed air intake, CAC intake, exhaust components * Installed remaining shrouds, stacks & components * Tension all fittings & fixtures to specification * Road test but blowing excessive smoke caused by contaminated catalyst * Contacted GF Gordo & advised to drive back to Rosewood bobtail to hopefully burn out excessive catalyst oil by then	27/01/2022	724558	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\TURBO	BREAKDOWN AFTER HOURS CALL OUT SUBLET: 7273152 $110.70 25/01/2022 CHECK ENGINE LIGHT ON AND STOP ENGINE LIGHT ON. Inspected and replaced failed coolant sensor. Tested, light now off, all ok. 25/01/2022 afternoon VEHICLE BLOWING SMOKE AND ENGINE LIGHT ON @ SHELLY.	* Technician returned to dealership	27/01/2022	724558	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	Diagnosed blown turbo and organised TCTC to repair.		26/01/2022	724376	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT ON -DERATING.	DIAGNOSED COOLANT LEVEL SENSOR FAULT. REPLACED SENSOR. CHECKED SYSTEM FOR PRESSURIZIN(	26/01/2022	724376	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Hydraulics\HOSES	Hoses		15/12/2021	1075728	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP1+2	supply and fit 2tyres		10/12/2021		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\BATTERY	TCTC supply		07/12/2021	1075728	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		26/11/2021	694449	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP7+8	supply and fit 4 tyres		26/11/2021	694449	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	A Service		23/11/2021	691102	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INDICATORS	repaired RH rear indicator		23/11/2021	691102	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DriCabRep\WIPERS	replaced wiper blades		23/11/2021	691102	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	A Service		16/11/2021	685236	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		16/11/2021	685236	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
				* Turned on dash lights & the fuse blew straight away * Inspected all lights & found rear parker lights not working oce the fuse was reset * Disconnected main harness for rear lights & lights didn't turn off * Reconnected & disconnected R/H tail lights & then fuse blew again * Disconnected L/H tail lights & fuse blew as well * Found plug for L/H tail lights was very hot * Stripped back harness & found multiple wires were melted for tail lights * Replaced tail light & replaced melted wiring * Secured wiring & harness * Tested operation of all lights/all ok								
			replace engine brake and trailer abs light globes									
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	CUSTOMER REPORTS DASH LIGHTS HAVE ALL GONE OUT, DIAGNOSE AND REPAIR AS REQUIRED - 15/11/21	* Repair complete	16/11/2021	685236	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\ELECT P&W	replace front diff sender unit		16/11/2021	685236	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Steering\HOSES	adjust mounting of steer brake hoses		16/11/2021	685236	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		02/11/2021	674796	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Body\ABS	re-affix ABS steer cable on left wheel A Service		02/11/2021	674796	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7269064 A Service		02/11/2021	674796	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7268988		27/10/2021	670372	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job replace dash/pack fuse with circuit breaker and check operation		27/10/2021	670372	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\ELECT P&W	TCTC PO # 7268776		22/10/2021	667463	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Susp\SPRNG PACK	left front spring twisted		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER

			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7268775		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	replace boost gauge light bulb (blown)		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	diff gauge inaccurate		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Cooling\COOL LEAKS	tighten dripping coolant hoses x2		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Body\LIGHTS	repair RH mirror light (replace)		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\CONSUMABLE	added 3 liters oil to engine and 5 liters all cool coolant		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		20/10/2021	664665	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	assist TCTC repair after treat light		15/10/2021	660442	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7268280		13/10/2021	660488	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		13/10/2021	660488	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Elect\HEAD LIGHT	Replace broken headlight		13/10/2021	660488	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\MOUNTS	mounting bracket around DPF broken		06/10/2021	655305	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			found broken muffler bracket at Service									
			ordered part and picked up at TCTC and replaced									
1008	Rosewood - Workshop	Engine\EXHAUST	TCTC PO # 7268033		06/10/2021	655305	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Body\MIRRORS	RHs mirror light		06/10/2021	655610	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	axle oil frt RR guage not working		06/10/2021	655610	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	no light turbo boost gauge		06/10/2021	655610	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Elect\HEAD LIGHT	RHS headlight broken		06/10/2021	655610	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Body\ELECT P&W	demister not working		06/10/2021	655610	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	speedo not accurate at 100km p/h		06/10/2021	655610	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7268030		02/10/2021	655304	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		02/10/2021	655304	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Hydraulics\DAMAGE	repair wiring on PTO idle up		02/10/2021	655304	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\AIR LEAK	repair air leak in PTO air pipe		02/10/2021	655304	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		29/09/2021		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		29/09/2021		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\TP1+2	supply and fit 6 tyres		29/09/2021		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7267407		25/09/2021	650014	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		25/09/2021	650014	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\OIL LEAK	some engine oil leaks and lots of blow by		25/09/2021	650014	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\COOL LEAKS	tighten several heater and coolant hoses		25/09/2021	650014	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		18/09/2021	644173	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7266942		18/09/2021	644173	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
				email from Paccar:								
				I have spoken to the fleet team – the invoice was charged to the customer as the work carried out was								
				to rectify damage caused to the vehicle.								
				The exhaust had been hit and pushed against the sump which caused the rubbing and wear on the								
1008	Albury - Workshop	Engine\EXHAUST	Exhaust Flange Twisted	sump.	15/09/2021	629814	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\DAMAGE	Tow vehicle from Rosewood to Cummins - Dropped Liner		10/09/2021	633760	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\CONSUMABLE	top up coolant		09/09/2021	636483	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
				call out to Jingellic, found alternator siezed and belt melted and severed								
				could not get old pulley off alternator, came back to Rosewood to get a pulley and fit to new alternator								
			replace alternator and belt	return to vehicle and fit alternator and test, all good 13.9 volt								
1008	Rosewood - Workshop	Elect\ALT	TCTC PO # 7266554. replace alternator and belt	return to home	09/09/2021	636483	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7266551		08/09/2021	635222	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		08/09/2021	635222	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\DAMAGE	check over post engine rebuild		08/09/2021	635222	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Cooling\COOL LEAKS	diagnose engine coolant leak/check engine light on. Found to have been pressurising. Hydraulic locked		03/09/2021	633760	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Hydraulics\OIL LEAK	repair hydraulic leak under the hydraulic tanks		03/09/2021	633760	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service Due at 625000									
1008	Rosewood - Workshop	VehService\AS	demister not working		03/09/2021	633760	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		31/08/2021	629814	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			exhaust flange clamp had twisted and worn partially through sump. I cut off clamp and replaced gasket and clamp									
1008	Rosewood - Workshop	Engine\EXHAUST	put a layer of silicon over wear ma was not leaking TCTC PO # 7265906		31/08/2021	629814	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\HOUSEKEEP	topped up oils, took 5 liters		31/08/2021	629814	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7265905		31/08/2021	629814	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service Due at 625000									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7266725		25/08/2021	624987	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Elect\DAMAGE	demister not working		25/08/2021	624987	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7265329		24/08/2021	623986	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		24/08/2021	623986	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\COOL LEAKS	header tank sight glass weaping coolant, was tighten need new		24/08/2021	623986	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\EXHAUST	assist TCTC replace exhaust flex and after treat		20/08/2021	621779	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Body\HOUSEKEEP	replace jack pivot bolt		19/08/2021		Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			tighten mudguard mounts									
1008	Rosewood - Workshop	Body\MUDGUARDS	TCTC PO # 7265183		19/08/2021		Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7265179		17/08/2021	618417	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		17/08/2021	618417	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\OIL LEAK	some oil leaks, various		17/08/2021	618417	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	screw mount door trims		17/08/2021	618417	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7264518		07/08/2021	611138	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		07/08/2021	611138	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		15/07/2021	595827	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			A Service									
			#added 5 liters oil to engine TCTC PO # 7263646									
			-replaced pto switch									
			-replace cruise light globe and 2 dash guage illum bulbs									
			-repair RHS mirror light									
			#a/c evaporator blocked and made selector actuator u/s									
1008	Rosewood - Workshop	VehService\AS	#radiator cross brace broken		15/07/2021	595827	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Tyres\TP9+10	replace 2 tyres		07/07/2021		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Rosewood - Workshop	Tyres\TP7+8	replace 2 tyres		07/07/2021		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\RADIO	fit driver facing camera		01/07/2021	1075728	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
			A Service									
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7262381		25/06/2021	589604	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
			sway bar bushes need replacement									
1008	Rosewood - Workshop	DrivLine\SUSPENSION	RHF torque rod, rear bush need replacing		25/06/2021	589604	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		25/06/2021	589604	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\TP1+2	Supply and fit 2 tyres		18/06/2021	587961	Completed	Myrtleford	GTK	XO01AE	Tumut Plant Hire - 4	P/MOVER
			chain guide under 2nd bolster broken									
1008	Tumut - Workshop	Body\CHN/RLR/MN	use loader to slide back		12/06/2021	586496	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\ELECT P&W	no PTO rev up engine switch		12/06/2021	586496	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\ELECT P&W	PTO switch playing up		12/06/2021	586496	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService	Service		10/06/2021	585931	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Brakes\BRAKE ADJ	front brakes pulling left		10/06/2021	585931	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Elect\WORK LIGHT	no work lights		10/06/2021	585931	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Body\PANELS	battery cover step loose		10/06/2021	585931	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\INST/GAUGE	PTO idle up needs wiring up		10/06/2021	585931	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Body\HOUSEKEEP	check over vehicle as it has just been returned to us		10/06/2021	585931	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\ELECT P&W	no indicators (unable to get into fusebox)		10/06/2021	585931	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\SLACK ADJ	LHM slack adjuster missing grease nipple		08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes\AIR LEAK	air dryer gasket leaking		08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\INST/GAUGE	Dim/Bright switch for dash lights do not work.	not complete/[pending	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\LIGHTS	Right hand headlights.	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\LIGHTS	No work lights.	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\HEATER REP	Demister does not work.	driver to monitor	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\WORK LIGHT	rear work lights not working properly right through - usually wriggle switch and may stay on	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER

1008	Wodonga - Workshop	DriCabRep\SEAT	seat has a bad squeals	driver to monitor - can't fault	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\OIL LEAK	rear seal front diff leaking	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\SUSPENSION	left and right rear shock rubbers worn	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Body\LIGHTS	Rear bar spot lights U/S	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\WHEEL SEAL	RHF Hub Seal blown.	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\ELECT P&W	DRL's need replacing (no lights 1 half lights	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\SUSPENSION	some drive shocks worn rubbers	not required	08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Workshop\MOVE ASSET	unfold trailers and move truck		08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\OIL LEAK	added 3 liters of oil		08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		08/06/2021	585414	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				Inspected all fuses found to be all good.								
				Inspected wiring no damge between turntable and connectors.								
1008	Wodonga - Workshop	Elect\WORK LIGHT	Inspected Loading light fault.	Looked for wiring diagram amongst equipment from Albury.	02/06/2021	581674	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\INDICATORS	blinkers not working		01/06/2021	581673	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\IDLER PULL	pulley beside ac seized		01/06/2021	581673	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Tumut - Workshop	Engine\BELTS/TENS	TCTC supply parts		01/06/2021		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Wodonga - Workshop	Body\LIGHTS	Rear bar spot lights U/S		29/05/2021	580431	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\WHEEL SEAL	RHF Hub Seal blown.		29/05/2021	580431	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\KING PIN	Slight knock in RH King pin, Monitor.		29/05/2021	580431	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist Jack up front end check steer bearings and kingpin movement.		29/05/2021	580431	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Change Cab air filter.		29/05/2021	580431	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		27/05/2021		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		27/05/2021		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		21/05/2021	574805	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		21/05/2021	574805	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\TP1+2	Supply and fit 6 tyres		21/05/2021	574805	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Wodonga - Workshop	Workshop\MOVE ASSET	Road test and hook up trailers.		18/05/2021	569220	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	DrivLine\WHL HUB	Replace wheel speed sensor on L/H front wheel. *MDVR disconnected *KW #1008 Travel to Greenfreight and return. Remove 412 tracking unit and fit 419. Found unit would not power up or turn on, suspect faulty unit. Put truck back together so driver could take truck without tracking unit. Return to workshop to diagnose unit. Fault find on bench. Discovered it was an sd card issue. Replace sd cards and re-test. Unit now tracking and working with mdvr on bench. Travel to Twin City and re fit tracking unit. Confirm its communicating with tablet and mdvr unit. Confirm with tech support that unit is tracking on there end. Return to workshop.		18/05/2021	571271	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\GPS	Unit Serial # 419005063		08/05/2021	580594	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\PRES CHECK	Pressure maintenance POS 5,9 & 10		08/05/2021	567432	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\CRUISE CON	CRUISE CONTROL CRUISE CONTROL REPORTED TO NOT WORK, INVESTIGATE AND REPAIR. * Related to engine brake fault * Removed fuse cover & inspected * Found dome fuse missing * Installed fuse & tested cruise control/all ok * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\JAKE BRAKE	ENGINE BRAKES ENGINE BRAKES STUCK ON, REPAIR AS REQUIRED Removed fuse cover & inspected * Found dome fuse missing * Installed fuse & tested engine brakes/all ok * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DriCabRep\SEAT	SEAT REPLACE TORN SEAT CUSHION COVER AS REQUIRED . * Removed seat cushion * Removed/replaced cushion cover as required * Installed cushion * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKES ADJUST BRAKES. * Inspect brake components * Adjust brakes to specification * Test braking operation * Brakes within specification * Return vehicle to service		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Body\REFLECTORS	REFLECTOR REPLACE MISSING REAR REFLECTORS. * Installed reflectors on rear of truck where required * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Susp\SHOCK ABS	SHOCKER REPAIR LOOSE SHOCKERS AS REQUIRED. * Attempted to tighten shockers but unable to due to worn bushes * Removed all lower drive shocker bushes * Installed new bushes & secured * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Susp\AXLES	PLATES REPLACE MISSING BACKING PLATE AS REQUIRED. * Installed backing plate on R/H front drive as required		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Chassis\EXHAUST	EXHAUST LEAK REPLACE SPLIT EXHAUST FLEX . * Removed exhaust flex * Installed exhaust flex with new gaskets & clamps * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\MOUNTS	ENGINE MOUNTS REPLACE FAILED REAR ENGINE MOUNTS AS REQUIRED. * Loosened off rear engine mount bolts * Raised & supported engine * Removed/replaced rear engine mounts * Lowered down engine & tensioned bolts * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Steering\WHEEL SEAL	HUB SEAL STEER REPLACE FAILED PASSENGER SIDE STEER HUB SEAL . * Supported steer axle * Removed wheel & brake drum * Found hub seal hadn't blown but had excessive grease * Cleaned the grease as required * Found s-cam required shimming * Shimmed as required * Reinstalled wheel & drum * Lowered down axle & tensioned wheel * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Steering\WHEEL HUB	WHEEL REPLACE CRACKED DRIVERS SIDE WHEEL NUT COLLET . * Removed/replaced R/H steer wheel but as required * Tensioned to specification * Repair complete		08/05/2021	567397	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER

			REPAIR CRACKED BATTERY BOX . * Removed batteries from battery box * Lowered down air tanks to gain access to crack * Removed walkway & brackets * Welded up crack in battery box * Painted battery box * Installed air tanks, walkway & brackets * Installed batteries & battery box cover									
1008	Tumut - Workshop	Engine\BATTERY	* Repair complete CARRIED OUT NSW ROADWORTHY STANDARD INSPECTION AS REQUIRED INSPECTION REPORT NUMBER #AX7733700.		08/05/2021	567397	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Insp\RWC COMP	BOOKING AND ADMINISTRATION FEE		08/05/2021	567397	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Insp\DEFECT	CLEAR RMS DEFECT NOTICE NUMBER 7700397541		08/05/2021	567397	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
			REPLACE BLOWN DASH GLOBES & CRACKED HEADLIGHT & REPAIR DAYTIME RUNNING LIGHTS . * Inspected & found blown dash globes & cracked headlight * Removed R/H headlight & replaced * Tested light operation/all ok * Removed dash panel to get access to globes * Replaced blown pyro & diff gauge lights * Tested dash lights/all ok * Installed dash panel * Inspected & diagnosed daytime runing light fault * Diagnosed possible failed module * Removed/replaced failed module * Reinstalled lights & tested operation/all ok									
1008	Tumut - Workshop	Elect\HEAD LIGHT	* Repair complete Replace stripes on Damaged section on truck at Royans workshop		08/05/2021	567397	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Wodonga - Workshop	Body\CONSUMABLE	Fleet no 1008	BEARING ROLL TRAVEL TO ROYANS TO CARRY OUT BEARING ROLL AS REQUIRED. $800.40 Drained oil and removed sump. Removed #4 main. Replaced bearings and thrust washers as required. Tensioned cap to spec. Removed main cap #1. Replaced bearings as required. Installed main and tensioned bolts as required to spec. Repeated process for all mains Removed big end caps as required Removed and replaced bearings – tensioned cap to spec as required. Repeated process for all big ends as required. Refit stiffener plate and oil pump and oil pickup as required Installed and tensioned sump filled up oil replaced oil filter.	01/04/2021	567362	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\ENG REBLD	TCTC supply parts deliver to Royans	Started vehicle and monitored oil pressure gauges as required – all ok.	01/04/2021	567362	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\DAMAGE	Travel To Royans. Download engine info to laptop as required. Return to workshop.		01/04/2021	567362	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Steering\WHEEL ALGN	Perform laser wheel alignment on Kenworth 03/05/2021		01/04/2021	567362	Completed	Myrtleford GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\GPS	remoed MTData hard drive. Consulted MTData. Downloaded player. Assessed camera footage for accident		27/11/2020		Completed	Myrtleford GTK	XO01AE	Albury Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\GPS	GPS NOT TRACKING	Travel to Greenfreight Albury to check truck not tracking. Found truck was tracking but unit was showir	25/11/2020	567362	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService	Service		24/11/2020	550065	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Susp\DAMAGE	RHF shackle pin extremely worn.. TCTC to pick up		24/11/2020	550065	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Engine\MOUNTS	LH Rear engine mount split		24/11/2020	550065	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\MOUNTS	replace front LH mudguard		21/11/2020	564458	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\MUDGUARDS	replace front LH mudguard		21/11/2020	564458	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Rosewood - Workshop	Hydraulics\VALVES	trailers slow to go in and out	check and set hydraulic pump pressures	20/11/2020	564488	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Hydraulics\OIL/FILTER	replace hydraulic filter		20/11/2020	564488	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Body\MUDGUARDS	REPLACE lhf DRIVE MUDGUARD	REMOVE BROKEN GUARD, DRILLED HOLES AND FITTED NEW fit 2x ride height valves replace height control valves as per discussion with Dave at TCTC	18/11/2020	564458	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Myrtleford - Workshop	Susp\HCV	spring pressures all over the place loaded level ground LH 2 RH 6 1/2	set ride heights	17/11/2020	563069	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\SCALES	travelling 2 1/2-3 6	fit 2x ride height valves	17/11/2020	563069	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\SUSPENSION	spring pressures a tool ineven	fit 2x ride height valves	17/11/2020	563069	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\SUSPENSION	spring pressures all over the place spring pressure all over the place coming in loaded LH 2&3 RH5-6	fit 2x ride height valves	17/11/2020	563069	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Susp\HOUSEKEEP	sometimes they are close and then all over the place	fit 2x ride height valves	17/11/2020	563069	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Tumut - Workshop	Steering\SUSPENSION	right front truck rod bush worn		30/10/2020	558596	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrivLine\SUSPENSION	left rear swing arm bush worn		30/10/2020	558596	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrivLine\OIL LEAK	repair leaking pinion nut		30/10/2020	558596	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrivLine\SUSPENSION	spring pressures all over the place		30/10/2020	558596	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabRep\SEAT	seat squeaking badly		30/10/2020	558596	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Hydraulics\OIL/FILTER	hydraulic tank repair		30/10/2020	558596	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Hydraulics\OIL/FILTER	needs hyd oil topped up please		29/10/2020	558432	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Hydraulics\OIL LEAK	hyd leak in fitting behind the tank		29/10/2020	558432	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	no high beam light on dashboard or mirror heater warmer light		20/10/2020	554865	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job replace RH fuel cross over P-clamp, broken		20/10/2020	554901	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Body\FUEL TANK	TCTC PO # 7251341 A Service		20/10/2020	554901	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	TCTC PO # 7251339		20/10/2020	554901	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Engine\FAULT CODE	after treat light come up on dash board		16/10/2020	553835	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\INDICATORS	no LHS indicators on guards and b.bar		14/10/2020	553192	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Susp\HCV	spring pressures all over the place		13/10/2020	552905	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		02/10/2020	549860	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\ELECT P&W	DRL's need replacing (no lights 1 half lights		02/10/2020	549860	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Susp\DAMAGE	RHF shackle pin extremely worn.. TCTC to pick up		02/10/2020	549860	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrivLine\SUSPENSION	some drive shocks worn rubbers check RH indicator not signalling from truck. Swapped with left relay and they both worked		02/10/2020	549860	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\INDICATORS	TCTC PO # 7250626 A Service		02/10/2020	549860	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService\AS	TCTC PO # 72500624	Added 3 Litres engine oil	02/10/2020	549860	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Body\MOUNTS	replace front LH mudguard		30/09/2020	549250	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService\BS	Service		30/09/2020	549250	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\ELECT P&W	engine brake - 1 head cutting in and out		23/09/2020	546643	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Myrtleford - Workshop	Engine\MOUNTS	LH Rear engine mount split		22/09/2020		Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Tumut - Workshop	VehService\AS	A Service		19/09/2020	545121	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		19/09/2020	545121	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\ELECT P&W	DRL lights faulty		19/09/2020	545121	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\ELECT P&W	ventilation fans not working		19/09/2020	545121	Completed	Myrtleford GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		19/09/2020	545121	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	A Service		19/09/2020	545121	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\MUDGUARDS	Replace LH mud guard	check m/guard (ok)	10/09/2020	539451	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes\ABS	ABS light on in dash	check abs system ok	10/09/2020	539451	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\DAMAGE	mysterious bend in air tank cover	tidy up air tnk cover check hub seal for leaks	10/09/2020	539451	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\WHEEL SEAL	has leaking RHR hub seal	(ok) may have been done	10/09/2020	539451	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\CLUTCH	clutch bearing line needs replacing		10/09/2020	539451	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Engine\HOUSEKEEP	slight injector line leak at no.4 called out to Tumut to diagnose/repair noise in gearbox/drive train test drove and inspected on pit discussed with Dave at TCTC		10/09/2020	539451	Completed	Myrtleford GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\GEARBOX	202km in ute		09/09/2020	542015	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	A Service	TCTC Service	02/09/2020	539017	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	axle temp guage lights not working	TCTC repaired axle temp light	02/09/2020	539017	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	fuel guage light not working	TCTC check fuel gauge light	02/09/2020	539017	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\INST/GAUGE	vent fans not working	TCTC check fan	02/09/2020	539017	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Elect\HEAD LIGHT	RH headlight out low beam A Service		22/08/2020	534698	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	PO # 7249546		22/08/2020	535109	Completed	Myrtleford GTK	XO01AE	Rosewood Workshop	P/MOVER

1008	Rosewood - Workshop	Brakes	Record check Results As Attached To this Job		22/08/2020	535109	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\WHEEL SEAL	has leaking RHR hub seal		22/08/2020	535109	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\CLUTCH	clutch bearing line needs replacing		22/08/2020	535109	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\HOUSEKEEP	slight injector line leak at no.4 replace RH low beam globe		22/08/2020	535109	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Elect\HEAD LIGHT	PO # 7249547		22/08/2020	535109	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Engine\BELTS/TENS	fan belts are slipping, fan belt are slipping		15/08/2020	531886	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		23/07/2020	526767	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\FITMENT	Job Added From Invoice		23/07/2020	526767	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Tyres\CASE STOCK	Job Added From Invoice weld up light bracket		23/07/2020	526767	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Body\MOUNTS	TCTC SPO # 7247472		19/07/2020	518326	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job A Service		15/07/2020	524903	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	TCTC SPO # 7247132		15/07/2020	524903	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\MUDGUARDS	Replace LH mud guard		08/07/2020		Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\SCALES	callibrate scales		08/07/2020		Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes\ABS	ABS light on in dash left hand low beam not working		08/07/2020		Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Tumut - Workshop	Elect\HEAD LIGHT	TCTC SPO # 7247471. left hand low beam not working clearance light drivers side back guard not working and broken off	replace left hand headlight bulb	03/07/2020	519988	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\TAIL LIGHT	TCTC SPO # 7247473. clearance light drivers side back guard not working and broken off	replace clearance light right rear	03/07/2020	514316	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job assist with brake relign. TCTC		03/07/2020	520261	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes\BRK RELINE	on front drive axle		03/07/2020	520261	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService\BS	B Service		03/07/2020	520261	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\IAP	Mt data install	in Tumut, disassemble rool console and passenger side door trims. Run and secure speaker cable, micrc	13/06/2020	507075	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		11/06/2020	510519	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	A Service low oil pressure light on stop engine light on	PO 7245879	11/06/2020	510519	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Engine\FAULT CODE	check fluids report to TCTC		29/05/2020	506349	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DriCabRep\WINDSCREEN	organise windscreen doctor Thursday for new screen		29/05/2020	505991	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
				check fluids oil/coolant ok check light codes none								
1008	Tumut - Workshop	Engine\FAULT CODE	check engine light keep coming on	visual check around engine ok	28/05/2020	505443	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\FAULT CODE	check codes etc. stop engine light on		28/05/2020	505841	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\HOUSEKEEP	check fluids		28/05/2020	505841	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes\BRK RELINE	brake relign on LHR drive		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\ELECT P&W	parking light not working		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Body\DAMAGE	mysterious bend in air tank cover		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\SCALES	CH2 & CH3 not working on scales		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\WORK LIGHT	rear cabin lights not working		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DriCabRep\WINDSCREEN	RH windscreen cracked		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Hydraulics\VALVES	trailers slow to go in and out		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\TAIL LIGHT	RH park light out		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService\AS	A Service	assist TCTC with service	27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\TRL LIGHTS	lights check a/c demister performance with TAE found sticking stepper motor not allowing full movement of vent door		27/05/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\ELECT P&W	#will need replacement		23/05/2020	503755	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Myrtleford - Workshop	DrCabElect\AIR CON	Air conditioner barely cool		23/05/2020	503219	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Body\MUDGUARDS	Replace rear RH mud guard found loose pittman arm		15/05/2020	500267	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Tumut - Workshop	Steering\HOUSEKEEP	tighten arm		12/05/2020	499144	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Steering\HOUSEKEEP	driver complains of truck all over then road steering		12/05/2020	499144	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	Steering\HOUSEKEEP	tightened loose pitman arm		12/05/2020	497500	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\SUSPENSION	ride heights good		12/05/2020	497500	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Steering\HOUSEKEEP	check poor steering/handling	PO 7245524	12/05/2020	497500	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\INST/GAUGE	Test Load Light Switch Loader Light Switch Playing Up		03/05/2020	495224	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\INST/GAUGE	Switch For Trailer Work Light Not Working Demister & Air Con Not Working		02/05/2020	495224	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\AIR CON	Parts On Order. Work light switch for trailers still faulty		02/05/2020	495224	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		17/04/2020	489944	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Elect\ENG FAN	fan badly cracked TCTC called out		17/04/2020	489944	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	VehService\AS	A Service As Per Attached Checklist Truck ABS light flashing ESC light Flashing	PO 7243512	17/04/2020	489944	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Tumut - Workshop	Brakes\EBS Kit	TAE		09/04/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\BREAKDOWN	call out to Monterey Rd		07/04/2020	486674	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\BOOST HOSE	change boost hose R/H upper	PO 7242957	07/04/2020	486674	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrivLine\CLUTCH	adjust clutch brake		04/04/2020	484221	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Elect\WORK LIGHT	work light switch still seems to be faulty		04/04/2020	484221	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService\AS	Service		04/04/2020	484221	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Myrtleford - Workshop	Elect\TAIL LIGHT	Rear number plate light not working		04/04/2020		Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Steering\PWR STEER	have new steer tyres fitted and still get small vibration through steering		04/04/2020		Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\HOUSEKEEP	slight vibration through floor of cab when under load		04/04/2020		Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Tumut - Workshop	DrivLine\CLUTCH	Check Clutch Brake Adjustment		29/03/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	R & R 119263	21/03/2020		Completed	Myrtleford	GTK	XO01AE	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		21/03/2020		Completed	Myrtleford	GTK	XO01AE	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1008	Tumut - Workshop	Chassis\FIFTH WHEE	fifth wheel pins		19/03/2020	478263	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Steering\HOUSEKEEP	check for wear in kingpins		19/03/2020	478263	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Body\FIFTH WHEE	fifth wheel pins		19/03/2020	478263	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Steering\HOUSEKEEP	check for wear in kingpins		19/03/2020	478263	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7242185	10/03/2020	474913	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job	knocking noise drivers have started	10/03/2020	474913	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrivLine\SUSPENSION	all rear suspension bushes posssible wear in torsion bar bushes	TCTC check rear suspension	08/03/2020	474535	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\MOUNTS	check engine mounts Turbo Boost Not Working Properly	check engine and gearbox mounts by Zac assist TCTC in job	08/03/2020	474535	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\FAULT CODE	R & R 119259	Cummins Adjusted Turbo	06/03/2020	474248	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes\BRAKE ADJ	check right front brake		29/02/2020	471994	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\COOL LEAKS	fit new radiator hose to engine		27/02/2020	470520	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
				split in radiator hose don't have any cut off at split refit tighten clamps fill with coolant and check truck back to work repair radiator hose fill with coolant								
1008	Tumut - Workshop	Engine\COOL LEAKS	repair straight radiator hose	check for leaks all good R&R 119257 repair radiator hose fill with coolant	27/02/2020	470002	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\COOL LEAKS	repair straight radiator hose	check for leaks all good	27/02/2020	470002	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\COOL LEAKS	radiator hose replace with new one top up with coolant		27/02/2020	471997	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes	Record Check Results As Attached To This Job		22/02/2020	469714	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	VehService\AS	A Service As Per Attached Checklist Truck & Trailer ABS Warning Light On At All Times	PO 7241633	22/02/2020	469714	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\INST/GAUGE	Work Done TAE 18/2/20 Load Switch Faulty		12/02/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	DrCabElect\INST/GAUGE	Work done 12/2/20		12/02/2020		Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Brakes\BOOSTER	called out to Coolaroo Rd. brake booster leaking blocked line off and drove to Tumut depot replace brake booster test all good		01/02/2020	458136	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7240172	19/01/2020	451465	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	LH HI/LO Beam Globe Not Working	PO 7240173	19/01/2020	451465	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/01/2020	451465	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\BELTS/TENS	Check Belts & Bearings - Replaced AC Tensioner & Belt As Required	PO 7239903	16/01/2020	450135	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7239898	11/01/2020	445447	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		11/01/2020	445447	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Engine\MOUNTS	please check engine mounts		19/12/2019	440772	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/12/2019	440772	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	B Service		19/12/2019	440772	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER

1008	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist		19/12/2019	440772	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7238929	13/12/2019	435220	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/12/2019	435220	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Replace Blown Headlight Globe	PO 7238682	05/12/2019	429586	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		05/12/2019	429586	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7238681	05/12/2019	429586	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/11/2019	425825	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist HOOK UP T/505	PO 7238487	28/11/2019	425825	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	& T/506		27/11/2019	425862	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	Service		21/11/2019	420362	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	A SERVICE		21/11/2019	420362	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	ORGANISE TYRES TO BE FITTED		21/11/2019	420362	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres	LEFT FROM FRIDAY NIGHT		17/11/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\TRL LIGHTS	rear left clearance light on bumper bar loose	remount clearance light mount (LHS)	16/11/2019	417571	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		15/11/2019	1	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		15/11/2019	1	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7237649	12/11/2019	414467	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		12/11/2019	414467	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine			07/11/2019	411208	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\EXHAUST	Replace First Section Of Exhaust Flex	po 7237292	07/11/2019	411208	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Susp\SHOCK ABS	Replace Worn Right Hand Side Front Lower Shock Mount Rubbers	PO 7237291	05/11/2019	409679	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		05/11/2019	409679	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7237290	05/11/2019	409679	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\TRL LIGHTS	Repaired mount bracket for LHR clearance light		02/11/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7237113	30/10/2019	405345	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/10/2019	405345	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	REPLACED LOAD/UNLOAD SWITCH	REPAIRED WIRING IN CONTROL BOX	26/10/2019	403141	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2019	399893	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\CS	carry out A service driver complaining off shuttering under cad		21/10/2019	399893	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\CLUTCH	adjust clutch		16/10/2019	397323	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\CLUTCH	ADJUSTED CLUTCH, CHUTTERING THOUGH PEDAL, NOW GOOD		16/10/2019	397323	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	DrivLine\DRV LN SER	CHECK DIFF TEMP ON FRONT DIFF WITH INFRA RED,, ALL GOOD	CHECKED DIFF LEVELS ON BOTH DIFFS, ALL GOOD. PLUG ON FRONT DIFF TEMP SENOR DAMAGED,, WIE PULLED TOO SHORT, REPLACED ;P; CLUMP, PLUDDED IN WIRES & CABLE TIED IN PLACE.	16/10/2019	397323	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7236372	12/10/2019	394994	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/10/2019	394994	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Tyres\AIR LEAK	CTI spinner air leak	repaired air leak at RHF drive CTI spinner	11/10/2019	394491	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\MOUNTS	Top Bonnet Stop Rubbers Perished	PO 7236144	03/10/2019	390490	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		03/10/2019	390490	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7236143	03/10/2019	390490	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\DRV TYRES	REP BLASTED FLAT DRIVE TYRES P9- P10		30/09/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	HOOK UP		27/09/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\GEARBOX	G/BOX UNI HAS WEAR (MOVEMENT)		24/09/2019	386097	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\R DIFF OIL	DRIVER COMPLAINING OF DRIV VIBRATION	CHECKED FRONT DIFF (MOVEMENT IN IMPUT) CHECKED DIFF OIL & FOUND FLAKES IN IT.	24/09/2019	386097	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RUN FLAT	BEAD BLASHED FLAT DRIVE TYRES. PG/ P10		23/09/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\COMPRESSOR	Replace Leaking Hot Line	PO 7235545	20/09/2019	384531	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7235533	20/09/2019	384531	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Replace Blown Headlight Globe	PO 7235534	20/09/2019	384531	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		20/09/2019	384531	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\TP09	Bead blasted 2x flat drive tyres P9-P10		16/09/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/09/2019	380214	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7235338	14/09/2019	380214	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Elect\ELECT P&W	Replace LH Park Light Globe As Required	PO 7235339	11/09/2019	377589	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7235209	07/09/2019	375556	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	Replace Blown Dash Globes	PO 7235313	07/09/2019	375556	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	Replace Day Time Running Lamp	PO 7235208	07/09/2019	375556	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attatched To This Job		07/09/2019	375556	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Body\DAMAGE	STRAIGHTEN REAR TAIL LIGHT IF POSSIBLE	Previously completed	06/09/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up T505 steering shaking		04/09/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	clunking in front end when turning		04/09/2019	373698	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/08/2019	370090	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7234660	28/08/2019	370090	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\FAULT CODE	after treat warning light stays on		20/08/2019	366166	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	test drive with driver to test at temperature		20/08/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\EXHAUST	replaced tank cap		20/08/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\EXHAUST	replaced filter in ad-blue tank		20/08/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\FAULT CODE	followed check procedures		20/08/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\FAULT CODE	after treatment light on. Checked codes		20/08/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\HOUSEKEEP	Replace Damaged Left Hand Steer Brake Hose	PO 7234232	18/08/2019	365710	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\HOUSEKEEP	Replace Broken Cab Filter Cover	PO 7234231	18/08/2019	365710	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		18/08/2019	365710	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Aattached Checklist	PO 7234230	18/08/2019	365710	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\TRL LIGHTS	brake lights staying on	removed RH stop/tail light, found loose connection, reassembled and tested in yard (could not fault aga	13/08/2019	362136	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Replace Blown Headlight Globe	PO 7234061	10/08/2019	361153	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Workshop\MOVE ASSET	Unhook for TCTC service & secured lines		10/08/2019		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes\ABS	Truck and Trailer ABS light comes on		09/08/2019	360734	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\BS	Service Due		09/08/2019	360734	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	load/unload switch opposite P.T.O switch faulty	replaced load/unload switch	02/08/2019	356353	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		01/08/2019	355262	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes\ABS	Trailer A.B.S light comes on when loaded		01/08/2019	355262	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7233562	01/08/2019	355262	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Replace LH Low Beam	PO 7233293	28/07/2019	352991	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7232947	24/07/2019	350112	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/07/2019	350112	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Cooling\ENG FAN	Replace Failed Horton Solenoid	PO 7233282 Repaired RHF guard outrigger Replaced outer guard bracket Replaced RHF CTI spinner	20/07/2019	349169	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Body\DAMAGE	Roo damage	Replaced RHF CTI hose	19/07/2019	346990	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\BATTERY	Jump start & put on charge		19/07/2019		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7232685	17/07/2019	345480	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ALT	Replace Faulty Alternator	PO 7232769	17/07/2019	345480	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\TAIL SHAFT	Replace Loose Input Shaft Nut	PO 7232768	17/07/2019	345480	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/07/2019	345480	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Hydraulics\OIL/FILTER	Replaced hydraulic tank filter canister	Topped up hydraulic oil, degreased, washed & replaced cover	14/07/2019	343460	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Steering\HOUSEKEEP	Replace Loose Pitman Arm Bolt	PO 7232421	09/07/2019	339358	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As attached To This Job		09/07/2019	339358	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist jump start truck	PO 7232419	09/07/2019	339358	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\BATTERY	hook up battery charger		08/07/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\COMPRESSOR	Replace Hotline As Required	PO 7233281	07/07/2019	338339	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7232513	03/07/2019	335418	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As attached To This Job		03/07/2019	335418	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Tyres\CTI Drive	Leaking CTI hose rear left wheel	Repaired damaged CTI fitting on tap	28/06/2019	331679	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7231823	27/06/2019	330874	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Brakes As Attached To this Job		27/06/2019	330874	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	Elect\BATTERY	Jump Start driver couldn't start engine. Load tested batteries	Interior Light left on	24/06/2019	328364	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Elect\BATTERY	jump started found Elphi2stone switches left on		18/06/2019	324799	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To this Job		15/06/2019	324799	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	clutch brake needs adjusting	PO 7231688	15/06/2019	324799	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Paperwork	PO 7231687	15/06/2019	324799	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\BREAKDOWN	truck only rpm to 1500		14/06/2019	323180	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\CRUISE CON	cruise control cuts out and can take time to reset. Before you reset it the engine appears to miss at random. Speed limiter also appears to cut out as I was able to c		13/06/2019	322983	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\DAMAGE	tow pin on bullbar bent		12/06/2019	321013	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\INST/GAUGE	Replace Failed Dash Lights	PO 7232983	09/06/2019	320570	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER

			unhook for TCTC B Service secure hoses										
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up			08/06/2019	321015	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\BS	B Service			08/06/2019	321015	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	carried out by TCTC		08/06/2019		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2019	316013	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	clutch brake adjustment	PO 7230953		01/06/2019	316013	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7230951		01/06/2019	316013	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\IDLER PULL	truck loses rev's now and then in wet weather truck derating			30/05/2019	313765	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\FAULT CODE	no codes stored			30/05/2019	313765	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\TAIL LIGHT	front right park light out. front right oark light out	replaced RH headlight insert		29/05/2019	312781	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\IDLER PULL	truck wouldn't rev over 1500 revs in the bush	checked truck for codes not fault detected		29/05/2019	312781	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			28/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7230683		26/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			18/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\WORK LIGHT	worklight RHS loose			18/05/2019	304664	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			18/05/2019	304664	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7230259		18/05/2019	304664	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			14/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\CLEAN	contacted Nich to organise Cummins			13/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Cooling\COOL LEAKS	found coolant leak from water pump transfer pipe			13/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up to T505/T506 unhooked for TCTC Service			13/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	secured lines			12/05/2019	300386	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\BS	B Service			12/05/2019	300386	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7230269		11/05/2019	300066	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To this Job			11/05/2019	300066	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			08/05/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To this Job			03/05/2019	294797	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7229901		03/05/2019	294797	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			30/04/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			30/04/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Rplace Blown LH Headlight. A Service	PO 7229448		28/04/2019	290930	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7229447		28/04/2019	290930	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			28/04/2019	290930	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			18/04/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			18/04/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			17/04/2019	284715	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7229485		17/04/2019	284715	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\INST/GAUGE	Replace Failed Third Button As Required			11/04/2019	280367	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	Adjust Clutch	PO 7228763		07/04/2019	277511	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\INST/GAUGE	transmission gauge light not working			04/04/2019	275180	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service			04/04/2019	275180	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7228756		04/04/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			03/04/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Contract Weekly Maintenance Cost			28/03/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			27/03/2019	270345	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7228299		27/03/2019	270345	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\STEER UNI	truck still has vibration at 95-100 km/h even after having new rear tyres put on and front steer's have been balanced			23/03/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			21/03/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7228297		19/03/2019	264844	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			19/03/2019	264844	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\OIL LEAK	has CTI leak on L/H front drive wheel	replaced LHF drive CTI spinner - leaking		14/03/2019	262267	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			13/03/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\HOUSEKEEP	please check tyre pressure in R/H steer tyre	checked tyre pressures LH 105 PSI. RH 106 PSI		12/03/2019	260530	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\SHOCK ABS	Replace Worn LHF Drive Lower Shicker Bushes	PO 7227784		10/03/2019	259700	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			10/03/2019	259700	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7227783		10/03/2019	259700	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			06/03/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7227416		03/03/2019	255484	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To this Job			03/03/2019	255484	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Engine\EXHAUST	Repair Exhaust Flex	PO 7227160		28/02/2019	253546	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost unhook 1008 sent to TCTC 2x hub seals 1x heater tap			27/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	wash down batteries			22/02/2019	249643	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up T505/T506			22/02/2019	249702	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7226840		21/02/2019	249643	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			21/02/2019	249643	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			20/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			13/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	pick up			09/02/2019	244422	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	unhook. Deliver to HTT to carry out wheel alignment			09/02/2019	244422	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Ckeck Results As Attached To this Job			09/02/2019	244422	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7226401		09/02/2019	244422	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	TRUCK PULLING LEFT	CARRY OUT WHEEL ALIGNMENT		09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up to T505/T506			09/02/2019	244422	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\SCALES	no scales on CH 2 & 3 truck pulls to the left	repaired scales		09/02/2019	244422	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	still got bad tyre vibration in rear			09/02/2019	244422	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\IAP	MTData not working properly can't activate rest breaks or mass axle limits	ARKON		09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	still shaking thrown steering wheel			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes\BRAKE ADJ	check brake adjustment			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\STEER TYRE	needs steer tyres			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Air Con\AIR CON	check airconditioner (windows fog up)	TCTC		09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Chassis\WINCH/STRP	front air winch is bent down maybe from a log or loader at mill (still works okay)	t505		09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\RADIO	tablet not charging properly			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\STEER UNI	steering column tilt function failed			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\INST/GAUGE	IPAD PLAYING UP. SAYS "TALON ON AVAILABLE"			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\TAIL LIGHT	REPAIR DAMAGED CLEARANCE LIGHT			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\RADIO	replace UHF mic holder mounting screw			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\BATTERY	engine cuts out while loading			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\STEER UNI	steering wheel off centre			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	Service			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	Service			09/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes\BRAKE ADJ	brake adjust			07/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			07/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up as double			01/02/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	B service	B Sevice completed by Twin City Truck Centre		01/02/2019	241214	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Engine\COOL LEAKS	Lower Hearer Tap Leaking			31/01/2019	240767	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\CTI Drive	L/F Rotator U/S			31/01/2019	240767	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\BELTS/TENS	Air Conditioner Belt Cracked Ribs			31/01/2019	240767	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	Change Over Before Service			31/01/2019	240767	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			31/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\STEER TYRE	truck also has bad vibration probably due to the mismatched drive tyres			25/01/2019	238137	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	truck pulls to the left maybe needs wheel alignment??			25/01/2019	238137	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			24/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	Repair Tacho Lights As Required	PO 7225668		22/01/2019	235682	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7225510		20/01/2019	234691	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			20/01/2019	234691	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up T505/T506			18/01/2019	233789	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\DRV TYRES	fit up drive tyres			18/01/2019	233789	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hook up as double			17/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost			17/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\EXHAUST	shorten exhaust stalks			17/01/2019	232901	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER

			can we shorten exhaust stacks? Please									
1008	Albury - Workshop	Engine\EXHAUST	hard to avoid low branches with oncoming traffic		17/01/2019	232902	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\IAP	MTData not working properly can't activate rest breaks or mass axle limits		17/01/2019	232902	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	DrCabElect\IAP	Unit checked out by IT not responding book repair through MTData		17/01/2019		Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Workshop\CLEAN	organise for TCTC to repair		16/01/2019	232600	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\BELTS/TENS	clutch bar crank bearings u/s		16/01/2019	232600	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Cooling\ENG FAN	engine fan cracked blades		16/01/2019	232600	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\DRV LIGHT	Driving Light	FIT UP DAY TIME RUNNING LIGHTS	16/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Body\SCALES	Scales	cleaned and secured scales connections tested	15/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7225226	11/01/2019	229446	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			Record Check Results As Attached To this Job									
1008	Albury - Workshop	Brakes	Nothing Recorded		11/01/2019	229446	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		09/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\IAP	cant log onto ipad (says no internet connection)		08/01/2019	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			Reposition RHS Spring Top Hat									
1008	Albury - Workshop	Susp\SUSPENSION	Insulate RH Steer Brake Hose	PO 7225531	04/01/2019	224900	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	Adjust Clutch & Repair Thro Out Bearing Grease Line As Required	PO 7225530	04/01/2019	224900	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		04/01/2019	224900	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7225528	04/01/2019	224900	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			Failed CTI Rotator									
1008	Albury - Workshop	Tyres\CTI Drive	Contractor Repair Book 0309	Nothing Claimed TCTC	04/01/2019	224900	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		03/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		03/01/2019		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				no horn/interior light								
				no cruise control								
			horn and interior lights not working	eng brake not turn off								
			cruise control not working	no control locking								
			cant turn off engine brake in steering wheel	replace blown fuse for horn/dome								
1008	Albury - Workshop	DrCabElect\ELECT P&W	remote central locking not working	driver explained excessive use of horn blew fuse	30/12/2018	224001	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		20/12/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7224792	18/12/2018	220088	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results AS Attached To This Job		18/12/2018	220088	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		16/12/2018	210730	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\BALANCE	Job Added From Invoice		16/12/2018	210730	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		16/12/2018	210730	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		16/12/2018	209675	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		16/12/2018	209675	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\CASE STOCK	Job Added From Invoice		16/12/2018	209675	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\WINDSCREEN	replace 2x screens		16/12/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		13/12/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7224364	11/12/2018	214849	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		11/12/2018	214849	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			Repair Leaking Throughshaft									
			Warranty Job									
1008	Albury - Workshop	DrivLine\OIL LEAK	Contractor Repair Book 0303	PO 7224543	11/12/2018	214849	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		06/12/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			both windscreens need replacing									
1008	Albury - Workshop	DriCabRep\WINDSCREEN	(crack in left and star in drivers view)		05/12/2018	210730	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7224253	05/12/2018	210246	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		05/12/2018	210246	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Chassis\MUDGUARDS	Mudguards & Mudflaps	tightened LHR outrigger.	30/11/2018	208169	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		29/11/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Repair Wiring To LH Headlight	PO 7223655	25/11/2018	204598	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7223653	25/11/2018	204598	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		25/11/2018	204598	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		22/11/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		22/11/2018	1	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		22/11/2018	1	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			Repair Boost Leak									
1008	Myrtleford - Workshop	Engine\BOOST HOSE	Contractor Repair Book 0245	PO 7223703	21/11/2018	202493	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\CS	Annual Service	C service completed by Twin City Truck Centre	17/11/2018	200328	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		16/11/2018	196091	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		16/11/2018	196091	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance Cost		15/11/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Maintenance Cost		08/11/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7223004	08/11/2018	194589	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		08/11/2018	194589	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Chassis\HEATER	heater not working (RNR attached)	turned on manual taps	08/11/2018	199006	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\BALANCE	Job Added From Invoice		07/11/2018	192003	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\ROTATION	Job Added From Invoice		07/11/2018	192003	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes\BRAKE ADJ	check brake adjustment - prime mover wouldn't hold while loading on slight hill - not normal	adjust drive brake	06/11/2018	191944	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			vibration in drive tyres									
			tyres - balanced steer									
			- drive fitted with correct of rotation									
			test drive at drivers request									
1008	Albury - Workshop	Tyres\DRV TYRES	old drive tyres have worn heel that could also contribute to vibration		06/11/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Maintenance Cost		02/11/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	hookup T505/T506		31/10/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	replaced rubber for loom to trailer		28/10/2018	189958	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	replaced trailer plug		28/10/2018	189958	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\WIPERS	Replaced Wiper Blades	PO 7222939	28/10/2018	189958	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	start A Service find radiator mountd u/s		28/10/2018	189958	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance		25/10/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		25/10/2018	185725	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\BALANCE	Job Added From Invoice		25/10/2018	185725	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		25/10/2018	185725	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Body\AIR LEAK	dump valve stays open now and then. Lose air pressure whilst loading	dump valve leaking. Nothing leaking on truck in workshop. Will with driver for more info with fault	21/10/2018	185176	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				not reving over 1500 rpm								
1008	Albury - Workshop	Engine\FAULT CODE	when taking off in the bush engine wont rev over 1500 rpm for 1km	check and adjust uss.	21/10/2018	185176	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				PTO fast idle								
				-PTO slow to go to fast idle								
1008	Albury - Workshop	Engine\FAULT CODE	fast idle not working sometimes when P.T.O engaged - also it happens once loaded	replaced inline air pressure switch	21/10/2018	185176	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	po 7222441	19/10/2018	185550	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To this Job		19/10/2018	185550	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Replace Blown RH high beam light	PO # 7222442	18/10/2018	184450	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine	Job Added From Invoice		18/10/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance		18/10/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres	Job Added From Invoice		16/10/2018	150170	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Replace RH headlight low beam globe	PO 7222082	15/10/2018	182303	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		11/10/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		11/10/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		10/10/2018	179163	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7221968	10/10/2018	179163	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	Adjust Clutch	PO 7221970	09/10/2018	179163	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance		09/10/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	Replace LH Headlight globe & parker globe	PO 7221652	08/10/2018	177274	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		05/10/2018	175860	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\BALANCE	Job Added From Invoice		05/10/2018	175860	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\STEER TYRE	steer tyres		03/10/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance		03/10/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		30/09/2018	174887	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7221651	30/09/2018	174887	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Workshop	Job Added From Invoice		29/09/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Maintenance Cost		25/09/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		22/09/2018	170071	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\EXHAUST	Replace leaking front exhaust flex	PO 7221224	22/09/2018	170071	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7221109	22/09/2018	170071	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract\CONTRACT	Weekly Contract Maintenance		20/09/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER

1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7220794	15/09/2018	165446	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/09/2018	165446	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		15/09/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		15/09/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				Refit LH door trim								
1008	Albury - Workshop	DriCabRep\DOOR LOCK	Rubber around door are loose	PO 7220421	05/09/2018	160523	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				Refit RHS door trim & replace Christmas tree clips								
1008	Albury - Workshop	DriCabRep\DOOR LOCK	Drivers door trim loose	PO 7220421	05/09/2018	160523	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				Replaced 3 x Globes								
1008	Albury - Workshop	DrCabElect\INST/GAUGE	2 globes out on dash (voltmeter & axle oil)	PO 7220421	05/09/2018	160523	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\SCALES	Scales on channel 2 fluctuating 3 tonne loaded to T505 came in at 64650		05/09/2018	160523	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres	Job Added From Invoice		02/09/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		02/09/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			REPLACE CTI HOSE.									
1008	Albury - Workshop	CTI\CTI Drive	DAMAGED BY WINCH STRAP		01/09/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Contract	Parts Added From Non Work Parts Area		30/08/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\INST/GAUGE	2 instrument light globes out on dash		30/08/2018	157917	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			send email/photo's etc conversation									
1008	Rosewood - Workshop	Body\MOUNTS	res trunnion mount bolts too long		28/08/2018		Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check As Attached To This Job		28/08/2018	155620	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7222031	28/08/2018	155620	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
				straighten and adjust RF outrigger								
				replaced outer mount for mudguard								
1008	Albury - Workshop	Body\MUDGUARDS	straighten and replace broken guard mount RHS front	(kangaroo damage)	22/08/2018	151373	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		22/08/2018	115271	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7222032	22/08/2018	115271	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
			Un-hook for TCTC radiator repairs									
1008	Albury - Workshop	Workshop\MOVE ASSET	Hook-up		18/08/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			unhook for work at TCTC									
1008	Albury - Workshop	Workshop\MOVE ASSET	secure trailer lines		16/08/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres	Job Added From Invoice		11/08/2018	141920	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		11/08/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		10/08/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		10/08/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres	Job Added From Invoice		10/08/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7219272	09/08/2018	145214	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		09/08/2018	145214	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
				organise tyre replacement								
				(rang emergency number agreed to steer replacement and fitter to bring tyres. Fitter arrived and informed me he couldn't complete job as he was required elsewhere. Driver sent to beaurepairs shop								
1008	Albury - Workshop	Tyres\STEER TYRE	needs steer tyres	on way to work)	07/08/2018	141900	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7218948	02/08/2018	140318	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Elect\INDICATORS	Repair RHR Indicator	PO 7218960	02/08/2018	140318	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		02/08/2018	140318	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Elect\INDICATORS	right indicator flashes fast	indicators working in workshop	27/07/2018	135766	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	trailers wont fold up	trailers hard to fold due to mismatch	27/07/2018	135766	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	have to use throttle when pto is engaged	repaired wiring to PTO rpm ramp switch	27/07/2018	135766	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		25/07/2018	135407	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7218696	25/07/2018	135407	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
			check low beam headlights (too high)									
1008	Albury - Workshop	Elect\HEAD LIGHT	(getting flashed at times)	adjust hi/low beam	22/07/2018	131872	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Air Con\AIR CON	check airconditioner (windows fog up)		22/07/2018	131872	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				replaced LH hi/low globe and parker								
1008	Albury - Workshop	Elect\HEAD LIGHT	left side low beam headlight	PO 7218700	20/07/2018	131872	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\OIL LEAK	check for leak on firewall		20/07/2018	131872	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres	Job Added From Invoice		20/07/2018	130326	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	droped trailers T505/T506		17/07/2018	131308	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			oil all over engine									
			lifted bonnet and found aircon high pressure									
1008	Albury - Workshop	Engine\OIL LEAK	hose rubbed turn on passenger side near radiator, rang callout number and organized for TCTC to pickup in morning for repairs		17/07/2018	131308	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/07/2018	129940	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist		12/07/2018	129940	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	NO DRIVING LIGHTS. NO RH HIGH BEAM	REPLACED HEAD LIGHT AND GLOBE	11/07/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	low beam lights not bright enough and pointing too low. Very dangerous whilst driving in heavy rain and fog on narrow roads. Hard to see when driving against on	GLOBES CHANGED AND ADJUSTED	11/07/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Elect\HEAD LIGHT	Repair headlight filled with water	PO 7217919	07/07/2018	125799	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		06/07/2018	125332	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7217768	06/07/2018	125332	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Elect\DRV LIGHT	Repair wiring for driving lights	PO 7217518	02/07/2018	121246	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Tumut - Workshop	VehService\BS	Service	service completed by TCTC	28/06/2018	119543	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
1008	Tumut - Workshop	Engine\EXHAUST	can exhaust's please be shortened by 200mm and repair dent on top of passenger side exhaust. Also request for stacks be refitted facing outwards instead of on t		28/06/2018	119543	Completed	Myrtleford	GTK	XO01AE	Tumut Workshop	P/MOVER
			checked ramp up switch wiring - all seemed ok (replaced switch)									
1008	Albury - Workshop	Elect\ELECT P&W	remount ramp up switch and rewire to suit		23/06/2018	116400	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			P.T.O revs drop in and out									
1008	Albury - Workshop	Engine\FAULT CODE	have to use foot pedal		23/06/2018	116400	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	needs RH headlight globe	replaced RH H1/LO insert & N4 globe (hole in lense - full of water)	20/06/2018	113254	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		16/06/2018	100282	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		16/06/2018	100282	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/06/2018	110160	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7216950	15/06/2018	110160	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7216679	07/06/2018	105315	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/06/2018	105315	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Elect\ELECT P&W	Replace blown globe - diff temp gauge	PO 7216530	05/06/2018	100282	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7216415	31/05/2018	100282	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		31/05/2018	100282	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		21/05/2018	95130	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7216116	21/05/2018	95130	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			air leak - airline for power									
1008	Albury - Workshop	Body\AIR LEAK	divider is brittle and snapped in half	repaired 1/4" air hose for power divider (hose had been damaged by rock or stick	18/05/2018	92847	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				PO 7215792								
1008	Myrtleford - Workshop	Engine\EXHAUST	Repair First exhaust hose blown out	Replace hose	16/05/2018	91798	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Tyres\BALANCE	Job Added From Invoice		16/05/2018	86902	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		16/05/2018	86902	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice		16/05/2018	86902	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7215857	14/05/2018	89981	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/05/2018	89981	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service As Per Attached Checklist	PO 7215533	07/05/2018	84791	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/05/2018	84791	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\BS	B service	B service completed by Twin City Truck Centre	02/05/2018	80737	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	RECORD CHECK RESULTS		22/04/2018	74922	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A SERVICE	PO 7214723	22/04/2018	74922	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	RECORD CHECK RESULTS		12/04/2018	70181	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A SERVICE	PO 7214310	12/04/2018	70181	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\ROTATION	Job Added From Invoice		12/04/2018	64015	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrivLine\CLUTCH	clutch pedal very heavy to use		08/04/2018	67223	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	RECORD CHECK RESULTS		05/04/2018	64604	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A SERVICE	PO 7214022	05/04/2018	64604	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	low beam headlights are pointing up too high (keep getting flashed)	adjusted headlights	04/04/2018	64015	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\WHEEL ALGN	straighten steering wheel please	adjust steering wheel	28/03/2018	61726	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		27/03/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		27/03/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres	Job Added From Invoice		27/03/2018	0	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	RECORD CHECK RESULTS		24/03/2018	60021	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
			A SERVICE									
1008	Myrtleford - Workshop	VehService\AS	checked king pins cleaned air filter bowls	PO 7213534	24/03/2018	60021	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Tyres\DRV TYRES	Drive tyres required		20/03/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			Steering column adjustment - not working									
1008	Myrtleford - Workshop	Steering\STEER UNI	re-attached, adjusted & secured cable		18/03/2018	54923	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	DrivLine\CLUTCH	Adjust clutch & move rose joint as per eatons instructions	PO 7213295	18/03/2018	54923	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	record check results		18/03/2018	54923	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER

			A SERVICE									
1008	Myrtleford - Workshop	VehService\AS	Checked king pins & checked & cleaned filter bowls	PO 7213286	18/03/2018	54923	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Rosewood - Workshop	DrCabElect\RADIO	tablet not charging properly		16/03/2018	54378	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Steering\STEER UNI	steering column tilt function failed		16/03/2018	54378	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Tyres\DRV TYRES	drive tyres worn		16/03/2018	54378	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Rosewood - Workshop	Steering\STEER UNI	steering column wont tilt back and forward		16/03/2018	54378	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	RECORD CHECK RESULTS		11/03/2018	50452	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
			A SERVICE									
1008	Myrtleford - Workshop	VehService\AS	checked king pins & cleaned air filter bowls	PO 7214267	11/03/2018	50452	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
			Air Filters not square in housing									
			replace air filters									
1008	Myrtleford - Workshop	Engine\FILTERS	LH hoursing ordered	PO 7214809	11/03/2018	50452	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Engine\OIL LEAK	Oil leaking: - loose fitting gearbox filter housing	PO 7212881	08/03/2018	48028	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	VehService\AS	A Service as per attached checklist	PO 7212639	02/03/2018	44900	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Myrtleford - Workshop	Brakes	Record check results as attached to this job		02/03/2018	44900	Completed	Myrtleford	GTK	XO01AE	Myrtleford Workshop	P/MOVER
1008	Albury - Workshop	Steering\STEER UNI	Remove covers on steering column. Re-fit adjustor cable. Lubricated mechanism. Assemble + test.	PO 7212700	27/02/2018	42545	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\BS	B2 SERVICE	DONE @ TCTC	22/02/2018	40397	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Body\DRV LIGHT	DRIVING LIGHTS ARE LOOSE	DONE @ TCTC	22/02/2018	40397	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\BALANCE	Job Added From Invoice		17/02/2018	34406	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\ROTATION	Job Added From Invoice		17/02/2018	34406	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		17/02/2018	34406	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres\STEER TYRE	Job Added From Invoice		17/02/2018	34406	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A service carried out by Albury Workshop		14/02/2018	34822	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Wodonga - Workshop	VehService\AS	Refer 73014 - correct entry	A service Complete	13/02/2018	34822	Completed	Myrtleford	GTK	XO01AE	Wodonga Workshop	P/MOVER
				checked hyd. oil level (ok)								
				checked hyd. Pressures: was 1750 PSI, set to 1850 PSI								
				washed hyd. tank								
1008	Albury - Workshop	Hydraulics\HYD LEAKS	wont pull A Trailer all the way up	tested loading/unloading trailers several times	11/02/2018	33550	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Tyres	Job Added From Invoice		08/02/2018	23295	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/02/2018	30327	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				Sent to TCTC								
1008	Albury - Workshop	VehService\AS	A SERVICE	require o/n	07/02/2018	30327	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\W/S MAINT	installed toolbox pads. Fitted fire extinguisher. Ordered new entinguisher		06/02/2018	29255	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				call out								
				travel to Batlow II - Greenhills forest way								
				replaced flex								
1008	Rosewood - Workshop	Engine\FAULT CODE	exhaust flex falling apart	Tumba to Rosewoos to Batlow II. Return to Tumba	02/02/2018	26895	Completed	Myrtleford	GTK	XO01AE	Rosewood Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/01/2018	25738	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\HOUSEKEEP	6 Liters engine oil		30/01/2018	25738	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	straighten clearance light on R/H side of rear bumper		30/01/2018	25738	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	Service		30/01/2018	25738	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Body\PANELS	Make and fit padding to step boxes		19/01/2018		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Workshop\MOVE ASSET	unhook T505/T506		14/01/2018	19979	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\BS	B1 SERVICE	TCTC	14/01/2018	19979	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		31/12/2017	15191	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A SERVICE		31/12/2017	15191	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				hyd leak from hyd hose								
				remove valve block from hyd tank and tightened loose lock nut on hyd fittiing								
1008	Albury - Workshop	Hydraulics\OIL LEAK	OIL LEAK @ VALVE BLOCK.	remount block and fill up tank	19/12/2017	9848	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/12/2017	9848	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A SERVICE		19/12/2017	9848	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DriCabRep\HOUSEKEEP	SUPPLY FIRST AID KIT		16/12/2017		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
				turned wheel two teeth to right								
1008	Albury - Workshop	Steering\STEER UNI	steering wheel off centre	TCTC PO 7210099	12/12/2017	6356	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	VehService\AS	A Service		10/12/2017	5376	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/12/2017	5376	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
			replaced RH hi beam globe									
1008	Albury - Workshop	Elect\ELECT P&W	adjusted lo beam		10/12/2017	5376	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Engine\BATTERY	engine cuts out while loading	Paul has been asked if idle shut down can be disenabled	10/12/2017	4986	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Steering\STEER UNI	steering wheel off centre	steering wheel to be straightened	10/12/2017	4986	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\ELECT P&W	low beam lights not bright enough and pointing too low. Very dangerous whilst driving in heavy rain and fog on narrow roads. Hard to see when driving against on	will look into better globes/lights	10/12/2017	4986	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	Elect\HEAD LIGHT	REPLACED BLOWN HEAD LIGHT GLOBE		10/12/2017		Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER
1008	Albury - Workshop	DrCabElect\RADIO	replace UHF mic holder mounting screw	R&R number 108101	08/12/2017	4187	Completed	Myrtleford	GTK	XO01AE	Albury Workshop	P/MOVER