EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
1073	Wodonga - Workshop	clutch adjustment	completed by AR SMc Labour-Mobile-Breakdown TravelledtoBPSouthCoffsHarbour	16/06/2026	481995	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
		Air Con\AIR CON	RemovedandreplacedA/Cblowerfanindash								
1073	Wodonga - Workshop	WW134309	Testednewfan-Allok Traveled to Tuckerbox, Gundagai Replaced long tail suzi leads as requested after being damaged	12/06/2026	480218	Completed	Wodonga	LHB	XW07GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1073	Wodonga - Workshop	Elect\SUZI COIL LEADS	Repaired airleak behind valve from suzi coil	09/06/2026	479915	Completed	Wodonga	LHB	XW07GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1073	Wodonga - Workshop	VehService\AS A Service	completed by AR EC	06/06/2026	478992	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Need's new windsceen wiper's.	completed by EC AR	06/06/2026	478992	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months B Service	completed by TP	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Serviced @ 456,177 Klms	completed by TP,JS inspected ok	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	front diff pinion seal leaking	completed by TP completed	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	*BUNK COOLER NOT BLOWING COLD AIR	completed by TP replace	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	*ABS LEAD BROKE. NEED REPLACING	completed by TP completed	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Front Diff leaking Oil.	completed by TP inspect ok	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Bunk Cooler blowing Hot Air.	completed by TP inspected OK	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Power dividor leak	completed by TP remove/replace	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Feet bush's n/s	completed by JS Travel to site at Foundation road, Truganina (Labour Charge) 30mins $77.40	25/04/2026	459344	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
		Chassis\SUZI COIL	Remove and replace damaged suzie coils (labour Charge) 1hr $155.00								
1073	Wodonga - Workshop	WW133432	x1 Long tail suzie coils Customer Reports Trailer Light Faults Suspected Trailer Light Faults Travel From Callaway WorkshopsTo Supplier Collect New Electrical Suzie Coil Travel Onto Site Mickleham (Labour Charge)1.5Hrs $232.50	17/04/2026	445467	Completed	Wodonga	LHB	XW07GY	CALLAWAY DIESEL	P/MOVER
1073	Wodonga - Workshop	Elect\SUZI COIL	Fit New electrical Suzie coil test Lights All Ok BREAKDOWN CALLED OUT TO VICTORIA ST RE-WIRE 7 PIN PLUG CHECK LIGHTS - OK RETURN TO WORKSHOP	17/04/2026	455582	Completed	Wodonga	LHB	XW07GY	CALLAWAY DIESEL	P/MOVER
1073	Wodonga - Workshop	Elect\TRL LIGHTS	WORKSHOP MATERIALS / EPA	17/04/2026	445467	Completed	Wodonga	LHB	XW07GY	G & S DIESEL SERVICE	P/MOVER
1073	Wodonga - Workshop	Tyres\ROTATION 1-2	SWAP RIMS & ROTATE TYRES completed at 421,752	13/04/2026	446704	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	VehService\AS A Service	SMc,TP	05/03/2026	422090	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Torque rod bush's worn needs replacing	Previously completed	04/03/2026	421743	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	drive shock bush's u/s	Previously completed	04/03/2026	421743	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Tyres\Punct POS 12	CALL OUT	31/01/2026	405556	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	VehService\AS A Service	SMc	28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Drive shock bushes		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
		Brake lights n/s									
1073	Wodonga - Workshop	Reverse lights n/s		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Shroud guard n/s		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Horton low		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	*AIR HORN DOESN'T WORK		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	ALT LIGHT COMING ON. VOLTS DROPPING.		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	BLINKERS ON TRUCK N/W.		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Need A Service A Service Due/ Over Due	SMc	28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	rear brakes need replacing		28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Radiator using coolant.	Checked by Shane Old Serial: P1002260-S00030198 New Serial: P1002260-S00036020 Check gaurdian not working. Check power, earth & ignition to unit. Try to connect laptop but wouldn't connect. Try to re-flash software but wouldn't accept. Diagnose faulty unit. Found another unit removed from another truck. Setup and run through tests but seat vibrator not working. Try another seat vibrator but still wouldn't work. Try another unit and run through setup and passed and worked. Call Gaurdian	28/01/2026	400564	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	DrCabElect\GPS GUARDIAN N/W	support to confirm all working. Re-assemble vehicle.	23/01/2026	400090	Completed	Wodonga	LHB	XW07GY	ARKON AUTO ELECTRICAL	P/MOVER
1073	Wodonga - Workshop	Check & Test Batteries Replace If Required	Started Truck, tilted over cabin, removed battery box lid, checked battery charge rate at batteries & at alternator, charge ra	09/01/2026	391810	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	*ABS LEAD BROKEN PLUG		05/01/2026	388766	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	*AIR LEAK. CAN HEAR BEHIND RIGHT STEER.		05/01/2026	388766	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Check & Repair Air Leak/s		05/01/2026	388766	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Repair/Replace Damaged EBS Lead		05/01/2026	388766	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Tyres\TP1+2		05/01/2026	391794	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	Engine\EXHAUST fix heat shield	pick up truck from tctc and fix heat shield	23/12/2025	383984	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Elect\BREAKDOWN TRAILER PLUG	ATTEND BREAKDOWN ON THE TRCUK SERVICE LANE NORTH BOUND	19/12/2025	381533	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Cooling\AIR FITTIN	REPLACE AIR FILTER AS REQUESTED	18/12/2025	381137	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1073	Wodonga - Workshop	VehService\CS		15/12/2025	382505	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
			REPLACED								
1073	Wodonga - Workshop	DrivLine\DIFF OIL	D.WICKS	15/12/2025	382505	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
		METAL AT FILL PLUG. SUSPECTED FRONT DIFF FAILURE. TCTC INSPECTING									
1073	Wodonga - Workshop		REPAIRED AT TCTC	15/12/2025	382505	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER

			LH WINDSCREEN BROKEN WHEN DRIVER HAD BAG ZIPPER NOT SECURED AND COLOGNE BOTTLE FELL OUT AND BROKE WINDSCREEN. . * Removed locking strip from LH windscreen. * Removed sealant. * Removed old windscreen LH side (Broken). * Cleaned seal up. * Fitted new LH windscreen and secured. * Fitted locking strip and secured. * Applied sealant. * Repair completed. .								
1073	Wodonga - Workshop	Body\WINDSCREEN BROKEN	* TCTC COVERED LABOUR TO R&R, CUSTOMER PAID FOR WINDSCREEN*.	05/12/2025	375963	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1073	Wodonga - Workshop	TURNED HEATER TAPS OFF. COOLANT LEAK.	Labour - Mobile - Breakdown Travelled to site Located and inspected unit	19/11/2025	369657	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Engine\ALT BREAKDOWN	Removed and replaced alternator	17/11/2025	367061	Completed	Wodonga	LHB	XW07GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1073	Wodonga - Workshop	Tyres\TP9+10		15/11/2025	367061	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	Tyres\TP11+12		15/11/2025	367061	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	Tyres\TP5+6		15/11/2025	367061	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	Tyres\TP7+8		15/11/2025	367061	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	Elect\TRL LIGHTS	onsite - Wallan southbound arrive onsite and locate vehicle, inspect trailer for lighting issues, trace wiring and inspect, found wiring in trailer plug to be broken, fix and repair wiring, replace trailer base and test operations (ok) -alternator issue checked over -battery, alternator and isolator terminals cleaned all were filthy or corroded -batteries tested, in ok condition -alternator tested, pulsing slight voltage drop, but still charging as intended	31/10/2025	361263	Completed	Wodonga	LHB	XW07GY	HOT SPARK AUTO ELECTRICAL	P/MOVER
1073	Wodonga - Workshop	driver complained that volt meter was going up and down and Alt light keeps comi	-driver told to monitor fault if it returns to swap alternator under warranty	20/10/2025	349133	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Repair/Replace Damaged Trailer Light Plug Replace Trailer Light Plug Heavy Duty To Standard Duty.	-trailer plug replaced	14/10/2025	346378	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	WW097378		08/10/2025	346354	Completed	Wodonga	LHB	XW07GY	MARULAN TRUCK & BUS PTY LTD	P/MOVER
1073	Wodonga - Workshop	LIGHTS AND BLINKERS NOT WORKING PROPERLY. PROBLEM IN TRUCK PLUG/ CABI		29/08/2025	329503	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	-BLINKERS ON TRAILER NOT WORKING AS SUSI COIL ELECTRICS CABLES BROKEN.		29/08/2025	329503	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
			TOPPED UP COOLANT ADJUSTED CLUTCH REPLACED DIFF OILS								
1073	Wodonga - Workshop	VehService\BS B Service		27/08/2025	328201	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils		27/08/2025	328201	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	TATIARA TRUCK & TRAILER- BREAKDOWN. DIAGNOSE AND REPAIR TRAILER INDICA		15/08/2025	479915	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Tyres\RUN OUT POS 10		12/08/2025	319286	Completed	Wodonga	LHB	XW07GY	BORDER BANDAG PTY LTD	P/MOVER
1073	Wodonga - Workshop	Elect\SUZI COIL BREAKDOWN REMOVE & REPLACE SUZI COILS		11/08/2025	320404	Completed	Wodonga	LHB	XW07GY	WARREGO TRANSPORT REPAIRS	P/MOVER
1073	Wodonga - Workshop	JRB DIESEL BOTANY- REPAIR TRAILER LIGHTS NOT WORKING.		01/08/2025	371302	Completed	Wodonga	LHB	XW07GY	JRB DIESEL	P/MOVER
1073	Wodonga - Workshop	REPLACE TRAILER PLUG.		29/07/2025	310190	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Elect\HOUSEKEEP replace trailer plug		29/07/2025	310190	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Engine\ALT light intermittently flashing on / off	Loose terminal on back of alternator	26/06/2025	290536	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS A Service		26/06/2025	290536	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS A Service		04/06/2025	280118	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Jump start truck		02/06/2025	279449	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Tyres\TP1+2		06/05/2025	265781	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
1073	Wodonga - Workshop	Elect\BRK LIGHT Brake light issues *Trailer plug ?? related *Press brake & turns LH rev light on Onsite @ GF @ Tyre bay Traveled onsite to Greenfreight Wodonga. Locate truck and test trailer lights. Found LH indiactor bought reverse lights on. No brake lights and no RH indicator. Checked trailer plug on truck side. Found blown fuse for brake lights caused by wire being pinched in trailer socket. Found LH indicator was in pin 2, put in pin 1 and tested LH indicator now works. Found rh indicator was in pin 5 changed to pin 4 and tested. Lights now work.		02/05/2025	264871	Completed	Wodonga	LHB	XW07GY	ARKON AUTO ELECTRICAL	P/MOVER
1073	Wodonga - Workshop	Brakes\BRK RELINE REPORTS DRIVE BRAKES LOW . * Inspected & confirmed drive brakes to be low * Ballast truck & removed wheel end equipment * Removed drum & hub assemblies * Removed & replaced brake shoes * Inspected bearings - All ok * Refit hub assemblies * Replaced brake drums * Refit wheel end equipment * Aligned, adjusted & tensioned all components * Test operations - All ok, no further faults AFTER CARRYING OUT RELINE, CARRIED OUT BRAKE TEST		01/05/2025	264408	Completed	Wodonga	LHB	XW07GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1073	Wodonga - Workshop	Engine\OIL LEAK REPORTS FRONT END OF ENGINE LEAKING OIL . * Hoisted truck & thoroughly cleaned down engine * Test drove truck * Inspected engine & unable to locate any further leaks * Tightened all bolts * Greenfreight reported oil filler cap left off		01/05/2025	264408	Completed	Wodonga	LHB	XW07GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1073	Wodonga - Workshop	* No further faults		01/05/2025	264408	Completed	Wodonga	LHB	XW07GY	PACCAR PARTS FLEET SERVICES	P/MOVER
1073	Wodonga - Workshop	VehService\BS		30/04/2025	263869	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months	Truck sent to TCTC for warranty repairs of drive brakes, Front diff reseal and engine oil leaks	14/04/2025	256915	Unlocked	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS A Service		14/04/2025	256915	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER

1073	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils	REPLACED OILS AS FRONT DIFF WAS RESEALED	14/04/2025	256915	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS A Service	Brake measurements checked by jaimon peters	01/04/2025	242938	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS		01/03/2025	229880	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Turbo timer Not working.		01/03/2025	229880	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Left front drive shocker covered in oil.	Warranty	07/02/2025	221295	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS		07/02/2025	221295	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Light plug broken.		07/02/2025	221295	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Bunk cooler not getting proper cold.	Blowing cool sir, not getting cold as set temp.	31/01/2025	217715	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
		Right windscreen broken									
1073	Wodonga - Workshop	Autoscreen		24/01/2025	214730	Completed	Wodonga	LHB	XW07GY	AUTOTEK AUSTRALIA	P/MOVER
1073	Wodonga - Workshop	VehService\AS		21/01/2025	212353	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Bunk cooler not cooling all the time	Turn on inspect gets cold and runs fine	20/01/2025	212352	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	alternator light flashing a few times	Drove around yard no light	20/01/2025	212352	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	check left front drive shock	Inspect not lose or leaking	20/01/2025	212352	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Wheel Alignment. (Hume Truck Technics P/O: WW091070)		17/12/2024	202549	Completed	Wodonga	LHB	XW07GY	HUME TRUCK TECHNICS	P/MOVER
1073	Wodonga - Workshop	BUNK AIRCON NOT GETTING COLD.	Shaun replaced air filter, checked gas pressures and tested. All ok.	17/12/2024	202546	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	SLOW TO ACCELERATE LOW ENGINE POWER	Cummin completed worked under warranty	17/12/2024	202546	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	LOW POWER.	Cummin completed worked under warranty	17/12/2024	202546	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	slow to accelerate low pulling power	Cummin completed worked under warranty	17/12/2024	202546	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
		C Service. (TCTC P/O: WW090849)									
1073	Wodonga - Workshop	Serviced @ 202505 Klms		14/12/2024	202505	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
		VehService\BS									
1073	Wodonga - Workshop	Serviced @ 200236 Klms		02/12/2024	200236	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS		02/12/2024	200236	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Replace Damaged Suzie Leads. (Elite Diesel's P/O: WW090388)		26/11/2024	361263	Completed	Wodonga	LHB	XW07GY	VAWDREY AUSTRALIA PTY LTD	P/MOVER
			Remove relay cover in top of dash. Drill hole next to the existing accessory socket and mount a new one. Run wiring from new socket over to the fuse panel. Wire in an inline fuse holder. Tap into the main earth wire behind the dash and pick up power at the fuse panel. Test ok. Refit all panels and carry out final tests								
1073	Wodonga - Workshop	FIT POWER SUPPLY IN DASH. (Arkon Auto Electrical P/O: WW090053)	and checks. Ok.	05/11/2024	182416	Completed	Wodonga	LHB	XW07GY	ARKON AUTO ELECTRICAL	P/MOVER
		A Service. (TCTC P/O: WW089894)									
1073	Wodonga - Workshop	Serviced @ 182419 Klms		01/11/2024	182374	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1073	Wodonga - Workshop	A SERVICE.		01/11/2024	182374	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1073	Wodonga - Workshop	STABILITY CONTROL TOO SENSITIVE	Unable to fault, Adjusted parameters, Driver to monitor.	01/11/2024	182374	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1073	Wodonga - Workshop	Left cupboard coming off wall	Loose screw tightened	01/11/2024	182374	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1073	Wodonga - Workshop	A SERVICE		01/11/2024	182374	Completed	Wodonga	LHB	XW07GY	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1073	Wodonga - Workshop	Tyres\PRES CHECK 1-10		23/10/2024	177784	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
1073	Wodonga - Workshop	Tyres\TP07		23/10/2024	177784	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
			Job allocated to tablet after it was completed can't start timer								
1073	Wodonga - Workshop	Adjust Ride Height.	Roughly 30 minutes	19/10/2024	175516	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS		14/10/2024	171222	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	VehService\AS	148500ks	04/09/2024	148935	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Tyres\TP9+10		26/08/2024	145439	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
1073	Wodonga - Workshop	Tyres\TP3+4		26/08/2024	145439	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
1073	Wodonga - Workshop	Tyres\TP5+6		26/08/2024	145439	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
1073	Wodonga - Workshop	Tyres\TP7+8		26/08/2024	145439	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
1073	Wodonga - Workshop	Tyres\TP01		19/08/2024	140573	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
		B Service									
1073	Wodonga - Workshop	Serviced @ 140491 Klms	140491ks	17/08/2024	140492	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils		17/08/2024	140492	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Tyres\TP1+2		01/08/2024	132023	Completed	Wodonga	LHB	XW07GY	BEAUREPAIRES	P/MOVER
		CUSTOMER REPORTS CLUTCH LINKAGE FAULT - 27/07/2024									
		.									
		* Inpsected all components									
		* Test clutch operations - unable to fault									
		* Unbolted & removed inspection cover									
		* Inspected internals & found no signs of damage present									
		* Further inspected truck & found steer tyre had previously blown & damaged inner guard, causing loose bolt to rattle									
		* Removed bracket & test operations									
1073	Wodonga - Workshop	* Found no further faults present		30/07/2024	132023	Completed	Wodonga	LHB	XW07GY	PACCAR PARTS FLEET SERVICES	P/MOVER
		Broken Air Line At Suzie Lines Elite Diesel P/O: WW086827									
1073	Wodonga - Workshop			19/06/2024	107141	Completed	Wodonga	LHB	XW07GY	VAWDREY AUSTRALIA PTY LTD	P/MOVER
1073	Wodonga - Workshop	B Service As Per Attached Checklist		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	TRUCK AIRCON CUTS IN AND OUT. NOT VERY COLD.		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	BUNK COOLER NOT WORKING.		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	FIT FIRE EXTINGUISHER.		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	REPLACE FIRST AID KIT.		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
		NO POWER. VERY SLOW TO TAKE OFF. WON'T PULL.									
		DIAGNOSED TURBO REQUIRES REPLACEMENT. CUMMINS TO REPAIR UNDER									
1073	Wodonga - Workshop	WARRANTY.		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	THROUGH-SHAFT SEAL LEAKING (WARRANTY)		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Record Check Results As Attached To This Job		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils		27/04/2024	73807	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	FIT FIRE EXTINGUISHER.		10/04/2024	62888	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	REPLACE FIRST AID KIT.		10/04/2024	62888	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	A Service As Per Attached Checklist		10/04/2024	62888	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Record Check Results As Attached To This Job		10/04/2024	62888	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	NO POWER. VERY SLOW TO TAKE OFF. WON'T PULL.	INSPECTED. WASTE GATE ACTUATOR ARM OK. FOUND TURBO IMPELLER TIGHT WITH EXCESSIVE END FLOAT. ADDED 12L ENGINE OIL.	23/03/2024	52858	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	A Service As Per Attached Checklist	CLEANED DIFF BREATHER.	22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	THROUGH-SHAFT SEAL LEAKING (WARRANTY)		22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	ADBLUE LIGHT HAS COME ON COUPLE OF TIMES.	NO CODES.	22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	TRUCK AIRCON CUTS IN AND OUT. NOT VERY COLD.		22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	BUNK COOLER NOT WORKING.		22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	FRONT WHEEL ALIGNMENT.		22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	NO POWER. VERY SLOW TO TAKE OFF. WON'T PULL.		22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Record Check Results As Attached To This Job		22/03/2024	52865	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	FIRST SERVICE.		03/02/2024	21508	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	A Service As Per Attached Checklist	relocate oil filler tube (RHS) hitting cabin as it lifted	03/02/2024	21508	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Record Check Results As Attached To This Job		03/02/2024	21508	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	A Service As Per Attached Checklist		03/02/2024	21508	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	FRONT RIGHT HUB OIL LEAK.		03/02/2024	21508	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER

1073	Wodonga - Workshop	Record Check Results As Attached To This Job		03/02/2024	21508	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	PICKUP TCTC.		13/01/2024	9629	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	ADJUST CLUTCH BRAKE.		10/01/2024	9593	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	bunk cooler not working		10/01/2024	9593	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	wheel alignment		10/01/2024	9593	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	low power		10/01/2024	9593	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Record Check Results As Attached To This Job		10/01/2024	9593	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
			* Removed/replaced engine filter & oil, specification used in parts section below. * Check all engine operation & components * Removed/replaced transmission oil filter * Check all hydraulic lines fitting & level lubricant levels to specification * Removed/replaced power steering filter & gasket * Removed/replaced differential oil, specification used in parts section below. * Removed/replaced fuel filter * Check cooling system & pressure test * Check all belts, idler pulleys, fan, shrouds & adjust to specification * Check all electrical routing, wiring looms, switches, sensors & components * Check all wheel equipment & steering components * Check all braking & adjust to specification * Check clutching & adjust to specification * Check all suspension components * Check all internal cabin operation, components & adjust to specification * Check all external cabin components & adjust to specification * Check windscreen washers, wipers, refill & test operation * Lubricate, adjust relevant components as required * Re torque all fitting & fixtures * Wash vehicle complete							
1073	Wodonga - Workshop	1st Service As Per Attached Checklist	* Road test, confirm & quality check	10/01/2024	9593	Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER
1073	Wodonga - Workshop	Truck Pre-delivery		16/12/2023		Completed	Wodonga	LHB	XW07GY	Wodonga Workshop	P/MOVER