EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
1063	Wodonga - Workshop	Engine\FAULT CODE AFTER TREATEMENT CODE FAULT	Vehicle came in with complaint of low power issue. To be checked over see what issue could be When vehicle arrived, check over vehicle, couldn't find any noticable issues. When turned IGN key on found only check and stop eng lights on dash illuminating aftertreatment light not lighting up. Plug in laptop and found fault code for aftertreatment, Code 1887. Rang and advised and decision made that truck would be driven to sydney to be repaired.	31/07/2026	819695	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	fitted new wiper blades		18/07/2026	816109	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	DIAGNOSE AND REPORT ON OIL LEAK AT DIFFS		17/07/2026	817028	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	5th wheel handle bent VehService\AS A Service	DIAGNOSE TURNTABLE FAULT FOUND TURNTABLE HANDLE BENT R&R TURNTABLE HANDLE & ADJUST MOVEMENT	01/07/2026	804468	Completed	Wodonga	HCU	XV13YL	G & S DIESEL SERVICE	P/MOVER
1063	Wodonga - Workshop	WW134409		26/06/2026	794817	Completed	Wodonga	HCU	XV13YL	G & S DIESEL SERVICE	P/MOVER
1063	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils	DEFECT REAR DIFF SEAL WASH 2ND & 3RD AXLE DIFF AREA CHECK 3RD AXLE DIFF YOKE MOVEMENT EXCESSIVE PINION MOVEMENT REMOVE JACK SHAFT DIFF YOKE & PINION SEAL CHECK PINION BEARING - FOUND COLLAPSED REMOVE COMPLETE DIFF CENTRE REPLACE WITH EXCHANGE DIFF ASSY RE-FIT DIFF ASSY & REPLACE GEAR OIL REPLACE 1ST AXLE GEAR OIL CARRY OUT A-SERVICE REPAIRS DEFECT ALL 4X WHEEL BEARINGS EXCESSIVELY LOOSE 2ND AXLE L/H SIDE HAS BLOWN HUB SEAL ADJUST 3X WHEEL BEARINGS REMOVE HUB ON 2ND AXLE L/H SIDE REPLACE SHOE SET REPLACE DRUM REPLACE HUB SEAL REFIT HUB & ADJUST TO PEC CARRY OUT BRAKE TEST TEST DRIVE VEHICLE This is the diff that failed in Sydney, Unit 1063	26/06/2026	794817	Completed	Wodonga	HCU	XV13YL	G & S DIESEL SERVICE	P/MOVER
1063	Wodonga - Workshop	DIFF FAILURE DIAGNOSED DURING BREAKDOWN OIL LEAK FROM REAR DIFF PINION AT G & S DIESEL	During repair they found a hub seal blown, diff input yoke unserviceable and all drive bearings out of adjustment. We asked them to service the other diff as well with dynadrive oil so that they're all up to date. DEFECT REAR DIFF SEAL WASH 2ND & 3RD AXLE DIFF AREA CHECK 3RD AXLE DIFF YOKE MOVEMENT EXCESSIVE PINION MOVEMENT REMOVE JACK SHAFT DIFF YOKE & PINION SEAL CHECK PINION BEARING - FOUND COLLAPSED REMOVE COMPLETE DIFF CENTRE REPLACE WITH EXCHANGE DIFF ASSY RE-FIT DIFF ASSY & REPLACE GEAR OIL REPLACE 1ST AXLE GEAR OIL CARRY OUT A-SERVICE REPAIRS DEFECT ALL 4X WHEEL BEARINGS EXCESSIVELY LOOSE 2ND AXLE L/H SIDE HAS BLOWN HUB SEAL ADJUST 3X WHEEL BEARINGS REMOVE HUB ON 2ND AXLE L/H SIDE REPLACE SHOE SET REPLACE DRUM REPLACE HUB SEAL REFIT HUB & ADJUST TO PEC CARRY OUT BRAKE TEST TEST DRIVE VEHICLE This is the diff that failed in Sydney, Unit 1063	24/06/2026	801083	Completed	Wodonga	HCU	XV13YL	G & S DIESEL SERVICE	P/MOVER
1063	Wodonga - Workshop	Rear input shaft seal leaking	During repair they found a hub seal blown, diff input yoke unserviceable and all drive bearings out of adjustment. We asked them to service the other diff as well with dynadrive oil so that they're all up to date. 25/05 Labour- Mobile Travelled to Yatala Mounted and wired reverse squawker	24/06/2026	801083	Completed	Wodonga	HCU	XV13YL	G & S DIESEL SERVICE	P/MOVER
1063	Wodonga - Workshop	Elect\ELECT P&W	Checked operation	09/06/2026	794017	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	repaired loose steering column	completed by SMc	01/06/2026	784031	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	repaired tr plug for b strailer		01/06/2026	784031	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	replaced drivers seat	completed by SMc	01/06/2026	784031	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months		12/05/2026	779230	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	Rr drive slack adjuster not auto adjusting, rl drive slack adjuster missing small pin	REPLACED	12/05/2026	779230	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	Dash light's for cruise control, mirror heat + engine brake Not Working.	REPLACED GLOBES	12/05/2026	779230	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	Centre roof light out	REPLACED	12/05/2026	779230	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	steering lock cable needs replacing		12/05/2026	779230	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	Steering unis n/s VehService\AS A Service	OK	12/05/2026	779230	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	WW133752		12/05/2026	779230	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	Check For Air Leaks & Repair	Labour-Mobile TravelledtoYatala Inspectedair leakwithtruck Foundairdrierfilterdamagedfromtrailer Calledforparts Waitedforpartsguytoarriveandopenup Collectedpart Removedoldfilterfittednewone	24/04/2026	769610	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Body\AIR LEAK	Nomoreairleakspresent	06/04/2026	759247	Completed	Wodonga	HCU	XV13YL	WARREGO TRANSPORT	P/MOVER
1063	Wodonga - Workshop	Tyres\TP9+10		21/03/2026	755821	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY L	P/MOVER
1063	Wodonga - Workshop	Tyres\TP5+6		21/03/2026	755821	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY L	P/MOVER
1063	Wodonga - Workshop	Tyres\TP11+12		21/03/2026	755821	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY L	P/MOVER
1063	Wodonga - Workshop	Tyres\TP7+8		21/03/2026	755821	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY L	P/MOVER
1063	Wodonga - Workshop	Tyres\TP1+2		04/03/2026	748991	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY L	P/MOVER
1063	Wodonga - Workshop	VehService\BS B Service	1hr	28/02/2026	741926	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Tyres\ROTATION POS 1-2 A Service		24/01/2026	726320	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY L	P/MOVER
1063	Wodonga - Workshop	Serviced @ 707,044 Klms		13/12/2025	703027	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Alternator Light Flickering On & Off, Volt Meter Staying Steady	Removed Steer Wheels and replaced leaking Wheel Seals, Brakes and Drums.	04/12/2025	701924	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Brakes\BRK RELINE		25/11/2025	698091	Completed	Wodonga	HCU	XV13YL	ADELAIDE TRUCK CENT	P/MOVER
1063	Wodonga - Workshop	Splitter Not Working Properly Not Very Safe When Changing - Won't Rev Up After Selecting Direct To Go Into Gear A Service	Job Previously Completed	22/11/2025	695310	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Serviced @ 691,291 Klms C Service. Serviced @ 679,600 Klms		22/11/2025	695310	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Diff Oil Change		01/11/2025	683678	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Changed @ 679,600 Klms Trans Oil Change		01/11/2025	683678	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Changed @ 679,600 Klms		01/11/2025	683678	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Jump Start & Check Batteries		01/11/2025	683678	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Replace Combination Switch		09/10/2025	670072	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS A Service		06/10/2025	667598	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER

1063	Wodonga - Workshop	Replace Leaking Drive Hub L/H Front Drive.		06/10/2025	667598	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	REPLACE WIPER BLADES		04/09/2025	652629	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
		Flat Batteries, Check & Test Batteries Replace f Required.									
1063	Wodonga - Workshop	(G&S Diesels P/O: WW096804)		02/09/2025	720324	Completed	Wodonga	HCU	XV13YL	G & S DIESEL SERVICE	P/MOVER
1063	Wodonga - Workshop	Tyres\TP9+10		15/08/2025	650066	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY I	P/MOVER
1063	Wodonga - Workshop	Tyres\TP11+12		15/08/2025	650066	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY I	P/MOVER
1063	Wodonga - Workshop	Tyres\TP7+8		15/08/2025	650066	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY I	P/MOVER
1063	Wodonga - Workshop	Tyres\TP5+6		15/08/2025	650066	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY I	P/MOVER
1063	Wodonga - Workshop	REPLACE RF RR AXLE GASKETS.		13/08/2025	650607	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS A Service		19/07/2025	655242	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			4HRS LABOUR (TIME & 1/2) AFTER HOURS $1,128.00								
			CALL OUT FEE $215.00								
			FLEET #1063								
			TRAVEL TO YENNORA CDM YARD								
			JUMP START VEHICLE								
			CHECKED CHARGE RATE								
			RECOMMEND SPARKY TO CHECK SYSTEM CHARGE RATE FLUCUATING & LOW								
1063	Wodonga - Workshop	UNKNOWN ELECTRICAL FAULT. DRAINS BATTERIES OVER NIGHT. VOLTAGE VARIES BETWEEN 11→8.5V.	TRAVEL BACK TO WORKSHOP	19/07/2025	655242	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Truck sluggish to start or needs a jump start after weekend with everything off.	-couldnt fault batteries, needs to be left in workshop longer for further testing.	19/07/2025	655242	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
		Engine\BOOST LEAK									
		CUSTOMER REPORTS COULD HEAR BOOST LEAK									
		-									
		* Test operations & confirmed fault									
		* Inspected & found boost hose off turbo damaged & worn at both ends									
		* Removed & replaced boost hose as required									
		* Replaced clamps									
1063	Wodonga - Workshop	* Test operations - All ok, fault no longer presen		03/07/2025	620934	Completed	Wodonga	HCU	XV13YL	PACCAR PARTS FLEET S	P/MOVER
1063	Wodonga - Workshop	VehService\AS A Service (TCTC PO#WW095239)		03/07/2025	613517	Completed	Wodonga	HCU	XV13YL	PACCAR PARTS FLEET S	P/MOVER
1063	Wodonga - Workshop	Tyres\TP1+2		19/06/2025	611658	Completed	Wodonga	HCU	XV13YL	BORDER BANDAG PTY I	P/MOVER
1063	Wodonga - Workshop	OVERDUE FOR B SERVICE		14/06/2025	608126	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\BS B Service		14/06/2025	608126	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	DrCabElect\HOUSEKEEP Fit anderson plug to back of passenger seat	-live anderson plug mounted to passenger seat	14/06/2025	608126	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			-coolaba A/C system tested and checked over, working as intended								
			-no fault with dash lights								
1063	Wodonga - Workshop	DASH LIGHTS FLICKER (UP/ DOWN IN BRIGHTNESS) WHILE DRIVING.	-slight issue with volume knob on radio, skips volum up and down while rotating	16/05/2025	587593	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS A Service		16/05/2025	587593	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	BUNK COOLER NOT CHARGING PROPERLY (10 HOURS DRIVING-1 VOLT)		16/05/2025	587593	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			Found broken return spring on side of gearbox. Replaced.								
1063	Wodonga - Workshop	Inspect and adjust clutch	Moved truck onto pit and inspected clutch. Found clutch pack adjuster wasn't locked in and had backed off the adjustment. Adjusted clutch and took for a test drive to confirm repair	10/05/2025	588235	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	NO TURN SIGNALS ON TRAILERS.	CLEANED HEAVY DUTY PLUG OF GREASE. RESET FUSE. OK.	29/04/2025	581391	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS A Service		24/04/2025	578496	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Front Drive Will Require Brake Reline Next Service	RELINED LF RF RR DRIVES. REPLACED HUB SEALS AND BEARINGS RF RR.	24/04/2025	574863	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Oil leak around front diff	Front Diff Has A Slight Weep Not A Leak	29/03/2025	564984	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Front diff rear thru shaft seal leaking	Thru Shaft Seal Weeping Not Leaking	29/03/2025	564984	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
		A Service.									
1063	Wodonga - Workshop	Serviced @ 560965 Klms		29/03/2025	564984	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Front RHS drive axle leaking oil	Found axle bolts were loose and the gasket has been completely blown out. Fitted new gasket and checked oil level. Hub fill bung is also damaged. Parts ordered	27/03/2025	562738	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			BENT BRACKET STRAIGHT THAT WAS IMPACTING.								
1063	Wodonga - Workshop	MARULAN TRUCK & BUS- DIAGNOSE AND REPAIR AIR LEAK IN CHASSIS RAIL.	NO CHARGE.	19/03/2025	558205	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Insp\ANN INSP		08/03/2025	552365	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	RHR drive blown hub seal	Disassembled by Ethan Capelleveen and completed by Blair Boswell	08/03/2025	552365	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Engine brake dash globe blown	Replaced blown globe	08/03/2025	552365	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	LHR Drive brake booster leaking	Replaced leaking booster. Completed by Jaimon Peters and Ethan Capelleveen	08/03/2025	552365	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS		08/03/2025	552365	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Steering\WHEEL SEAL CHECK REAR HUB SEAL	Checked ok driver to monitor	22/02/2025	543921	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\BS	539903km	22/02/2025	543921	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Chassis\SKID PLATE / CHECK WALK PLATE		07/02/2025	530527	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ESC light is on , on dash		07/02/2025	530527	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Bunk cooler turns off after less than 6 hours with flat battery	Shaun spoke with driver	07/02/2025	530527	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			TRUCK COMPLAINT - SLOW TO BUILD AIR								
			CHECK COMPRESSOR OUTPUT								
			CHECK SOFT LINE FROM COMPRESSOR TO AIR DRYER								
			CHECK AIR DRYER								
			CHECK COMPRESSOR GOVERNOR VALVE								
			CHECK COMPRESSOR UNLOADER VALVE & FIND ITS STUCK								
			REPLACE COMPRESSOR & SOFT LINE TO AIR DRYER								
			REPLACE AIR DRYER FILTER								
		G & S DIESEL	TEST NEW COMPRESSOR								
1063	Wodonga - Workshop	REPLACE COMPRESSOR.	TEST DRIVE TRUCK	07/02/2025	721117	Completed	Wodonga	HCU	XV13YL	G & S DIESEL SERVICE	P/MOVER
1063	Wodonga - Workshop	VehService\AS	Top up coolant replace cap as not sealing	31/01/2025	530915	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Tyres\TP7+8		22/01/2025	525715	Completed	Wodonga	HCU	XV13YL	BEAUREPAIRES	P/MOVER
1063	Wodonga - Workshop	Tyres\TP9+10		22/01/2025	525715	Completed	Wodonga	HCU	XV13YL	BEAUREPAIRES	P/MOVER
1063	Wodonga - Workshop	Tyres\TP3+4		22/01/2025	525715	Completed	Wodonga	HCU	XV13YL	BEAUREPAIRES	P/MOVER
1063	Wodonga - Workshop	Tyres\TP1+2		22/01/2025	525715	Completed	Wodonga	HCU	XV13YL	BEAUREPAIRES	P/MOVER
1063	Wodonga - Workshop	Tyres\TP5+6		22/01/2025	525715	Completed	Wodonga	HCU	XV13YL	BEAUREPAIRES	P/MOVER
1063	Wodonga - Workshop	Power Socket Not Working.	Checked fuse's, found blown fuse replaced, tested circuit & checked for any shorts, refitted all panels, sent truck back to work.	21/01/2025	524244	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	front diff leak	Through shaft slight leak check warranty	11/01/2025	519743	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			505600ks								
			Check on warranty status								
			Left rear hub seal gone warranty ?								
1063	Wodonga - Workshop	VehService\AS	No walk plate	11/01/2025	505600	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Reverse buzzer not working	Wzrranty	11/01/2025	519743	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Air horn not working properly	Air Horne was clogged with debris. Washed it out and it works fine	11/01/2025	519743	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS	I	07/12/2024	501935	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Clear Defect. (CMV Wodonga P/O: WW090439)		27/11/2024	519743	Completed	Wodonga	HCU	XV13YL	CMV TRUCK & BUS - W	P/MOVER
1063	Wodonga - Workshop	Jump Start, Check & Test Batteries R Replace Batteries If Required.	JUMP STARTED. TEST DROVE. LOAD TESTED BATTERIES. OK.	18/11/2024	487620	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS		06/11/2024	484618	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS		23/10/2024	476369	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	C Service		23/10/2024	476369	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	DrivLine\DIFF OIL		23/10/2024	476369	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\BS		23/10/2024	476369	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Prevent\TRANS OIL		23/10/2024	476369	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
		Engine\ALT									
1063	Wodonga - Workshop	Light Issue	Alt has been changed	14/10/2024	475367	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS		07/10/2024	471021	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	SERVICE DUE.		21/09/2024	464539	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	VehService\AS	360520ks	21/09/2024	464539	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	INTERIOR CABIN LIGHTS NOT WORKING.		19/08/2024	442056	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	REPLACE LEFT WIPER BLADE RUBBER.	Have been replaced CB. SR	19/08/2024	442056	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Unknown when last serviced windscreen has C service due @ 414000, sticker on seat has B service due @ 436000		19/08/2024	442056	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			Found oil filter very loose and leaking oil.								
1063	Wodonga - Workshop	B Service	Have Tightened this filter more than usual due to possibility of it loosening under vibration	19/08/2024	442056	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	A Service		06/06/2024	399840	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	fit new walk plate		04/06/2024	399840	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	re-line drive brakes	Cody Shane McCabe worked on this job as well	04/06/2024	399840	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Pinion Bearing Needs Adjustment		04/06/2024	399840	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	B Service As Per Attached Checklist		21/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		21/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Drivers Side Seat Belt Needs Replacing		21/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ESC Still Displayed On Dash	OK.	21/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ATC Button Still Lights Up	OK.	21/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		21/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER

1063	Wodonga - Workshop	Tyre Position 1 + 2		09/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	Tyre Position 9 + 10		07/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	Tyre Position 7 + 8		07/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	Tyre Position 5 + 6		07/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	Tyre Position 3 + 4 FOUND LIGHTS ON TRAILER NOT WORKING FOUND LIGHTS ON TRUCK NOT WORKING FOUND SHORT IN WIRING ON A TRAILER REPAIR AS REQUIRED CARRY OUT RESET PROCEDURE FOR TRUCK MODULE		07/04/2024	372298	Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	CHECK OPERATION OK TRAVEL TO DEPOT REVERSE LIGHTS NOT WORKING ON TRUCK OR TRAILERS FOUND BUSTED LIGHTS ON TRAILERS REPLACE LIGHTS AS REQUIRED RESET BREAKER IN TRUCK		17/03/2024		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	OPERATION OK		17/03/2024		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	A Service As Per Attached Checklist		17/03/2024	350500	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC STILL LIGHTING UP. ESC IS ALSO DISPLAYED ON DASH.		17/03/2024	350500	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC & ESC displayed on dash		17/03/2024	350500	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		17/03/2024	350500	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ESC LIGHT ON.	no faults found	17/03/2024	350500	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	RELINE LR.	3mm untill at wear limit	17/03/2024	350500	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		17/03/2024	350500	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		03/03/2024	342016	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ESC LIGHT ON.		03/03/2024	342016	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	RELINE LR.		03/03/2024	342016	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	OVERDUE FOR A SERVICE.		03/03/2024	342016	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	A Service As Per Attached Checklist		03/03/2024	342016	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		03/03/2024	342016	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	FIT SUPPLIED BATTERIES		20/02/2024		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	bunk cooler not working	Investigate reported fault code E04. Found condenser fan had failed causing high gas pressure code (E04) . Remove rear condenser cover and change out condenser fan .Reassemble and test unit. OK.	14/02/2024		Completed	Wodonga	HCU	XV13YL	HUME TRUCK TECHNIC	P/MOVER	
1063	Wodonga - Workshop	BUNK COOLER NEEDS REPAIR. SHOWING CODE E04 ON PANEL. MAIN OUTSIDE BOX IS SHOWING UP RED IN COLOUR.	Replace blocked cabin filter Condenser fan = no charge, part	14/02/2024		Completed	Wodonga	HCU	XV13YL	HUME TRUCK TECHNIC	P/MOVER	
1063	Wodonga - Workshop	A Service As Per Attached Checklist		13/02/2024	332486	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC & ESC displayed on dash		13/02/2024	332486	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		13/02/2024	332486	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Adjust Clutch Brake & Free Travel		12/01/2024	314576	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	wheel alignment	Perform laser wheel alignment	08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	atc button stays on, esc still displayson dash		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	FRONT LEFT SIDE WINDSCREEN CRACKED UP TOP NEAR MIDDLE. NEEDS REPLACING.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	BUNK COOLER NEEDS SERVICING.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL STAYS LIT UP. ESC STILL STAYS ON DASH.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	REAR AIR, FUEL AND AXLE OIL GUAGES NEEDS NEW GLOBES IAP TABLET NOT CHARGING		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	CHECK FOR CONNECTION / FUSE. IAP NOT WORKING		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STAYS ON ALSO ESC STAYS ON DASH		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC Button still lights up. ESC button still displayed on dash and stays on.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	WIPER BLADES NEED REPLACING.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ENGINE RETARTER NOT SHOWING ON DASH.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ESC STILL DISPLAYS ON DASH. BUTTON STILL LIGHT UP AND STAYS ON.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	PARK BRAKE RETURN VALVE LEAKING AIR.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON ESC STILL STAYS ON DISPLAYED ON DASH.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	PARK BRAKE RETURN VALVE LEAKING AIR.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	SWITCH FOR OUTSIDE MIRRORS NEEDS REPLACING.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP. ESC STILL DISPLAYS ON DASH. DRIVER'S SEAT NEEDS TO BE REPLACED DUE TO MUCH LEAN TO THE LEFT.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Check and advise. DRIVER'S SEAT NEEDS TO BE REPLACED DUE TO MUCH LEAN TO THE LEFT.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP. ALSO ESC STILL DISPLAYS ON THE DASH AND STAYS ON.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	BLINKERS ON TRAILER TRIPPED OUT.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	LOST INDICATORS ON BOTH TRAILERS.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP ALSO ESC DISPLAYED ON DASH.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC LIGHTS UP. ESC STILL DISPLAYING ON DASH. NEED NEW R&R BOOK.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	C Service As Per Attached Checklist		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP. ESC ALSO DISPLAYS ON DASH.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP AND ESC STILL SHOWS UP ON DASH. ATC BUTTON LIGHT UP & STAYS UP.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ESC STILL SHOWING UP ON DASH.		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		08/01/2024	314524	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Adju.st Clucth Brake.		05/12/2023	294731	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Replaced Transmission Oil Pressure Switch		05/12/2023	294731	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Perform laser wheel alignment		11/10/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	A Service As Per Attached Checklist		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	WIPER BLADES NEED REPLACING.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ENGINE RETARTER NOT SHOWING ON DASH.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ESC STILL DISPLAYS ON DASH. BUTTON STILL LIGHT UP AND STAYS ON.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	PARK BRAKE RETURN VALVE LEAKING AIR.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON ESC STILL STAYS ON DISPLAYED ON DASH.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	PARK BRAKE RETURN VALVE LEAKING AIR.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	SWITCH FOR OUTSIDE MIRRORS NEEDS REPLACING.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP. ESC STILL DISPLAYS ON DASH.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	DRIVER'S SEAT NEEDS TO BE REPLACED DUE TO MUCH LEAN TO THE LEFT.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP. ALSO ESC STILL DISPLAYS ON THE DASH AND STAYS ON.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	BLINKERS ON TRAILER TRIPPED OUT.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	LOST INDICATORS ON BOTH TRAILERS.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP ALSO ESC DISPLAYED ON DASH.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC LIGHTS UP. ESC STILL DISPLAYING ON DASH. NEED NEW R&R BOOK.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP. ESC ALSO DISPLAYS ON DASH.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP AND ESC STILL SHOWS UP ON DASH. ATC BUTTON LIGHT UP & STAYS UP.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	ESC STILL SHOWING UP ON DASH.		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		08/10/2023	257665	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER	
1063	Wodonga - Workshop	3-10		03/10/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	Tyre Position 1 + 2		03/10/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Albury - Workshop	IAP NOT WORKING.		29/09/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Albury - Workshop	IAP NOT WORKING.		29/09/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Albury - Workshop	IAP WAS WORKING, NOW NOT CHARGING AT ALL.		29/09/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Albury - Workshop	IAP NOT WORKING AT ALL AS IT WON'T CHARGE DUE TO WIRES BEHIND BEING SQUASHED.		29/09/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Albury - Workshop	IAP NOT WORKING.	*PM 1063 *Tablet not charging *Should be able to fix but need to get another cradle, out of stock here at the moment. Please arrange new cradle. The tablet not charging. Replaced the cradle as cable was squashed.	29/09/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Albury - Workshop	IAP NOT WORKING DUE TO NOT HOLDING UNIT CHARGE.	Tablet now charging and check tracking.	29/09/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	
1063	Wodonga - Workshop	1-2		01/09/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER	

		CHECK INTERMITTEN SHORT FOR TRALIER INDICATOR ON TRUCK AND TRALIER SET FLEET NO ON TRALIERS: A TRALIER T567 B TRALIER T568 CALLOUT AFTER HOURS GOT CALL FROM SHUAN. TRAVEL OUT TO JOB CHECK TRALIERS INDICATORS AND LIGHTS NOT FAULTYING. CHECK AND SHOOK WIRING ON A AND B TRALIER AND TRUCK FOUND EXPOSED EBS WIRING ON A TRALIER BUT COULD NOT FAULT INDICATORS TAPE UP AND SPLIT TUBED EBS WIRING.GOT SHAUN TO TEST DRIVE TRUCK WITH TRALIER SET FOUND INDICATORS FAULT WHEN MOVING. INSPECT TAILLIGHTS ASSEMBLY ON BOTH A AND B TRALIER OK INSPECT CHECK A TO B POLLAK CONNECTOR FOUND POLLACK PLUG CASEING ON A TRALIER AINCING ON B TRALIER SOCKET CHECK POLLAK PLUG FOUND RUB INDICATOR WIRE IN THE SPRING ON THE POLLAK CONNECTOR. REMOVE REPLACE											
1063	Wodonga - Workshop	POLLAK CONNECTOR TEST OK TRAVEL BACK HOME.		27/08/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	WHEN TURNING HEATER ON SMELLS LIKE COOLANT COMING THROUGH.	CHECKED. OK.	27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ATC LIGHTS UP. ESC STILL DISPLAYING ON DASH. NEED NEW R&R BOOK.		27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	RED & YELLOW BUTTON HAS POSSIBLE AIR LEAK. ON FLAT GROUND AFTER 10 MINS OR SO DROPS UNDER 600.	CHECKED. OK.	27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	SUSPECTED HEATER CORE MAYBE LEAKING. EVERY TIME YOU TURN IT ON TO HEAT YOU CAN SMELL COOLANT COMI	CHECKED. OK.	27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP. ESC ALSO DISPLAYS ON DASH.		27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	IF I AM PARKED ON FLAT GROUND FOR 9JHR OR SO DROPS AIR QUICKLY, POSSIBLY A OR B.	NO FAULT FOUND.	27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ATC BUTTON STILL LIGHTS UP AND ESC STILL SHOWS UP ON DASH.		27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	IAP NOT WORKING DUE TO NOT HOLDING UNIT CHARGE. ATC BUTTON LIGHT UP & STAYS UP.		27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ESC STILL SHOWING UP ON DASH.		27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Left front windscreen cracked in the middle. B Service As Per Attached Checklist	REPLACED WINDSCREEN.	27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Oil Sample SIF 42625553		27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		27/08/2023	231602	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	1-2		23/07/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	ATC button wont push in.		03/07/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ESC light up on dash and stays on	Refer job # 413968	03/07/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Seat requires attention. ECS LIGHTS UP. ATC BUTTON ALSO LIGHT UP.		03/07/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRUCK SENT TCTC FOR REPAIRS UNDER WARRANTY.. ECS LIGHTS UP. ATC BUTTON ALSO LIGHT UP. LEFT FRONT WINDSCREEN CRACKED IN THE MIDDLE. (Albury Autoscreen)		03/07/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Purchase Order Number: WW09139. LEFT FRONT WINDSCREEN CRACKED IN THE MIDDLE.		22/06/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			CHECK ALL GAUGES AND WARNING ALARMS check and found warning alarms has been disconnected								
		while returningfrom TCTC speedo and tacho stopped working. Found 10A fuse blown replaced with a 10A breaker (keeps breaking)	and wiring had shorted together, re-connect buzzer plus check all okay check oil pressure light flashing, when I/h flasher on.								
1063	Wodonga - Workshop	Hagans to complete	diagnose faulty I/h warning cluster order new one.	03/06/2023	186136	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Repair Front Diff Oil Leak		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ENGINE BRAKE LIGHT NOT SHOWING ON DASH.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	PLEASE CHECK BRAKES. HAS VERY SQUEALING NOISE EVERY TIME YOU BRAKE.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	WIPERS NEED REPLACING.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	OUTSIDE LIGHTS ON TOP OF MIRROR NEED TIGHTEN UP.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	DRIVER SEAT NEEDS REPLACING AS IT IS EITHER COLLAPSED OR IN WRONG POSITION AS WHEN YOU SIT ON IT, IT HAS		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRUCK DROP AIR OVERNIGHT.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR HORN NOT WORKING PROPERLY.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	PARK BRAKE ALARM NOT WORKING.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ALL INTERIOR LIGHTS STOP WORKING.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	INTERIOR LIGHTS NOT COMING ON WHEN DOOR OPEN.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	CLUTCH NEEDS ADJUSTING.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	MIDDLE STEERING WHELL COVER WHERE THE HORN IS NEEDS REPAIR..		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FOR 5-10 MINUTES EVERY TIME TO BUILD UP AIR.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	INSPECTED PARK BRAKE ALARM NOT WORKING. FUSES GOOD. HORN PLUGGED IN. TCTC TO REPAIR UNDER WARRAN		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		31/05/2023	412331	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ASSISTED BEAUREPAIRES TO FIT DRIVE TYRES.		28/05/2023	183473	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 1 + 2		28/05/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 9 + 10		28/05/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 7 + 8		28/05/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 5 + 6		28/05/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 3 + 4		28/05/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	Pressure Check		02/04/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	A Service As Per Attached Checklist		12/03/2023	134759	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job Seat in need of repairs		12/03/2023	134759	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	To be repaired by TCTC under Warranty.	TCTC could not fault the seat and returned to service.	28/02/2023	412324	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	INSPECTED PARK BRAKE ALARM NOT WORKING. FUSES GOOD. HORN PLUGGED IN. TCTC TO REPAIR UNDER WARRAN		07/02/2023	121845	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	MIDDLE STEERING WHELL COVER WHERE THE HORN IS NEEDS REPAIR..		07/02/2023	121845	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRAILER ABS STILL SHOWING UP ON DASH.	REPLACED FUSE.	07/02/2023	121845	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR RESTRAIN GUAGE NEEDS NEW BULB.	REPLACED MULTIPLE GLOBES.	07/02/2023	121845	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	GEARBOX OUT PUT SHAFT HAS MOVEMENT.		07/02/2023	121845	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	RESEAL FRONT DIFF- UNDER WARRANTY. TCTC TO COMPLETE.		07/02/2023	121845	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		07/02/2023	121845	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	B Service As Per Attached Checklist		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	A Service As Per Attached Checklist		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	MIDDLE STEERING WHELL COVER WHERE THE HORN IS NEEDS REPAIR..		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRAILER ABS STILL SHOWING UP ON DASH.		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR RESTRAIN GUAGE NEEDS NEW BULB.		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	GEARBOX OUT PUT SHAFT HAS MOVEMENT.		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	RESEAL FRONT DIFF.		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FRONT DIFF LEAKING.		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		25/01/2023	116228	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 1 + 2		20/01/2023		Completed	Wodonga	HCU	XV13YL	Albury Workshop	P/MOVER
1063	Wodonga - Workshop	GEARBOX OUT PUT SHAFT HAS MOVEMENT.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	A Service As Per Attached Checklist		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	POSSIBLE AIR LEAK SOMEWHERE. HAVE TO BUILD UP AIR EVEN WHEN YOU STOP ON FLAT GROUND FOR 15 MINS OR		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AFTER TREAT LIGHT COMING ON AND OFF.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR HORN NOT WORKING PROPERLY.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRAILER ABS SHOWING UP ON DASH.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR RESTRAIN GUAGE NEEDS NEW BULB.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	RESEAL FRONT DIFF.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FRONT DIFF LEAKING.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ORDER AND FIT NHVAS STICKER.		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		01/01/2023	103417	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	A SERVICE DUE.		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FIT TRUCKSAFE STICKER.		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	RESEAL FRONT DIFF.		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	A Service As Per Attached Checklist		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRAILER ABS STAYS ON ALL THE TIME.	#398319	11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRAILER ABS LIGHT STILL UP ON DASH AND STAYS LIT UP.	#398319	11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	POSSIBLE AIR LEAK SOMEWHERE. HAVE TO BUILD UP AIR EVEN WHEN YOU STOP ON FLAT GROUND FOR 15 MINS OR		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR HORN NOT WORKING PROPERLY.	#398320	11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AFTER TREAT LIGHT COMING ON AND OFF.		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRAILER ABS COMES UP ON DASH AND STAYS ON.	#398319	11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR HORN NOT WORKING PROPERLY.		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	TRAILER ABS SHOWING UP ON DASH.		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	BRAKES POSSIBLY COOKED DUE TO OVERUSE AS TRAILER BRAKES HAVE NOT BEEN ADJUSTED AND DO NOT WORK PR		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER

1063	Wodonga - Workshop	GEARBOX NEEDS INSPECTION - SOMETIMES DOES NOT ENGAGE GEAR (FULL GEAR NOT SPLIT) WHEN IN BOTTOM BO		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	AIR RESTRAIN GUAGE NEEDS NEW BULB.		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		11/12/2022	91054	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	CHECK ENGINE LIGHT ON.	CODE FOR WATER IN FUEL. DRAINED FUEL PRO, CLEANED OUT AND REPLACED FILTER. TESTED. CLEARED CODES.	25/10/2022	59560	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	FRONT DIFF LEAKING.		23/10/2022	58802	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	B Service As Per Attached Checklist		23/10/2022	58802	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		23/10/2022	58802	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Pressure Check		11/10/2022		Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Rewire Trailer Plug		06/10/2022	47679	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	A Service As Per Attached Checklist		01/10/2022	46212	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		01/10/2022	46212	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	PBS CERTIFICATION		24/08/2022		Completed	Wodonga	HCU	XV13YL	VAWDREY AUSTRALIA I	P/MOVER
1063	Wodonga - Workshop	A Service As Per Attached Checklist		14/08/2022	17530	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Trailer brake light active when engine brake on		14/08/2022	17530	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Front end shutter under heavey braking		14/08/2022	17530	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Steering wheel LH low - pulls to the left		14/08/2022	17530	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ORDER AND FIT NHVAS STICKER.		14/08/2022	17530	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		14/08/2022	17530	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	check over front end		09/08/2022	13923	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	puncture repair		08/08/2022		Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Bunk cooler unit inside cab rattles. Needs attention	Sent to Hume Truck Technics	01/08/2022	411443	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ALIGNED STEERING WHEEL AS REQUESTED		30/07/2022	7558	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			The following 1st service inspection for Greenfreight, to a K200 Kenworth Truck, Chassis#1F5DJJJJJJNA78623, and registration #XV13YL included:								
			.								
			* Removed/replaced engine filter & oil, specification used in parts section below.								
			* Check all engine operation & components								
			* Removed/replaced transmission oil filter								
			* Check all hydraulic lines fitting & level lubricant levels to specification								
			* Removed/replaced power steering filter & gasket								
			* Removed/replaced differential oil, specification used in parts section below.								
			* Removed/replaced fuel filter								
			* Check cooling system & pressure test								
			* Check all belts, idler pulleys, fan, shrouds & adjust to specification								
			* Check all electrical routing, wiring looms, switches, sensors & components								
			* Check all wheel equipment & steering components								
			* Check all braking & adjust to specification								
			* Check clutching & adjust to specification								
			* Check all suspension components								
			* Check all internal cabin operation, components & adjust to specification								
			* Check all external cabin components & adjust to specification								
			* Check windscreen washers, wipers, refill & test operation								
			* Lubricate, adjust relevant components as required								
			* Re torque all fitting & fixtures								
		***COMPLIMENTARY NO CUSTOMER LABOUR CHARGE KENWORTH TRUCK 1st SERVICE POLICY ***	* Wash vehicle complete								
1063	Wodonga - Workshop	***CUSTOMER RESPONSIBLE FOR ALL PARTS REQUIRED FOR 1st SERVICE***	* Road test, confirm & quality check	30/07/2022	7558	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	DROP OFF TCTC. PICK UP.		24/07/2022		Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Record Check Results As Attached To This Job		23/07/2022	411443	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	C Service As Per Attached Checklist		23/07/2022	411443	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			Vawdrey Larapinta carry out repair of suzi								
1063	Wodonga - Workshop	Split suzi behind coupling	PO # WW073049	20/07/2022	411443	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	ORDER AND FIT NHVAS STICKER.		14/07/2022	879	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
			TARE WEIGHT: STEER 5700KG								
1063	Wodonga - Workshop	New Truck Pre Delivery	OVERALL 9250KG	14/07/2022	879	Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 9 + 10		01/07/2022		Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 7 + 8		01/07/2022		Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Tyre Position 5 + 6		01/07/2022		Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER
1063	Wodonga - Workshop	Supply and fit 8 tyres to suit High Cube - the replaced tyres dropped to Wodonga Yard		01/07/2022		Completed	Wodonga	HCU	XV13YL	Wodonga Workshop	P/MOVER