| EquipmentName | Workshop | Description | CompletionComments | DateDone | DistanceDone | Workstate | Location | Division | Rego | Supplier | EquipmentType |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1055 | Wodonga - Workshop | REBULD ENGINE REPLACE HEAD LINERS BIG ENDS & MAINS TURBO THERMOSTATE & JAKE KIT (FIT NEW AIR FILTER HOUSING & TURBO AIR INTAKE RUBBER) GF SUPPLIED THESE PARTS | ENGINE REBIULT AT 893195 KMS<br>Complaint:<br>Engine derating won't accelerate past idle<br>Cause:<br>Wiring To Throttle Pedal<br>Correction:<br>Guidanz: 01955471<br><br>ECM KM: 897,410<br>ECM Fuel Used: 468,192<br>ECM Hours: 12,658<br><br>Correction:<br>- Travel from Cummins Wodonga to Thurgoona Drive Albury<br>- Vehicle in unsafe position to work on.<br>- In Form Shaun from GreenFreight and he will get Truck towed to safe place to work on it.<br>- Travlled from Thurgoona back to Cummins Wodonga.<br><br>- Recived call from Cummins Call Center 4 hours later informing Green Freight had truck had been moved to BP North Albury & Green Freight would like us to attend new safe site now.<br>- Travel from Cummins Wodonga to North Albury.<br>- Connect laptop and download ECM Image<br>- Find no relevant codes<br>- Raise cabin | 01/09/2026 | 893251 | Completed | Wodonga | HCU | XV18VU | CUMMINS SOUTH PACIFIC P/L | P/MOVER |
| 1055 | Wodonga - Workshop | THROTTLE NOT WORKING- (ORIGIONAL DRIVER COMPLAINT OF NO POWER) | - Carry out wiring resistance checks of throttle pedal | 14/08/2026 | 903500 | Completed | Wodonga | HCU | XV18VU | CUMMINS SOUTH PACIFIC P/L | P/MOVER |
| 1055 | Wodonga - Workshop | Prevent\TRANS OIL | checked by Aaron | 30/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Engine water temp not working. | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Engine water temp gauge, Not working. | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RHS TORQUE ROD BUSHES WORN | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ABS needs repair and replace | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | something loose in drivers door (rattles & clunks) | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | primemover AC has its moments where it struggles to keep up | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DrivLine\DIFF OIL Replace Diff oils | done in c service | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FIT LOW PROFILE TUNTABLE FROM 1039. | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Insp\ANN INSP To Complete R/W within 12 months | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\CS C Service<br>REPLACE DAMAGED AIR FILTER HOUSING & CLAMPS | | 29/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FIT NEW TURBO RUBBER ELBOW | DONE AT | 29/07/2026 | 893251 | Completed | Wodonga | HCU | XV18VU | CUMMINS SOUTH PACIFIC P/L | P/MOVER |
| 1055 | Wodonga - Workshop | engine brake : obviously set to come on at 103kmh. this is absolute stupid on wet slippery roads you hit 102/10 | NEW PROGRAMME INSTALLED AT CUMMINS | 27/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ENGINE BRAKE COMING ON 103+ | NEW PROGRAMME INSTALLED AT CUMMINS | 27/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Normal operation with 103 overun jake comes on when cruise is set.. Please turn this stupid function off or set a | NEW PROGRAMME INSTALLED AT CUMMINS | 27/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ENGINE BRAKE COMING ON AT 103KM | NEW PROGRAMME INSTALLED AT CUMMINS | 27/07/2026 | 893242 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DrivLine\OIL LEAK | Truck Came To Callaway Workshops With OiL leaking At Front Hub Assembly, Inspect Found That Hub was Overfull, Drain To Correct Level, Refit Plug, Clean Rim and Tyre,Test For Leaks All Ok (Labour Charge) 1 Hr | 04/05/2026 | 882483 | Completed | Wodonga | HCU | XV18VU | CALLAWAY DIESEL | P/MOVER |
| 1055 | Wodonga - Workshop | TAKING 40-50 MINUTES FOR TRAILERS BODIES TO COME DOWN WHEN EMPTY. | Wrong truck | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR SHIFTING IS HARD (TO GET OUT OF GEAR & INTO GEAR. VERY GRITTY AT SHIFTER. ADJUST CLUTCH PROPE<br>After treat light is on. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | (Parts Supplied By TCTC P/O: WW133318 | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | shudder coming up through truck not sure if steers or drives | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Ad-Blu filler cap is Very Hard to Open.<br>VehService\BS B Service | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | WW133298 | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | gear change is hard to engage & disengage in certain shifts can be very gritty. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Need first aid kit. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Top R/H windscreen cracked, need's to be replaced. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Can Be Extremely Hard To Get Out Of Revers | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | gears can be hard to select at times (selectors) gears have trouble selecting in split it will neutralize | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | clunking banging under front end (mounts) | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | windscreen wiper blade's need to be replaced. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Front air gauge, need's new globe/light. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | mounting bar with pogo stick need 1 clamp for chassis | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | *FRONT END FEELS LOOSE-CLUNKS & BANGS | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Hour Meter Not Working | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | L/H Top Marker On Cab Very Dull | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Front air gauge light not working. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Pogo stick need's to be replaced. | | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR SHIFTING IS HARD TO GET OUT OF GEAR & INTO GEAR VERY GRITTY AT SHIFTER | Labour- Mobile- Breakdown<br>Travelled to Balranald<br>Located and inspected unit<br>Found suzi line at the rear of the cab loose causing an air leak<br>No fault found with trailer brake boosters<br>Fitting was retightened and secured<br>Air system was re-pressurised and checked for leaks<br>Brake system operation was tested and confirmed satisfactory | 07/04/2026 | 868497 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Chassis\AIR LEAK | No further air leaks detected | 01/04/2026 | 868494 | Completed | Wodonga | HCU | XV18VU | WARREGO TRANSPORT REPAIRS | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Called to south East Freeway 17/2/2026 at 9.30 am<br>Inspected alternator<br>Found it to be failed internally<br>Removed<br>Switched the pulley and reinstalled the new alternator<br>Inspected belt but found to be damaged - recommend replacing<br>Tested alternator was charging at about 13.2v due to low batteries<br>Also found turbo inlet pipe clamp loose - tightened | | | | | | | | |
| 1055 | Wodonga - Workshop | Engine\ALT | CREDIT WAS GIVEN FOR ALTERNATOR AS IT WAS FAULTY, REPLACED BY HOT SPARK | 17/03/2026 | 861663 | Completed | Wodonga | HCU | XV18VU | MOORE MECHANICAL | P/MOVER |
| 1055 | Wodonga - Workshop | Electrical Repair's | | 11/03/2026 | 854611 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\RUN OUT POS 5-6 | | 09/03/2026 | 854799 | Completed | Wodonga | HCU | XV18VU | BORDER BANDAG PTY LTD | P/MOVER |
| 1055 | Wodonga - Workshop | Elect\ELECT P&W<br>FOUND STEER HUB SEALS LEAKING BOTH SIDES. | TRAVEL TO BREAKDOWN AT COKE IN BRAEESIDE AS REQUESTED, INSPECTED | 03/03/2026 | 875509 | Completed | Wodonga | HCU | XV18VU | ELITE DIESEL REPAIRS | P/MOVER |
| 1055 | Wodonga - Workshop | REPLACED. ELITE DIESEL.<br>VehService\AS A Service | | 28/02/2026 | 850124 | Completed | Wodonga | HCU | XV18VU | ELITE DIESEL REPAIRS | P/MOVER |
| 1055 | Wodonga - Workshop | WW099234 | ELITE DIESEL | 28/02/2026 | 850124 | Completed | Wodonga | HCU | XV18VU | ELITE DIESEL REPAIRS | P/MOVER |
| | | | Check for reported starting and charging issues, found alternator not charging,<br>inspect wiring, found S terminal not connected, connect wiring as required, alternator faulty, supply and fit new unit.<br>Inspect batteries, found batteries swollen and leaking acid, replace as | | | | | | | | |
| 1055 | Wodonga - Workshop | Engine\ALT2 DR<br>Chassis\FIFTH WHEE<br>TURNTABLE TOP REPLACEMENT | required, test starting and charging | 18/02/2026 | 853216 | Completed | Wodonga | HCU | XV18VU | HOT SPARK AUTO ELECTRICAL | P/MOVER |
| 1055 | Wodonga - Workshop | TURNTABLE LUBRICATION - BREAKDOWN - WARREGO WW098039 | | 24/01/2026 | 830997 | Completed | Wodonga | HCU | XV18VU | G & S DIESEL SERVICE | P/MOVER |
| 1055 | Wodonga - Workshop | Clutch need's to be Adjusted. | | 31/12/2025 | 819881 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS A Service | | 31/12/2025 | 819881 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP1+2<br>Replace Damaged Suzie Leads (Air) | | 31/12/2025 | 823262 | Completed | Wodonga | HCU | XV18VU | BORDER BANDAG PTY LTD | P/MOVER |
| 1055 | Wodonga - Workshop | | | 13/12/2025 | 811094 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | | Plug laptop into the gaurdian unit and test, found the ffc was not working and the seat vibrator was not working.<br>Check the seat vibrator and found the wiring had been cut, join back together<br>and test, the vibrator is now working.<br>Unpluged the ffc and plug a new camera in to test, the unit still was not reading the ffc. Tried reseting the unit, the ffc still did not work.<br>Changed the unit and set up for the vehicle. Test, the unit is now working correctly, plugged the truck ffc back in and found it was faulty, remove and replaced with the new ffc, test. All is working correctly.<br>Old unit s/n- p1002260-s00009494.<br>New unit s/n- p1002260-s00027162. | | | | | | | | |
| 1055 | Wodonga - Workshop | DrCabElect\GPS GUARDIAN N/W<br>B Service<br>Serviced @ 810,200 Klms<br>WW098498 | Parts out of Greenfreight stock | 11/12/2025 | 813738 | Completed | Wodonga | HCU | XV18VU | ARKON AUTO ELECTRICAL | P/MOVER |
| 1055 | Wodonga - Workshop | | | 30/11/2025 | 810200 | Completed | Wodonga | HCU | XV18VU | WARREGO TRANSPORT REPAIRS | P/MOVER |
| 1055 | Wodonga - Workshop | PLEASE CHECK FRONT AXLE SEALS | | 30/11/2025 | 810200 | Completed | Wodonga | HCU | XV18VU | WARREGO TRANSPORT REPAIRS | P/MOVER |
| 1055 | Wodonga - Workshop | DrivLine\DIFF REPMN - DIFF REBUILD<br>Apply Greenfreight's New ECM Program. | Diff can be rebuilt. Estimated price for this is $9,350 + GST (Parts will need to | 26/11/2025 | 807664 | Completed | Wodonga | HCU | XV18VU | TWIN CITY TRUCK CENTRE - OLD | P/MOVER |
| 1055 | Wodonga - Workshop | (Cummins Wodonga P/O: WW097606)<br>Replace Both Windscreen's | | 30/10/2025 | 830997 | Completed | Wodonga | HCU | XV18VU | CUMMINS SOUTH PACIFIC P/L | P/MOVER |
| 1055 | Wodonga - Workshop | (Autotek P/O: WW097360 | | 11/10/2025 | 796506 | Completed | Wodonga | HCU | XV18VU | AUTOTEK AUSTRALIA | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS A Service | | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Drive shaft has started to leak | Repaired By TCTC When Diff Was Replaced | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Transmission may need servicing. | | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | gearbox howl / whine in 3rd & 7th getting louder | | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ADJUST CLUTCH PROPERLY! PLEASE | | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | *FRONT DIFF PINION?/ OR BLOCKED BREATHER SPRAYING OIL. | Repaired By TCTC When Diff Was Replaced | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DIFF PINION LEAKING AGAIN ONLY JUST STARTED. | Repaired By TCTC When Diff Replaced | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Oil Leaking From Front Diff Pinion Again<br>HARD TO GET OUT OF GEAR. HAS A VERY GRITTY FEEL TO IT. | Repaired By TCTC When Diff Was Replaced | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CLUTCH NEEDS TO BE ADJUSTED CORRECTLY.<br>*STOP ENGINE LIGHT COMING ON. BASICS ARE ALL GOOD. OIL, COOLANT ETC. | | 11/10/2025 | 796588 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | (Cummins Wodonga P/O: WW097091 | | 23/09/2025 | 830997 | Completed | Wodonga | HCU | XV18VU | CUMMINS SOUTH PACIFIC P/L | P/MOVER |
| | | | LAB T - BREAKDOWN - AH<br>BREAKDOWN LOCATION: BP MARULAN - SOUTH BOUND HUME HIGHWAY<br>BREAKDOWN DETAILS: VEHICLE DE-RATED<br>Attended breakdown on site. Connected diagnostic scan tool and confirmed fault related to high engine oil temperature. Checked live data – sensor readings operating correctly. Topped up engine oil with 4L. Warmed vehicle and confirmed cooling system operation. Suspect fault with oil thermostat. Driver advised by employer to continue journey | | | | | | | | |
| 1055 | Wodonga - Workshop | Engine/DE-RATED BREAKDOWN<br>BREAKDOWN AT HALFWAY CREEK NORTH OF COFFS HARBOUR. | to Melbourne with caution. Returned to workshop | 22/09/2025 | 785609 | Completed | Wodonga | HCU | XV18VU | MECHANIKA MOTORS PTL LTD | P/MOVER |
| 1055 | Wodonga - Workshop | TRUCK NOT BUILDING UP ENOUGH AIR. G&R COFFS HARBOUR ATTENDING. | | 16/09/2025 | 662076 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1055 | Wodonga - Workshop | Fault code on | | 15/09/2025 | 830997 | Completed | Wodonga | HCU | XV18VU | B&M MECHANICAL REPAIRS | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP9+10 | | 01/09/2025 | 774310 | Completed | Wodonga | HCU | XV18VU | BORDER BANDAG PTY LTD | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP5+6 | | 01/09/2025 | 774310 | Completed | Wodonga | HCU | XV18VU | BORDER BANDAG PTY LTD | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP7+8 | | 01/09/2025 | 774310 | Completed | Wodonga | HCU | XV18VU | BORDER BANDAG PTY LTD | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP11+12 | | 01/09/2025 | 774310 | Completed | Wodonga | HCU | XV18VU | BORDER BANDAG PTY LTD | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\Puncture POS 9 | | 28/08/2025 | 772666 | Completed | Wodonga | HCU | XV18VU | BORDER BANDAG PTY LTD | P/MOVER |
| 1055 | Wodonga - Workshop | Audible park brake alarm not working | | 07/08/2025 | 757464 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FUSE KEEPS BLOWING AFFECTING CRUISE/ INTERIOR/ ENGINE BRAKE- I BELEIVE IT IS THE HORN CAUSING THE P | | 07/08/2025 | 757464 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | fuse keeps blowing affecting cruise & engine brake | -horn short followed to find faulty horn and wiring, horn replaced and wiring repaired | 07/08/2025 | 757464 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FUSE KEEPS BLOWING AFFECTING CRUISE/INTERIOR/ENGINE BRAKE - I BELIEVE ITS THE HORN | 11.30 - 1.30 | 07/08/2025 | 757464 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEARBOX OIL LEAK AT FILTER-<br>REPLACED FILTER. TIGHTENED FITTINGS. | | 25/07/2025 | 751087 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Insp\ANN INSP | | 23/07/2025 | 745416 | Completed | Wodonga | HCU | XV18VU | G & S DIESEL SERVICE | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\CS (PO:WW095666) | | 23/07/2025 | 745416 | Completed | Wodonga | HCU | XV18VU | G & S DIESEL SERVICE | P/MOVER |
| 1055 | Wodonga - Workshop | DrivLine\DIFF OIL Replace Diff oils | | 23/07/2025 | 745416 | Completed | Wodonga | HCU | XV18VU | G & S DIESEL SERVICE | P/MOVER |
| 1055 | Wodonga - Workshop | BROWN & HURLEY YATALA-BREAKDOWN.<br>DIAGNOSE AND REPAIR AFTER TREAT FAULT. | | 25/06/2025 | 729091 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |
| 1055 | Wodonga - Workshop | Repair/Replace Damaged Electrical Suzie Lead. (G&S Diesel P/O: WW094972) | | 16/06/2025 | 724229 | Completed | Wodonga | HCU | XV18VU | G & S DIESEL SERVICE | P/MOVER |
| 1055 | Wodonga - Workshop | LHF drive hub seal started to leak. Brakes still good | | 12/06/2025 | 722997 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS A Service | | 12/06/2025 | 722997 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Fit Anderson Plug To Side Of Battery Box. | | 12/06/2025 | 722998 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Carry Out Full Road Worthy Inspection.<br>(Gilbert & Roach Hexham P/O: WW094658) | Carry out Inspection - Vehicle involved in collision<br>Carried out Inspection<br>- 2nd drive LH side shock loose<br>- 1st drive RH side wheel bearing movement<br>Repair defects<br>- Carry out brake test<br>- Adjust 1st drive axle RH side wheel bearing<br>- Replace 2nd drive LH side shock. Had to remove wheels & guards to oxy cut out old shock. | 31/05/2025 | 722158 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS A Service | | 10/05/2025 | 714438 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | COOLABAH AIRCON HAS STOPPED WORKING. TURNS ON THEN STOPS WORKING. REPLACE CHARGER | Checked operation of bunk ac. Found no power to AC. Checked battery voltage and found 0. 7v. Put 24v supply on battery and charged back up. Found 24v charger for battery and tested. Found charger was working but not 100%. Advised GreenFreight to monitor charger and if it doesnt charge advised we will need to order a new 24v charger for battery. | 01/05/2025 | 708268 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | HEATING FUNCTION HAS STOPPED WORKING ON BUNK COOLABAH A/C UNIT | #449236 | 01/05/2025 | 708268 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Coolabah bunk aircon not working it is throwing codes and error 1. Unit very noisey on outside | #449236 | 01/05/2025 | 708268 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CUMMINS WODONGA-<br>DROPPED LINER. REPLACED BLOCK. (@702515km)<br>REPLACED ENGINE MOUNTS.<br>(Cummins Wodonga P/O: WW095240) | Cummins Wodonga rebuilt engine using brand new block, reused cylinder he | 29/04/2025 | 731469 | Completed | Wodonga | HCU | XV18VU | CUMMINS SOUTH PACIFIC P/L | P/MOVER |
| 1055 | Wodonga - Workshop | CUMMINS-<br>REPLACED CLUTCH. | | 29/04/2025 | 731469 | Completed | Wodonga | HCU | XV18VU | CUMMINS SOUTH PACIFIC P/L | P/MOVER |
| 1055 | Wodonga - Workshop | oil was topped up to full / coolant was low it took 1.5 water cans about 4-6 litres of water. on thursday . I have s | | 15/04/2025 | 702608 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\BS | | 15/04/2025 | 702608 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | check engine / stop engine lights are coming on | | 15/04/2025 | 702608 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS A Service | | 28/03/2025 | 702507 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Air Leak Prime Mover. | | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | voltmeter not working | Broken wire near fuse new fuse holder fitted but needs new blade fuse holde | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ABS LIGHT ON (TRAILER) | Spoke to driver no abs lead connected | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | alternator light keeps flashing | Replace sub fuse as wire broken | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Driver side door rattling internally (door) | | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | clutch adjust | | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | heating side doesnt work | | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FIX RIGHT HAND MIRROR. | | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ABS LIGHT ON (TRAILER) | Spoke with driver to check no ebs lead connected | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Windscreen wiper/indicator switch broken. | | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS A Service | | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | alternator light keeps flashing | Duplicate | 07/03/2025 | 691265 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP1+2<br>Replace Diff Oils | | 06/03/2025 | 695141 | Completed | Wodonga | HCU | XV18VU | BEAUREPAIRES | P/MOVER |
| 1055 | Wodonga - Workshop | Done @ 660416 Klms | | 21/02/2025 | 683006 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Air Con\AIR CON BUNK COOLER REPAIRES | | 18/02/2025 | 680333 | Completed | Wodonga | HCU | XV18VU | G & S DIESEL SERVICE | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS G&S Diesel<br>Pinion seal leaking | | 18/02/2025 | 679178 | Completed | Wodonga | HCU | XV18VU | G & S DIESEL SERVICE | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT DIFF REQUIRES RESEAL. (Gilbert & Roach Huntingwood P/O: WW091116) | | 31/12/2024 | 651885 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT DIFF PIN IN SEAL LEAKING. (Gilbert & Roach Huntingwood P/O: WW091116) | | 31/12/2024 | 651885 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |
| 1055 | Wodonga - Workshop | DIFF OIL GETTING SPRAYED EVERYWHERE. (Gilbert & Roach Huntingwood P/O: WW091116) | | 31/12/2024 | 651885 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |
| 1055 | Wodonga - Workshop | ADJUST CLUTCH & CLUTCH BRAKE. | | 31/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CLUNKING UNDER FRONT OF CABIN. (Repaired By TCTC) | | 31/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CLUNKING UNDER FRONT OF CABIN. (Repaired By TCTC) | | 31/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEARSHIFT WENT SOFT/ NOT QUITE SLOPPY. TRUCK HAS ALWAYS BEEN A BIT HARD TO SELECT GEARS. PLEASE | | 31/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CAB / ENGINE MOUNTS CLUNKING & BANGING UNDERFOOT. (Repaired By TCTC) | | 31/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Clunking undercab (can mounts). (Repaired By TCTC) | | 31/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CLUNKING UNDER FRONT OF CABIN. (Repaired By TCTC) | | 31/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Diffs spraying oil everywhere | Diff pinion seal to be replaced in Sydney | 20/12/2024 | 649272 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\BS | | 20/12/2024 | 649272 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Driver side windscreen cracked | Windscreen replaced on the 5/12/2024 by auto screens albury PO #WW0906 | 10/12/2024 | 642893 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SERVICE DUE. | | 06/12/2024 | 640387 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Adjust play in front diff, sent to TCTC for front diff input seal, needs a new horton fan,<br>Bent crossmember at back of fuel tanks | | | | | | | | |
| 1055 | Wodonga - Workshop | VehService\AS | Clutch needs adjustment, too be done when back from tctc | 06/12/2024 | 640387 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | POGO STICK BROKEN. | Pogo stick ok | 06/12/2024 | 640387 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Replace Windscreen R/H Sie . (Albury Autoscreen P/O: WW090674) | | 06/12/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | AUTOTEK AUSTRALIA | P/MOVER |
| 1055 | Wodonga - Workshop | CHECK ENGINE LIGHT ON. | CHECKED CODES. ADDED 10L COOLANT. | 22/11/2024 | 630992 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VOLT METER NOT WORING AGAIN. | PREVIOOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | AIRCON/ HEATER LOST IT'S HEAT CYCLE. | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DOORS NEED ADJUSTING IN. THEY LEAK & WIND NOISE. | PREVIOUSLY COMPLPETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECKER PLATE ACROSS CHASSIS IS MISSING! | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRUCK HAS AIR LEAK LHS NEAR FUEL TANKS. | Couldn't hear air leak | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CLUTCH NEEDS ADJUSTING? DRAGGING. | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECK ENGINE LIGHT ON. (MAY BE LOOSE WIRE) | CHECKED. NO CODES ACTIVE. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | voltmeter playing up work sort of works | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ABS trailer coming on going off | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DRIVERS DOOR CATCH POPPING OPEN WHILE DRIVING- REQ READJUSTMENT. | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | rotate steer tyres | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Heating not working coolabah not working | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECK STARTER MOTOR? NOISEY INTERMITTENT/ KICKING IN/OUT.<br>(DRIVER REPORTS STARTER HAS NOW BEEN REPLACED) | | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ADBLUE LIGHT COMES ON NOW N THEN, ACCORDING TO GAUGE NOT USING A LOT BUT THEN IT WILL. | Took for high nox reset | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | COOLING SYSTEM HAD A STRONG SMELL TODAY OF COOLANT IN THE CABIN. | Checked today and there was no smell or sign of leakage in cab | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | clutch adjust / clutch brake aswell | PREVIOUSLY COMPLETED. | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\AS | | 29/10/2024 | 615804 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP1+2 | | 25/10/2024 | 613515 | Completed | Wodonga | HCU | XV18VU | BEAUREPAIRES | P/MOVER |
| 1055 | Wodonga - Workshop | Rattling Noise Coming From Engine P/O WW086801 (Brown & Hurley Yatala) | | 17/10/2024 | 523926 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |
| 1055 | Wodonga - Workshop | truck not starting<br>Kenworth Beresfeild attending | | 17/10/2024 | 610337 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\Punct | | 17/10/2024 | 610337 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Elect\TRL LIGHTS<br>*brake light issue<br>Travel to Greenfreight. Inspect trailer light operation. Brake lights keep<br>tripping the fuse. Disconnect B trailer. Fuse still tripped. Disconnect a trailer.<br>Fuse did not trip. Remove front cover on a trailer and inspect wiring. Ok.<br>Connect a short detector and short did not trip. Open up and inspect trailer<br>plug on prime move and found that the brake wire had been pinched in the<br>plug housing. Repair wire and reassemble trailer cover and plug. Test brake<br>lights ok. Carry out final tests and checks ok. | | 11/09/2024 | 585893 | Completed | Wodonga | HCU | XV18VU | ARKON AUTO ELECTRICAL | P/MOVER |
| 1055 | Wodonga - Workshop | ABS TRAILER LIGHT ON / FLICKER / GOES OUT COMES ON WHEN TOUCH BRAKES GOES OUT WHEN ACCEL<br>*Lights not working<br>*Call Out<br>Got callout at 7pm, traveled onsite to Greenfreight Wodonga.<br>Locate truck and checked brake lights n/w. Found when i wiggled<br>trailer plug brake lights would come on and off. Found pins on trailer<br>side were close. Spread pins and tested. All lights are working. Returned home. | | 11/09/2024 | 585893 | Completed | Wodonga | HCU | XV18VU | ARKON AUTO ELECTRICAL | P/MOVER |
| 1055 | Wodonga - Workshop | DrCabElect\HOUSEKEEP<br>ESC LIGHT REPORTED TO CONSTANTLY BE ON<br>.<br>* Connected laptop & scanned for faults<br>* Found active fault present for RH rear speed sensor<br>* Inspected & found recently replaced brakes & hub oil present<br>* Inspected speed sensor & confirmed not fit correctly<br>* Refit wheel speed sensor as required<br>* Cleared fault code & test operations<br>* All ok, fault no longer present | | 10/09/2024 | 583878 | Completed | Wodonga | HCU | XV18VU | PACCAR PARTS FLEET SERVICES | P/MOVER |
| 1055 | Wodonga - Workshop | A Service | | 03/09/2024 | 579177 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | C Service | | 03/09/2024 | 579177 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Annual Inspection Carried Out With C Service 02/09/2024 @579177 Klms<br>Transmission Oil Change | | 02/09/2024 | 579122 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Completed @ 579177 Klms<br>Diff Oil Change | | 02/09/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Completed @57177 Klms | | 02/09/2024 | 651912 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP3+4 | | 01/08/2024 | 553830 | Completed | Wodonga | HCU | XV18VU | BEAUREPAIRES | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP9+10 | | 01/08/2024 | 553830 | Completed | Wodonga | HCU | XV18VU | BEAUREPAIRES | P/MOVER |
| 1055 | Wodonga - Workshop | Tyres\TP7+8 | | 01/08/2024 | 553830 | Completed | Wodonga | HCU | XV18VU | BEAUREPAIRES | P/MOVER |
| 1055 | Wodonga - Workshop | VehService\BS Klms Were 549,372 at Time Of Service | B Service completed by Dan, Cody & Russell | 30/07/2024 | 562474 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VOLT METER NOT WORKING AGAIN. | Blown fuse replaced and upgraded at alternator | 30/07/2024 | 562474 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | L/H/S INDICATOR NOT WORKING. | Found broken wire at side indicator, repaired broken wire & tested | 30/07/2024 | 562474 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECKER PLATE NEEDS TO BE MOVED FORWARD & SECURED AS LEADS DROP DOWN ONTO TAILSHAFT. | Deck Plate adjusted and tightened | 30/07/2024 | 562474 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | WIPER BLADES. REPLACE PLEASE. | New Wiper blades fitted | 30/07/2024 | 562474 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT ENGINE MOUNTS. | | 26/06/2024 | 525473 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | LEAKING EXHAUST. | | 26/06/2024 | 525473 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | REPLACED EXHAUST MANIFOLD GASKETS, EEXHAUST FLEX, GASKETS, CLAMPS AND FRONT ENGINE MOUNTS. R | | 26/06/2024 | 525473 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | LH FUEL TANK J-BRACKETS CAN PLEASE STRAIGHTEN UP. | | 26/06/2024 | 525473 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SUZI COIL REPLACE PLEASE. | | 26/06/2024 | 525473 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Engine\BELTS/TENS | Not tensioner ended up being front right engine mount badly damaged | 06/06/2024 | 514957 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | a lot of wind coming through top of door seal | | 06/06/2024 | 514957 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | AFTER HOURS ROAD SIDE SERVICE AT BREADALBANE, TO GREENFREIGHTS K200, CO71JN. FOUND ALTERNATOR | Removed both belts & checked for noise<br>Replaced fan belt tensioner<br>found alternator noisy<br>replaced alternator with s/hand unit<br>refit belts & ran engine | 29/05/2024 | 505854 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Alternator pulley noise | noise gone | 25/05/2024 | 504355 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | B Service As Per Attached Checklist | | 01/05/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | change Diff oils | RELACED OIL AND FILTER. | 01/05/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1055 | Wodonga - Workshop | ABS LEADHAS BEEN RIPPED OFF. | | 01/05/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RH DOOR CONSTANT AIR/ WIND NOISE. NEEDS ADJUSTING. | | 01/05/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | AIR LEAK PRIMEMOVER. | | 01/05/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEEDS NEW ABS LEAD. | | 01/05/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 01/05/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | AMP GAUGE NOT WORKING. | | 23/03/2024 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Low Engine Power | | 23/03/2024 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALT LIGHT GOING ON AND OFF ON DASH. | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BADLY WEARING LEFT TYRE NEEDS CHANGING ON CHECKING. | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Low Engine Power | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Knocking in front suspension | TEST DROVE. COULDN'T GET TO KNOCK. MAY NEED TRAILERS HOOKED UP. | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | REPLACE FRONT DIFF INPUT SEAL. | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | AMP GAUGE NOT WORKING. | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEEDS NEW ABS LEAD. | | 17/03/2024 | 458062 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TIGHTENED GUARDIAN CAMERA. FIXED DASH CAMERA TO ROOF. | | 08/03/2024 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 1 + 2 | | 08/03/2024 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | 13-14 | | 07/03/2024 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 11 + 12 | | 07/03/2024 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | replaced 1st diff input under warrenty and replaced diff oil | Need to replace input Yoke | 30/01/2024 | 434105 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | REPLACE FRONT DIFF INPUT SEAL. | | 17/01/2024 | 423170 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | re-seal roof lights (water coming into cab) | | 17/01/2024 | 423170 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Knocking in front suspension | | 17/01/2024 | 423170 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | REPLACED GEARSTICK BOOT. | 17/01/2024 | 423170 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job<br>Replace Diff Oils | | 17/01/2024 | 423170 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Done @ 459021 Klms | | 17/01/2024 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Grease Truck | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | B Service As Per Attached Checklist | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | front diff oil leak | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | replace EBS susi lead | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | replace left fuel tank plate | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | repair checker plate | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | service | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Low Engine Power | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Fix EBS Lead | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Knocking in front suspension | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | LEFT FUEL TANK PLATE BENT. | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tank Bracket bent LHS. | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 19/12/2023 | 414883 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 21/11/2023 | 398853 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Knocking in front suspension | | 21/11/2023 | 398853 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BASH PLATES BEHIND CAB ARE TURNING UP & MISSING BOLTS. | | 21/11/2023 | 398853 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job<br>Replace Damaged Steer Tyre (Beaurepaires) | | 21/11/2023 | 398853 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Purchase Order Number: WW081836 | | 19/10/2023 | 528437 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Replaced Town Horn | | 07/10/2023 | 371168 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Adjust Clutch | | 07/10/2023 | 371168 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tank Bracket bent LHS. | | 05/10/2023 | 371160 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Carry Out Annual Inspection | | 05/10/2023 | 371160 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | Bunk cooler not cooling code E04. | Coolabah repair. Check Coolabah operation. Turn on unit. Will run for brief time them log high pressure gas code. Notice condensor fan not cutting in. Notice evaporator filter butchered and totally blocked. Shelf unit very dirty and full of fluff. Tilt cab and check condensor fan fuses. Fan fuse blown. Replace fuse - dead short and blowing straight away . Organise parts .Remove rear condensor cover and remove fan. Fit new fan and reassemble cover. Replace fuse and lower cab . Blow out evaporator and replace cab filter. Start unit and test current draw. Condensor fan now working. | | | | | | | | |
| 1055 | Wodonga - Workshop | Hagans. Bunk cooler not cooling code E04. | Check parameters and lithium charging. All | 05/10/2023 | 371160 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Knocking in front suspension | | 05/10/2023 | 371160 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECKER PLATE MISSING. | | 05/10/2023 | 371160 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | + NEW R&R BOOK. | | 05/10/2023 | 371160 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | WHILST CARRYING OUT DIFF RESEAL, FOUND DIFF OIL REQUIRING REPLACEMENT<br>.<br>* Drained both diffs<br>* Cleaned out diff screens | | | | | | | | | |
| 1055 | Wodonga - Workshop | * Replaced diff oil as required | | 04/10/2023 | 371070 | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | LEFT FUEL TANK PLATE BENT. | | 23/09/2023 | 371070 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | POGO STICK BRACKET MISSING BOLT. LOOSE. | | 23/09/2023 | 371070 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VOLT METER N/W. | | 23/09/2023 | 371070 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER ABS LIGHT ON. | NO FAULT. | 23/09/2023 | 371070 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | OIL LEAK AT FUEL PUMP. | NO FAULT. | 23/09/2023 | 371070 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BASH PLATES BEHIND CAB ARE TURNING UP & MISSING BOLTS.<br>Replace Fuel Tank Covers/Steps (RC Metal Craft) | | 23/09/2023 | 371070 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Purchase Order Number: WW080664 | | 30/08/2023 | 528437 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RESEAL FRONT DIFF. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | OIL LEAK AT FUEL PUMP. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT DIFF OIL LEAK. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | LEFT FUEL TANK PLATE BENT. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | POGO STICK BRACKET MISSING BOLT. LOOSE. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECKER PLATE MISSING. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECKER PLATE MISSING. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECKER PLATE MISSING. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1055 | Wodonga - Workshop | + NEW R&R BOOK. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BASH PLATES BEHIND CAB ARE TURNING UP & MISSING BOLTS. | ORDERED. | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BACK DIFF IS LEAKING OIL. | NOT LEAKING. | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | MISSING OIL DIPSTICK & OIL FILLER. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | R/H/F HUB SEAL LEAKING. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEED NEW DRIVE TYRES. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VOLT METER N/W. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Need constant 12V plug fitted for fridge please | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALTERNATOR LIGHT STILL COMING ON. | 14.5V. | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER ABS LIGHT ON. | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | REPAIR PARK BRAKE ALARM. | CONNECTED HORN. | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 23/08/2023 | 359531 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | MANUFACTURED BRACKET FOR CROSSMEMBER. | | 22/08/2023 | 358547 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECK HORTON FAN FOR AIR LEAK. | CHECKED HORTON FOR LEAKS. WASHED FRONT DIFF AND CHECKED FOR LEA | 22/08/2023 | 358547 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SERVICE CLUTCH BRAKE. | | 22/08/2023 | 358547 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER LIGHTS PLUG BROKEN. | | 22/08/2023 | 358547 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | BROKEN FITTINGS OFF AD BLUE FILTER<br>Travelled to truck, inspect ad blue filter, found broken air fitting on top of ad blue filter housing.<br>Removed damaged fitting, installed new. Reconnect lines, started and check operation, all okay. | | | | | | | | | |
| 1055 | Wodonga - Workshop | Connect laptop and cleared after treat faults. | | 18/08/2023 | 358543 | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | JUMP START TRUCK | Go to Greenfreight yard, jacked cab, connect jumper pack and jump started t | 10/08/2023 | 358542 | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| | | Replace Damaged Air Suzies & Fittings (CMV Adelaide) | | | | | | | | | |
| 1055 | Wodonga - Workshop | Purchase Order Number: WW079756 | | 24/07/2023 | 528151 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | ravelled to site. Inspected and found bracket for air tank drain cock line is bent causing drain cock to be pulled open<br>constantly. Bent bracket back into correct position. Built up air and checked over - all ok. Travelled home | | | | | | | | | |
| 1055 | Wodonga - Workshop | Kenworth Derrimut PO# WW079517. | | 07/07/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Checked Trailer Plug And Lead | Found no rubbed wiring. | 15/06/2023 | 382270 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | INSPECTED REVERSE BEEPER. CONSULTED SUPERVISOR. CORRECT ONE INSTALLED FOR COLES. | | 18/05/2023 | 339511 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECKED CORRECT REVERSE BEEPER INSTALLED. | | 18/05/2023 | 339511 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 1 + 2 | | 10/05/2023 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 9 + 10 | | 10/05/2023 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 7 + 8 | | 10/05/2023 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 5 + 6 | | 10/05/2023 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 3 + 4 | | 10/05/2023 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Check & Test Batteries Replace Batteries If needed | REPLACED BATTERIES. | 04/05/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | B Service As Per Attached Checklist | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | REPAIR PARK BRAKE ALARM. | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RESEAL FRONT DIFF. | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEED NEW DRIVE TYRES. | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VOLT METER N/W. | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Need constant 12V plug fitted for fridge please | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SPRING PACKS EXCESSIVELY NOISY. | GREASED SHACKLES. | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SEVERE SUSPENSION NOISE COMING FROM FRONT END-SHOCKS/ BUSHES SOMETHING SOUNDS VERY DRY & C | GREASED SHACKLES. | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALTERNATOR LIGHT STILL COMING ON. | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER ABS LIGHT ON. | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | OIL LEAK AT FUEL PUMP. | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 27/04/2023 | 330565 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | Replace R/H Inner Front Drive Tyre (Goodyear Autocare Warrick)(Beaurepairs) | | | | | | | | | |
| 1055 | Wodonga - Workshop | Purchase Order Number: WW077841 | | 18/04/2023 | 528151 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEED NEWDRIVE TYRES. | | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | R/H SEAT BELT NOT RETRACTING. | removed bits of seat cover out of retractor. | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEED NEW HEADLIGHT COVERS. | Fitted new head light covers | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VOLT METER N/W. | | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Factory fridge beginning to fail- not cooloing fully & compressor cycling randomly and noisy. | Replaced fridge | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Need constant 12V plug fitted for fridge please | | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | No A/C fan | Completed by TCTC under Warranty | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Needs new steer tyres | New steer tyres have been fitted. | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | JAKE & OIL PRESSURE LIGHTS BLOWN. | Replaced blown globes | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SPRING PACKS EXCESSIVELY NOISY. | | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALT LIGHT COMING ON, VOLTAGE SEEMS HIGH AT TIMES 14> | Refer Job # 408117 | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR LINKAGES FEEL LIKE IT HAS EXCESSIVE PLAY. | Adjusted free play in linkages. | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SEVERE SUSPENSION NOISE COMING FROM FRONT END-SHOCKS/ BUSHES SOMETHING SOUNDS VERY DRY & C | | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALTERNATOR LIGHT STILL COMING ON. | | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | ENGINE OIL PRESSURE GLOBE BLOWN. | | | | | | | | | |
| 1055 | Wodonga - Workshop | ENGINE RETARD GLOBE BLOWN. | Replaced blown light globes. | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER ABS LIGHT ON. | | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | INTERMITTENT BEARING NOISE WHILE DRIVING FROM FRONT END. | Removed belts + checked all bearings. All good no noisy bearings. | 16/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | L/H Windscreen | | | | | | | | | |
| 1055 | Wodonga - Workshop | Autotek PO# WW077606 | | 01/04/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 1 + 2 | | 29/03/2023 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | ADDED16.5L ENGINE OIL. | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Factory fridge beginning to fail- not cooloing fully & compressor cycling randomly and noisy. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Need constant 12V plug fitted for fridge please | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | No A/C fan | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Needs new steer tyres | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | JAKE & OIL PRESSURE LIGHTS BLOWN. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SPRING PACKS EXCESSIVELY NOISY. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALT LIGHT COMING ON, VOLTAGE SEEMS HIGH AT TIMES 14> | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR LINKAGES FEEL LIKE IT HAS EXCESSIVE PLAY. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SEVERE SUSPENSION NOISE COMING FROM FRONT END-SHOCKS/ BUSHES SOMETHING SOUNDS VERY DRY & C | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALTERNATOR LIGHT STILL COMING ON. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | ENGINE OIL PRESSURE GLOBE BLOWN. | | | | | | | | | |
| 1055 | Wodonga - Workshop | ENGINE RETARD GLOBE BLOWN. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER ABS LIGHT ON. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | INTERMITTENT BEARING NOISE WHILE DRIVING FROM FRONT END. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | OIL LEAK AT FUEL PUMP. | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 21/03/2023 | 307460 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 20/03/2023 | 528151 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 20/03/2023 | 528151 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | OIL Replace Diff Oils | | | | | | | | | |
| 1055 | Wodonga - Workshop | Done @ 274,031 Klms | | 23/02/2023 | 485973 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 1 + 2 | | 11/02/2023 | | Completed | Wodonga | HCU | XV18VU | Albury Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Autoscreen RH Windscreen Replacement | #POWW076253 | 20/01/2023 | 528151 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR LINKAGES FEEL LIKE IT HAS EXCESSIVE PLAY. | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SEVERE SUSPENSION NOISE COMING FROM FRONT END-SHOCKS/ BUSHES SOMETHING SOUNDS VERY DRY & C | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALTERNATOR LIGHT STILL COMING ON. | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | ENGINE OIL PRESSURE GLOBE BLOWN. | | | | | | | | | |
| 1055 | Wodonga - Workshop | ENGINE RETARD GLOBE BLOWN. | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER ABS LIGHT ON. | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | INTERMITTENT BEARING NOISE WHILE DRIVING FROM FRONT END. | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | OIL LEAK AT FUEL PUMP. | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 18/01/2023 | 269429 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Replaced LHF Guard, Mudflaps And Both Outriggers | | 11/01/2023 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | OIL LEAK AT FUEL PUMP. | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | ADJUST CLUTCH. | | | | | | | | | |
| 1055 | Wodonga - Workshop | ADJUST CLUTCH BRAKE. | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TRAILER ABS LIGHT ON. | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | INTERMITTENT BEARING NOISE WHILE DRIVING FROM FRONT END. | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ALT LIGHT COMING ON. | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | B Service As Per Attached Checklist | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CHECK ENG LIGHT ON. | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 04/01/2023 | 258057 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 10/12/2022 | 243190 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 10/12/2022 | 243190 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ANY CHANCE OF A CONSTANT 12V FRIDGE PLUG FITTED. | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CAN I PLEASE GET 2 NEW MUDFLAPS ON THE REAR. | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CAN I PLEASE GET THE DENT IN THE FRONT BAR STRAIGHTENED OUT AS MUCH AS POSSIBLE. | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Roof leaking has turned into niagra falls over the fuse box and leaing through the dash to the floor. | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEED NEW HEADLIGHT COVERS. | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Trailer ABS still inop - wiring between a & b, works when only b is connected to prime mover | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | R/H Windscreen cracked + Left Hand has stonechip. | | | | | | | | | |
| | | Albury Autotek replaced. | | | | | | | | | |
| 1055 | Wodonga - Workshop | PO# WW075250. R/H Windscreen cracked + Left Hand has stonechip. | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 21/11/2022 | 527960 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BATTERIES NEED REPLACING- SLOW STARTING AND NEEDING TO USE JUMP START AT TIMES.. BATTERIES NEED | | 20/11/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Replaced Reverse Buzzer | | 09/11/2022 | 223763 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | supply and fit 2tyres | | 22/10/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 22/09/2022 | 194200 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ROTATE STEERS PLEASE. | | 22/09/2022 | 194200 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DRIVE TYRE DUE FOR REPLACEMENT. | | 22/09/2022 | 194200 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 22/09/2022 | 194200 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | C Service As Per Attached Checklist | | 07/09/2022 | 182622 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 07/09/2022 | 182622 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | replace R/H windscreen | Albury Auto Screen to carry out repair P/O WW073882 | 05/09/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 7 + 8 | | 26/08/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 5 + 6 | | 26/08/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 3 + 4 | | 26/08/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | supply and fit 8 tyres | | 26/08/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PICK UP TCTC. | | 21/08/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | KNOCK IN STEERING COLUMN. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RE-SEAL L/H CLEARANCE LIGHT & HORN ON ROOF- SUSPECT THIS IS WHERE WATER LEAK IS FROM. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SEVERE BRAKE NOISE- R/H/F LOUD & EMBARASSING. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BATTERIES NEED CHECKING- LOW VOLTAGE AFTER BEING LEFT OVERNIGHT & HARD TO START. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DRIVER'S DOOR NEEDS TO BE ADJUSTED. LOTS OF ROAD NOISE & WIND COMING IN. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ROOF STILL LEAKS IN RAIN. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Slow to start after a weekend | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Alternator charge rate is fluctuating and lights are going dim at idle | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | CAN I GET A CONSTANT 12V PLUG FOR FRIDGE WIRED IN PLEASE? | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | OVERHEAD CONSOLE DOOR SOESN'T STAY UP. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VIBRATION 60-90. SETTLES DOWN AT 100KM. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ROOF STILL LEAKS L/H. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TANK STEP CHECKER PLATE NEEDS REPLACING AFTER TOWING STANDARD SET. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BAD RATTLE FROM STEERING COLUMN AREA, LOWER DASH. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR SHIFTER BOOT SPLIT. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | MTDATA NOT WORKING | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT DIFF NEEDS TO BE RESEALED. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RESEAL FRONT DIFF | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT DIFF CENTRE LEAKING. | | 19/08/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | REPLACED TRUCKSAFE STICKER. | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | | Front Diff Oil Sample SIF # 43276893 | | | | | | | | |
| 1055 | Wodonga - Workshop | Diff Oils | Rear Diff Oil Sample SIF # 43276640 | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BATTERIES NEED CHECKING- LOW VOLTAGE AFTER BEING LEFT OVERNIGHT & HARD TO START. | | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | DRIVE TYRE DUE FOR REPLACEMENT. | | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Trailer ABS still inop - wiring between a & b, works when only b is connected to prime mover | | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | VIBRATION 60-90. SETTLES DOWN AT 100KM. | | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BAD RATTLE FROM STEERING COLUMN AREA, LOWER DASH. | | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 17/08/2022 | 165434 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | STRAIGHTENED BRACKET FOR DRAIN COCK. | | 11/08/2022 | 139110 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | REPLACED BOTTOM RH MUDFLAP ON BAR. | | 09/07/2022 | 133795 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | Right Hand Windscreen replacement. | | | | | | | | | |
| 1055 | Wodonga - Workshop | Albury Autoscreens PO# WW072836 | | 07/07/2022 | 527261 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PICK UP HTT. | | 29/06/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | REPLACED RH WIPER. ADDED 5L ENGINE OIL. | 29/06/2022 | 125241 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Trailer ABS still inop - wiring between a & b, works when only b is connected to prime mover | | 29/06/2022 | 125241 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | | Perform laser wheel alignment. | | | | | | | | |
| 1055 | Wodonga - Workshop | Wheel alignment required | JUMP STARTED. UN HOOKED. DROPPED AT HTT. | 29/06/2022 | 125241 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1055 | Wodonga - Workshop | VIBRATION 60-90. SETTLES DOWN AT 100KM. | | 29/06/2022 | 125241 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BAD RATTLE FROM STEERING COLUMN AREA, LOWER DASH. | | 29/06/2022 | 125241 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR SHIFTER BOOT SPLIT. | | 29/06/2022 | 125241 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 29/06/2022 | 125241 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | POS 3-10 | | 25/06/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | supply and fit 2tyres | | 25/06/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PICK UP TCTC. | | 04/06/2022 | 104856 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | JUMP STARTED. | | 29/05/2022 | 104526 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | REPLACED DAMAGED EBS PLUG. | | 24/05/2022 | 103456 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | JUMP STARTED. | | 24/05/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | JUMP START. | | 18/05/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 11/05/2022 | 99648 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT DIFF NEEDS TO BE RESEALED. | | 11/05/2022 | 99648 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | TANK STEP CHECKER PLATE NEEDS REPLACING AFTER TOWING STANDARD SET. | | 11/05/2022 | 99648 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | NEED NEW WIPERS AND AIM WASHER JETS PLEASE. | | 11/05/2022 | 99648 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PYRO LOOSE | | 11/05/2022 | 99648 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | L/H WINDSCREEN CRACKED. | | 11/05/2022 | 99648 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 11/05/2022 | 99648 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | OIL Replace Diff Oils | | | | | | | | | |
| 1055 | Wodonga - Workshop | Done @ 98,064 Klms. | | 07/05/2022 | 796519 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | L/H Windscreen Replacement | | | | | | | | | |
| 1055 | Wodonga - Workshop | Albury Autoscreen PO# WW071641 | | 06/05/2022 | 527117 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | | Engine Oil Sample SIF # 42622469 | | | | | | | | |
| | | B Service As Per Attached Checklist | Front Diff Oil Sample SIF # 42622385 | | | | | | | | |
| 1055 | Wodonga - Workshop | Change Diff Oils | Rear Diff Oil Sample SIF # 42620637 | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RESEAL FRONT DIFF | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | EXCESSIVLY LOUD BRAKE SQUEAL-R/H/R. | | | | | | | | | |
| 1055 | Wodonga - Workshop | -REALLY BAD FOR A NEW TRUCK. | TEST DROVE. BRAKES NOT NOISY. | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | EBS LIGHT ON. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | R/H STEER TO BE FLIPPED. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ABNORMAL TYRE WEAR. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PULLING LEFT, STEERING WHEEL OFF CENTRE. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | ROOF LEAKS WHEN IT RAINS- WATER IS COMING IN THROUGH THE L/H SPEAKER AND RUNNING INTO THE DASI | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BAD RATTLE FROM STEERING COLUMN AREA, LOWER DASH. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | GEAR SHIFTER BOOT SPLIT. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | BRAKE NOISE VERY BAD. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PULLING LEFT ALL OF A SUDDEN- STEERING WHEEL NOT STRAIGHT. | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 27/04/2022 | 91991 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | ADDED 10L ENGINE OIL. | 30/03/2022 | 74418 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FRONT DIFF CENTRE LEAKING. | | 30/03/2022 | 74418 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 30/03/2022 | 74418 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | L/H WINDOW CRACKED. | | | | | | | | | |
| | | Replace L/H Window. | | | | | | | | | |
| | | Albury Autoscreen | | | | | | | | | |
| 1055 | Wodonga - Workshop | PO#WW071020. L/H WINDOW CRACKED. | | 29/03/2022 | 527117 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | POS 1 & 2 | | 27/02/2022 | 48703 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | fit new rims and balance | | 23/02/2022 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | ADJUSTED CLUTCH. | 16/02/2022 | 39959 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 16/02/2022 | 39959 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PICK UP HTT. | | 11/02/2022 | 37162 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | RADIO LOOSES POWER, RESETS & COMES BACK ON. | TCTC | 02/02/2022 | 31025 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | DAMAGED FROM BLOWOUT: | | | | | | | | | |
| | | X1 MIRROR POLISHED RIM | | | | | | | | | |
| | | RH HEADLIGHT COVER | | | | | | | | | |
| | | NUT COVERS | | | | | | | | | |
| 1055 | Wodonga - Workshop | KW CENTRE CAP | TCTC | 02/02/2022 | 31025 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | A Service As Per Attached Checklist | | 02/02/2022 | 31025 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job | | 02/02/2022 | 31025 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | LIMITER TO BE INCREASED 96 TO 100 | TCTC | 02/02/2022 | 31025 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | SEVERE BRAKE SQUEAL R/H/F. | TCTC | 02/02/2022 | 31025 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | | The following 1st service inspection for Greenfreight Distribution Pty Ltd, to a | | | | | | | | |
| | | | K200 Kenworth Truck, | | | | | | | | |
| | | | Chassis#6F5000000MA471425, and registration #XV18VU included: | | | | | | | | |
| | | | . | | | | | | | | |
| | | | * Removed/replaced engine filter & oil, specification used in parts section | | | | | | | | |
| | | | below. | | | | | | | | |
| | | | * Check all engine operation & components | | | | | | | | |
| | | | * Removed/replaced transmission oil filter | | | | | | | | |
| | | | * Check all hydraulic lines fitting & level lubricant levels to specification | | | | | | | | |
| | | | * Removed/replaced power steering filter & gasket | | | | | | | | |
| | | | * Removed/replaced differential oil, specification used in parts section | | | | | | | | |
| | | | below. | | | | | | | | |
| | | | * Removed/replaced fuel filter | | | | | | | | |
| | | | * Check cooling system & pressure test | | | | | | | | |
| | | | * Check all belts, idler pulleys, fan, shrouds & adjust to specification | | | | | | | | |
| | | | * Check all electrical routing, wiring looms, switches, sensors & components | | | | | | | | |
| | | | * Check all wheel equipment & steering components | | | | | | | | |
| | | | * Check all braking & adjust to specification | | | | | | | | |
| | | | * Check clutching & adjust to specification | | | | | | | | |
| | | | * Check all suspension components | | | | | | | | |
| | | | * Check all internal cabin operation, components & adjust to specification | | | | | | | | |
| | | | * Check all external cabin components & adjust to specification | | | | | | | | |
| | | | * Check windscreen washers, wipers, refill & test operation | | | | | | | | |
| | | | * Lubricate, adjust relevant components as required | | | | | | | | |
| | | | * Re torque all fitting & fixtures | | | | | | | | |
| | | | * Wash vehicle complete | | | | | | | | |
| 1055 | Wodonga - Workshop | C Service As Per Attached Checklist | * Road test, confirm & quality check | 12/01/2022 | 12714 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | GF GRAHAM CONTACTED BREAKDOWN TECHNICIAN AT 10.00PM 11/1/22, REQUESTING TO OPEN DEALERSHIP<br>SO GF<br>COULD PICK THE TRUCK UP.<br>TECHNICIAN OPENED UP DEALERSHIP, GF PICKED UP TRUCK & RETURNED TO SERVICE.<br>TECHNICIAN SECURED DEALERSHIP & RETURNED HOME | | | | | | | | | |
| 1055 | Wodonga - Workshop | 2 HOURS CHARGED ONLY $ 350.00 (MINIMUM RATE NORMALLY $ 612.50) | | 12/01/2022 | 12714 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Record Check Results As Attached To This Job<br>Front right hand side major scuff marks from tyre.<br>Body will need to be buffed out.<br>TCTC (Lance Warr) has been made aware of this. | | 12/01/2022 | 12714 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Ash has photos on his phone.<br>Booster Damaged due to Blowout<br>PACCAR Called to attend | | 06/01/2022 | 527117 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | To be billed to TCTC as this a new truck. | | 06/01/2022 | 527117 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | Blown Steer Tyre.<br>Beaurepairs Contacted to attend.<br>To be billed to TCTC as this is a new truck. | Warrick Beaurepairs WW069892 issued for tyre.<br>TCTC have responded with they cannot get warranty on tyre as the photos taken and given to Goodyear they have looked at and have come to the | | | | | | | | |
| 1055 | Wodonga - Workshop | Called paccar assitt to replace RH steer brake booster as damaged from blow out | conclusion the tyre ran over a foreign object and caused the blow out. | 06/01/2022 | 527117 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | JUMP STARTED TRUCK | | 14/12/2021 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | FITTED SEAT COVER TO DRIVERS SEAT. | | 02/12/2021 | 586 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | pre delivery as per check list | TARE= 10850KG | 26/11/2021 | 584 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | reset air bag height to comply with PBS<br>2 x Stickers 3 Points of Contact<br>Safepak Albury | TCTC to carry out adjustment | 25/11/2021 | 527117 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | PO#WW068703 | | 22/11/2021 | 527117 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 9 + 10 | | 19/11/2021 | 454 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 7 + 8 | | 19/11/2021 | 454 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | Tyre Position 5 + 6 | | 19/11/2021 | 454 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| 1055 | Wodonga - Workshop | supply and fit 8 tyres | | 19/11/2021 | 454 | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |
| | | Tablet serial # 000041725<br>Tracking unit serial # 479001825<br>Tracking unit sim card # 8200098249533<br>Tag #'s 024948 & 024947<br>MDVR serial # C704CBAFC1727<br>Phone # 0409934652 | Mount and wire up supplied IAP tracking unit under passenger seat.<br>Mount GPS and high gain antennas on rope rail above LH door just behind door. Mount tablet and mic above radio & gauges, mount speaker above rear<br>of RH door. Mount MDVR under passenger seat, wire up, mount forward facing<br>camera, run wiring and connect camera to MDVR. Connect and wire in engine<br>data control box to CAN wiring & power and earth as necessary. Connect scales<br>to tracking unit. Connect power, earth & ignition, mic and speaker, re-assemble<br>truck and test. Contact MtData support to setup and test unit. Complete IAP | | | | | | | | |
| 1055 | Wodonga - Workshop | Support persons name - Martin | paperwork & send off. | 27/10/2021 | | Completed | Wodonga | HCU | XV18VU | Wodonga Workshop | P/MOVER |