EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Location	Division	Rego	Supplier	EquipmentType
1054	Wodonga - Workshop	VehService\AS A Service	Aaron also on job Labour-Mobile-A/H Breakdown Traveled to Yass Service Centre Southbound Inspected truck losing coolant from the heater corE area Removed the lower kick panel on the passenger side of the cab and found the bottom of the cab full of coolant Visually inspected and felt all heateR hoses for damage—No damage found on any of the lines Inspected underneath the truck and found oil spread extensively across the underside Checked the engine oil level—No oil was present on the dipstick Added engine oil until the level reached half way on the dipstick Filled the radiator with ten litres of red coolant concentrate and ten litres of water Turned both heater taps off Ran the truck at high idle for ten minutes The check-engine lights cleared,no coolant leaks were visible, and the oil level remained stable	15/07/2026	795405	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Cooling\COOL LEAKS	Packed up the service truck and returned to Goulburn	24/06/2026	787046	Wodonga	LHB	XV17VU	WARREGO TRANSPORT REPAIRS	P/MOVER
1054	Wodonga - Workshop	Tyres\TP11+12	LOW	18/06/2026	787047	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP7+8	LOW	18/06/2026	787047	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP9+10	LOW	18/06/2026	787047	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP5+6	LOW	18/06/2026	787047	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Heater Core Leaking Replace/Repair		18/06/2026	786631	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\AS A Service	completed by SS JS EC	18/06/2026	786631	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Body\DAMAGE	REPLACE TRAILER PLUG	14/05/2026	770462	Wodonga	LHB	XV17VU	ADELAIDE TRUCK CENTRE	P/MOVER
1054	Wodonga - Workshop	DrivLine\DIFF OIL		02/05/2026	765696	Wodonga	LHB	XV17VU	CALLAWAY DIESEL	P/MOVER
1054	Wodonga - Workshop	Transmission Oil Change		02/05/2026	765696	Wodonga	LHB	XV17VU	CALLAWAY DIESEL	P/MOVER
1054	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months	Carry Out C Service As per Attached Service Service Sheets $1,700.00 Filter Kit x 1 (Parts Charge) $500.00 Air Filter x 1 (Parts Charge) $135.85 Remove And Replace All Rear Mud Guards (Labour Charge)4Hrs $620.00 Wheel Guards x 4 (Parts Charge) $425.00 Guard Bracket x 1 (Parts Charge) $22.12 1st axle Pinion Seal Leaking At Diff, Remove Tail shaft, Remove Pinion Nut, Remove Yoke, Remove Seal, Upon Removal Of Yoke It was Noted That Yoke Is U/s And New yoke Required Travel To Collect New required Parts Return To Callaway Workshops and Fit New Seal, Fit New yoke, Fit new Pinion Nut Lock tight and Torque To Spec, Refit Tail shaft Assembly And Torque Tail shaft Bolts To Spec,Drain And Replace diff Oils Bothdiffs, Clean Diff Breathers (Labour Charge)4Hrs $620.00 Yoke Spl250 x 1 (Parts Charge) $1,625.00 Pinion Seal And Nut Kit x 1 (Parts Charge) $238.60 40 Litres Diff Oil (Parts Charge) $440.00 1st Drive Axle Hub Seals Goe And Contaminated Brakes Shoes,Mangers Informed, New Brakes Required, Once Drums Were Removed It was Noted That Drums Have Excessive Lips, New Drums Required, Remove and Replace 1st axle Hub Seals Both Side, Carry Out Bearing Adjustment, Remove and Replace Brake shoes and drums Both Sides Refit Wheels And tyres Torque All Wheel nuts To Spec(Labour	02/05/2026	765696	Wodonga	LHB	XV17VU	CALLAWAY DIESEL	P/MOVER
1054	Wodonga - Workshop	VehService\CS C Service Steering\STEER UNI Reline RF drive hub-est $300 Replace front input shaft seal on front diff-est $350 Replace 4 guards-est $450	Charge)4hrs	02/05/2026	765696	Wodonga	LHB	XV17VU	CALLAWAY DIESEL	P/MOVER
1054	Wodonga - Workshop			02/05/2026	765696	Wodonga	LHB	XV17VU	CALLAWAY DIESEL	P/MOVER
1054	Wodonga - Workshop	Steer wheel bearings		02/05/2026	765696	Wodonga	LHB	XV17VU	CALLAWAY DIESEL	P/MOVER
1054	Wodonga - Workshop	Tyres\Punct POS 6		20/03/2026	748211	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Air line's has a hole in it. [Replace Suzi Line's]		19/03/2026	746151	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Checker plate has been bent up.[Deck Plate]		19/03/2026	746151	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyres\RUN OUT POS 6		28/02/2026	741238	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP05		28/02/2026	741238	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	VehService\AS A Service		28/02/2026	738835	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER

			ROAD SIDE SERVICE TO HUME, 40KMS. FOUND OIL LEAKING FROM HUB CAP. REMOVED HUB CAB AND FOUND METAL CHUNCKS IN HUB. REMOVED AND CLEANED HUB. REPLACED INNER AND OUTTER BEARINGS.							
1054	Wodonga - Workshop	Steering\HUBCAP	REASSEMBLED TRUCK, ALL OK. FLEET #1054 TRAVEL TO SOLARIA PAPER PEMULWAY DEFECT MAJOR LEAK INSPECT POWER STEER UNIT FOR MAJOR LEAK NOTE: RETURN TO WORKSHOP TO DIAGNOSE WASH ENGINE TO DIAGNOSE LEAKS DIAGNOSE MAJOR COOLANT LEAK REPAIR LEAK TOP UP COOLANT TEST DRIVE & CHECK FOR LEAKS	24/02/2026	737334	Wodonga	LHB	XV17VU	CANBERRA TRUCK REPAIRS	P/MOVER
1054	Wodonga - Workshop	Engine\COOL LEAKS	INSPECT & TOP UP ENGINE OIL	12/02/2026	734874	Wodonga	LHB	XV17VU	G & S DIESEL SERVICE	P/MOVER
1054	Wodonga - Workshop	Tyres\TP08	SIDE WALL CRACKED FROM IMPACT	03/02/2026	728497	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP1+2		03/02/2026	729360	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Water temp gauge not working.		03/02/2026	731198	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Both rears need reline		03/02/2026	731198	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	No brake or reverse light reverse buzzer also not working		03/02/2026	731198	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Repair/Replace Deck plate.		03/02/2026	731198	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\AS A Service		16/01/2026	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		DrCabElect\IAP	Removed gaurdian unit from its housing to plug in the scan tool. Check the operation of the gaurdian unit, found the forward facing camera was not working and a fault in the buzzer. Remove the required panels to get to the camera wiring. Found the wiring was damaged. Unplug and test with a new camera. Diagnosed the camera to be faulty, fit new camera. Fit all removed panels correctly. Check the buzzer, found the buzzer was not faulty after speaking with gaurdian tech support but the software installed into the unit was faulty. Need to reboot the unit with a new software callibration. Test, the unit is now working correctly. Put the unit back into its housing.							
1054	Wodonga - Workshop	GUARDIAN FAULT - LOSS CONTACT WW098027		19/11/2025	720672	Wodonga	LHB	XV17VU	ARKON AUTO ELECTRICAL	P/MOVER
1054	Wodonga - Workshop	Wind shield on driver's door window about to fall off.		18/11/2025	712843	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Truck Stink's when A/C is on.		18/11/2025	712843	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACED FUEL PRO FILTER		08/11/2025	685338	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			ADJUSTED CLUTCH.							
1054	Wodonga - Workshop	CLUTCH NEEDS ADJUSTING	S.McCABE	08/11/2025	685338	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	PANEL BEAT WALK PLATE. MADE HOLD DOWN BRACKETS. FIT		08/11/2025	685338	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			Respond To Breakdown Call Mangers Report Truck Doesn't Start, Travel from Callaway workshops To Site In sunshine,(Labour Charge)20Mins Jump Start Truck, Truck Fails to Start,New Batteries Required, Remove Batteries Travel To Supplier To collect new batteries Return To Site And Fit Start Run test All Ok (Labour Charge) 2Hrs Batteries 12volt x 4 (Parts Charge) Workshop consumbales Charge							
1054	Wodonga - Workshop	Engine\BATTERY	Return To Callaway Workshops (Labour Charge)20mins	05/11/2025	694888	Wodonga	LHB	XV17VU	CALLAWAY DIESEL	P/MOVER
		B Service								
1054	Wodonga - Workshop	Serviced @		29/10/2025	689216	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACED FAULTY UNLOADER VALVE		29/10/2025	689216	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACED POWER STEERING PUMP GASKET		29/10/2025	689216	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Flex leaking		29/10/2025	689216	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Replace Fan Belt		29/10/2025	689216	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Body\WIPERS NEW WIPER BLADES	RUBBER WIPER REFILL X 2	30/09/2025	676092	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	Tyres\TP5+6		15/08/2025	652686	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP11+12		15/08/2025	652686	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP7+8		15/08/2025	652686	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP9+10		15/08/2025	652686	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	engine gauge not working (temp)		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	fuel gauge out by a quarter		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	ride height on rear to be checked		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	LHS tank to be welded (torn on top)		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	3x Drive Tyres Need Replacing On Front Diff Right Inner Alrea		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Check All Tyres Vibration		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	ENGINE NOISEY. SHOULD HAVE BEEN RE-RINGED AS WELL.		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		A Service								
1054	Wodonga - Workshop	Serviced @ 635,029 Klms.		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Check Steer Brakes Noisy Under Braking		29/07/2025	638834	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER

		Brakes Making Grinding Noise When Stopping.								
1054	Wodonga - Workshop	(Ttransall Motors P/O: WW095929)		29/07/2025	720866	Wodonga	LHB	XV17VU	TRANSALL MOTORS - 3	P/MOVER
1054	Wodonga - Workshop	DIAGNOSED AND REPLACED ADBLUE DOSER PUMP.		25/07/2025	638335	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACED EXHAUST GASKET.		25/07/2025	638335	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Workshop\MOVE ASSET								
1054	Wodonga - Workshop	move around organise RHSR brake reline		15/07/2025	629811	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			BUSINESS HOURS CALL OUT							
			Priority response call out / break down during normal business hours							
			TRAVLOC 1.00 TRAVEL LOCAL AREA							
			TRAVELLED FROM 19 HALE ST BOTANY TO 1891 BOTANY RD, MATRAVILLE							
			TRAVELLED FROM 1891 BOTANY RD, MATRAVILLE TO 19 HALE ST BOTANY							
			REMOVED AND REPLACED AIR SUZI COILS							
			REMOVED OLD 7 PING TRAILER PLUG, WIRED LEAD ONTO NEW							
		Repair Damaged Air Suzie Leads.	PLUG AND INSTALLED PLUG. 5 PIN SETUP, WIRES INSTALLED BASED							
1054	Wodonga - Workshop	(JRB Mechanical P/O: WW095593)	ON CUSTOMER PROVIDED PIN OUT	15/07/2025	631156	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Front End Moving Grease X2 :)		11/07/2025	627760	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	3 guage lights not working		11/07/2025	627760	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	front shocks to be looked at rough to drive on left banging		11/07/2025	627760	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	wipers to be replaced		11/07/2025	627760	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\AS A Service		11/07/2025	627760	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	2 guards to be replaced		11/07/2025	627760	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyres\Puncture POS 1		09/07/2025	627141	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Tyres\TP1+2		08/07/2025	626815	Wodonga	LHB	XV17VU	BORDER BANDAG PTY LTD	P/MOVER
1054	Wodonga - Workshop	Check Front End Bushes	REPLACED LR UPPER SPRING SHACKLE AND PIN.	26/06/2025	619127	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\AS A Service		26/06/2025	619127	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Adjust governor		26/06/2025	619127	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	EXHAUST LEAK AFTER TURBO.		26/06/2025	619127	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Unhook trailers and move truck into workshop for service		25/06/2025	619127	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			CHECKED ALL AIRBAGS. OK.							
1054	Wodonga - Workshop	Check Left rear Air Bag	S.McCABE.	20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			INSPECTED. NO FAULT FOUND.							
1054	Wodonga - Workshop	Squeaking Could Be Belt Not Sure	S.McCABE.	20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Clean truck inside and out		20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Front Diff Going Up To 100c FRTRR RR RR Going Up As Well Cl	Checked diff oils at service, levels ok	20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	HUB SEAL LEAKING.	Ethan / Dan replaced bearings and seal during break re line	20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Service Truck		20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			Rhs middle loose and							
			Rear shock loose needs new bushings							
			Rhs middle hub seal leak							
			Replaced first aid kit							
1054	Wodonga - Workshop	VehService\AS	Replaced X3 blown dash globes	20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Torque rod bushes worn		20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			REPLACED ALL BUSHES.							
1054	Wodonga - Workshop	Sway bar bushes worn		20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			REPLACED BOOT.							
1054	Wodonga - Workshop	NEED NEW SHIFT BOOT. HAS A HOLE.	S.McCABE.	20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Full drive reline		20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Turn Table Need To Be Adjusted Sloppy In Jaw	Adjusted	20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	TEMP GAUGE NOT WORKING.		20/05/2025	601014	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyres\Puncture PO 5		19/05/2025	600292	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	AIR LEAKING, STRUGGLING TO BUILD AIR UP.	Tightened loose air fitting on airdryer	10/05/2025	590664	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACED AIR DRYER.		15/04/2025	581192	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACED LF HUB SEAL.		15/04/2025	581192	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	ADJUSTED DIFF.		15/04/2025	581192	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	LHF drive hub seal starting to leak	Replaced seal and bearings	15/04/2025	580860	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Air dryer blown out gasket		15/04/2025	580860	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\BS		15/04/2025	580860	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Clutch Replaced & Install Kit Fitted. (TRP Pakenham P/O: WW		12/04/2025	579676	Wodonga	LHB	XV17VU	CUMMINS SOUTH PACIFIC P/L	P/MOVER
		Engine Rebuild Due To Dropped Liner, Engine Block Replaced Due to Soft Metal When Counter-Bore Were Cut.								
1054	Wodonga - Workshop	(Cummins Pakenham P/O: WW093932)		12/04/2025	579676	Wodonga	LHB	XV17VU	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1054	Wodonga - Workshop	Check Engine Coolant Usage. (Cummins Pakenham P/O: WW0		26/03/2025	579539	Wodonga	LHB	XV17VU	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1054	Wodonga - Workshop	PLATE ON BACK OF TRUCK REPLACE.	Repaired during C service	18/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	TURNTABLE NEEDS TO TO BE CHANGED.	Previously completed	18/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	SERVICE	Completed C service	18/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			Horton hub swapped out for spare rebuilt hub and replaced hose due to damaged hose end - 15/3/25							
1054	Wodonga - Workshop	Horton fan hub due for rebuild	Horton being rebuilt as spare - 17/3/25	18/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Annual Inspection		18/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	C Service		18/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	TICKING, KNOCKING SOUND COMING FROM UNDER CAB.	Previously completed, ref Shaun.	16/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	TRAILER RELEASE VALVE LEAKING AIR.		16/03/2025	717364	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER

1054	Wodonga - Workshop	QT DIESEL- TRUCK OUT OF FUEL- BARRABOOL RD, GEELONG		05/03/2025	573371	Wodonga	LHB	XV17VU	QT DIESEL SERVICES	P/MOVER
1054	Wodonga - Workshop	ADJUST CLUTCH	ADJUSTED CLUTCH BRAKE AND FREE TRAVEL.	28/02/2025	561892	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Clutch Adjust.	Duplicate job	04/02/2025	550957	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Cruise light & front air guage light Not Working.	Cherish completed this job	04/02/2025	550957	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\BS	547152ks	04/02/2025	550957	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Right Steer Wheel Bearing Need To Be Checked.		04/02/2025	550957	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			All the bolts are in this plate It needs a new chequer plate as this has been damaged and does not correctly due to							
1054	Wodonga - Workshop	CHECKER PLATE BACK OF TRUCK NEEDS BOLT & BENT BACK D	attempted repairs	04/02/2025	550957	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Adjust Clutch.		04/02/2025	550957	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyres\TP01		14/01/2025	538799	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	Tyres\TP01		18/12/2024	527251	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	Tyres\TP1+2		10/12/2024	521698	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	Tyres\TP01		04/12/2024	518534	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
		CALL OUT CMV. TRAVELLED TO TRUCK NEAR MURRAY BRIDGE. CHECKED								
1054	Wodonga - Workshop	GEARBOX OIL AND WIRING. REPLACED SENSOR AND FILTER.		03/12/2024	513816	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\AS	500426ks	09/11/2024	504226	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Heater not working, fibreglass D/S panel broken, holes in gua		09/11/2024	504226	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Susp\Torque Rod TORQUE ROD WHILST CARRYING OUT REPAIRS, FOUND MULTIPLE TORQUE								
1054	Wodonga - Workshop	ROD BUSHES WORN		16/10/2024	495119	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
		Diff Oil Change DIFF OIL REPLACEMENT REPLACED DIFF OILS WHILST CARRYING OUT DIFF RESEALS -								
1054	Wodonga - Workshop	WARRANTY REPAIRS		16/10/2024	495119	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
		Brakes\BRAKE ADJ WHILST CARRYING OUT REPAIRS, FOUND FRONT DRIVE BRAKES LOW . * Ballast axle & removed wheel end equipment * Removed drum & hub assemblies * Removed & replaced brake shoes * Checked wheel bearings - All ok * Greased all components * Refit hubs & adjusted all components * Refit all components * Aligned, adjusted & tensioned all components									
1054	Wodonga - Workshop	* Test operations - All ok		16/10/2024	495119	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
		DIFFS LEAKING OIL. SPRAYING EVERYWHERE FROM REAR DRIVE BACK.								
1054	Wodonga - Workshop	DIFF OIL REPLACEMENT		16/10/2024	495119	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
		diffs leaking oil spraying everywhere from rear drive back								
1054	Wodonga - Workshop	DIFF OIL REPLACEMENT		16/10/2024	495119	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1054	Wodonga - Workshop	CLUTCH ADJUSTED- BADLY.		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	NEATON SUZI COILS.		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	WIPER BLADES.		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	NO CHECKER PLATE.		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	TRAILER PLUG.		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	no checker plate		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	neaton suzi coils		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	wiper blades		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	clutch adjustment - badly		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	trailer plug		10/10/2024	490827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	DRIVER SEAT LEAKING AIR.	COULDN'T FAULT.	05/10/2024	494632	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		A Service Serviced @ 490,068 Klms								
1054	Wodonga - Workshop			03/10/2024	490068	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Repair/Replace Brake Suzie Leads. (G&S Diesel's P/O: WW08		03/09/2024	493874	Wodonga	LHB	XV17VU	G & S DIESEL SERVICE	P/MOVER
1054	Wodonga - Workshop	Tyres\TP1+2		27/08/2024	479056	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	Replace Radio.		20/08/2024	476126	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			Doug did the top							
1054	Wodonga - Workshop	B Service	Keith did the bottom	20/08/2024	476126	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Replace Leaking Hub Seal & Brake Shoes (Elite Diesel's P/O: V		07/08/2024	472199	Wodonga	LHB	XV17VU	ELITE DIESEL REPAIRS	P/MOVER
1054	Wodonga - Workshop	Tyres\TP3+4		29/07/2024	472199	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	Tyres\TP9+10		29/07/2024	472199	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	Tyres\TP5+6		29/07/2024	472199	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER
1054	Wodonga - Workshop	Tyres\TP7+8		29/07/2024	472199	Wodonga	LHB	XV17VU	BEAUREPAIRES	P/MOVER

1054	Wodonga - Workshop	Engine\START MOTR REPORTS STARTER CABLES SHORTED OUT & FRIED STARTER $2,346.39 . * Inspected starter components & found earth wires & starter to be burnt out * Unbolted & removed starter motor * Installed replacement starter motor * Test operations & found starter motor constantly trying to engage * Inspected all components & found earthing fault present * Removed & replaced all burnt out earths * Replaced earth from starter to battery & alternator earth * Cleaned & inspected all other earths * Found cab earths to be loose * Tensioned all to specifications * Whilst carrying out inspections, found damaged wiring behind oil filler neck * Repaired as required * Refit batteries & all connections * Test operations - All ok, starter motor now engaging as required	26/07/2024	472087	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1054	Wodonga - Workshop	Engine\FAULT CODE Test operations - All ok, fault no longer present	26/07/2024	472087	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1054	Wodonga - Workshop	DrivLine\GEARBOX TRUCK TOWED IN AS UNABLE TO SELECT GEARS $502.80 . * Test operations & confirmed fault * Found unable to move gear shifter side to side * Inspected shift cables & found to be melted due to earthing fault * Disconnected & removed gear shift cables * Installed replacement cables with replacement clamps * Installed heat shielding & secured all in place * Aligned, adjusted & tensioned all to specifications * Test operations - All ok, fault no longer present	26/07/2024	472087	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1054	Wodonga - Workshop	DrivLine\CLUTCH ADJUSTED CLUTCH AS REQUESTED $251.40 . * Inspect clutch components & assembly * Found clutch lever & free travel adjuster worn * Removed & replaced free travel adjuster, spring & clutch lever * Adjusted clutch to specifications * Test operations - All ok, fault no longer present	26/07/2024	472087	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1054	Wodonga - Workshop	Truck Won't Select Reverse Tow 1056 To 1054 In Yarrawoga T	20/07/2024	472056	Wodonga	LHB	XV17VU	AAA TOWING SERVICE	P/MOVER
1054	Wodonga - Workshop	Truck Won't Start Check & Test Batteries Replace If Needed (	21/06/2024	459180	Wodonga	LHB	XV17VU	PACCAR PARTS FLEET SERVICES	P/MOVER
1054	Wodonga - Workshop	REPAIRED AIR LEAK AT SEAT.	17/05/2024	442011	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Jump Start & Check Batteries (Barry Maney P/O: WW085157	04/04/2024	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	1-2	29/03/2024	420680	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	1-2	29/03/2024	420680	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	CHECK OVER FOR AIR LEAKS - Checked over complete truck and found drain on top air tank leaking. Remove and replaced drain bung, re check for leaks all okay.	23/03/2024	420680	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACE WIPER BLADES - Replaced wiper blades	23/03/2024	420680	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	RHR DRIVE BACKING PLATE LOOSE - Tensioned all backing pla	23/03/2024	420680	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	CLUTCH ADJUSTMENT - Carried out clutch adjustment as requ	23/03/2024	420680	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist	23/03/2024	420680	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job	23/03/2024	420680	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER

		BREAKDOWN - Afterhours breakdown - 3PM - 7AM 4.92 $1,081.67 LOCATION: Western Highway, Trawalla CONTACT: Driver 0417 150 350 FAULT: Blown drive airbag. . Travelled to KDM & Collected parts. Travelled to site. Inspected vehicle identified drive tyre had blown and damaged airbag. Removed & Replaced airbag as required. Built up air pressure and checked over for leaks - Ok.							
1054	Wodonga - Workshop	Packed up & Departed site.	07/03/2024	464349	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 8	07/03/2024	420680	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Myrtleford - Workshop	LH STEER OIL LEAK - Inspect oil leak, found to be from hub cap gasket. Removed bolts & hub cap. Cleaned off gasket & install new. Tightened bolts, ok.	24/02/2024	406347	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Myrtleford - Workshop	CHECK BELTS & PULLEYS FOR RATTLE OR SQUEAL NOISE - checked belts, okay. Found noise coming from A/C belt tensioner. Removed belts and remove tensioner. Installed new, refit belts.	24/02/2024	406347	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	REKIT AIR DRIER - Removed air drier and installed rekit as requ	13/02/2024	400880	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	WORN SHOCKER BUSHES - Replace worn shocker bushes on LH rear shocker. Tighted RH rear shcoker bolts.	13/02/2024	400880	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	ADJUST CLUTCH - Inspect clutch gap & free play, all within spe	13/02/2024	400880	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	AIR LEAK - Checked over with soapy water. Brakes on and off,	13/02/2024	400880	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	WASHER BOTTLE MISSING BOLT - Installed new screw as requ	13/02/2024	400880	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	C Service As Per Attached Checklist. PO# WW084021	13/02/2024	400880	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job	13/02/2024	400880	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	CHECK ABS CODES - Connect laptop and check ABS codes. No codes present. Take vehicle for a test drive, all okay.	26/01/2024	392116	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	ENGINE BRAKE LIGHT N/W - Remove dash cluster, replace blo	26/01/2024	392116	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	ADJUST CLUTCH - carried out clutch adjustment to spec.	26/01/2024	392116	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	CHECK LIGHTS - Checked over indicators for fault, found issue with trailer plug, wire for indicator had come out. Re join wire into plug check operation all okay.	16/01/2024	381642	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	SUZI LEADS RIPPED OUT AGAIN - need to change set up and replace suzi's to different length Suzis are getting caught on EBS plug due to low turntable. Removed plug from location & drilled hole in new location for plug. Run wiring and mount plug, wired in & connect. Remvoed old EBS lead & connect. Removed old EBS lead & run new lead to suit. Rerun all suzi lines to prevent them getting caught due to the low turntable & all lines continuously getting caught up on the deck plate.	16/01/2024	381642	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	REPLACE STEER AND DRIVE HUB CAPS AS SUPPLIED BY DRIVER - Installed new steer & drive hub caps as supplied by driver.	06/01/2024	380523	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	TRAILER PLUG DAMAGED - Found trailer plug and EBS leads were damaged. Replaced trailer light plug & joined wiring. Repalced EBS lead on truck.	06/01/2024	380523	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	INSPECT DRIVELINE VIBRATION - Found yoke nut had come loose on back of gearbox and has rust behind it. Unbolt and removed tail shaft removed yoke nut. Installed new yoke nut and refit tail shaft with new bolts. Tensioned.	06/01/2024	380523	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	CHECK STEERING - VIBRATION THROUGH STEERING WHEEL - Check uni joints on steering arm, all okay. Checked pitman arm, all okay. Greased all steering components. Jacked front axle and check king pins, all okay.	06/01/2024	380523	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	NEATEN SUZI COILS GETTING CAUGHT UP - Tidy up suzi coils t	06/01/2024	380523	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	REPAIR DASH LIGHTS N/W - Removed dash cluster, replaced b	06/01/2024	380523	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 1 + 2	06/01/2024		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist	04/01/2024	380523	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job	04/01/2024	380523	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Myrtleford - Workshop	JUMP START	19/12/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER

1054	Wodonga - Workshop	REPLACE WIPER BLADES - Removed the old worn rubbers & fitted new ones, Cleaned windscreen & checked operation, all okay.		12/12/2023	368165	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	S&F NEW WEATHER SHEILD - Cleaned all surfaces and fitted tl		12/12/2023	368165	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	GEAR LEVER WON'T FOLD DOWN - Sprayed lube on the latch and hit with a mallet, when it moved up, found a clump of hair was jammed in the pivot point. Pulled the hair out with multigrips, okay.		12/12/2023	368165	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	ADJUST CLUTCH - carried out clutch adjustment to spec, all ok		12/12/2023	368165	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	AFTER TREATMENT LIGHT ON DASH - Driver asked to inspect after treatment light on dash. Advised it was due to batteries having low voltage. Still wanted it to be plugged into and checked. Connect laptop and check faults, Found inactive code for low battery voltage, cleared inactive code. No further faults.		25/11/2023	360000	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	JUMP START TRUCK - Travelled to Greenfreight yard, connect jumper pack & jump started truck. Truck returned to BMG workshop. Removed battery cover, load tested all batteries, found charge was low. Leave charger on over night. All okay following day.		25/11/2023	360000	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 8		31/10/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist Barry Maney PO# WW081398		03/10/2023	359997	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		03/10/2023	359997	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	1-10 Truck has EBS Faults		12/09/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Barry Maney PO#WW080912 WHEEL SEAL LEAKING Found RH steer wheel seal was leaking. Removed wheel, brake drum & hub. Removed leaking seal, cleaned bearings & hub. Installed new seal, refit hub. Filled hubs with new oil. Refit brake drum & wheel, adjusted bearing.		08/09/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	To Complete R/W within 12 months		05/09/2023	337738	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Barry Maney PO# WW080774		05/09/2023	347243	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist Barry Maney PO# WW080739		02/09/2023	347243	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		02/09/2023	347243	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	68 Angles For Reels (Barry Maney) Purchase Order Number: WW080750		01/09/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	RH WINDOW WASHER N/W - Blow out rubber lines, clean out supply. Tested, hose coming off washer jet. Secured hose properly, all okay.		23/08/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Steer Shaft Uni		21/08/2023	464349	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Check & Adjust Steer Brakes, Check Front End (MM Diesel's) Purchase Order Number: WW080316 Purchase Order Number: WW080366 Steering Box (Warranty)		15/08/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Mini B Service As Per Attached Checklist Please jack front and check steer king pins Barry Maney PO# WW080142		09/08/2023	335738	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		09/08/2023	335738	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist Barry Maney PO# WW079577		14/07/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		14/07/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	FOUND PRESSURE FAULTS DIAGNOSE ERRATIC FUEL PRESSURE REMOVE AND REPLACE FUEL FILTERS RUN TEST OK		21/06/2023	31153	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	After hours call out - After treatment light on Check fault codes, found 1 inactive fault for low fuel rail pressure. Jacked cab, check sensor & wiring. Carry out trouble shooting, found water in plug on engine harness, cleaned out and filled with dielectric grease, cleared faults, test drive with data monitoring, okay		21/06/2023	311208	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	B Service As Per Attached Checklist		16/06/2023	311062	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		16/06/2023	311062	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist (Barry Maney) Purchase Order Number: WW078748		03/06/2023	305286	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		03/06/2023	305286	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Check Charging Issue		20/05/2023	299307	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	UNABLE TO USE CRUISE CONTROL TO RAISE IDLE SPEED.	TESTED CRUISE CONTROL. REPLACED DASH GLOBE AND TESTED FUSES. AUTO ELEC TO COI	18/05/2023	298556	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	DIAGNOSED AND REPLACED FAULTY VOLT GAUGE.		18/05/2023	298556	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER

		CHECK CRUISE N/W TURNS ON TRAVEL TO GREENFREIGHT YARD test and found cruise not working hook up scantool and found ECU brake switch not working check wiring at switch and daignose switch as faulty remove and replace with one suplied by GF								
1054	Wodonga - Workshop	test and found working fine pack up and travel back		18/05/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop			17/05/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Replace reverse buzzer to comply with customer site. Brown & Hurley Darra								
1054	Wodonga - Workshop	PO# WW078353		15/05/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Driving Light		11/05/2023	291543	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	1&2		09/05/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
		A Service As Per Attached Checklist								
1054	Wodonga - Workshop	PO# WW078146		07/05/2023	291642	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		07/05/2023	291642	Wodonga	LHB	XV17VU	BARRY MANEY - 3	P/MOVER
		Load Angels (Barry Maney)								
1054	Wodonga - Workshop	Purchase Order Number: WW078165		05/05/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 1 + 2		03/05/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		27/04/2023	28426	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		27/04/2023	28426	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Replace Batteries		06/04/2023	275083	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
		A Service As Per Attached Checklist								
1054	Wodonga - Workshop	Barry Maney PO# WW077641		04/04/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		04/04/2023	464349	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	POS 1& 2		31/03/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
		Secure suzi lines								
1054	Wodonga - Workshop	Resecure suzi cords to pogo stick		26/03/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Supply and fit new wiper blades		26/03/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Service As Per Attached Checklist	FITTED HI-CUBE TURNTABLE.	17/03/2023	265596	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		17/03/2023	265596	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	trailer wiring pulled out	pat simon atending at ballarat weightbridge west bound. Payed By Dean	09/03/2023	464166	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	B Service As Per Attached Checklist	ADJUSTED TURNTABLE JAWS.	01/03/2023	255757	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		01/03/2023	255757	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 7		01/03/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
		Replace bent wiper arm drivers side. Removed the bent arm on drivers side, replaced with new								
1054	Wodonga - Workshop	part. Refitted arm, adjusted arm		28/02/2023	244453	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 7		24/02/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 9 + 10		19/02/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 7 + 8		19/02/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 5 + 6		19/02/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 3 + 4		19/02/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
		No Trailer Lights (Breakdown)								
1054	Wodonga - Workshop	M M Diesel Repairs Purchase Order Number: WW076721		13/02/2023	464166	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		XV17VU FLEET NUMBER 1054 241463KMS TRAVEL TO TRUCK STOP, REPLACE 7 PIN PLUG,								
1054	Wodonga - Workshop	TEST OPERATION		11/02/2023	241463	Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
		A Service As Per Attached Checklist								
1054	Wodonga - Workshop	Purchase Order Number: WW076670 (Barry Maney)		11/02/2023	244453	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		11/02/2023	244453	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	CHECKER PLATE NEEDS REPAIRING AROUND TURNTABLE.		12/01/2023		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist	FIT CHECKER PLATE. ADDED 4L ENGINE OIL.	07/01/2023	237088	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	*WHEEL ALIGNMENT*		07/01/2023	237088	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		07/01/2023	237088	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 1 + 2		07/01/2023		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
		Replace R/H Windscreen Autotek to repair								
1054	Wodonga - Workshop	PO# WW076030		06/01/2023	464166	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		08/12/2022	220101	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Replace Right Hand Guards		08/12/2022	220101	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		08/12/2022	220101	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Replace Cab Jack TCTC to do repair								
1054	Wodonga - Workshop	Truck is under Warranty		07/12/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tightened Grille Mounting Bolts		01/12/2022	215435	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Replaced Blown Dash Globes		01/12/2022	215435	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	loosen tank strap reposition cover plates, fit new bolt & tighte		25/11/2022		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	FLATTEN WALK PLATE.. MADE BRACKETS. BOLTED WALK PLAT		22/11/2022	211837	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 1 + 2		21/11/2022		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
			Travel to truck, driver said needed all new batteries. Jump stated truck, checked ,ok							
1054	Wodonga - Workshop	Jump Start	Flat as fridge left running in truck all weekend	20/11/2022		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER

		A Service As Per Attached Checklist								
1054	Wodonga - Workshop	Barry Maney PO# WW075149		17/11/2022	211070	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		THROUGH-SHAFT SEAL LEAKING. WARRANTY.								
1054	Wodonga - Workshop	Covered under Warranty.		17/11/2022	211070	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		17/11/2022	211070	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Snapped Belts and Pulley has fallen off.								
1054	Wodonga - Workshop	Towed to Brown & Hurley Kyogle.		03/11/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Checkover Bunk Cooler		29/10/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Install Extra Auxillary Power Socket		29/10/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		21/10/2022	197124	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	THROUGH-SHAFT SEAL LEAKING. WARRANTY.		21/10/2022	197124	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		21/10/2022	197124	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	C Service As Per Attached Checklist		08/10/2022	189483	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	*WHEEL ALIGNMENT*		08/10/2022	189483	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		08/10/2022	189483	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	NEEDS RATCHET ON PASSENGER SIDE FOR CURTAIN AND 6 BC	NOT TRUCK R&R	05/10/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop			04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	-Leak near LH cab ram		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	-RHF shock missing lower mount nut and bush		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Rear Diff Oil Leak		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	CHECK BATTERY (ALWAYS FLAT)		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	GRILL IS COMING LOOSE.		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	NEXT SERVICE PLEASE CHECK BATTERY.		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	FRONT DIFF LEAKING.		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Front diff leaking need back to go to TCTC for repair		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	RESEAL FRONT DIFF.		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	RESEAL FRONT DIFF.		04/10/2022	464005	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	TRUCK SERVICE.	Refer Job# 391917	27/09/2022	185867	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	B-SERVICE.	Refer Job# 391917	27/09/2022	185867	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist	TIGHTENED OIL FILTER.	27/09/2022	185867	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		27/09/2022	185867	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	NEW WINDSCREEN (PASSENGER SIDE)	Refer Job # 391915	27/09/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Replace Left Hand Windscreen								
		Truck Defected # HVN0630059								
1054	Wodonga - Workshop	Albury Autoglass PO# WW074273		27/09/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	JUMP START.	JUMP STARTED AT LINFOX SERVICE ROAD.	16/09/2022	179148	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACED DAMAGED SUZI COILS, EBS CABLE AND LIGHTS PLU		06/09/2022	173417	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist	REPLACED DIFF OILS.	30/08/2022	169828	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			Front Diff Oil Sample SIF # 43276632							
1054	Wodonga - Workshop	Replace both diff oils	Rear Diff Oil Sample SIF # 42627968	30/08/2022	169828	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		30/08/2022	169828	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	PBS CERTIFICATION		23/08/2022	464005	Wodonga	LHB	XV17VU	VAWDREY AUSTRALIA PTY LTD	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		02/08/2022	151922	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		02/08/2022	151922	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	ADJUSTED CLUTCH.		28/07/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	TURNTABLE NEEDS ADJUSTMENT.	REPLACED TUNTABLE WITH HIGHER ONE.	28/07/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Change turn table		22/07/2022	145512	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	change to higher turntable		22/07/2022	145512	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Perform laser wheel alignment on K200 prime mover after steer tyre blowout	Tyre make : New Goodyear mounted on new rims							
		Perform on vehicle steer wheel run out check :	Report left - Hung outer bead - tyre shaking							
1054	Wodonga - Workshop	Driver reports shaking	Report right - G ood	16/07/2022	141300	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	FRONT DIFF LEAKING.		15/07/2022	141153	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	B Service As Per Attached Checklist	Engine Oil Sample SIF # 42623474	15/07/2022	141153	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		15/07/2022	141153	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	VehService\AS		22/06/2022	124827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A SERVICE.		22/06/2022	124827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Front diff leaking need back to go to TCTC for repair		22/06/2022	124827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		22/06/2022	124827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		22/06/2022	124827	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Truck set up with different tyre sizes.								
		Cummins callled in to calibrate ECM.								
1054	Wodonga - Workshop	PO# WW72201		01/06/2022	463385	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	RESEAL FRONT DIFF.		27/05/2022	108141	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		27/05/2022	108141	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		27/05/2022	108141	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		12/05/2022	98871	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	"A" SERVICE.		12/05/2022	98871	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	LH WINDSCREEN CRACKED.		12/05/2022	98871	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		12/05/2022	98871	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service		22/04/2022	88324	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			Front Diff Oil Sample SIF # 41797572							
			Rear Diff Oil Sample SIF # 42628864							
		A Service As Per Attached Checklist	FITTED NUT COVERS TO RH STEER. REPLACED RR MUDFLAP. REPAIRED DASH LIGHTS.							
1054	Wodonga - Workshop	Drain and Replace Diff Oils	ADDED 4L ENGINE OIL.	22/04/2022	88324	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	LH WINDSCREEN CRACKED.		22/04/2022	88324	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER

1054	Wodonga - Workshop	RESEAL FRONT DIFF.		22/04/2022	88324	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		Replace Left Hand Windscreen								
1054	Wodonga - Workshop	Albury Autoscreen PO# WW071368		22/04/2022	88324	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACE FAULTY RH STEER SLACK ADJUSTER ASAP.	COULDN'T FAULT.	22/04/2022	88324	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		22/04/2022	88324	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	supply and fit 2 tyres		23/03/2022		Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	B-SERVICE		22/03/2022	67103	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	REPLACE FAULTY RH STEER SLACK ADJUSTER ASAP.		22/03/2022	67103	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	B Service As Per Attached Checklist	HAD TO MANUALLY ADJUST RH STEER SLACK ADJUSTER. BRAKE DRAGGING. ADJUSTER HA	22/03/2022	67103	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		22/03/2022	67103	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Tyre Position 2		01/03/2022		Wodonga	LHB	XV17VU	Albury Workshop	P/MOVER
1054	Wodonga - Workshop	A SERVICE		11/02/2022	48331	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		11/02/2022	48331	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		11/02/2022	48331	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		25/01/2022	37879	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		25/01/2022	37879	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	A Service As Per Attached Checklist		09/01/2022	27151	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		09/01/2022	27151	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
			The following 1st service inspection for F L Green Distribution, to a K200 Kenworth Truck, Chassis#471424, and registration #XV17VU included: * Removed/replaced engine filter & oil, specification used in parts section below. * Check all engine operation & components * Removed/replaced transmission oil filter * Check all hydraulic lines fitting & level lubricant levels to specification * Removed/replaced power steering filter & gasket * Removed/replaced differential oil, specification used in parts section below. * Removed/replaced fuel filter * Check cooling system & pressure test * Check all belts, idler pulleys, fan, shrouds & adjust to specification * Check all electrical routing, wiring looms, switches, sensors & components * Check all wheel equipment & steering components * Check all braking & adjust to specification * Check clutching & adjust to specification * Check all suspension components * Check all internal cabin operation, components & adjust to specification * Check all external cabin components & adjust to specification							
		C Service As Per Attached Checklist	* Check windscreen washers, wipers, refill & test operation							
		***COMPLIMENTARY NO CUSTOMER LABOUR CHARGE	* Lubricate, adjust relevant components as required							
		KENWORTH TRUCK 1st SERVICE POLICY ***	* Re torque all fitting & fixtures							
		***CUSTOMER RESPONSIBLE FOR ALL PARTS REQUIRED FOR	* Wash vehicle complete							
1054	Wodonga - Workshop	1st SERVICE***	* Road test, confirm & quality check	07/12/2021	8846	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Record Check Results As Attached To This Job		07/12/2021	8846	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	DROP AT TCTC		07/12/2021	8633	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	trailer light issue	progress heavy vehicle POww068799	26/11/2021	463385	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		2 x Stickers 3 Points of Contact								
		Safepak Albury								
1054	Wodonga - Workshop	PO#WW068700		23/11/2021	1156	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
1054	Wodonga - Workshop	Truck Pre Delivery	TARE= 10850KG	23/11/2021	1156	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER
		*MT Data Install-MDVR	Mount and wire up supplied IAP tracking unit under passenger seat.							
		*IAP Install	Mount GPS and high gain antennas on rope rail above LH door just behind							
		Tablet serial # 000041724	door. Mount tablet and mic above radio & gauges, mount speaker above rear							
		Tracking unit serial # 479001824	of RH door. Mount MDVR under passenger seat, wire up, mount forward facing							
		Tracking unit sim card # 8200098249525	camera, run wiring and connect camera to MDVR. Connect and wire in engine							
		Tag #'s 024958 & 024957	data control box to CAN wiring & power and earth as necessary. Connect scales							
		MDVR serial # C704CBAFC1724	to tracking unit. Connect power, earth & ignition, mic and speaker, re-assemble							
		Phone # 0417216359	truck and test. Contact MtData support to setup and test unit. Complete IAP							
1054	Wodonga - Workshop	Support persons name -Reubin	paperwork & send off.	27/10/2021	1054	Wodonga	LHB	XV17VU	Wodonga Workshop	P/MOVER