EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.									
1049	Mt Gambier - Mt Gambier	VehService\B1 Svc	Replace cabin filter.	CHECK PITMAN ARM ABOUT TO FALL OFF Inspect and found pitman arm worn causing to nearly fall off. Remove split pin, nuts, and bolts. Fit new pitman arm with new nuts and bolts. Refit split pin and tension all components to spec. Road test and check steering straight,	04/09/2026	903597	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Mt Gambier - Mt Gambier	Steering\UNI JOINTS	Steering\UNI JOINTS	all OK	04/09/2026	903597	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\COMPRESSOR	Engine\COMPRESSOR load rattle blowing of air when shutting down truck possible governor valve		27/08/2026	899817	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\EBS FAULTS	EBS fault when turning corners	Replaced rubbed EBS lead, further diagnosis to be conducted on trailers	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Body\AIR FITTIN	Remove water in air tanks	Drained air tanks	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\SLACK ADJ	Replace RHR slack adjuster (worn teeth)	Removed and replaced RHR slack adjuster	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF drive shock (upper mount pulled through)	Replaced LHF drive shock	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BOOSTER	Replace missing booster cage bolt, LHR drive	Fitted new booster cage bolt to LHR drive	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\ELECT P&W	Secure loose front diff sensor wiring	Cable-tied loose diff sensor wiring	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\SLACK ADJ	Tighten s-cam tube bolt (loose)	Tightened loose S-cam tube bolts	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Cooling\COOL LEAKS	Remedy coolant leak	Tightened coolant hose clamp to remedy coolant leak, to be rechecked next service	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\ELECT P&W	Secure loose mirror cables	Fitted cable ties to secure loose LH mirror wiring	13/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
			VehService\AS A Service	Completed "A Service" as per attached service sheet								
1049	Myrtleford - Workshop	VehService\AS	L135062	Topped up engine oil and adjusted clutch Fault – No start possible. Suspected starter failure. Cause – Diagnosed starter motor as faulty on arrival. – Starter unable to engage/rotate engine. Correction – Travelled to site. – Disconnected batteries. – Removed all starter cables. – Removed starter mounting bolts and extracted starter. – Cleaned starter cable lugs. – Swapped cables from old starter to new starter. – Installed new starter and tightened mounting bolts. – Reconnected and tightened all cables. – Tidied wiring and ensured correct routing. – Tested starter operation – OK. – Travelled back to workshop.	07/08/2026	892014	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\START MOTR	Engine\START MOTR		04/08/2026	888905	Completed	Mt Gambier	STK	XV65RM	HALLORAN DIESEL - 3	P/MOVER
			REPLACE DOSER PUMP ASM	Truck rolled in with after treatment light. Plug insite tool in and check codes - active code for loss of prime and input lines on manual system not operating correctly. Attempt to flush pump multiple times but unsuccessful. Try to clean solenoid but not able to carry out click test. Check codes again and had active open solenoid code. Cut out wiring for solenoid and run new wiring. Reconnect all wiring back to pump but still not able to carry out click test for solenoid. Source and fit new doser pump as required. Carry out click test, all OK. Carry out pump override test, measure ad blue and ensure correct amount being dosed. Clear all codes, road test and check, all OK CU5273337RX RECON DOSER PUMP 12V 1 3498.44							
1049	Myrtleford - Workshop	Engine\ADBLUE	PLUG IN AND CHECK AFTER TREATMENT LIGHT ON DASH	Misc:DFT DIAGNOSTIC TOOL FEE	18/07/2026	883059	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
			REPLACE FAULTY STEERING BOX	CHECK STEERING FAULT - NOT REACTING AND STEERING AS IT SHOULD NOTICES IT MOST WHEN LOADED Road test truck, found slight jolt in steering and steering not reacting correctly. Lower bull bar and jack cab. Inspect king pins, springs, steering shaft, and tie rod ends - all components OK. Grease all components. Disconnect truck from trailer and inspect turn table - found wear pads gouged out and un-serviceable. Replace turn table wear pads as required. Reconnect truck and trailer, road test truck and found steering not reacting as should. Carry out pressure and flow test on steering box and found to have failed. Undo and remove steering box. Fit and secure new steering box. Fill with new power steering fluid. Bleed system, set poppets and road test truck. Steering wheel							
1049	Myrtleford - Workshop	Steering\PWR STEER	FIT NEW WEAR PADS ON TURN TABLE TOP	straight and operating as required. Deliver back to yard.	15/07/2026	883059	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
			Insp\ANN INSP Annual insepction as per check sheet									
1049	Myrtleford - Workshop	Insp\ANN INSP	L134525		01/07/2026	879076	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
			VehService\BS B Service									
1049	Myrtleford - Workshop	VehService\BS	L134524		30/06/2026	879076	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	.ENGINE BRAKE HAS TROUBLE TURNING OFF ON STEERING WHEEL	Checked switch, found globe was blown in dash. Removed dash cluster and replaced blown globes. Refit dash. Checked steering wheel buttons, found to be faulty, removed buttons and replaced with new.	30/06/2026	879076	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BRAKE ADJ	CHECK FRONT DRIVE S-CAM BUSHES FOR WEAR	Checked s-cam bushes, all okay.	30/06/2026	879076	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\FAULT CODE	CHECK AFTER TREATMENT LIGHT ON DASH	Connect laptop and check faults for after treatment light. Faults for blockage. Carry out air side click test and ad blue flush. Codes changed to inactive. Cleared inactive coders and test drive truck, no further faults. Misc:DFT DIAGNOSTIC TOOL FEE	30/06/2026	879076	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\DAMAGE	PANEL ON FRONT OF SEAT HAS LOOSE BOLTS	Drilled new hole into seat frame, fit new screw and checked all secure.	30/06/2026	879076	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
			JUMP START VEHICLE @ YARD	Get tools and supplies then travel to GF yard. Jack cab, remove battery box and jump start truck - unsuccessful. Connect batteries to ute to charge for 10 minutes and attempt to re-jump - unsuccessful. Source another jumper pack and retry but no good. Diagnose faulty batteries, remove and replace x4 batteries as required. Start truck, all working as should.							
1049	Myrtleford - Workshop	Elect\BATTERY	REPLACE ALL 4 BATTERIES	KWTRP-700HD SEALED MAIN FREE BATTERY CCA 700, RC 160	19/06/2026	875319	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		15/06/2026	875319	Completed	Mt Gambier	STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	Elect\BREAKDOWN	Jump start truck at yard	Travel to GF yard, put cab over and jump start truck as required, all okay	05/06/2026	872410	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
			VehService\AS A Service									
1049	Myrtleford - Workshop	VehService\AS	L134041		29/05/2026	871093	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\ELECT P&W	DrCabElect\ELECT P&W	Truck came in with window not going up could hear the window regulator working when pressing the switch. removed door handle outer plate then unplugged window switch plug and interior light plug in bottom of door then removed upper and lower interior door card. then removed outer screws that hold in metal door card and removed unlock actuating rod and locking cable unplugged electric door unlock and lock switch. Unplugged door computer module. removed window regulator bolts and metal door card came off, removed window regulator, found that the window regulator spring had broken. fitted up new window regulator put metal inner door card back in , did up all the outer screws and then done up window regulator screws. plugged in window door computer module. refitted unlocking and locking switch and actuating rods and cable. refitted the interior upper and lower door cards. checked that the window went up and down fully and the door unlocked and relocked.	20/05/2026	865348	Completed	Mt Gambier	STK	XV65RM	COOKY'S DIESEL MECHANIC REPAIRS - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\CRUISE CON	NO CRUISE, HORN AND ENGINE BRAKE STAYING ON	Inspect and found fuse blown, replace fuse and check cruise, horn, and brake light operation, all working as should	15/05/2026	862655	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\BELTS/TENS	MISSING IDLER PULLEY	spect and found missing pulley. Source new pulley and bolt. Fit to truck and check operation, all okay CU3681587 PULLEY IDLER	13/05/2026	862655	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
			3 03KWZZZ100 SUSPENSION Tech(s): 8100 81.25	Tension loose nut to spec. Fit new split pin as required,								
1049	Myrtleford - Workshop	Steering\TIE ROD	LOOSE TIE ROD END	all okay	13/05/2026	862655	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER

1049	Myrtleford - Workshop	Elect\RADIO	INSTALL UHF SPEAKER PLEASE CHECK UHF EXTENSION SPEAKER IS WORKING CORRECTLY OR IT HAS 1 FITTED	Check over and found speaker working as should	13/05/2026	862655	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\MIRRORS	passenger side circular mirror has fallen off. needs replacing.	REPLACE LH SPOTTER MIRROR Remove and replace broken LH spotter mirror as required KWSNS-005-0007 MIRROR-SPOTTER 7"	13/05/2026	862655	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter. L133729		12/05/2026	858189	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION 1-2		11/05/2026	865348	Completed	Mt Gambier STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	Engine\ADBLUE	DIAGNOSE & REPAIR AFTER TREAT LIGHT IS ON.		05/05/2026	858189	Completed	Mt Gambier STK	XV65RM	JF MECHANICALS - 3	P/MOVER
1049	Myrtleford - Workshop	Chassis\FIFTH WHEE	ADJUST TURN TABLE JAWS	Adjust turn table as required, all OK	24/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Cruise control off button intermittent	Check cruise control off button operation multiple times, unable to fault operation. To monitor and report if issue occurs	24/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Mirror light n/w	Check mirror light not working, remove and replace blown globe as required, all OK	24/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLTUCH	Carry out clutch adjust as required, all OK	24/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\BRK LIGHT	brake lights come on when engine brake is on (turn off)	THIS JOB WILL BE LEFT HOW ITS SET IN THE ECM (WD)	24/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\AIR LEAK	REPAIR WATER LEAK LH SIDE OVERHEAD CONSOLE NEAR SPEAKER	Check over where reports of leak, found water leaking through bolt hole. Silicon shut hole, let dry and check over for leaks, all ok	24/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\SEAT	FIT ISOLATOR SHOCK TO SEAT AS PREVIOUSLY ORDERED AND CHARGED VehService\AS A Service L133353	Remove seat base, remove and replace seat shocker. Refit seat base and check on road test, all OK	24/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS			22/04/2026	851294	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8	CALL OUT - WARRANAMBOOL	20/04/2026	851690	Completed	Mt Gambier STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BRK RELINE	REMOVE WHEELS AND CHECK BRAKES FROM LAST NIGHT'S BREAKDOWN RELINE ALL 4 X DREIVE BRAKES	Truck returned to workshop for further inspection after breakdown. Jacked up all axles and removed wheels and drums. Inspect brake linings and found to be glazed on front axles and LH rear. LH rear also had flat spots on rollers and RH rear brake linings were contaminated with grease. Remove brake boosters, slack adjusters and s-cam tubes. Replaced s-cam bushes and seals. Installed new brake shoes and drums. KWDB017TRP TRP 16.5 X 7 STEEL JACKET DRUM 4 726.48 KWKSMA3124707QP KIT-BRAKE SHOE DRIVE 16.5 X 7 MERITOR Q- 4 520.00 KWK1T8042 KIT - CAMSHAFT REPAIR 1 37.57 KW2210V7536FWPZ S-CAM 28S 11.6" R/H TRP EQUIVALENT CS966 1 99.90 KW2210W7537FWPZ S-CAM 28S 11.6" L/H TRP EQUIVALENT CS966 Travelled to truck and inspected brakes. Checked slack adjuster operation and brake adjustment. Jacked up axle and check for brake drag, all okay. Checked for back pressure when releasing, okay. Followed truck back to Mt Gambier and checked temps. Found temps were consistent and slowly going down. Return to workshop and inspect drums, recommend booking into workshop for further inspection. Suspect truck was driven with black button in, truck brakes on trailers released.	16/04/2026	848690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BRK O/HAUL	BRAKES GETTING HOT		16/04/2026	848690	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12 VehService\BS B Service	TYRES CHANGED IN FEB 26 BUT HAVE DONE 44,225KM AS WELL AS HAVING BRAKE ISSUES THIS WEEK	09/04/2026	848690	Completed	Mt Gambier STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	L133112		01/04/2026	842616	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	Rh headlight has fallen out of holder	Removed headlight, refit with new screws. Fit new headlight surround. Fit RH headlight protector. KWR22-1365R COVER - HEADLAMP RIGHT HAND 1 167.42 KW1307-03 7" CHROME TRIM RING INC SCREW	31/03/2026	843068	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\FAULT CODE	AD BLUE LIGHT COMES ON INTERMITTENTLY	Check over all ad blue hoses, all looked OK. Plug in and check codes, found inactive code for pressure. Check ad blue breather and found filter blocked. Remove and replace ad blue filter. Clear codes, all OK	31/03/2026	843068	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\BATTERY	LOAD TEST AND CHECK BATTERIES	LOAD TEST BATTERIES AND **ADVISE WAYNE OF FINDINGS BEFORE TRUCK LEAVES** Clean off batteries. Remove negative and positive clamps. Load test all batteries and check, all batteries in good condition	31/03/2026	843068	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WINDSCREEN WASHER BOTTLE (LEAKING)	Remove A/C air drier to gain access. Undo and remove washer bottle. Fit new washer bottle as requested. Refit all components and check, all OK KW1743202 TANK SCREENWASH	31/03/2026	843068	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\SCALES	SCALES N/W IN CAB	Check cab scale function, intermittently not working. Carried out isolation procedures in trailers, found wiring incorrect in trailers. Repaired on separate invoice.	25/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\SEAT	Damper on seat n/w inspect and advise	Remove seat base and inspect, found both seat dampeners broken and not operational. Remove and replace dampeners as required. Reassemble and refit seat base, all OK. KW98889-07 SOCK ABSORBER TO SUIT SEAT 1 380.30 KW98890 ISOLATOR SHOCK ABSORBER	25/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\ELECT P&W	FIT NEW SCREWS IN FUSE PANEL	Fit x3 new screws in fuse panel where missing KWX206-132-208K SCREW-THUMB, MACHINE HEAD	25/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\WORK LIGHT	LOADING LIGHTS STUCK ON SINCE CHANGING TO B DOUBLE SET UP VehService\AS A Service	Inspect light wiring found wiring joined incorrectly. Change wiring to be correct and check, all lights operating as should. Remove ignition supply from trailer lead and rejoin reverse light wiring.	23/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	L099254 AFTER H'RS BREAKDOWN CALL OUT FEE		12/03/2026	832257	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\BREAKDOWN	NGCALLOUT PARTS A/HRS CALLOUT	Travel to workshop, get tools and supplies required then head to Greenfreight yard. Truck not starting, attempt to jump start but unable to get to turn over as batteries were too flat. Remove and replace batteries as required. Check starting operation, all OK	06/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\BATTERY	CHECK BATTERIES TRUCK WON'T START	KWTRP-700HD SEALED MAIN FREE BATTERY CCA 700, RC 160	06/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS ON WITH PARK LIGHTS	Found work lights coming on with park lights. Inspect trailer plug and found wiring incorrect. Rewire trailer plug wiring, check operation, all lights operating as should. SCALES IN TRUCK WORKING	06/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\SCALES	DrCabElect\SCALES	Reported scales in truck not working. Check over fuses behind dash and in battery box, found fuse blown. Remove and replace fuse as required. Power up scales in truck, found not getting signal from trailers. Check trailer scales, all working as should. Just unable to see trailer weights in truck. Need further diagnosis time	03/03/2026	829851	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BREAKDOWN	Brakes\BREAKDOWN	Repairs Carried Out: Inspect drive breaks due to driver complaint of breaks had been stuck on, build up air release breaks, inspect to see that all the drive breaks had released correctly, no faults found, inspect for air leaks, no faults found, apply service break, inspect operation and for air leaks no faults found. Travel return	25/02/2026	826969	Completed	Mt Gambier STK	XV65RM	COOKY'S DIESEL MECHANIC REPAIRS - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32) VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.		19/02/2026	822694	Completed	Mt Gambier STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	L098947		11/02/2026	820100	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER

				an you please check the temp gauge because Cummins fitted new temp sender on 11/09. Check the earth to the gauge please & maybe hook up to the ECM and check temps also to see when the horton comes in.								
			Radiator may need blowing our as running warmer than usual at times	Connect laptop and checked engine coolant temp, verses the gauge temp, found to be reading the same. Check earth to								
1049	Myrtleford - Workshop	Cooling\RADIATOR	BLOW OUT RADIATOR	temp gauge and found only .1 amp drop. Blow out radiator.	31/01/2026	813955	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				KW56044BL TERMINAL-BLADE,F,4MMF/INS(PK10 Found ad blue sender had a pinched o'ring and leaking ad blue. Removed sender and replaced o'ring. Cleaned area from leak.								
				KWHHW0116 ADBLUE FILTER AND O RING 1 Internal Misc:E-2 ENVIRONMENTAL LEVY 35.75 Misc:SHOPT SHOP SUPPLIES 35.75								
1049	Myrtleford - Workshop	Engine\FAULT CODE	AD BLUE LEAK	Misc:RND ROUNDING	31/01/2026	813955	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				HIGHBEAM LHS N/W 21/01 Found LHS high beam not working. Remove LED light, check power and earth, found faulty. Fit new light as required and check operation, all okay. 22/01 Truck hit kangaroo and smash LH head light cover. Remove and replace outer cover as required, all okay.								
				KWP54-1326-1-002 12V/24V LED H-LIGHT HI 1 620.03								
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	HIGHBEAM LHS N/W	KWR22-1365 COVER - HEADLAMP LEFT HAND	31/01/2026	813955	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS A Service L098650		29/01/2026	813955	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Travelled to GF yard, removed panels to access blower fan. Tested for power, diagnosed faulty blower fan. Removed fan and replaced with new, connected. Tested operation, all okay. Refit panels as required.								
			HECK AIR CONDITIONING OPERATION HEATER/ A/C FAN OPERATION									
1049	Myrtleford - Workshop	Air Con\AIR CON	replace faulty fan motor	KWF31-TP-1000 FAN ASSEMBLY-BLOWER	19/01/2026	806277	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\ENG TUNE	Engine\ENG TUNE AT 801134KMS		13/01/2026	806277	Completed	Mt Gambier	STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
				Degas A/C system and check, found to be full of gas but dropping in vent. Check evaporator and found blocked. Remove HVAC box, remove evaporator and thermistor. Fit new evaporator with new thermistor as required. Refit evaporator box and reassemble dash. Remove recover dryer and replace as required with new o'rings. VAC system and regas with 1.4kg of gas. Check A/C operation, all working as should.								
				KW25189998 CORE-EVAPORATOR ASSEMBLY 1 622.75 KWGD11350 TRP RECEIVER DRYER 1 45.41 KW55300918 THERMISTOR 1 117.02								
1049	Myrtleford - Workshop	Air Con\AIR CON	air conditioner needs looking at. not very cold	POL AIRCONDITIONING GAS R134A	07/01/2026	801121	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Check daytime running lights, found not working. Remove and replace x3 diodes as required. Check operation, all working as should.								
1049	Myrtleford - Workshop	Elect\DAY LIGHTS	DAY TIME RUNNING LIGHTS	KW56022BL TERMINAL-BLADE,MALE,4MM(PKT14)	07/01/2026	801121	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Fit new sun visor clip on passenger side as required, all okay								
1049	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	SUNVISOR CLIP BROKEN	KWS16-1023-601 CLIP-VISOR, INTERIOR	07/01/2026	801121	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Check mirror, remove lens and replace lower globe as required. Fit new gasket and refit lens. Check operation, all okay.								
				KW8GP003594121 GLOBE,WEDGE BASE 12V5W 1 1.34								
1049	Myrtleford - Workshop	Elect\ELECT P&W	MIRROR LIGHT RHS - N/W VehService\CS C Service	KWML72 GASKET-MIRROR LAMP	07/01/2026	801121	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\CS	L098299		19/12/2025	801125	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Flip cab and turn on all lights and power consumers. Test and inspect all wiring. Found alt positive red hot. Cut all cable ties and pull wiring through to have enough length in cable. Cut end off, sandblast and crimp new cable on then heat shrink. Load test shorting circuit and found x2 leads un-serviceable and lead at battery box. Make up x2 new starter to earth battery cables. Remove and replace cables and secure neatly. Tighten and clean battery terminals and re-load test truck, all okay. Make up x2 new link cables from top battery to bottom battery, fit cables and secure neatly, all okay.								
				KWW84-1000 STRAP-HARNESS TIE 2 23.12								
			REDO BATTERY CABLES AND LUGS FROM/TO STARTER MOTOR	Sublet15112136 SUPPLY PARTS 295.55								
1049	Myrtleford - Workshop	Elect\ELECT P&W	AS BATTERY CABLES WERE GETTING HOT	POL battery cable w/shop supply	10/12/2025	792836	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Recieved breakdown for brakes being locked on. Travel to breakdown at Caroline. Checked over all brake components on truck and trailers. Built up air and released brakes, all working as normal. Inspect further and found truck to be bogged. Travel back to workshop and get recovery strap,								
			TRUCK BROKEN DOWN - DOLLY BRAKES ARE LOCKED ON									
1049	Myrtleford - Workshop	Brakes\BREAKDOWN	BLOCK CAROLINE 64 OFF MT SINAI RD	return to breakdown and pull truck free, all okay.	28/11/2025	790239	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Remove earth cables, check and tested all 4 batteries - tested ok. Check cables under load and found lower earth cable and earths on starter getting hot. Recommend rebooking to run new cables and replace lugs. Unable to								
1049	Myrtleford - Workshop	DrCabElect\BATTERY	LOAD TEST AND CHECK BATTERIES	replace lugs as cables will be too short.	21/11/2025	792836	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Straighten front grille as required, clean off old glue, refit and glue back on with sticky flex. Cable tie grille								
1049	Myrtleford - Workshop	Body\HOUSEKEEP	REFIT BOTTOM RAIL ON FRONT GRILLE	until glue dry then remove cable ties and check, all ok	21/11/2025	792836	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.									
1049	Myrtleford - Workshop	VehService\B1 Svc	L097910		21/11/2025	790239	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		20/11/2025	787761	Completed	Mt Gambier	STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
				ENGINE BRAKE GETTING STUCK SOMETIMES Test operation of brake, found to be working as should.								
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	off button for engine brake is a little dicky also sound the horn occassionally when pressed.	Test drive and inspect but unable to fault.	18/11/2025	787761	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Plug in and found poor deficient issue. Isolate fault to dolly then inspect loom through dolly. Found 3 rubs in thru draw bar and high corrosion through plug. Remove section of loom, make up and join in new section. Plug back into A trailer and found fault still present. Will need more time to diagnose.								
1049	Myrtleford - Workshop	Brakes\ABS	CHECK TRAILER ABS LIGHT ON DASH	KW4304023 O'RING - FILLER PLUG	18/11/2025	787761	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Remove seat base and inspect, found missing bolt for shocker. Fit new bolt, refit seat base and seat cover, all ok. Also replace missing bolt on B trailer first binder as								
			drivers seat needs looking at there is no firmness just soft bounces and bottoms out									
1049	Myrtleford - Workshop	DriCabRep\SEAT	CHECK / REPAIR DRIVERS SEAT VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.	was missing.	18/11/2025	787761	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	L097030 VehService\AS A Service		18/11/2025	781290	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	L097688		14/11/2025	781290	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				Inspect brakes and adjusted on service as required. Found LHR booster unserviceable. Remove booster, swap all fittings to new booster then fit new booster. Test operation, all ok								
1049	Myrtleford - Workshop	Brakes\BRAKE ADJ	PM BRAKES NOT HOLDING ON HILL WHEN LOADING	NGWT3030 30/30 BRAKE BOOSTER	31/10/2025	772300	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
				REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Inspect cab filters, all okay. Connect up A/C equipment and recovered gas from system. Charge with nitrogen and tested for leaks, no leaks found. Re gassed with new R134A gas.								
			aircon need looking at before weather starts getting hot									
1049	Myrtleford - Workshop	Air Con\AIR CON	not getting cold enough VehService\BS B Service	Will need further inspection if continues to fault.	31/10/2025	772300	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	L097441		31/10/2025	772300	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER

1049	Myrtleford - Workshop	DriCabRep\DAMAGE	REPLACE DRIVERS SIDE BUNK WINDOW	Arranged bunk window to be replaced. KWR44-1065R GLASS - SLEEPER WINDOW 1 383.14Sublet 15111661 Replace bunk window	29/10/2025	772300	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		22/10/2025	772300	Completed	Mt Gambier	STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		22/10/2025	772300	Completed	Mt Gambier	STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	Chassis\DAMAGE	Chassis\DAMAGE	ADJUST BINDER AS REQUIRED Binder was bent, twisted and missing hook. Use forklift to bend binder back to correct position. Cut out new hook and grind out. Installed new hook and secured binder with new bolts.	18/10/2025	764415	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS A Service L097258		13/10/2025	760395	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\FUEL TANK	REPLACE X2 MISSING FUEL TANK RUBBERS	Loosen fuel straps and rubber strips. Clean all surfaces and fit new rubber strips. Fit tank straps back to truck and tighten, all ok	08/10/2025	764415	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair wire where it has come out of the trailer plug needs to be re joined longer	Remove electrical tape and check wiring, fit joiner, open plug and check over all other wiring, all ok. Tape wiring and cover with conduit. Check light operation, all ok	08/10/2025	764415	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\MIRRORS	DRIVERS SIDE MIRROR BRACKET LOOSE	Tighten mirror as required. Found door cracking, taken photos	08/10/2025	764415	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\AIR LEAK	air leak under checker plate	Found air tank drain valve leaking. Remove and replace drain valve and installed with sealant. KWTRP123 VALVE DRAIN Check air cti issue	08/10/2025	764415	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CTI Drive	CTI fault valve connectiion lost	Jacked cab and remove cover off control box. Traced wiring and found 4 broken wires. Cut out broken wiring and rejoined to plug for controller. Refit panel and start truck. Test operation, all working okay.	08/10/2025	764415	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust drive brakes	THE BRAKES WOULD HAVE BEEN ADJUSTED ON WO 201104 B1 SERVICE AT B/M	24/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\ELECT P&W	horn on steering wheel not working	HORN ON STEERING WHEEL N/W Check fuses, relays, horn on steering wheel, power at plugs under cab, all ok. Horns partially work when knocking on them. Remove and replace horns - check operation, all ok. KWP49-1005-100 ELECTRIC HORN-12V	24/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\WORK LIGHT	REAR LIGHT BAR LIGHTS NOT WORKING	Unplug work lights and test for power, found no power at plug, followed wires back stripping conduit to find breaks in wire. Found rubbed wire but not relating to work lights, cut and rejoin rubbed wire as needed. Inspect wiring further and found cut wire in the dash for work lights. Strip and join wire as needed. Check operation, all ok	24/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CLUTCH	CARRY OUT CLUTCH ADJUST	Check and adjust clutch, all ok	24/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Steering\SUSPENSION	REPLACE LH & RH FRONT & REAR STEER SHACKLE PINS & BUSHES AS REQUIRED	Remove and replace front shackle pins and bushes and side plates Work Order #200807 Jack and support chassis. Remove batteries, battery box, u bolts and shackle pins. Removed spring from truck. Pressed out bushes from spring, cleaned surface and pressed in new bushes, welded bushes in place. Hit out hanger bushes and installed new. Reinstalled spring and fit u bolts, tensioned. Fit front pins. Jack rear of axle and fit shackles then tension. Refit battery box and batteries. Remove ad blue tank and all components attaching spring to chassis then remove spring. Press out bushes for spring then press and weld in new bushes. Hit out hanger bushes then hit new ones in. Fit spring and tighten u-bolts. Fit front pin, jack axle and fit new shackles as old ones were worn. Tension all components then refit ad blue tank. Lower truck and plug in computer, check for after treat faults - found no active codes. Carry out override test, system operating as should. Test drove, all ok.	18/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\TAIL LIGHT	Elect\TAILLIGHTS FLICKERING	TAIL LIGHTS ON TRUCK FLICKERING Test lights. Remove deck plates and inspect plugs and harness. Compare to diagram. Cut open plug and found corroded and broken wire. Repair wire and check. All lights working as should	18/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DrCabElect\INST/GAUGE BREAKDOWN - COOLANT GUAGE NOT WORKING - ERRATIC FAN	INVESTIGATE CUSTOMER COMPLAINT OF TEMP GUAGE N/W LIFT CAB & INSPECT KW SENSOR AND WIRING ALL LOOKED OK. LOWER CAB ROAD TEST & MONITOR TEMPS WITH LAPTOP & GUAGE WAS OPERATIONAL. RAISE CAB & DRAIN COOLANT & REPLACE KW TEMP SENSOR FAN WAS GETTING SWITCHED ON BY AIR CON PRESSURE & NOT ENGINE TEMP - AIR CON NEEDS INSPECTING	12/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS A Service L096682		08/09/2025	742356	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION POS 1-2		08/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	Body\WIPERS	wiper blades need replacing	Replace blades Remove and replace wiper blades as required KW1362060DC04 BLADE ASSY-WIPER	05/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\AIR FITTIN	fitting for red air line back of cab/front of a trailer might need replacing	Red air line back of cab front of A trailer replace Remove suzi fittings and found damaged connectors. Remove and replace connectors as required, no further leaks KWASA93-35 SELF SEALING 1/2" NPSF 1 21.32KW200-CA93-109	05/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\SUZI COIL	Elect\SUZI COIL	Red air line back of cab front of A trailer replace Remove suzi fittings and found damaged connectors. Remove and replace connectors as required, no further leaks	05/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Susp\Torque Rod	Front and rear left torque rods starting to wear (monitor	MONITOR CHECK SHACKLE PINS Found side plate mis aligned on service, Remove lock bolts in RH shackles. Remove adblue tank, jacked and removed weight from spring. Remove shackles and found them seized. Reinstall top and bottom pins and hanger/ shackle plate. Reinstall adblue tank with new lock bolts.	05/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Steering\SUSPENSION	CHECK STEER SHACKLE PINS & BUSHES ON BOTH SIDES	Greased. Found all pins and bushes worn. KWK209-77 SHACKLE-FORGED 1 123.19KWB65-1020 PIN-THREADED, SPRING SHACKLE	05/09/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Susp\AIR LEAK	CALLOUT - Repair air leak on truck Travelled to greenfreight yard and found tank drain cord was stuck open. Moved cord and resecured. Truck built up air okay.		28/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\WORK LIGHT	ALL WORK LIGHTS N/W FROM TRUCK TO TRAILERS	WORK LIGHTS N/W FROM TRUCK TO TRAILERS Work order 200246 Check work light fault, found no power to relay. Remove fuse box, found wire came out of back of fuse box. Refit fuse box and make sure it clicked into holder. Replace fuse, check power to A trailer, all ok. Check power to dolly, found to have electrical short to chassis. Will need more attention. Rejoin 3 lights that had been cut of	25/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\ELECT P&W	ORDER DIFF LOCK SWITCHES		25/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\SLACK ADJ	DRIVE S-CAM BUSH R/H/R	RH REAR DRIVE S-CAM MOVEMENT Remove slack adjuster pins, backed off brake. Remove CTI lines. Jacked up axle and removed wheels and brake drum. Remove brake assembly and brake booster. Remove slack adjuster and s-cam tube. Hit out s-cam bushes, removed s-cam. Installed new s-cam and bushes, refit s-cam tube/ Refit brake shoes and drum. Refit wheels and tensioned. Fit s-cam and booster. Adjusted brakes. KWK1T8042 KIT - CAMSHAFT REPAIR 1 37.57KWCS9661M TRP S-CAM 28S 11.6' L/H EQUIVALENT 2210W	25/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER

1049	Myrtleford - Workshop	Brakes\S-CAM	Brakes\S-CAM RH REAR S-CAM HAS EXCESSIVE MOVEMENT	RH REAR DRIVE S-CAM MOVEMENT Remove slack adjuster pins, backed off brake. Remove CTI lines. Jacked up axle and removed wheels and brake drum. Remove brake assembly and brake booster. Remove slack adjuster and s-cam tube. Hit out s-cam bushes, removed s-cam. Installed new s-cam and bushes, refit s-cam tube/ Refit brake shoes and drum. Refit wheels and tensioned. Fit s-cam and booster. Adjusted brakes	25/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\ABS	TRAILER - ABS LIGHT ON		25/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Diff lock switch lighting wires need checking. (cameron BMF knows about it as he did patch up repairs 14/08/25 on a call out) VehService\BS B Service		25/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	PO # L096365		20/08/2025	732027	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\ELECT P&W	Elect\ELECT P&W LOST GAUGES ON DASH	LOST GAUGES ON DASH Inspect fuses, tested and found one fuse blown. Replaced fuse with new. Removed dash panel and inspected diff lock switches and wiring. Unplugged switches. Could not fault anything. Refit dash.	19/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Susp\KING PIN	Susp\KING PIN R&R KING PINS	Flipped cab, lowered bull bar, jacked and supported steer axle. Backed off brakes, removed hubs caps and wheel bearing hardware. Removed hub, tie rod, drag link split pins and nuts. Hit out tie rod, then repaired thread on drag link. Had trouble removing drag link as was seized in ackerman arm. Removed backing plate from stub, then repeat on passenger side. Remove cotter pins, kingpins, end caps and stub. Wash off stub axles and main axle. Removed and replaced king ping bushes. Rheemed bushes to suit. Used jack and got shim thickness. Lube new king pins and bearings. Fit stub axle and check movement. Install new cotter pins, filled ends with grease then installed new end caps. Repeat process for other side. Reinstalled backing plates, tie rod and drag link. Installed new split pins. Removed old wheel seals, cleaned bearings and hub, installed new seals then reinstalled bearings and hub. Adjusted wheel bearings and reinstall hub caps with new gaskets, then filled hubs. Adjust brakes, greased king pins and check over. Jack axle, remove supports, lower jack and cab then lift bull bar. Road test and check over, all ok	13/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	trailer abs light on dash staying on	Connect laptop and check codes, found code 180 active power fault. Check fuses in module, found blown fuse. Replace fuse, then check for power coming out of rear of A trailer, A trailer had power, earth and can. Suspect fault in lead between cable from A trailer to dolly. Will require more time for this repair	08/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Chassis\FIFTH WHEE	cable on turntable release handle broken	Work order # 199702Make up suitable cable cover with nylon tube, secure with cable ties and clamps, all ok	08/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\ELECT P&W	roof dome light not working in cab	Inspect centre dome light and check globes, found globes to be blown. Install new globes and check operation, all ok.	08/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	diff lock dash lights not working.(never have)	Remove dash panel and found plugs to switches were disconnected. Reconnect front diff wiring harness and checked operation, blew fuse. replaced fuse. Smoke starting appearing from dash. Connect front diff harness to rear cross lock switch and observe wiring and switch all okay. Disconnected harness. Driver advised he previously had wiring issues which Browny (Auto Elect) had started investigating. Ordered new diff lock switches. Need to know where Browny is at with his wiring job before continuing	08/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Susp\SHOCK ABS	TIGHTEN FL SHOCKER	LHF drive shocker was loose, tighten shocker nut, check, all ok	08/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	engine brake light not working on dash	Remove dash panel, the remove blown dash globe and replace with new. Check operation, all ok	08/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\RERATE	Engine\RERATE		05/08/2025	721276	Completed	Mt Gambier	STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ FULL ROTATION ON DRIVE/STEER		04/08/2025	716625	Completed	Mt Gambier	STK	XV65RM	BORDER BANDAG PTY LTD -3	P/MOVER
1049	Myrtleford - Workshop	Engine\FAULT CODE	Engine\FAULT CODE	-connect laptop & download -found active FC1887 internal NOX sensor circuit -test voltage to plug under load 12.2v.ok -attempt to remove sensor & was seized in exhaust -cut off sensor & extract from exhaust pipe -tidy both threads -replace NOx sensor & ran wires neatly -road test & fault went inactive -clear faults & take final download.	31/07/2025	716625	Completed	Mt Gambier	STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\EBS FAULTS	Test EBS	Tested EBS. Turned ignition on and all warning lights illuminated including ESC. Started truck and all light turned off. As they should Turned on off road switch and ESC and ABS warning lights flashed to indicated they were turned off. As they should turned off off road switch and lights turned off. As they should.	24/07/2025	716621	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Check the ebs locks. no lights on dash	Inspect inside dash and found 2 blown globes. Replaced globes, check operation, all ok	23/07/2025	716625	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Steering\PUMP	P/STEERING GASKET BLOWN	Clean power steering pump and compressor thoroughly. Remove pump and clean sealing surfaces. Replace gasket and tension, check for leaks, all ok	19/07/2025	714103	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.	MINI B SERVICE Jack up steer axle, check bearing & king pin. Replace cab filter Carried out Mini B Service as per Greenfreight checklist Customer Instructions: Greased and Adjusted Brakes Checked all Fluid Levels Completed paperwork & Cleaned area Replaced cabin air filter.	17/07/2025	716625	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		17/07/2025	716625	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKES	Check brake adjustment, and adjusted all brakes as required. Road test and check brake operation, all ok	17/07/2025	713023	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CTI Drive	CTI NOT WORKING	Check CTI comms. Lift cab, remove cover and inspect valve body, found broken wiring, cut and rejoin wiring. Reinstall cover, lower cab and check operation, all ok	17/07/2025	713023	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\MOUNTS	Body\MOUNTS	REPLACE GREASE FITTING ON CAB MOUNT Remove and replace grease fitting on cab mount.	09/07/2025	704038	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS	R&R LEFT HAND FRONT DRIVE SHOCKERS Inspect and found bottom shocker bush worn, remove and replace bush with new.	09/07/2025	704038	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS	FIT NEW HEADLIGHT COVERS Remove old covers and replace with new.	09/07/2025	704038	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\MIRRORS	Body\MIRRORS	R&R LH mirror light Light mirror on LHS not working. Inspect and found globes to be blown. Replaced both globes, check operation, all ok	09/07/2025	704038	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	USB socket on dash not working	USB SOCKET IN DASH N/W work order #198745 Pulled dash apart, tested for power and earth. Replaced switch and test operation, all ok. Reassemble dash.	09/07/2025	704038	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		05/07/2025	704038	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL		05/07/2025	704038	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER

1049	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK	Check over for air leaks on truck and trailers Driver called up at 2 am and said he would lose all air when he used the foot brake, but said will wait until the morning. Went to truck at 7 am, built up air, pressed pedal, all seemed fine. Check over truck and trailer for air leaks, all ok. Another tech came out and had a look, he agreed that it was all ok. Also fit new wiper blades.	28/06/2025	697140	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEE	REPLACE TURNTABLE PADS Found turntable pads and jaws were worn. Removed worn jaws, installed new and adjusted to spec. Removed worn turntable pads and fit new	26/06/2025	697140	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS	RH HIGH BEAM DULL Check operation of RH headlight as dull, found light to have an internal fault. Remove old light and fit new.	26/06/2025	697140	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\FUEL TANK	Body\FUEL TANK	R&R DAMAGED FUEL TANK STRAPS Undo fuel tank straps and remove worn rubbers. Installed new rubbers and refit tank strap	26/06/2025	697140	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CTI Drive	CTI hose on rear wheel drivers side seems to be rubbing on the tyre at times	CTI HOSE ON DRIVERS SIDE REAR WHEEL RUBBING ON TIRE SOMETIMES Found RH rear air cti hose was rubbing. Replaced hose and moved hose mount out to prevent further rubbing.	26/06/2025	697140	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	CARRY OUT ANNUAL INSPECTION AS PER CHECKLIST Carried out annual inspection as per Greenfreight	13/06/2025	687566	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP	checklist. CARRY OUT STEER WHEEL ALIGNMENT	06/06/2025	687566	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\WHEEL ALGN	DrivLine\WHEEL ALGN	Steer alignment carried out at Trident Truck tyres CHECK OUT AIR LEAKS - REPLACE VALVE Inspect under dolly, found brake valve leaking. Drained air tank and remove brake hoses. Remove leaking valve and replace with new. Refit brake hoses and check operation,	04/06/2025	682892	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\AIR LEAK	Brakes\AIR LEAK	all ok	27/05/2025	687543	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2	GREENFREIGHT A SERVICE	27/05/2025	677853	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	Carry out service as per Greenfreight checklist. Inspect under truck, found oil filter hose leaking, and found slight leaking on compressor. Leaking very minor wash	25/05/2025	687543	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\OIL LEAK	CHECK FOR ANY OIL LEAEK AS I HAVE TOP UP ENGINE OIL UP A COUPLE OF TIMES	down and monitor. REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Connect machine and vacced system, found refrigerant level low, causing poor performance. Perform leak test, no leak	22/05/2025	681977	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Air Con\AIR CON	AIR CONDITION A BIT AVERAGE SINCE ENGINE REBUILD ?	present, re gas system. Tested A/C, unable to fault Remove old weather shield and bolt new weather shield into	22/05/2025	681977	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\WINDOW REG	NEW DRIVERS SIDE WIND SHIELD AROUND WINDOW	brackets. Removed sticky adhesive and push on firmly CHECK ALL LIGHTS - FLICKERING Inspected light issue and found lights flickering. Check and test wiring found issue in plug, remove old trailer plug and wire in new one. Cover and protect wiring. Check over wiring for work light, found damaged section of wiring in chassis, remove and re join. Also found work lights only half working Replaced left rear dolly work light. All	22/05/2025	681977	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\DAY LIGHTS	Elect\DAY LIGHTS	lights working ok Carried out Mini B Service as per Greenfreight checklist Customer Instructions: Greased and Adjusted Brakes Checked all Fluid Levels Completed paperwork & Cleaned area	20/05/2025	677853	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc	Replaced cabin air filter. Inspect horton for fault, found to be unserviceable. Removed fan and mounting bolts. Disassembled horton and and carry out rekit as required. Cut off the fan mounting studs and nuts. Cleaned up threads and refitted. Refit horton and tensioned studs. Refitted fan belt, test operation, all	07/05/2025	672314	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\ENG FAN	horton fan noisy. engine getting warm	okay Remove and replace wiper blades as required.	07/05/2025	672314	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\WIPERS	NEW WIPER BLADES NEED CHECKING AS METAL RUNNERS ARE COMING OUT	work order # 196248 Drive side mirror loose. Went over all bolts, tightened as	07/05/2025	672314	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\MIRRORS	DRIVERS SIDE MIRROR LOOSE	needed, all ok. OIL WEEP REAR OF ENGINE work order # 196248 Inspect engine oil power steering pump mounting gasket leaking. Remove power steering pump, clean gasket surface, install new gasket. Apply loctite to bolts. Install pump.	23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\OIL LEAK	SLIGHT OIL WEEP REAR OF ENGINE	Tighten bolts, spray with brake cleaner, all ok. AIR CTI HOSE LOOSE	23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CTI Drive	DrivLine\CTI Drive	Check over all air CTI hoses and tightened as required. DASH LIGHT OUT FOR HIGH IDLE work order # 196248	23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\ELECT P&W	DASH LIGHT OUT FOR HIGH IDLE	Remove dash panel, replaced blown globe DRIVERS SIDE LOW BEAM NEEDS ADJUSTING DOWN -TOO HIGH work order # 196248	23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	DRIVERS SIDE LOW BEAM NEEDS ADJUSTING DOWN POINTING TO HIGH	Adjusted head light as required. PASS SIDE HEADLIGHT N/W Passenger side headlight found to be very dull. Removed	23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\LIGHTS	passengers side low beam nw	light checked for power, found light needed replacing. Replaced light, all ok. REPLACE WIPER BLADES work order # 196248	23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\WIPERS	WIPER BLADES REQUIRE CHANGING	Replaced old wiper blades	23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS		23/04/2025	662777	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres	WHEEL NUT INDICATORS RECO HORTON FAN REPLACE BOTH HEATER TAPS		04/04/2025	655461	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES	P/MOVER
1049	Myrtleford - Workshop	Engine\ENG FAN	CHANGE ENGINE COOLANT	$14071.97 QUOTE $14477.20 INVOICE	21/03/2025	649740	Completed	Mt Gambier STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\ENG REBLD	NEW STYLE ENGINE BLOCK & LINNERS & MAIN BEARINGS BIG END BEARINGS & NEW CYLINDER HEAD ALL GASKETS SUPPLIED BY CUMMINS (V FIT CLUTCH KIT & INPUT SHAFT INSTALL KIT &CLUTCH FORK KIT REPLACE REAR ENGINE MOUNTS & BOLTS & NUTS	DONE AT 649747 KMS	21/03/2025	649740	Completed	Mt Gambier STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CTCH PACK	FIT UPPER & LOWER RADIATOR MOUNTS		21/03/2025	649740	Completed	Mt Gambier STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brakes\BRAKE ADJ	Put over pit. Inspect brakes and found over stroking. Release brakes and adjust brakes. Needs new s-cams and bushes	15/03/2025	643740	Completed	Mt Gambier STK	XV65RM	TRIPLE S DISTRIBUTORS - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DriCabRep\DOOR LOCK	DRIVERS SIDE DOOR SKIN KEEPS FALLING OFF Removed door skin clips and replaced with new. Reinstalled door trim and checked all secure	14/03/2025	649740	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\KING PIN	King pins have up and down movement	CHECK KING PIN MOVEMENT Reinspect king pin movement, all within spec. Will continue to monitor on services.	14/03/2025	649740	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\DRIVES	Front drive s-cams have movement	CHECK S-CAM MOVEMENT FRONT DRIVE RH REAR EXCESSIVE Both front drive and RH rear s-cams were worn. Removed axles and hub assembly. Replaced s-cam bushes and s-cams. Shimmed to spec. Cleaned over axle gaskets and replaced with new. Replaced wheel seals. Reinstalled hub assembly and wheels. Inspect RH rear axle, found s-cam bushes worn but s-cam was okay. Reinstalled and shimmed to spec. Refit axles with new gaskets and hub assembly with new wheel seal. Adjust wheel bearings and brakes.	14/03/2025	649740	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\MOUNTS	Front engine mounts	REPLACE FRONT ENGINE MOUNTS Removed bolts from front engine mounts. Jacked up engine and replaced front engine mounts. Fit up bolts, all okay	14/03/2025	649740	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER

1049	Myrtleford - Workshop	Susp\SHOCK ABS	Cab shockers leaking	CAB SHOCKERS LEAKING Jacked cab, use strap to hold tension on spring and removed RH cab shocker. Installed new shocker and tightened all components. Travel to Greenfreight yard, carried out pressure test and checked over. Pressure did not drop. Return to workshop and collect new radiator cap. Return to truck, pressure still okay. Remove pressure tester and fitted new cap. Removed breather line and removed both belts. Started truck with breather hose in bottle, found truck was pushing exhaust gas into bottle, indicating exhaust gases in cooling system. Refit all components and advised	14/03/2025	649740	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Cooling\BREAKDOWN	REPAIR COOLANT LEAK - SUSPECTED HEADER TANK	to take to Cummins for further investigation	11/03/2025	646165	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		06/03/2025	646165	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4 GOODYEAR AUTOCARE MOUNT GAMBIER.		06/03/2025	646165	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\ROTATION	ROTATED STEER TYRES.		26/02/2025	663442	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	VehService\BS		26/02/2025	640439	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\ELECT P&W	DriCabRep\ELECT P&W	PARK BRAKE DASH LIGHT N/W Removed dash cluster and replaced blown globe for park brake. Refit dash	25/02/2025	640439	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Steering\DAMAGE	Steering\DAMAGE	REPLACE STEERING CABLE work order 194201 Removed steering column surround, removed cable and replaced with new. Tested operation, found steering strut had movement, removed strut and replaced with new. Operated steering, all okay. Refit covers.	25/02/2025	640439	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\DOOR LOCK	driver side iner door skin needs replacing of somehow fixing as hanging of	DRIVERS SIDE DOOR SKIN HANGING OFF Work order 194201 Removed door card and refit clips, secured in door trim. Refit door card.	25/02/2025	640439	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\ST Weel	STEERING WHEEL SPRING LOCK PLAYING UP. NEED CABLE REPLACED.	Removed covers and refit outer cable back into adjuster. Lubricate adjuster and moved steering wheel, all okay. Refit covers.	19/02/2025	635407	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Air Con\AIR CON	AIRCONDITIONER NOT WORKIING ONLY BLOWING HOT AIR	Labour @ 635404 Kms - Remove washer bottle ass. & assoc components. Dismantle passenger floor as nec for evap outlet pipe access. C/O pipe with new o-rings. C/O r/dryer, vac & gas, test, all good. Reassemble as nec	17/02/2025	635404	Completed	Mt Gambier STK	XV65RM	MIDWINTER MECHANICAL - 3	P/MOVER
1049	Myrtleford - Workshop	Body\TOOLBOX	Body\TOOLBOX	REPLACE DRIVERS SIDE TOOLBOX SEAL Removed worn seal on drivers side tool box. Cleaned mounting surface and installed new seal.	11/02/2025	629726	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\BRK LIGHT	Elect\BRK LIGHT	BRAKE LIGHTS COME ON WHEN TURNING LEFT Turned on LH indicator, wriggled trailer plug on truck, no fault. Wriggled trailer plug on back of A trailer, faulting on dolly side of plug. Removed casing of trailer plug. Found wire pulled out of back and screws were rusty. Remove ALL WIRES FROM PLUG, WIRED UP NEW PLUG AS REQUIRED. NO FURTHER FAULTS.	11/02/2025	629726	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	need new drivers side mat	REPLACE FLOOR MAT DRIVERS SIDE Supply and fit new floor mats as required.	11/02/2025	629726	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\ENG FAN	truck seems to get a bit warmer/hotter more often sometimes. Horton fan kicks in more often	TRUCK GETTING HOTTER THAN USUAL AND HORTON FAN KICKS IN MORE OFTEN work order 193613 Inspect radiator, all okay. Checked coolant, topped up 5L on service. Road tested truck, data monitored coolant temp and check thermostat. all okay. Would need further diagnosis if symptoms persist.	11/02/2025	629726	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\DOOR LOCK	rubber seal around door needs replacing	REPAIR / REPLACE RUBBER SEAL AROUND DOOR Work order 193613 Removed worn door seal. Cleaned all surfaces and installed new door seal	11/02/2025	629726	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS 629708kms		03/02/2025	627951	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Cooling\ENG FAN	HORTON COMES ON WITH A/C	HORTON COMES ON WITH A/C Diagnosed faulty pressure switch. Removed existing pressure switch that controls operation of the Horton & replaced with new switch. Checked operation, all ok. No longer coming on with the A/C	30/01/2025	619385	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\WIPERS	washer bottle leaking	Flipped cab & removed existing washer bottle and replaced with new. Checked operation, all ok.	30/01/2025	619385	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Chassis\EXTE TU	AIRBINDER LEAKING FROM INSIDE HOUSING	Breakdown - Rear Trailer YV78JO Odomoter US Labour - C/O forward most ratcheting binder assembly due to internal air leak. Swap over strap spool, test, all good.	24/01/2025	627951	Completed	Mt Gambier STK	XV65RM	MIDWINTER MECHANICAL - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\OIL LEAK	check engine oil leak VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.	truck arrived with oil all over the front of the engine and underneath. Lowered bull bar and jacked cab over. Inspected front of engine and found missing timing cover bolt and others were loose. Sourced new bolt and tensioned all others to spec. Secured bolts with loctite and cleaned all surfaces from leak.	23/01/2025	625911	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		18/01/2025	619385	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\BATTERY	Engine\BATTERY	DRIVE TO GF AND JUMPSTART TRUCK Attended truck at Greenfreight yard. Lowered bullbar and lifted cab. Load tested batteries. All four batteries failed. Removed all batteries and replaced with new ones as required. Re tested, all ok	10/01/2025	617012	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Elect\SUZI COIL	Elect\SUZI COIL	BRAKE LIGHT FUSE IS THROWING ITSELF A COUPLE OF TIMES, HAVE HAD TO RESET IT Inspected wiring and found short on suzi lead. Repaired damaged section & resecured	18/12/2024	611037	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\FUEL TANK	Body\FUEL TANK	LH SIDE FUEL TANK BRACKET CRACKED REPLACE RUBBER On inspection found LH side tank bracket was cracked. Ground out crack & welded. Once cooled, painted red. Replaced rubber..All ok	18/12/2024	611037	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DrCabElect\INST/GAUGE	FUEL GAUGE STILL NOT READING PROPERLY Inspected & tested sender, all looked ok. Inspected wiring, all looked fine. Recommended to re wire as the fault is intermittent.	18/12/2024	611037	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brakes\BRAKE ADJ	CHECK BRAKES, THEY WORK BUT SOMETIMES DONT HOLD WHEN ON A SLIGHT HILL GETTING LOADED Inspect & check brake adjustment & operation of auto slack adjusters. Carried out brake test. All operating as should	18/12/2024	611037	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\SEAT	DriCabRep\SEAT	REPLACE DRIVERS SEAT BELT Removed seat cover, seat fabric & seat belt cover. Unbolted the seat belt at the top and removed belt. Fit new seat belt as required. Refit all components & tensioned. Checked operation. All ok	18/12/2024	611037	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		11/12/2024	618447	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION	steer rotation	06/12/2024	612003	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS	Carry out service as per Greenfreight checklist.	03/12/2024	618447	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Air Con\AIR CON	Air Con\AIR CON	Labour - Diagnose AC n/w. Zero refrigerant in system. Remove grill & floor panel to access evap & cond. No visible leaks found. Perform n2/h2 test, no leaks detected. System held pressure, believe all good. C/O r/dryer, vac, gas, reassemble, test.	03/12/2024	596878	Completed	Mt Gambier STK	XV65RM	MIDWINTER MECHANICAL - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\TURBO	Engine\TURBO	found turbo waste gate leaking air during tune up remove turbo, adjust wastegate on new & install	02/12/2024	606697	Completed	Mt Gambier STK	XV65RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER

1049	Myrtleford - Workshop	Engine\COMPRESSOR	Engine\COMPRESSOR G/F SUPPLIED NEW AIR COMPRESSOR & GASKETS FOR COOKYS TO FIT (PARTS SUPPLIED BY CUMMINS)	Repairs Carried Out: Travel to PNR yard inspect truck not building up air remove and replace governor valve start truck and check pressure slow to build up air remove discharge pipe found lack of air pressure ring up and order new air compressor ,remove power steering pump, intake pipes, drain coolant remove coolant pipes, air intake pipe unbolt compressor and remove, Clean up mounting faces refit new compressor with new gasket. Fit air intake pipe coolant pipes, power steering pump with new gasket fit intake pipe, refill with coolant start engine and check for leaks ok check air compressor return to work shop	26/11/2024	605375	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Elect\WORK LIGHT	work light relay needed	3 13KWZZZ009 WORK LIGHTS Tech(s): 8096 150.00REPLACE WORK LIGHT RELAY Checked fuses for work lights, removed dash panel and found plug was disconnected, refit plug and check operation. Found one work light was flickering. Removed light and repaired wiring, all okay.	13/11/2024	600697	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\ELECT P&W	break light circuit breaker throwing of a couple times keep resetting it	BRAKE LIGHTS KEEP BLOWING CIRCUIT BREAKER Brake lights n/w, test and check all fuses and relays, found 1 blown fuse check operation still not working correctly. Check and test hobb switch under dash. Found to be not working. organise new switch and remove and replace. Check operation all working correctly. KWTRP274746 SWITCH STOP LIGHT SL4 1 31.53KW800005002 HOLDER-GLOBE INCLUDE GLOBE	13/11/2024	600697	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS	REPLACE WORK LIGHT RELAY Checked fuses for work lights, removed dash panel and found plug was disconnected, refit plug and check operation. Found one work light was flickering. Removed light and repaired wiring, all okay.	13/11/2024	600697	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS	BRAKE LIGHTS KEEP BLOWING CIRCUIT BREAKER Brake lights n/w, test and check all fuses and relays, found 1 blown fuse check operation still not working correctly. Check and test hobb switch under dash. Found to be not working. organise new switch and remove and replace. Check operation all working correctly	13/11/2024	600697	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Cooling\RADIATOR	needs new radiator cap fitted	REPLACE RADIATOR CAP Supply and fit new radiator capREPLACE RADIATOR CAP Supply and fit new radiator cap	13/11/2024	600697	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\RADIO	uhf seems to be playing up sometimes. distorted and crackily on other end.also channel dial knob is a little dicky when changing channels.	REPLACE UHF RADIO UNIT IF STILL FAULTING Removed dash panel and replaced UHF head unit. Also found spring gauge had a split air line and was leaking air. Sourced new olive and fitting, refit air line and checked, no further leaks. Refit dash panel.	13/11/2024	600697	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\CS	C Service		12/11/2024	599122	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS	NO BRAKE LIGHTS ON TRUCK OR TRAILERS Travel to meet driver at BMG workshop. Checked fuses and relays, all okay. Found one rear hot relay, change over stop lights relay with mirror heat relay. Check lights, worked okay and then cut out again. Source wiring diagram, traced wiring, no faults found. Remove interior panels, found some loose wiring on hobb switches. Tightened loose wiring and lights were working okay, refit all components.	06/11/2024	596589	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	CTI\CTI Elect	CTI wiring need looking at shorting out possible wire loom in front of R/H steer tyre	AIR CTI FAULT, DROPPING OUT, NO COMMUINICATION Inspected loom, from control box to entry point at cab. Found multiple rubs in wire near steering box. Cut damaged sections out and re joined. Checked operation, no communication. Opened control box, found earth to be snapped at the terminals. Stripped & re-connected. All ok	01/11/2024	596589	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CTI Drive	DrivLine\CTI Drive	AIR CTI FAULT, DROPPING OUT, NO COMMUINICATION Inspected loom, from control box to entry point at cab. Found multiple rubs in wire near steering box. Cut damaged sections out and re joined. Checked operation, no communication. Opened control box, found earth to be snapped at the terminals. Stripped & re-connected. All ok.	31/10/2024	596321	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Engine\AIR LEAK	Engine\AIR LEAK	R&R Governor Valve Found the governor valve to be leaking. Remove & replace with new valve. Tested operation, all ok.	31/10/2024	596321	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	VehService\BS		22/10/2024	591131	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\TAIL SHAFT	DrivLine\TAIL SHAFT	R&R UNI JOINT @ GEARBOX Unbolt and removed tail shaft. Remove and replaced yoke nut, tightened to spec. Reinstalled tail shaft with new bolts and tensioned.	22/10/2024	591131	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\WIPERS	replace wiper blades	REPLACE WIPER BLADES Supply and fit new wiper blades.	22/10/2024	591131	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\BATTERY	batteries seem to be getting slugish	LOAD TEST & CHECK BATTERIES Removed all battery terminals and load tested all batteries. Passed all okay. Driver to monitor	22/10/2024	591131	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\LIGHTS	Body\LIGHTS	PASSENGER SIDE LOW BEAM LIGHT Lowered bull bar and removed cover from RH light. Found low and high beam not working. Disconnected plugs and test for 12v and earth, all okay. Sourced new light assembly, installed. Test operation, all okay. Refit cover and bull	17/10/2024	589651	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		16/10/2024	589115	Completed	Mt Gambier	STK	XV65RM	BEAUREPAIRES - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	VehService\BS		14/10/2024	552109	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	VehService\AS		28/09/2024	580271	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Tyres\FITMENT	Tyres\FITMENT 1+2		27/09/2024	580271	Completed	Mt Gambier	STK	XV65RM	BEAUREPAIRES - 3	P/MOVER
1049	Myrtleford - Workshop	Body\FUEL TANK	fuel gauge still playing up at times doesn't seem to read correct	CHECK FUEL GAUGE NOT READING CORRECT Driver advised fuel gauge working intermittently. Shows full tank when tank is not full. Inspected wiring & plug from fuel level sensor to side of gear box. Wire was squashed in multiple places. Plug had come loose. Removed the damaged wiring & replaced plug. Ran new wire and fit up. Cable tied in place & check operation. All operating correctly. Advised driver to monitor.	26/09/2024	579907	Completed	Mt Gambier	STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1049	Myrtleford - Workshop	Engine\OIL LEAK	Engine\OIL LEAK	CHECK OIL CAP Oil cap required replacing. Collected new cap from spare parts & fit to engine securely.	26/09/2024	579907	Completed	Mt Gambier	STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc		14/09/2024	571694	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\FUEL TANK	fuel guage working intermittently	Tested wiring to sender and gauge, could not fault.	11/09/2024	571364	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DriCabRep\ELECT P&W	passenger side mirror light not working	Removed lense and found to have blown globes. Replaced globes and fit new gasket in mirror. Refit lense.	11/09/2024	571364	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Chassis\SUSPENSION	rose joint on ride height rod worn	Replaced rose joints on ride height.	11/09/2024	571364	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\BREATHER	ADD BLU TANK NOT BREATHING PROPERLY	AD BLUE TANK NOT BREATHING Found filter on breather was blocked with crystalised ad blue. Cleaned out breather and replaced filter.	11/09/2024	571364	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	TURBO BOOST DASH LIGHT IS OUT	On inspection found the turbo boost light was n/w on dash. Removed the dash panel & found the globe was blown. Removed & replaced with new globe. Tested operation, all ok. Re-installed dash panel.	11/09/2024	571364	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Chassis\FUEL TANK	Fuel Guage Not Working. (Barry Maney P/O: L088337)	R&R FUEL SENDER Brought truck into workshop. Removed fuel sender from tank & replaced with new. Found gauge in cab was incorrect, tested with VDO. Found gauge was faulting, removed from dash & fit with new gauge. Turned ignition on, all was working ok. Put dash back together & returned manuals.	24/08/2024	560423	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Steering\PWR STEER	Check Steering, Truck Steering All Over The Road. (Barry Maney P/O: L088337)	CHECK STEERING - ALL OVER THE ROAD AND 1/4 OF A TURN SLACK AT WHEEL Jacked steer axle, check king pins & tie rod ends. Tensioned pinch bolt on pitman arm. Check sector shaft movement, all in spec. Recommend rotating steer tyres, due to uneven wear.	24/08/2024	560423	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CLUTCH	Check And Adjust Clutch. (Barry Maney. P/O: L088337)	CARRY OUT CLUTCH ADJUSTMENT Inspected clutch adjustments, all within specification.	24/08/2024	560423	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER

				CTI HOSE LEAKING Inspected CTI hoses & fittings, sprayed with soapy water. Found crimped fitting on RHR inner hose to be leaking.							
1049	Myrtleford - Workshop	CTI\CTI Drive	Check All CTI Hoses For Leaks. (Barry Maney P/O: L088337)	Removed & replaced hose. All ok	24/08/2024	560423	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Engine\BREATHER TAKES A WHILE TO LEVEL OUT BETWEEN TANKS, BLOCKED BREATHER OR CROSS OVER PIPE ? GAUGE SHOWING HIGHER THAN ACTUAL LEVEL Inspected tanks, made sure both tanks were fully open. Inspected breathers for blockages, found RH breather to be									
1049	Myrtleford - Workshop	Engine\BREATHER	blocked. Cleaned o		23/08/2024	558440	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			DrivLine\CLUTCH Adjust clutch Adjusted the clutch to specification. Started truck &									
1049	Myrtleford - Workshop	DrivLine\CLUTCH	tested operation. All ok		23/08/2024	558440	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Engine\FUEL TANK CHECK FUEL GAUGE (RELAY) Removed fuel sender from fuel tank & tested operation. Found sender to be faulty. No part in stock. New part ordered & truck to return for fitting once arrived. Put									
1049	Myrtleford - Workshop	Engine\FUEL TANK	components back together.		23/08/2024	558440	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Air Con\AIR CON R&R A/C BELT Inspected on service & found A/C belt was worn. Removed and replaced A/C belt, tensioned.									
1049	Myrtleford - Workshop	Air Con\AIR CON	Tested operation, all ok		23/08/2024	558440	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Susp\SHOCK ABS RHR SHOCKER BUSH R&R Unbolted shocker, removed old bushes. Fit new bushes and									
1049	Myrtleford - Workshop	Susp\SHOCK ABS	tensioned bolt to spec. All ok		23/08/2024	558440	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\AS	VehService\AS		21/08/2024	558192	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\FITMENT	1+2		18/08/2024	552779	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4		17/08/2024	552779	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		17/08/2024	552779	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		17/08/2024	552779	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		17/08/2024	552779	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		17/08/2024	552779	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\AS	VehService\AS		29/07/2024	527926	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		24/07/2024	542486	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
			AIR CTI SYSTYEM STILL PLAYING UP, BK FIXED BROKEN WIRE LAST TIME Further inspect wiring from control box to cab. Pulled control box apart and inspected, found two wires snapped at									
1049	Myrtleford - Workshop	CTI\CTI Drive	communication module. Cut back wiring an		19/07/2024	542486	Completed	Mt Gambier STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\AS	VehService\AS INSPECT AIR CTI ISSUE Checked wiring in cti box on LH side of engine. Checked over head console wiring where displays are for CTI, all okay. Chased wiring from CTI box to cab. Found wire rubbed under cab. Cut out rubbed section and rejoined. Secured wiring and checked inflation on tires, all okay.		19/07/2024	541604	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	CTI\CTI Drive	NGACX1211 INSUL TAPE BLACK		17/07/2024	541604	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrivLine\CLUTCH	CLUTCH NEEDS ADJUSTING. DRIVERS SIDE MIRROR LIGHT OUT Found high beam not working on service. Removed cover and found blown globe, got new globe and fitted. Fit cover and		17/07/2024	541604	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Elect	all okay.		04/07/2024	531914	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	CTI\CTI Drive	PASS SIDE AIR CTI LINE SHORT AND RUBBING ON TYRE Found air cti hose rubbing on guard, remove hose & fitted correct hose		04/07/2024	531914	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			AD BLUE LEAK Found adblue tank sender leaking, removed tank sender, replaced filter and oring. Put back in and cleaned up. All									
1049	Myrtleford - Workshop	Engine\ADBLUE	okay		04/07/2024	531914	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	CTI\CTI Drive	PASSENGER SIDE FRONT CTI HOSE APEARS TO SHORT AS RUBBING ON TYRE	AB	30/06/2024	529796	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			REPLACE LOW LHR DRIVE BRAKE - Removed air cti lines. Jacked up LH rear axle, removed wheels, brake drums & linings. Installed new brake pads with new hardware. Fit new brake drum. Refit wheels									
1049	Myrtleford - Workshop	Brakes\BRK RELINE	& tensioned. Adjust brakes.		19/06/2024	508944	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	DRIVERS SIDE HEAD LIGHT BROKEN DAY LIGHT LENSE - Inspect light, light working okay, damaged lense only. Head light to replaced as a complete unit. LABOUR $94.50		16/06/2024	522564	Completed	Mt Gambier STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER	
1049	Myrtleford - Workshop	Elect\BATTERY	CHECK BATTERIES - Load tested batteries, found one battery failed. Removed battery & replaced with new. Tested voltage & charging, all okay. PARTS $143.17 | LABOUR $202.50		16/06/2024	522564	Completed	Mt Gambier STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER	
			USB DASH PLUG / SOCKET N/W - Inspect fuse, all okay. Tested power with multimeter, all ok. Found usb charger faulty. Repalced with new. PARTS $70.68 | LABOUR $135									
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DASH LIGHTS - Removed dash cluster, replace blown globe. PARTS $7.14 | LABOUR $67.50		16/06/2024	522564	Completed	Mt Gambier STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER	
1049	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH - Carried out clutch adjust to spec check operation all okay. LABOUR $94.50		16/06/2024	522564	Completed	Mt Gambier STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION B Service		13/06/2024	518841	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\BS	SERVICE KMS 519012		08/06/2024	517859	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\B1 Svc	B 1 Service		08/06/2024	508944	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\Punct	3 ADJUST CLUTCH - carried out clutch adjustment as required. LABOUR $94.50 REPLACE AD BLUE CAP - Supply and fit new ad blue cap. PARTS $66.03 | LABOUR $67.50		31/05/2024	493983	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	DrivLine\CLUTCH	CRUISE LIGHT N/W - Removed dash cluster and replaced blown globe, refit dash.		24/05/2024	493983	Completed	Mt Gambier STK	XV65RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER	
1049	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection PO# L086172	KM's 508944	24/05/2024	493983	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION DRIVERS SIDE WINDSCREEN PISSA NEEDS REPLACING.- Removed and replaced both		23/05/2024	493983	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabRep\WIPERS	washers, all okay. COMPLETED ON 30/4/24 L085815. DRIVERS SIDE WINDSCREEN PISSA NEEDS REPLACING.		11/05/2024	514933	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrivLine\DIFF OIL	REPLACE FRONT & REAR DIFF OIL DRIVERS SIDE HEADLIGHT SEEMS TO HAVE A SLIGHT WOBBLE IN IT WHEN DRIVING - Removed head light and tightened the loose bowl holder for head light. Secured with pop rivet and refit light. also, Replaced mirror globe on. DRIVERS SIDE HEADLIGHT SEEMS TO		11/05/2024	514933	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	HAVE A SLIGHT WOBBLE IN IT WHEN DRIVING.	COMPLETED ON 30/4/24 L085815	11/05/2024	514933	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabRep\WINDSCREEN	-BOTH WINDSCREENS NEED LOOKING AT WITH THE CLIPS & CRACKS IN THEM. Service As Per Attached Checklist **MINI B SERVICE**		11/05/2024	514933	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\B1 Svc	PO# L085797		11/05/2024	493983	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		11/05/2024	493983	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Steering\WHEEL ALGN	STEER ALIGNMENT - TRIDENT TRUCKS CARRIED OUT STEER ALIGNMENT Carry out A Service as per job card for T909 X15		30/04/2024	492598	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\AS	PO# L085539		27/04/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		27/04/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabRep\SEAT	-NEED A NEW DRIVERS SIDE SEAT COVER.	Supply lambs wool seat cover as requested.	17/04/2024		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
1049	Myrtleford - Workshop	Susp\WHEEL ALGN	*NEEDS WHEEL ALIGNMENT (URGENT) PULLING LEFT BAD.GOOD YEAR MT GAMBIER TURNED STEER TYRES ON THE RIM TO STOP 1049 PULLI		06/04/2024	480145	Completed	Mt Gambier STK	XV65RM	BEAUREPAIRES - 3	P/MOVER	
1049	Myrtleford - Workshop	Tyres\FITMENT	1-2		06/04/2024		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body	THUD OCCASIONALLY UNDER DRIVERS FEET AREA - Found grille was loose and hitting front of cab. Removed grille, found bolts were stripped & rubbers wornb. Replaced rubbers & install new bolts.		05/04/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Elect\DRV LIGHT	REPAIR LIGHTS - Found RH low beam shroud was missing a screw. Installed new screw as required. Adjusted both high & low beam lights.		05/04/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Body\DAMAGE	CHECK BULL BAR DAMAGE AFTER HITTING ROO - Inspect bull bar for cracks, all okay. Checked mountings, all okay.		05/04/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabRep\WIPERS	NEW WIPER BLADES. Service As Per Attached Checklist	REPLACE WIPER BLADES - Supply and fit new wiper blades.	05/04/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	VehService\BS	PO# L085105		05/04/2024	480145	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		05/04/2024	480145	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabRep\SEAT	-NEED A NEW DRIVERS SIDE SEAT COVER.		05/04/2024		Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabRep	-SLIGHT THUD/ TAPPING OCCASIONALLY UNDER DRIVERS FEET AREA AGAIN. ALTERNATOR NOT CHARGING - Drove to breakdown and found the fan belt tensioner was seized. Removed belt and tensioner. Installed new tensioner and fit new belt. Started and tested charging of		05/04/2024		Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Engine\BELTS/TENS	alternator, 14.2 volts, all okay. After hours breakdown alternator not charging. Cookys diesel to attened. Travel to site, tilt cab and found a;ternator seized.Disconnect batteries and remove belt, unbolt alternator attempt to remove pulley but it was seized. Travel back to work shop to retive new pulley. Fit new pulley, install new alternator connect wiring and belt		29/03/2024	477815	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Engine\ALT2 DR	start truck and check operation all charing correctly. Travel back to work shop.	Sublet repair did not get KMS	28/03/2024		Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabRep\WIPERS	-NEED NEW WINDSCREEN WIPER BLADES.job done refer entry 184155 job432415. -NEED NEW WINDSCREEN WIPER BLADES.		17/03/2024	471928	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	

			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	PO# L084698		17/03/2024	471928	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/03/2024	471928	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Engine\FUEL TANK	NEW WIPER BLADES.	REPLACE RHF FUEL TANK STRAP RUBBER - replace RH fuel tank strap rubber, fit new and tension all okay.	17/03/2024	471928	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabRep\WIPERS	BLOCK LEFT HAND WINDSCREEN SQUIRTER.	CHECK WIPERS - Blow out sprayer lines, found split line. Remove and replace sprayer line test operation all okay.	17/03/2024	471928	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabRep\HOUSKEEP	NEED A NEW DRIVERS FLOOR MAT.	REPLACE DRIVERS FLOOR MAT - Replace drivers side floor matt.	17/03/2024	471928	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Body\FUEL TANK	PASSENGER SIDE FUEL TANK NOT BREATHING PROPERLY.	CHECK FUEL TANK - Checked for blocked breathers/both fuel tanks,clean out both breathers - ok	17/03/2024	471928	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			TEST & CHECK BATTERIES - Load tested the 4 batteries. Top 2 were fine, the bottom 2 were not										
			functioning. removed the bottom 2 batteries & refitted with new ones. Put all terminals back on. Started										
1049	Myrtleford - Workshop	Engine\BATTERY	truck, started fine - all ok.		09/03/2024	468512	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		09/03/2024		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	DrCabRep\DOOR LOCK	DOOR CARD LOOSE - Remove door card, replaced door clips as required, resecured door card.		25/02/2024	460276	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		25/02/2024	460276	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Service As Per Attached Checklist										
			** MINI B-SERVICE**										
1049	Myrtleford - Workshop	VehService\B1 Svc	PO# L084217		25/02/2024	460276	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			AIR LEAK @ GF - Travel to Greenfreight yard, check for faults, found governor valve was constantly										
			exhausting. Return to workshop and collect parts. Return to truck, remove governor valve & replaced										
1049	Myrtleford - Workshop	Engine\GOV VALVE	new. Adjusted vlave, checked, all okay.		24/02/2024	460033	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Comp	SPEED LIMIT CERTIFICATE - Carried out speed limiter check as required.		09/02/2024	460276	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Tyres\FITMENT	1-2		09/02/2024		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
			AD BLUE TANK SUCKED IN - Found ad blue tank was sucked in. Removed cap & check filter, found to be blocked										
1049	Myrtleford - Workshop	Engine\ADBLUE	Attempt to clean out, no good. Replaced tank filter.		03/02/2024	450045	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			REPAIR TANK STRAPS - Found x4 tank strap rubbers were bunched up. unbolt tank straps & remove rubbers,										
1049	Myrtleford - Workshop	Body	cleaned straps & installed new rubbers. Tightened straps.		03/02/2024	450045	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			HEATER TAP LEAK - Found heater tap leaking. Blocked off coolant lines, remove heater tap & repalced with new.										
1049	Myrtleford - Workshop	Engine\HEATER TAP	Reconnect coolant lines, cleaned area from leak.		03/02/2024	450045	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			ABS FAULTS - Connect to truck to locate abs fault. Found no power getting to A trailer as plug was corroded on										
1049	Myrtleford - Workshop	Brakes\ABS	truck. Cleaned out corrosion in plug & continue repair on trailer.		03/02/2024	450045	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabRep\DOOR LOCK	DOOR TRIM COMING OFF - Refit door trim & secured.		03/02/2024	450045	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Body\WIPERS	REPLACE WIPER BLADES - Supply & fit new wiper blades.		03/02/2024	450045	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Elect\WORK LIGHT	LOADING/ WORK LIGHTS NOT WORKING.		02/02/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	PO# L083745		02/02/2024	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Service As Per Attached Checklist										
1049	Myrtleford - Workshop	VehService\BS	PO# L083310		14/01/2024	440288	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		14/01/2024	440288	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabElect\RADIO	NO DASH LIGHT FOR (MAIN TRANS TEMP GAUGE)done on B service refer invoice 374473. NO DASH LIGHT FOR (MAIN TRANS TEMP GAUGE)		14/01/2024	440283	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
				FRIDGE N/W - Removed mattress and removed fridge cover. Disconnect fridge and removed from									
				truck. Send to be tested, failed. Kenworth supplied new fridge. Recover brackets from original fridge,									
1049	Myrtleford - Workshop	DrCabElect\ELECT P&W	TRUCK FRIDGE??	fit to new. installed new fridge to truck, checked operation, all okay.	13/01/2024	435335	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	DrCabElect\GPS	DVR health check.		12/01/2024	529796	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\FITMENT	1-2		12/01/2024		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	DrCabRep\DOOR LOCK	WEATHER SHEILD RATTLING - Removed the weather shield from the door & cleaned the surfaces on the truck and weather sheild. Applied new		20/12/2023	434222	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
			THUMPING FEELING UNDER DRIVERS FEET SOMETIMES - Tighten loose grille. Checked										
1049	Myrtleford - Workshop	DriCabRep	kingpins for excessive movement, all okay, no faults.		14/12/2023	431013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH - carried out clutch adjustment to spec, all okay.		14/12/2023	431013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			TRUCK FRIDGE PLAYING UP - Removed the mattress and lift cover off fridge. Tested power										
1049	Myrtleford - Workshop	DrCabElect\ELECT P&W	output, all okay. Fridge to be replaced. Sorting with KW.		14/12/2023	431013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
				LH DOOR SEAL LEAKING - Applied grease to door seal. Checked sealing and closing okay.									
1049	Myrtleford - Workshop	DriCabRep\DOOR LOCK	LEFT SIDE DOOR SEAL STILL LEAKS SOME WATER IN WHEN WASHING CAB.	Ordered new door seal. Replace next service.	14/12/2023	431013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
				UHF STATIC WHEN TALKING - Removed dash panel & replaced UHF hand piece. Tested,									
1049	Myrtleford - Workshop	DrCabElect\RADIO	UHF HANDLE NEEDS REPLACIMNG APPARENTLY A LITTLE. STATICY WHEN WE TALK.	all okay.	14/12/2023	431013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	#L082912		14/12/2023	43013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		14/12/2023	43013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Air Con\AIR CON	AIRCON NEEDS LOOKING AT (NOT REALLY COLD AIR)repaired at B/M refer invoice 373481. AIRCON NEEDS LOOKING AT (NOT REALLY COLD AII		14/12/2023	431013	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Tyres\ROTATION	rotate steer tyres		01/12/2023	423291	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER		
			B 1 Service,										
			Jack up steer axle check bearings and king pins. Disconnect from trailers to grease & inspect turn table.										
1049	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		26/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	order number - L082425		26/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Body\MOUNTS	CAB STILL SEEMS TO LEAN DOWN SLIGHTLY ON DRIVER'S SIDE FRONT.		26/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		26/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
				Found ad blue fitting and hose leaking during service. No hose in stock.									
				organise new fitting, remove old fittings. Source new fittings & hose. Manufactured new hose & install									
1049	Myrtleford - Workshop	Engine\FUEL TANK	REPAIR AD BLUE LEAK	, secure in position. Start & check over for leaks, all okay	24/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
				Found coolant leak during service, found heater tap not fully open. Opened fully									
1049	Myrtleford - Workshop	Cooling\COOL LEAKS	heater tap leak. NOT REQUIRED.	& cleaned surface. Also found coolant filter leaking. Replaced filter & pressure test system, no leaks	24/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Engine\OIL LEAK	ENGINE OIL DIPSTICK RUBBER SEAL IS A LITTLE PERISHED.	ordered new part.	24/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabRep\SEAT	DRIVERS SEAT BELT JAMMING UP. HARD TO GET OUT. KEEPS LOCKING UP. (HAS STARTED TO FREE UP SOMETIMES)	check operation of seatbelt, cleaned & lubricate all operating okay.	24/11/2023	419864	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Elect\ELECT P&W	MIRROR LIGHT N/W - Removed mirror cover, replaced blown globe. Refit cover.		03/11/2023		Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabRep\DOOR LOCK	PASSENGER SIDE DOOR SEAL SEEMS TO LEAK WATER WHEN WASHING TRUCK.	PASSENGER SIDE DOOR LEAKING - Adjusted door to seal shut.	03/11/2023		Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	DASH LIGHT OUT FOR (AXLE OIL FRT RR)	DASH LIGHTS - removed dash and replaced blown globe for axle temp. Refit dash, all okay.	03/11/2023		Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	PO# L082025		03/11/2023	410046	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/11/2023	410046	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Tyres\FITMENT	1-2		25/10/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	Engine\ENG TUNE	Engine Tuneup		22/10/2023	404463	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
			Service As Per Attached Checklist										
1049	Myrtleford - Workshop	VehService\CS	PO# L081606		14/10/2023	400513	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		14/10/2023	400513	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes\YEL VALVE	YELLOW PARKING BRAKE. PUSH IN, PULL OUT, BUTTON IS LEAKING A LITTLE AIR.	YELLOW BRAKE BUTTON LEAKING AIR - Removed dash panel, replaced park brake valve as required. Replaced dash panel, tested operation.	13/10/2023	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Brakes\EBS FAULTS	EBS LEAD CORRODED - removed EBS lead and replaced with new. End was broken off and other end was corroded. Secured with new.		13/10/2023	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	ENGINE WATER TEMP GAUGE DASH LIGHT OUT.		13/10/2023	529796	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L081315		28/09/2023	391263	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	ENGINE WATER TEMP GAUGE DASH LIGHT OUT.		28/09/2023	391263	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Brakes\YEL VALVE	YELLOW PARKING BRAKE. PUSH IN, PULL OUT, BUTTON IS LEAKING A LITTLE AIR.		28/09/2023	391263	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		28/09/2023	391263	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		21/09/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
			Service As Per Attached Checklist										
1049	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L080844		07/09/2023	380224	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/09/2023	380224	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Body\PANELS	MISSING SMALL BOLT FROM DRIVER'S SIDE REAR BELLY PLATE AT THE BACK OF IT.done on A service refer invoice 368407. MISSING SMALL BO		29/08/2023	369847	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	DRIVER'S SIDE HEADLIGHT COVER NEEDS REPLACING. WAYNE SAID TO GET IT REPLACED.done on A service refer invoice 368407. DRIVER'S SID		29/08/2023	369847	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L080458		23/08/2023	369847	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Susp\SPRNG PACK	PASSENGER SIDE STEER SPRING SEEMS TO BE SAGGING LOW THAN PASSENGER SIDE.	SPRING ARCH REPORT COMPLETED.	23/08/2023	369847	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		23/08/2023	369847	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		16/08/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		16/08/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		16/08/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		16/08/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		16/08/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
			B 1 Service,										
			Jack up steer axle check bearings and king pins.										
			Replace cabin filter.										
1049	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L080043		03/08/2023	359728	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Susp\SPRNG PACK	PASSENGER SIDE STEER SPRING SEEMS TO BE SAGGING LOW THAN PASSENGER SIDE.		03/08/2023	359728	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Cooling\ENG FAN	ENGINE FAN SOMETIMES COMING ON AND STAYING ON.		03/08/2023	359728	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	ENGINE BRAKE LIGHT IS OUT ON DASH.replace dash light globes as per invoice 366700. ENGINE BRAKE LIGHT IS OUT ON DASH.		14/07/2023	349791	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	HEAD LIGHT COVERS- REPLACE TORX SCREWS WITH PHILLIPS HEADS.		14/07/2023	349791	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
			Carry out A Service as per job card for T909 X15										
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L079535		13/07/2023	349791	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		13/07/2023	349791	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		12/07/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER		
1049	Myrtleford - Workshop	DrCabElect\UNST/GAUGE	ENGINE BRAKE LIGHT ON DASH NOT WORKING. Done on A service. ENGINE BRAKE LIGHT ON DASH NOT WORKING.		28/06/2023	340890	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		
			Service As Per Attached Checklist										
1049	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L079229		28/06/2023	340890	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		28/06/2023	340890	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER		
1049	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE TANK STILL NOT BREATHING PROPERLY.unblock and clean breahter refer invoice 365408 the job was done while 1049 was having it A		15/06/2023	332431	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER		

			Carry out A Service as per job card for T909 X15 (Barry Maney)									
1049	Wodonga - Workshop	VehService\AS	Purchase Order Number: WW078922		14/06/2023	332431	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		14/06/2023	332431	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\ROTATION	Rotation		25/05/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
1049	Myrtleford - Workshop	Engine\COOL FILTR	replace leaking coolant filter		21/05/2023	319994	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
1049	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DRIVER'S DOOR LATCH MAY NEED A SLIGHT ADJUSTMENT. HAS SLIGHT WIND NOISE AROUND DOOR WHILE DRIVING.		20/05/2023	319994	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Mini B Service As Per Attached Checklist									
1049	Wodonga - Workshop	VehService\BS	Barry Maney PO# L078430		18/05/2023	319994	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	DriCabRep\MOUNTS	STILL HAS A THUD UNDER DRIVER'S SIDE OF CAB.		18/05/2023	319994	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
			REPLACE WORN KING PINS.									
1049	Wodonga - Workshop	Steering\KING PIN	(BOOK IN, EXTRA TIME REQUIRED)		18/05/2023	319994	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/05/2023	319994	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
			REPLACE WORN KING PINS.									
1049	Myrtleford - Workshop	Steering\KING PIN	(BOOK IN, EXTRA TIME REQUIRED)		03/05/2023	309738	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Carry out A Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\AS	PO# L078064		03/05/2023	309738	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DriCabRep\MOUNTS	STILL HAS A THUD UNDER DRIVER'S SIDE OF CAB.		03/05/2023	309738	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/05/2023	309738	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Breather on Fuel tank									
1049	Myrtleford - Workshop	Engine\FUEL TANK	Removed blocked breather, cleaned and refit		20/04/2023	304305	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		13/04/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
			Service As Per Attached Checklist									
1049	Wodonga - Workshop	VehService\CS	Barry Maney PO# L077694		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Body	Ignore		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	DrivLine\DIFF OIL	Diff Oil Change		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	DrivLine\CLUTCH	CLUTCH NEEDS ADJUSTING.		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	DriCabRep\MOUNTS	STILL HAS A THUD UNDER DRIVER'S SIDE OF CAB.		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	DrCabElect\INST/GAUGE	NO ENGINE BRAKE LIGHT.		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Brakes\ABS	DASH LIGHTS ON ALL THE TIME. (ESC, ABS/ATC OFF ROAD, TRUCK ABS)		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/04/2023	300299	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP09	puncture repair		28/03/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
			Lights fault on dash with key on/off									
1049	Myrtleford - Workshop	Elect\ELECT P&W	Trace fault to diode inline for daytime lights. Remove diode & replace with new. All ok		25/03/2023	293472	Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
1049	Myrtleford - Workshop	DriCabRep\WIPERS	WIPER BLADES.		23/03/2023	289002	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\WIPERS	FILL WASHER BOTTLE.		23/03/2023	289002	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\FUEL TANK	ADD BLUE TANK SOMETIMES NOT BREATHING PROPERLY AGAIN.		23/03/2023	289002	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\ROTATION	1 & 2		23/03/2023		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
			Carry out A Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L077253		16/03/2023	289002	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\HOUSEKEEP	Grill outer chrome cover loose L/H Side		16/03/2023	289002	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Cruise control light on dash not working.		16/03/2023	289002	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		16/03/2023	289002	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
			B 1 Service,									
			Jack up steer axle check bearings and king pins.									
1049	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		25/02/2023	280090	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Service As Per Attached Checklist									
			MINI B SERVICE									
1049	Myrtleford - Workshop	VehService\BS	PO# L076825		25/02/2023	280090	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Body\FUEL TANK	CLEAN/BLOW OUT FUEL TANK BREATHERS PLEASE. 07/02/2023		25/02/2023	280090	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	NO DASH LIGHT ON FOR ENG OIL PRESS GAUGE. 07/02/2023		25/02/2023	280090	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Brakes\ABS	ABS/ATC OFF ROAD BUTTON STILL LIGHTING UP ITSELF ON AND OFF. 07/02/2023		25/02/2023	280090	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	NO FUEL GAUGE DASH LIGHT. 07/02/2023		25/02/2023	280090	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		25/02/2023	280090	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
			Carry out A Service as per job card									
1049	Myrtleford - Workshop	VehService\AS	PO# L076578		08/02/2023	270111	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		08/02/2023	270111	Completed	Mt Gambier STK	XV65RM	BARRY MANEY - 3	P/MOVER	
1049	Myrtleford - Workshop	Engine\JAKE BRAKE	NO ENGINE BRAKE DASH LIGHT.		24/01/2023	260832	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes\ABS	ABS/ATC OFF ROAD LIGHT ON AND OFF BY ITSELF A FEW TIME EACH DAY.		24/01/2023	260832	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Service As Per Attached Checklist									
1049	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L076200		18/01/2023	260832	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Engine\OIL LEAK	CUMMINS TO FIX OIL WEEP.		18/01/2023	260832	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		18/01/2023	260832	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		15/12/2022		Completed	Mt Gambier STK	XV65RM	Albury Workshop	P/MOVER	
			Carry out A Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L075590		07/12/2022	529796	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/12/2022	529796	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\MUDGUARDS	DRIVERS SIDE FRONT DRIVE GUARD NEEDS TIGHTENING.		01/12/2022	243002	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\MUDGUARDS	DRIVERS SIDE FRONT DRIVE GUARD NEEDS TIGHTENING.		29/11/2022	243000	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body	SEEMS TO BE A SLIGHT THUD NOISE SOMETIMES AND SEEMS TO MAYBE BE FROM UNDER THR THE DRIVERS FOOT AREA.		29/11/2022	243000	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Elect\DRV LIGHT	DRIVERS SIDE SPOTLIGHT SEEMS TO FLICKER AT TIMES.		29/11/2022	243000	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Carry out Mini B Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L075288		24/11/2022	243002	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		24/11/2022	243002	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DrCabElect\IAP	repairs to forward facing camera		03/11/2022		Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Carry out A Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L074806		02/11/2022	230980	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\PANELS	FRONT DECK PLATE NEEDS A TACK WELD.		02/11/2022	230980	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	DIFF LOCK BUTTONS NOT WORKING I DON'T THINK.		02/11/2022	230980	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Elect\BATTERY	TRUCK BATTERIES SEEM WEAK AT TIMES. ONLY JUST STARTED FOR ME ON MONDAY 10/10/22.	replace batteries	02/11/2022	230980	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		02/11/2022	230980	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
			Service As Per Attached Checklist									
1049	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L074521		11/10/2022	219772	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		11/10/2022	219772	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\PANELS	REAR LIGHT/ TAIL BAR NEEDS TIGHTENING ON BOTH SIDES.		01/10/2022	210742	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Elect\DAY LIGHTS	LEFT HAND SIDE HEADLIGHT DAY RUNNING LIGHT PLAYING UP OR IS OUT.		01/10/2022	210742	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DASH LIGHT (AXLE OIL RRRR) IS OUT.		01/10/2022	210742	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\ROTATION	pos 1 & 2		28/09/2022		Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Carry out A Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L074156		20/09/2022	210742	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/09/2022	210742	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
			Service As Per Attached Checklist									
1049	Myrtleford - Workshop	VehService\CS	Barry Maney PO# L073789		31/08/2022	199599	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DrivLine\DIFF OIL	Diff Oil Change		31/08/2022	199599	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		31/08/2022	199599	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DRIVER'S SIDE WEATHER GUARD NEEDS RE-STICKING DOWN.		13/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes\ABS	ABS/ATC OFF ROAD BUTTON LIGHTS IS CONTINUOUSLY ON.		13/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Elect\HEAD LIGHT	HEADLIGHT SWITCH HAS SOMETHING GOING ON, YOU SWITCH THEM ON WITH KEY OFF AND IT TURNS POWER TO DASH ON AND MAKES A N		13/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Elect\ELECT P&W	TURBO TIMER HAS LOST POWER.		13/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Cooling\COOL LEAKS	COOLANT LEAK CHECKED.		13/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Mini B Service As Per Attached Checklist									
1049	Wodonga - Workshop	VehService\BS	Barry Maney PO# L073379		09/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Body\DAMAGE	STICK JAMMED UNDER CAB NEAR DRIVERS FUEL TANK ONLY JUST SEEN.		09/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Cooling\RADIATOR	COOLANT LEVEL CHECKED PLEASE.		09/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Engine\EXHAUST	EXHAUST CLAMP BEHIND DRIVERS SIDE OF CAB NEEDS TIGHTENING OR REPLACING.		09/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/08/2022	189665	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 8 tyres		31/07/2022		Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		31/07/2022		Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		31/07/2022		Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
1049	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		31/07/2022		Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Carry out A Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\AS	PO # L073121		24/07/2022	180368	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Engine\ADBLUE	Adblue tank sucking in	CLEARED VENT.	24/07/2022	180368	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		24/07/2022	180368	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DrCabElect\GPS	Unit not tracking		07/07/2022	529796	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Service As Per Attached Checklist									
1049	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L072618		28/06/2022	168807	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		28/06/2022	168807	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Body\MOUNTS	Removed grill assemble to remove light mounting bar		23/06/2022	159380	Completed	Mt Gambier STK	XV65RM	Myrtleford Workshop	P/MOVER	
			Carry out A Service as per job card for T909 X15									
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L072319		09/06/2022	159384	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DriCabRep\ST Weel	STEERING WHEEL WON'T TILT FORWARD. CABLE MIGHT BE JAMMED..		09/06/2022	159384	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DOOR SKIN DRIVER SIDE KEEPS PULLING AWAY FROM DOOR.		09/06/2022	159384	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	
1049	Myrtleford - Workshop	Elect\ELECT P&W	CLEARANCE LIGHT FRONT BOLSTER LEFT HAND SIDE NEEDS REPLACING.		09/06/2022	159384	Completed	Mt Gambier STK	XV65RM	Wodonga Workshop	P/MOVER	

1049	Myrtleford - Workshop	DrivLine\CLUTCH	CLUTCH BRAKE NEEDS ADJUSTING.		09/06/2022	159384	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		09/06/2022	159384	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\GPS	Unit restarting eratically. Signal dropping in & out, replaced sim card & SD card but fault still occurring. Sent unit to MTDATA for repairs		01/06/2022	529796	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres		01/06/2022	159380	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Elect\ELECT P&W	breakdown repairs Brownys Mobile Auto Electrics		28/05/2022	529796	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service As Per Attached Checklist		27/05/2022	151645	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Wodonga - Workshop	VehService\B1 Svc	Barry Maney PO# L072043 Carry out A Service as per job card for T909 X15		27/05/2022	151645	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	Barry Maey PO# L071749		13/05/2022	140776	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		13/05/2022	140776	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Wodonga - Workshop	VehService\BS	Barry Maney PO# L071487		28/04/2022	129625	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Wodonga - Workshop	Body\HOUSEKEEP	Grill outer chrome cover loose L/H Side		28/04/2022	129625	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Wodonga - Workshop	DrCabElect\INST/GAUGE	Cruise control light on dash not working.		28/04/2022	129625	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		28/04/2022	129625	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L071265		14/04/2022	121567	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Body\HOUSEKEEP	Grill outer chrome cover loose L/H Side		14/04/2022	121567	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Cruise control light on dash not working.		14/04/2022	121567	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Engine Tune Up Cummins Mt Gambier		14/04/2022	121567	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Engine\ENG TUNE	PO# L071105		03/04/2022	111751	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service Service As Per Attached Checklist		31/03/2022	109943	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	Barry Many PO# L071039		31/03/2022	109943	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	DrivLine\DIFF OIL	Replace Diff Oils & Filters Carry out A Service as per job card for T909 X15		19/03/2022	100967	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	Conducted by Barry Maney PO# L070749		18/03/2022	100767	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		18/03/2022	100767	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres		09/03/2022	91850	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Body	fit supplied bullbar Truck hit box on road, driver complaining pulling to the left badly Check over on pit, jack up & check damage spin wheel, no run out, could not locate any damage.		05/03/2022	91851	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Steering	Driver to monitor Service As Per Attached Checklist		03/03/2022	88874	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L070457		03/03/2022	91851	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/03/2022	91851	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Tyres\ROTATION	POS 1 & 2 Carry out A Service as per job card for T909 X15		02/03/2022	89100	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	PO # L070142		15/02/2022	81070	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job NEED NEW DRIVER SIDE WIPER BLADE.		15/02/2022	81070	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Wodonga - Workshop	DriCabRep\WIPERS	NEW DRIVER WIPER BLADE.	REPAIRED AT BARRY MANEY, MT GAMBIER.	11/02/2022	77618	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Wodonga - Workshop	DrCabElect\SCALES	"C" CHANNEL ON RIGHTWEIGH SCALES IN TRUCK CABIN KEEPS LOSING POWER.	REPAIRED AT BARRY MANEY, MT GAMBIER	11/02/2022	77618	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Wodonga - Workshop	DrivLine\GEARBOX	GEAR CABLES/ LINKAGES NEED ADJUSTING ON GEARBOX. (VERY GRIPPY)	REPAIRED AT BARRY MANEY, MT GAMBIER	11/02/2022	77618	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP09	puncture repair		02/02/2022	71562	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP07	puncture repair		30/01/2022	70550	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Engine\ADBLUE	After Treat Light coming on at times.		26/01/2022	71546	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	DrivLine\CLUTCH	Please Adjust Clutch(No Free Play)		26/01/2022	71546	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist Mini B Service		26/01/2022	71546	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\B1 Svc	PO# L069784 Carry out A Service as per job card for T909 X15		26/01/2022	71546	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	O/N L12863		11/01/2022	60901	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job fuel tank strap and j bracket bent (hit roo)		11/01/2022	60901	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\DAMAGE	straighten fit supplied lights behind grill		18/12/2021	56694	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Elect\DRV LIGHT	L12830		18/12/2021	56694	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Body\DAMAGE	replace damaged air horn Service As Per Attached Checklist		10/12/2021	50604	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Wodonga - Workshop	VehService\BS	O/N L 12764		09/12/2021	50604	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/12/2021	50604	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\IAP	GPS Not working Carry out A Service as per job card for T909 X15		25/11/2021	529796	Completed	Mt Gambier	STK	XV65RM	Wodonga Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	O/N L12640		20/11/2021	40575	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/11/2021	40575	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Body\MOUNTS	make 2x light bars		19/11/2021	40574	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2 tyres - steer tyre run flat bolt on runout to return to workshop and fit new tyres Service As Per Attached Checklist ********* MINI B SERVICE **********		03/11/2021	30796	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	VehService\BS	O/N L12515		02/11/2021	31159	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		02/11/2021	31159	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\AS	O/N L12406		14/10/2021	20510	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		14/10/2021	20510	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2021	7877	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	VehService\CS	O/N L12244 Remove old unit. Run wires and cables for supplied IAP unit. Replaced cable as necessary. Mounted new unit under passenger seat and wire in. Re-assemble and test correct operation. Setup with MT Data support and run tests. Old unit was in top console and IAP unit didn't fit up		17/09/2021	7877	Completed	Mt Gambier	STK	XV65RM	BARRY MANEY - 3	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\IAP	there so had to go under passenger seat.		18/08/2021	468	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	DrCabElect\INST/GAUGE	fit park brake alarm		23/06/2021	500	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Elect\DRV LIGHT	fit driving lights		23/06/2021	500	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Elect\WORK LIGHT	fit work lights		23/06/2021	500	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
1049	Myrtleford - Workshop	Body\TOOLBOX	supply CTI tools + box + CTi spares		23/06/2021	500	Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER
				*Fit supplied Mtdata tracking unit kit (with tablet & MDVR) *Fit Load scales and wire into Mtdata *Park brake alarm tracking unit serial #474002305 Travel to TCTC & return. Mount and wire up supplied Mtdata tracking unit with Tablet, phone & GPS antennas, MDVR with forward facing camera & Engine data module. Connect cabling, connect power, earth & ignition, remove and refit dash and trim panels to access and run wiring, solder connections, program tracking unit and MDVR and setup with Mtdata as necessary. Secure and insulate wiring assemble and test. Fit supplied airweigh gauge and connect to Mtdata tracking unit and connect airlines to truck airbag lines as necessary. Fit relays to factory relay holders to make factory park brake							
1049	Myrtleford - Workshop	DrCabElect\GPS	Arkon - Install new MT Data Units	alarm work and test operation.	17/06/2021		Completed	Mt Gambier	STK	XV65RM	Myrtleford Workshop	P/MOVER