EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
1048	Colac - Colac	Brakes\ABS	TRAILER ABS FAULT, CLEAR ALL CODES & TEST		01/09/2026	870000	Completed	Mt Gambier	GTK	XV64RM	MM DIESEL - 3	P/MOVER
1048	Colac - Colac	DrCabElect\ELECT P&W	DIAGNOSE & REPAIR WIPER MOTOR ISSUE. WIPER MOTOR FAULTY & REPLACED.		18/08/2026	870000	Completed	Mt Gambier	GTK	XV64RM	MM DIESEL - 3	P/MOVER
1048	Colac - Colac	DrCabElect\JAP	CHECKED MT DATA FAULT. REMOVED & REPLACED UNIT FROM DECOMMISSIONED TRUCK		26/07/2026	870000	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\SLACK ADJ	AUTO SLACK ADJUSTERS ON REAR DRIVE APPEAR FAULTY. REPLACE WORN THROTTLE PEDAL		07/07/2026	870000	Completed	Mt Gambier	GTK	XV64RM	MM DIESEL - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\RWC COMP	L134646		01/07/2026	860889	Completed	Mt Gambier	GTK	XV64RM	MM DIESEL - 3	P/MOVER
1048	Myrtleford - Workshop	Body	FUEL & AD-BLUE TANK RUBBERS NEED REPLACING		18/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Body\PANELS	MODIFY & FIT REAR DECK PLATE		17/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\FAULT CODE	SCAN ENGINE, CHECK ENGINE LIGHT ON. FAULT WITH PRIMER PUMP WIRING. VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		16/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		15/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\SEAT	REPAIR FAULTY SEAT BASE		11/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKES		09/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Hydraulics\VALVES	FIT HYDRAULIC CONTROL SWITCHES, PLUM UP HYDRAULIC LINES TO TRAILER, CHECK OPERATION OF ALL TRAILERS		07/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\WORK LIGHT	CHECK REVERSE LIGHT FAULT & REPAIR		03/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\ELECT P&W	CONTINUATION OF PTO CONTROLS WIRING		03/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\ELECT P&W	MAKE UP WIRING LOOM, FIT HYDRAULIC HOSES & WIRING FOR TRAILER CONTROLS. FIT RIGHT WEIGH GAUGE & PLUMB/WIRE.		01/06/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\MOUNTS	REPLACE FRONT CAB MOUNTS		28/05/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	RECTIFY BLOCKED AD-BLUE BREATHER.		28/05/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		27/05/2026	860889	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Hydraulics\PUMP	FIT PTO & HYDRAULICS CONTROL UNIT.		16/05/2026	860489	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\AIR BAG	Susp\AIR BAG	REMOVE AND REPLACE LH DRIVE FRONT AIRBAG Fit 4 new batteries Remove radiator and clean out Clean intercooler Replace lower radiator mounts Remove and clean bottom of the core Fit new bottom radiator tank Refit radiator to the truck Radiator tank and gaskets supplied. 12 May Refit A/C condensor; intake pipes; grill and coolant hoses. Test drive.	13/05/2026	860489	Completed	Mt Gambier	GTK	XV64RM	MM DIESEL - 3	P/MOVER
1048	Myrtleford - Workshop	Cooling\RADIATOR	RADIATOR BOTTOM TANK TO BE REPLACED DUE TO THE MOUNTS BEING BROKEN OFF. PARTS SUPPLIED BY BORDER RADIATORS.	Fit new cab shocks to the left hand front and right hand front - Cab shocks supplied	11/05/2026	860489	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\BATTERY	Engine\BATTERY	FIT 4 NEW BATTERIES diagnose faulty clutch, discuss with wayne & rod replace clutch	11/05/2026	860489	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH VehService\BS B Service	clutch supplied by eaton	02/05/2026	860489	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	L133766		28/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Susp	ALL DRIVE LOWER SHOCK BUSHES NEED REPLACING	REPLACED TWO LOWER SHOCKER RUBBERS	28/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Steering	RH FRONT STEER HUB METALLIC, CHANGE WITH KING PINS	FIT NEW KING PINS + WHEEL BEARINGS TO STEER AXLE	28/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Susp	HCV ROSE JOINTS WORN	FIT NEW ROSE JOINTS	28/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		16/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	BORDER BANDAG PTY LTD -3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12		16/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	BORDER BANDAG PTY LTD -3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		16/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	BORDER BANDAG PTY LTD -3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		16/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	BORDER BANDAG PTY LTD -3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\BATTERY	CHECK BATTERY CONDITION, REPLACE TWO WITH S/HAND ONES.		14/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	REPLACE MISSING AD-BLUE CAP		08/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 9	CALL OUT	01/04/2026	860489	Completed	Mt Gambier	GTK	XV64RM	BORDER BANDAG PTY LTD -3	P/MOVER
1048	Myrtleford - Workshop	Elect\BATTERY	CALL OUT TO JUMP START TRUCK AT CUMMINS DERRIMUT CARPARK		31/03/2026	860489	Completed	Mt Gambier	GTK	XV64RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		30/03/2026	860489	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\WORK LIGHT	REPAIR LOAD LIGHT FAULT CHECK ENGINE DOWN ON POWER & BLOWING BLUE SMOKE REFIT CLIP ON TURBO WAIST GATE		19/03/2026	860489	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\HOUSEKEEP	INTERCOOLER IS U/S		13/03/2026	860489	Completed	Mt Gambier	GTK	XV64RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\Cool	REPLACE INTERCOOLER & MOUNTS (CUMMINIS SUPPLIED PARTS)		13/03/2026	860489	Completed	Mt Gambier	GTK	XV64RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\SEAT	REPLACE SEAT WITH SPARE VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		12/03/2026	860489	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		28/02/2026	860489	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		21/02/2026	854407	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\BOOSTER	REPLACE LEAKING BRAKE BOOSTER ON RIGH HAND FRONT DIFF.		18/02/2026	854407	Completed	Mt Gambier	GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	VehService\BS B Service AFTER H'RS BREAKDWON CALL OUT FEE	BELT TENSIONER FAILED Get tools and supplies from workshop then travel to breakdown at Kentbruck. Remove and replace fan belt tensioner as required, test - all OK KW89440DYC TENSIONER BELT AUTOMATIC H.D. 1 110.65	10/02/2026	844082	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\BELTS/TENS	NGCALLOUT DIAGNOSE & REPAIR 0 VOLTAGE ON VOLT GAUGE, CHECK ALT FAULT, REPLACED FUSE HOLDER. DIAGNAOSE & REPAIR CTI FAULT, REPAIRED BROKEN WIRING ON CTI UNIT.	POL Travel kms: 120	09/02/2026	819250	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\BREAKDOWN	DIAGNOSE & REPAIR AFTYER TREAT LIGHT ON, REMOVED & CLEANED AD-BLUE INJECTOR.		07/02/2026	843517	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\CS	VehService\CS C Service		23/01/2026	819250	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		19/01/2026	829370	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\DOOR LOCK	REPAIR BENT HINGE ON DRIVERS DOOR FROM A WIND GUST		17/01/2026	829370	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		12/01/2026	819250	Completed	Mt Gambier	GTK	XV64RM	BORDER BANDAG PTY LTD -3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		08/01/2026	819250	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\WHEEL SEAL	R/R HUB SEAL LEAKING		04/01/2026	819250	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Chassis\FIFTH WHEE	CHECK QRTT FOR SERVICEABILITY		15/12/2025	775586	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Replace Diff oils		15/12/2025	806627	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\TRANS OIL	VehService\TRANS OIL Replace Synthetic Transmision oil		15/12/2025	806627	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.		26/11/2025	793579	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter. CHECK KING PINS Jack and check king pin play. Found RHS to have slight		22/11/2025	786472	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	Steering\HOUSEKEEP	movement up and down -		22/11/2025	786472	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	BodyLab	CHECKED A/C DRAIN HOSE FOR BLOCKAGE & CLEAR BLOCKAGE.		17/11/2025	775586	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	ElecLab	CHECK DAYTIME RUNNING LIGHT & PARK LIGHT FAULT DriCabRep\SEAT		17/11/2025	775586	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\SEAT	NEW SEAT BELT BUCKLE FIT TEMPORARY ROAD TRAIN SIGNAGE TO BULL BAR		16/11/2025	775586	Completed	Mt Gambier	GTK	XV64RM	JF MECHANICALS - 3	P/MOVER
1048	Myrtleford - Workshop	BodyLab	L097776		11/11/2025	775586	Completed	Mt Gambier	GTK	XV64RM	MAXIPARTS P/L - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	CHECK AND REPLACE BLOWN DASH LIGHTS	Remove dash cluster and replaced blown globes for turbo boost and engine oil temp. Refit dash. KW800005002 HOLDER-GLOBE INCLUDE GLOBE	31/10/2025	770824	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\SEAT	DRIVERS SEAT CONSTANTLY SQEAKING VehService\AS A Service	Tightened loose shocker bolt for seat. Lubricated seat mechanism.	31/10/2025	770824	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	L097499		30/10/2025	770824	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER

				Jack RH Rear axle, remove wheels, brake booster, slack adjuster, s-cam tube, drum and brake assembly. Punch out old bushes then punch in new bushes. Fit new s-cam, then refit s-cam tube, slack adjuster, booster, brake, drum and wheels. Adjust as needed, all ok								
1048	Myrtleford - Workshop	Brakes	S-cams on truck wearing, replace when brakes are due	KWCK3993BM TRP S-CAM BUSHING KIT BUSHING KIT 1 16.32KW2210W7537FWPZ S-CAM 28S 11.6' L/H TRP EQUIVALENT CS966	20/10/2025	762606	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE BREATHER BLOCKED	Remove adblue breather and blow out. Reconnect and check, all ok	20/10/2025	762606	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	MAIN TRANS TEMP DASH LIGHT N/W	Remove and replace dash light as required KW800005002 HOLDER-GLOBE INCLUDE GLOBE	20/10/2025	762606	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Elect\DRV LIGHT	LH DAYTIME RUNNING LIGHT N/W	Lights on LH side going out then sometimes RH lights going out. Working intermittently, will need more diagnosis time	20/10/2025	762606	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DrivLine\CLUTCH	clutch needs adjusting VehService\BS B Service	Adjust free play in clutch and clutch brake gap	20/10/2025	762606	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\BS	L097266		14/10/2025	759432	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Engine\BREAKDOWN	AFTER HOURS CALL OUT 27/9/25 TO G/F MT GAMBIER YARD L097204	Travel to Greenfreight yard, jacked cab and connect jumper pack. Truck would not turn over. Remove panel under ignition and inspect fuse, all okay. Checked fuses in passenger side dash, all okay. Tested start motor voltage, and voltage when key turned. No voltage. Check fuses in battery box, found ignition and cab fuse blown. Replaced both fuses. Started truck all okay.	01/10/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Body\MIRRORS	MIRROR HEAT N/W	Un-clip door trims and inspect, found plug for mirror heat loose. Tighten plug and check operation, all ok	29/09/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DriCabRep\AIR CON	water leak on passenger floor (possible to do with windscreen washer)	WINDSCREEN WASHERS N/W - LEAKING IN CAB Pull dash apart and inspect for leaks, found none. Reassemble dash and inspect further. Found motor for washers not working and plug broken. Remove and replace plug and fit new motor. Check operation, all ok KWP10600 PUMP - 12 VOLT 1 43.11KW963040-3 CONNECTOR 1 16.30KW0-0929937-3 TERMINAL 2 3.88K	29/09/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	windscreen washer not working (possible leaking on passenger floor)	WINDSCREEN WASHERS N/W - LEAKING IN CAB Pull dash apart and inspect for leaks, found none. Reassemble dash and inspect further. Found motor for washers not working and plug broken. Remove and replace plug and fit new motor. Check operation, all ok KWP10600 PUMP - 12 VOLT 1 43.11KW963040-3 CONNECTOR 1 16.30KW0-0929937-3 TERMINAL 2 3.88K	29/09/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Body\HOUSEKEEP	AD BLUE TANK BREATHER BLOCKED	Adblue tank breather blocked, remove and flush breather with hot water until clear	29/09/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Steering\HOUSEKEEP	CHECK KING PINS	Jack and check king pin play. Found RHS to have slight movement up and down - all ok, within spec	29/09/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	TANK RUBBERS WORN AND TWISTED VehService\AS A Service	Inspect and found x2 left and x1 right rubber worn and need replacing. Undo bolts and remove rubbers. Install new rubbers and secure KWK89-1004-1260 LINING-TANK STRAP	29/09/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\AS	L097038	GREENFREIGHT A SERVICE Carry out service as per Greenfreight checklist.	26/09/2025	752281	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DriCabRep\RADIO	DriCabRep\RADIO UHF HAND PIECE NEEDS REPLACING	UHF HAND PIECE NEEDS REPLACING Work order 200925 Pull dash apart and unplug hand piece. Replace with new magnetic hand piece. Reassemble dash and check operation. UHF still not working as should. Check aerial, all looked ok. Looked into UHF further, found needs replacing. Remove dash and pin holder. Fit new pin holder and fit new unit. Refit dash and test operation, all ok. KWMC553B UHF MICROPHONE 1 59.39KWTX4500S RADIO CB 5W 80 CHANNEL INCLUDES SCAN SLI	18/09/2025	740049	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DrCabElect\ELECT P&W	MIRROR HEATING NOT WORKING	MIRROR HEAT N/W Work order 200925 Unable to complete due to time restrictions UHF HAND PIECE NEEDS REPLACING Work order 200925 Pull dash apart and unplug hand piece. Replace with new magnetic hand piece. Reassemble dash and check operation. UHF still not working as should. Check aerial, all looked ok. Looked into UHF further, found needs replacing. Remove dash and pin holder. Fit new pin holder and fit new unit.	18/09/2025	740049	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DriCabRep\RADIO	UHF HANDPIECE NEEDS REPLACING.	Refit dash and test operation, all ok CHECK BRAKES AND WHEEL BEARING HAS A RUBBER SMELL FROM lh DRIVE Check brake temperatures, found both brakes sitting even and shoe gap wears the same. Check ride height, was aligned correctly. Inspect further and saw new drive tyres, smell	18/09/2025	740049	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Steering\WHEEL BRGS	Steering\WHEEL BRGS CHECK WHEEL BEARINGS	possibly from tyres wearing in. WINDSCREEN NOT DEFROSTING REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563	10/09/2025	740049	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DriCabRep\AIR CON	check aircon. Not defrosting windscreen at times unable to see clearly. DONE 3/9/25	Check A/C operation, found to be dropping to 7 degrees and heater going to 45 degrees. Remove cover and check mixer for direction and airflow, all working as should. WELD BOTTOM RADIATOR MOUNTS	08/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Cooling\RADIATOR	Weld bottom radiator mounts DONE 3/9/25	Inspect bottom radiator mounts. Grind crack and weld repair. Paint as required, all ok WELD BOTTOM RADIATOR MOUNTS	08/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Body\MOUNTS	WELD UP BOTTOM RADIATOR GUSSET FOR BOTTOM RAD MOUNT DONE 3/9/25	Inspect bottom radiator mounts. Grind crack and weld repair. Paint as required, all ok 5 02KWZZZ110 AIR LEAKS Tech(s): 8101 8097 113.75Air slow to build up check for leaks Inspect for air leaks, found several leaks at fittings in to air tanks remove and re seal. Re check for air leaks all okay.	08/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Body\AIR LEAK	Body\AIR LEAK DONE 3/9/25	KWAQ68-D0T-4X2 PTC CNCTR 1/4 X 1/8 M CTI throwing up error leak	08/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	CTI\CTI Drive	CTI\CTI Drive DONE 3/9/25	Inspect fault codes for CTI in unit. Re stick aerial on windscreen as needed, test operation, all ok repair dash lights n/w	08/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Elect\ELECT P&W	Elect\ELECT P&W 3/9/25	Inspect and replace globe for cruise and globe for retard, check operation, all ok KWK87006 GLOBE & HOLDER-12 VOLT	08/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12		08/09/2025	740049	Completed	Mt Gambier GTK	XV64RM	BORDER BANDAG PTY LTD -3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		08/09/2025	740049	Completed	Mt Gambier GTK	XV64RM	BORDER BANDAG PTY LTD -3		P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter. L096668	MINI B SERVICE Jack up steer axle, check bearing & king pin. Replace cab filter Disconnect truck and trailer. Check over turntable and king pin. Greased all components, all within spec. Reconnect.	05/09/2025	740049	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6 DRIVE		02/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BORDER BANDAG PTY LTD -3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2 STEER		02/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BORDER BANDAG PTY LTD -3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8 DRIVE		02/09/2025	730804	Completed	Mt Gambier GTK	XV64RM	BORDER BANDAG PTY LTD -3		P/MOVER

1048	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DriCabRep\DOOR LOCK	Rh door having trouble opening and closing Test operation of door, found not working. Remove door card and found light wiring interfering with hook. Reroute and test, found to still be hard to open. Investigate further found mechanism loosed. Fasted bolts as required, operation all ok.	30/08/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Air Con\AIR CON	REPLACE LEAKING HOSE FROM CONDENSOR TO COMPRESSOR WO #199340 REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 ordered parts.	REPALCE RUBBED A/C HOSES AS PREVIOUSLY DIAGNOSED REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Connect A/C gauges and recovered remaining gas. Cut cable ties and removed p clamps. Remove worn hoses and installed new. Remove receiver drier and replaced with new. Vacced down system and charge with new gas. tested A/C and checked operation, all okay.	25/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Cooling\RADIATOR	radiator mounts worn	RADIATOR MOUNTS WORN Found bottom radiator mounts were cracked. Repair next service	25/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\WIPERS	washer bottle leak	WASHER BOTTLE LEAK Removed old washer bottle. Change over parts to new bottle and installed. Connect hoses	25/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	GREENFREIGHT A SERVICE Carry out service as per Greenfreight checklist	22/08/2025	730804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 27-28		20/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BORDER BANDAG PTY LTD -3	P/MOVER
1048	Myrtleford - Workshop	Engine\COMPRESSOR	Condensor hose to compressor has rub in it - recommend to be replaced next service	REPLACE LEAKING HOSE FROM CONDENSOR TO COMPRESSOR WO #199340 REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 ordered parts.	18/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS FRONT AXLE TOP RH SHOCKER BUSHES	FRONT AXLE TOP RH SHOCKER BUSHES Unbolt top of RH front drive shocker, remove worn bushes and replaced with new. Refit shocker and tensioned bolts	18/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	Replace ad blue hose from douser pump to ad blue housing has rubbed through	REPLACE AD BLUE HOSE FROM DOSER TO AD BLUE HOUSING Work order 199340 Remove rubbed ad blue hose and replaced with new. Cable tied in position to prevent further rubs.	18/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\MIRRORS	TOP LH MIRROW LIGHT N/W	TOP LH MIRROR LIGHT N/W Removed mirror cover, replaced blown globe and refit cover	18/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS REAR AXLE SHOCKER BUSHES	REAR AXLE BOTTOM SHOCKER BUSHES Attempt to remove mounting nut on RH rear drive, would not come off. Cut off shocker and replaced with new.	18/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEEL	REPLACE PULL CORD ON TRUCK FOR TURNTABLE Inspect turn table cord, found to be too short. Remove and replace cord with new, all ok	18/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	Carried out B service as per checklist Disconnect truck and trailer. Check over turntable and king pin. Greased all components, all within spec. Reconnect	12/08/2025	724104	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON	CONNECTED TO DIAGNOSTIC SOFTWARE CONDUCT AIR SOLENIOD TEST FLUSH AIR SOLINOID WITH WATER CLEAN ADBLU INJECTOR REASEMBLE	07/08/2025	721471	Completed	Mt Gambier GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	CHECK ENGINE LIGHT CAME UP LAST NIGHT - NOW GONE OFF	Plugged into truck, found inactive code for ad blue doser air solenoid. Carried out solenoid click test, re check, all ok. Driver to monitor.	06/08/2025	720804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\HEAD LIGHT	Headlight globe n/w	Remove headlight and test wiring, found low beam to have no power, and found wiring to be broken. Repaired broken wiring, test operation of light found to still not be working. Remove headlight and replace with new, re-check operation, all ok	06/08/2025	720804	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service	GREENFREIGHT A SERVICE Carry out service as per Greenfreight checklist.	24/07/2025	710835	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\EBS FAULTS	Test EBS	Tested EBS. Turned ignition on and all warning lights illuminated including ESC. Started truck and all light turned off. As they should Turned on off road switch and ESC and ABS warning lights flashed to indicated they were turned off. As they should turned off off road switch and lights turned off. As they should.	24/07/2025	710061	Completed	Mt Gambier GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrivLine\CTI Drive	REPLACE LHR DRIVE AIR CTI ROTATOR DUE TO BEARING FAILED AND LEAKING AIR	Remove and replace LHR rotator	23/07/2025	710835	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\AIR LEAK	CAB AIR BLOWER LEAKING	Remove and replace cab air blower nozzle, all ok	23/07/2025	710835	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Chassis\SUSPENSION	VIBRATION/RATTLE UNDER DRIVERS SIDE FOOTWELL WHEN HITTING BUMPS AT SPEED . GETTING WORSTE	Tighten grille bolts and cover bolts over gearshift linkage, all ok	23/07/2025	710835	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\MOUNTS	R&R FRONT ENGINE MOUNTS	Undo front engine mounts. Jack up engine and remove old mounts. Install new mounts and lower engine. Tighten all bolts, all o	23/07/2025	710835	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	Engine\ADBLUE	Plug in and check fault codes, found air solenoid below normal range moderate level. Tilt bull bar and cab, remove air lines into pump and fit 6mm flush hose. Fill with water and set solenoid flush to 3 second intervals, complete solenoid flush and try to run doser override test, wouldn't run properly as ad blue not atomising properly. Inspect and found tank sucked in. Removed lid and found tank in vacuum. Removed pick up and drilled out blockage from breather. Refit and complete over ride test, passed successfully. Inspect dash lights for faults, turn ignition on, all working as should. Turn truck off and back on a few more times, no faults	23/07/2025	707460	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.		18/07/2025	702215	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Replace Diff oils		18/07/2025	702215	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\DAMAGE	Susp\DAMAGE	CLUNKING UNDER FEET WHEN GOING OVER BUMPS @ SPEED Work order 199062 Inspect all king pins, spring shockers, and cab mounts, all look ok. Inspect further and found bottom bolts on front grill about to fall out. Suspect the grill hitting on cab due to loose bolts is the cause for the clunking.	16/07/2025	702211	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\MOUNTS	DriCabRep\MOUNTS	CHECK BUMP STOPS AND REPLACE IF NEEDED Work order 198878 Check over all bump stops, all look ok	16/07/2025	702211	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS	CHECK LH SIDE SHOCKER MOUNT Work order 198878 Check over LH side shocker mount, mount was fine but has worn shocker bushes. Unbolt top shocker bolt and replaced worn bushes	16/07/2025	702211	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\LIGHTS	replace head light and protector L/H	DAMMGED HEADLIGHT AND COVER Removed and replaced headlight and protector. Found LH indicator was also damaged. Lowered bull bar and lifted cab to access wiring. Remove and replace indicator, check operation, all working ok	15/07/2025	703703	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER

1048	Myrtleford - Workshop	DrivLine\CTI Drive	DrivLine\CTI Drive	AIR CTI LINE RUBBING ON TYRE Removed air CTI line. Replaced with new one that is slightly longer so doesn't rub on tyre. Once fit made sure there was no leaking, all ok	14/07/2025	702211	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\SHOCK ABS	check shocker mounts L/H side	REPAIR DRIVE SHOCKERS Remove nut and remainder of rubber off shocker. Fit new washer and rubber, then tightened to spec. All ok	09/07/2025	692837	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	Body\FUEL TANK	RHF tank strap all rippled and fallen. Remove and replace with new, all ok	09/07/2025	692837	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\MIRRORS	Body\MIRRORS	MIRROR LIGHT N/W LH mirror light N/W, found both globes to be blown. Replaced globes, check operation, all ok	09/07/2025	692837	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		04/07/2025	692837	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\BREAKDOWN	Elect\BREAKDOWN	Travel to Camperdown BP Replace 2 blown ECM fuses & start truck.	04/07/2025	688737	Completed	Mt Gambier GTK	XV64RM	QT DIESEL SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\CTI Drive	BLOWN AIR CTI - REPLACE AND REORDER	Pulled truck in, spray over air CTI system and found loose fittings. Resealed, re tightened and retested, all ok	27/06/2025	689240	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\ELECT P&W	Check for voltage issue and de rate, possible wiring fault in battery box Blew both ECM fuses last night	Check fuse holders, all wiring in battery box. Plugged in and check codes, no codes active. Looked at wiring diagram and followed wiring up to cab found rubbed section of wiring, repaired cover and protect. Re check for faults okay. Road test did not re fault.	26/06/2025	689240	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\FUEL TANK	FUEL NOT CROSSING OVER BETWEEN TANKS	Check cross over lines, all ok. Check and removed breathers then cleaned. Found adblue breather blocked. Pulled sender out and cleaned breather. Refit sender into tank, all ok	19/06/2025	684499	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\AIR LEAK	air leak when engaging rear diff lock and interlock. possible coming from under cab. diff lock not engaging	When engaging diff lock, found air leak under cab. Removed clamps and cut air line out and fit joiner. Tested, all ok.	19/06/2025	684499	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\BATTERY	CHECK BATTERIES, LOAD TEST ETC	Check batteries, pulled all four terminals off and cleaned, also cleaned clamps. Check battery cells and topped up water levels. Fit everything back together. Truck went flat at GF yard. Remove old batteries after load test failed. Fit new batteries. Start truck, all seemed ok	19/06/2025	684499	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\HCV	Susp\HCV	RUBBED RIDE HEIGHT VALVE Found whole hose to be old and brittle. Replaced hose, and test operation. All ok	18/06/2025	679968	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\OIL LEAK	check oil. put 2 litres in on the 10/6	CHECK OIL, TOPPED UP 2 LITRES 10/06 Work order #198017 Inspect and found down pipe hose clamp loose. Tighten up and check, all ok	18/06/2025	679968	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\COOL LEAKS	check coolant. put 2 litres of coolant in on the 10/6	CHECK COOLANT - TOPPED UP 2 LITRES 10/06 Work order #98017 Checked coolant level, all looked ok	18/06/2025	679968	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	GF B SERVICE Carried out service as per chekclist Customer Instructions: Completed paperwork & Cleaned area TOOK ENGINE OIL SAMPLE & ECU DOWNLOAD Disconnect truck and trailer. Check over turntable and king pin. Greased all components, all within spec. Reconnect	13/06/2025	679968	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\BATTERY	Engine\BATTERY	JUMP START TRUCK AT YARD Travelled to Greenfreight yard and jump started truck.	12/06/2025	678965	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\TAIL SHAFT	DrivLine\TAIL SHAFT	R&R INPUT AND OUTPUT SHAFT SEAL Input and output seal leaking. Removed tail shaft, yokes and old seals. Cleaned area and installed new seals on yolk and diff. Fit new yolk nut to both ends. Fit tail shaft with 8x new bolts and tensioned to spec. Cleaned diffs, took for road test all ok.	04/06/2025	670527	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Cooling\HOUSEKEEP	Cooling\HOUSEKEEP	CHECK COOLING SYSTEM On test drive found water on passenger floor. Removed kick panels and inspect A/C components. Found evaporator drain blocked. Blew out drain, reinstalled and secured. Put all kick panels back together and cleaned water off floor	04/06/2025	670527	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DrCabElect\INST/GAUGE	SPEEDO GAUGE FLUCTUATING - MAYBE LOOSE WIRE Work order 197094 Tested wiring to the speedo and couldn't fault. Checked the sensor wiring and found a break in the wiring at yoke. Cut broken wires out and ran new wiring. Also found plug was broken internally. Fit new plug and secured all wiring. Test drove truck and test speedo operation, all ok	04/06/2025	670527	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\HCV	Susp\HCV	R&R ROSE JOINT ON RIDE HEIGHT Disconnected ride height rod from truck. Remove and replace worn rose joint on bottom RH side. Fit rod all ok	04/06/2025	670527	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP		02/06/2025	672469	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		02/06/2025	672469	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\RADIO	DrCabElect\RADIO	CHECK OUT UHF AND AERIAL - DRIVER SAID ALL HE COULD HEAR WAS STATIC Check UHF, test circuit from radio and aerial, all tested ok. Found aerial loose. Tighten and check, all ok	02/06/2025	670527	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\WIPERS	Body\WIPERS	REPLACE WASHER BOTTLE - LEAKING Remove washer bottle and replace with new	28/05/2025	664385	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\ELECT P&W	Elect\ELECT P&W	Wire up power socker in locker box with on off switch and constant power Ran wiring from fuse box down panel and under floor to passenger side tool box and added an inline fuse. Made bracket to hold cigarette socket. Mounted in toolbox, secured all wiring, all ok	28/05/2025	664385	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\ELECT P&W	speedo guage fluctuating. maybe loose wire	SPEEDO GAUGE FLUCTUATING Work order 197094 Unable to complete due to time restrictions Check for air leak under lh side of the cab Inspect for air leaks, found unloader valve and governor valve leaking. Replaced both with new. Recommend rekitting	28/05/2025	664385	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\AIR LEAK	Body\AIR LEAK	air drier due to water contamination. CHECK WIRING TO SCALES Inspect scales wiring and found wire broken off at back of plug. Cut wiring and pulled pin out of plug. Joined wire and refit to plug. Join wiring back to wiring on trailer,	26/05/2025	663580	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Chassis\SCALES	Chassis\SCALES	check operation, all ok filter Carried out Mini B Service as per Greenfreight checklist Replaced cab filter and air filter Customer Instructions: Greased and Adjusted Brakes Checked all Fluid Levels Completed paperwork & Cleaned area	23/05/2025	677195	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.	Replaced cabin air filter.	16/05/2025	663580	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		30/04/2025	650730	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER

1048	Myrtleford - Workshop	DriCabRep\WIPERS	CHECK WIPER WASHER FLUID	Filled up washer bottle, tested washers, no water spraying out, and motor not working. Found hole in washer bottle, drained and removed washer bottle. Remove bracket, cover hole, glue rubber to prevent rubbing. Fit washer bottle, test motor worked, reconnect plug, fill up washer bottle, all ok. Order new washer bottle to replace next service.	30/04/2025	650730	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\BLK VALVE	check black button (brakes) scales not working properly	Check over trailer for air leaks, located one in centre of dash. Remove triangle cover, find air leak in hose, remove air line from fitting, remove valve from bracket, remove fitting. Fit new fitting, refit valve into place, reconnect airlines and test, all ok. Refit triangle cover	30/04/2025	650730	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	VehService\BS		15/04/2025	640317	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Air Con	Air Con not working	24/3/25 -Labour - Diag AC no work. Remove grill to inspect cond. Carry out n2/h2 test, find cond US. Reassemble as nec, order parts 29/3/825 -Labour @ 632820 Kms - Retrieve truck from yard. Dismantle grill to access cond. Remove cond & repair seized pipe fitting. Modify mounting plates for new style cond & install/paint. C/O r/dryer, fit new style bug screen, vac & gas, C/O cabin filter, 500.00 1 550.00 Labour - Remove washer bottle & protect AC hoses from rubbing per 1049, reassemble, all good. Deliver back to yard.	04/04/2025	630264	Completed	Mt Gambier GTK	XV64RM	MIDWINTER MECHANICAL - 3	P/MOVER
1048	Myrtleford - Workshop	Steering\KING PIN	Steering\KING PIN	R & R KING PINS On service, found thrust bearing in king pin had collapsed. Jacked up steer and support on stands. Removed wheels and foundation plate. Remove stub axles, remove and replace bushes, rheemed to suit. Refit stub axles and installed. Shimmed king pins. Refit foundation plates and fit wheels. Adjust wheel bearings and filled hubs with oil. Tensioned all wheel nuts.	28/03/2025	631341	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	FIX/REPLACE WINDOW SQUIRTER	FIX/REPLACE WINDOW SQUIRTER work order 195506 Remove wiper blades and replace with new. Inspect windscreen washer nozzle ends and replaced with new, all okay	28/03/2025	631341	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ELECT P&W	USB PORTS NOT WORKING ON DASH. Michael spoke to James B	USB PORTS STILL NOT WORKING work order 195506 Tested USB ports found to one to be not connecting correctly, got new and installed check operation all working	28/03/2025	631341	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		28/03/2025	631341	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		28/03/2025	630643	Completed	Mt Gambier GTK	XV64RM	BEAUREPAIRES - 3	P/MOVER
1048	Myrtleford - Workshop	Body\DAMAGE	Body\DAMAGE	Deck plate/bash plate come off Supply and fit new deck plate locks. Adjusted to hold chassis, checked all ok.	19/03/2025	625807	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\RADIO	UHF mic not working	Test UHF, found hand piece was faulty. Remove and replace hand piece, test, all okay	18/03/2025	626746	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc		14/03/2025	621136	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\GEARBOX	DrivLine\GEARBOX	TRANSMISSION TOWER GASKET LEAKING Removed gear selector. Scrapped off old gasket and cleaned oil off. Fitted new tower gasket and mounted gear selector, all okay	14/03/2025	621136	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\AIR TANKS	Brakes\AIR TANKS	REPLACE PULL CORD CABLES ON AIRTANKS Found x3 pull cords were broken. Removed fittings and cut new ones to correct length. Fitted to truck, tested, all okay.	14/03/2025	621136	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ELECT P&W	DriCabRep\ELECT P&W	USB's in dash still dont have enough power have tried different leads Removed dash cluster and found polarities were opposites. Refitted polarities correctly, all working okay	14/03/2025	621136	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\SUSPENSION	Susp\SUSPENSION	Check over for rattle/squeak in front end Take truck for a test drive to inspect squeak or rattle. Found most evident on bumps. Return to workshop and put truck over shaker and inspect springs. Found springs are looking worn and sitting flat. Greased all points but still squeaking.	14/03/2025	621136	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\BRK RELINE	front drive axcle brakes getting low	FRONT DRIVE BRAKES GETTING LOW work order 194184 Inspect brakes, all were within spec.	14/03/2025	621136	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FIFTH WHEE	Turn table wear pads require replacing.	REPLACE TURN TABLE PADS work order 194184 Removed all bolts, welded nuts onto seized bolts and removed with socket. Removed turntable pads, cleaned surface and installed new. Tightened nuts to spec	14/03/2025	621136	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Steering\STEER UNI	Steering\STEER UNI	Replace steering column Remove steering column surround, removed steering column with puller. Unbolted clock spring and moved out the way. Unbolted indicator stalk and bracket, moved to the side. Disconnect steering shaft at bottom of column. Removed steering column, fit new. Refit all components previously removed.	26/02/2025	610350	Completed	Mt Gambier GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes\BRK O/HAUL	Brakes\BRK O/HAUL	REPLACE REAR DRIVE BRAKES Rear brake linings were past wear limit. Jacked up rear axle, removed wheels, brake drums and shoes. Installed new brakes and hardwear. Refit wheels, lowered axles. Tensioned wheel nuts and adjust brakes, all okay	26/02/2025	610350	Completed	Mt Gambier GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ELECT P&W	DriCabRep\ELECT P&W	USBs not getting enough power Tested USB power and behind switch. Power was low, removed USB port and replaced with new.	26/02/2025	610350	Completed	Mt Gambier GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS	Carry out service as per Greenfreight checklist. Customer Instructions: Completed paperwork & Cleaned area	20/02/2025	610350	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL		19/02/2025	600993	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\CS	VehService\CS		19/02/2025	600993	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\TRANS OIL	Transmission Oil Change		19/02/2025	600993	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\CTCH PACK	FIT NEW CLUTCH KIT (supplier by EATON under good will) FREE OF CHARGE done at (600080)kms		11/02/2025	601038	Completed	Mt Gambier GTK	XV64RM	BARRY MANEY - 3	P/MOVER

1048	Myrtleford - Workshop	DrivLine\GEARBOX	FIT REBUILT GEARBOX & NEW OIL & FILTER FIT NEW REAR MAIN SEAL MACHINE FLYWHEEL REPLACE REAR ENGINE MOUNTS all done at 600080kms	CHECK TRANS FOUND TOOTH IN GEARBOX Removed air lines and air tanks. Unbolt and removed tail shaft, remove trans cooler lines and fuel cross overs. Remove shifter and installed cover. Removed wiring loom and clutch linkage. Fit gearbox to jack, removed rear supports and bell housing bolts. Disconnect grease lines , lowered out gearbox. Change over sensors to new gearbox. change over input shaft. Removed clutch and fly wheel, send flywheel to be machined. Replaced rear main seal. Replaced spigot bearing. Reinstalled flywheel and tensioned. Installed new clutch and tensioned. Fitted new gearbox to jack and installed gearbox into truck. Fit bell housing bolts and rear support. Remove gearbox jack, reinstalled shifter and wiring loom. Connect up grease lines and arranged new adapotors and fittings where required for trans cooler lines. Refit fuel cross overs and air lines, Refit all other components previously removed. Carried out clutch adjustment. Take truck for a test drive, all okay. Inspect old gear box. Removed shift bar housing and inspected internals. Found tooth had come from auxiliary section of gearbox. Also had wear on main box dogs	11/02/2025	601038	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\DAMAGE	REPAIR FAILED IDLER GEAR BUSH IN GEAR TRAIN CUMMINS TO PAY FOR ALL PARTS & 1/2 OF LABOUR REPLACE DAMAGED GAERS GASKETS & SEALS FIT OIL COOLER FIT MAIN BEARINGS CLEAN ALL PARTS CHANGE ENGINE OIL & FILTER TUNE ENGINE	(WE PAYED EXTRA ON JOB NOT COVERED BY WARRANTY) FIT NEW TURBO BIG END BEARINGS RADIATOR MOUNTS OIL & FILTERS & 1/2 LABOUR COST done at (600080)kms	30/01/2025	598883	Completed	Mt Gambier	GTK	XV64RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\ABS	Brakes\ABS	CHECK ABS CODES DUE TO LIGHT ON Connected PC to truck & checked for codes. Found code 12 for router. Inspected all 3 routers and A, Dolly & B. Checked all fuses & plugs, all ok. Inspected for power at plugs, all ok. Further investigation found the A trailer to have a fault in the router. See A trailer RO for job.	28/01/2025	600993	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS	R&R RECOMMENDED BUSHES Removed & replaced the LH bottom shocker as required. Remove Lh shocker, found one of the studs was seized. Required oxy to cut and remove shocker. Replaced with new, all ok.	28/01/2025	600993	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	VehService\BS	5 13KWZZZ244 CHECK ACCESSORIES Tech(s): 040362 150.00USB PORT POWER NOT SUFFICIENT Tested power to USB, found good voltage & no current drop. Removed the USB & fit new socket in place. Tested cigarette socket & traced wires, found open circuit in rear of dash. Repaired damaged wiring and re tested. All ok	07/01/2025	590109	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ELECT P&W	cigarette lighter socket has no power	KW20868?4-2 USB CHARGE PORT - DUAL, NO BAC 5 13KWZZZ244 CHECK ACCESSORIES Tech(s): 040362 150.00USB PORT POWER NOT SUFFICIENT Tested power to USB, found good voltage & no current drop. Removed the USB & fit new socket in place. Tested cigarette socket & traced wires, found open circuit in rear of dash. Repaired damaged wiring and re tested. All ok	23/12/2024	598883	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ELECT P&W	USB ports not enough power to charge phone & tablet	KW20868?4-2 USB CHARGE PORT - DUAL, NO BAC 4 14KWZZZ201 Tech(s): 040362 75.00 CHECK WIPERS	23/12/2024	598883	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\WIPERS	need new windscreen washer bottle has leak	WINDSCREEN WASHER BOTTLE LEAKING work order #192594 Inspected washer bottle for obvious leaks. Jacked cab and tested for leaks. Unable to fault.	23/12/2024	598883	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Susp\Torque Rod	LH rear torque rod needs replacing next service	2 06KWZZZ003 TORQUE ROD BUSHES Tech(s): 8094 8100 225.00LH REAR TORQUE ROD BUSHES work order #192594 Removed rear LH torque rod, 2 x bolts were seized and required cutting. Pressed out existing bushes & fit with new. Re fit torque rod back in place & tightened mounting bolts. All ok.	23/12/2024	598883	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\SLACK ADJ	S-cams; RH rear, LH rear & LH front need shim kit at next service. LH rear also needs bush kit at next service.	KWB3931O BUSHING 2 232.20 RESHIM S-CAMS: RH REAR, LH REAR AND LH FRONT NEW BUSH KIT TO LH REAR work order #192594 On inspection found both LH drive axle s-cam bushes were worn. Jacked up axles, removed wheels, drums, brakes, slack adjusters & s-cam tubes. Hit bushes out of the s-cam tubes & removed the s-cam. Fitted new bushes to s-cam tubes. Fitted seals and secure s-cams & fit booster back to mount. Fitted slack adjusters to s-cam & shimmed as required. Refit brakes, drums and wheels. Connected air CTI and tensioned all wheels & nuts. Removed supports & built up air. Adjusted brakes and greased as required. All ok. KWK1T8042 KIT - CAMSHAFT REPAIR 1 34.86KWCS9661M TRP S-CAM 28S 11.6' L/H EQUIVALENT 2210W 1 60.06KWCS9662M TRP S-CAM 28S 11.6' R/H EQUIVALENT 2210V 1 60.06<<< Total For Job 1 >>> 754.98	23/12/2024	598883	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\DAY LIGHTS	LH daytime running light n/w	Cut cable ties & test for power flow. Found diode u/s. Sourced 6A diode from Anvil. Wired into truck & secured. All ok	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\BRAKE ADJ	LH drive s-cams slight movement	Inspected s-cams. RH rear, LH rear & LH front need shim kit at next service. LH rear also needs bush kit at next service	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\MOUNTS	Front and rear engine mounts wear	FRONT & REAR ENGINE MOUNTS - RECHECK Inspected front & rear engine mounts. All ok. Monitor & re check next service.	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Steering\TIE ROD	LH rear torque rod slight wear	Inspected LH rear torque rod bush, ok for now. Will need replacing at next service.	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\WIPERS	DRIVERS SIDE WINDSCREEN WASHER N/W	Checked operation of windscreen washers. Water was not hitting window. Cleaned out sprayers. Jacked cab & checked if washer bottle motor was operating all working, Blew air in fluid hose, air hit windscreen. Filled washer bottle, put cab down & filled the bottle to the top. Tested operation. All operating ok	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\DOOR LOCK	Drives door seal falling off	Removed door seal and installed new door seal.	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	STEERING WHEEL ADJUSTMENT cant lock in place	Tested operation of steering column, unable to lock. Removed column cover & checked all parts & components. Priced a new steering column and advised service manager. Re fit steering column cover.	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\SEAT	SEAT BELT NOT RETRACTING	SEAT BELT NOT RETRACTING Tested operation of seat belt, seemed ok. Used some silicone spray to free up & tested again. All ok	13/12/2024	581325	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER

			CHECK ENGINE FEELS LIKE GOT NO POWER & IS LOADED LOSING AIR PRESSURE Connect laptop and check faults, found active code for ad blue pressure high. Removed injector and found doser pump was continuously pumping air. Carry out download and confirmed with Cummins ad blue pump faulty. Removed ad blue pump and replaced with new. Carry out doser over ride test,									
1048	Myrtleford - Workshop	Engine\ADBLUE		10/12/2024	585711	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	Job Created from Purchase Order #: 106216	10/12/2024	584575	Completed	Mt Gambier	GTK	XV64RM	BEAUREPAIRES - 3		P/MOVER
			GREENFREIGHT A SERVICE Carry out service as per Greenfreight checklist. Replaced air filter Customer Instructions: Replace air tank drain bung									
1048	Myrtleford - Workshop	VehService\AS	VehService\AS	02/12/2024	581321	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Brakes\AIR TANKS	Brakes\AIR TANKS	26/11/2024	570169	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			CHECK RADIATOR USING COOLANT Work Order # 191411 Inspect and pressure test cooling system to locate leaks. Found drips coming from heater tap. Remove and replace heater tap as required. Topped up coolant levels and tested									
1048	Myrtleford - Workshop	Cooling\COOL LEAKS	check radiator. using coolant??	26/11/2024	570169	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			Steering wheel moves up and down when locked Removed steering wheel covers and inspect movement. Need to order new shocker and cable. Fit next service. Refit									
1048	Myrtleford - Workshop	Steering\PWR STEER	Steering\PWR STEER	26/11/2024	570169	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc FAULTY STEERING SHOCKER AND CABLE	22/11/2024	570169	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	Gas Strut	18/11/2024	575160	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			CHECK ADBLUE BREATHER AS BLOCKED Found the Ad Blue tank breather to be blocked. Removed level sensor, unblocked the breather tube, poured hot water									
1048	Myrtleford - Workshop	Engine\ADBLUE	Engine\ADBLUE	01/11/2024	551525	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			FRONT GRILL LOOSE AND RATTLING Tightened grill bolt. Inspected steering column, was able to move column up whilst locked in. Removed steering shaft plastic covers. Removed & replaced steering column lock									
1048	Myrtleford - Workshop	Steering	Steering	01/11/2024	551525	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	DrCabElect\RADIO	radio/stero arial needs to be replaced.	01/11/2024	551525	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			CHECK LIGHTS On inspection found LH mirror lights inoperable. Remove cover from mirror and replace globes as required. Checked									
1048	Myrtleford - Workshop	Elect\HEAD LIGHT	Elect\HEAD LIGHT	01/11/2024	551525	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS	31/10/2024	561997	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			UHF radio cutting out, not sure if hand piece or complete unit Inspect UHF for fault, found hand piece was faulty. Removed hand piece and installed new. Also replaced hand piece hook									
1048	Myrtleford - Workshop	DrCabElect\RADIO	DrCabElect\RADIO	22/10/2024	557248	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\BS	VehService\BS	14/10/2024	553145	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			CAMERA ON WINDOW NEEDS REMOUNTING Cleaned surface area for guardian camera to mount. Fix									
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DrCabElect\INST/GAUGE	14/10/2024	540632	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Body\MIRRORS	Body\MIRRORS	14/10/2024	540632	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			USB PORT KEEPS LOSING POWER Ordered new USB port to suit. Part arrived. Fitted new USB port to truck, also repaired broken wire.									
1048	Myrtleford - Workshop	DrCabElect\ELECT P&W	cigarette lighter socket doesnt work for phone charging	14/10/2024	540632	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2	05/10/2024	549163	Completed	Mt Gambier	GTK	XV64RM	BEAUREPAIRES - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS	04/10/2024	540632	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			Check RH door seal On inspection found RH door seal stretched & worn. Removed									
1048	Myrtleford - Workshop	DriCabRep\DOOR LOCK	door seal leaking R/H side	24/09/2024	543560	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc	30/08/2024	528925	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	VehService\BS	VehService\BS	27/08/2024	510616	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			RE KIT HORTON FAN Removed fan and air line from horton. Removed belt and loosened mounting bolts, removed horton. Disassembled horton and carried out rekit as required. Reinstalled horton and refit all components. Tensioned mountings and									
1048	Myrtleford - Workshop	Engine\ENG FAN	Rebuild Horton. (Barry Maney P/O: L088345)	21/08/2024	525430	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			REPLACE AIR TANK DRAIN VALVE Inspect for air leaks, found air leaking from air tank									
1048	Myrtleford - Workshop	Chassis\AIR LEAK	Replace Air Tank Drain Cock. (Barry Maney P/O: L088345)	21/08/2024	525430	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			CTI AIR LEAK LHF DRIVE Found LH front drive air CTI had a loose fitting, tightened									
1048	Myrtleford - Workshop	CTI\CTI Drive	Check For Air Leak's. (Barry Maney P/O: L088345)	21/08/2024	525430	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			CHECK BELTS - FREQUENTLY SQUEELING Inspected both engine belts, all okay. Removed belts and checked pulleys, found tensioner had excessive movement.									
1048	Myrtleford - Workshop	Engine\BELTS/TENS	Check Belt's. (Barry Maney P/O: L088345)	21/08/2024	525430	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			DRIVER SIDE SEAT BOTTOMING OUT GOING OVER BUMPS Inspect seat for fault, found to have a snapped cable.									
1048	Myrtleford - Workshop	DriCabRep\SEAT	Driver's Seat Bottoming Out. (Barry Maney P/O: L088345)	21/08/2024	525430	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			ABS LIGHT ALWAYS ON THE DASH ABS Light Always On. (Barry Maney P/O: L088345) Connect laptop to inspect ABS fault. Found all codes were									
1048	Myrtleford - Workshop	Brakes\ABS	relating to trailers. Repair carried out on trailer.	21/08/2024	525430	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			ELECTRIC HORN N/W Inspect fuses and plugs, all okay. Found electric horn was									
1048	Myrtleford - Workshop	Elect\ELECT P&W	Check Electric Horn. (Barry Maney P/O: L088345)	21/08/2024	525430	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
			VehService\AS									
1048	Myrtleford - Workshop	VehService\AS	A Service	19/08/2024	520718	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4+5+6+7+8+9+10 DriCabRep\SEAT SEAT SHOCKER CABLE BROKEN Found seat cable was broken. Removed seat base, removed cable and fitted new one. Checked over, all okay, refitted	18/08/2024	517836	Completed	Mt Gambier	GTK	XV64RM	BEAUREPAIRES - 3		P/MOVER
1048	Myrtleford - Workshop	DriCabRep\SEAT	seat base	17/08/2024	531253	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4	17/08/2024	517836	Completed	Mt Gambier	GTK	XV64RM	BEAUREPAIRES - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10	17/08/2024	517836	Completed	Mt Gambier	GTK	XV64RM	BEAUREPAIRES - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8	17/08/2024	517836	Completed	Mt Gambier	GTK	XV64RM	BEAUREPAIRES - 3		P/MOVER
1048	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6	17/08/2024	517836	Completed	Mt Gambier	GTK	XV64RM	BEAUREPAIRES - 3		P/MOVER

1048	Myrtleford - Workshop	Brakes\AIR LEAK	STRUGGLING TO BUILD UP AIR - Driver reports that he pushes black button in but when goes to push yellow button in and take off the brakes wont release like it has not built up enough air. Inspected trailer for air leaks. Found multiple leaks. Removed & replaced push fits on both trailer park brake signal lines as required. Removed & replaced both ride height valves as they were leaking badly on dolly. Remove & replaced 1 x ride height valve on A trailer. Replaced u/s drain cock & other push fits on height valve. CHECK THE AIR SYSTEM FOR AIR LEAKS. PROBLEM IS LOSING AIR ON THE FIRST TRI & DOLLY. CHECK THE RIDE HEIGHT VALVE. NOT STICKING. Check for air leak possible booster Driver advised of air leak on B-trailer when brake on. Tried to replicate fault, unable to. Put truck over pit & attempted to replicate again. No leak present.		11/08/2024	517506	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Body\AIR BAG		eplace trailer plug Disassembled trailer plug. Cut wires from plug as they were soldered in. Stripped wires & re wired into plug. Reassembled plug. Disassembled socket from truck & wired in new socket & fit. Tested operation of lights, RH indicator not working. Removed socket to inspect & found a loose wire. Refit the wire and refit socket. Tested again. All lights working as they should.	31/07/2024	512197	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\ELECT P&W	Elect\ELECT P&W EnREPLACE FAULTY STARTER MOTOR Travel to GF yard to collect truyck, would not start. Return to BMG to collect jumper pack to jump start truck, no good. Had to hit starter motor to get truck going. Bring back to workshop and replaced starter motor. Disconnected batteries, cut cable ties and unplugged trigger wire. Remove positive and negative cables from starter. Removed stand off brackets from sump to gain access. Removed starter, change over trigger wire to new starter. Fit new starter motor and tightened bolts. Connect cables and fit stand off brackets. Refit battery cables, check operation, all okay.		31/07/2024	512197	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\START MOTR	Engine\ALT INSPECT RUBBER/PLASTIC BURNING SMELL Checked over truck to locate fault, checks starter motor, all okay. Got driver to go for a test drive and reinspect for smell. Tilted cab, found smell coming from pulley area, removed belts and found alternator bearing was worn and unserviceable. Disconnect batteries, removed alternator cables, removed alternator. Change over pulley to new alternator, installed new alternator and fit cables. Fit new belt and reconnect battery cables. Cleaned area and test drive, no further faults.		31/07/2024	512197	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ALT	Removed plastic covers around steering wheel. Removed lower cover on dash, remove and replaced stalk assembly. Refit all covers and checked operation, all ok		31/07/2024	507830	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ELECT P&W			20/07/2024	507830	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	VehService\AS		14/07/2024	501952	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\DIFF OIL	Diff Oil Change		14/07/2024	501952	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	A Service PO# L086387		08/07/2024	478273	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Steering\HOUSEKEEP	GREASE STEERING SHAFT Grease steering column as requested, checked uni's, all okay.		03/07/2024	495817	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\BATTERY	CHECK BATTERIES - HAS NEEDED TO BE JUMP STARTED THE LAST COUPLE DAYS Inspected & load tested batteries. Found all to have failed. Disconnect terminals, undo mounting bolts. Removed and replaced batteries. KW122810 PACCAR GENUINE BATTERY (K306-42 XP630)		03/07/2024	495817	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	AD BLUE BREATHER BLOCKED & TANK SUCKING IN On inspection found pick up to be completely blocked over requiring it to be drilled out. Once drilled out, flushed system and attempt doser override test. Found adblue was only dripping from injector. Flushed out the pump and air system as required & retry override test. No good. After blowing out all lines, found a small hole in suction line. Removed and repaired section, ordered new hose. Refit and carried out override test once more. Still no good. Forced air and water through system & reconnected. Ran doser override test again, found dirty adblue. Re flushed and tested. All working. Hose arrived, removed supply line and replaced with new. KWMAQ62-D0T-6 PTC UNION 6MM 1 8.36KWM50-1015-6DCS10310 HOSE - ADBLUE TANK TO DOSING		03/07/2024	495817	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DASH LIGHTS - removed dash panel, replaced blown globe, refit dash. PARTS $6.17 | LABOUR $155		23/06/2024	491913	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	AD BLUE TANK CRACKED - Removed ad blue tank and installed new tank as supplied. Filled with new ad blue and replaced ad blue magnet. PARTS $297.82 | LABOUR $403 | CONSUM $18 TOTAL $968 KMS 489263		23/06/2024	491913	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	B 1 Service P/O: L086815		22/06/2024	489263	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Wodonga - Workshop	Tyres\ROTATION	Tyres\ROTATION		22/06/2024	487000	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	B Service PO# L048283		21/06/2024	471532	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	INSPECT AD BLUE LEAK @ EXHAUST - Found dry ad blue above tank coming out of exhaust. Cleaned off ad blue, removed exhaust clamp. Push exhaust apart, cleaned surface of flange on both sides. Use hot water & wire brush to clean all surfaces. Installed new gasket & clamp. Tightened clamp & check operation, all okay. PARTS $91.94 | LABOUR $202.50 | CONSUM $10 AFTER HRS - AD BLUE LEAK Found to have crack in side of tank near bottom. Cleaned off crystalised ad blue around tank. Attempt to dry area & seal leak, no good. Dried area with air blower & taped up. Temp repair only. Tank needs to be replaced. CALL OUT FEE $100 | LABOUR $135		18/06/2024	485183	Completed	Mt Gambier	GTK	XV64RM	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK			14/06/2024	484581	Completed	Mt Gambier	GTK	XV64RM	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep	STEERING WHEEL TILT	Found steering strut ws U/S. Remove and replace strut, checked operation, all okay.	31/05/2024	478273	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	AD BLUE TANK HOLDING PRESSURE	Removed ad blue lines, removed plug & breather hose. Found breather hose was blocked. Flushed systen	31/05/2024	478273	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\CONSUMABLE	RHS HUB CAP MISSING	Supply & fit new hub cap	31/05/2024	478273	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection PO# L086439		30/05/2024	478273	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	GREASE STEERING COLUMN.		27/05/2024	460362	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	CTI\CTI Drive	Replace bent CTI mounting post located between drive guards. REPLACE DAMAGED CTI HOSE - On inspection, found mount pole had been bent upwards & stretched air cti lines. Removed hose from bracket, removed bracket & fitted new guard pole. Replaced bolt & tensioned. Fitted CTI mounting bracket, replaced CTI hose to rear wheel. Checked air leaks.		27/05/2024	460362	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ELECT P&W	FRIDGE COMPRESSOR SEIZED, ORDER REPLACEMENT - Old fridge has already been removed. removed mattress out, undid fridge cover & removed. Went to fit new fridge but it would not fit due to compressor. Moved to RH side where it would fit. Fitted in & did up RH mount, LH mount was missing, ordered new bracket. Wired fridge into power & tested operation, all okay. Secured fridge until new bracket arrived. Refit cover. Bolted cover down & fitted mattress back in. New brackets arrived. Pulled bed & cover off and fitted new bracket ensuring fridge was secure.		27/05/2024	460362	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Wodonga - Workshop	Tyres\TP1+2	Rotate steer tyres		21/05/2024	460362	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER

1048	Myrtleford - Workshop	DrCabElect\SCALES	NOTHING SHOWING ON SCALES - Inspect fuses, found scales fuse was blown. Checked wiring in battery box, checked all plugs behind scales, found water in B trailer plug and would not stay connected. Cleaned out both ends of plug & reconnected, all okay. Found a little bit of water in fuse holder in battery box, cleaned out. Installed new 30 amp fuse, all okay Truck later returned, lost scales again. Found fuse had blown again. Traced wiring loom for daytime running lights that provides power to scales, no faults in wiring. Traced into roof console and checked plugs, all okay. Inspect trailer wiring & airway plugs, all okay. Checked A trailer plug, all okay. Found two broken wires in chassis loom for sclaes. Cut, stripped & Truck returned as fuse fell out and scales turned off. Replaced fuse, scales working but A trailer screen was not working.	Inspect under trailer and found damaged power wire. Rewired power to A trailer screen, checked, all okay.	25/04/2024	460362	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WIPER BLADES.		21/04/2024	459963	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WIPER BLADES. Carry out A Service as per job card for T909 X15	REPLACE WIPER BLADES - Supply and fit new wiper blades.	21/04/2024	459963	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	PO# L085421		21/04/2024	459963	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		21/04/2024	459963	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	GREASE STEER COLUMN (CHATTERING)this was greased on the A service refer invoice 378759. GREASE STEER COLUMN (CHATTERING)		21/04/2024	459963	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\WIPERS	BM SUPPLY WASHER JET PART		17/04/2024	460362	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Albury - Workshop	Air Con\HEATER	*REPLACE HEATER FAN.	CHECK A/C OPERATION HEATER FAN N/W - Bring vehicle into workshop, removed panels on passenger side. Removed fuse panel and tested fan wiring, no faults. Tested fan and found to have internal fault. removed heater fan & replaced with new. Reinstalled all panels, tested A/C, no further faults. Supplied vents to driver.	04/04/2024	450665	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		29/03/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist **MINI B-SERVICE**		29/03/2024	449730	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	PO# L084986		29/03/2024	449730	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\AIR TANKS	AIR TANK DRAIN BUNG NEEDS REPLACING - Remove and replace air tank drain cable		29/03/2024	438312	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\DAY LIGHTS	DAYTIME RUNNING LIGHTS NW / MIRROR LIGHT NW - Remove and replace LH mirror light globes		29/03/2024	438312	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Steering\HOUSEKEEP	CHECK STEERING-PITMAN ARM LOOSE - Tensioned pinch bolts - all ok. Carry out A Service as per job card for T909 X15	BELLY BAR BOLTS LOOSE - Tightened belly bar bolts.	29/03/2024	438312	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	PO# L084434		03/03/2024	438312	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/03/2024	438312	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\DAY LIGHTS	DAY TIME RUNNING LIGHTS N/W - Inspect LH day time running light, cut into harness and test power flow. Found power coming through first diode but not passing through second diode.		03/03/2024	438312	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\TRL LIGHTS	Will need truck to return for repair on week day to locate new parts REPLACE LIGHT PLUG ON TRAILER. (WIRE LEAD TO SUIT SCALE POWER)		02/03/2024	438312	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Albury - Workshop	Unknown	GREASE STEERING COLUMN AND SUSPENSION.	STEERING COLUMN TILT N/W - Inspect steering column tilt operation, found not unlocking properly. Remove plastic covers inspect cable & found to be broken. Replaced cable, all okay.	22/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	Engine\HOT PIPE	REPLACE DISCHARGE LINES- Cut cable ties, remove clamps. Removed hose off air drier & compressor line. Arrange new hose to be made as per sample. Installed new hose. Tightened fittings & secured. Built up air, tested, okay.		22/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	Elect\ELECT P&W	REPAIR LIGHTS- Replaced blown globe in mirror.		22/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	CTI\CTI Drive	AIR CTI BEEPING - Check operation of air cti, turn on taps build up air, air cti components all working correctly. Found pressure protection valve was leaking. Removed valve & replaced with new, tested operation, all okay.		22/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	DrivLine\CLUTCH	"CLUTCH"- LOOSING CLUTCH BRAKE/ FREEPLAY FINE?	ADJUST CLUTCH - carried out clutch adjustment to spec.	22/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	DrCabElect\ELECT P&W	FRIDGE NOT WORKING. (LIGHT COMES ON BUT NOT GETTING COLD)	FRIDGE N/W - Removed fridge and take to trident for testing.	22/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	Brakes\ABS	ABS TRAILER LIGHT DASH LIGHT ON. Service As Per Attached Checklist	trailer plug issue	22/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\CS	PO# L084027		15/02/2024	429675	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/02/2024	429675	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\FITMENT	1-2		02/02/2024		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist **MINI B SERVICE**		21/01/2024	418958	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	PO# L083450		21/01/2024	418958	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	ONE FUEL TANK STRAP SLIDING DOWN ON BOTH TANKS.	FUEL TANK STRAPS - LH front and RH rear tank strap rubbers were falling down. Unbolt tank straps & remove rubbers, installed new. Refit straps, tensioned bolts.	21/01/2024	418958	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	STRAIGHTEN R/H FUEL TANK BRACKETS.		20/01/2024	493418	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Chassis\AIR LEAK	LOSING AIR SOMEWHERE CAUSING CTI LOW AIR WARNING BUZZER TO COME ON.		20/01/2024	493418	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\EBS FAULTS	TRAILER ABS DASH LIGHT ON.		20/01/2024	493418	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\SEAT	REPLACE LAMBS WOOL SEAT COVER - Removed old seat cover. Supply & installed new seat cover as requested. Carry out A Service as per job card for T909 X15		10/01/2024	413096	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	PO#L082928		17/12/2023	409429	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/12/2023	409429	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	AD BLUE TANK LEAKING - Inspect ad blue leak, found to be coming from pick up line. Removed filter & replaced with new. Cleaned out lines, cleaned surfaces from leak.		17/12/2023	409429	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\RADIO	REPLACE UHF MICROPHONE/HAND PIECE - Removed the centre dash panel to access the back of the UHF and unplug the hand piece. Removed the hand piece & replaced it with a new one. Tested operation of the hand piece. All working okay.		15/12/2023	405070	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		05/12/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Engine\BATTERY	AFTER HOURS BREAKDOWN - REPLACE BATTERIES Received call, drove to greenfreight & jump-started truck. Tested charging system, all okay. Disconnect terminals and removed all faulty batteries. Installed new & connected. Tested operation, all okay.		04/12/2023	402202	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		03/12/2023	402202	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	CTI\CTI Drive	CDI HAS LOST AIR TO SYSTEM EVEN WHEN TAPS ARE TURNED OFF. (LEAKING)	CTI COMING UP WITH NO AIR WHEN IGNITION IS TURNED OFF & BACK ON CHECK FOR LEAKS - checked,	03/12/2023	402202	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes\EBS FAULTS	TRAILER ABS DASH LIGHT ON.		03/12/2023	402202	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	"AFTER TREAT" LIGHT RANDOMLY COMING ON.	AFTER TREATMENT LIGHT COMES ON RANDOMLY - Connect laptop & check codes, found code for high system pressure. Removed ad blue lines from the dosing pump & from the tank. Removed the ad blue sender & flushed out the sender lines. Flushed out the lines to the pump & also completed a flush on the pump. Refit the sender and ad blue lines, tested system operation, all okay.	03/12/2023	402202	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	STRAIGHTEN R/H FUEL TANK BRACKETS. (BOTTOMED OUT IN RUTTS IN BUSH)	STRAIGHTEN RH FUEL TANK BRACKETS AFTER BOTTOMING OUT IN BUSH- Found J bracket was bent, not a repair to be completed on a Saturday. Truck to be rebooked with more time.	03/12/2023	402202	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/12/2023	402202	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	STEERING COLUMN WON'T TILT - On inspection found steer column wouldn't not tilt. Removed steering column surrounds, found cable was not connected to strut. Refit cable & test operation, all working. Refit steering column, surround.		17/11/2023	394954	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Engine\BATTERY	A/HRS BREAKDOWN - JUMP START Travel to Greenfreight, jack cab, connect jumper pack and jump started truck.		14/11/2023	392493	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\BALANCE	1-2 Carry out A Service as per job card for T909 X15		08/11/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	PO# L082056		05/11/2023	389341	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		05/11/2023	389341	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\ELECT P&W	REPAIR LIGHTS N/W - Found passenger side mirror light n/w. Removed cover & replaced blown globes refit cover, all okay. Found LH spot lights n/w. Traced to find plug was unserviceable. Cut off male end of plug & replaced with new. Tested, all okay.		05/11/2023	389341	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	1-2 Service As Per Attached Checklist (MINI B SERVICE)		03/11/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	PO# L081695		19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Steering	GREASE STEERING COLUMN. This job was done as part of the B service sheet service item. GREASE STEERING COLUMN.		19/10/2023	380410	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Albury - Workshop	Engine\BELTS/TENS	A/C BELT - replaced worn A/C Belt.		19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER

1048	Albury - Workshop	CTI\CTI Elect	WHEN TURN TRUCK OFF THEN START C.T.I BEEPS (SLOW LEAK)	AIR CTI LEAK - Inspect all air lines & modules with soapy water, no leaks. Check control panel in truck. Drained air and simulatedm no leaks. Try again with taps on & off, no leaks.	19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	Elect\INDICATORS	CHECK LIGHT PLUG. BLINKERS DON'T WORK.	TRAILER PLUG - Remove plug & found damaged wiring inside plug. Removed wiring, tidy up & fit into new plug.	19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	Body\FUEL TANK	ADBLUE TANK BREATHER MAY BE BLOCKED AGAIN.		19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT COMING ON AND OFF EACH DAY.	AFTER TREATMENT - connect laptop & check codes, carry out trouble shooting & flush sytem. Cleaned out ad blue breather. Filter on ad blue pump was blocked. Attempt to clean, no good. Repalced filter. Cleaned out Ad Blue breather, replaced cap. Carry out over ride test, codes changed inactive.	19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	Elect\DRV LIGHT	L/H DRIVING LIGHT HAS BAD CONNECTION AT LIGHT PLUG. (DROPS IN AND OUT)	LH DRIVING LIGHT - Inspect driving light on LH side, found plug was corroded. Disassembled and cleaned out terminals. Reassembled, test, all okay.	19/10/2023	380401	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	L/H WIPER ALSO DAMAGED.		18/10/2023	493418	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WINDSCREEN	HIT TREE. BOTH WINDSCREEN SECTION TO BE REPLACED.	BOTH WINDSCREENS SMASHED - Sublet repair to install new screens. Remove & replace wiper and blade from LH side of truck.Vacuum out excess glass from cab.	18/10/2023	493418	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Steering\HUBCAP	NEW HUB CAP ON STEER WHEEL RHS.		18/10/2023	493418	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	PACK GREASE IN STEERING COLUMN.		18/10/2023	493418	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	1+2		29/09/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Susp\SHOCK ABS	CHECK ALL SHOCKS ON "A" TRAILER.		28/09/2023	493418	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	PACK STEERING COLUMN WITH GREASE. Carry out A Service as per job card for T909 X15		28/09/2023	493418	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L081382		28/09/2023	493418	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		28/09/2023	493418	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect	MIRROR LIGHTS - Replaced blown globe in LH mirror.		06/09/2023	358486	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Steering\WHEEL SEAL	LEAKING WHEEL SEAL - RH front drive wheel seal leaking. Removed wheels, axle and hub. Removed seal and cleaned all surfaces. Installed new seal. Refit all components. Service As Per Attached Checklist		06/09/2023	358486	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L080775		05/09/2023	358486	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		05/09/2023	358486	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Wodonga - Workshop	DrivLine\GEARBOX	BREAKDOWN @ NELSON BORDER - LOST BOTTOM HALF OF G/BOX, ONLY 1ST AND 3RD Travel to breakdown at nelson, truck wont select bottom gears. Inspect gearbox shifter & housing, okay. Found loose rose joint, tighten up. Check gearshift cables all okay. Remove panel under gearstick & check roll pin, all okay. Lube cables & linkages, start truck, check operation. Selecting gears correctly.		22/08/2023	353046	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\CLEANSKIN	Cleanskin		16/08/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Unknown\INST/GAUGE	PARK BRAKE LIGHT ON DASH OUT.done on A servivice refer invoice 368116. PARK BRAKE LIGHT ON DASH OUT.		15/08/2023	350250	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	REPACK STEERIN G COLUMN WITH GREASE.done on A service refer invoice 368116. REPACK STEERIN G COLUMN WITH GREASE. Carry out A Service as per job card for T909 X15		15/08/2023	350250	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L080267		15/08/2023	350250	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE TANK KEEPS BLOCKING BREATHER (NOT OVER FILLING TANK) (WARRANTY)	CHECK AD BLUE BREATHER Removed ad bllue breather, flushed unit with hot water and replaced breather. Reassembled, okay.	15/08/2023	350250	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrivLine\CLUTCH	CLUTCH PEDAL GOING HARDER TO PUSH.	CLUTCH PEDAL HARD Inspect clutch, found to be out of adjustment. Adjusted to spec, all okay.	15/08/2023	350250	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/08/2023	350250	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		09/08/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		09/08/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		09/08/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		09/08/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		09/08/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Engine\GOV VALVE	NOT BUILDING UP AIR (GOVERNOR VALVE?)	COMPRESSOR HAS BEEN REPLACED.	26/07/2023	342829	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Steering	GREASE STEERING AND BALL JOINTS.		26/07/2023	342829	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service As Per Attached Checklist		26/07/2023	342829	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L079775		26/07/2023	342829	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\ST Weel	GREASE STEERING COLUMN.refer A service sheet done on 7/7/23. GREASE STEERING COLUMN.		08/07/2023		Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE BREATHER BLOCKED AGAIN.refer barry maney invoice 366467. ADBLUE BREATHER BLOCKED AGAIN.		08/07/2023		Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	WATER LEAK L/H SIDE (RUNS DOWN L/H SIDE ROOF PILLAR.done while 1048 was having it A service refer invoice 366467. WATER LEAK L/H SIDE (RUNS Carry out A Service as per job card for T909 X15		08/07/2023		Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L079438		06/07/2023	331681	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Steering	GREASE STEERING AND BALL JOINTS.		06/07/2023	331681	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	LHS DIFF LOCK BUTTON DOESN'T LIGHT UP WHEN ON.		06/07/2023	331681	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect\DAY LIGHTS	FIX DAY LIGHT LHS.		06/07/2023	331681	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		06/07/2023	331681	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	Rotation		29/06/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP07	Tyre Position 7 Service As Per Attached Checklist		28/06/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L078956		15/06/2023	319376	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/06/2023	319376	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\BALANCE	1-2		07/06/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Steering	GREASE ALL STEERING AND SUSPENSION JOINTS. Done on A service refer invoce 364837. GREASE ALL STEERING AND SUSPENSION JOINTS.		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	FUEL TANK STRAP RUBBER SLID DOWN ON BOTH SIDES.done refer invoice 364837. FUEL TANK STRAP RUBBER SLID DOWN ON BOTH SIDES. BUGGER ALL FREE PLAY IN CLUTCH PEDAL.		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\CLUTCH	Adjust clutch on A service refer invoice364837. BUGGER ALL FREE PLAY IN CLUTCH PEDAL. Carry out A Service as per job card for T909 X15		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L078687		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE TANK HOLDING PRESSURE.		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Steering\STEER UNI	PACK GREACE IN STEERING COLUMN.		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Chassis\FIFTH WHEE	TRUCK TURNTABLE STILL A BIT OF SLOP IN IT.		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Steering\TIE ROD	CHECK BALL JOINTS IN FRONT END.		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Chassis\FIFTH WHEE	BIT OF SLOP IN TURNTABLE (BUSHES)		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/06/2023	310453	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	Rotation		25/05/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	RECORD CHECK RESULTS. B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.		16/05/2023		Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L078349 Carry out A Service as per job card for T909 X15		16/05/2023		Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L077874		21/04/2023	289455	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\ELECT P&W	REPLACED WIPER & INDICATOR STALK.		21/04/2023	289455	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Broken mudguard pole & bracket		21/04/2023	289455	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\MUDGUARDS	Straighten out pole. Make up new bracket to suit. Cut and insert holes as required. Fit new bolts, ok		20/04/2023	320662	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	DrCabElect\ELECT P&W	NO COMMANDS ON STEERING WHEEL WORKING.		18/04/2023	286122	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Albury - Workshop	DrCabElect\ELECT P&W	WATER ACCIDENTLY SPRAYED INTO CAB. HORN GOING OFF, ENGINE BRAKE ON.	Horn Stuck on Remove horn cover & outer control plug, horn stopped. Plug in different controls, fault remianed. Remove horn contacts, full of water. Cleaned all surfaces, refit & secure with tape. Remove clock spring & replace with new. Tested all ok. Test drive, no further problems	18/04/2023	286122	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	1&2		12/04/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10 Service As Per Attached Checklist		12/04/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L077524		29/03/2023	280803	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		29/03/2023	280803	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Steering	GREASE ALL STEERING JOINTS.		11/03/2023	270190	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	FRONT R/HSIDE FUEL TANK STRAP SLIDING DOWN.		11/03/2023	270190	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER

1048	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE TANK BREATHER BLOCKED AGAIN (VACUUM)		11/03/2023	270190	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	REPAIR OR REPLACE AIR BLOWER HOSE IN CABIN. Carry out A Service as per job card for T909 X15		11/03/2023	270190	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	PO# L077087		08/03/2023	270190	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		08/03/2023	270190	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2 Service As Per Attached Checklist **MINI B SERVICE**		28/02/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	PO# L076685		16/02/2023	259864	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		16/02/2023	259864	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15		29/01/2023	251458	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Wodonga - Workshop	DriCabRep\WINDSCREEN	CRACKED WINDSHEILD. L/HAND DAY RUNNING LIGHT OUT. (BUT WORKS WHEN PARKERS TURNED ON)		29/01/2023	251458	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Wodonga - Workshop	Elect\ELECT P&W	NO BIG DEAL AS I DRIVE WITH HEADLIGHTS ON.		29/01/2023	251458	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Wodonga - Workshop	DrivLine\CLUTCH	RUNNING OUT OF CLUTCH PEDAL FREE PLAY.		29/01/2023	251458	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/01/2023	251458	Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\BALANCE	Balance		26/01/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\FITMENT	pos 1 & 2		20/01/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service As Per Attached Checklist		07/01/2023	240678	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L076034 B 1 Service, Jack up steer axle check bearings and king pins.		07/01/2023	240678	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Wodonga - Workshop	VehService\B1 Svc	Replace cabin filter.		07/01/2023		Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	pos 1&2		06/01/2023		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP07	puncture repair		05/12/2022		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\PANELS	DRIVER'S SIDE FRONT GRILL OUT TRIM LOOSE. Carry out A Service as per job card for T909 X15	TIGHTENED GRILL TRIM.	01/12/2022	230858	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L075344		29/11/2022	230858	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		29/11/2022	230858	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L075082		12/11/2022	222715	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/11/2022	222715	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	steer tyres		02/11/2022		Completed	Mt Gambier	GTK	XV64RM	Albury Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE TANK BUILING UP PRESSURE.		26/10/2022	209767	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	CRUISE CONTROL LIGHT ON DASH FLICKERING.		26/10/2022	209767	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	COOLANT TEMP GAUGE LIGHT OUT. Carry out A Service as per job card for T909 X15		26/10/2022	209767	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L074650		20/10/2022	209567	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/10/2022	209567	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Cooling\COOL LEAKS	HEATER TAP ON ENG R/H SIDE LEAKING. LUCKILY TURNING TAP OFF STOPPED LEAK.		01/10/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Body	POGO STICK SPRING OR BOLT BROKEN.		01/10/2022	195127	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	ADBLUE TABK STILL PRESSURING.		01/10/2022	195127	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	R/H SPEEDO LIGHT OUT. Service As Per Attached Checklist		01/10/2022	195127	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\CS	Barry Maney PO# L074293		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrivLine\DIFF OIL	Change Diff Oils PULL FRONT TRAILER PLUG APART (MALE END ON LEAD)		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect\TRL LIGHTS	(HAS BAD CONNECTION IN IT ALSO WATER GETTING IN MESSING UP SCALES)		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	R/H SPEEDO GLOBE OUT AND ENG OIL GAUGE LIGHT.		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WIPER BLEADES.		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Engine\ADBLUE	ADBLUE TANK STILL HOLDING PRESSURE.		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	WASHER BOTTLE NEEDS REPLACING.		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		28/09/2022	200186	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrivLine	CHECK DRIVELINE FOR BACKLASH AND TURNTABLES PLEASE.		16/09/2022	195127	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service As Per Attached Checklist		16/09/2022	195127	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L074077		16/09/2022	195127	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres		13/09/2022		Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	ADBLUE TANK PRESSURISING AGAIN. Service As Per Attached Checklist		07/09/2022	179488	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L073631		24/08/2022	179488	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrivLine	CHECK DRIVELINE FOR BACKLASH AND TURNTABLES PLEASE.		24/08/2022	179488	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		24/08/2022	179488	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\CLEANSKIN	Replace Drive tyres x 8		19/08/2022		Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	POS 1&2		17/08/2022		Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrivLine\WHL HUB	PUIT HUB CAP TO R/H STEER PLEASE.		13/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DRIVER DOOR TRIM COMING OFF. (NO TECH SCREWS PLEASE)		13/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	L/HAND REAR FUEL TANK STRAP RUBBER SLIDING DOWN. Service As Per Attached Checklist		13/08/2022	149764	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L073359		06/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Cruise control dash light out		06/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\Pogo	Spring on pogo stick broken (cable tied to exhaust bracket)		06/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes\ABS	ESC LIGHT ON.		06/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect\BATTERY	CHECK BATTERIES. JUST STARTING AFTER A DAY OFF. (HAD ONE CALLOUT)	REPLACED BATTERIES.	06/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\FUEL TANK	REAR FUEL TANK STRAP MOVED ON L/H TANK.		06/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		06/08/2022	170133	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L072969		19/07/2022	160313	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	ESC light on		19/07/2022	160313	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect\BATTERY	Check batteries, just starting after a day off (Had one callout)		19/07/2022	160313	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Chassis\FUEL TANK	Rear fuel tank strap moved on LH tank		19/07/2022	160313	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		19/07/2022	160313	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	POS 1-10 B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.		02/07/2022	144513	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L072622		28/06/2022	149764	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Engine\BATTERY	After hours call out to jump start truck after long weekend, 1am in the morning. Minimum call out fee applies		15/06/2022	139599	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP10	puncture repair Carry out A Service as per job card for T909 X15		10/06/2022	144513	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L072325		09/06/2022	139597	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		09/06/2022	139597	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Wodonga - Workshop	VehService\BS	Barry Maney PO# L071970		25/05/2022	130805	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/05/2022	130805	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	tyre rotation pos 1 & 2 Carry out A Service as per job card for T909 X15		19/05/2022		Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Wodonga - Workshop	VehService\AS	Barry Maney PO# L071670		10/05/2022	120950	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Tune Engine.		10/05/2022	120950	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Wodonga - Workshop	Engine\ENG TUNE	Done by Cummins Mount Gambier.		29/04/2022	112675	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service as per Checklist		21/04/2022	110194	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L071363		21/04/2022	110194	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrivLine\R DIFF OIL	Replace rear diff oil		06/04/2022		Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrivLine\DIFF OIL	Replace front diff oil Carry out A Service as per job card for T909 X15		06/04/2022		Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L071106		06/04/2022	100207	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		06/04/2022	100207	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER

1048	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2 tyres		02/04/2022		Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\GPS	Telematics to do repairs Service As Per Attached Checklist		18/03/2022	493418	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L070754		18/03/2022	90022	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Body			18/03/2022	90022	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WIPER BLADES x 2.		18/03/2022	90022	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WINDOW REG	L/HAND WINDOW STILL GOING DOWN OCCASIONALLY WHEN WATER HITS R/H SIDE DOOR WHEN WASHING WINDOWS.		18/03/2022	90022	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		18/03/2022	90022	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\DAMAGE	Fit supplied bull bar parts, replace damaged grill & light		12/03/2022	86253	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect\DRV LIGHT	fit bullbar and relocate driving lights		06/03/2022		Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\BALANCE	POS 1 & 2 Carry out A Service as per job card for T909 X15		04/03/2022	80717	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L070461		03/03/2022	82442	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/03/2022	82442	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WIPERS	replace wiper blades x2		20/02/2022	73457	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DriCabRep\WINDOW REG	L/hand window still going down occassionally when water hits R/H side door when washing windows		20/02/2022	73457	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP1+2	fit 2 runouts Service As Per Attached Checklist ****** MINI B SERVICE *******		18/02/2022	71969	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	PO # L070233		18/02/2022	73457	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		18/02/2022	73457	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Wodonga - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15		18/02/2022	1	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/02/2022	1	Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Tyres\TP07	puncture repair Carry out A Service as per job card for T909 X15		28/01/2022	59229	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	PO# L069780		26/01/2022	59706	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		26/01/2022	59706	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	O/N L12859		07/01/2022	50165	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/01/2022	50165	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Elect\DRV LIGHT	Fit Supplied Driving Lights & Bracket Carry out A Service as per job card for T909 X15		23/12/2021	48487	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	ORDER # L12737		07/12/2021	39279	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		07/12/2021	39279	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Tyres\ROTATION	POS 1&2 Service As Per Attached Checklist ****** MINI B SERVICE *******		26/11/2021	34933	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	VehService\BS	O/N L12586		12/11/2021	30088	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		12/11/2021	30088	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\AS	O/N L12447		21/10/2021	20138	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	led light under door mirror light out	21/10/2021	20138	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	VehService\CS	O/ N L12277	engine brake to work with cruise	22/09/2021	9176	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Remove old unit. Run wires and cables for supplied IAP unit. Replaced cable as necessary. Mounted new unit under passenger seat and wire in. Re-assemble and test correct operation. Setup with MT Data support and run tests. Old unit was in top console and IAP unit didn't fit up		22/09/2021	9176	Completed	Mt Gambier	GTK	XV64RM	BARRY MANEY - 3	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\IAP	there so had to go under passenger seat.		18/08/2021	803	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up Jeremy from TCTC after dropping 1048 off.		02/07/2021		Completed	Mt Gambier	GTK	XV64RM	Wodonga Workshop	P/MOVER
1048	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up truck		30/06/2021	717	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\INST/GAUGE	fit park brake alarm		23/06/2021	500	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect\DRV LIGHT	fir driving lights		23/06/2021	500	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Elect\WORK LIGHT	fit work lights		23/06/2021	500	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	Body\TOOLBOX	supply CTI tools + box + CTI spares L11868		23/06/2021	500	Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER
1048	Myrtleford - Workshop	DrCabElect\GPS	Arkon - Install new MT Data Units	Fit supplied Mtdata tracking unit kit (with tablet & MDVR) *Fit Load scales and wire into Mtdata *Park brake alarm tracking unit serial #474002304 email workshopEmail@greenfreight.com.au for order number Travel to TCTC & return. Mount and wire up supplied Mtdata tracking unit with Tablet, phone & GPS antennas, MDVR with forward facing camera & Engine data module. Connect cabling, connect power, earth & ignition, remove and refit dash and trim panels to access and run wiring, solder connections, program tracking unit and MDVR and setup with Mtdata as necessary. Secure and insulate wiring assemble and test. Fit supplied airweigh gauge and connect to Mtdata tracking unit and connect airlines to truck airbag lines as necessary. Fit relays to factory relay holders to make factory park brake alarm work and test operation.	17/06/2021		Completed	Mt Gambier	GTK	XV64RM	Myrtleford Workshop	P/MOVER