EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
			Steering\TIE ROD									
1051	Mt Gambier - Mt Gambier	Steering\TIE ROD	CHECK BRAKES - DRIVER BELIEVES BRAKES ARE SHUDDERING		08/09/2026	854681	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			FIT NEW C/OVER CTI DISPLAY UNIT IN DASH									
1051	Myrtleford - Workshop	DrCabElect\ELECT P&W	(SUPPLIED BY TRT WD)	PO DELETED - TRT DO NOT HAVE GST - INVOICE PUT STRAIGHT INTO TRANSLOGIX.	04/09/2026	850368	Completed	Mt Gambier	STK	XV14VU	TRT AUSTRALIA -3	P/MOVER
				GREENFREIGHT A SERVICE								
				Carry out service as per Greenfreight checklist.								
				CARRY OUT GREENFREIGHT ABS CHECKLIST								
1051	Mt Gambier - Mt Gambier	VehService\AS	VehService\AS A Service	Unable to complete on Saturday due to time restrictions	01/09/2026	850368	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				CHECK LOW BRAKES								
				Found all drive brakes at 2mm on service. Jack axles. Remove								
				wheels and brake components. Install new brake shoes and fit								
				new brake drums. Refit and tension wheel nuts. Carry out for								
				both drive axles. Lower and adjust brakes as needed. Road								
				test and check over, all OK								
				LH rear drive s-cam slight movement. No parts available as								
				already after 12:30 on Saturday. Needs to be booked in								
1051	Mt Gambier - Mt Gambier	Brakes\BRAKE ADJ	Rear brakes low - recheck next service	during week to have jobs completed.	30/08/2026	850368	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Connect diagnostic laptop and check codes - fault for LHS								
				steer sensor open circuit. Test sensor, had low								
				resistance. Remove and inspect sensor, all looked OK. Trace								
				wiring to RH wheel arch. Cut cable ties and removed wrap,								
				inspect wiring for ABS and found some rubbed and broken								
				wires. Separate wiring, cut and rejoined wiring together.								
				Checked faults on laptop, faults changed to inactive.								
				Resecured all wiring and protect with tape. Drive truck								
1051	Mt Gambier - Mt Gambier	Brakes\ABS	Truck abs and trailer abs lights on al time	around yard and fault cleared successfully with wheel speed.	30/08/2026	850368	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	VehService\BS B Service		27/08/2026	847399	Completed	Mt Gambier	STK	XV14VU	HALLORAN DIESEL - 3	P/MOVER
				Pull truck into workshop and notice ABS light on. Connect								
				laptop - wheel speed sensor shorted fault. Remove plug and								
				test for resistance, had open circuit. Remove and replace								
				sensor as needed. Road test and operate brakes. Check over								
				temps on all trailers, A and dolly around 28-32 degrees and								
				B trailer about 15 degrees. Inspect when brakes applied,								
				notice B trailer brakes not applying. Remove suzi coil lines								
				to B trailer and apply brakes - had no air coming through								
				suzi coils lines. Check over and found service line tap had								
			BRAKES NOT PULLING UP - POSSIBLE ISSUE IN B TRAILER, CHECKS	been turned off. Turn tap on, reconnect lines and recheck								
1051	Mt Gambier - Mt Gambier	Brakes\BREAKDOWN	REAR AND HUBS WEREN'T HOT	brake operation, all OK	25/08/2026	847399	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				- No ABS warning lights on dash during inspection- Connected scan tool and checked for fault codes, no active or inactive ABS faults								
1051	Myrtleford - Workshop	Brakes\EBS FAULTS	ebs/abs issues	present- Note made to be rechecked during next service	15/08/2026	839217	Completed	Mt Gambier	STK	XV14VU	HALLORAN DIESEL - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\THROTTLE	accelerator issues no power on throttle		14/08/2026	842208	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\OIL LEAK	possible front crank seal leak		11/08/2026	842208	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CTI Drive	DrivLine\CTI Drive		05/08/2026	839217	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			VehService\AS A Service									
1051	Myrtleford - Workshop	VehService\AS	L134786		05/08/2026	829773	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		30/07/2026	835167	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
				Inspect CTI system, check air supply to CTI module and check CTI								
				system for air leaks no faults found. Switch CTI of on LHS drop CTI pressure								
				and re inflate to see if CTI fault was specific to a side no faults found. Check								
				power and earth supply to module check all connectors for corrosion no faults								
1051	Myrtleford - Workshop	DrivLine\CTI Drive	check CTI unit. not deflating to low setting of 32. Alarm is going off constantly. Found and repaired broke	found, suspected fault inside CTI module.	30/07/2026	835167	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Plug into truck and check codes - 'Cam or crank mechanical								
				system not responding' fault. Check over plugs and wiring								
				but unable to fault. Engine light not on at time of								
			ESC LIGHT AND TRUCK AND TRAILER ABS	inspection. Road test and attempt to fault but unsuccessful.								
1051	Myrtleford - Workshop	Brakes\ABS	TRAILER ABS ONLY BECOMES ACTIVE WHEN BRAKE PUSHED	Misc:DFT DIAGNOSTIC TOOL FEE	29/07/2026	835167	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				1049 A TRAILER SWAP WITH 1051 A TRAILER								
				1047 A TRAILER SWAP WITH 1051 DOLLY								
				1047 B TRAILER SWAP WITH 1051 B TRAILER								
				Travel around to GF yard. Disconnect and remove scales and								
1051	Myrtleford - Workshop	DrCabElect\SCALES	SWAP OVER SCALES AS INSTRUCTED	fit to new units as instructed.	22/07/2026	832553	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				S&F MIRROR COVER								
				Supply and fit new mirror cover.								
				DF1644325 COVER- MIRROR, MAIN, BLACK MAIN MIRROR 1 18.18								
1051	Myrtleford - Workshop	Body\MIRRORS	REPLACE MIRROR COVER	Sublet1S113763 PAINT MIRROR COVER	21/07/2026	832553	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Replace bateries and check starter opertion/condition								
				Remove and replace batteries as requested. Check starting								
				operation multiple times, unable to fault. Drop truck back								
				to yard								
1051	Myrtleford - Workshop	Elect\BATTERY	REPLACE ALL 4 BATTERIES	KW122810 PACCAR GENUINE BATTERY (K306-42 XP630)	21/07/2026	832553	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				LH FRONT DRIVE GUARD BRACKET LOOSE								
				Unable to tighten as threads on bolt no good. Oxy off nut,								
1051	Myrtleford - Workshop	Chassis\MUDGUARDS	RHS front drive guard bracket loose	replace nut and bolt and tighten guard.	15/07/2026	830493	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\ELECT P&W	Truck flat at yard possible needs new batteries and maybe a starter motor	Travel to GF yard and jump start truck, all OK	09/07/2026	824406	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Inspect and test drive to diagnose noise, driver instructed								
				noise had not returned since Penola. Inspect and found all								
				looks okay. Driver explained sounded like a rock in brakes.								
1051	Myrtleford - Workshop	DrivLine\DRIVES	INSPECT GRINDING / GROANING NOISE	Suspect possible rock in brakes but now fine.	30/06/2026	824406	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				AIR COMPRESSOR DONE AT 817111KMS								
1051	Myrtleford - Workshop	Engine\COMPRESSOR	REPLACE AIR COMPRESSOR WITH 30% WARRANTY COVERAGE	9/6/26	30/06/2026	824406	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
			TRUCK NOT BUILDING AIR TO 800PSI..POSSIBLE AIR COMPRESSOR.									
			REPLACE FRONT & REAR DISCHARGE HOSES OR HOT LINES AT COMPRESSOR & GEARBOX									
1051	Myrtleford - Workshop	Engine\AIR LEAK		FIT NEW AIR COMPRESSOR	30/06/2026	824406	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
			Insp\ANN INSP Annual insepction as per check sheet									
1051	Myrtleford - Workshop	Insp\ANN INSP	L134348		20/06/2026	820573	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			VehService\B1 Svc B 1 Service,									
			Jack up steer axle check bearings and king pins.									
			Replace cabin filter.									
1051	Myrtleford - Workshop	VehService\B1 Svc	L134347		20/06/2026	820573	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION 1-2	ROTATE STEERS	19/06/2026	821691	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
				STRAIGHTEN STEERING WHEEL								
				PRESSURE CHECK								
				WHEEL ALIGNMENT								
1051	Myrtleford - Workshop	Tyres\ALIGNMENT	Tyres\ALIGNMENT		19/06/2026	821691	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
				CLUNK IN LH FRONT OF TRUCK								
				(CHECK STEER SHOCKERS, CAB MOUNTS, STEER SPRING EYE BUSHES								
				AS PER WAYNE)								
				Inspect for clunk, found both side steer shocker bushes were								
				worn. Unbolt shockers and replaced top and bottom bushes as								
				required. Refit shocker, tensioned bolts.								
1051	Myrtleford - Workshop	Susp\SHOCK ABS	HEARING CLUNKING SOUND ON PASSENGER SIDE ON FRONT OF PMOVER	KW73D2002 BUSH-SHOCK ABSORBER	19/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Clutch brake slow to engage. Adjust clutch and free play -								
1051	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH	check, all OK	19/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Check scales operation found right weigh software needed								
				an update. Carry out updates, checked scales, all working								
1051	Myrtleford - Workshop	DrCabElect	BLUETOOTH SCALES STOPPED WORKING IN WET WEATHER	okay.	19/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				REPLACE BOTH FILTERS ON CIT CANISTER & REPAIR BROKEN WIRE IN CTI UNIT & TEST ALL WORKING CORRECTLY								
1051	Myrtleford - Workshop	DrivLine\CTI Drive	CTI SYSTEM NOT DEFLATING	DONE BY SCOTT & WD	16/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		15/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		15/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		15/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12	NOT ON PROFORMA BUT JC CONFIRMED THESE WERE CHANGED	15/06/2026	819746	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER

1051	Myrtleford - Workshop	Engine\FAULT CODE	AFTER H'RS BREAKDOWN CALL OUT FEE GEARBOX PRESSURE LIGHT FLASHED ON DASH	Meet driver at workshop with report of gearbox pressure light coming on when low on air. Suspect air leak, inspect and found bush in fitting leaking. Push in further and found light not on dash. Send driver, all okay	04/06/2026	814009	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\GEARBOX	DrivLine\GEARBOX pressure light came on CHECK TRANSMISSION GEARBOX PRESSURE LIGHT ON	Check trans level and top up 1L as required. Remove and inspect sensor, found sensor to fall apart and terminals corroded. Replace sensor as required, start truck and check no faults active, all okay KWFD20-2111-4PS1 SWITCH-PRESSURE 4PSI NC	04/06/2026	814009	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Hydraulics\HOSES	x1 cab jack hose weeping LH out of fitting crimp Check cab jack hose leak, will need hose replaced will need time to remove hose and have new one made up re-book for repair.	CAB JACK HOSES U/S Found cab jack hoses leaking out of crimps. Remove fittings and put caps on ends. Cut cable ties, remove hoses and arranged new hoses to be manufactured as required. Top up oil reservoir and check over for leaks, all okay Sublet15113664	03/06/2026	814009	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Steering\KING PIN	King pin movement - monitor check next service before greasing Check over king pin movement before greasing, found significant movement. Re-book for king pin replacement DONE 28/5/26 AT 813751 KMS	R & R KING PINS Jack and support axle. Remove wheels and hub assemblies. Clean bearings and hub. Remove foundation plate, tie rod ends, drag link, king pin caps, and cotter pins. Removed king pins. Fit new king pin bushes and rheemed to size then install seals. Fit steering knuckle and shimmed. Refit all components previously removed. Adjust wheel bearing to spec. Refit wheels and tension wheel nuts to spec. Fill with hub oil, road test truck - all OK	03/06/2026	814009	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\ELECT P&W	LHS MIRROR FACING OUTWARDS - SAYS CANT HEAR MOTOR WORKING	Check truck mirror operation, found mirror working as should and mirror button wasn't clicked onto left mirror. Give check over of mirror wiring just to be safe, all looked okay	29/05/2026	813671	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CTI Drive	CTI consistently beeping when going to lower psi settings DONE ON 21/5/26 AT B/M	Repair leaking fitting Inspect and found leaking fitting. Replace fitting, check over for leaks, all okay KWAQ69-D0TS-4X4 PTC ELBW 1/4 X 1/4 M 1 7.91 KWAQ62-D0T-6 PTC UNION 3/8 1 8.40 NGSCRAPH0SE scrap hose	26/05/2026	811550	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS A Service L133942		26/05/2026	811550	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\ENG TUNE	Engine\ENG TUNE		21/05/2026	808158	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\DIFF REPMN	Front diff weep - recheck DIFF WILL NEED A RESEAL NEXT C/ SERVICE DONE AT 800200KMS	FRONT DIFF INTERFACE SEAL LEAKING Clean off diff, remove axles and drain diff oil. Remove all diff bolts then clean off interface. Apply new sealant, refit all bolts, refill diff (replaced on service invoice) and refit axles. Check over for leaks, all okay KW2208S1215 GASKET 2 7.20 NGTOYOTA toyota black	07/05/2026	802216	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\SUSPENSION	R n R TORQUE ROD BUSHES	Remove torque rod, push out old bushes then fit new bushes. Refit torque rod, check over all okay KW839310 BUSHING	07/05/2026	802216	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\TRANS OIL	VehService\TRANS OIL		06/05/2026	800200	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL VehService\CS C Service		06/05/2026	800200	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\CS	L133605		06/05/2026	800200	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 7-8		29/04/2026	799405	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION POS 1-2		29/04/2026	799405	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\SCALES	Fit right weigh scale to truck	Make up bracket to suit right weigh scale. Remove deck plate, run air lines from air bag hoses. Mount gauge and connect wiring and air lines. Check operation all working correctly. Re fit deck plate. NG201-EBT-028 D/INPUT WEIGHT GAUGE 1 910.00 KWAQ64-D0T-4 PTC UNION TEE 1/4 2 22.98 KWPFT-4A-BLK-100 TUBE-BLACK,1/4' 30MT.ROLL 7 13.16 Sublet1S113215 Weight gauge bracket 132.83 <<< Total For Job 1 >>> 1728.97 Job# 2 09KWZZZ244 CHECK ACCESSORIES Tech(s): 8107 0.00 Wire scales on all trailers to be on separate circuit Spoke with John, will see how trailers go before this is completed	29/04/2026	799405	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	gps stopped working. gps disc has broken wires coming from it.	COMPLETED BY BROWNY 2/4 Checked with John, is performing better with a right weight	21/04/2026	794487	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\SCALES	REWIRE SCALES TO HAVE OWN POWER SUPPLY AS VOLTAGE TO BLUETOOTH KEEPS DROPPING OUT	scale in the truck, no need to complete this job.	21/04/2026	794487	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\TAIL SHAFT	Movement in front tail shaft spines between trans to front diff Check tail shaft movement, found to be within spec. Monitor throughout services.	Check tail shaft movement, all within spec unable to fault 14/4/26 at 792082kms	21/04/2026	794487	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRAKE ADJ	brakes extremely touchy	CHECK BRAKES - EXTREMLY TOUCHY Check and adjust brakes as part of service.	21/04/2026	794487	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH	Carried out clutch adjust as required, all OK Turn on all dash lights and found all working as should. Pull dash apart and inspect, clip fuel gauge in properly and replace oil pressure gauge holder as melted and not clipping in properly. Reassemble dash, all OK	21/04/2026	794487	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REPAIR DASH LIGHTS (TEMP GAUGE)	KW8000S0002 HOLDER-GLOBE INCLUDE GLOBE	21/04/2026	794487	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\WORK LIGHT	no passenger work light VehService\AS A Service	LH WORK LIGHT N/W Check LH work light, found working as should. Check over all other work lights, all working correctly	21/04/2026	794487	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	L133336		16/04/2026	792082	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK FULL PRESSURE CHECK		10/04/2026	789998	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION POS 1-2		10/04/2026	789998	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Brakes\EBS FAULTS	Check power and earth supply to A trailer all modules were clicking randomly VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.	Remove trailer plug at A trailer and inspect rear of plug - Found power wire not clamped in terminal and just sitting there causing erratic power issue. Re-crimp power wire in correctly and check, all OK. Check EBS faults all okay. Road test and check operation all working correctly.	02/04/2026	783105	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	L133094		01/04/2026	782136	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Air Con\AIR CON	aircon/heater fasn keeps cutting off DONE ON INVOICE 406674 24/3/26	Driver stated A/C stopped working then could smell burning. Inspect and check over all relevant fuses, all looked OK. Remove heater fan and check, found heater fan burnt out. Fit new hear fan and check operation, all working as should KWF31-TP-1000 FAN ASSEMBLY-BLOWER REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563	31/03/2026	783105	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\AIR CON	CHECK A/C NOT WORKING - SMELL BURNING	Driver stated A/C stopped working then could smell burning. Inspect and check over all relevant fuses, all looked OK. Remove heater fan and check, found heater fan burnt out. Fit new hear fan and check operation, all working as should KWF31-TP-1000 FAN ASSEMBLY-BLOWER	30/03/2026	782136	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\HEAD LIGHT	RH HEADLIGHT FLICKERING	Remove RH headlight cover and headlight. Fit new headlight as required. Refit cover and check light operation, all OK KWP54-1326-1-001 KW 12V/24V LED H-LIGHT HI/LO	23/03/2026	771168	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	Recommendations RH steer shocker bush to be replaced	RH steer shocker bush needs to be replaced Remove nut from stud, remove bottom of shocker and fit new bushes. Refit shocker and tighten all to spec, all OK KW73D2002 BUSH-SHOCK ABSORBER	18/03/2026	771168	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER

1051	Myrtleford - Workshop	DriCabRep\ST Weel	STEERING COLUMN STILL RATTLES (PARTS ORDERED)	STEERING COLUMN EXTENDS AND RETRACTS BY ITSELF Remove covers off column. Attempt to adjust cable but no good. Inspect cable and gas strut, found cable stretched and gas strut not locking correctly. Remove and replace cable and gas strut as required. Found steering column movement operating as should, all OK Found steering shaft movement upon service. Remove and replace steering shaft unis as required, all OK	18/03/2026	771168	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Steering\UNI JOINTS	R&R BOTTOM STEERING SHAFT UNI JOINT	KWS.103X UJ KIT 100 STEERING COLUMN EXTENDS AND RETRACTS BY ITSELF Remove covers off column. Attempt to adjust cable but no good. Inspect cable and gas strut, found cable stretched and gas strut not locking correctly. Remove and replace cable and gas strut as required. Found steering column movement operating as should, all OK RH steer shocker bush needs to be replaced Remove nut from stud, remove bottom of shocker and fit new bushes. Refit shocker and tighten all to spec, all OK	18/03/2026	771168	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\ST Weel	steering column doesnt hold have to keep pudhing back in		18/03/2026	771168	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	Drivers side steer shockie - replace VehService\AS A Service	KW73D2002 BUSH-SHOCK ABSORBER	18/03/2026	771168	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	L099370		14/03/2026	771168	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\SCALES	AIR LEAK AT SCALES - CAUSING INCORRECT WEIGHTS	Remove dash panel to access behind scales. Inspect and found fittings for transducers leaking. Remove and replace fittings on airlines as required. Build up air and check over for leaks, refit dash panel, all OK KWAQ68-D0T-4X4 PTC CNCTR 1/4 X 1/4 M 2 9.64 KWABF153 PIPE SCKT 1/4 X 1/4	27/02/2026	762925	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\ST Weel	steering column rattles COLUMN HAS RATTLES WHILST DRIVING & THE IN OUT FUNCTION DOES NOT HOLD - RECTIFY	Inspect steering column, found to have wear and knocking noise. Would recommend new steering column will send through a quote. Repairs Carried Out: Travel to site, inspect for burning plastic smell, no faults found, Tilt cab, engage A/C compressor and Horton fan, no faults Found. Remove both belts, check all pulleys no faults found. Wait for	26/02/2026	762925	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\IDLER PULL	Engine\IDLER PULL VehService\BS B Service	driving to got for a lap around the block re inspect for faults nothing found	25/02/2026	762925	Completed	Mt Gambier	STK	XV14VU	COOKY'S DIESEL MECHANIC REPAIRS - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	L099051 OIL LEVEL LOW. TAKE TO CUMMINS TO CHECK OUT		24/02/2026	762219	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\OIL LEAK	L099065		18/02/2026	758899	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\RERATE	Elect\RERATE		17/02/2026	758899	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DASH LIGHTS N/W DONE ON 5/2/26 first drive interface minor leak Inspect and found to have minor leak, check oil and found	Inspect where dash lights not working. Remove and replace x2 dash globes as required, all OK KW80005002 FRONT DIFF OIL LEAK - CHECK AND ADVISE Check front diff leak, minor will recheck next service	12/02/2026	753500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\DRIVES	still full - continue to monitor. 2/12/25	CHECKED AT 753629KMS 5/2/26 Check work light operation, found not working. Inspect and trace all wiring from work lights through harness to door, all wiring looked ok. Go over and check all connectors for wiring, all looked OK. Check for power at lights - no power found. Check over fuses and relay panel, test and found fuse for work lights blown. Remove and replace fuse as required, all OK. Check work light	12/02/2026	753500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS N/W DONE ON 5/2/26	function, all lights working as should. Fit new mirror cover as required.	12/02/2026	753500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\ABS	Trailer ABS light on DONE ON 5/2/26	Check trailer ABS light and found globe blown. Remove and replace globe as required. ABS light on, carry out diagnosis and repair on trailer RO.	12/02/2026	753500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	Microphone needs replacing. receiver cant hear anything	UHF MICROPHONE NEEDS REPLACING - RECEIVER CANT HEAR ANYTHING Take truck on drive and test UHF operation, 5km out the road was still able to hear clearly from BMG workshop, unable to fault. DONE ON 5/2/26	12/02/2026	753500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		11/02/2026	753500	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Steering\HOUSEKEEP	CHECK FOR VIBRATION IN FRONT END AT 90KM/H VehService\AS A Service	Put truck over shaker and check all components, no fault found all steering components and suspension ok. Road test and found vibration present between 80-90 km. Suspect issue with steer tyres. Driver un loaded, travel to GF yard disconnect truck and take to trident. R n R both steer tyres collect and road test all okay.	11/02/2026	753500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	L098869	Plug in and check codes, found 2 codes for invalid pressure and bad intelligent device. Check power, earth, and CAN, found to have no direct battery power. Isolate parts of loom and ran new wiring through single wire from battery to connector with fuse in between. When running new wire found CAN wiring damaged at connector point. Cut out damaged wiring and wire in 2 new pieces of wiring where required. Test operation and fund code still present for invalid pressure. Inspect and found adblue injector severely blocked. Attempt to unblock with water but unsuccessful. Replace adblue injector as required. Also found internals of doser blocked, flush water through multiple times until unblocked. Once all unblocked all codes went out, but found truck not exceeding 1,500 rpm with no present codes. Carry out general check over of components: damaged plugs, sensors or wiring, found one of the pins in the connector for the speed sensor damaged. Repair pin and test, all okay. Return truck to yard. CU5307918 6 HOLE INJECTOR DOSER 1 465.65 KWS4406BL INLINE STD ATS BLADE FUSE HOLDER WITH W/ 1 4.99 KWS2820BL FUSE-BLADE,20AMP,BLISTER(5 PK) 1 1.92	06/02/2026	753629	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\FAULT CODE	CHECK ENGINE - LOW ON POWER, CAN'T GET TO 100KMH UNLOADED	CU4935806 CONNECTOR,QCK DISCONNECT Travel to Greenfreight yard and started all trucks. Found 3 trucks were slow to start, leave those trucks running to charge. Return to yard and turn off all trucks, lock up and put keys away. Painted turntable locks yellow as requested.	21/01/2026	743474	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\BREAKDOWN	Jump start truck at yard	NG9315363018663 YELLOW PAINT Undo bolts and loosen tank straps. Removed broken bracket and v out cracks. Welded over cracks and painted bracket. Reinstalled with new rubber. Also replaced RH tank strap rubber. Resecured tank straps.	07/01/2026	740660	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\FUEL TANK	x1 LH and RH tank strap - replace next service LH FUEL TANK STRAP BRACKER CRACKED - CAN THIS BE WELDED ???	KWK89-1004-1260 LINING-TANK STRAP REPAIR DASH LIGHTS N/W	05/01/2026	738032	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	x1 dash light not working - engine oil temp light	Inspect dash lights, all working as required. Undo bolts and loosen tank straps. Removed broken bracket and v out cracks. Welded over cracks and painted bracket. Reinstalled with new rubber. Also replaced RH tank strap rubber. Resecured tank straps.	05/01/2026	738032	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\FUEL TANK	x1 LH tank strap bracket has small crack	KWK89-1004-1260 LINING-TANK STRAP	05/01/2026	738032	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER

				EPAIR WORK LIGHTS - KEEPS BLOWING FUSES Inspected fuse, found to be okay. Fitted resettable fuse to locate fault. Connected wires for rear bar work lights and trailer work lights. Checked operation, fuse blown. Reset fuse and disconnected trailer plug. Found work light wiring							
			work lights not working to trailers keeps blowing fuse work lights on truck working but not to trailers	had been connected t reverse pin in trailer plug. Change over wiring and checked operation of lights, all okay, no							
1051	Myrtleford - Workshop	Elect\WORK LIGHT	when in reverse they work on trailers	further faults.	05/01/2026	738032	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH	Carried out clutch adjustment as required.	05/01/2026	738032	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.								
1051	Myrtleford - Workshop	VehService\B1 Svc	L098406		05/01/2026	740485	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Travel to GF yard and check brakes not releasing. Found red button pulled out. Build up air and try to release brakes - brakes working as should. Move truck and double check brake							
1051	Myrtleford - Workshop	Brakes\BREAKDOWN	CHECK BRAKES - Not releasing @ Greenfreight yard VehService\AS A Service	operation, all okay	17/12/2025	734249	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	L098066		09/12/2025	729506	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
				REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Remove LH dash panels, replace cab filter and spray							
			CHECK AIR CONDITIONING OPERATION - CAB SMELLS OF CIGARETTE	disinfectant spray in evaporator bx and cab intake. Refit							
1051	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	SMOKE	panels and run A/C for a while.	05/12/2025	729506	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Cooling\RADIATOR	CHECK COOLING SYSTEM - R&R RADIATOR CAP	Top up coolant and replace radiator cap as required, all okay.	05/12/2025	729506	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MOUNTS	ENGINE FAN SHROUD MISSING BOLT	Inspect where bolts missing, replace as required, all okay.	05/12/2025	729506	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
			pack grease in steering THIS WAS DONE ON WO202841 A SERVICE B/M								
1051	Myrtleford - Workshop	Steering\CONSUMABLE	2/12/25		05/12/2025	729506	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRK O/HAUL	Rear drive s-cam bush slight movement	Inspect LH middle brake, all within spec. 28/10/2025 729573KMS	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SUSPENSION	CHECK RUBBER BUSHES IN SHOCKERS STEER & DRIVES	Inspect shockers, bushes fine and do not need replacing.28/10/2025 729573KMS MIRROR HEAT N/W	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MIRRORS	mirror heat not working	Tested mirror heat, working as it should.28/10/2025 729572 KMS Work order 201919	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\OIL LEAK	Hose on right side of sump leaking	Tightened clamp and cleaned off. 31/10/2025 729572KMS Work order 201919	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	All drive shockie bushes worn or weaping	Inspect all drive shockers for wear or leaks, all okay. 28/10/2025 729572KMS Work order 201919	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\Torque Rod	Torques rods	Inspect torque rod bushes, all okay. 28/10/2025 729572KMS Work order 201919	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\TAIL SHAFT	Shaft out of trans movement	Inspect movement with dial indicator, movement 3', all okay. 31/10/2025 729572KMS Work order 201417	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRK O/HAUL	ML brake need to be replaced next service	Inspect LH middle brake, all within spec. 28/10/25 729572KMS work order 201417	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	Steer shockie bushes worn VehService\BS B Service	Inspect shockers, bushes fine and do not need replacing. 28/10/25 729572KMS	07/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	L097504		04/11/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Travel to GF yard, unplug starter motor and test for power, all ok. Refit starter motor and try to turn over, unsuccessful. Disconnect batteries, remove positive and negative stud on starter. Set up extensions and crack loose all starter bolts. Move wiring loom then remove starter motor. Swap over wiring on solenoid then fit new starter motor. Tighten all bolts then connect all wiring back up. Connect batteries and start truck, started first turn over,							
			TRUCK PULLED INTO GF WASH BAY AND NOW WONT START - CAN SMELL	all ok							
1051	Myrtleford - Workshop	Elect\START MOTR	BURNING	KW061-1004-004 STARTER - PACCAR DP60, KWA 11 TOOTH	29/10/2025	716347	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Inspect all brakes and check for air leaks. Checked over all brake adjustment, check air lines. Inspect for any kinks or evidence of previous kinked air lines. Check air lines lines and connections were secure. Liase with driver for information, said air pressure never dropped but							
			BRAKES LOCKED ON WHEN PULLING OUT OF MILL, TOOK A LONG TIME	couldn't release brakes. Driver mentioned drive wheels were							
			TO RELEASE.	still spinning. Advised driver, if faults again, remove EBS							
1051	Myrtleford - Workshop	Brakes\AIR LEAK	CHECK OVER ALL BRAKE SYSTEMS AND AIR LINES	cord and advise workshop in attempt to diagnose fault. TRUCK PULLED INTO GF WASH BAY AND NOW WONT START - CAN SMELL BURNING	28/10/2025	716347	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Travel to GF yard, unplug starter motor and test for power, all ok. Refit starter motor and try to turn over, unsuccessful. Disconnect batteries, remove positive and negative stud on starter. Set up extensions and crack loose all starter bolts. Move wiring loom then remove starter motor. Swap over wiring on solenoid then fit new starter motor. Tighten all bolts then connect all wiring back up. Connect batteries and start truck, started first turn over,							
1051	Myrtleford - Workshop	Engine\START MOTR	Engine\START MOTR	all ok	28/10/2025	734249	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Plug into truck and check codes, found codes: 1673, 1671, 1695, 1669 and 1668 - all inactive. Check time stamps and found to all be very old codes. Clear system and light on							
1051	Myrtleford - Workshop	Engine\ADBLUE	PLUG IN AND CHECK CODES	dash went away, all ok. GREENFREIGHT A SERVICE Carry out service as per Greenfreight checklist. Drain and refit 1st diff as was very dirty. Oil changed not	24/10/2025	714199	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
			VehService\AS A Service								
1051	Myrtleford - Workshop	VehService\AS	L097262	long again, got sample and cleaned filter.	09/10/2025	710061	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\DAMAGE	Elect\DAMAGE	Find & repair broken wire. breakdown at Heywood. Auto elect placed a temp solution until broken wore can be found and fixed. R&R BALL RACE	07/10/2025	694064	Completed	Mt Gambier STK	XV14VU	BROWNYS MOBILE AUTO ELECT - 3	P/MOVER
				Remove turn table, ball race and base plate. Drill holes on top and bottom on new ball race. Fit ball race to base plate. Fit turn table to ball race, tighten all bolts and bolts using nylock nuts. Run grease lines and grease, all ok also delivered truck to tridents to have wheel alignment							
1051	Myrtleford - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEE	carried out as originally booked. No saturday labour rates Test each trailer and found short in truck from bulkhead to plug at pogo stick. Driver needed to go. Will need to be rebooked.	07/10/2025	694064	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS N/W	KWS2825BL FUSE-BLADE AF25,(PACK OF 5)	30/09/2025	694064	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.								
1051	Myrtleford - Workshop	VehService\B1 Svc	L097045		24/09/2025	694064	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
				REPLACE WINDOW GUARD & DOOR STRIKER Remove broken weather shield and replace with new. Remove door striker and replace with new KWR56-1164 STRIKER-POST B-CAB 1 Internal							
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	drivers side door stop latch broken	KWKW1001DR WIND DEFLECTOR-DAYLITE DOOR RH REPLACE WINDOW GUARD & DOOR STRIKER Remove broken weather shield and replace with new. Remove door striker and replace with new KWR56-1164 STRIKER-POST B-CAB 1 Internal	23/09/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	drivers side window guard broken	KWKW1001DR WIND DEFLECTOR-DAYLITE DOOR RH	23/09/2025	719571	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER

				Pry off driveshaft, undo and remove yoke then remove seal. Remove adjuster nut and unbolt front housing plate. Clean off fork and front housing plate, replace thrust washer and put power divider back in. Seal front housing plate and reinstall adjusting nut. Install new seal and reinstall yoke and nut. Reinstall drive shaft. Adjust play in adjuster, tension uni cap bolts, all ok								
			REPLACE WORN THRUST WASHER IN FRONT DIFF	KW50O7417 BOLT 4 9.44KW131008K KIT-PINION OIL SEAL & NUT 1 160.46KW132440-B WASHER-THRUST, INPUT SHAFT DIF 1 46.02KWL0CS1531								
1051	Myrtleford - Workshop	DrivLine\DRV LN SER	DONE AT 701109 KMS	LOCTITE 515 FLEXIBLE MASTER GASKET SEALA	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Work order 201919								
1051	Myrtleford - Workshop	Susp\SWAYBAR	Front sway bar bushes wear- monitor	Inspect torque rod bushes, all okay.28/10/25 729572KMS	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				work order 201066								
1051	Myrtleford - Workshop	Engine\OIL LEAK	power steering cap leak	Inspect oil leak, only minor. Cleaned surfaces.28/10/25 729572KMS	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				nspect and found 3 blown dash globes. Remove and replace all globes as required, all ok								
			ENGINE OIL TEMP GAUGE LIGHT N/W	KW800005002 HOLDER-GLOBE INCLUDE GLOBE 2 14.66KW800005002 HOLDER-GLOBE INCLUDE GLOBE 1 7.33DF2138517 COVER- MIRROR,								
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	TURBO BOOST GAUGE LIGHT N/W	MAIN, UNPAINTED MAIN MIRR	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Inspect LH work light and found not working. Test and found blown 25a LH work light fuse. Replace fuse and found to blow straight away. Trace wiring and test, found a short to earth. Remove LH door trim to access and test wiring, found to be all ok. Found when removing dash plug not connected properly. Cut spare circuit away from circuit as not needed. Retest - fuse not blowing. Reassemble dash and refit door trim, all ok.								
1051	Myrtleford - Workshop	Body\LIGHTS	left load light not workng	KWS2825BL FUSE-BLADE AF25,(PACK OF 5) 1 1.92KWS2815BL FUSE-BLADE,15AMP,BLISTER(5 PK)	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\LIGHTS	RHS head lights flick on when you go from parkers to lights on	inspect system and test power, suspect diode passing power on start up.	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\AIR LEAK	REPAIR/ REPLACE COMPRESSOR HOT PIPE AS REQUIRED	Found air leak when testing at metal hot pipe. Remove p-clamps and metal pipe and found steel line rubbed through. Get new hose made up from GWB. Fit and modify mounts to suit. Fit p-clamps, all ok	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	clutch brake needs adjustment	Adjust clutch as required, all ok	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				FIT NEW BACKING PLATE WHERE MISSING ON RH SIDE								
1051	Myrtleford - Workshop	Brakes\BACK PLATE	Brakes\BACK PLATE	Ordered new backing plate. KW973956 DUST SHIELD	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				nspect and found 3 blown dash globes. Remove and replace all globes as required, all ok								
				KW800005002 HOLDER-GLOBE INCLUDE GLOBE 2 14.66KW800005002 HOLDER-GLOBE INCLUDE GLOBE 1 7.33DF2138517 COVER- MIRROR,								
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	engine oil temp gauge light not working	MAIN, UNPAINTED MAIN MIRR	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Work order 201919								
1051	Myrtleford - Workshop	Susp\Torque Rod	Front torque rod bushes - monitor	Inspect torque rod bushes, all okay. 28/10/25 729572KMS	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\WIPERS	RH wiper washer	Tested, all working. 28/10/25 729572 KMS	23/09/2025	719571	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.									
1051	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		19/09/2025	660680	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				INSPECT AND REPLACE BLOWN HEADLIGHT/LOW BEAM LIGHT AS REQUIRED								
				Inspect fuse and test power to plugs, all ok. Remove and								
1051	Myrtleford - Workshop	Elect\HEAD LIGHT	Elect\HEAD LIGHT	replace LH high/low beam light, check operation, all ok	10/09/2025	694064	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			DriCabRep\MOUNTS									
1051	Myrtleford - Workshop	DriCabRep\MOUNTS	NEED NEW HINGES FOR OVERHEAD CONSOLE	Remove and replace broken hinges as requested	05/09/2025	694064	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Check engine light on and de rated, no acceleration Travel to Kingston, plug in and check codes. Found code 1695 active. Found to be an intermittent fault through harness leaking to 5v supply sensors. Inspect wiring, all looked ok. Cut 5v supply at OEM harness and run new wiring to adblue as sensor level gauge was playing up. Test drive, all ok. Truck drove to robe and played up slightly, but then drove back to Mt Gambier and was fine. Truck when faulted when driver went to leave Plug into truck, found 5v sensor supply started to high source. Inspect SCR harness, test and inspect, all ok. inspect harness from gear box, over engine and under engine, all ok. Inspect under engine, all ok. Cut RHS cable ties, remove complete harness and inspect wiring. Found many wires broken and corroded, including 5v supply wire. Numerous wires black and green with corrosion. Repair wiring as required, refit SCR harness and secure. Test drive, all ok. Repaired door catch as roll								
			ENGINE CHECK LIGHT ON. TRUCK DERATING. BREAKDOWN REPIRING WIRING ISSUES.									
1051	Myrtleford - Workshop	Engine\ELECT P&W	REPAIR RUBBED WIRING IN MAIN ENGINE HARNESS WHERE P CLAMPS ARE LOCATED (WD)	p	04/09/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				R&R BATTERIES Remove batteries as found them to be flat. Load tested, found 3 to be no good at all. Fit 3 new batteries Put batteries on charge and load tested, all okay. Will								
1051	Myrtleford - Workshop	Engine\BATTERY	Engine\BATTERY	keep aside as spare set for GF	28/08/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				weigh scale plug n/w Remove scales plug and solder new wires for new plug. Put								
			Chassis\SCALES	silicon around wires to protect from water damage, tape up								
1051	Myrtleford - Workshop	Chassis\SCALES	BROKEN SCALE PLUG	and test operation, all ok	23/08/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			VehService\AS A Service	GREENFREIGHT A SERVICE								
1051	Myrtleford - Workshop	VehService\AS	L096369	Carry out service as per Greenfreight checklist.	20/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\WIPERS	Body\WIPERS RH WIPER WASHER N/W	RH WIPER WASHER N/W	20/08/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				TIDY UP WIRING								
			Elect\SUZI COIL	TIDY UP WIRING NEAR PLUGS GOING INTO A TRAILER								
			TIDY UP WIRING NEAR PLUGS GOING INTO THE TRAILER (SUZI COIL) BARE WIRES SHOWING NOT DOING	Removed old 7 core wiring, zip tied loom together and								
1051	Myrtleford - Workshop	Elect\SUZI COIL	ANYTHING	wrapped in coil wrap to prevent any further rubbing.	20/08/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BACK PLATE	Brakes\BACKING PLATE CRACKED	BACKING PLATE CRACKED	20/08/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				REPLACE REAR ENGINE MOUNTS Cut cable ties and undo p clamps to gain access to engine mounts. Undo bolts, jacked up engine and removed bolts and bushes. Cleaned mounting surface and installed new rear engine mounts. Tightened bolts to spec. Lowered engine.								
1051	Myrtleford - Workshop	Engine\MOUNTS	Engine\MOUNTS CRACKED ENGINE MOUNTS	KWK066-421 BUSHING SNUBBER BAR 2 417.80KWD13-1001-4 BUSHING-REAR ENGINE BARRY 2 646.26	20/08/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine	DrivLine	FRONT DRIVE INPUT SHAFT LEAKING	20/08/2025	689500	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				GF B SERVICE Carry out service as per checklist Disconnect truck and trailer. Check over turntable and king pin. Greased all components, found turn table to need								
1051	Myrtleford - Workshop	VehService\BS	VehService\BS B Service	replacing	17/08/2025	680529	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 21-22		15/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Body\MIRRORS	fit ne l/h mirror cover	Installed new LH mirror covered as required	14/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Steering\UNI JOINTS	steering column needs greasing (rattles)	Inspect steering column, greased, all ok	14/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	clutch needs adjusting	Carried out clutch adjust as required	14/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Inspect and found diff leaking from hose and pump housing. Check diff level, seemed to be all ok. Will recheck next								
1051	Myrtleford - Workshop	DrivLine\OIL LEAK	RECHECK DIFF INPUT SHAFT LEAKING	service	14/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Inspect filler pipe leak at sump, tighten all clamps and								
1051	Myrtleford - Workshop	Engine\OIL LEAK	Filler pipe leaking sump	fittings, all ok	14/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Remove and replace 3 tank strap rubbers as they were								
1051	Myrtleford - Workshop	Chassis\FUEL TANK	fuel tank strap rubber sliding down	sliding down	14/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				STEER SHOCKER BUSH WORN								
				Loosen shocker bolts and remove bushes. Install new bushes								
1051	Myrtleford - Workshop	DriCabRep\ST Weel	STEER SHOCKER BUSH WORN	and tighten nut to spec, all ok	14/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER

1051	Myrtleford - Workshop	Tyres\ALIGNMENT	Tyres\ALIGNMENT		06/08/2025	679343	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Chassis\MUDGUARDS	TIGHTEN LOOSE GUARD POLE	Inspect and found guard pole loose. Removed plastic cap, hold back of bolt to tighten, refit cap, all ok	05/08/2025	683928	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		29/07/2025	679343	Completed	Mt Gambier	STK	XV14VU	BORDER BANDAG PTY LTD -3	P/MOVER
1051	Myrtleford - Workshop	Brakes\EBS FAULTS	Test EBS	Tested EBS. Turned ignition on and all warning lights illuminated including ESC. Started truck and all light turned off. As they should Turned on off road switch and ESC and ABS warning lights flashed to indicated they were turned off. As they should turned off off road switch and lights turned off. As they should.	24/07/2025	679343	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Elect\BREAKDOWN	Elect\BREAKDOWN	REPAIRS ✓ Repairs Carried Out: Travel to site, inspect starting issue found engine would crank over but wouldn't fire. Found engine lights not illuminated and electronic fuel pump not running. Suspect ECU not powering up tried to connect scan tool. Had no luck connecting to ECU. Check fuses in battery box all good check all fuses in fuse panel all good remove panel in driver side kick panel check ignition fuse all good. Disconnect OEM connector off of ECU check power and earth supplies to ECU all good. Check ignition power to ECU all good. Re connect OEM connector. Disconnect batteries load test all batteries all good re connect batteries. Suspected a fault with the ECU get a auto electrician to come and complete further trouble shooting. Auto electrician found a broke wire and did a patch up to get truck home re fit all remove covers travel return.	23/07/2025	676815	Completed	Mt Gambier	STK	XV14VU	COOKY'S DIESEL MECHANIC REPAIRS - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	DrCabElect\RADIO	LH UHF ANTENNA NEEDS NEW TIP Replace aerial tip	17/07/2025	673915	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SUSPENSION	Susp\SUSPENSION	DRIVE SHOCKER BUSHES WORN Remove bolts, bush and washer. Replace with new bush and washer, tighten nut all ok	17/07/2025	673915	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	DrCabElect\RADIO	CHECK POWER TO TABLET CRADDLE - NOT CHARGING, NEEDS CORD Checked holder and charging element then gave a good clean over. Charger working all ok. Monitored all day, all ok	17/07/2025	673915	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	Susp\SHOCK ABS	DRIVE SHOCKER BUSHES WORN Remove bolts, bush and washer. Replace with new bush and washer, tighten nut all ok	10/07/2025	671505	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	MIRROR HEAT LIGHT ON DASH	MIRROR HEAT LIGHT ON DASH N/W Inspect and found mirror heat not working. Inspect globe found it to be blown. Removed dash and replaced globe. Found fuel tank light to also be out due to a blown globes replaced.	10/07/2025	671505	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	OIL PRESSURE LIGHT WARNING CAME ON WHEN WET	OIL PRESSURE WARNING CAME UP WHEN WET Remove and replace oil pressure sender unit	10/07/2025	671505	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\BATTERY	LOAD TEST BATTERIES. JUST STARTING ??	LOAD TEST & CHECK BATTERIES Check and clean battery terminals and topped cell water, Check battery health, 1 battery failed test, remove and replaced battery with workshop stock.	10/07/2025	671505	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	tablet cradle not charging. check wiring	CHECK POWER TO TABLET CRADDLE - NOT CHARGING, NEEDS CORD Checked holder and charging element then gave a good clean over. Charger working all ok. Monitored all day, all ok	10/07/2025	671505	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	L/H UHF ANTENNA NEEDS A TIP	LH UHF ANTENNA NEEDS NEW TIP Replace aerial tip	10/07/2025	671505	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		09/07/2025	671505	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DrCabElect\INST/GAUGE	AFTERTREATMENT LIGHT N/W Removed dash panel and replaced blown globe for after treatment light.	27/06/2025	660680	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MIRRORS	Body\MIRRORS	REPLACE SPOTTER MIRROR ON LHS glass was missing from spotter mirror. Removed spotter mirror and replaced with new	27/06/2025	660680	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WIPER BLADES	REPLACE WIPER BLADES Work order 197999 Remove and replace wiper blades. Also supplied extra parts to driver as requested	27/06/2025	660680	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\FUEL TANK	STRAIGHTEN L/H FUEL TANK BRACKET	STRAIGHTEN LH FUEL TANK BRACKET FLATTEN OUT BOTTOM STEP ON RH FUEL TANK Work order 197999 Connect sling up to LH fuel tank J bracket and straightened out as best as possible. Ran out of time to flatten out bottom step.	27/06/2025	660680	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CTI Drive	CHECK CTI AIR DRAIN HOSE FOR BLOCKAGE DUE TO TROUBLE DROPPING DOWN AIR VERY SLOW	CHECK CTI AIR DRAIN HOSE FOR BLOCKAGE DUE TO TROUBLE DROPPING DOWN AIR VERY SLOW Work order 197999 Inspect air cti system for blockages. Removed exhaust silencer and replaced with new. Also found main filter was dirty, removed filter, blow out and refit.	27/06/2025	660680	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\BREAKDOWN	Engine\BREAKDOWN -DERATED WITH NO BOOST	Connect laptop & download No related faults present road test & monitor engine operation confirm boost is on the low side check wastegate travel & found wastegate leaking remove and replace wastegate set travel to spec road test & monitor. good boost & no issues.	27/06/2025	660546	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP		18/06/2025	660680	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\BREAKDOWN	LACK OF POWER FAULT - NOX SENSOR	LACK OF POWER FAULT - NOX SENSOR Check dash, found no lights active. Check for obvious boost leaks, unable to find any. Turbo also ok, not making unusual sounds. Checked for blocked air filter, all seemed ok. Checked wiring to speed sensors, found water dripping out and some rubbed wiring. Cut out rubbed wiring and joined back to plug. Connect computer, found NOX sensor short fault. Tested power and can signals at the plug, all had correct voltages. Remove and replace NOX sensor, test drove truck, all faults went inactive, but truck still lacking power. Test system for boost leaks, couldn't fault. Removed intake lines and check fins on turbo, all ok. Lynchy took truck back to yard	12/06/2025	660475	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SUSPENSION	RHS SUSPENSION DROPPED AGAIN AT LEAST 2 INCHES ride hight valve	TRUCK LEANING OVER TO LH SIDE Inspected suspension and found it to be sitting lower on the RH side. Adjusted ride height on drive suspension so it sat level. Adjusted right hand front drive mudguard as it was also sitting lower and rubbing on tyre. Recommend ride height valve gets changed when truck comes in for next service	28/05/2025	653325	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\ST Weel	steering wheel need to be re-centered now new suspentsion fitted	STEERING MOVING Steering column strut had failed and column was moving up and down. Remove steering column surround, removed strut and replaced with new. Checked all okay. Drove truck and straightened steering wheel, pulled steering wheel off and adjusted. Remove covers from column and inspect found had been rubbing, modify to prevent squeak	28/05/2025	653325	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\ST Weel	steering wheel need to be re-centered now new suspentsion fitted		28/05/2025	652668	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SUSPENSION	RHS SUSPENSION DROPPED AGAIN AT LEAST 2 INCHES ride hight valve	Removed hoses, removed old ride height valves and replaced with new ones. Connected hoses and test function, all ok	28/05/2025	652668	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		28/05/2025	653325	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\BATTERY	Load test batteries	Truck struggled to start in the morning, performed load test on batteries, all came back good	23/05/2025	652668	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER

1051	Myrtleford - Workshop	Engine\RADIATOR	INSPECT AND BLOW OUT RADIATOR -RUNNING HOT ON COOL DAYS	Blew out radiator with hose. Excessive amount of dust build up. Driver to monitor	23/05/2025	652668	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\ADBLUE	Engine\ADBLUE	DOSER PUMP AD BLUE TANK Inspect ad blue line, found to be rubbed on feed line. Removed lines and sourced new hose. Installed hose and secured with conduit and heat protection. Tested, no further leaks	23/05/2025	652668	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRAKE ADJ	primemover brakes not holding truck on hills whilst loading	Inspect and found brakes to be slightly out of adjustment. Adjusted brakes and check operation of slack adjusters. All okay.	23/05/2025	652668	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		20/05/2025	649213	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		20/05/2025	649213	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4		20/05/2025	649213	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		20/05/2025	649213	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SPRNG PACK	Recommend getting 2 new springs.	Jack chassis up and support with stands. Removed front bolts, rear shackle bolts and U bolts. Remove springs out of truck. Found both side bushes on hangers very worn. Removed hangers and pressed bushes out, then back in. Refit hangers, and fit in new springs. Fit in 4 new U bolts, and 8 new nuts. Did up rear shackles and front bolts. Do up U bolts and tension. Check over everything, road test, all ok.	24/04/2025	639095	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	VehService\BS	AD BLUE TANK STRAP	23/04/2025	639095	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\ADBLUE	Engine\ADBLUE	Found bottom of ad blue tank strap was perished. Removed strap and replaced with new. Secured tank strap and bracket	17/04/2025	639095	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\MOUNTS	DriCabRep\MOUNTS	CAB SQUEAK - CHECK CAB MOUNTS Greased cab supports on service.	17/04/2025	639095	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\SEAT	DRIVER SEAT -LOWER BACK LUMBER SUPPORT NOT BLOWING UP	DRIVERS SEAT LOWER BACK KUMBAR SUPPORT NOT BLOWING UP work order #196216 Remove seat base, Located air leak from rubbed hose in lumbar support. Fit a joiner onto rubbed hose and heat shrink. Refit seat base, tested operation, all okay.	17/04/2025	639095	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\DAMAGE	ALLOY REAR CHECKER PLATE NEEDS FASTENING AT FRONT BEHIND TURN TABLE	ALLOY REAR CHECKER PLATE NEEDS FASTENING AT FRONT BEHIND TURNTABLE work order # 196216 Fit 3 deck plate locks to rear alloy checker plate. Adjusted and tightened, all ok	17/04/2025	639095	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WIPER CONTROLS (FALLS APART) B/M FITTED NEW STALK CONTROL 10/4/25 637080KMS	1 09KW2Z2730 CHECK ALL LIGHTS Tech(s): 8098 150.00Indicator stalk fallen apart Removed steering column trim and removed indicator stalk. Remove kick panel and steering column bolt. Replaced stalk with new, reinstalled kick panel. Remounted steering column and fit trim. Tested operation, all okay. KW202-841 SWITCH-TURN INDICATOR	17/04/2025	639095	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	fit oil temp gauge sender if arrived	REPLACE OIL TEMP GAUGE SENDER work order 196216 Remove oil temp sensor from sump and replace with new sensor. Driver to test when loaded and engine oil is hot	17/04/2025	639095	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\AIR FITTIN	Brakes\AIR FITTIN	FITTINGS MISSED BEING CHARGED ON INVOICE # 392096 air supply	15/04/2025	637080	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\ELECT P&W	DriCabRep\ELECT P&W	Indicator stalk fallen apart Removed steering column trim and removed indicator stalk. Remove kick panel and steering column bolt. Replaced stalk with new, reinstalled kick panel. Remounted steering column and fit trim. Tested operation, all okay.	15/04/2025	637080	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Body\AIR LEAK	Body\AIR LEAK	SWAP AIRLINE FROM SECONDARY TANK TO PRIMARY - SEE ML Drained air from tank, removed air line and fitting from tank 1. Removed bung from second tank and fitted into tank 1, where air line was removed. Cut hose to size and installed into tank 2, secured with thread sealant. Started truck and built up air to check for leaks.	15/04/2025	637080	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		11/04/2025	634797	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		31/03/2025	630916	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\HCV	Susp\HCV	CHECK REAR SUSP - REPLACE RIDE HEIGHT ROSE JOINTS Removed and replaced 4 rose joints as they were worn.	31/03/2025	630916	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	DrivLine\CLUTCH	CARRY OUT CLUTCH ADJUST Carried out clutch adjust. Adjusted freeplay	31/03/2025	630916	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\OIL LEAK	Engine\OIL LEAK	ENGINE OIL LEAK - OIL FILLER PIPE LEAKING Found oil leak at hose from oil filter pipe. Replaced hose clamp, all okay.	31/03/2025	630916	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRAKE ADJ	TRUCK BRAKES NOT HOLDING WHILE LOADING. CHECK IF AUTO BRAKE AJUSTERS ARE ALL WORKING.	CHECK BRAKES AND SLACK ADJUSTERS - NOT HOLDING WHILE LOADING work order 195515 All brakes above wear limit, just need adjustment. Adjusted on service, tested operation, all ok.	31/03/2025	630916	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SUSPENSION	front of truck sagging to the right (springs)	FRONT OF TRUCK SAGGING TO THE RIGHT work order 195522 Found RH side leaf spring sagging and flat. Passenger side still had little bit of bend. Recommend getting 2 new springs.	31/03/2025	630916	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS	REPAIR BROKEN GAURD Removed bolts off guard, put guard back into position and resecured bolts.	24/03/2025	624780	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes\AIR TANKS	Brakes\AIR TANKS	Fit constant air supply to front of A trailer upgrade trailer plug wiring to 6mm Sourced new pressure protection valve and air hose. Run air line and cut to length. Fit conduit over hose and connected hose to air tank and trailer fitting. Secure new hose in position. Upgraded trailer plug wire. Cut old wires and move out of the way. Sourced new 6mm 7 core wire, cut to length. Wrap conduit around wire and connect wires into plug on truck and trailer side. Run under deck plate up through turntable along side trailer air supply. Cable tie in position. Deliver truck to yard and connect to trailer. Tested lights and air operation, all okay	14/03/2025	623518	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Chassis\SCALES	fit new 6mm wire to Suzie coil between truck and A trailer to increase amps to trailers for scales	Fit constant air supply to front of A trailer upgrade trailer plug wiring to 6mm Sourced new pressure protection valve and air hose. Run air line and cut to length. Fit conduit over hose and connected hose to air tank and trailer fitting. Secure new hose in position. Upgraded trailer plug wire. Cut old wires and move out of the way. Sourced new 6mm 7 core wire, cut to length. Wrap conduit around wire and connect wires into plug on truck and trailer side. Run under deck plate up through turntable along side trailer air supply. Cable tie in position. Deliver truck to yard and connect to trailer. Tested lights	04/03/2025	624780	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Chassis\SCALES	Chassis\SCALES		04/03/2025	624780	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Rotate Tyres Positions 1&2. (Mt Gambier Goodyear Autocare P/O: L092482)		28/02/2025	619673	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Body\LIGHTS	Nuber plate light cover missing	Supply and fit new number plate light cover	28/02/2025	619673	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\ABS	Trailer EBS fault	Plugged into all trailers to check for abs faults, no codes found. Plugged into truck, no faults. Monitor if light reoccurs.	28/02/2025	619673	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER

				MINI B SERVICE Jack up steer axle, check bearing & king pin. Replace cab filter Carried out Mini B Service as per Greenfreight checklist Customer Instructions: Greased and Adjusted Brakes Checked all Fluid Levels Completed paperwork & Cleaned area						
1051	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc	Replaced cabin air filter.	28/02/2025	619673	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRAKE ADJ	Brakes\BRAKE ADJ	CHECK AND ADJUST BRAKES Check over and adjusted drive brakes to spec	21/02/2025	614922	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	cruise control light on dash not working	CRUISE CONTROL LIGHT N/W work order 193800 Removed dash panel and replaced blown globe for cruise control. Refit dash	18/02/2025	611772	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	oil temp gauge on dash not working	OIL TEMP GAUGE ON DASH N/W Work order 193800 Inspect sensor at sump, found plug was smashed off. Removed remains of plug and installed new, plugged in and test operation. Still not working. May also required new sender at B service when oil is drained	18/02/2025	611772	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS		14/02/2025	611772	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\SUZI COIL	can not remove ABS plug to clean	TRAILER ABS LIGHT ON LOOSE CHECKER PLATE RUBBING AGAINST ABS LEAD ON BACK OF CAB Removed deck plate, remove and replaced locks, adjusted. Found EBS plug wires were rubbed and full of corrosion. Cut out rubbed and corroded section, extended loom and refitted plug. Connect laptop to truck and check codes, cleaned	30/01/2025	606442	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes\ABS	Brakes\ABS	TRAILER ABS LIGHT ON LOOSE CHECKER PLATE RUBBING AGAINST ABS LEAD ON BACK OF CAB Removed deck plate, remove and replaced locks, adjusted. Found EBS plug wires were rubbed and full of corrosion. Cut out rubbed and corroded section, extended loom and refitted plug. Connect laptop to truck and check codes, cleaned inactive faults. reinstalled deck plate.	23/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	red light out on bottom of drivers door	RED LIGHT OUT ON BOTTOM OF DRIVERS DOOR 191365 Removed door trim and removed faulty light. Found light had pulled wire in back of the housing. Installed new light and tidy up wiring, refit door trim, check operation, all okay	23/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	engine oil temp gauge not working	ENGINE OIL TEMP GAUGE N/W 191365 Removed dash, tested plug on gauge, all okay. Inspect sensor on sump, found plug was broken. Make new wire clip for plug and reinstalled, checked secure, all okay	23/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	drivers door slide comes out of cab	DRIVERS DOOR STRAP COMES OUT OF CAB 193165 Removed floor panels in way and slide the door catch through the door. Fitted catch to door and secured with split pin. Tested operation, all okay.	23/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	truck brake light out on dash	TRUCK BRAKE LIGHT OUT ON DASH 193165 Removed dash panel, replaced blown globe, refit dash.	23/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\TRANS OIL	Transmission Oil Change		21/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\CS	VehService\CS		21/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL		21/01/2025	600867	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		15/01/2025	598752	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\ENG FAN	Engine\ENG FAN	HORTON REKIT Removed inter cooler pipe & fan. Removed fan hub. Rebuild hub and per hortons rebuild procedure. Bench tested fan hub. All operating as it should. Re fit fan hub & fan, Adjusted fan shroud & fit blades to hub. Tested again, all ok.	15/01/2025	594952	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Steering\KING PIN	Steering\KING PIN	R & R KING PINS Jacked axle & removed wheels & drums. Removed brake linings & hub. Removed backing plate. When removing steering joints, LH side thread was stripped. Ordered new tie rod end. Removed caps & anchor bolts then hit out king pin. Cleaned stub axle in parts washer. Hit out old bushes & pressed in new. Cleaned RH side tie rod end thread & fit seals under bushes. Inspected the filament of king pin in bushes. One bush was good. Reamed one bush until king pin fit. Fit stub axle with bearing & jacked axle. Fit shims in top, fit caps & greased nipples. Fit anchor pin bolts, then back plate. Removed wheel seal and replaced with new. Fit hub & adjusted the wheel bearing to spec. Fit brake shoes, drum & wheels. Fit hub cap with new gasket. Top up hub oil. Fit new LH side bush to stub axle & reamed bushes. Fit grease seals, bearings and shims. Fit king pins & anchor pins in place. Re attach backing plate & fit hub with new seals. Fit brake assembly, drum & wheel. Adjust wheel bearing as required. Fit cap with new gasket & top up hub. Remove jack stands& tension wheel nuts. Road test, top up hub oil & refit covers. All ok.	18/12/2024	594952	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	DrivLine\CLUTCH	Carry out clutch adjust Removed clutch cover & checked gap. All look good. Adjust free play to spec. All good & selecting gears fine.	18/12/2024	594952	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\CCC	Replace air compressor	Replace Air compressor	06/12/2024	586526	Completed	Mt Gambier STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc		30/11/2024	589746	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	clutch needs adjusting running out of free play and clutch brake	Carried out clutch adjust to specification	23/11/2024	589746	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	engine oil gauge light cuts of alot	Remove dash cluster and replaced blown globe in dash	23/11/2024	589746	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MUDGUARDS	replace mud flap on r/h side between drives	Remove broken mud flap and replaced with new	23/11/2024	589746	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\MUDGUARDS	TIGHTEN LOOSE GUARD POLE	TIGHTEN LOOSE GUARD POLE Truck pulled up out the front, driver advised me both LH guard poles were loose. Removed end caps, sprayed INOX on threads and re tightened guard poles. Refitted end caps, all okay.	14/11/2024	586526	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\ST Weel	steering wheel leather pealing off	Pulled truck into workshop, removed horn/steering wheel cover. Disconnected horn wiring and clock spring wiring. Then undid and removed locking nut for steering wheel, once nut was removed, connected wheel puller and removed old steering wheel. Unboxed new one and fitted in the same position and tensioned the lock nut to spec. Checked for play and movement, all okay. Reconnected all wiring and fitted the horn cover. Tested to make sure all steering wheel buttons worked, and horn was audible. Wiped down wheel, all okay.	14/11/2024	586526	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WINDSCREEN	need new drv side windscreen badly sand blasted and few chips	REPLACE DRIVERS SIDE WINDSCREEN Arranged weston tinting and windscreens to replace the windscreen.	14/11/2024	586526	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Air Con\AIR CON	CHECK AIR CONDITIONING OPERATION STOPPED WORKING		14/11/2024	586526	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\AIR LEAK	Check over trucks and trailers for air leaks keeps losing air		14/11/2024	586526	Completed	Mt Gambier STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\ROTATION	Rotate Tyres On Rims Position's 1 & 2.. (Mount Gambier Goodyear Autocare P/O: L089979)		05/11/2024	580867	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\Punct	Puncture Repair Position 3. (Mount Gambier Goodyear Autocare P/O: L089980)	Repaired Puncture Position 3.	05/11/2024	580867	Completed	Mt Gambier STK	XV14VU	BEAUREPAIRES - 3	P/MOVER

1051	Myrtleford - Workshop	Engine\ENG TUNE	Engine\ENG TUNE		01/11/2024	580867	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS		01/11/2024	579137	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\AIR LEAK	still have air leak in truck somewhere. airbags drop onto guards after 1 hr	On inspection found hole in ram. Using epoxy, patched up the hole as required. Disconnected line & waited for it to set. Inspected truck for further leaks. None found, all ok.	01/11/2024	577289	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\DAMAGE	knock can be heard from cab, more so when empty sounds like bit like exhaust on cab?	Driver explained it was binder bar in locker box	01/11/2024	577289	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\ELECT P&W	bad connection in light plug when key off, sometimes no trailer lights until key on	Disassembled light plug & cleaned all components. Opened pins for better contact, zip tied wires cover in place & test for faults. All ok	01/11/2024	577289	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\ELECT P&W	L/H indicator flashes fast	WORK ORDER #190778 Inspected & tested LH side indicator. Found it to be faulty, removed & replaced as required. & re tested operation. All ok	01/11/2024	577289	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		17/10/2024	574335	Completed	Mt Gambier	STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\WHL HUB	Chassis\WHL HUB	SUPPLY WHEEL NUT COVER supply parts	16/10/2024	572603	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\BATTERY	CHECK BATTERIES. FLAT SAT AND FLAT TODAY. JUMP STARTED BOTH DAYS.	check batteries keep going flat Inspected and tested all batteries. Found all 4 to be faulty. Removed & replaced with new & refit terminals. PLUG IN AND CHECK CODES Connected PC and checked for codes. Found inactive codes for high nox. 1 x active code for high fuel pressure 1911. Inspected wiring from sensors to ECU, all ok. Checked fuel actuator resistance, all ok. Removed pressure sensor & fit new. Cleared codes and tested. All ok. Truck returned still faulting, remove and check both fuel filters for any issues. All okay, changed main fuel filter, road test and check pressure okay. Had aftertreatment code for speed sensor, check wiring at speed sensor and found rubbed. Repair rubbed wiring. Collect trailers and data	15/10/2024	569957	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\ADBLUE	ENGINE DE RATED 5 TIMES FROM TARPEENA TO MT GAMBIER. AFTER TREAT LIGHT CAME ON AFTER 1ST	monitor all okay.	15/10/2024	569957	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	VehService\BS		14/10/2024	569538	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		05/10/2024	569957	Completed	Mt Gambier	STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\FITMENT	Tyres\FITMENT 1+2		27/09/2024	567076	Completed	Mt Gambier	STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS		17/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\ELECT P&W	FIT NEW USB CHARGING PORT TO DASH	Removed dash and removed old charging port. Installed new USB charging port and secured in dash. Refit dash.	09/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\AIR LEAK	A LOUD SQUEALING NOISE CAN BE HEARD IN CAB. SOUNDS LIKE AN AIR VALVE ?	Inspect for squealing fault, found to be coming from trailer park brake button in cab. Remove and replaced park brake button and rechecked operation, all okay.	09/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Engine Oil temp guage not working	Found plug at sensor at come loose. Resecured plug to sensor with cable ties. May require new plug	09/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WINDOW REG	DRIVERS WINDOW STICKS WHEN GOING DOWN	Removed door card, inspect window and found wiring was getting caught under window. Reroute wiring so it doesn't interfere with window operation. Operated window, all okay. Reinstalled door card.	09/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Light out on axel oil RR RR guage	Removed dash panels and replaced blown globes as required	09/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	CLUTCH NEEDS ADJUSTMENT. LOOSING FREE PLAY AND CLUTCH BRAKE	Removed inspection plate and carried out clutch adjustment as required. Checked free play, all within spec. Inspect for air leaks, found bolts on base of air drier were oose. Tightened bolts. If leak continues, may require	09/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\AIR LEAK	Still have an air leak in truck somewhere	new gasket.	09/09/2024	560869	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS		09/09/2024	540389	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP07	Tyres\TP07		03/09/2024	555664	Completed	Mt Gambier	STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\BULLBAR	Chassis\BULLBAR REPAIR BENT BULLBAR TUBE Attached tube to bollard and attempted to pull the tube back into place. No good. Needs to be repaired by aluminium welder		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\AIR LEAK	Chassis\AIR LEAK AIR LEAKS AROUND DRIVE AREA Removed all deck plates & raised cab. Covered chassis & lines in soapy water and checked for leaks. Found small leak, tensioned the loose fittings &refit deck plates. Lowered cab		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DAMAGE	DriCabRep\DAMAGE REPAIR DRIVERS DOOR TRIM HAGING OFF Removed door card & replaced all clips necessary. Refastened the door card to the door & tested. All ok		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Steering\HOUSEKEEP	LH STEER MODULATOR MISSING SILENCER LH steer modulator was missing on inspection. Parts are on back order		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MOUNTS	Body\MOUNTS FRONT ENGINE MOUNTS On inspection found front engine mounts were worn. Supported the engine & removed all components connecting to the engine mount bracket. Removed the bracket & used air chisel to remove the bushes. Fir new mounting bolt to bracket & mounted. Tensioned all mounting bolts. Lowered the engine and tensioned engine mount bolts & re-connected all components to bracket. All ok		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MUDGUARDS	Body\MUDGUARDS Ordered new mudguards as requested. Unbolt and removed all mud guards. Measure and drilled holes in new guards. Mounted guards and secure in place. Installed mudflaps and loop kits. Tightened all bolts.		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	DrCabElect\RADIO REPLACE BOTTOM UHF MIC Removed dash panels, disconnected mic. Fit new mic & secured. Tested operation, all good. Refit dash panels in place		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\SKID PLATE	Chassis\SKID PLATE REPAIR DECKPLATE On inspection found 2 bolts at rear of deck plate were missing. Drilled & tapped 2 holes. Fit new bolts and secured. All ok.		30/08/2024	553212	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
				Replace rear light bar Removed rear mudguard bracket bolts & lights on both sides. Removed loading lights & number plate lights. Removed the number plate, wiring bracket bolts and removed rear bar. Fit new bar in place & attached all lights to bar. Re fit number plate and lights. Fit brackets & guard brackets. Connect lights & zip tie in place. Test lights, found one								
1051	Myrtleford - Workshop	Chassis\DAMAGE	Replace Damaged Rear Light Bar. (Barry Maney. P/O: L088338).	tail light not working. Removed light and replaced with new.	24/08/2024	551799	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc Serviced By Barry Maney @ 549.15S Km		22/08/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MUDGUARDS	rear bumper (light bar) is bent needs straightening		20/08/2024	550407	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER

1051	Myrtleford - Workshop	Elect\HEAD LIGHT	Trailer park light coming on with ignition but not with light switch by itself TRAILER PARK LIGHT COMING ON WITH IGNITION BUT NOT WITH LIGHT SWITCH BY ITSELF WO# 188067 Tested trailer lights, found lights to only operate with ignition and not the headlights. Lifted cab, removed battery box cover & found the relay was missing. Fit the relay and & re-tested. All ok Work lights not coming on with switch, only in reverse. Tested power at plug, all okay. Pulled all lights out of light bar and checked all plugs for power, all good. Removed deck plate and checked wiring, no faults. Pulled plug apart and change over pin 2 & 5, checked lights, all okay.		30/07/2024	534676	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WINDOW REG	DRIVERS WINDOW STICKS WHEN GOING UP DRIVERS WINDOW STICKS GOING UP WO# 188067 Inspected & tested window, pulled all the door trim off of the door. Checked all rails for any damage. Unable to fault. Used silicone spray in rails and reassembled door. Tested, window operating slightly faster.		30/07/2024	534676	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\RADIO	L/H Areal coax broken on areal base LH AERIAL COAX BROKEN ON AERIAL BASE WO# 188067 On inspection found coax cord coming out of the antenna. Disassembled antenna & re-soldered cord back to the antenna. Tested operation. All ok.		30/07/2024	534676	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	Steering\STEER UNI	GREASE STEERING COLUMN SHARFT GREASE STEERING COLUMN WO# 188067 Lifted cab, greased all steering components. All ok		30/07/2024	534676	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	TOP L/H AXLE OIL FRT RR GUAGE LIGHT OUT LH TOP AXLE OIL GAUGE LIGHT OUT WO# 188067 Removed dash panel to inspect. Found 3 blown dash light. Removed and replaced 3 x globes. Tested operation, all ok. Re fit dash & secured.		30/07/2024	534676	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\AIR LEAK	air leak somewhere near guards AIR LEAK NEAR GUARDS WO# 188067 Driver advised he could hear air leaks near guards. Sprayed all air components with soapy water. Found one in the binder strap fitting. Replaced fitting. Also found air leak at top RH side of air tank. Removed fittings and air line. Installed new air line and replaced fittings. Found multiple air leaks at air tanks removed fittings and re sealed. Re checked over could not locate anymore air leaks.		30/07/2024	534676	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		23/07/2024	534676	Completed	Mt Gambier	STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\WIPERS	wiper blades need replacing		20/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\WIPERS	windsceen washer need aligning DriCabRep\DOOR LOCK		20/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	INSIDE SKIN OF DRIVERS DOOR HANGING OFF	Done	15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\DOOR LOCK	passenger door not sealing at top of door	Done 15/7	15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\DOOR LOCK	Driver door not aligned correctly has trouble shutting door	Done 15/7	15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\Unknown	Squeaky rattle L/H side dash behind fuse box Fit white mud guards to drives REPLACE ALL DRIVE GUARDS TO WHITE GUARDS WO# 188067	Done 15/7	15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\MUDGUARDS	Did not complete		15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Body\RADIATOR	Latch for radiator inspection cap broken	Done 15/7	15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	mirror heat light on dash not working		15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Chassis\AIR LEAK	Air leak around drive axels		15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	bottom UHF needs new microphone		15/07/2024	548265	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRK RELINE	RELINE RH & LH STEER BRAKES & FIT 2 NEW BRAKE DRUMS CHECK BRAKES - DRIVER MENTIONED THAT BRAKES FEEL LIKE THE ARE GRINDING WHEN APPLIED (FRONT END) Removed both steer wheels & drums to inspect. Found both had uneven surfaces. RH showed signs of heat marks. Removed linings and replaced with new linings and drums. Re fit wheels & tensioned. Fit nut indicators in cab & adjusted brakes. All okay KWDB003TRP TRP BRAKE DRUM 16-1/2 X 6" 2 318.06KW2SS098125 BRAKE SHOE 6" HD DANA D2000F STEER AXLE		10/07/2024	530116	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	B Service		10/07/2024	534536	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection PO # L086424		30/06/2024	526283	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS P/O: L086805		19/06/2024	519987	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	VehService\AS		17/06/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	B 1 Service PO # L086421		17/06/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Air Con\HEATER	CHECK HEATERS INTERMITTANT OPERATION - Removed fuse panel & dash panels on passenger side. Connect A/C equipment & recovered gas from Removed air ducts & heater hoses. Remove mounting bolts for HVAC system & pulled back to access heater motor. Removed blender motor & replaced with new. Refit HVAC system, refit hoses with new o'rings. Charge with new A/C gas and tested operation, all okay. PARTS $267.91 | CONSUM $40 | LABOUR $810 A Service PO# L048278		14/06/2024	518136	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS		KM's	03/06/2024	502540	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CTCH PACK	replace clutch pack		01/06/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\BRAKE ADJ	A/HRS BREAKDOWN	Checked over for fault of no service brake. Found tap on suzi coil was closed, opened tap. Adjusted all brakes, all okay. Check operation of all brak	31/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION	KM's 510304 Tested heaters, could not fault while in workshop.	31/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Air Con\HEATER	HEATERS INTERMITTENT	KM's 509692	30/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DRIVERS DOOR LATCH MISSING A BOLT	Door catch missing a pin, remove panel under pedal, fit new & re fit panel all okay.	30/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH	Carried out clutch adjust to spec check operation all okay	30/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\ELECT P&W	SUBLET REPAIRER - LIGHTS N/W AT HEYWOOD Attended by Cookys Diesel Mechanic Repairs. check for power at trailer plug, no power. Check relay battery box, found relay bypassed. Check power, fit jump wire, lights working okay. Refit battery box & lower cab. SUBLET $221.38 check fuel not transferring from right to left tank	checked cross over pipe & taps for blockages - OK checked tank breather on right tank - OK	28/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	Body\FUEL TANK	KM's 1036558	removed foot plate on right tank to access breather - breather was blocked, cleaned and checked - OK	28/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	JF MECHANICALS - 3	P/MOVER
1051	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		24/05/2024	504434	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\ENG TUNE	Engine\ENG TUNE		23/05/2024	504434	Completed	Mt Gambier	STK	XV14VU	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1051	Myrtleford - Workshop	Body\MUDGUARDS	BROKEN MUDGUARD POLE - Removed mudguard and pole, installed new pole & bolt. Reinstalled mud guard.		23/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
1051	Myrtleford - Workshop	Air Con\HEATER	HECK HEATERS, CAN SMELL COOLANT IN CAB - Removed passenger panel, inspected cabin air air filter - was dirty. Replaced filter, turned on heaters and tested - no smell, all okay.		23/05/2024	502540	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER

			HRS BREAKDOWN - TRAILER LIGHTS N/W Met driver at workshop, inspected and found no power at truck trailer plug. Checked fuses & relays in cab, all ok. Put cab over & checked fuses, found fuse was blown, replaced & tested lights. Lights working okay, turned on ignition & fuse blew again. Checked and tested relay, no good. Bypassed											
1051	Myrtleford - Workshop	DriCabRep\ELECT P&W	relay with some terminals and wire. Retested multiple times - working fine.		23/05/2024	505179	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\Re-Tor	Tyres\Re-Tor		22/05/2024	489974	Completed	Mt Gambier	STK	XV14VU	BEAUREPAIRES - 3	P/MOVER
1051	Myrtleford - Workshop	Body\WHL HUB	SUPPLY 10 CHROME WHEEL NUT COVERS		10/05/2024	489974	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\Re-Tor	Re-Torque		01/05/2024	489974	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\FITMENT	1-2		30/04/2024	489974	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\OIL LEAK	REPLACE BROKEN GREASE NIPPLE ON DRAG LINK - Removed broken grease nipple & fitted new.		24/04/2024	489974	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	RH FRONT DRIVER SHOCKER LOOSE - Found shocker bushes were worn. Unbolt shocker & replaced bushes, resecured.		24/04/2024	489974	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\MOUNTS	BOTTOM RADIATOR MOUNT LOOSE - Tightened loose radiator mount bolts.		24/04/2024	489974	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\BS	PO# L085530		24/04/2024	489974	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		24/04/2024	489974	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			LH LOW BEAM - Tested power for LH low beam light, no good. Checked fuse, all okay. Checked relay, no power. Inspected wiring loom for faults, all okay. Needed further inspection, truck needed to go back to work. Soured power from RH side, run wire into LH light and tested, all okay. Refitted light									
1051	Myrtleford - Workshop	Elect\HEAD LIGHT	to truck, to return for completion, only temp repair.		12/04/2024	485257	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			ALTERNATOR NOT CHARGING VOLTAGE DROPPED TO 12 VOLTS Brought vehicle into workshop, load tested batteries, okay. Tested alternator, not charging. Removed									
1051	Myrtleford - Workshop	Engine\ALT2 DR	belt, disconnected batteries and removed & replaced alternator. Tested charge, all okay.		09/04/2024	482051	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			RH INDICATOR - Inspect indicator, found to be full of water. Lowered bull bar & lift cab. Remove retaining bolt, fit new									
1051	Myrtleford - Workshop	Elect\INDICATORS	indicator & tested, all okay. Lowered cab and lifted bull bar.		06/04/2024	481357	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	GAUGE LIGHT OUT - Removed dash cluster, replaced blown globe as required.		06/04/2024	481357	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			REPLACE RH DOOR HINGE - Removed drivers side foot well panels, disconnect door wiring loom. Unbolted door hinge to cabin, removed door. Placed door on stand, removed door panels & door handle /lock. Removed window & all hardware. Cut & hit out huck screws on door hinge, installed new hinge with all new huck screws. Refit window & hardware, reinstalled all components to door. Mounted door to cabin. Tensioned bolts, connect wiring loom. Test window operation, found to be hitting door. Removed door panel & adjusted window & tracks. Refit, all okayu. Take truck for a test drive, found slight wind									
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	noise. Altered door hinge. Cleaned top door edge, found to be hitting cab.		06/04/2024	481357	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\AIR CLNR	AIR CLEANER - Straightened air cleaner pipe as required.		06/04/2024	481357	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\CRUISE CON	CRUISE CAN CONTROL HIGH IDLE DROPS OUT WHEN LOADING AS SOON AS YOU PUT A GRAPPLE ON. SIN	CRUISE CONTROL HIGH IDLE DROPS OUT WHEN LOADING/UNLOADING - Removed kick panel and dash, locate hob switch behind triangle, tested all switches, all okay. Connect laptop to test clutch switch and brake switch. Found clutch switch was not releasing every time, adjusted switch. Monitored brake switch, found brake pedal not releasing and switch all okay. Cruise would not work as it thinks the brake is being applied. Lifted cab and inspect wiring for faults. Found numerous rubbed and broken wires. Cut out and rejoined all wires where required. Found brake switch wire broken under the sump. Repaired wire, tape and secure wiring loom as required. Inspect computer, showing brake as released. Refit all components, take truck for a test drive and data monitored, all working	28/03/2024	479494	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	CAN YOU PLEASE FIX DOOR SKIN R/H. DUST LEAKING IN BADLY.	DUST LEAKING IN DOOR - Found dust seal was worn, removed seal and replaced with new. Truck needs to be rebooked for door hinge replacement.	28/03/2024	479494	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			PROGRAM MAX SPEED 100 AND JAKES COME ON AT 103 - Connect cummins laptop,									
1051	Myrtleford - Workshop	Comp	programmed max speed to be 100 and jake brakes to come on at 103kms to prevent over speeds.		28/03/2024	479494	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Myrtleford - Workshop	VehService\AS	PO# L084859		21/03/2024	479494	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		21/03/2024	479494	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP07	Tyre Position 7		14/03/2024		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
			ADJUST CLUTCH - Got tools required, drove to Greenfreights yard & adjusted clutch brake & free play									
1051	Myrtleford - Workshop	DrivLine\CLUTCH	to spec, all okay. Drove back to work and cleaned up tools.		29/02/2024	471921	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			TRUCK HAS FLATE BATTERIES - Attended Greenfreight yard, jacked cap & connect jumper pack pack to truck. Jump started truck, check charge rate, refit covers and lowered cab. Leave truck									
1051	Myrtleford - Workshop	Engine\BATTERY	running & advised.		27/02/2024	470345	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			REPLACE LOAD CELLS - Disconnect truck and trailer. Unbolt and removed turntable, remove load									
1051	Myrtleford - Workshop	Chassis\SCALES	cells and installed new as supplied. Refit turntable, tensioned bolts. Reconnect to trailer.		24/02/2024	470333	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\FUEL TANK	Fuel Tank & System		24/02/2024	470333	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		24/02/2024	470333	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			Service As Per Attached Checklist **MINI B-SERVICE**									
1051	Myrtleford - Workshop	VehService\B1 Svc	PO# L084214		24/02/2024	470333	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			REPAIR SCALES ISSUE - Check scale operation, sitting steady but high weights. Inspect filters on both trailers, found B trailer filter was blocked. Remove & replaced filter. Found to have a leaking air bag. Unbolt and removed air bag, change over fittings and installed new air bag. Connect all air lines & replaced leaking air fitting. Load cement block onto trailer to test scales, all working okay. Requested further info on fault. Replaced transducer with spare & test drive truck to recreate faults, all okay. Change back to original transducer. Remove and fit new link cable from trabnsducer to slave module. Test again, slave module shorted out. Travel to Greenfreight yard & remove slave module from spare truck. Return to workshop & remove and replace module. Tested, no further faults. Re road test and									
1051	Myrtleford - Workshop	Chassis\SCALES	truck did not play up. Deliver truck back to yard. Channel 3 now operating correctly.		14/02/2024	463590	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\Torque Rod	REPLACE WORN SHOCKER BUSHES ON STEER - Remove and replace worn shocker bushes.		08/02/2024	460162	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
			LOW DRIVE BRAKE LH REAR - Remove air cti hoses, remove wheels. Remove brake drum & linings.									
1051	Myrtleford - Workshop	Brakes\BRK RELINE	Fit new brake shoes & new drum. Re fit wheels & tension wheel nuts. Refit CTI hoses & adjust brakes.		08/02/2024	460162	Completed	Mt Gambier	STK	XV14VU	PACCAR PARTS FLEET SERVICES - 3	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Myrtleford - Workshop	VehService\AS	PO# L083880		08/02/2024	460162	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		08/02/2024	460162	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE WORN SHOCKER BUSHES ON STEER - Remove and replace worn shocker bushes.		08/02/2024	460162	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			LOW DRIVE BRAKE LH REAR - Remove air cti hoses, remove wheels. Remove brake drum & linings.									
1051	Myrtleford - Workshop	Brakes\BRK RELINE	Fit new brake shoes & new drum. Re fit wheels & tension wheel nuts. Refit CTI hoses & adjust brakes.		08/02/2024	460162	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		26/01/2024		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		26/01/2024		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\BS	PO# L083449		20/01/2024	449627	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/01/2024	449627	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Albury - Workshop	Susp\WHEEL ALGN	NEEDS WHEEL ALIGNMENT ASAP- PULLING LEFT BADLY - NEW STEER TYRES FITTED 1 WEEK AGO.	CARRY OUT STEER WHEEL ALIGNMENT	20/01/2024		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\GPS	DVR health check		12/01/2024	526283	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER

1051	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		12/01/2024	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep	RH VENT MISSING - Removed the dash panel & sourced new vent and installed. Refit dash.		16/12/2023	437980	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\ADBLUE	TANK LEAKING AD BLUE - Found an O-ring leaking ad blue, disconnected the hoses & removed level sensor, fit new filter. Repalced o'ring and refit components.	REPLACE EXHAUST GASKET - Found clamp at muffler was leaking ad blue. Removed clamp & found gasket was worn. Scraped off gasket and replaced with new. Refit clamp & tensioned.	16/12/2023	437980	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DASH LIGHTS - removed dash and replaced blown globe for oil & trans temp. Refit dash, all okay.		16/12/2023	437980	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15 PO# L082916		16/12/2023	437980	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job B 1 Service, Jack up steer axle check bearings and king pins.		16/12/2023	437980	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		30/11/2023	429418	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Carry out A Service as per job card for T909 X15		30/11/2023	429418	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		30/11/2023	429418	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Elect\ELECT P&W	ENGINE RETARDER LIGHT N/W	Removed the dash & inspected globe for engine retarder. Found globe was blow. Remove & replace globe. Refit dash, check operation.	30/11/2023	429418	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	REPAIR RH DOOR	On inspection found door hinge to be bent. Attempted to straighten. not much better. New hinge required to fix completely. Rebook.	30/11/2023	429418	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Cooling\COOL LEAKS	REPAIR TAP LEAKING	On inspection found heater tap to be leaking. Drained coolant, unscrewed tap and fit new. Filled with coolant then bleed system. Topped up the coolant with 15 L. Tested, ok	30/11/2023	429418	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Insp\RWC COMP	SPEED LIMIT CETIFICATE	carried out speed limiter check as required	30/11/2023	429418	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes\EBS FAULTS	ABS, ESC AND TRACTION CONTROL Carry out A Service as per job card for T909 X15	constantly on, wont turn off Connected computer into truck & checked for faults. Found fault was for the left and right wheel speed sensor on the steer. Checked for power at plugs underneath truck. Found LH side had correct power but RH side didn't. Chased the wiring & was unable to fault. Found corrosion & water in plug. Cleaned and blew the plug out with air. Cleaned all terminals & tested for power. All ok. Tested for power at the wheel speed sensor, all okay. Secured all wiring & cleared codes	25/11/2023	427400	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	PO# L082161	CHECK BATTERIES - On service inspection, removed terminals and load tested batteries. Found x1 had failed. Removed battery and replaced with new. Connect terminals and started truck, all okay.	10/11/2023	419619	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		10/11/2023	419619	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Engine\BATTERY	JUMP START - travel to GF yard, lowered bull bar & jacked cab over. Connect jumper pack & jump started truck. Inspect and found fridge was left on, causing the drained batteries. Advised to run truck & charge batteries. Test on next service.		07/11/2023	418344	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\ENG TUNE	Engine Tuneup		29/10/2023	416178	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\ADBLUE	AFTER TREATMENT LIGHT ON - Connect laptop to check faults. Found to have loss of prime faults. Flushed unit & carry out overide test, found no ad blue. Checked suction lines & found rubbed hose in pipe between filter and doser pump. Removed & manufactured new hose to suit. Fit & secured.	Carry out overide test again, all okay.	28/10/2023	416050	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\Re-Tor	7-10		25/10/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\ADBLUE	AFTER TREATMENT LIGHT ON/OFF - Connect laptop and check faults. Found high pressure at injector code. Removed injector and cleaned out. Ran doser overide test, all okay. On air purge, found bubbles coming out of injector. Found injector was cracked. Replaced injector, cleared inactive faults test drive, all okay.		21/10/2023	410594	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Steering	CHECK FRONT END SHUDDER - Jacked front end, checked king pins, all within spec. Road tested truck, issue possible due to steer wheel imbalance.		20/10/2023	409607	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WIPERS	RH WIPER BLADE OR ARM NOT STAYING ON THE SCREEN.	CHECK WIPERS, RH NOT STAYING ON SCREEN - Found drivers side arm was loose. Removed & found wiper arm had been rounded on mounting bolt. Removed arm, replaced with new. Replaced worn wiper blades on other wiper.	20/10/2023	409607	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	PLEASE ADJUST CLUTCH. NO CLUTCH BRAKE. NO FREE TRAVEL. Service As Per Attached Checklist	ADJUST CLUTCH - carried out clutch adjustment as required.	20/10/2023	409607	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\CS	PO# L081699		20/10/2023	409607	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/10/2023	409607	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp	FRONT END HAS VIOLENT SHUDDER AT 90-95KPH.		19/10/2023	526283	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	ADJUST CLUTCH. 100MM FREE PLAY AT TOP. NOT FREE PLAY FROM FLOOR.		19/10/2023	526283	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WINDSCREEN	REPLACE RH WINDSCREEN. 4 STONE CHIPS.		19/10/2023	526283	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		18/10/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		18/10/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		18/10/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\FITMENT	1-2		17/10/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\FITMENT	1-2		11/10/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DASH LIGHT OUT. L/H AIR GAUGE.	Removed dash, repalced blown globe. Refit dash panel. Tested, okay.	05/10/2023	399649	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Cooling\COOL LEAKS	CAN SMELL COOLANT. PLEASE CHECK FOR A LEAK.	Found loose hose clamp. Tightened clamp, checked over, all okay.	05/10/2023	399649	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Elect\HEAD LIGHT	LIGHT COVER R/H SIDE. Mini B Service As Per Attached Checklist	S&F new RH light cover.	05/10/2023	399649	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L081421		03/10/2023	399649	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		03/10/2023	399649	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	PO# L081095		17/09/2023	390476	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		17/09/2023	390476	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Albury - Workshop	Engine\BATTERY	CHECK BATTERIES - load test batteries, replaced as required.		09/09/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Albury - Workshop	Engine\BELTS/TENS	WORN BELT - remove damaged fan belt and replaced with new.		09/09/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Albury - Workshop	Steering\STEER UNI	STEERING WHEEL LINKAGE RATTLING NEEDS GREASE I THINK.	STEER SHOCKERS - RH front shocker had worn bushes. Unbolt shocker, replaced worn bushes.	09/09/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Albury - Workshop	DrCabElect\SCALES	SCALES CHANNEL 1.3.	REPLACE LOAD CELLS - Removed t/table & feet. Removed load cells & installed new. Refit t/table & feet. Tensioned and refit turntable top.	09/09/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Albury - Workshop	DriCabRep\WIPERS	WIPER BLADES PLEASE. Service As Per Attached Checklist	REPLACE WIPER BLADES - supply and fit new wiper blades.	09/09/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L080671		01/09/2023	379595	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/09/2023	379595	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\BATTERY	JUMP START TRUCK	Go to Greenfreight yard, jacked cab, connect jumper pack and jump started truck. Vehicle returned to BMG yard and load tested batteries, two batteries failed. Removed batteries and replaced with new. Started truck, checked alternator is charging, all okay. *battery 12 month warranty*	12/08/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\BATTERY	JUMP START TRUCK Carry out A Service as per job card for T909 X15	Go to Greenfreight yard, jacked cab, connect jumper pack and jump started truck	10/08/2023	371000	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L080057		04/08/2023	369131	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.		04/08/2023	369131	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L079767		25/07/2023	3630038	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Elect\ELECT P&W	MARKER LIGHTS ON 1ST BOLSTER NOT WORKING PROPERLY, THEY KEEP FLICKERING.		25/07/2023	3630038	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE STEER SHOCK BUSHES.		25/07/2023	3630038	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Steering\WHEEL ALGN	CARRY OUT WHEEL ALIGNMENT		19/07/2023	360120	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Wodonga - Workshop	Susp\WGHT GAUGE	Fit Remote Scales. Barry Maney PO# L079547.	Mount scales to cross over bar behind cab. Run wiring from back of gearbox to R/H side of truck. Trace wires through guard well into cab through steering column to RHS of Cab. Connect to weight scales, wire remote to power. Check operation all OK.	09/07/2023		Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2 Carry out A Service as per job card for T909 X15		08/07/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L079444		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE STEER SHOCK BUSHES.		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Chassis\HOUSEKEEP	BROOM HOLDER ON A TRAILER, DROP BY 2 RUNGS PLEASE.		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DRIVER'S SIDE DOOR SEAL STILL LEAKING AIR. PLEASE FIX EVEN IF YOU HAVE TO REPLACE THE DAMN DO		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Chassis\KING PIN	CHECK TRAILER PIN FOR WEAR.		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Chassis\FIFTH WHEE	TURNTABLE NEEDS ADJUSTING.		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DOOR PANEL NEEDS REFIXING TO DOOR.		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER

1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	SEALS ON D/S WINDOW STILL LEAKING & DOOR RATTLES.		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Susp\WHEEL ALGN	STEERING PULLING TO THE LEFT. NEEDS WHEELS BALANCING OR WHEEL ALIGNMENT.		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Service As Per Attached Checklist		07/07/2023	351474	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L079096		21/06/2023	342155	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		21/06/2023	342155	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	PO# L078818		07/06/2023	331906	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Susp\WHEEL ALGN	STEERING PULLING TO THE LEFT. NEEDS WHEELS BALANCING OR WHEEL ALIGNMENT.		07/06/2023	331906	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service As Per Attached Checklist		07/06/2023	331906	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L078555		26/05/2023	322838	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes			26/05/2023	322838	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Body\MIRRORS	PASSENGER SIDE MIRROR FRAME & MIRROR SHAKING. UNUSABLE WHEN DRIVING. WHOLE THING NEED BOTH DRIVER AND PASSENGER DOOR SEALS NOT SEALING. NEED REPLACING. REFER INVOICE 364514 BOTH DOOR SEALS WERE REPLACED. BOTH DRIVER AND PASSENGER DOOR		26/05/2023	322838	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	SEALS NOT SEALING. NEED REPLACING. Carry out A Service as per job card for T909 X15		26/05/2023	322838	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L078238		11/05/2023	312043	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Body\MIRRORS	L/H MIRROR LOOSE ON MOUNT.		11/05/2023	312043	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\SCALES	SCALES CHANNEL 1 SHOWING NO POWER, WITH WEIGHT STAYS 12,650 POWER FAULT. CHANNEL ONE O		11/05/2023	312043	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	FUEL GAUGE LIGHT. OIL PRESSURE LIGHT. JAKE BRAKE LIGHT.		11/05/2023	312043	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	R/H DOOR RATTLE. STRIKER NEEDS ADJUSTMENT.		11/05/2023	312043	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WIPERS	WIPER BLADES PLEASE.		11/05/2023	312043	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		11/05/2023	312043	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	DrivLine\DIFF OIL	Diff Oil Change Service As Per Attached Checklist		05/04/2023		Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L077539		30/03/2023	298586	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		30/03/2023	298586	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	PO# L077093		09/03/2023	290187	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job B 1 Service, Jack up steer axle check bearings and king pins.		09/03/2023	290187	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter. Service As Per Attached Checklist **MINI B SERVICE**		23/02/2023		Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	PO# L076820		23/02/2023		Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job CTI WON'T GO UP OR DOWN. Checked air inflation system. Removed the cover to traction airbox. Inspected for air supply and found the box wasn't getting air. Floowoed airlines back to the tank into the pressure protection valve. Tested the valve, found to be faulty. Removed and replaced the protection valve. Checked the operation of the system and all ok. Refitted the cover to the box.		23/02/2023		Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	CTI\CTI Drive			22/02/2023	279954	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\FUEL TANK	DRIVER CALLED. TRUCK WON'T START. ADVISED DRIVER TO CHECK FUEL TANKS AND FILTER BOWL. NO FI Carry out A Service as per job card		15/02/2023	276331	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	PO# L076582		09/02/2023	272426	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WINDOW REG	LEFT HAND WINDOW NOT WORKING OR GOING UP OR DOWN.		09/02/2023	272426	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		09/02/2023	272426	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Tyres\CLEANSKIN	Cleanskin Service As Per Attached Checklist		04/02/2023		Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	PO# L076284		26/01/2023	263424	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Turntable lock broken		26/01/2023	263424	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Chassis\FIFTH WHEE	Remove turntable lock & replace with new. Painted red, test operation, okay Carry out A Service as per job card for T909 X15		30/12/2022	247130	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L075731		15/12/2022	253274	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		15/12/2022	253274	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\BATTERY	Go to truck and jumpstart. Tested batteries & replaced all 4		01/12/2022	244350	Completed	Mt Gambier	STK	XV14VU	Albury Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\BATTERY	Jump Start		26/11/2022	244200	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrivLine\GEARBOX	GEAR STICK CABLES VERY TIGHT.	ADJUSTED CABLES.	19/11/2022	242982	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DrivLine\CLUTCH	CLUTCH NEED ADJUSTING.	ADJUSTED.	19/11/2022	242982	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\WINDSCREEN	PASSENGER WINDSCREEN NEEDS REPLACING. VERY LARGE CRACK.	REPLACED.	19/11/2022	242982	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Mini B Service As Per Attached Checklist		15/11/2022	242982	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L075088 Carry out A Service as per job card for T909 X15		15/11/2022	242982	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L074791		01/11/2022	232441	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/11/2022	232441	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		15/10/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		15/10/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		15/10/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 8 tyres Service As Per Attached Checklist		15/10/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L074587		14/10/2022	226692	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		14/10/2022	226692	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L074470		07/10/2022	213570	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job TRUCK PULLS TO THE LEFT.		07/10/2022	213570	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Steering\WHEEL ALGN	WHEEL ALIGNMENT RECOMMENDED. Service As Per Attached Checklist	Wheel Alignment done by Trident Truck Centre.	24/09/2022	195960	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\CS	Barry Maney PO# L074074		16/09/2022	200454	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrivLine\DIFF OIL	Please change Diff Oils		16/09/2022	200454	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	UHF AERIEL BROKEN.		16/09/2022	200454	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		16/09/2022	200454	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres Carry out Mini B Service as per job card for T909 X15		08/09/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L073904		07/09/2022	193748	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job Carry out A Service as per job card for T909 X15		07/09/2022	193748	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	Barry maney PO# L073557		19/08/2022	179415	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Steering	TRUCK PULLS TO THE LEFT.	CHECKED ALL STEERING AND BRAKE COMPONENTS. OK. RECOMMEND WHEEL ALIGNMENT.	19/08/2022	179415	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	PLUS THE DRIVER SIDE DOOR IS WARPED.	STRAIGHTENED DOOR.	19/08/2022	179415	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Elect\BRK LIGHT	BRAKE LIGHT FUSE KEEPS TRIPPING WHEN YOU PUT IT IN REVERSE FOR TOO LONG.	DIAGNOSED AND REPAIRED RUBBED WIRING. TESTED.	19/08/2022	179415	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DriCabRep\DOOR LOCK	DRIVER SIDE DOOR LATCH NEEDS TO BE TIGHTENED.	TIGHTENED STRIKER AS REQUESTED.	19/08/2022	179415	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\RADIO	UHF AERIEL BROKEN.		19/08/2022	179415	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		19/08/2022	179415	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REAR AIR GAUGE LIGHT FALLEN OUT OF SOCKET.		13/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Elect\ELECT P&W	CIGARETTE LIGHTER SOCKET FALLEN OUT.		13/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON.		13/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Wodonga - Workshop	DrCabElect\INST/GAUGE	OIL PRESSURE GAUGE LIGHT BLOWN.	REPLACED GLOBE.	04/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	Elect\HEAD LIGHT	HIGH BEAM DASH LIGHT BLOWN.	REPLACED GLOBE.	04/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	Cooling\COOL LEAKS	USING 3L COOLANT PER WEEK. CAN SMELL. PLEASE CHECK FOR US!! Service As Per Attached Checklist	NO LEAK FOUND. PRESSURE TESTED AGAIN.	04/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	VehService\BS	Barry Maney PO# L073294		04/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	DrCabElect\INST/GAUGE	TABLET NOT CHARGING FROM CRADLE.	CHECKED. CHARGING OK.	04/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/08/2022	171821	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP03	puncture repair Carry out A Service as per job card for T909 X15		28/07/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	VehService\AS	PO # L073128		24/07/2022	164437	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER

1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	TABLET NOT CHARGING FROM CRADLE.		24/07/2022	164437	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		24/07/2022	164437	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\INST/GAUGE	TABLET NOT CHARGING FROM CRADLE.		05/07/2022	152027	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		05/07/2022	152027	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L072745		05/07/2022	152027	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Wodonga - Workshop	VehService\AS	Barry Maney PO# L072472		21/06/2022	142481	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		21/06/2022	142481	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L072159		01/06/2022	128889	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/06/2022	128889	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Myrtleford - Workshop	VehService\AS	PO # L071873		20/05/2022	120466	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		20/05/2022	120466	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Remove air pipe & rocker cover									
			Carry out Tune up									
			All valves tight, adjust									
			Adjust engine breaks									
			Refiit rocker cover with original gasket									
			Check belts, tensioners and air filters, ok									
			Pressure test CAC, ok									
			Flush air side of adblue									
			Check turbo wastegate, out of spec									
			Remove turbo and adjust wastegate									
			Refit Turbo with new gasket									
			Road test and final check over									
1051	Myrtleford - Workshop	Engine\ENG TUNE	All ok		13/05/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2tyres		11/05/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/05/2022	110302	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Service As Per Attached Checklist									
			Mini B Service									
1051	Wodonga - Workshop	VehService\B1 Svc	Barry Maney PO# L071607		05/05/2022	110302	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrivLine\DIFF OIL	Replace diff oil and filters		24/04/2022		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L071369		22/04/2022	101386	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		22/04/2022	101386	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\BS	Barry Maney PO# L071227		12/04/2022	92840	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/04/2022	92840	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\AS	Barry Maney PO# L070951		29/03/2022	82636	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes\ABS	ABS LIGHT STAYING ON.		29/03/2022	82636	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		29/03/2022	82636	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		12/03/2022		Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Mini B Service									
			Jack up steer axle check bearings and king pins.									
			Replace cabin filter.									
1051	Myrtleford - Workshop	VehService\B1 Svc	Barry Maney PO# L070657		12/03/2022		Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Myrtleford - Workshop	VehService\AS	PO # L070387		01/03/2022	60045	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		01/03/2022	60045	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\BS	PO # L070228		18/02/2022	53214	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		18/02/2022	53214	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Elect\ELECT P&W	tablet not charging from cradle		16/02/2022	49970	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes\ABS	abs light staying on		16/02/2022	49970	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Myrtleford - Workshop	VehService\AS	PO # L069923		02/02/2022	42768	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2022	42768	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
			Mini B Service									
			Jack up steer axle check bearings and king pins.									
1051	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		18/01/2022	31483	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
			Carry out A Service as per job card for T909 X15									
1051	Wodonga - Workshop	VehService\AS	O/N L 12805		18/12/2021	19643	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/12/2021	19643	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
			Service As Per Attached Checklist									
1051	Myrtleford - Workshop	VehService\CS	O/N L12727		03/12/2021	7927	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		03/12/2021	7927	Completed	Mt Gambier	STK	XV14VU	BARRY MANEY - 3	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\SCALES	calibrate scales		19/11/2021	667	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
			2 x Stickers 3 Points of Contact									
			Safepak Albury									
1051	Wodonga - Workshop	Body\CONSUMABLE	POWW068693		16/11/2021	586	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Wodonga - Workshop	Insp\Truck Pre	Truck Pre Delivery Inspection		16/11/2021	586	Completed	Mt Gambier	STK	XV14VU	Wodonga Workshop	P/MOVER
1051	Myrtleford - Workshop	DrCabElect\SCALES	fit scales and Elphinstone trailer supply lines		28/10/2021	464	Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Body\FIFTH WHEE	fit Elphinstone turntable lock		07/10/2021		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER
1051	Myrtleford - Workshop	Chassis\FIFTH WHEE	make up turnbtable with scales and grease lines		01/09/2021		Completed	Mt Gambier	STK	XV14VU	Myrtleford Workshop	P/MOVER