| EquipmentName | Workshop | CodeAndSubCode | Description | CompletionComments | DateDone | DistanceDone | Workstate | Location | Division | Rego | Supplier | EquipmentType |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and king pins. | | | | | | | | | |
| 1050 | Mt Gambier - Mt Gambier | VehService\B1 Svc | Replace cabin filter. | | 08/09/2026 | 703051 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Mt Gambier - Mt Gambier | Chassis\CROSS MBR | Chassis\CROSS MBR | | 08/09/2026 | 699599 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Mt Gambier - Mt Gambier | Engine\ADBLUE | Excessive adblue usage | | 07/09/2026 | 699599 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1050 | Mt Gambier - Mt Gambier | Engine\EXHAUST | AD BLUE INLET AREA RUSTED OUT | | 21/08/2026 | 691529 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Remove steering wheel cover, fit a set of test steering<br>wheel buttons, road test and check, fault did not correct.<br>Refit original buttons and check over wiring to steering<br>wheel, diagnose possible smart module faulty or wiring fault<br>from smart module to engine ECU. Would need to inspect<br>further behind dash for repair. Truck to return for further | | | | | | | | |
| 1050 | Mt Gambier - Mt Gambier | DrCabElect\CRUISE CON | CRUISE RESET BUTTON N/W | investigation and repair | 21/08/2026 | 691529 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Colac - Colac | Engine\ADBLUE | REMOVE & REPAIR EXHAUST PIPE & ADBLUE DOSER CONNECTION | | 21/08/2026 | 691529 | Completed | Mt Gambier | STK | XV13VU | JF MECHANICALS - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\SUSPENSION | Missing grease nipple | Fitted new grease nipple to cab suspension | 16/08/2026 | 691529 | Completed | Mt Gambier | STK | XV13VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\MUDGUARDS | Loose mudguard pole, LHR | | 16/08/2026 | 691529 | Completed | Mt Gambier | STK | XV13VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service | | 16/08/2026 | 691529 | Completed | Mt Gambier | STK | XV13VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\WORK LIGHT | Rear cab light not working | | 12/08/2026 | 685774 | Completed | Mt Gambier | STK | XV13VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\DRV LIGHT | RH roof clearance light not working | | 12/08/2026 | 685774 | Completed | Mt Gambier | STK | XV13VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ALT | Alternator light on and not charging | Replaced alternator and checked charging system — OK | 12/08/2026 | 685774 | Completed | Mt Gambier | STK | XV13VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\RADIO | INTERFERENCE WITH RADIO / SCALES. NEEDS A SECOND EARTH FROM UHF RADIO | Remove dash panels and check over antenna connections. Check<br>scale connections, check ohms to antennas - RH high<br>resistance. Remove and replace RH antenna. Recheck<br>operation but still had interference. Check hand pieces and<br>swap over connections - found extension leads for hand<br>pieces source off issue. Manufacture x2 new extensions. Fit<br>new extensions and fit throughout dash, up pillar and across<br>top. Check UHF operation but still having some issues. Check<br>earths at different points - scales work when new RH antenna<br>disconnected. Remove and replace antenna and check<br>operation, still having issues. Check over all connections<br>several times but could not fault. Disconnect antenna so<br>scales work, to have truck return for further diagnosis and<br>repair | 05/08/2026 | 680252 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | DrCabElect\INST/GAUGE | Jack up axle and remove RH wheel. Turn steer arm all the way<br>to the right. Remove split pins and nuts. Remove drag link<br>then remove worn tie rod end. Fit new tie rod end, refit<br>drag link and tension. Fit new split pins, refit wheel and<br>tension wheel nuts, all OK<br>RH WINDSCREEN WASHER N/W<br>REPLACE WIPER BLADES | 05/08/2026 | 680252 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\WIPERS | drv side windscreen washer not working<br>left hand side wiper blade. change both | Replace wiper blades as requested. Inspect and found RH<br>washer not working due to blocked line. Remove nozzle and<br>blow out. Refit nozzle, top up washer bottle, all OK<br>R&R BALL RACE | 05/08/2026 | 680252 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\FIFTH WHEE | Chassis\FIFTH WHEE | Split truck and trailer. Remove base plate bolts. Set up<br>lifting device then lift turn table off. Remove bolts<br>holding ball race onto base then lift off ball race and fit<br>new. Refit turn table and tighten bolts. Fit turn table to<br>track and grease ball race, all okay<br>Found tacho not operating.<br>Found no conduit left on speed sensor wiring.<br>Wriggled wiring and confirmed tacho began working intermittently.<br>Identified poor wiring protection/connection as cause of fault.<br>Recommend: Repair/replace conduit and secure speed sensor wiring to prevent<br>future failure. John to discuss with Gary Brown auto elec. | 04/08/2026 | 683863 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | Elect\ELECT P&W<br>VehService\BS B Service | | 04/08/2026 | 683863 | Completed | Mt Gambier | STK | XV13VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | L135044 | Travelled to Warrnambool at the front or morse bearings<br>Checked fault codes<br>No codes were present<br>Checked over fuel system for any leaks or where it could<br>be sucking in air from all check out ok<br>Inspected wiring loom for damaged wiring there were no<br>obvious sign<br>Started the truck it ran ok with no issues could not find<br>cause of the issue<br>3.00<br>150.00<br>10%<br>450.00<br>14/07<br>Labour- Mobile- Breakdown<br>Travelled back to truck at 1:30 due to completely shutting<br>down and not turning over anymore<br>Checked all fuses<br>Found that the engine ignition fuse<br>had less than 5 volts<br>Checked power supply to engine<br>ignition relay<br>Found it had bad power<br>Temporally fixed by removing the power supply wire from<br>relay and put in a<br>switched power supply from a spare plug near the relays to<br>get him back to mount gambier | 01/08/2026 | 680252 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\AIR LEAK | Engine\AIR LEAK | Inspect and advise customer new air drier required.<br>Remove and replace air drier unit. Found compressor charge<br>hose brittle and breaking apart. Measure and source new<br>hose. Fit and run hose. Spray over and check for air leaks,<br>all OK. Drop truck back to yard<br>NGE20300NG AIR DRYER KIT W/ TAN 1 1142.17 | 17/07/2026 | 676913 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\AIR LEAK | air dryer blown gasket | Sublet15113900 hose<br>Remove all components to access. Remove and replace UHF<br>aerial as required. Run new lead to radio and reassemble,<br>check operation - all OK | 17/07/2026 | 676913 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\RADIO | R&R HAND PIECE - PREV DIAG<br>NEED TO CHECK AIR DRYER. STILL GETTING ALOT OF WATER DRAINED FROM TANKS DAILY.<br>WD ASKED TO CHECK IF SILENCERS ARE BLOCKED AND | KWAE4012K1 BASE W/AERIAL-WHIP 4.5MTR COAX<br>Inspect air drier filter - found water. Remove lines and<br>rekit air drier as required. Change base over to rippled<br>base to prevent gasket from blowing out, all OK | 06/07/2026 | 670673 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\AIR TANKS | POTENTIALLY REMOVE THEM | KWT2000SK-P KIT AIR DRYER | 06/07/2026 | 670673 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | BLOWN GLOBES ON DASH | Remove dash cluster and replaced blown globes. | 06/07/2026 | 670673 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and king pins.<br>Replace cabin filter. | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | L134614 | | 01/07/2026 | 670673 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Inspect air leak, found gasket to be blown out bottom of<br>air drier. Drop trailers, remove deck plate, unbolt air<br>dryer and replace gasket as required. Refit air dryer and tension<br>to spec. Test and inspect for leaks, all OK | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\AIR LEAK | INSPECT / REPAIR AIR LEAK FROM BOTTOM OF AIR DRIER | KW228CR KIT T2000 AIRDRYER | 01/07/2026 | 669922 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1050 | Myrtleford - Workshop | DriCabRep\DAMAGE | CRACK IN DRIVER SIDE STEP ASSEMBLE ON 1050<br>Inspect step and found crack in fibre glass. Damage not significant and will not cause issue. Can be fixed at Southern Paint and Panel but would require truck to be off road for about 2 days. | | 25/06/2026 | 666063 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\BOOST HOSE | ENGINE DOWN ON POWER. GET CUMMINS TO CHECK IT OUT. | CHECK WASTEGATE INTERCOOLER AIR FILTER & CODE ALL OK ALSO TEAT DRIVE WITH DRIVER AND CHECK WHILE DRIVING A/ | 25/06/2026 | 666063 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\BELTS/TENS | CHECK BELTS SQUEELING AND ALT LIGHT ON | Test voltage at alternator - all OK. Inspect and found pulley noisy. Remove and replace belt and pulley, recheck, all OK<br>KWD84-1000-3122380DYC BELT-FAN DRIVE 1 176.05<br>KW89440DYC TENSIONER BELT AUTOMATIC H.D.<br>Get tools and parts required then travel out to truck. | 24/06/2026 | 666063 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\WHL HUB | AFTER H'RS BREAKDOWN<br>CALL OUT FEE<br>LH STEER HUB GASKET LEAKING | Remove LH steer hub cap and inspect, found to look warped and cap had a crack causing leak. Replace cap, top up with oil and check over for leaks, all OK<br>NG90001-HUB HUB OIL 1 21.45<br>KW1613CR CAP-FRONT HUB<br>Release brakes and removed clevis pins. Back off brakes, remove and replace slack adjusters as required. Refit shims, adjust brakes and grease as required. Road test and check brake temps, all okay | 16/06/2026 | 663125 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\SLACK ADJ | R&R rear drive slack adjuster<br>VehService\AS A Service | KWPA881132PZ ADJUSTER-SLACK, AUTO, 5.5' PACCAR GENUIN | 12/06/2026 | 660620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | L134271<br>Insp\ANN INSP Annual insepction as per check sheet | | 12/06/2026 | 660620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Insp\ANN INSP | L134272 | | 12/06/2026 | 660620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\DRV LN SER | REMOVE POWER DIVIDER FROM FRONT DIFF & INSPECT THRUST WASHERS & GEARS & BEARINGS ALSO CHECK PONION BEARINGS & REPORT ON FINDINGS<br>(METAL WAS FOUND IN FRONT DANA DIFF OIL) WD<br>L134142 | Inspect front diff input, check thrust washer and components for wear<br>Remove deck plate, tail shaft, diff lock air line, and all power divider bolts. Pry out power divider and inspect - all looked okay. Inspect inside of diff - all looked okay. Fit power divider back to diff and secure all bolts with loctite and sealant around face. Tighten and tension all bolts to spec. Refit tail shaft with new bolts and tension to spec. Manufacture bracket to be able to use dial indicator, found all within spec. Check and adjust yoke in and out movement to spec. Refit diff lock air hose and deck plate. Drain and refill diff oil. Road test truck and inspect for diff leaks. Check over tail shaft and jack shaft, all okay. | 05/06/2026 | 656426 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\RADIO | UHF RADIO SCCATCHY WHEN TALKING, LOTS OF PEOPLE COMPLAINING. OK WHEN RECEIVING. | REPLACE UHF HAND PIECE<br>Complaint of bad signal, pull dash apart and unplug UHF. Swap over UHF handles and reassemble dash. Check operation, all working as should<br>KWMCS538 UHF MICROPHONE | 29/05/2026 | 655144 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\DAMAGE | RUBBER AROUND DOOR SEAL DRIVERS SIDE NEEDS REPAIRING | Remove old drivers side door seal and fit new.<br>KWU42-1014-3145 SEAL-PINCHWELD 1 50.16<br>KWR42-1084 SEAL-DOOR CAB PRIMARY | 22/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | L/H fuel cap wont tighten | Replace fuel cap on and replace<br>KWHM1022-B FUEL CAP - POLISHED | 22/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\SLACK ADJ | LHR RHR SLACKIES | CHECK LH REAR AND RH REAR AUTO DRIVE BRAKE SLACK ADJUSTERS AND REPLACE AS REQUIRED<br>Checked drive slack adjusts for correct operation and adjust accordingly | 22/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\AIR CON | strong coolant smell when heater on floor | Remove passenger side cover to heater core and found split hose, remove and cut off end and re fit. | 22/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\HEAD LIGHT | R/H front parker not working | Rh parker light and headlight fallen out. Re secure light and repair broken wire.<br>RH FRONT PARKER LIGHT N/W | 22/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\LIGHTS | rhs headlight loose & parker not working | Rh parker light and headlight fallen out. Re secure light and repair broken wire. | 22/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\SEAT | REPAIR FAULTY SEAT - FEELS LIKE SOMETHING HAS BROKEN OR FALLEN APART<br>FIT C/OVER G/F SEAT<br>VehService\AS A Service | Complaint of seat feeling unstable. Remove top of base, could see when moving left and right rollers were worn. Organise new seat. Remove seat, fit guardian and airline to new seat, road test and feel seat, all okay | 22/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | L133833 | | 21/05/2026 | 650588 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\SLACK ADJ | Brakes\SLACK ADJ | Adjust all drive brakes to spec, check on road test, all okay | 15/05/2026 | 653140 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Steering\KING PIN | CHECK KING PINS & REPLACE IF REQUIERED<br>REPLACE LH TIE ROD END ASLO (BM HAD TO WAIT FOR PARTS)<br>VehService\BS B Service | Jack up steer axles, removed hubs and backing plates. Removed brake shoes, disconnect steering linkages. Removed stub axle, cleaned surfaces. Removed tie rod and found RH cap had fallen out. Ordered new tie rod, remove and replaced with new. Removed bushes, installed new and reemed to suit. Refit stub axle and shimmed correctly. Refit steering linkages, refit brake shoes, refit hub assemblies with new seals and adjust bearings to spec. Tensioned wheel nuts, adjust brakes. Test drive, recheck hub oil, all okay.<br>KW331435 KINGPIN KIT 1 888.77<br>NG10088 LUCAS HUB OIL 1 30.15<br>KW453795CR GASKET-HUB CAP 2 18.48<br>KW43764S SCOTSEAL 2 100.64<br>KW220TR118 TIE ROD END - LH TIE ROD END - LH 1 502.16<br>NGFREIGHT FREIGHT | 15/05/2026 | 653140 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | L133443 | | 14/05/2026 | 640989 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\BATTERY | Load test batteries & REPLACE ALL 4 BATTERIES (WD) | Load tested batteries, found 1 failed and 3 were okay. Confirmed with Wayne to replace all 4. Removed all batteries and replaced with new. | 12/05/2026 | 649554 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\DRIVES | Truck still having driveline vibration check diffs take samples, check tyres | Inspect engine and drive line, found thru shaft uni had excessive movement 0-006'. Remove jack shaft and replace thru shaft uni as required. Refit jack shaft, tension caps and advise driver to report if issue rectified, driver called back and reported all okay then reported not ok in morning. Inspect drive line, jack up drive wheel and rotate drive shafts. Check uni joints and inspect front and rear engine mounts - found rear diff pinion nut slightly loose. Tension to spec.<br>Remove drive shaft and take front and rear diff oil samples.<br>NG116944 OIL TEST KIT 2 150.00<br>KW5007417 BOLT 4 9.92<br>NGSDSPL170SF4X KIT UNI JOINT SPL170 | 12/05/2026 | 649554 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\AIR FITTIN | AIR TANK DRAIN WIRE BROKEN BEHIND FUEL TANK (RHS).<br>WIRE NEEDS TO BE MOUNTED AT BACK OF TOP OF FUEL TANK. | Replace drain cord (broken)<br>Remove and replace air tank drain cord valve as required.<br>KW12104 VALVE-DRAIN 1 67.34<br><<< Total For Job 2 >>> | 12/05/2026 | 649554 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP11+12 | Tyres\TP11+12 | | 11/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP7+8 | Tyres\TP7+8 | | 11/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP9+10 | Tyres\TP9+10 | | 11/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP5+6 | Tyres\TP5+6 | | 11/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 11/05/2026 | 651722 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Pre-Diagnose clutch condition and adjustment<br>Check Lubrication<br>Remove intake components, deck plate, tail shaft. Unplug<br>trans plugs, connect trans to sling, unbolt and remove<br>transmission. Remove clutch and flywheel (take flywheel to<br>get machined) Remove cross shafts and bushes. Fit new<br>bushes then refit cross shaft and clutch brake. Remove rear<br>main, refit flywheel, fit new clutch and tension to spec.<br>Refit transmission and all other components previously<br>removed. Adjust clutch to spec, road test, all operating as<br>should. Truck returned next day, adjust clutch and free<br>travel, all working as should. Truck returned again with<br>complaints of vibration.<br>KWK-4450-PAC CLUTCH KIT INC KW X SHAFTS SUITS 14 SPLI 1 636.05<br>CU5609787 KIT,SEAL 1 231.61<br>KW5007417 BOLT 4 9.92<br>KW4309447 GASKET-HOUSING,SHIFT LEVER 1 17.70<br>KW715-8016-006 CONNECTOR ELBOW 1/4 - 3mm 1 8.04<br>KW5007417 BOLT 4 9.92 | | | | | | | |
| 1050 | Myrtleford - Workshop | DrivLine\CTCH PACK | CLUTCH BRAKE PLAYING UP (G/BOX WILL NEED TO BE REMOVED TO INSPECT CLUTCH) REPLACE CLUTCH KIT UNDER WARRANTY BY EATC | Sublet1S113440 Machine flywheel | 11/05/2026 | 645142 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | Jump start truck at yard<br>Get jumper pack from workshop then head to GF yard. Jump | AFTER H'RS BREAKDOWN<br>Call out to truck 12:50am | | | | | | | | |
| 1050 | Myrtleford - Workshop | DrCabElect\BREAKDOWN | start truck, all okay<br>REPLACE RH WINDSCREEN | CALL OUT FEE<br>KWR44-1125R GLASS- WINDSHIELD K200 RHS 2014 - CURREN 1 282.39 | 07/05/2026 | 645142 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\WINDSCREEN | **westons booked 2pm** | Sublet1S113355 Install new windscreen<br>Removed dash panel and replaced oil pressure dash globe. | 30/04/2026 | 642747 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | OIL PRESSURE DASH GLOBE | Refitted dash panel. | 27/04/2026 | 642747 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\MOUNTS | TIGHTEN LOOSE BARS | Tightened fastening bolts on belly bar as required. | 27/04/2026 | 642747 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\BOOSTER | LHR BOOSTER LEAKING | Disconnect lines to brake booster, unbolt and removed. Get<br>new booster, cut push rod to length and installed. Connect<br>lines and checked operation, all okay.<br>NGWT3030 30/30 BRAKE BOOSTER<br>Drained air from tanks. Removed air drain bungs that were<br>leaking and fitted new. | 27/04/2026 | 642747 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\AIR FITTIN | AIR TANK DRAINS LEAKING | KWTRP123<br>Remove horn cover, found mounting clips broken. Order new<br>cover as required. Replaced horn cover. | 27/04/2026 | 642747 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\HOUSEKEEP | horn cover not staying on | KWS63-1036 PAD - STEERINGWHEEL, MPX<br>Ad blue tank was sucked in. Opened up breather and found to<br>be blocked. Removed and cleaned out breather, flushed and | 27/04/2026 | 642747 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | CLEAN OUT AD BLUE BREATHER | refitted.<br>RH HEADLIGHT INTERMITTENTLY NOT WORKING<br>Check over RH headlight loom for faults, all looked OK.<br>Test all through loom but unable to fault. Check over<br>connections at light and found all looked OK. Test for<br>power to light, had power - diagnose faulty headlight. Get<br>new headlight, remove and replace as required, all working<br>OK. | 27/04/2026 | 642747 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | AFTER H'RS BREAKDOWN<br>10:30pm call out to BMG workshop<br>CALL OUT FEE | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Elect\BREAKDOWN | NGCALLOUT PARTS A/HRS CALLOUT<br>RECHECK BALL RACE UP & DOWN MOVEMENT<br>* ADVISE WHEN DO WE NEED TO REPLACE THIS ?* | KWP54-1326-1-001 KW 12V/24V LED H-LIGHT HI/LO<br>Re check ball race up and down movement<br>Split trailer off truck, rechecked turntable movement, all | 14/04/2026 | 636082 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\FIFTH WHEE | Checked movement, within spec. Continue to monitor. | within spec.<br>Removed adblue tank breather and fitting, flushed hot water<br>through fitting and hose until clear, refitted to truck, | 08/04/2026 | 631620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | TANK BREATHER BLOCKED | all okay | 08/04/2026 | 631620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | CLUTCH NEEDS ADJUSTMENT PLEASE | Carried out clutch adjustment as per usual, all okay.<br>BMG supplied windscreen. Weston windscreen and tinting fit<br>to truck<br>NGR44-1125RA R/H WINDSCREEN 1 337.74 | 08/04/2026 | 631620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\WINDSCREEN | Remove and replace RH windscreen<br>VehService\AS A Service | Sublet1S113179 REPLACE RH WINDSCREEN | 02/04/2026 | 631620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | L133191 | | 01/04/2026 | 631620 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\SUSPENSION | Torque rod bushes LH front monitor | H FRONT TORQUE ROD BUSH<br>Removed deck plate, removed torque rod and pressed out worn<br>bushes. Refit torque rod.<br>KW839310 BUSHING CAN USE TRB68250<br>replaced water pump. Refit belts and topped up coolant.<br>Started and run truck, all okay.<br>KWAE9976132 CAP-RADIATOR 15 PSI 1 14.43<br>CU5719759 CORE, WATER PUMP 1 1358.02<br>CU3684384 SEAL,O RING 1 68.75 | 12/03/2026 | 621539 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\WATER PUMP | REPLACE LEAKING WATER PUMP | KWELC40-5M PACGEN ELC40 PREMIX 5L EXTENDED LIFE COO | 12/03/2026 | 621539 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\COOL LEAKS | Driver smells burnt coolant. please check. poss liner ?? | DRIVER CAN SMELL BURN COOLANT<br>Jacked cab over, inspect for coolant fault. Found radiator<br>cap was faulty and coolant was leaking out of weep hole.<br>Replaced radiator cap. Drained coolant, removed and<br>RESEAL FRONT DIFF OIL LEAK - LET SIT OVER NIGHT AND FINISH<br>SATURDAY<br>Wash down diff area. Drained diff oil, pulled out both<br>axles. Removed bolts and unit. Remove saddles and tail<br>shaft. Slide diff back and cleaned all surfaces. Applied<br>new sealant, refit diff and bolt in. Refit tail shaft and<br>axles. Let sit over night to sealant to set.<br>Refilled diff with new oil.<br>NGTOYOTA toyota black 1 73.43 | 12/03/2026 | 621539 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | Front drive interface seal leaking - needs to be repaired. Will need<br>to let sit overnight to seal properly. Please rebook for this time | KW220BS1215 GASKET 2 7.20<br>KW5007417 BOLT 4 9.92 | | | | | | | | |
| 1050 | Myrtleford - Workshop | DrivLine\OIL LEAK | frame. | POL ULTRA CLEAR LS 80/140<br>EBS COMING ON WHEN TRAILERS ARE EMPTY & LOCKING UP BRAKES | 12/03/2026 | 621539 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\EBS FAULTS | EBS coming on empty trailers turning right. locking on brakes and smoking wheels<br>VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and king pins.<br>Replace cabin filter. | Repaired on trailers. | 12/03/2026 | 621539 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | L099258 | | 11/03/2026 | 621539 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | CHECK TAIL LIGHT N/W<br>AFTER H'RS BREAKDOWN | Check tail lights not working. Check over all fuses in<br>dash, all looked OK. Remove tail light cover, found<br>corroded wiring. Clean out all corrosion, cut and rejoin<br>wires where required. Test for power - no power. Trace<br>wiring back to rear bar light plug, cut all cable ties and<br>removed plug. Found a broken pin in plug and corroded<br>wires. Repaired pin in plug and clean off corroded wires.<br>Test for power before plug, no power. Found fuse on<br>separate wire coming from trailer plug was blown. Replaced<br>fuse. Tested, still no power. Remove deck<br>plate front and rear, trace wiring down chassis and found<br>had been teed into brown wire before plug. Cut wire and<br>test for power - had power. Run test wire from power side<br>of plug to after plug, check operation - tail lights now<br>working. Run new wire and secure with conduit. Tape up all<br>exposed wires and zip tie secure. Refit all covers and deck | | | | | | | |
| 1050 | Myrtleford - Workshop | Elect\BREAKDOWN | CALL OUT FEE<br>VehService\AS A Service | plates, all OK | 24/02/2026 | 612873 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | L098984 | | 20/02/2026 | 612333 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 19/02/2026 | 612873 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Steering\HOUSEKEEP | Pull truck over shaker and check over all steering components: steering aspects, wheel bearings, and king pins all looked OK. Suggest will need tyre balance and wheel | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Steering\HOUSEKEEP | HITS 80 KMH AND STARTS SHAKING - ONLY WHEN LOADED | alignment. | 18/02/2026 | 612873 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Check over wiring coming out of truck, found loose wiring connections for scales. Went to remove screw and found top stripped, had to cut slot to fit screwdriver in. Tighten | | | | | | | | | |
| 1050 | Myrtleford - Workshop | DrCabElect\SCALES | CHECK FOR BROKEN WIRE TO SCALES | screw as required, wiring now sitting secure, all OK | 18/02/2026 | 612873 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | REPLACE ROCKER COVER GASKET | | | | | | | | | |
| | | | Engine\ENG TUNE | FIT RECO NOX SENSOR | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\ENG TUNE | | REPLACE PLUG ON GEAR HOUSING | 09/02/2026 | 608635 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Engine\EXHAUST | Exhaust manifold sligt leak | INSPECTED BY CUMMINS ALL OK 17/1/26 | 05/02/2026 | 606097 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Check and inspect heaters. Found heater core leaking. Remove kick panel, remove and replace heater core as required. Jack cab and turn on all heater taps then road test and check heaters, all working as should. | | | | | | | | | |
| | | | HEATERS N/W | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Air Con\HEATER | REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 | KW25189001 CORE-HEATER CAB OVER | 31/01/2026 | 603878 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Remove and replace air intake rubber as required, all okay. | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Body\DAMAGE | CHECK ENGINE - AIR INTAKE RIPPED | KWG42-1008 | 23/01/2026 | 602323 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Remove ad blue sender, found filter to be blocked. Attempt to clean out, no good. Installed new filter and cleaned out breather. Refit sender, all okay. | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Adblue sender blocked | KWHHW0116 ADBLUE FILTER AND O RING | 23/01/2026 | 602323 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | VehService\CS C Service | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\CS | L098557 | | 21/01/2026 | 601283 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Scales would not wirelessly connect, inspect for faults. Carried out TX reset and powered down. Started up again and | | | | | | | | | |
| 1050 | Myrtleford - Workshop | DrCabElect\SCALES | REPAIR WEIGH SCALES | checked operation. all okay. | 19/01/2026 | 597808 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Travelled to GF yard at 5.30am and ensure all trucks started okay. Stay at yard on stand by until all trucks | | | | | | | | | |
| | | | GO TO YARD AND MAKE SURE ALL TRUCKS STARTED ENSURE ALL RUNNING OKAY AND BE ON STANDBY TO ASSIST AS | have left to assist with any issues arising as trucks start | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | REQUIRED | back. | 19/01/2026 | 597808 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\RUN OUT | Tyres\RUN OUT POS 6 | | 10/01/2026 | 597808 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER | |
| | | | VehService\AS A Service | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\AS | L098184 | | 17/12/2025 | 591069 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Found ad blue breather was blocked, Cleaned out breather, | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\FUEL TANK | ADBLUE TANK SUCKED IN | all okay. | 16/12/2025 | 589193 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | DISCONNECT AND CHECK MOVEMENT IN BALL RACE Disconnect truck and A trailer. Greased ball race and checked movement in turntable and ballrace. Found to have | | | | | | | | | |
| | | | Monitor movement in ballrace | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Chassis\FIFTH WHEE | checked on 13/12/25 still within spec as per invoice 403289 | movement but within spec. Reconnected truck and A trailer | 16/12/2025 | 589193 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Put truck over pit inspect all drive line components and clutch all okay. Inspect and test drive truck, not able to | | | | | | | | | |
| | | | CHECK CLUTCH AND/OR GEARBOX - HAS A RATTLE FEEL AND NOISE ON | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | DrivLine\DRIVES | TAKE OFF/WHEN LOADED | hear or feel any rattles. Driver to monitor | 04/12/2025 | 584547 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\ROTATION | Tyres\ROTATION FULL ROTATION | | 01/12/2025 | 584547 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\PRES CHECK | Tyres\PRES CHECK FULL PRESSURE CHECK | | 01/12/2025 | 584547 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER | |
| | | | VehService\BS B Service | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\BS | L097916 | | 26/11/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | First drive interface seal slight leak | | | | | | | | | | |
| | | | double up on job refer wo 200454 | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | DrivLine\DRIVES | | | 13/11/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | CHECK S-CAM MOVEMENT | | | | | | | | | |
| | | | | Both axles on front drive had worn s-cam bushes. Disconnect Air CTI lights and removed wheels. Removed brake drum and axle. Drained oil, removed bearings and put in parts washer. Remove brake shoes and disconnect slack adjuster. Removed s-cams, bushes and seals. Cleaned surfaces and installed new bushes and seals, installed new s-cams. Refit slack adjusters and brake linings. Removed wheel seals, cleaned surfaces and installed new wheel seals. Refit hub assembly, adjust wheel bearings to correct end float. Refit brake drums and wheels, refit axles. Connect air cti, | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Chassis\S-CAM | Chassis\S-CAM | tensioned wheels and adjust brakes. | 13/11/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Inspect battery cables, cleaned out corrosion with bi carb soda. Didn't have enough time to see how far the corrosion goes through cables. Cleaned cables on battery side, all | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\BATTERY | REPAIR CORRODED BATTERY CABLES | okay. | 13/11/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Re-secure airlines and pipe to prevent further rubbing | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Cooling\RADIATOR | Steel radiator pipe rubbing | anymore, all ok. | 13/11/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Remove and replace rear LH and front RH tank straps as required. | | | | | | | | | |
| | | | | KWK89-1004-1260 LINING-TANK STRAP 1 36.19 | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | Tank rubbers worn | KWK161-793-4000 LINING TANK STRAP,50MM X 4MTR | 13/11/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Remove dash panel, replaced blown globe. | | | | | | | | | |
| 1050 | Myrtleford - Workshop | DrCabElect\DOOR LOCK | Open door light n/w | KW47762 GLOBE-DASH PANEL,12V 1.2W BLACK BASE B8. | 13/11/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | VehService\AS A Service | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\AS | L097508 | | 10/11/2025 | 570334 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Drain water from tanks, remove unloader valve and compressor line. Found to have a little bit of water. | | | | | | | | | |
| | | | TANKS ACCUMULATING WATER AND HAVE BEEN DRAINED | Replace filter and unloader valve. Check, all ok | | | | | | | | | |
| | | | FT & RR AIR GAUGES 690 KPA RADIDLY GOING TO 810 KPA THEN | KWT224P CARTRIDGE AIR DRYER 1 Internal | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\AIR LEAK | SLOWLY FALLING THEN REPEATING EVERY 3.5 MINUTES | KW235 KIT-UNLOADER,AIRDRYER | 29/10/2025 | 566296 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | nspect, found RHS high beam flickering. Remove and replace light. Check operation, all ok. | | | | | | | | | |
| | | | CHECK ALL LIGHTS | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Elect\HEAD LIGHT | REPLACE RH LED HEAD LIGHT | KWP54-1326-1-002 12V/24V LED H-LIGHT HI 1 620.03KW1307-03 7' CHROME TRIM RING INC SCREW | 29/10/2025 | 566296 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | 2 08KWZZ0008 CHECK ADBLUE OP. | Lift cab, remove breathers, tube and fitting into tank. | | | | | | | | | |
| | | | Tech(s): | Unblock and reassemble. Loosen tank straps and reposition | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | 20238 162.50ADBLUE BREATHER BLOCKED AND TANK MOVED | tank and rubber strips. Tighten straps, all ok | 29/10/2025 | 566296 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Found when foot on brake air was leaking from service port. Inspect and found pot stuck. Did not have new port in stock, so fit a plug to stop air leak. Check for leaks, all ok | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Brakes\AIR LEAK | LH 2nd drive air leak | KW238807 HEX HEAD PLUG 3/8 | 20/10/2025 | 560836 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Inspect light and found to be working. Check all connectors | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Elect\HEAD LIGHT | R/H head light high beam not working | and wiring but unable to fault | 20/10/2025 | 560836 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | clutch needs adjusting has no free play | Inspect and adjust clutch to spec, check all ok | 20/10/2025 | 560836 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | VehService\B1 Svc B 1 Service, | | | | | | | | | | |
| | | | Jack up steer axle check bearings and king pins. | | | | | | | | | | |
| | | | Replace cabin filter. | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | L097314 | | 18/10/2025 | 560915 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Lift cab, remove breathers, tube and fitting into tank. Unblock and reassemble. Loosen tank straps and reposition | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | ADBLUE BREATHER BLOCKED AND TANK MOVED | tank and rubber strips. Tighten straps, all ok | 10/10/2025 | 541918 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | CHECK ALL LIGHTS Inspect, found RHS high beam flickering. Remove and replace light. Check operation, all ok. | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Elect\HEAD LIGHT | R/H HIGH BEAM NOT WORKING | KWP54-1326-1-002 12V/24V LED H-LIGHT HI 1 620.03KW1307-03 7' CHROME TRIM RING INC SCREW | 10/10/2025 | 541918 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Drain water from tanks, remove unloader valve and compressor line. Found to have a little bit of water. | | | | | | | | | |
| | | | TANKS ACCUMULATING WATER AND HAVE BEEN DRAINED | Replace filter and unloader valve. Check, all ok | | | | | | | | | |
| | | | FT & RR AIR GAUGES 690 KPA RADIDLY GOING TO 810 KPA THEN | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\AIR LEAK | SLOWLY FALLING THEN REPEATING EVERY 3.5 MINUTES | KWT224P CARTRIDGE AIR DRYER 1 203.64KW235 KIT-UNLOADER,AIRDRYER | 10/10/2025 | 541918 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | VehService\AS A Service | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\AS | L097036 | | 09/10/2025 | 535787 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | DriCabRepL | DIAGNOSE & REPLACE FAULTY WINDOW CONTROL. | | 04/10/2025 | 560836 | Completed | Mt Gambier | STK | XV13VU | JF MECHANICALS - 3 | P/MOVER | |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Both axles on front drive had worn s-cam bushes. Disconnect Air CTI lights and removed wheels. Removed brake drum and axle. Drained oil, removed bearings and put in parts washer. Remove brake shoes and disconnect slack adjuster. Removed s-cams, bushes and seals. Cleaned surfaces and installed new bushes and seals, installed new s-cams. Refit slack adjusters and brake linings. Removed wheel seals, cleaned surfaces and installed new wheel seals. Refit hub assembly, adjust wheel bearings to correct end float. Refit brake drums and wheels, refit axles. Connect air cti, tensioned wheels and adjust brakes.<br>KW2208S1215 GASKET 2 7.20<br>KW476975 SCOTSEAL 2 66.22<br>KWK1265808 KIT-CAM/BRACKET 3 193.86<br>KW815462 CAMSHAFT USE WITH WASHER P/NO 806380 1 310.74<br>KW815463 CAMSHAFT 1 217.39 | | | | | | | |
| 1050 | Myrtleford - Workshop | Brakes\BRAKE ADJ | Drive s-cams replaced next service<br>CHECK S-CAM MOVEMENT DONE ON 24/11/25 | KW316896 SPRING PACKAGE - BRAKE SPRING PACKAGE - | 05/09/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Steering\TIE ROD | Front right torque rod bushes (monitor) | Torque rod bushes all okay.<br>CHECK BY B/M 26/11/25 INVOICE Page 1 of 2 KWCT402484<br>582134 kms<br>1 0SKWZZZ102 ENGINE MOUNTS<br>Tech(s):<br>8101 8094 406.2SREPLACE REAR ENGINE MOUNTS<br>Remove mounting nuts. Remove and replace mounts as required. Tighten mounts all ok | 05/09/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\MOUNTS | Rear engine mounts replace next service<br>DONE ON 2/9/25 AT 535787KMS | KWD13-1001-4 BUSHING-REAR ENGINE BARRY 2 646.26KWK066-421 BUSHING SNUBBER BAR | 05/09/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\SWAYBAR | Front right sway bar bush (monitor)<br>CHECK BY B/M 26/11/25 INVOICE Page 1 of 2 KWCT402484<br>582134 kms | | 05/09/2025 | 581223 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 01/09/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | VehService\BS B Service<br>L096536 | GF B SERVICE<br>Carried out B service as per checklist | 30/08/2025 | 541918 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\AIR LEAK | Brakes\AIR LEAK | Air leak near air dryer possibly again<br>Removed dryer and completed overhaul. Did not fit filter screen. Refit dryer, found air leak at 45 degree fitting. Resealed and tightened to spec. Replaced governor valve and inspect signal lines and charge lines for internal damage, all looked ok. Check operation of dryer and recheck for any leaks at dryer, all ok | 26/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\MIRRORS | replace LHS mirror back cover due to damage from hitting tree | left hand mirror cover broken<br>Remove broken LH mirror cover and replace with new, all ok | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\FIFTH WHEE | Chassis\FIFTH WHEEL/TURNTABLE FOOT BUSHES | WORN TURNTABLE FOOT BUSHES<br>Unbolt pin stoppers, used air chisel to get pins out, but found them to be seized. Had to oxy out pins. Once pins out, lift top, put hydraulic ram in and pushes bushes out. Cleaned foot bush mounts out. Installed new bushes, dog bones and pin. Tensioned stoppers, all ok | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | Elect\ELECT P&W | CHECK ALL DASH LIGHTS<br>Found diff lights to not be working. Removed dash panel and removed globes. Fit new globes and check operation, all ok | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\SLACK ADJ | Brakes\SLACK ADJ | CHECK BRAKES - MISSING SLACK ADJUSTER PINS<br>Inspect where pin missing, install new pin and split pin | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\SHOCK ABS | Susp\SHOCKER NUT | LOOSE SHOCKER NUT ON REAR LEFT<br>LH rear shocker had a loose nut but was seized. Sprayed inox on nut and thread.. Replaced shocker bushes as were showing signs of wear | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\DAMAGE | DECK PLATE LOCKING FASTNERS BROKEN | REPLACE DECK PLATE LOCKS<br>Work order 199558<br>Removed plate and removed old locks. Adjust locks then place back onto chassis, check, all ok | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | FUEL TANKS NOT LEVELLING | FUEL TANKS NOT LEVELLING<br>Work order 199558<br>Inspect tank breathers, found RH breather was blocked. Clean out breather then check tank levels, all working ok | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Steering\STEER UNI | Steering\STEER UNI | REPLACE BOTTOM STEERING SHAFT UNI DUE TO MOVEMENT<br>Remove pin bolt from steering box and slip knot. Once removed pressed out old uni joint, then pressed in new uni joint. Tension all bolts to spec, all ok | 18/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service | | 07/08/2025 | 526021 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\AIR FITTIN | Re check tanks full of water remove bungs and drain | Re check tanks full of water remove bungs and drain<br>Built up air and inspect air tanks for moisture. Drained air system, removed drain plugs and ran truck to flush tanks. Reinstall drain plugs and recheck tanks. Removed deck plate and replace air dryer filter. Test air dryer, all ok. Reinstall deck plate | 05/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\AIR FITTIN | Air tanks full of water again air dryer gasket blown out | Driver called up and explained air tank drain lines were dragging on the ground. Inspect lines, and refit correctly so wouldn't drag. Driver also wanted to have air dryer compressor checked over. Inspect and didn't find anything wrong with air dryer. | 05/08/2025 | 530084 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP9+10 | Tyres\TP9+10 | | 04/08/2025 | 526021 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP7+8 | Tyres\TP7+8 | | 04/08/2025 | 526021 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP5+6 | Tyres\TP5+6 | | 04/08/2025 | 526021 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP11+12 | Tyres\TP11+12 | | 04/08/2025 | 526021 | Completed | Mt Gambier | STK | XV13VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\AIR LEAK | Engine\AIR LEAK | REPAIRS<br>✓ Repairs Carried Out:<br>Travel to PNR log yard. Inspect and found air dryer cork gasket had blown out due to loose bolts. Disconnect hoses and remove all bolts around middle of air dryer. Lift up dryer. Remove and replace gasket. Refit hoses and mount air dryer. Build up full air and check for leaks, all good. Return travel. | 01/08/2025 | 521453 | Completed | Mt Gambier | STK | XV13VU | COOKY'S DIESEL MECHANIC REPAIRS - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\AIR LEAK | Body\AIR LEAK | REPAIRS AS PER ATTACHED INVOICE | 26/07/2025 | 526021 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\EBS FAULTS | Test EBS | Tested EBS.<br>Turned ignition on and all warning lights illuminated including ESC.<br>Started truck and all light turned off. As they should<br>Turned on off road switch and ESC and ABS warning lights flashed to indicated they were turned off. As they should turned off off road switch and lights turned off. As they should. | 24/07/2025 | 526021 | Unlocked | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and king pins.<br>Replace cabin filter. | | 18/07/2025 | 519571 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1050 | Myrtleford - Workshop | Brakes\BRAKE ADJ | Brakes\BRAKE ADJ | CHECK BRAKES CHANGE SPRING IN RELAY VALVE<br>Truck returned with brakes still not correctly performing in. Connect air gauges to truck and trailer. Carry out numerous tests checking air flow to trailer, road test and check temps on wheels on truck and trailers and record readings. Brake roller test complete unit and to diagnose brake issue. Found brakes performed better with EBS disconnected, Inspect EBS plugs on truck and found corroded and incorrect voltage getting to trailer. Fit spring in relay valve on the truck to give the trailers more air pressure. Remove and replace TPS valve on truck, road test and check brake temps and pressures, still not performing as it should. Liase with Elphinstone and suggested to remove files from EBS modules for them to inspect. Found when attempting to connect to trailer could not connect to EBS computers in trailer. (repairs carried out on trailers to power up modules) so we could extract the files. Elphinstone said poor voltage to trailers. After repairs carried out on trailers numerous brake roller tests and road test checking heat and pressures. | 16/07/2025 | 516049 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\MOUNTS | check front & rear engine mounts (all ok in serviceable condition)<br>519571 kms | 1 05KWZZZ102 ENGINE MOUNTS<br>Tech(s):<br>8050 0.00FRONT & REAR ENG MOUNTS WORN<br>Work order # 198319<br>Inspect front and rear engine mounts, found to be in a serviceable condition<br><<< Total For Job 1 >>> | 14/07/2025 | 521149 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\REFLECTORS | L/H REAR REFLECTOR | LH REAR REFLECTOR<br>Work order 198319<br>Remove and replaced reflectors where missing. | 14/07/2025 | 521149 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\AIR DRYER | replace air dryer for rebuilt one | INSPECT AIR DRYER FOR LEAKS, REPAIR AS REQUIRED<br>REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU02472<br>Test air dryer, found to continually be going off. Remove old air dryer, swap fittings to new rebuilt air dryer. Fit new silencer. Test, no more leaking. | 17/06/2025 | 515279 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\AIR TANKS | CHECK AIR COMP - TRUCK NOT BUILDING AIR @ GREENFREIGHT YARD | Travelled to Green freight yard, check truck for any obvious leaks. Charge line for any leaks, unable to find anything. Remove charge line from compressor, found little to no air coming out. Topped the head where the piston sits and freed the pistons. Air pumping as per normal. Connected lines and built up pressure, all ok. Compressor will need replacement.<br>< | 14/06/2025 | 512725 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | ADBLUE TANK BLOCKED<br>Inspect tank, found breather to be blocked. Removed pick up and washed ad blue out of system. Refit and connected hoses, all ok | 12/06/2025 | 510195 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service | Carry out service as per Greenfreight checklist<br>CARRY OUT ANNUAL INSPECTION AS PER CHECKLIST<br>ENGINE MOUNTS FRONT AND REAR WORN | 05/06/2025 | 510195 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Insp\ANN INSP | Insp\ANN INSP | L/H REAR REFLECTOR<br>Rear RH drive brake booster leaking badly at tarps mill | 05/06/2025 | 510195 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\BOOSTER | Brakes\BOOSTER | Travelled to truck in Tarpeena. Removed and replaced broken brake booster. Adjusted brake, all ok | 04/06/2025 | 513545 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\ROTATION | Tyres\ROTATION | | 27/05/2025 | 501914 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\BRAKE ADJ | ADJUST ALL BRAKES ON TRUCK AND TRAILER | ADJUST ALL BRAKES ON TRUCK AND TRAILER<br>Inspected and found brakes on trailer to be out of adjustment, adjusted all 3 trailer brakes. | 23/05/2025 | 504353 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | AFTER TREATMENT LIGHT ON | AFTER TREATMENT LIGHT ON<br>Plugged in cummins computer and check codes. Code for loss of prime in the doser. Attempted to flush doser, unable to flush would not complete click test. Follow trouble shooting, lead to faulty doser. Remove and replace doser, connected all lines, ran doser override test a few times to get ad blue through system. All measured ok and faults went inactive | 23/05/2025 | 504353 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\CS | VehService\CS | | 19/05/2025 | 499765 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\FITMENT | Tyres\FITMENT RESEAL AND REFIT POS 9 | | 12/05/2025 | 496548 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\BRK RELINE | CHECK BRAKES STILL MAKING GRINDING NOISE INSEPCT DRIVE<br>BRAKES FOR STEER HAS BEEN REPLACED | Jacked up 4 drive wheels, removed air CTI lines and removed all 4 wheels and drums. Check linings and drums, found drums to all be unserviceable. Removed and replaced all 4 drums and linings. Refit all CTI lines and adjusted brakes, also adjusted trailer brakes. Test drove, all ok | 08/05/2025 | 498540 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service | | 27/04/2025 | 492073 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\BRK O/HAUL | Brakes\BRK O/HAUL | CHECK BRAKES SHUDDER/GRINDING NOISE FROM STEER BRAKES<br>CHECK ADJUSTMENT ON ALL<br>Adjusted all brakes and took for a drive. Found brakes still shuddering. Jacked up the steer and removed wheels and drums. Found brakes glazed. Scuffed the linings and drums, put all back together. Tensioned and adjusted wheels. Take for a test drive, all okay. Driver to monitor. Brakes still shuddering.<br>Jack up and support steer axle. Removed wheels, removed brake drums and brakes. Fit new shoes and drums. Reinstalled wheels. Removed jack and supports. Tensioned wheels and adjusted brakes. | 27/04/2025 | 493056 | Completed | Mt Gambier | STK | XV13VU | PACCAR PARTS FLEET SERVICES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\DAMAGE | gear stick boot split | Removed top half of gear stick, removed all floor panels and mount for gear stick boot. Removed old split gear stick boot. Fit new gear stick boot, and aligned mounting plate, tightened mounting bolts to spec. Reassembled floor panels and gear stick, all ok. | 16/04/2025 | 492073 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\AIR CON | Heater not working | REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563<br>Inspected heater taps, found 1 tap was turned off. Turned ack on and checked operation, all okay | 16/04/2025 | 492073 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\MUDGUARDS | Body\MUDGUARDS | SUPPLY GUARD MOUNTS | 09/04/2025 | 484642 | Completed | Mt Gambier | STK | XV13VU | ELPHINSTONE ENGINEERING - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | VehService\BS | | 01/04/2025 | 481142 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\SHOCK ABS | Susp\SHOCK ABS | rear RH shocker loose<br>Found shocker had worn bushes. Removed bushes and replaced with new. Fit new nut and washer, tensioned bolts. | 01/04/2025 | 481142 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Steering\UNI JOINTS | Steering\UNI JOINTS | CHECK OVER BALL JOINTS - POSSIBLE MOVEMENT<br>Both ball joints worn on drag link. Removed spit pins, hit out drag link, measured, adjusted end so it was correct length. Installed new drag link and tensioned to spec, all okay | 01/04/2025 | 481142 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\HCV | Susp\HCV | Rose joint rods worn<br>Removed the two ride height rods. Replaced worn rose joints. Set ride height to correct length, all okay | 01/04/2025 | 481142 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | ADblue breather blocked<br>Found ad blue breather blocked. Washed out breather and unblocked, all okay. | 01/04/2025 | 481142 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\ELECT P&W | DriCabRep\ELECT P&W | CHECK AND REPLACE DASH LIGHTS<br>Removed dash panel, replaced blown globes for oil temp and front air gauges. Tested, all okay. refit dash panel. | 14/03/2025 | 470217 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | CHECK BELTS<br>Found both A/C and engine fan belts were worn. Removed both | | | | | | | | |
| 1050 | Myrtleford - Workshop | Air Con | Air Con | belts and checked tensioners. All okay, installed new<br>belts, adjusted to spec | 14/03/2025 | 470217 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| | | | | Adblue leaking<br>Cleaned off leaking ad blue to locate source of leak. Found<br>inlet to doser module was not clipped in. Clip was faulty.<br>Removed clip and sourced new, installed and cleaned area, | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | no further faults | 14/03/2025 | 470217 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 06/03/2025 | 470217 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | | LOAD TEST AND CHECK BATTERIES<br>Load tested batteries, found all four batteries had failed.<br>Removed batteries and installed new. Cleaned terminals and | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\BATTERY | Engine\BATTERY | refit cover | 18/02/2025 | 463030 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\FITMENT | Tyres\FITTING 1-2 | | 18/02/2025 | 463664 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | VehService\B1 Svc | | 11/02/2025 | 458949 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\RADIO | REPLACE BROKEN MTDATA ARIAL | REPALCE BROKENMTDATA ARIAL ON TRUCK 1050<br>Tested air CTI system, could not fault. Lifted cab and | 05/02/2025 | 458656 | Completed | Mt Gambier | STK | XV13VU | BROWNYS MOBILE AUTO ELECT - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CTI Drive | CTI playing up | removed CTI box cover, all okay<br>Connect laptop and checked faults, found code for exhaust<br>fluid pressure. Checked filler cap. and breather, all okay.<br>Checked return and supply lines. Removed pick up and<br>inspected, all okay. Attempt to carry out doser pump flush,<br>no good. Suspect blockage in pump. Liase with cummins and<br>carry out further diagnostic testing. Got pump unblocked<br>and flushed with warm water. Carry out doser overide test | 04/02/2025 | 458949 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | ad blue filter needs relocating out of the dust | and ensure injec<br>Mark and drilled holes in seat base. Mounted new bracket | 04/02/2025 | 458949 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\SCALES | Elphinstone handheld locating bracket needs fixing. | and fit remote.<br>Attended GF yard and inspected truck. Driver advised the<br>governor line was leaking. Found the governor valve to be<br>constantly exhausting. Removed the airlines & governor<br>valve. Scraped existing gasket off, cleaned down and fit<br>new gasket and governor valve in place. Re fit air lines & | 04/02/2025 | 458949 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\AIR LEAK | airline from governor leaking | tested operation. All working fine, no further leaks.<br>CARRY OUT CLUTCH ADJUSTMENT | 16/01/2025 | 451643 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | DrivLine\CLUTCH | Carried out clutch adjustment as required, all okay.<br>RH HEAD LIGHT COVER MISSING<br>Work order 192601<br>On inspection found RH headlight cover was missing. Removed | 16/01/2025 | 450783 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\LIGHTS | rhs headlight cover missing | bolts on headlight, fit new cover & fit new bolts, secured.<br>AD BLUE TANK STRAPS RUBBING ON TANK<br>Work order 192601<br>Inspected & found tank straps were loose and rubber had<br>started to slip away. Removed tank strap and repositioned | 16/01/2025 | 450783 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | ad blue tank straps need fixing -tank rubbing | rubber. Refit strap and tensioned bolts.<br>REPLACE DASH GLOBES - DIFF TEMP & ENGINE OIL TEMP<br>On inspection found multiple dash globe to be out. Removed<br>dash & tested power at holder. Correct power found. Fit new<br>globes & checked operation. Not working. After testing,<br>found globe holder faulty. Replaced with new and re tested<br>operation. All ok. Also replaced globes for oil pressure & | 16/01/2025 | 450783 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | engine oil pressure guage light not working | oil temp. Refit dash and secured.<br>REPLACE RH REAR BRAKE<br>Work order 192601<br>Both rear brakes were past wear limit. Jacked axle and<br>removed CTI lines & plugged. Removed<br>wheels. Drums were stuck due to ripples, but eventually<br>removed them. Removed brake assembly. Fit new brake<br>assembly's, followed by drums & wheels. Tensioned wheels | 16/01/2025 | 450783 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\R.R.R | R/H rear brake requires replacement next service | and refit CTI lines back on<br>REPLACE WORN TURNTABLE BUSHES<br>Work order 192601<br>Removed foot pins. Flipped turntable over, cut foot bushes<br>& pushed them out. Pushed new bushes in. Flipped turntable | 16/01/2025 | 450783 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\FIFTH WHEE | Turn table bushes getting low replace next service | back over. Fit new pins in & secured. | 16/01/2025 | 450783 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 14/01/2025 | 449911 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\SHOCK ABS | front shockys bottoming out | Inspect steer axle shockers, found both had worn rubbers<br>and were unserviceable. Unbolt and removed shockers. Found<br>top RH stud has stripped thread. No new studs available.<br>Repair with thread file and installed new shockers,<br>tensioned bolts | 28/12/2024 | 437911 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\BATTERY | Engine\BATTERY | Flat batteries at yard<br>Attended GF yard, jump started truck due to flat batteries | 20/12/2024 | 446887 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 13/12/2024 | 444983 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | CHECK AFTER TREATMENT LIGHT ON DASH | Connected PC to truck & checked for codes Found active<br>codes for ad blue pressure too high. Unbolted bullbar and<br>tilted cab. Removed ad blue injector and attempted to<br>perform override test but unable to complete. Carried out<br>air solenoid click test as solenoid was stuck open. Removed<br>ad blue tank cap and found it was pressurised. Removed ad<br>blue level sensor & cleaned breather port. Replaced<br>breather filter. Re attempted to carry out the override<br>test and completed successfully. Refit ad blue injector and<br>lowered cab, secured bull bar | 12/12/2024 | 444983 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | VehService\BS | Carried out B service as per Greenfreight checklist. All ok<br>Customer Instructions:<br>Completed paperwork & Cleaned area<br>TOOK ENGINE OIL SAMPLE & ECU DOWNLOAD<br>TRUCK BROKEN DOWN ON GLENELG RIVER RD - WONT BUILD UP AIR<br>CANT HEAR ANY AIR LEAKS. BACK TANKKS EMPTY, FRONT AT 400 AND<br>WONT BUILD UP ANY MORE<br>Glenelg river rd / Caveton<br>Channel 16<br>Tim - 0429 545 070<br>Travel to truck broken down, unable to build up air. Found<br>air tank fitting had broken off. Use easy out to remove<br>fitting, cleaned up threads and installed new. Checked | 28/11/2024 | 439833 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\AIR FITTIN | Body\AIR FITTIN | over, no further leaks. | 13/11/2024 | 431911 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 08/11/2024 | 429085 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\SCALES | Chassis\SCALES | FIT REMOTE FOR SCALES<br>Fit transmitter to rear of truck and run cable to dash<br>along chassis. Secured wiring. Connect to head unit. Found<br>head unit was not operating correctly, no voltage coming<br>out to run transmitter. need to replace head unit | 07/11/2024 | 429470 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\ELECT P&W | cruise control light not working | Removed dash panel, replaced blown globe for cruse control.<br>Refit dash panel.<br>Repair engine oil leak from oil fill pipe<br>Removed drivers side filler tube. Cleaned mount flange.<br>Remove & replaced silicone hose & replaced clamps. Cleaned | 01/11/2024 | 429085 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\OIL LEAK | Engine\OIL LEAK | & re installed filler tube. Tested , all ok | 01/11/2024 | 428227 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 29/10/2024 | 409725 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1050 | Myrtleford - Workshop | Susp\AIR LEAK | Check operation of Air cti bringing up faults | Inspected operation range of system with no issues found. Opened control box and inspected, all looks ok. Traced wiring & found no issues. Monitored operation for a period of time with nothing faulting. Driver required truck so will need to monitor for further issues. | 24/10/2024 | 424672 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\OIL LEAK | Check major engine oil leak at yard | Attended truck at GF yard with tools & oil. Inspected & assessed leak, determined it was coming from the base of oil fill tube. Tightened hose clamps & bolts holding the tube to block. Topped up with 5L of oil. Advised driver to monitor for continued leak. May require new gasket. | 23/10/2024 | 424672 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Chassis\MUDGUARDS | REPAIR MUD GUARD ON TRUCK | Cut zip ties holding guard in place. Removed broken bolt & replaced with new, fit nut & tighten. Fit guard pole & nut then tighten. All ok | 23/10/2024 | 424672 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\ROTATION | Tyres\ROTATION<br>1 + 2 turn on rim | | 18/10/2024 | 422845 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | CHECK EXHAUST SYSTEM CRACKED AGAIN AND LEAKING ADBLUE<br>Found system had excess ad blue at exhaust pipe. Poured hot water over & removed with chisel & hammer. Removed hose clamps & mounting bracket. Cleaned off excess ad blue and welding. Tack along weld and then grind back. Fit exhaust back to truck with new gasket & clamp. Tighten all bolts to spec. All ok<br>Removed pipe and fit new pipe and gaskets. Fit new clamp, checked all secure | 18/10/2024 | 421548 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | ADBLUE TANK BREATHER BLOCKED AND TANK MOVED<br>Unbolt tank straps and jack up tank. Refit tank rubber and move tank back in correct position. Tightened straps. Removed ad blue level sensor and flushed with hot water. Blow out breather pipe. Refit all components, all okay.<br>CARRY OUT CLUTCH ADJUSTMENT | 18/10/2024 | 421548 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | DrivLine\CLUTCH | Carried out clutch adjustment as required | 18/10/2024 | 421548 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | B 1 Service | | 16/10/2024 | 420327 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\SEAT | drivers seat goes up & down when sitting still. Air leak ?? | | 30/09/2024 | 413698 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | no clutch brake | Carried out clutch adjustment as required. Adjusted free-play to specification. All ok. | 28/09/2024 | 411609 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | Adblue leak at exhaust and tank sucking in<br>On inspection found a crack in weld on exhaust. Unbolted exhaust at clamp, unbolted the mount and removed exhaust. Cleaned prepped the area and welded the cracked section. Re fit the exhaust to truck and tested operation. All ok | 28/09/2024 | 411609 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\FAULT CODE | Engine\FAULT CODE | ENGINE LIGHT ON<br>Travelled to truck broken down at Glencoe turnoff. Connect laptop and checked faults, found water in fuel fault. Driver also mentioned oil pressure light was fading in and out. Checked oil level, found level to be low but still in range. Drained fuel bowl, found only to have diesel present, no water. Started truck and data monitored, truck showed plently of oil pressure on data monitor. Advised driver to get unloaded and return to BMG workshop for further inspection. Truck arrived at workshop, jacked cab over and inspect wiring for water in fuel sensor. Found WIF wire rubbed on chassis earth. Cut out and repaired wires. Code now changed to inactive, cleared codes. Topped up oil level and rechecked oil pressure on laptop. All okay. Advised driver to monitor oil pressure light for refaulting | 24/09/2024 | 409720 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | rear lights flickering | | 19/09/2024 | 409720 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | Check & Repair Adblue Leak. (Barry Maney P/O: L088461) | AD BLUE LEAK<br>Inspected piping & found rubbed line. Fit new joiner and covered hose in conduit. Needed to order new hose. Part ordered. Removed & replaced ad blue supply hose, secured with cable ties. All ok. | 31/08/2024 | 400753 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Left spring pressure light not working. (Barry Maney P/O: L088461) | CHECK DASH LIGHTS<br>Removed dash panel, inspected & found globe to be blown. Removed & replaced globe & globe holder. Tested operation. All ok.<br>ENGINE BRAKE N/W | 31/08/2024 | 400753 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\JAKE BRAKE | engine brake not working properly. (Barry Maney P/O: L088461) | Remove rocker cover. Checked wiring to all engine brake solenoids, all okay. Carried out complete engine tune up, including engine brake solenoids. Engine brakes all within spec. Replaced rocker cover gasket and road test. All working okay.<br>TURBO BOOST LIGHT N/W<br>LEFT SPRING PRESSURE LIGHT N/W | 31/08/2024 | 400753 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Turbo boost light not working. (Barry Maney P/O: L088461) | Removed dash panels, replaced blown globes as required. Refit dash. | 31/08/2024 | 400753 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 27/08/2024 | 399326 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\TRANS OIL | Transmission Oil Change | | 27/08/2024 | 399160 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\CS | VehService\CS | | 27/08/2024 | 399160 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\DIFF OIL | Diff Oil Change | | 27/08/2024 | 399160 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\WIPERS | Wipers Won't Turn Off. (Barry Maney P/O: L088246) | CHECK WIPERS WON'T TURN OFF;<br>Travelled to yard and inspected for fault. Found switch was broken. Removed steering wheel covers and removed stalk. Installed new stalk and connected wiring, tested operation. all okay. | 20/08/2024 | 396422 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\HEAD LIGHT | L/H Low Beam Not Working (Barry Maney P/O: L088171) | L/H Low Beam N/W;<br>Inspected wiring behind L/H low beam light & checked fuses in battery box. Tested power, found light N/W. Removed and replaced light. All ok | 14/08/2024 | 392955 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 09/08/2024 | 390325 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP01 | Tyres\TP01 | | 09/08/2024 | 387598 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | 31/07/2024 | 387598 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP9+10 | Tyres\TP9+10 | | 31/07/2024 | 387598 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP5+6 | Tyres\TP5+6 | | 31/07/2024 | 387598 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP7+8 | Tyres\TP7+8 | | 31/07/2024 | 387598 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\SEAT | DriCabRep\SEAT( FIT NEW SEAT COVER) | | 25/07/2024 | 383323 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| | | | CHECK AIR CONDITIONING OPERATION NOT COLD<br>REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563<br>Connect A/C equipment and check gas levels, found to be low on gas. Recovered remaining gas and test for leaks. Found condensor was leaking. Sourced new condensor and receiver drier. New condensor is bigger and needed modifications to suit. Removed covers from radiator, drill out holes to mount condensor, refit coverts and mount bolts. Reconnect all lines, replaced receiver drier. Vac down system and charge with new gas. Tested, all okay.<br>KW55304128 CONDENSOR 1 688.72<br>KWM200-70EP BUSHING-RADIATOR 6 198.00<br>KWK251-571 FILTER-FREON, RECEIVER/DRYER 1 124.39<br>POL | | | | | | | | | |
| 1050 | Myrtleford - Workshop | Air Con\AIR CON | AIRCONDITIONING GAS R134A | | 25/07/2024 | 383323 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 23/07/2024 | 383323 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 23/07/2024 | 383323 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 21/07/2024 | 383323 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ENG FAN | RECO HORTON FAN WITH OUTBACK KIT | | 04/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ENG TUNE | Engine\ENG TUNE & REPLACE ROCKER SHARFTS (OUT OF EXTENED ENGINE WARRANTY) | | 04/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\CONSUMABLE | engine brake light on dash not working | | 04/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1050 | Myrtleford - Workshop | Elect\INDICATORS | right front indicator on cab has water in it | | 04/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\CONSUMABLE | engine water temp gauge light not working | | 04/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\BRAKE ADJ | Brakes\BRAKE ADJ | CHECK BRAKES TRAILER BRAKES SLOW TO RELEASE<br>Found breathers for brake valves to be blocked, cleaned out<br>and refitted. Retested, all okay. | 02/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\INDICATORS | Elect\INDICATORS | Right front indicator n/w<br>RHF indicator was dull, inspect and found to be full of<br>water. Removed light and replaced with new.<br>Engine water temp light n/w<br>Engine brake light n/w<br>Remove dash cluster, replaced blown globes as required. | 02/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | Elect\ELECT P&W | Refit dash. | 02/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | A Service<br>Engine\ENG REBLD kms 368730 ENGINE WAS DUSTED BY BARREY MANEY<br>FIT NEW HEAD TURBO AIR COMPRESSOR LINERS & PISTONS & RINGS BIG ENDS & MAIN BEARINGS REPAIR OIL LEAK & CLEAN | | 01/07/2024 | 371646 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ENG REBLD | INTERCOOLER &CHANGE OIL & FILTERS (NO CHARGE TO G/G)<br>TURBO TEMP GAUGE FLUCTUATING & HR METER | | 19/06/2024 | 370179 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | CRUISE CONTROL LIGHT N/W<br>TURBO TEMP GAUGE FLUCTUATING & HR METER<br>CRUISE CONTROL LIGHT N/W | Found wiring was rubbed through up to sensor. Replaced sensor & wiring, checked over & tested operation of gauge, all okay<br>Found wiring was rubbed through up to sensor. Replaced sensor & wiring, checked over & tested operation of gauge, all<br>okay. Checked hour meter, not able to be reset, it will need to be replaced.<br>Replaced blown globe<br>Removed bottom kick panel & found what one was leaking. Removed both terminals and fitting - replaced fittings & | 02/06/2024 | 366853 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | AIR LEAK BEHIND DASH WITH SERVICE BRAKE APPLIED | connected terminals. | 02/06/2024 | 363945 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\AIR LEAK | AIR LEAK BEHIND DASH WITH SERVICE BRAKE APPLIED | Removed bottom kick panel & found what one was leaking. Removed both terminals and fitting - replaced fittings & connecti | 02/06/2024 | 366853 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Insp\ANN INSP | Annual Inspection PO # L086450<br>B Service PO # L086446 | | 02/06/2024 | 363945 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | SERVICE KMS 362838 | | 02/06/2024 | 368724 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CTCH PACK | replace clutch pack replacement | | 01/06/2024 | 363945 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\HOUSEKEEP | TEST ENGINE BLOW BY (ENGINE HAS BEEN DUSTED) | | 31/05/2024 | 359197 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | SCALES PLUG DAMAGED | Removed squashed scales plug. Installed new plug as supplied by GF. Joined wiring and connect plugs, test operation, all oka | 31/05/2024 | 359197 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | CLUTCH NEEDS FREE PLAY - Carried out clutch adjustment as required. | | 27/05/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | PACCAR PARTS FLEET SERVICES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2<br>Carry out A Service as per job card for T909 X15 | | 22/05/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | BEAUREPAIRES - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | PO# L085802 | | 10/05/2024 | 351398 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | CRUISE CONTROL LIGHT NOT WORKING. | | 10/05/2024 | 351398 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | EHC METER NOT WORKING. STUCK ON 9999.9. | | 10/05/2024 | 351398 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 10/05/2024 | 351398 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\SUSPENSION | LOUD BANGING WHEN TAKE OFF LOADED- REPORT LAST TIME. THE TRUCK IS ON A LEAN TO ONE SIDE LOOKING AT FRONT ON WHEN LO<br>remove & replace worn spring shackle bush - Lowered bull bar and flipped cab. Removed oil cooler,<br>jacked front of truck and supported chassis. Removed steer wheels, & battery box. Inspected all<br>shackle pins & bushes. Found LH rear was unserviceable. Removed U-bolts, rear shackle pin bolts,<br>shackles, front pin bolts & pins. Removed LH spring. Grind out welds for bushes & removed bushes.<br>Cleaned eyes of spring and mounting surface. Installed new bushes to spring and weld in position.<br>Reinstalled spring, installed new pins, reinstalled u-bolts & battery box. Reinstalled wheels, oil cooler | | 10/05/2024 | 351398 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Steering\SUSPENSION | jacked & removed supports, tensioned wheels and U-bolts. Greased shackle pins, all ok. | | 01/05/2024 | 346804 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 24/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\Torque Rod | CHECK FRONT SUSPENSION - Inspect suspension, found LH spring eye bush was worn. *Needs to<br>ALTERNATOR LIGHT ON DASH - Tested alternator & found to be unserviceable. Remove & replaced | | 14/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ALT2 DR | alternator. Changed over pulley & repaired bolt holes where required. Tested operation, all okay. | | 14/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\RADIO | BOTTOM UHF INTERFERES WITH THE SCALES IF USED. | | 14/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\RADIO | TOP UHF HAS A RANGE OF A FEW HUNDREDS METRES. | | 14/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist<br>**MINI B-SERVICE** | | 14/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | PO# L085260 | | 14/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\FITMENT | 1-2 | | 06/04/2024 | 339257 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | NO FREE PLAY IN CLUTCH PEDAL. | ADJUST CLUTCH - carried out clutch adjustment to spec. | 24/03/2024 | 330813 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp | LHS FRONT CLUNKING IF THROTTLE IS APPAUD HEAVY THEN RELEASED. | CHECK FOR CLICKING NOISE LH FRONT - Inspect steering components, all okay. Jacked axle &<br>inspected king pins, all okay. Inspected spring bushes, all okay. Driver to monitor. | 24/03/2024 | 330813 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\ADBLUE | A B TANK - WHEN CAP REMOVED PRESSURE IS RELEASED AND TANK ACTUAL POPS.<br>Carry out A Service as per job card for T909 X15 | ADBLUE TANK BLOCKED - removed ad blue breather and blow out. Removed pump & flushed with<br>hot water to clear breather. Reinstalled pump, all ok. | 24/03/2024 | 330813 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | PO# L084900 | | 23/03/2024 | 370179 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 23/03/2024 | 370179 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\AIR LEAK | REPAIR AIR LEAK - Received phone call, head into workshop. Wait for truck to arrive, once arrived<br>removed deck plate. found air line rubbed got half inch push in joiner from work ute cut rubbed section<br>out, fit joiner and check for leaks all okay. Re secure air lines to prevent further rub. Re fit deck plate | | 20/03/2024 | 323980 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\BELTS/TENS | REPLACE FAN BELT - Inspected belts, found belt to be worn. Replaced fan belt - all ok. | | 10/03/2024 | 369177 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | FIT 12V PLUG WITH 20A FUSE - Fit second plug on on LH side of seat, wire into fuse box & run<br>wiring, mount accessory socket to seat. Check operation all okay. | TRUCK BLOWING FUSES - Checked over all wiring for any obvious faults - couldn't fault. Checked<br>operation of jakes and found they were working fine. Further inspection found dash light out, replaced<br>and tested - all ok. | 10/03/2024 | 369177 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\GEARBOX | UNABLE TO SELECT GEARS - Moved truck over pit, removed cover and inspect bell housing with<br>magnet. No metal debris present. Carried out second clutch adjustment,selecting gears okay. If truck<br>faults again, clutch will need replacing. Eaton rep also inspected and recommend replacing clutch.<br>INSPECT CLUTCH - Had trouble getting gears after road test, check clutch brake adjustment. Clutch<br>Clutch adjustment okay, inspect clutch brake & found not stopping when trying to select gears, clutch<br>brake very worn. Removed deck plate, disconnect air lines. Removed gear stick tower, undo p clamps<br>& cut cable ties. Unbolt & removed tail shaft. Removed all lines to gear box, undo rear support & bell<br>housing bolts. Slide gear box back until input shaft was out. Replaced clutch brake. Pushed gear box<br>back in and tensioned bell housing bolts. Replaced bushes on rear support bar. Refit all components | | 06/03/2024 | 323980 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | previously removed. Secured all lines. Take truck for a test drive, adjusted clutch, all okay. | | 24/02/2024 | 320207 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | MAIN TEMP TRANS LIGHT NOT WORKING. | SPEEDO & TACHO LIGHTS KEEPS BLOWING FUSES - Turned lights and ignition on, fit new fuse,<br>blew straight away. Removed dash and relay panels, traced wiring through loom & locate rubbed<br>section in rear of head unit. Repaired section of wires, secured with silicone hose, Refit all panels,<br>replaced relay. No further faults. | 24/02/2024 | 320448 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Comp | SPEED LIMIT CERTIFICATE - Carried out speed limiter check as required.<br>DASH LIGHTS - Removed dash and radio panels. Removed blown globes & replaced with new. | | 22/02/2024 | 320193 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | Refit panels, all okay.<br>Service As Per Attached Checklist | AFTER TREATMENT LIGHT ON - Connect laptop and check faults, found no faults in system for<br>after treatment. Cleared past inactive codes, tested, all okay. | 22/02/2024 | 320193 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | PO# L084044 | | 18/02/2024 | 322608 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 18/02/2024 | 322608 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 09/02/2024 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\BATTERY | CHECK BATTERIES.refer entry 183345 job 430488 2 batteries were replaced on 3/2/24. CHECK BATTERIES.<br>Carry out A Service as per job card for T909 X15 | | 04/02/2024 | 312018 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | PO# L083749 | | 04/02/2024 | 312018 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 04/02/2024 | 312018 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | ADJUST CLUTCH - carried out clutch adjustment to spec.<br>TRAILER ABS LIGHT ON - Truck has ABS light on, connect to truck to locate fault. Remove B trailer<br>plug & cleaned out corrosion. Attempt to connect to trailer, would not connect. Checked all other<br>plugs along truck & cleaned out debris and corrosion. Checked power at EBS lead coming out of truck,<br>all okay. Checked power at plug after slide section on A trailer, no power. needs further diagnosis due | | 04/02/2024 | 312018 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | to time constraints. | | 04/02/2024 | 312018 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\BATTERY | CHECK BATTERIES -Load test and check batteries. Two bottom batteries failed test. Remove &<br>replaced with new. Connect terminals & checked operation, all okay. | | 04/02/2024 | 312018 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Engine\BATTERY | AFTER HRS BREAKDOWN - JUMP START<br>Travelled to Greenfreight yard, connect jumper pack & jump started truck. Checked charging okay,<br>return to workshop. | | 09/01/2024 | 300134 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\GPS | I need a technician to repair an issue with "No Internet Connection" to the following unit ASAP | | 03/01/2024 | 370179 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\WIPERS | REPLACE WIPER BLADES - Supply and fit new wiper blades. | | 23/12/2023 | 299284 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | BREATH ON FUEL TANK "LEFT" NOT WORKING. "NOTY DRAINING TO THE RIGHT TANK" | | 23/12/2023 | 299284 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | CLUTCH ADJUSTMENT. | ADJUST CLUTCH - carried out clutch adjustment to spec, all okay. | 23/12/2023 | 299284 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | FUEL TANK BREATHER NOT WORKING, FUEL ISN'T TRANSFERING FROM ONE TANK TO THE OTHER. | LH BREATHER NOT WORKING & NOT DRAINING TO RH TANK - inspect breather on fuel tank,<br>found hose was blocked. Disconnect hose, flushed & unblocked. Checked cross over hose, fuel<br>reaching both tanks. | 23/12/2023 | 299284 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Service As Per Attached Checklist<br>**MINI B SERVICE** | | | | | | | | | | |
| 1050 | Myrtleford - Workshop | VehService\BS | PO# L083119 | | 23/12/2023 | 299284 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 23/12/2023 | 299284 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\FITMENT | 1-2<br>Service As Per Attached Checklist | | 05/12/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\AS | order number - L082429 | | 26/11/2023 | 289632 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 26/11/2023 | 289632 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| | | | | Inspect fault for drive airbags going flat. Found air leak in<br>overhead console. Removed console & inspect wiring, found transducers for air weigh scales leaking. | | | | | | | | | |
| 1050 | Myrtleford - Workshop | DriCabRep\AIR LEAK | AIR LEAK IN SCALES BEHIND DASH | Ordered parts. Removed air sensors & replaced with new, secured new air lines. | 22/11/2023 | 279730 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | FUEL GAUGE LIGHT NOT WORKING. Done on B service refer invoice 371461. FUEL GAUGE LIGHT NOT WORKING.<br>Service As Per Attached Checklist | | 02/11/2023 | 279697 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\BS | PO# L082021 | | 02/11/2023 | 279697 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 02/11/2023 | 279697 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Wodonga - Workshop | VehService\AS | Service As Per Attached Checklist | | 27/10/2023 | 272850 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 27/10/2023 | 272850 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | DASH LIGHTS OUT - Removed dash panel, replaced blown globes as required. Checked, all working<br>okay. Refit dash. | | 27/10/2023 | 277940 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Chassis\SCALES | Test 490 loadcells | | 26/10/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 20/10/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | Insp\END WARR | END OF WARRANTY ISNPECTION AND REPAIRS<br>BARRY MANEY PO# NOT REQUIRED<br>Carry out A Service as per job card for T909 X15 | | 09/10/2023 | 370179 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L081431 | | 04/10/2023 | 269903 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 04/10/2023 | 269903 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\TP5+6 | Tyre Position 5 + 6 | | 04/10/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\TP3+4 | Tyre Position 3 + 4<br>B 1 Service,<br>Jack up steer axle check bearings and king pins.<br>Replace cabin filter. | | 04/10/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | BARRY MANEY PO# L080873 | | 08/09/2023 | 259258 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\TP9+10 | Tyre Position 9 + 10 | | 08/09/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\TP7+8 | Tyre Position 7 + 8 | | 08/09/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | Body\PANELS | CHECKER PLATE ON THE BACK OF THE CHASSIS SLIDE BACK, APPEARS TO HAVE 2 BOLTS MISSING.<br>CHECK FRONT SUSPENSION. LEANS TO THE RIGHT. | MISSING BOLTS ON CHECKER PLATE - Supply and fit new bolts where missing. Tightened all bolts | 07/09/2023 | 370179 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | Susp\SUSPENSION | PLEASE PROVIDE A QUOTE BEFORE REPAIRS COMMENCE. CHECK FRONT SUSPENSION. LEANS TO THE RIGHT.<br>Carry out A Service as per job card for T909 X15 | | 07/09/2023 | 370179 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L080352 | | 18/08/2023 | 250666 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | DASH LIGHTS OUT. | | 18/08/2023 | 250666 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 18/08/2023 | 250666 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\BS | Barry Maney PO# L079852 | | 27/07/2023 | 240662 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Elect\HEAD LIGHT | R/H HEADLIGHT COVER BOLTS CAN'T UNDO THEM. | | 27/07/2023 | 240662 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 27/07/2023 | 240662 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Elect\CONSUMABLE | GT Industrial - 4 x Brass fittings to block of air connectors to run as a single.<br>Carry out A Service as per job card for T909 X15 | | 25/07/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L079394 | | 05/07/2023 | 230282 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Air Con\AIR CON | AIR CON NOT GETTING COLD. | | 05/07/2023 | 230282 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes\YEL VALVE | YELLOW BRAKE LEAKS SOMETIMES (VALVE) | | 05/07/2023 | 230282 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DriCabRep\ST Weel | STEERING WHEEL NEEDS TO BE RECENTERED. | | 05/07/2023 | 230282 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Steering\HUBCAP | REPLACE HUB CAP ON LEFT STEER PLEASE. | | 05/07/2023 | 230282 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DriCabRep\ST Weel | STEERING COLUMN NEEDS REPLACING WITH GREASE, STARTING TO CHATTER ON ROUGH ROADS. | | 05/07/2023 | 230282 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Wheel Alignment | | 05/07/2023 | 230282 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Steering\WHEEL ALGN | Carry out balance and tyre rotation | | 28/06/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Mini B Service As Per Attached Checklist | | 15/06/2023 | 220214 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | Barry Maney PO# L078945<br>REPAIR STEP ON LEFT HAND SIDE OF TRUCK IF YOU HAVE TIME. | | 15/06/2023 | 220214 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Body\PANELS | Refer invoice 364518 step was repaired. REPAIR STEP ON LEFT HAND SIDE OF TRUCK IF YOU HAVE TIME.<br>Carry out A Service as per job card for T909 X15 | | 30/05/2023 | 211055 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\AS | PO# L078632 | | 27/05/2023 | 211055 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 27/05/2023 | 211055 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\CS | Barry Maney PO# L077983 | | 27/04/2023 | 197517 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrivLine\DIFF OIL | Please change Diff Oils | | 27/04/2023 | 197517 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>UHF Poor Reception | | 27/04/2023 | 197517 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrCabElect\RADIO | Remove top console & check connections, ok. Remove triangle in centre of dash and inspect joiner for aerial. Found solder connection<br>in joiner had come apart. Resolder join and reconnect, test operation, ok<br>Carry out A Service as per job card for T909 X15 | | 19/04/2023 | 198607 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | VehService\AS | Barry Maney PO# L077703 | | 12/04/2023 | 190965 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | DrCabElect\INST/GAUGE | NO ENGINE BRAKE LIGHT, NO CRUISE CONTROL LIGHT, NO WATER TEMP LIGHT, NO FRONT AIR GAUGE LIGHT SINCE LAST SERVICE. | | 12/04/2023 | 190965 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 12/04/2023 | 190965 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | AXLE OIL FRT RR & SPRING PRESS LEFT GAUGE LIGHTS NOT WORKING.<br>Service As Per Attached Checklist | | 21/03/2023 | 179718 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\BS | PO# L077096 | | 10/03/2023 | 179718 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 10/03/2023 | 179718 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\Re-Tor | POS 1-10<br>1/ Replace broken antenna. Top section broken of due to hitting low branch. | | 07/03/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | DrCabElect\GPS | 2/ repair or replace satellite tracking disc. External disc antenna is loose and has a broken wire. | | 02/03/2023 | 370179 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\FITMENT | 10 tyres | | 02/03/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2<br>After hours breakdown - truck won't start | | 02/03/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Engine\BATTERY | Remove and replace batteries | | 01/03/2023 | 174927 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Body\PANELS | CABIN STEPS HAVE BEEN BENT ON PASSENGER SIDE. NEEDTHEEM STRAIGHTENED.<br>Service As Per Attached Checklist | | 23/02/2023 | | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\AS | PO# L076692 | | 18/02/2023 | 171180 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist<br>Mini B Service | | 18/02/2023 | 171180 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Albury - Workshop | VehService\BS | PO# L076287 | | 31/01/2023 | 161153 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Albury - Workshop | Body\FUEL TANK | FUEL TANK RUBBERS BOTH SIDES. | | 31/01/2023 | 161153 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Albury - Workshop | DrivLine\CLUTCH | CLUTCH NEEDS ADJUSTING. | | 31/01/2023 | 161153 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Albury - Workshop | Brakes | Record Check Results As Attached To This Job<br>Mini B Service,<br>Jack up steer axle check bearings and king pins. | | 31/01/2023 | 161153 | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | Replace cabin filter. - SEE 172803 | | 28/01/2023 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER | |
| 1050 | Wodonga - Workshop | VehService\AS | Carry out A Service as per job card<br>Annual insepction as per check sheet | | 16/12/2022 | 150169 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Insp\ANN INSP | PO# L075654 | | 10/12/2022 | 150169 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\AS | Carry out A Service as per job card | | 10/12/2022 | 150169 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | LEFT HAND INDICATOR HAS STOPPED WORKING. FULL OF WATER. (INDICATOR NEAR DOOR) | | 10/12/2022 | 150169 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | Elect\INDICATORS | PO# L075643. LEFT HAND INDICATOR HAS STOPPED WORKING. FULL OF WATER. (INDICATOR NEAR DOOR)<br>Service As Per Attached Checklist | | 10/12/2022 | 150169 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER | |
| 1050 | Myrtleford - Workshop | VehService\BS | Barry Maney PO# L075182 | | 18/11/2022 | 140139 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 18/11/2022 | 140139 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER | |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | -Carried out tune up as requested<br>-Remove air cleaner pipes and rocker cover<br>-Adjust engine brakes & valve set; all valves tight<br>-Check engine brakes operation; ok<br>-Install rocker cover<br>-Inspect air filters, belts & tensioners ; ok<br>-Air filter due for replacement<br>-Measure wastegate travel; out of spec<br>-Remove turbo, adjust to spec & refit<br>-Pressure test CAC; ok<br>-Carry out adblue air side system flush<br>-Check over for oil & coolant leaks; ok | | | | | | | | |
| 1050 | Myrtleford - Workshop | Engine\ENG TUNE | Tune Up #1050<br>After hour call out | -Road test, all good | 15/11/2022 | 139148 | Completed | Mt Gambier | STK | XV13VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Susp\AIR LEAK | Travel to truck @ NF Mcdonald Mill. Found RH drain cords snapped on tank. Sourced parts, return to truck. Removed fittings, fit new drain cords<br>Carry out A Service as per job card for T909 X15 | | 12/11/2022 | | Completed | Mt Gambier | STK | XV13VU | Albury Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L074767 | | 28/10/2022 | 132632 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CLUTCH | NO FREE TRAVEL IN CLUTCH PEDAL. | Adjust Clutch. | 28/10/2022 | 132632 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | GAUGE LIGHTS IN DASH NOT WORKING. | replaced globes | 28/10/2022 | 132632 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | L.E.D LIGHT ON BOTTOM OF RIGHT HAND SIDE DOOR NEEDS REPLACING. | removed and replaced | 28/10/2022 | 132632 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | FUEL GAUGE LIGHT STILL NOT WORKING. | Not in book. | 28/10/2022 | 132632 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Carry out A Service as per job card for T909 X15 | | 28/10/2022 | 132632 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L074330 | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\FUEL TANK | RUBBERS ON FUEL TANK STRAPS NEED ATTENTION. | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | TURNTABLE SLIDE SWITCHES STILL HAVEN'T BEEN CHANGED. | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\MOUNTS | 1050 NEEDS CAB MOUNTS AND ENGINE MOUNTS CHECKED. (KNOCKING NOISE ON LEFT SIDE) | COULD NOT FAULT. | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | FUEL GAUGE LIGHT NOT WORKING. | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\WORK LIGHT | REAR BAR LIGHTS SWITCH HAS STOPPED WORKING AGAIN. DIDN'T LAST A WEEK. | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | FUEL GAUGE LIGHT NOT WORKING. | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | NEED TO CHANGE THE SLIDE SWITCHES IN THE CAB FOR BOTH FRONT AND BACK TRAILERS. THEY CAN BE TURNED ON ACCIDENTLY WHIC | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Need to change the slide switches in the cab for both front and back trailers they can easily be turned on accidentally which would cause | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 29/09/2022 | 120508 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | NEED TO CHANGE THE SLIDE SWITCHES IN THE CAB FOR BOTH FRONT AND BACK TRAILERS. THEY CAN BE TURNED ON ACCIDENTLY WHIC | | 07/09/2022 | 110400 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Need to change the slide switches in the cab for both front and back trailers they can easily be turned on accidentally which would cause | | 07/09/2022 | 110400 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 07/09/2022 | 110400 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | Barry Maney PO# L073897 | | 07/09/2022 | 110400 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | Reverse light n/w | Reverse switch was faulty. Replaced switch & found melted wiring. Repaired wires | 01/09/2022 | 107578 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\PHONE | MIC NOT WORKING FOR HANDS FREE PHONE. | Mic had fallen out of holder secured. Ok | 01/09/2022 | 107578 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\ELECT P&W | Tail lights go out with head lights on, jack up cabin find relay fitted to turn on headlights, trace wiring to blown fuse in loom replace & che | | 24/08/2022 | 136570 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | CRUISE CONTROL LIGHT NOT WORKING.<br>Carry out A Service as per job card for T909 X15 | | 19/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | VehService\AS | Barry Maney PO# L073398 | | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | DrivLine\DIFF OIL | Change Diff oils | | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | DrCabElect\INST/GAUGE | CRUISE CONTROL LIGHT NOT WORKING. | REPLACED GLOBE. | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | DrCabElect\INST/GAUGE | Need to change the slide switches in the cab for both front and back trailers they can easily be turned on accidentally which would cause | | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | DrCabElect\INST/GAUGE | AIRWAY GAUGE FLICKERS ON AND OFF. | COULDN'T FAULT. | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | Brakes\ABS | TRAILER ABS LIGHT STAYING ON. | INACTIVE FAULT. CLEARED. | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | DrCabElect\RADIO | MICROPHONE ON DASH PUSHED THROUGH BEHIND DASH. | OK. MEANT TO BE FLUSH MOUNTED. | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 10/08/2022 | 99697 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Tyres\TP1+2 | supply and fit 2tyres<br>Service As Per Attached Checklist | | 21/07/2022 | | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | Barry Maney PO# L072965 | | 19/07/2022 | 89719 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | AIRWAY GAUGE FLICKERS ON AND OFF. | | 19/07/2022 | 89719 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes\ABS | TRAILER ABS LIGHT STAYING ON. | | 19/07/2022 | 89719 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\RADIO | MICROPHONE ON DASH PUSHED THROUGH BEHIND DASH. | | 19/07/2022 | 89719 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 19/07/2022 | 89719 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | CTI\CTI Drive | CTI not working, remove control unit & reset, no different, jack up cab & check unit had no air trace fault to air adjust pressure valve lock<br>Carry out A Service as per job card for T909 X15 | | 23/06/2022 | 81573 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | Barry Maney PO#L072271 | | 07/06/2022 | 80249 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 07/06/2022 | 80249 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\HOUSEKEEP | Road train signs and covers | | 04/06/2022 | 78754 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | Elect\TRL LIGHTS | no trailer lights | Elite diesel repairs Poww071937 | 23/05/2022 | 370179 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | Mini B Service,<br>Jack up steer axle check bearings and king pins.<br>Replace cabin filter.<br>Barry Maney PO# L071807<br>REPLACE LH WINDSCREEN. TREE BRANCH THROUGH WINDSCREEN. | | 17/05/2022 | 74181 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DriCabRep\WINDSCREEN | REFER TO WAYNE. | | 17/05/2022 | 74181 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | Elect\BATTERY | JUMP STARTED. | | 13/05/2022 | 68203 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\DAMAGE | TCTC supply grille<br>Greenfreight Truck k200 Chassis No # 473089 Rego XV13VU<br>Vin 6F5000000MA473089 Fit up extra cable to truck to suit towing<br>Elphinstone/Std Flattow road train Trailer. Swap over EWM-II Display to<br>IAP unit. Remove front cover. Run accessories cable from rear<br>turntable into Cab & connect to switches. Fit pressure protection valve, | | 11/05/2022 | 68603 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Elect\ELECT P&W | Extra airline to rear turntable. Test operation. | | 28/04/2022 | | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\WINDSCREEN | Replace windscreen (sublet) | | 24/03/2022 | | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Body\DAMAGE | Roof damage, remove broken sunvisor & fit new air snorkel<br>Carry out A Service as per job card for T909 X15 | | 24/03/2022 | | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L070660 | | 12/03/2022 | 61930 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 12/03/2022 | 61930 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\BS | PO # L070336 | | 25/02/2022 | 50125 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Carry out A Service as per job card for T909 X15 | | 25/02/2022 | 50125 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | PO # L070130 | | 15/02/2022 | 41380 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 15/02/2022 | 41380 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist<br>Mini B Service | | 29/01/2022 | 29222 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\B1 Svc | PO# L069854 | | 29/01/2022 | 29222 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrivLine\CTI Drive | Air CTI very hot, had damage to housing, replaced at yard with one supplied<br>Carry out A Service as per job card for T909 X15 | | 26/01/2022 | 26516 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | VehService\AS | O/N L12873 | | 14/01/2022 | 20116 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 14/01/2022 | 20116 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Wodonga - Workshop | VehService\CS | O/N L12778 | | 14/12/2021 | 8337 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 14/12/2021 | 8337 | Completed | Mt Gambier | STK | XV13VU | BARRY MANEY - 3 | P/MOVER |
| 1050 | Wodonga - Workshop | Insp\Truck Pre | Truck Pre Delivery<br>2 x Stickers 3 Points of Contact<br>Safepak Albury | TARE= 10900KG | 30/11/2021 | 630 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Wodonga - Workshop | Body\CONSUMABLE | PO#WW068691 | | 30/11/2021 | 630 | Completed | Mt Gambier | STK | XV13VU | Wodonga Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\SCALES | fit scales and elphinstone trailer supply lines<br>*MT Data Install-MDVR<br>*IAP Install<br>Tablet serial # 000041721<br>Tracking unit serial # 479001821<br>Tracking unit sim card # 8200098249491<br>Tag #'s 024984 & 024983<br>MDVR serial # C704CBAFC1723<br>Phone # 0417484478 | Mount and wire up supplied IAP tracking unit under passenger seat.<br>Mount GPS and high gain antennas on rope rail above LH door just behind<br>door. Mount tablet and mic above radio & gauges, mount speaker above rear<br>of RH door. Mount MDVR under passenger seat, wire up, mount forward facing<br>camera, run wiring and connect camera to MDVR. Connect and wire in engine<br>data control box to CAN wiring & power and earth as necessary. Connect scales<br>to tracking unit. Connect power, earth & ignition, mic and speaker, re-assemble<br>truck and test. Contact MtData support to setup and test unit. Complete IAP | 11/11/2021 | 647 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |
| 1050 | Myrtleford - Workshop | DrCabElect\IAP | Support persons name - Aaron | paperwork & send off. | 27/10/2021 | | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1050 | Myrtleford - Workshop | Chassis\FIFTH WHEE | MAKE UP TURNTABLE WITH SCALES AND GREASE LINES L12380 | | | | 21/09/2021 | Completed | Mt Gambier | STK | XV13VU | Myrtleford Workshop | P/MOVER |