| EquipmentName | Workshop | CodeAndSubCode | Description | CompletionComments | DateDone | DistanceDone | Workstate | Location | Division | Rego | Supplier | EquipmentType |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Supply K200 LH Half screen<br>KW1023 | | | | | | | | |
| 1052 | Mt Gambier - Mt Gambier | DriCabRep\WINDSCREEN | Replace passenger windscreen | Installation | 08/09/2026 | 741027 | Completed | Mt Gambier | STK | XV15VU | WESTON TINTING & WINDSCREENS | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | FIT DUAL INPUT RIGHT WEIGH SCALES TO TRUCK | | 08/09/2026 | 737206 | Completed | Mt Gambier | STK | XV15VU | JF MECHANICALS - 3 | P/MOVER |
| | | | | ROTATION<br>BALANCE SAND | | | | | | | | |
| 1052 | Mt Gambier - Mt Gambier | Tyres\ROTATION | Tyres\ROTATION | 2 ROTATION AND BALANCE P 1.2 DONE MOUNT GAMBIER | 04/09/2026 | 737206 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Mt Gambier - Mt Gambier | VehService\AS | VehService\AS A Service | | 22/08/2026 | 733762 | Completed | Mt Gambier | STK | XV15VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\EXHAUST | fit missing exhaust tip (stack) | Refitted exhaust stack with new clamp | 18/08/2026 | 731696 | Completed | Mt Gambier | STK | XV15VU | HALLORAN DIESEL - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | | 05/08/2026 | 724061 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Remove and replace indicator stalk<br>WO#208187<br>Inspect and found indicator stalk falling apart. Remove<br>covers and cut cable ties. Remove and replace indicator | | | | | | | | |
| 1052 | Mt Gambier - Mt Gambier | DrCabElect\INDICATORS | DrCabElect\INDICATORS<br>VehService\BS B Service | stalk as required. Test operation and refit covers. | 04/08/2026 | 724061 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | L134991 | | 01/08/2026 | 720776 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | CHECK ROSE JOINTS ON RIDE HEIGHT VALVES & REPLACE AS | Inspect rose joints, found 2 were very worn. Removed rose joints and replaced with new. Checked ride height set | | | | | | | | |
| 1052 | Myrtleford - Workshop | Susp\HCV | REQUIRED | correctly, all okay. | 29/07/2026 | 720776 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DRV LN SER | ADJUST END FLOAT IN FRONT DANA DIFF | | 29/07/2026 | 720776 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\SEAT | SEATBELT NOT RETRACTING CORRECTLY | Sprayed seat belt with silicone spray and work seat belt back and forth. Retracting all okay. | 29/07/2026 | 720776 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Move steering wheel cover and confirm fault. Remove steering covers and found cable for steering wheel tilt stretched. Remove and replace cable, check steering wheel operation then reassemble, all OK | | | | | | | | |
| 1052 | Myrtleford - Workshop | Steering\PWR STEER | CANT MOVE STEERING WHEEL BACK AND FORWARDS | KW450205F CABLE-GEN 2.5 STR COLUMN<br>Plug in and check for codes - fault relating to ad blue.<br>Check over ad blue system and found breather on ad blue tank blocked. Remove breather and flush until clean. Refit ad blue components, clear codes, all OK<br>KWAQ62-D0T-6 PTC UNION 3/8 1 8.40<br>KWABF161 OLIVE SHRT NUT 3/8 1 0.52<br>KWPFT-6B-BLK-100 TUBE BLACK 3/8' 30MT RO 1 3.00 | 29/07/2026 | 720776 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\FAULT CODE | CHECK ENGINE LIGHT ON DASH | Misc:DFT DIAGNOSTIC TOOL FEE | 29/07/2026 | 720776 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\AIR LEAK | CHECK FOR AIRLEAKS | Found air leak coming from drain bung on RH first air tank. Remove and replace drain bung. Check over for leaks, all OK<br>KW12104 VALVE-DRAIN | 14/07/2026 | 713635 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering\STEER UNI | R&R STEERING UNI'S - REPLACE WITH GREASEABLE | Remove steering shaft. Remove and replace steering unis to greaseable ones. Refit and tension steering shaft, all OK<br>KW5.103X | 14/07/2026 | 713635 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\SUSPENSION | ROSE JOINTS HAVE WEAR | Inspect rose joints, found to have wear but not worn. To recheck next service | 14/07/2026 | 713635 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | CHECK DAMAGED WINDSCREEN<br>HOW BAD ??? | | | | | | | | |
| 1052 | Myrtleford - Workshop | DriCabRep\WINDSCREEN | windscreen damaged | Inspect windscreen, found to have a few minor chips | 14/07/2026 | 713635 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering\HOUSEKEEP | STEERING COLUMN TILT - N/W | Inspect and found cable for column fallen off. Refit cable and secure. Check steering tilt operation, all working as should | 14/07/2026 | 713635 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\COOL LEAKS | COOLANT LEAKING - FIX<br>VehService\AS A Service | Inspect and found coolant leak coming from loose clamp on small coolant hose. Tighten clamp and wash down, all OK | 14/07/2026 | 713635 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | L134763 | | 14/07/2026 | 711616 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Check over all steering components, found steering shock broken. Remove and replace steering shock, refit all components, all OK | | | | | | | | |
| 1052 | Myrtleford - Workshop | DriCabRep\ST Weel | STEERING WHEEL TILT WONT LOCK IN | KW499080B TILT LOCK-GAS STRUT GEN 2.5 ST | 07/07/2026 | 705578 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\GEARBOX | excessive free play in gearstick | CHECK OUT EXCESSIVE MOVEMENT IN GEARSTICK SELECTION<br>Inspect gear linkage and grease as required. Check for movement all OK. Driver to monitor | 25/06/2026 | 701882 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\BELTS/TENS | CHECK BELTS REPLACE ENGINE FAN BELT | Inspect engine fan belt and found to be worn and perishing on edges. Source new belt and fit as required.<br>KW12PK2380 V BELT-MICRO | 24/06/2026 | 701882 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Travel out to truck at Greenwald. Jump start truck and inspect faults. Found alternator not out putting voltage due to be installed incorrectly. Removed alternator and replaced with new. Test output - 13.8 volts. Test batteries, all OK | | | | | | | | |
| 1052 | Myrtleford - Workshop | Elect\ALT | FIT NEW ALTERNATOR AT G/F YARD | KWLBP2408 ALTERNATOR 12V 170A PAD FI LEECE NEVILLE | 24/06/2026 | 701882 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | RH king pin presenting with movement<br>Jack up front axle and check king pin movement, recommend to be replaced. LH king pin movement worse than RHS measure movement with dial indicator | CHECK KING PIN MOVEMENT<br>Set up dial indicator, jack axle and record king pin movement on both sides.<br>LHS 15 thou | | | | | | | | |
| 1052 | Myrtleford - Workshop | Steering\KING PIN | next service | RHS 10 thou both side are with in dana spec 30 THOU | 23/06/2026 | 701882 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\SCALES | REPLACE AIR WEIGH GAUGE WITH BLUETOOTH UNIT<br>VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and king pins.<br>Replace cabin filter. | | 23/06/2026 | 702000 | Completed | Mt Gambier | STK | XV15VU | JF MECHANICALS - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | L134386 | | 23/06/2026 | 701077 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DIFF OIL | DrivLine\DIFF OIL Replace Diff oils<br>Insp\ANN INSP Annual insepction as per check sheet | COMPLETED JOB #4 | 23/06/2026 | 701077 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Insp\ANN INSP | L134387 | | 23/06/2026 | 701077 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\Punct | Tyres\Punct POS 7 | | 19/06/2026 | 701882 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| | | | | jump start truck at yard<br>Travel to GF yard and jump start truck, test alternator - at 14.2 volts, all okay. Truck went flat again. Travel to yard, jump start truck and bring to BMG workshop. Load test batteries - failed. Remove and replace batteries, check charge rate, all okay. | | | | | | | | |
| 1052 | Myrtleford - Workshop | Elect\BATTERY | JUMP START & REPLACE ALL 4 BATTERIES | KWKGE780HD BATTERY-12V,SMF HD 780CCA,94AH,170RC | 11/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | CAN SMELL POWER STEERING FLUID BURNING<br>ALSO VERY TWITCHING INSTEERING WHEN TURNING CHECK STEERING<br>Inspect and found steering box leaking. Unbolt steering shaft and pitman arm. Unbolt and remove steering box. Fit and secure new steering steering box as required. Refit pitman arm and steering shaft - tensioned to spec. Carry out steering box bleed as per procedure. Road test and check over for leaks, all okay. *Will need poppets stops reset with special tool* | | | | | | | | |
| | | | REPLACE FAULTY STEERING BOX (it was leaking and had movement in the sector shaft) WD | NGTAS85123TRPRC TAS85123 S/BX 1 1905.28 | | | | | | | | |
| 1052 | Myrtleford - Workshop | Steering\PWR STEER | REPLACE POWER STERING FILTER | KWLF637 LUBE, CARTRIDGE OIL FILTER | 05/06/2026 | 693747 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\Punct | Tyres\Punct POS 1 | FIT SPARE TO POS 1 | 03/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP02 | Tyres\TP02 | NWR | 03/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP5+6 | Tyres\TP5+6 | | 03/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP9+10 | Tyres\TP9+10 | | 03/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP7+8 | Tyres\TP7+8 | | 03/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP11+12 | Tyres\TP11+12 | | 03/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4<br>VehService\AS A Service | | 03/06/2026 | 696932 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | L133946 | | 27/05/2026 | 690730 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\DAMAGE | FIT NEW GUARD + X2 GUARD POLES AS REQUIRED TO RH REAR<br>DRIVER JACK KNIFED TRUCK & DAMAGED 2 X M/GUARDS THAT NEED REPLACING | Remove broken guard and poles. Measure and dill new guard then fit new guard pole and brackets to guard. Fit Guard to truck and tighten, all okay<br>KWSSCT-1 SUPPORT-FENDER CHASSIS TUBE 1 48.40<br>KWSSBK-1 SPRAYSAFE FENDER SUPPORT KIT 2 31.72<br>KWK127-1116-08A FENDER RED SPRAYSAFE 1 68.00<br>KWK197-6398 REINFORCEMENT-MUDFLAP 1 82.93<br>KWSSBK-1 SPRAYSAFE FENDER SUPPORT KIT<br>REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 | 26/05/2026 | 690730 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\AIR CON | CHECK AIR CONDITIONING OPERATION<br>*** QUOTE BEFORE REPAIR PLEASE ***<br>Check A/C operation, found not as cold as could be. Will need more info from driver and to rectify next service due to time restrictions | Check A/C operation, remove LH dash panels and check cab filter, evaporator and evaporator drain, all looked okay.<br>Run A/C and got temp to come down to 10.5 degrees (unable to tilt cab at the time to access A/C lines) but A/C getting cold. If fault persists will revisit and rectify issue<br>REPAIR COVER PLATE UNDER FIRST BAY | 26/05/2026 | 690730 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\BRAKE ADJ | Rear s-cam bushes worn<br>THIS JOB WAS DONE BECAUSE THE DRIVE HUB SEAL WAS ALSO LEAKING | Inspect and found plate had snapped bracket. Remove deck plate. Prep area and weld repair bracket as required. Refit deck plate, all okay | 26/05/2026 | 690730 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\LIGHTS | CHECK DASH LIGHTS | Inspect and found turbo boost and engine oil press gauges had globes not working. Removed dash panel and replaced globe for oil pressure. Refit turbo boost globe back in position. Refit dash. Check operation and refit dash panel, all okay | 26/05/2026 | 690730 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | CHECK ENGINE LIGHT ON DASH - PLUG IN AND CHECK | Inspect for fault, found truck was low on ad blue. Advised driver to fill with ad blue and call if fault remains. | 12/05/2026 | 685266 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | VehService\BS B Service<br>L133673 | | 07/05/2026 | 681821 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | repair weigh gauges n/w | Found no scale operation for dolly scales, inspected power supply from plug and had no power on inspection seen that wire in back of A trailer plug had been pulled out, refitted wire and tested power again no power to unit so tested down the loom and found power to be broken in part of loom near Draw bar. Removed part of the loom and began to inspect for break. Once finding cut out and rejoined with new wire and joiners. Plugged in scales and still no operation. Noticed that scale unit in cab was now reading from drivers observation. Zip tied loom back up and put tooling away | 29/04/2026 | 677431 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\BREAKDOWN | AFTER HRS BREAKDOWN B/M | Breakdown 8:30 - Check power to A trailer, all components had power. Spread terminals, A trailer plug and all trailer worked until key on and truck running. Inspect and found fuse in battery box blown. Replace fuse as required, check and found didn't blow. Truck went back to work then got a call 10 minutes later that had blew again. Driver stated fuse blowing when foot on brake. Apply brake and shake all wiring from trailer plugs to rear bars, could not get fuse to fault. | 28/04/2026 | 677431 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\ELECT P&W | REPAIR LIGHTS B/M | Next morning had senior auto elect look at truck, inspect trailers for shorts, test and follow power flow and found trailer plug had shorted wires for parkers rubbing on plug shell. Remove and rewire plug, check all OK | 28/04/2026 | 677431 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\BRK O/HAUL | TRUCK BRAKES LOCKING ON<br>NO TRAILER BRAKES AT ALL | Checked trailer brake adjustment and all brake operation. all adjustment okay, test drive truck and trailer temps were down compared to truck checked operation and found brakes not fully operating on trailers. Check air pressures with gauges, found air from truck not sufficient, remove and replace quick release valve re check operation all okay.<br>KW800332N VALVE-CHECK | 27/04/2026 | 677431 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\BRAKE ADJ | CHECK BRAKES - DONT SEEM TO BE WORKING VERY WELL | Check and adjust brakes as required, all OK | 23/04/2026 | 675201 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | REVERSE LIGHTS AND BEACON LIGHTS ARE STUCK ON | Check reverse switch, all ok. Unplug trailer plug and found reverse stopped. Open plug and wires fell out - rewire plug as required and check operation, found reverse still on. Check over trailer plugs and found B trailer plug broken, wire in new plug and check, no more reverse stuck on, all OK. Also found blown fuse in battery box, replace fuse as required, all OK<br>KWB2161BL PLUG-TRAILER,6MM CABLE,7PIN | 23/04/2026 | 675201 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\AIR LEAK | Check for air leaks under deck plates | Check over airlines under deck plate, found hose to gearbox rubbed and leaking. Cut out rubbed section of hose and fit joiner. Secure hose out of way, all OK | 17/04/2026 | 671410 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service<br>L133313 | | 16/04/2026 | 671193 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\ELECT P&W | R & R CLOCK SPRING | Check and found all steering wheel switches not working. Check power and fuses, all okay. Diagnose faulty clock spring. Remove components to remove clock spring, fit new clock spring, reassemble and test, all working as should.<br>KW455089 CLOCK SPRING Do not delete location | 16/04/2026 | 681821 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DIFF OIL | CHECK DIFF WEEP<br>Check diff interface, found leaking, will need to be re-booked for repair | CHECK DIFF INTERFACE LEAK<br>Check over diff, unable to detect any leaks. To monitor and report where leaking<br>checked at 681821 kms | 16/04/2026 | 681821 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 10/04/2026 | 671410 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\WORK LIGHT | PASSENGER SIDE WORK LIGHT N/W | Check passenger side work light, found working as should. Check over wiring and relevant connections, all looked OK | 31/03/2026 | 666473 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Dash light for temp n/w | Checked dash globes and replace as required | 31/03/2026 | 666473 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering\SUSPENSION | CHECK STEERING AXLE U BOLTS | Check steer axle u-bolts, looked to be starting to rust. Check tension and found loose. Tension all steer axle u-bolts, all OK<br>AIR LEAKS | 31/03/2026 | 666473 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\AIR LEAK | AIR LEAK AROUND AIR DRYER | Check over truck for air leaks, found bolt around air dryer base loose. Tighten loose bolt and recheck for leaks, all OK<br>Get tools and parts required then travel out to truck. Inspect ABS cord, had fallen down near gearbox/tail shaft area and shredded itself. Remove remaining ABS cord, fit new cord, connect and secure. Remove hot pipe and check compressor, all was OK. Inspect further and found air dryer to tank hose had broken off. Get required fitting and fit to air dryer. Reconnect hose to new fitting and check, all OK now building up air.<br>KW275491GDV GOVERNOR D2 TRP 100-120 PSI 1 28.39<br>KWK129-232-0810 FITTING 45 DEG MALE 1 12.34<br>KWABF128 ADAPTER 1/2 F X 3/8 M 1 6.77 | 31/03/2026 | 666473 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\AIR LEAK | Check for air leaks, turned on to bush track and now wont build up air | KWB2560 12/24V 7 CORE EBS SUZI 4.5M | 25/03/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | Elect\TAIL LIGHT | REVERSE LIGHTS | Upon service found reverse lights, dash light, and buzzer not working. Check for power at reverse light, 15 ohms 0 volts. Check over fuse, all looked OK. Check over relay, found had no power. Remove and replace relay and check, still no power. Inspect and test reverse switch, found not working, replaced switch as required, all OK.<br>KW22940 REVERSE LIGHT SWITCH<br>ORDER NEW LIGHTS<br>Remove and wire in new driving light as previously quoted. Check operation, all OK | 19/03/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\DRV LIGHT | REPLACE FAULTY DRIVING LIGHT<br>VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and king pins.<br>Replace cabin filter. | KWTRP4DL70 TRP 7' DRIVING LIGHT 70W V4 COMBO BEAM 5 | 19/03/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | L132922 | | 19/03/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ENG REBLD | REPLACE FAULTY ENGINE BLOCK & LINERS & GASKETS RINGS & BEARINGS<br>REBUILT KMS 657829<br>REPLACE CLUTCH BRAKE & SPIGOT BEARING (CLUTCH OK)<br>REAR ENGINE MOUNTS (OK)<br>HORTON (Ok) AIR COMPRESSOR(OK)<br>REPLACE RADAITOR MOUNTS | CLYLINDER HEAD WAS (OK)<br>TURBO & WATER WAS REUSED<br>AIR COMPRESSOR (WAS CHANGED 605656KMS)<br>HORTON (WAS REBIULT 584416KMS) | 18/03/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\HOUSEKEEP | REPLACE HEATER TAPES | | 18/03/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\IAP | DrCabElect\IAP | Guardian Gen 2 - Forward Facing Camera Kit<br>Forward Facing Camera<br>Mounting Foot<br>Alcohol Wipes | 26/02/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | TELEMATICS - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Cooling\HOUSEKEEP | Cooling\HOUSEKEEP | COOLANT<br>RADIATOR CAP<br>JALTEST LAPTOP CONNECTION FEE | 26/02/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | COOKY'S DIESEL MECHANIC REPAIRS - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\HEAD LIGHT | DIAGNOSE & REPAIR FAULT IN LEFT HAND HEADLIGHT LOW BEAM CIRCUIT. | | 25/02/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | JF MECHANICALS - 3 | P/MOVER |
| | | | REPAIR AIR CON SYSTEM<br>REPLACE EVAPORATOR<br>REPLACE DRIER | REPLACE EVAPORTOR AND RECIVER DRIER AS PER QUOTE<br>REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563<br>Connect A/C equipment and recovered gas from system. Unbolt HVAC system and removed evaporator. Assembled new TX to evaporator and installed new evaporator to HVAC system. Replaced receiver drier as required. Vac down A/C system and tested for leaks, all okay. Charge with new gas. Also replaced cab filter as required.<br>KWS31-TP-1000 EVAPORATOR CORE KW 1 217.27<br>KWTRP997TX TX VALVE KW GENUINE PART 25188997 1 43.59<br>KWGD11350 TRP RECEIVER DRYER 1 40.00<br>KWF37-TP-1000 FILTER CABIN K200 1 22.58 | | | | | | | |
| 1052 | Myrtleford - Workshop | Air Con\AIR CON | LABOUR | POL AIRCONDITIONING GAS R134A | 25/02/2026 | 656444 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\Punct | Tyres\Punct POS 10 | CALL OUT | 19/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\HEAD LIGHT | head lights flicker when going over bumps | Operate high beams, found passenger side spot light not working. Check over and wiggle wiring, found light flickering. Inspect further and found wiring breaks right at spotlight and unable to repair. Quote and get new spot lights approved and ordered. | 17/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\RADIO | Tablet cradle not charging properly. Check cable connection from truck side. | Remove triangle on dash and inspect wiring, found wires squished. Route wiring so is not being squished. Unplug and re-plug in all components, tablet charging as should, all OK | 17/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\SLACK ADJ | REFIT RHS SLACK ADJUSTER | Remove split pins and pins to slack adjuster. Get shim kit and fit shims as required. Fit slack adjuster, shims and e-clip as required. Adjust brakes and check, all OK<br>KWT02-310B-AU KIT-S CAM WASHER,GP | 17/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | ADJUST CLUTCH | Adjust clutch and free play to spec, all OK | 17/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Air Con\AIR CON | air conditioner not keeping cab cold | A/C NOT KEEPING CAB COLD<br>***CHECK AND ADVISE, JOB NEEDS TO BE QUOTED***<br>REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563<br>Remove LH cab panels and inspect, found cab filter extremely blocked - replace cab filter as required. Inspect further and found evaporator drain blocked, unblock and drain water. Check inside top of evaporator blocked. Refit all panels and advise of blocked evaporator, will need to be re-booked. | 17/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DRIVES | Movement in shaft between diffs<br>CHECKED BY B/M 11/2/26<br>VehService\AS A Service | MOVEMENT IN JACK SHAFT BETWEEN DIFFS - PLEASE CHECK AND ADVISE IF WITHIN SPEC<br>Check over jack shaft and tail shaft movement, found movement minor and to be within spec. | 17/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | L098975 | | 17/02/2026 | 651636 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\SCALES | scales head unit in truck nw. possible broken wire<br>VehService\BS B Service | SCALES UNIT IN CAB TURNS OFF AND ON<br>Remove dash panel and check over fuses and wiring, all looked OK. Check over wiring at plug and found wire had pulled out of join. Re-join wires at plug and check, scales working as should. | 16/02/2026 | 648720 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | L098646 | | 28/01/2026 | 643147 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DIFF OIL | DrivLine\DIFF OIL | DIFF OILS DONE AT 600352 KMS 19/9/25 B/M | 19/01/2026 | 637139 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | NO SCALES IN CAB<br>VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and kingpins.<br>Replace cabin filter. | Display in cab not working<br>jacked cab and checked battery box fuses. Checked fuse pane, all okay. Remove overhead console and check fuse and power. Fuse was okay but had no power. removed side panel and dash, traced wiring but found they went through the floor panel and into chassis. Found power supply was broken. Repaired section of wiring loom and reconnect scales. Checked operation, all okay. Resecured wiring and refit panels. | 09/01/2026 | 636263 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | L097675 | | 09/01/2026 | 618905 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Susp\SHOCK ABS | Drive shockies, RHR and LHF - replace next service | Remove and replace RH rear shocker as required. Replace bushes on LH front and LH rear drive as required.<br>KWC71-1006 SHOCK ABSORBER-REAR SUSP'N 1 420.38<br>KW7050-06-6860 SHOCK ABS BOTTOM BUSH KIT SUITS C71-1006 1 53.71<br>KW7050-06-6860 SHOCK ABS BOTTOM BUSH KIT SUITS C71-1006 | 17/12/2025 | 636184 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\BRAKE ADJ | FR s-cam movement | heck s-cam movement on RH front drive, found bushes need replacing. Jack diff, remove axle, wheels, slack adjuster, brake drums, and s-cams. Punch old bushes out then punch new bushes in. Refit all components previously removed, all okay<br>KW815463 CAMSHAFT | 17/12/2025 | 636184 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Brakes\BRAKE ADJ | Check s-cam movement on RH front drive, found bushes need replacing. Jack diff, remove axle, wheels, slack adjuster, brake drums, and s-cams. Punch old bushes out then punch new bushes in. Refit all components previously removed, all | | | | | | | | |
| 1052 | Myrtleford - Workshop | Brakes\BRAKE ADJ | DRIVE'S CAM BUSHES WEARING | okay | 17/12/2025 | 636184 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Steering\TIE ROD | nspect sway bar bushes and send photos to Wayne. Do not | | | | | | | | |
| 1052 | Myrtleford - Workshop | Steering\TIE ROD | SWAY BARS AND TORQUE ROD BUSHES NEED REPLACING | need to be replaced. THEY ARE OK AT THE MOMENT | 17/12/2025 | 636184 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | heck over brakes, found to be out of adjustment. Adjust | | | | | | | | |
| 1052 | Myrtleford - Workshop | Brakes\BRAKE ADJ | BRAKES ARE NOT HOLDING ON A HILL | brakes as required, all okay | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Remove dash cluster. Replaced blown globes for high beam and engine brake. Refit dash cluster. | | | | | | | | |
| | | | | KW47762 GLOBE-DASH PANEL,12V 1.2W BLACK BASE B8. 1 11.61 | | | | | | | | |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | EXHAUST BRAKE LIGHT ON DASH N/W | KWS6040BL TERMINAL-BLADE,F,9.5MM(PKT 10) | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | REPLACE WEATHER SHIELD ON DOOR | | | | | | | | |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | driverside door wind deflector loose and flapping around. | Remove and replace drivers side weather shield as required, all ok | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Remove dash cluster. Replaced blown globes for high beam and engine brake. Refit dash cluster. | | | | | | | | |
| | | | | KW47762 GLOBE-DASH PANEL,12V 1.2W BLACK BASE B8. 1 11.61 | | | | | | | | |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | high beam light on dash not working | KWS6040BL TERMINAL-BLADE,F,9.5MM(PKT 10) | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Remove and replace fuel tank rubbers as required, all okay | | | | | | | | |
| 1052 | Myrtleford - Workshop | Body\FUEL TANK | Tank rubbers | KWK161-793-4000 LINING TANK STRAP,50MM X 4MTR | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Front drive brakes low | FRONT DRIVE BRAKES GETTING LOW | | | | | | | | |
| | | | 5/9/25 - | Inspect brakes, still in alright condition, recheck next | | | | | | | | |
| 1052 | Myrtleford - Workshop | Brakes\BRK RELINE | INSPECTED BRAKES ALL LOOKED OK - CHECK NEXT SERVICE | service. Brakes all at 6-7mm | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Remove dash cluster. Replaced blown globes for high beam and engine brake. Refit dash cluster. | | | | | | | | |
| | | | | KW47762 GLOBE-DASH PANEL,12V 1.2W BLACK BASE B8. 1 11.61 | | | | | | | | |
| 1052 | Myrtleford - Workshop | Body\LIGHTS | HIGH BEAM LIGHT OUT SINCE LAST SERVICE NEED FIXING AND CHECKING | KWS6040BL TERMINAL-BLADE,F,9.5MM(PKT 10) | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Remove cigarette lighter plug, fit new female connector and | | | | | | | | |
| 1052 | Myrtleford - Workshop | DriCabRep\RADIO | LIGHTER PLUG BEHIND PASSENGER SEAT HAS STOPPED WORKING. PLEASE CHACK & FIX | fit plug. Check operation, all working as should | 12/12/2025 | 633150 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | VehService\AS A Service | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | L098075 | | 09/12/2025 | 641400 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | ADJUST CLUTCH Tech(s): 8091 113.75 | | | | | | | | | |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | ADJUST CLUTCH | Carried out clutch adjustment as required. | 14/11/2025 | 621277 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | SCALES N/W | | | | | | | | |
| | | | | Received phone call, arranged to meet driver at BMG workshop. Inspect wiring going to all trailers, found truck suzi faulty. Remove conduit and found broken wiring. Join | | | | | | | | |
| | | | AFTER H'RS BREAKDOWN | wires where broken and fit conduit back. Check over all | | | | | | | | |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | CALL OUT FEE no scales | wiring. | 13/11/2025 | 621277 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP11+12 | Tyres\TP11+12 (31-32) | | 11/11/2025 | 621277 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP7+8 | Tyres\TP7+8 (27-28) | | 11/11/2025 | 621277 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 (23-24) | | 11/11/2025 | 621277 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| | | | | Inspect truck and found RH low beam light not working. Unplug lights and found voltage on both wires, suspect to have rubbed together. Cut into harness and trace wiring, found voltage back in main harness. Remove headlight, test and found power and earth in the correct spots - suspect light internally faulting crossing power. Remove and replace light and check operation, all ok. Secure wire and tape out of was. Also found earth pin fallen out of main plug, repair, all ok. | | | | | | | | |
| 1052 | Myrtleford - Workshop | Elect\HEAD LIGHT | BLOWN HEAD LIGHT GLOBE L E D L/BEAM | KWP54-1326-1-001 KW 12V/24V LED H-LIGHT HI/LO | 30/10/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | TRAILER BRAKES TAKE A LONG TIME TO RELEASE | | | | | | | | |
| | | | | Work order 201554 | | | | | | | | |
| 1052 | Myrtleford - Workshop | Brakes\BRAKE ADJ | TRAILER BRAKES TAKING ALONG TIME TO RELEASE | Job carried out on dolly RO | 29/10/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | RADIATOR MOUNTS WORN | | | | | | | | |
| | | | | work order 200950 | | | | | | | | |
| 1052 | Myrtleford - Workshop | Cooling\RADIATOR | Radiator mounts worn | Check over radiator mounts, found to be all ok | 29/10/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | STEERING UNI VERY SLIGHT MOVEMENT | | | | | | | | |
| | | | | Work order 200950 | | | | | | | | |
| 1052 | Myrtleford - Workshop | Steering\UNI JOINTS | Steering uni very slight movement | Check uni, found very slight movement but is all ok. | 29/10/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\RERATE | Elect\RERATE | re-rate speed - customer request | 21/10/2025 | 612878 | Completed | Mt Gambier | STK | XV15VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| | | | | Connect laptop & download | | | | | | | | |
| | | | | - Remove air cleaner pipes and rocker cover | | | | | | | | |
| | | | | - Adjust engine brakes & valve set; all valves tight | | | | | | | | |
| | | | | - Check engine brake operation; ok | | | | | | | | |
| | | | | Install rocker cover | | | | | | | | |
| | | | | - Inspect air filters, belts & | | | | | | | | |
| | | | | - Measure wastegate travel; ok | | | | | | | | |
| | | | | - Pressure test CAC; ok | | | | | | | | |
| | | | Engine\ENG TUNE | tensioners; ok | | | | | | | | |
| | | | PLUG, GEAR COVER | - Carry out adblue air side system flush | | | | | | | | |
| | | | GASKET VALVE COVER | - Check over for oil & coolant leaks | | | | | | | | |
| | | | ESI WATER FILTER BLANK | - Replace leaking water filter | | | | | | | | |
| 1052 | Myrtleford - Workshop | Engine\ENG TUNE | L097468 | - Steam clean & road test, all good. | 21/10/2025 | 612878 | Completed | Mt Gambier | STK | XV15VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| | | | VehService\AS A Service | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | L097316 | | 17/10/2025 | 611064 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Jacked cab, drained coolant and removed intake pipe, fuel filter ad coolant lines. Removed power steering pump and governor valve. Undo all compressor mounting bolts, removed old compressor, change over fittings to new compressor. Cleaned up mounting surfaces and fit new gaskets. Installed new compressor, tensioned mounting bolts to spec. Refitted all parts as previously removed. Filled truck with coolant and washed down area. Take truck for a test drive, all okay. | | | | | | | | |
| | | | | CU3690864RX RECON AIR COMPRESSOR ISX 1 3827.87CU5440813 GASKET, ACC DRIVE SUPPORT 1 74.60KW4988280 GASKET 1 | | | | | | | | |
| 1052 | Myrtleford - Workshop | Engine\COMPRESSOR | REPLACE AIR COMPRESSOR & GASKETS | 20.90KW236577N GASKET-GOVERNER 1 10.64KWHS016-20 PERFORATED HOSECLAMP BA | 13/10/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | | Connect A/C gauges and removed gas from system. Removed A/C belt, Disconnect hoses, unbolt and removed A/C compressor. Found A/C belt was cracked. Installed new A/C compressor and new belt, tensioned mounting bolts. Refit A/C belt. Replaced receiver drier. Charge system with new A/C gas and tested system, all okay. | | | | | | | | |
| | | | | KW6PK1590 A/C BELT 1 46.22KWF69-1019 COMPRESSOR-REFRIGERANT 1 448.00KWK251-571 FILTER-FREON, RECEIVER/DRYER | | | | | | | | |
| | | | | TRP GD11350 1 126.88POL | | | | | | | | |
| 1052 | Myrtleford - Workshop | Air Con\AIR CON | REPLACE A/C COMPRESSOR | AIRCONDITIONING GAS R134A | 09/10/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | R & R KING PINS<br>Work order 201281<br>Jacked up steer axles, removed wheels and brake assembly.<br>Drained hubs and remove backing plates. Removed steering<br>nut and rod. Removed anchor bolts. Removed bottom and top<br>caps. Remove stub axles, remove and replace<br>bushes, rheemed to suit. Refit stub axles and installed.<br>Shimmed king pins. Refit foundation plates and fit wheels.<br>Adjust wheel bearings and filled hubs with oil. Tensioned<br>all wheel nuts.<br>KW33143S KINGPIN KIT 1 851.33KW43764S SCOTSEAL 2 99.16NG10088 LUCAS HUB OIL 1 29.82KW160HD105 BUSH KING PIN 1 | | | | | | | |
| 1052 | Myrtleford - Workshop | Steering\KING PIN | FIT LH & RH STEER KING PIN KITS | 24.64KW45379SCR GASKET-HUB CAP | 30/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\CS | VehService\CS<br>L096921 | | 25/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\DAMAGE | alloy plate needs bolts replacing | ALLOY PLATE NEEDS BOLTS REPLACING<br>Work order 201098<br>Look over alloy plate, all seems ok. | 24/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\MUDGUARDS | broken guards | BROKEN GUARDS<br>Did a temporary fix to guards as had time restrictions | 24/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Cooling\RADIATOR | engine temp running at 98 - 108 while operating on cold days | ENGINE TEMP 98-108 DEGREES WHILE OPERATING ON COLD DAYS<br>Recommend truck to come in loaded so can be tested properly<br>and determine what faults are coming up and monitor engine<br>temp via Cummins. No faults relating to truck over heating | 24/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Cooling\COOL LEAKS | drivers can smell coolant in cab | DRIVER CAN SMELL COOLANT IN CAB<br>Remove all covers over heater core but unable to find any<br>leaking coolant and coolant level was all ok. | 24/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP7+8 | Tyres\TP7+8 | | 17/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP5+6 | Tyres\TP5+6<br>extra seal needs putting around drivers door as it is still leaking air and when it rains or washing<br>truck it leaks. | FIT EXTRA SEAL AROUND DRIVERS DOOR, STILL LEAKING AIR AND<br>WATER | 17/09/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | DONE ON13/10/25 | Fit foam seal around door to prevent wind noise, all ok | 05/09/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Fuel light , cruise light , jake light, axel oil light not working<br>DONE ON 13/10/25 | HIGH BEAM LIGHT ON DASH N/W<br>Work order 200466<br>Remove dash and found globes for high beam blown. Remove<br>and replace globes and test operation, all ok.<br>KW80005002 HOLDER-GLOBE INCLUDE GLOBE | 05/09/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\Cool | DrivLine\Cool SMELL COMING INTO CAB | COOLING SMELL COMING INTO CAB<br>Removed LH cab panel and inspect cooling components.<br>Inspect for any leaks or low coolant level, all looked ok,<br>unable to fault | 05/09/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | hi beam light on dash not working<br>HIGH BEAM LIGHT ON DASH N/W<br>Work order 200466 | Remove dash and found globes for high beam blown. Remove<br>and replace globes and test operation, all ok.<br>KW80005002 HOLDER-GLOBE INCLUDE GLOBE<br>DONE ON 13/10/25 400853 | 05/09/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Cooling\COOL LEAKS | coolant smell coming into cab<br>DONE 30/8/25 AT 584416KMS<br>VehService\B1 Svc B 1 Service,<br>Jack up steer axle check bearings and kingpins.<br>Replace cabin filter. | COOLING SMELL COMING INTO CAB<br>Removed LH cab panel and inspect cooling components.<br>Inspect for any leaks or low coolant level, all looked ok,<br>unable to fault | 05/09/2025 | 615123 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | L096540 | MINI B SERVICE | 31/08/2025 | 591092 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | Elect\ELECT P&W | Repair rubbed wires . found 11 repaired<br>Rewire twisted cable from Trailer plug to head unit in cab.<br>Fix broken wire at back of cab. | 25/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BROWNYS MOBILE AUTO ELECT - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\SCALES | Chassis\SCALES | Reconnect correct wires into head unit as per Airweigh instruction. | 25/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BROWNYS MOBILE AUTO ELECT - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ENG FAN | Horton fan friction plate getting low | REKIT HORTON<br>Remove all components in way of Horton. Remove fan and belt<br>then loosened and removed Horton. Re-kit Horton as<br>required, re-mount and tension Horton. Check operation, all<br>ok | 22/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | Drivers side door hinge requires replacing | REPLACE DOOR HINGE<br>Remove interior panels and disconnect wiring. Remove door<br>from truck and strip door (Removed wind deflector and<br>replaced with new as per WD). Drilled out rivets holding<br>hinge, remove hinge then rivet on new hinge. Re-install all<br>components, run wiring through door, mount and adjust door<br>as required. | 22/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\MIRRORS | up/down mirror adjust not working on drivers side | REPLACE MIRROR<br>Remove old mirror and replace with new. Tension bolts to<br>spec and paint new cover white | 22/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CTCH PACK | DrivLine\CTCH PACK | ADJUST CLUTCH BRAKE<br>Inspect and adjust clutch to spec. Found one of the springs<br>to be completely snapped, requires clutch R&R.<br>Remove tail shaft, airlines off air tank, air tank, fuel<br>cross over bar and fuel hose, all electrical plugs, and<br>trans hoses. Remove all bell housing bolts and gearbox.<br>Remove clutch and flywheel. Remove and replace rear main<br>seal. Refit machined flywheel. Installed new clutch and<br>tension. Remove bolts for rear engine mounts, jack motor up<br>and replace engine mounts, then tighten bolts to spec.<br>Replace input shaft, bearing, front cover, gasket,<br>cross shaft bushes, and cross shaft. Refit gearbox and<br>tension bell housing bolts. Replace rear gearbox support<br>bushes and replace free play adjuster. Refit everything<br>taken off in removal process, and tension as required.<br>Road test truck, all ok. Grease clutch system, all ok | 08/08/2025 | 575257 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service | GREENFREIGHT A SERVICE<br>Carry out service as per Greenfreight checklist. | 07/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\MIRRORS | UP/DOWN MIRROR ADJUST N/W ON DRIVERS SIDE | Remove rear cover of mirror and tested power while<br>operating. Power okay. No new mirror motors in stock | 06/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Cooling\ENG FAN | HORTON FRICTION PLATE LOW | Inspect horton and measured wear pads and movement. Current<br>friction plate at 2mm, new one at 4mm. Will re kit when<br>doing door hinge repair | 06/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\MUDGUARDS | FIT NEW MUDFLAPS ON BACK GUARDS | Removed old mud flap and installed new | 06/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | BLOWN DASH GLOBE | Remove dash panel and replaced blown globe | 06/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\INDICATORS | LH INDICATOR N/W | Inspect LH indicator for fault. Found to have water in the<br>light. Removed light and replaced with new, test operation,<br>all okay. | 06/08/2025 | 579975 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\SCALES | REPLACE MALE PLUG AT BACK OF CAB - WEIGH SCALES NOT WORKING | Inspect and replace trailer plug from truck Suzi. Check<br>weight scales, still no gauge. Remove panel for gauge and<br>check power and earth, found no power. Trace wiring from<br>Suzi lead and found wiring rubbed through on deck plate.<br>Cut rubbed section out and run new twin core from rub<br>to trailer plug. Join with joiners, reassemble and test<br>operation, all working ok. | 04/08/2025 | 578751 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | see attached | 01/08/2025 | 575257 | Completed | Mt Gambier | STK | XV15VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | 31/07/2025 | 575257 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | CTI's losing gps connection please have a look at. needs fixing as wont adjust tyre pressure. | Remove old GPS aerial and replace with new one. Test operation, all ok | 30/07/2025 | 564747 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\EBS FAULTS | Test EBS | Tested EBS. Turned ignition on and all warning lights illuminated including ESC. Started truck and all light turned off. As they should Turned on off road switch and ESC and ABS warning lights flashed to indicated they were turned off. As they should turned off off road switch and lights turned off. As they should. | 24/07/2025 | 575257 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | VehService\BS B Service | 3 09KWZZZ723 GAUGES N/W | 17/07/2025 | 570457 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | spring pressure light out on guage done on 11/7/25 at 570457kms | Tech(s): 8080 113.75GAUGE LIGHTS N/W Remove dash panel and replaced blown globes in dash as required. KW800005002 HOLDER-GLOBE INCLUDE GLOBE 2 14.66KW800005002 HOLDER-GLOBE INCLUDE GLOBE | 16/07/2025 | 570457 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\SUZI COIL | loose plug on suzi coil at trailer end making lights flash done in mt gambier yard 14/7/25 at 570457kms | NO INDICATORS OR LOADING LIGHTS AT YARD, DRIVER PUSHED PLUG BACK IN AND NOW WOKRING BUT WOULD LIKE CHECKED Inspect wiring in truck plug, was unable to find any loose or disconnected wiring. Inspect further and found truck plug pin to be pushed in. Spread pins apart and cleaned. Test operation, all working ok. | 16/07/2025 | 570457 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\INDICATORS | blinker on passenger side flashing quickly done in mt gambier yard 14/7/25 at 570457kms | NO INDICATORS OR LOADING LIGHTS AT YARD, DRIVER PUSHED PLUG BACK IN AND NOW WOKRING BUT WOULD LIKE CHECKED Inspect wiring in truck plug, was unable to find any loose or disconnected wiring. Inspect further and found truck plug pin to be pushed in. Spread pins apart and cleaned. Test operation, all working ok. | 16/07/2025 | 570457 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | DrCabElect\INST/GAUGE | GAUGE LIGHTS N/W Remove dash panel and replaced blown globes in dash as required. | 16/07/2025 | 570457 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | ADBLUE BLOCKED Removed ad blue sender and replaced filter and flush out breather. Unblock pipe for breather filter, all ok | 16/07/2025 | 570457 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\SUZI COIL | Elect\SUZI COIL | NO INDICATORS OR LOADING LIGHTS AT YARD, DRIVER PUSHED PLUG BACK IN AND NOW WOKRING BUT WOULD LIKE CHECKED Inspect wiring in truck plug, was unable to find any loose or disconnected wiring. Inspect further and found truck plug pin to be pushed in. Spread pins apart and cleaned. Test operation, all working ok. | 16/07/2025 | 570457 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 09/07/2025 | 564747 | Completed | Mt Gambier | STK | XV15VU | BORDER BANDAG PTY LTD -3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\TRL FLOOR | Body\TRL FLOOR | MISSING CLIPS ON DECK PLATE Fit new locks to deck plate to keep secure, and fit new key to truck set. Tighten and adjust locks, all okay | 25/06/2025 | 561854 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\WINDSCREEN | passenger side windscreen has a big star/chip in it | Windscreen replaced by Weston Windscreen and Tinting | 24/06/2025 | 551020 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\LIGHTS | LHS headlight protector needs to be replaced | LH HEADLIGHT PROTECTOR NEEDS TO BE REPLACED work order 197943 Remove and replace LH headlight protector as per drivers request | 17/06/2025 | 559630 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\FUEL TANK | check magnet on add blue tank | CHECK MAGNET ON AD BLUE TANK work order 197943 Removed and tested magnet in ad blue filler neck, tested, not good. Got new filler from parts, installed, all ok | 17/06/2025 | 559630 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\FUEL TANK | both breathers on fuel tanks need cleaning out | CLEAN OUR FUEL TANK BREATHERS Work order 197943 Removed breather line and blew out. Reinstalled and tested, all ok | 17/06/2025 | 559630 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\RADIATOR | LOOSE CHROME SHROUND LHS RADIATOR. VIBRATES | GRILLE LH SIDE LOOSE AND VIBRATING Work order 197943 Driver complain grille was vibrating. Inspect and found top LH side bolt loose. Tighten loose bolt, all ok | 17/06/2025 | 559630 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\GEARBOX | Truck broken down on Millicent road has lost all gears | Truck broken down on Millicent road has lost all gears Travel to breakdown on Millicent Road. Inspect truck, found selector pin to have fallen out. Removed linkage cover, reinstall pin and get truck to workshop. Ordered new pin, installed bolt for time being, reinstall cover, all ok | 16/06/2025 | 559890 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Insp\ANN INSP | Annual Inspection | CARRY OUT ANNUAL INSPECTION AS PER GREENFREIGHT CHECKLIST | 15/06/2025 | 559630 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service | GREENFREIGHT A SERVICE Carry out service as per Greenfreight checklist. | 14/06/2025 | 559630 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CTI Drive | Air CTI still not operating correctly, when trying to deflate tyres not actually dropping pressure to tyres | Air CTI not working and GPS says lost cam. Lifted cab and removed cover from control box. Took control panel out of cab, run and test numerous times with control unit,. checked they were communicating correctly and all solenoids were working. Checked air flow between tyres, all okay. Checked air filter in CTI box, all okay. Put a pressure gauge onto tyres and checked PSI reading when dropping and filling, it read same as what control screen would say. Could not fault, checked wiring to control box, all okay. Order new GPS cable for truck | 29/05/2025 | 553875 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter. | | 27/05/2025 | 551020 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CTI Drive | tap on front drive need replacing drivers side | TAP ON FRONT DRIVE NEEDS REPLACING (DRIVERS SIDE) Work order 197265 Remove and replace broken air CTI tap. Checked CTI box, all okay. Repositioned GPS tracker and fault codes disappeared. Faults returned. Removed panel and check wiring on back of module, all okay. Followed wiring back to aerial, all okay. Repositioned aerial onto windscreen. If fault reoccurs, will need new aerial. | 27/05/2025 | 551020 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\AIR FITTIN | air hose needs trigger nozzle re attached | AIR HOSE NEEDS TRIGGER NOZZLE RE-ATTACHED Work order 197265 Cut nylon tube flush and refit to air nozzle. | 27/05/2025 | 551020 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | clutch brake needs adjusting | CLUTCH BRAKE NEEDS REPLACING Work order 197265 Carry out clutch adjustment as required. | 27/05/2025 | 551020 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\FIFTH WHEE | Chassis\FIFTH WHEE | CHECK TURNTABLE BOLTS Tension loose ripple plate bolts. | 27/05/2025 | 551020 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering\STEER UNI | Front input shaft movement - Monitor | CHECK FRONT INPUT SHAFT MOVEMENT Work order 197265 Inspect end float of input shaft bearing. 010 - 015' heat up lock nut and remove grub screw. Adjust bearing end float to 004' and fit grub screw, tighten lock nut | 27/05/2025 | 551020 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\WIPERS | new wiper blades fitted keep coming out apears wrong ones fitted | | 20/05/2025 | 545083 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | DrCabElect\INDICATORS | DrCabElect\INDICATORS | LH INDICATOR NOT WORKING<br>Arranged to meet driver at workshop. Tested truck for power at the plug,<br>found no power. Opened plug, found wire pulled out, removed all wires and cut to same length. Fit wires back to plug and put all back together. Test operation, all ok | 15/05/2025 | 548027 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS A Service | Work order 196377 | 27/04/2025 | 540095 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Fuel gauge light not working | Inspected dash, found fuel gauge light blown. Removed and replaced with new globe. | 24/04/2025 | 539044 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\WIPERS | needs new wiper blades and squirter nozzles adjusted | Removed old wiper blade and replace with new.<br>work order 196377 | 24/04/2025 | 539044 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Susp\Torque Rod | LH rear torque rod bush worn - replace next service | Found 3 worn bushes, removed and fit with new bushes<br>Inspected and found airbag to be worn. Jacked up chassis, | 24/04/2025 | 539044 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Susp\AIR BAG | REPLACE AIR BAG | removed airbag and replaced with new. Once fitted pumped up | 24/04/2025 | 539044 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | CHECK BELTS - REPLACE DUE TO WORN | 22/04/2025 | 540095 | Completed | Mt Gambier | STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\BELTS/TENS | Engine\BELTS/TENS | Found fan belt was worn, loosened tensioner and replaced belt. Tensioned belt<br>Rose joints worn, needs replacing | 11/04/2025 | 530687 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering\UNI JOINTS | Steering\UNI JOINTS | Rose joints worn, removed bolts and removed rose joints. Installed new, tightened to spec.<br>ENGINE MOUNTS - REPLACE DUE TO WEAR | 11/04/2025 | 530687 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\MOUNTS | Rear engine mounts worn | Front engine mounts were worn, loosened mounts and jacked up engine. Hit out mount and installed new. Lowered engine and tightened bolts. | 11/04/2025 | 530687 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | VehService\BS | REPLACE AIR BAG - FR DRIVE AIR BAG | 04/04/2025 | 530687 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Susp\AIR BAG | Susp\AIR BAG | Jack up chassis. Remove airline from top of airbag. Remove top 2 bolts, and bottom nut. Remove and fit new airbag. Tensioned bolts and connect air lines. Checked operation, all okay. | 26/03/2025 | 526369 | Unlocked | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\SUZI COIL | Chassis\SUZI COIL | REMOVE AND REPLACE SUZI COIL<br>Inspect and found 7 pin narva plug snapped, got new plug from parts remove old plug fit new one check operation all okay | 26/03/2025 | 524853 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | Elect\ELECT P&W | Turn airline taps out of the way. Repair broken wiring for scales | 25/03/2025 | 523806 | Completed | Mt Gambier | STK | XV15VU | TRIPLE S DISTRIBUTORS - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS | Carry out service as per Greenfreight checklist.<br>Inspect air filter and replaced with new | 20/03/2025 | 520871 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | CTI\CTI Drive | CHECK LHR DRIVE TYRE FOR AIRLEAKS - KEEPS GOING FLAT | Inspect tyre, found a leaking fitting on Air CTI rotator. Removed fitting on rotator and reinstalled with new thread sealant. Checked, no further leaks. | 20/03/2025 | 520871 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | engine oil and turbo boost gauge lights not working | Removed dash cluster and replaced blown globes. Refitted dash, checked, all okay. | 20/03/2025 | 520871 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\BATTERY | SUPPLY & FIT 4 NEW BATTERIES | | 08/03/2025 | 519138 | Completed | Mt Gambier | STK | XV15VU | QT DIESEL SERVICES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\GEARBOX | Check operation of gearstick cant get gears at Millicent bypass near KCA | Travelled to truck at Millicent bypass. Checked gear selector operation. Operating side to side but not front to back. Inspect gear linkages while driver moved gearstick, linkages all operating okay. Found pin had come out of selector arm and snapped. Hit pin into selector arm, now operating gears, return to BMG workshop and ordered new part.<br>Removed gear selector cover, removed bolt and fitted new pin. Refitted cover | 27/02/2025 | 520871 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\BRK LIGHT | Elect\BRK LIGHT | Trailer plug broken at bypass near main gate of sale yards<br>Travelled to truck at sale yards. Removed broken casing around trailer plug. Fit new casing and checked lights, all okay. Return to workshop. | 25/02/2025 | 514329 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | VehService\B1 Svc | MINI B SERVICE<br>Jack up steer axle, check bearing & king pin. Replace cab filter<br>Carried out Mini B Service as per Greenfreight checklist<br>Replace cab filter and air filter.<br>Customer Instructions:<br>Greased and Adjusted Brakes<br>Checked all Fluid Levels<br>Completed paperwork & Cleaned area<br>Replaced cabin air filter | 20/02/2025 | 510377 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\ELECT P&W | guardian device cover loose<br>light staying on | GUARDIAN DEVICE COVER LOOSE AND LIGHT STAYING ON<br>Work order 193768<br>Resecured guardian cover. Unsure about light staying on, not a BMG repair | 19/02/2025 | 510377 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\ST Weel | steering wheel out of alignment pointing to 10 o'clock when going straight | STEERING WHEEL OUT OF ALIGNMENT<br>Work order 193768<br>Removed steering shaft from box. Moved to have straight steering wheel. Refit shaft and tighten bolts. | 19/02/2025 | 510377 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | mirror heat light on dash not working | ENGINE BRAKE & MIRROR HEAT GLOBES N/W<br>SWIVEL INTERIOR LIGHTS N/W<br>Removed dash cluster and replaced blown globes as needed. Also replaced interior swivel lights | 19/02/2025 | 510377 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | 17/02/2025 | 512978 | Completed | Mt Gambier | STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP7+8 | Tyres\TP7+8 | | 17/02/2025 | 512978 | Completed | Mt Gambier | STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\DAMAGE | Chassis\DAMAGE | Straighten tow bin<br>Tow pin bent from getting bogged, attempt to cut old pin out but had to get oxy and get out. Fit new tow pin | 30/01/2025 | 503090 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | Clutch has no clutch brake | INSPECT CLUTCH BRAKE<br>Actuated clutch and inspected. Found clutch brake had a massive gap. Carried out clutch adjust as required. Tested operation, all okay. | 24/01/2025 | 503090 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS | GREENFREIGHT A SERVICE<br>Carry out A service as per Greenfreight checklist.<br>Replaced dirty air cleaner, topped up engine oil.<br>Customer Instructions:<br>Completed paperwork & Cleaned area | 19/01/2025 | 499839 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DIFF OIL | DrivLine\DIFF OIL | REPLACE DIFF OIL<br>Drained and replaced diff oils. | 19/01/2025 | 499839 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | DrCabElect\INST/GAUGE | Remove dash panel, replaced blown globe as required | 18/01/2025 | 502364 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | volt gauge not working | Remove dash and checked gauge, found plug had fallen out, resecure, all working okay.<br>VOLT GAUGE N/W<br>Work order # 188540 | 18/01/2025 | 502364 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | volt guage not working | Inspect volt gauge for fault, found all working as required.<br>Noticed axle oil temp gauge was out, replaced blown globe | 16/01/2025 | 499839 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | DriCabRep\AIR CON | the fan in the heater/aircon needs fixing | FAN IN HEATER / AIR CON NEEDS FIXING<br>Work order 188540<br>REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563<br>Inspect A/C and heater for concern, found to be making a very bad noise. Removed dash panels, found blower fan was faulty and mounts were worn. Unplugged blower fan, installed new. Secured mounts, refit dash panels. Operated A/C and heater, both working okay. | 16/01/2025 | 499839 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 15/01/2025 | 500597 | Completed | Mt Gambier STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP5+6 | Tyres\TP5+6 | | 10/01/2025 | 499217 | Completed | Mt Gambier STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | 10/01/2025 | 499217 | Completed | Mt Gambier STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP07 | Tyres\TP07 | | 07/01/2025 | 496838 | Completed | Mt Gambier STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | VehService\BS | | 06/01/2025 | 496838 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\FITMENT | Reseat All Drive Tyres On Rims Due To Driver Leaving CTI Taps On & All Drives Going Flat Positio | | 02/01/2025 | 496838 | Completed | Mt Gambier STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\MIRRORS | Body\MIRRORS | REPAIR MIRROR COVER MISSING<br>Inspected mirror bracket & attempted to straighten. Unable to fix, quoted new mirror bracket & covers. Parts ordered. Removed mirror bracket & internal trim to access wiring. Fit new mirror & brackets & reconnected wiring. Repaired corroded plug in the rear of door. Re fit work lights and connect wiring. Fit door trim back in place & fit painted covers | 20/12/2024 | 481161 | Completed | Mt Gambier STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | FIT NEW AD BLUE HOSE<br>Remove old hose & swap fittings over. Heat shrink wrap & fit new ad blue hose. Zip tie into place to secure. Clean all excess ad blue off & check for leaks. All ok. Monitor & check at next service | 29/11/2024 | 488358 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\WINDOW REG | Passenger window sticking when lowering and raising | PASSENGER SIDE WINDOW STICKING WHEN LOWERING OR RAISING<br>On inspection found window was dragging on window seal. Sprayed silicone spray on window seal, moved window up & down. Window now tracking ok. Cleaned window, all ok. | 29/11/2024 | 488358 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\MIRRORS | driver side mirror wont adjust up or down | DRIVERS SIDE MIRROR WONT ADJUST UP AND DOWN<br>Inspected switch for mirror, all looked ok. Removed mirror & cover of RHS. Check wiring & found earth pin had bad connections. Pushed it into place. All ok. Refit mirror & cover back in place and tested operation. All ok | 29/11/2024 | 488358 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Cooling\COOL LEAKS | strong smell of coolant in cab might have small leak behind dash | STRONG SMELL OF COOLANT BEHIND DASH<br>Inspected truck for coolant leak. Unable to find any leaks. Could not smell coolant. Checked coolant levels, all look normal | 29/11/2024 | 488358 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\ELECT P&W | cruise control light not working | CRUISE CONTROL LIGHT N/W<br>Removed dash, & inspect globe. Found cruise globe to be blown. Removed globe & replaced with new. Refit the dash. All ok | 29/11/2024 | 488358 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | AD BLUE LIGHT ON DASH<br>has been on since yesterday<br>Plugged PC into truck and checked for codes. Found active codes 3548 'loss of prime'. Followed diagnostic procedure & found ad-blue hose between filter & doser was leaking. Part needed to be ordered as none in stock. Fit joiner to temporarily fix until part arrives. Carried out pump override test & flushed pump. Fitted injector into jar & measured quantity of ad-blue injected. All ok. Found breather to be blocked on tank. Removed & cleaned the breather. Lowered cab and re secured bull bar. | 26/11/2024 | 487959 | Completed | Mt Gambier STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\WHEEL SEAL | CHECK WHEEL SEAL RH DRIVE | Moved truck over pit, jacked up axle. Backed off brake, removed wheels and brake drum. Removed hub and wheel seal. Cleaned bearings and hit in new seal. Cleaned brake shoes, reinstalled. Refit hub and adjust wheel bearings to spec. Refit brake drum and wheels, tensioned wheel nuts. Reinstalled axle with renzoil. | 13/11/2024 | 484419 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\DAMAGE | Body\DAMAGE | INSPECT NOISE IN DIFF<br>Test drive truck to inspect noise complaint. Very bad grinding noise. Check under truck and steering, all okay. Applied more grease to turntable and recheck, no change. Disconnect truck and trailer, inspect wear pads and found to be worn. Remove and replace wear pads. Test drive, all okay.<br>Truck returned, noise had come back. Reinspect with other technicians, all diagnosed to be coming from turntable area, advised to unload trailers and come back to workshop. Checked skid plate, found was not completely straight but was warped. Use straight edge to inspect. Cleaned out dirt from king pin and horse shoe, applied new grease. Reconnect trailers. Noise has gone but trailer needs to be repaired major issue with skid plate. | 13/11/2024 | 481657 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 07/11/2024 | 480162 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\SCALES | Check operation of scales not reading correctly and CTI keeps saying dump or inflate only.<br>needs new volmeter | Found the air loss was due to taps being turned on for the wrong set of suzi coils & a kinked over line causing the air to drop which affected the scales. Repaired the kinked airline and rerouted. Found the CTI problem was due to the taps not being turned on at all, retested all okay. | 28/10/2024 | 475717 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Cruise control light out on dash and voltmeter gauge is not reading correctly.<br>Inspected & replaced cruise globes. Checked volt meter, found 10.7v at rear of gauge. Traced wiring. Removed fuse at alternator & cleaned and tightened contacts. Refit dash<br>cluster | | 10/10/2024 | 469263 | Completed | Mt Gambier STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | VehService\B1 Svc | | 10/10/2024 | 470000 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | cruise control light out on dash | reading correctly.<br>Inspected & replaced cruise globes. Checked volt meter, found 10.7v at rear of gauge. Traced wiring. Removed fuse at alternator & cleaned and tightened contacts. Refit dash<br>Plugged into truck and found active codes for airside out of pump. Carried out diagnostics, after pumping hot water through air system was still no good. Next step on diagnostics was to replace doser pump, as the air solenoid in the pump had failed.<br>Once doser pump was replaced carried out override test and codes went inactive. | 10/10/2024 | 469263 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | Engine\ADBLUE | Road tested and all okay | 01/10/2024 | 465129 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ALT | Elect\ALT | CHECK ALTERNATOR VOLTAGE<br>Lifted cab, checked alternator voltage, 13.86 volts, all okay. Lowered cab and tightened bull bar. | 01/10/2024 | 466337 | Completed | Mt Gambier STK | XV15VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | Chassis\FUEL TANK | after treat light on | Connect laptop to truck and inspect fault codes. Found code for blockage on air side. Disconnect hose and flushed system to unblock air side of pump. Carried out override test, fault became inactive. Take truck for a test drive, no further faults. | 20/09/2024 | 460046 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS | | 17/09/2024 | 459888 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | DriCabRep\DOOR LOCK | Inspect door for fault, found to be bent. Loosen hinge and straighten out door. Tightened bolts on hinge and checked for leaks, all okay | 17/09/2024 | 459888 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DIFF REPMN | DrivLine\DIFF REPMN | CHECK DIFF PINION MOVEMENT AND ADJUST AS REQUIRED<br>Check and adjust pinion movement, found to be at 20 thou. Remove deck plkate, removed bolt and adjust bearing cage two more splines. Test movement, adjust one more turn and recheck. Found to be at 3 thou, within spec. Refit guiding bolt and locking nut. Tensioned. Refit deck plate. | 17/09/2024 | 459888 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\BRK RELINE | Brakes\BRK RELINE | Replace RL drive brake<br>Disconnect air CTI lines, jacked axle and removed wheels. Removed brake drum and shoes. Installed new brakes and hardware. Refit wheels, lowered axle and tensioned wheels. Connect air CTI lines and adjust brakes | 17/09/2024 | 459888 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | driver side wind deflector keeps falling off | | 17/09/2024 | 459888 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | spring pressure gauge light not working | Inspect for ad blue fault. Found tank was sucked in and breather was blocked. Replaced filter and cleaned out lines from crystalised ad blue. Light became inactive, cleared | 17/09/2024 | 459888 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\FUEL TANK | after treat light on dash is on | faults. | 16/09/2024 | 460046 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | Repair trailer plug | 09/09/2024 | 458508 | Completed | Mt Gambier | STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\BREAKDOWN | Repair Damaged Trailer Light Plug, After Hours Call Out. (Barry Maney P/O: L088468) | Drove to BMG workshop, collected parts required. Removed & replaced trailer plug. Tested operation. All ok. | 29/08/2024 | 454415 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\FUEL TANK | Engine Not Starting Sounds Like Air Lock. (Barry Maney P/O: L088446) | CHECK ENGINE FOR NOT STARTING AT NF MCD MILL UP THE TOP. TURNS OVER BUT NO FIRE POSSIBLY SUCKED IN SOME AIR<br>Truck arrived at workshop, possible fault in fuel cross overs. Checked breathers and taps, all okay. Inspect fuel cross over pipe, all okay. Checked fuel and found to be equal in both tanks. Unable to fault, driver to monitor. | 24/08/2024 | 452994 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | B Service | | 21/08/2024 | 449418 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | Scales Dropping Out. (Barry Maney P/O: L088344) | SCALES DROPPING OUT ON DISPLAY UNIT<br>Inspect screen, removed panel from dash. Inspect plug and wiring, all okay. Inspect fuses and found screen to cut out when moving fuses. Found one fuse with hairline crack. Replaced fuse with new, tested, all okay. | 21/08/2024 | 451581 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\HOUSEKEEP | Check Dash Lights. (Barry Maney P/O: L088344) | CHECK DASH LIGHTS<br>Remove dash cluster and replaced blown globe. Refit dash, all okay. | 21/08/2024 | 451581 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | Check & Adjust Clutch. (Barry Maney P/O: L088344) | ADJUST CLUTCH<br>Carried out clutch adjustment as required. | 21/08/2024 | 451581 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\HOUSEKEEP | Replace Weather Sheild. (Barry Maney P/O: L088344) | REPLACE WEATHER SHEILD<br>Remove loose weather sheild. Cleaned surfaces and installed new weather sheild. | 21/08/2024 | 451581 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 18/08/2024 | 445812 | Completed | Mt Gambier | STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS<br>leather on steering wheel half missing and frayed (is it possible to repair)<br>Repalce steering wheel<br>Removed horn cover and unplugged horn and clock spring. Removed steering wheel and installed new. Refit all components, make sure steering wheel was straight. | | 12/08/2024 | 440332 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\ST Weel | KWS91-1014-110 WHEEL - STEERING | | 31/07/2024 | 440519 | Completed | Mt Gambier | STK | XV15VU | PACCAR PARTS FLEET SERVICES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | AFTER TREATMENT LIGHT<br>Connect laptop and checked faults, found fault code for nox sensor low voltage. Cleared code, monitorAD BLUE BREATHER BLOCKED removed ad blue breather, flushed system and cleaned out breather. Refit components. | | 25/07/2024 | 433861 | Completed | Mt Gambier | STK | XV15VU | PACCAR PARTS FLEET SERVICES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | REPLACE RUBBER ON DRIVERS SIDE TOOL BOX<br>Removed rubber from tool box, cleaned mounting surface and installed new rubber.<br>KWT42-1001-1770 SEAL -TOOLBOX/SLEEPER DOOR 1 Internal<br>KWT42-1001-1770 SEAL -TOOLBOX/SLEEPER DOOR | | 25/07/2024 | 433861 | Completed | Mt Gambier | STK | XV15VU | PACCAR PARTS FLEET SERVICES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\YEL VALVE | YELLOW PARK LEAKING AIR<br>Inspect yellow park brake button for air leaks, could not locate air leak. Applied, disabled and reapplied, no faults.<br>REPLACE RUBBER ON DRIVERS SIDE TOOL BOX<br>Removed rubber from tool box, cleaned mounting surface and installed new rubber.<br>KWT42-1001-1770 SEAL -TOOLBOX/SLEEPER DOOR 1 Internal | | 25/07/2024 | 433861 | Completed | Mt Gambier | STK | XV15VU | PACCAR PARTS FLEET SERVICES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRepL\AIR BAG | KWT42-1001-1770 | | 25/07/2024 | 433861 | Completed | Mt Gambier | STK | XV15VU | PACCAR PARTS FLEET SERVICES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | VehService\AS<br>TRAVELL OUT TO PINE HALL AVE AND REPLACE TRAILER PLUG<br>Travelled to truck on Pine hall Ave, found male suzi plug had snapped. Removed 7 pin plug and replaced with new. Tested operation, all okay. | | 18/07/2024 | 435115 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | KW82161BL PLUG-TRAILER,6MM CABLE,7PIN | | 10/07/2024 | 425941 | Completed | Mt Gambier | STK | XV15VU | PACCAR PARTS FLEET SERVICES - 4 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | after treat light staying on<br>ad blue breather blocked | CHECK AFTER TREATMENT LIGHT ON DASH<br>ad blue breather blocked as well<br>Plugged into truck too check fault codes, found NOX sensor code and loss of prime code. Also driver mentioned the adblue tank breather was blocked, put cab over removed tank pick up and drilled out very blocked breather fitting and flushed with water. Refit sender and reconnect lines etc. Diagnosed faulty nox sensor. Removed sensor and replaced with new, complete doser flush test. All okay. Refit injector to exhaust, lower cab, road test and drop back to GF yard. | 04/07/2024 | 423779 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ADBLUE | done by B/M when after treat fault was repaired refer 381906 invoice | | 02/07/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\DAMAGE | Body\DAMAGE | REPAIR LOG DAMAGE<br>repair fibreglass surface<br>replace windscreen<br>replace mirror cover<br>replace weather shield<br>Removed broken shield & double sided tape. Cleaned the area and fit new weather shield in place.<br>Arranged mirror cover to be painted. Installed new cover.<br>Arranged windscreen to be replaced and surfaces be repaired from damage | 21/06/2024 | 425941 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | B 1 Service P/O: L086807<br>SERVICE KMS 418349 | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | | | 20/06/2024 | 416577 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | A/HRS BREAK DOWN - MUD GUARD POLE BOLT SNAPPED | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Body\MUDGUARDS | Hit out broken bolt in guard. Installed new bolt and nut, tensioned. | | 14/06/2024 | 420337 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\BELTS/TENS | FAN BELT | Inspected engine components & found fan belt was worn. Removed & replaced, ok. | 05/06/2024 | 411450 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | ADJUST CLUTCH | Carried out clutch adjust to spec check operation all okay. | 05/06/2024 | 411450 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CTI Drive | AIR CTI LEAK | Removed cover off valve box & trace wiring from cab, found wire pulled out of module. Removed wiring & cut outer sheath, ma | 05/06/2024 | 411450 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | DASH LIGHTS | Remove cluster, voltmeter, dash & globe. Fit new globe & holder. Refit cluster, test all okay | 05/06/2024 | 411450 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Wodonga - Workshop | VehService\AS | A Service | KM's 411756 | 05/06/2024 | 411450 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ENG TUNE | Engine\ENG TUNE & replace exhaust manifold gaskets | | 31/05/2024 | 404200 | Completed | Mt Gambier | STK | XV15VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| | | | INSTALLED NEW BULL BAR - Removed front bumper & mounting bracket. Mount up bull bar mount bracket and fit bar up.<br>Mounted spot lights & ran wires, secure, ok. Supply & fitted new road train sign decals. PARTS $67.90 \| LABOUR $607.50<br>YELLOW BUTTON LEAKING AIR - Removed loose yellow & red button nuts. Removed trim panel bolts & hit pin out of<br>buttons. Remove nuts, pull trim off & removed air hoses on yellow button module. Swap over fitting & fit hoses to new<br>module. Fitted trim back on and re-fitted yellow & red button nuts. Position yellow & red button in place & hit roll pins back<br>in. Tightened button nuts & trim bolts, started truck & build up air. Tested, ok. PARTS $152.68 \| LABOUR $405<br>REPLACE BROKEN RH HEADLIGHT COVER - Replaced head light cover. PARTS $155.64 \| LABOUR $67.50 | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Chassis\HOUSEKEEP | REPLACE BOTTOM 2 BATTERIES - Both bottom batteries were faulty. Removed & replaced both bottom 2 batteries | | 29/05/2024 | 394468 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyres\TP1+2 | | 21/05/2024 | 394468 | Completed | Mt Gambier | STK | XV15VU | BEAUREPAIRES - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\CS | C Service PO# L048291 | | 21/05/2024 | 394468 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | AFTER HRS BREAKDOWN - JUMP START<br>Travel to Greenfreight yard, lifted cabin and jump started vehicle. Check to see if batteries are charging | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Elect\BREAKDOWN | all within spec. Travel back to workshop. | | 10/05/2024 | 394468 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | LH FRONT DRIVE WHEEL SEAL - Backed off brake, jacked up and removed axle. Removed hub with<br>wheels & cleaned wheels at wash bay. Hit out seal & hit new seal in after cleaning bearings. Cleaned<br>off backing plate & axle. Found brake linings had oil contamination, fitted new brakes & refitted wheels. | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Steering\WHEEL SEAL | Adjusted wheel bearing & refit axle. Adjusted brakes, all okay. | | 28/04/2024 | 391226 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | INPUT FRONT DIFF LEAK - Found input to front diff leaking quite badly. Removed drive shaft & yoke.<br>Heated nut up with Oxy, removed seal out of diff, cleaned & fitted new seal. Fitted yoke, refitted tail | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | DrivLine\DIFF OIL | shaft & fitted new bolts. Tensioned. | | 28/04/2024 | 391226 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Comp | ROAD TRAIN SIGNS - Cleaned bumper bar & fitted road train signs. | | 28/04/2024 | 391226 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\FUEL TANK | ADBLUE CAP TO HARD TO UNDO & DO UP. | REPLACE AD BLUE CAP - Supply and fit new ad blue cap. | 28/04/2024 | 391226 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | PO# L085584 | | 27/04/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\YEL VALVE | YELLOW BRAKE BUTTON, WHEN APPLIED LEAKS AIR. | | 27/04/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 27/04/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\BULLBAR | SUPPLY 2 X TOW HOOKS FOR BUMPER BAR | | 25/04/2024 | 394468 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | A/HRS CALL OUT - JUMP START<br>Travelled to Greenfreight yard, removed battery box and jump started truck. Checked all | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Engine\BATTERY | running ok. | | 23/04/2024 | 388444 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP5+6 | Tyre Position 5 + 6 | | 06/04/2024 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyre Position 3 + 4 | | 06/04/2024 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | FUEL & TEMP LIGHTS NOT WORKING ON GAUGES.REFER ENTRY 185065 JOB 435011 and also on | | 04/04/2024 | 379950 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | FUEL & TEMP LIGHTS N/W ON GAUGES - Removed dash cluster, replaced blown globes as | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | required. Refit dash. | | 04/04/2024 | 379950 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 04/04/2024 | 379950 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Service As Per Attached Checklist<br>**MINI B-SERVICE** | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | PO# L085101 | | 04/04/2024 | 379950 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | ALT. NOT CHARGING/LIGHT ON - When going to deliver truck ALT light come on, test alternator out put found only putting out 12volts. Disconnect batteries, remove cables from alternator and<br>remove old alternator. Fit new and re connect cables, reconnect batteries and start and check out put | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Engine\ALT2 DR | 14.5V. All okay deliver truck. | | 10/03/2024 | 369177 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | PO# L084544 | | 10/03/2024 | 369177 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 10/03/2024 | 369177 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | STILL HEAR AIR COMING IN DRIVER'S SIDE DOOR. | | 09/03/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\SEAT | NEED A LAMBS WOOL SEAT COVER TO RELIEVE BACK ACHE. | REPLACE SEAT COVER: BLACK LAMBS WOOL - Took off old seat cover and replaced with new seat cover | 09/03/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\ELECT P&W | TRUCK KEEPS BLOWING FUSES THAT CONTROLS ENGINE BRAKE ETC. | TRUCK BLOWING FUSES - Checked over all wiring for any obvious faults - couldn't fault. Checked operation of jakes and found they were working fine. Further inspection found dash light out, replaced and tested - all ok. | 09/03/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\ELECT P&W | GET A 12V PLUG (CIG) WITH 20 AMP FUSE PUT ON PASSENGER SIDE- REAR OF SEAT TO RUN AN | FIT 12V PLUG WITH 20A FUSE - Fit second plug on on LH side of seat, wire into fuse box & run wiring, mount accessory socket to seat. Check operation all okay. | 09/03/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | DOOR STILL LETTING AIR IN & STARTED TO LEAK WATER WHEN IT RAINS OR GETS WASHED. | | 09/03/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\BELTS/TENS | REPLACE FAN BELT - Inspected belts, found belt to be worn. Replaced fan belt - all ok. | | 09/03/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | CHECK FOR GRINDING NOISE IN FRONT END - Complaint of grinding noise when turning. Jacked up LH steer axle, check wheel bearings and king pins, all okay. Jacked up RH steer axle, check wheel<br>bearings and king pins, all okay. On further inspection, found turntable had hard debris stuck in wear | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Chassis\FIFTH WHEE | pads. This was cleaned out when disconnecting from trailers. Driver to monitor. | | 22/02/2024 | 359828 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Service As Per Attached Checklist | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\BS | PO# L084040 | | 17/02/2024 | 359828 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 17/02/2024 | 359828 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 09/02/2024 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | PO# L083554 | | 28/01/2024 | 350743 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 28/01/2024 | 350743 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | REPAIR PASSENGER SIDE STEP - Travel to Greenfreight and cut bolts off damaged step, straighten<br>step best we could and get photos for insurance order parts. Once parts arrived removed all required<br>parts from LH side, install new panel and huck into place. Fit rest of LH steps, found parts had not<br>ordered enough steps to complete repair. Once correct steps arrived fit all correct steps & bolt into | | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Body\DAMAGE | place. Replaced step lights as old one was damaged. | | 18/01/2024 | 339267 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | Tyres\TP7+8 | Tyre Position 7 + 8 | | 16/01/2024 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\GPS | DVR health check. | | 12/01/2024 | 421493 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\COOL LEAKS | COOLANT LEAK - Inspect coolant leak, found transfer hose o'ring was leaking. Drained coolant and disconnect transfer pipe housing. Cleaning mounting surface & installed new gasket. Replaced o'ring on pipe. Refit transfer pipe, refilled coolant<br>Road tested, no further leaks. | | 22/12/2023 | 334734 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\WIPERS | REPLACE WIPER BLADES & LH ARM - Removed LH wiper arm, found to be unserviceable. Fit new arm & wiper blade.<br>Replace RH wiper blade. | | 22/12/2023 | 334734 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\GOV VALVE | GOVERNOR VALVE - On inspection, found governor valve was constantly exhausting. Removed valve from compressor<br>Change fittings over to new valve. Cleaned gasket surface on compressor, connect air lines to new valve & installed.<br>Built up air & checked, pressure okay. | | 22/12/2023 | 334734 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\SEAT | REPLACE SEAT BELT - Removed seat cover. Remove seat base & anchor point for seat belt. Remove seat skin &<br>replaced seat belt. Refit all components.<br>Service As Per Attached Checklist<br>** MINI B SERVICE** | | 22/12/2023 | 334734 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | PO#L083044 | | 20/12/2023 | 339247 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 20/12/2023 | 339247 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | ORDER NEW DOOR SEAL - Removed the passenger door seal that was worn. Cleaned surfaces & installed new seal. Tested operation. All okay.<br>after hours call out 10pm - 11:30pm | | 20/12/2023 | 339247 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\TRL LIGHTS | Diagnose and repair fault for trailer park lights | | 07/12/2023 | 331575 | Completed | Mt Gambier | STK | XV15VU | QT DIESEL SERVICES - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\SEAT | SEAT BELT GETTING JAMMED - ordered new seat belt | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Body | TIGHTEN GRILLE - Found grille was missing a bolt. Installed new bolt & tightened. Check over and tighten all others. | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | SPEED LIMIT CETIFICATE - carried out speed limiter check as required. | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\EXHAUST | CHECK EXHAUST LEAK - Locate exhaust leak. Removed the clamp & found exhaust gasket leaking. Removed gasket & installed new gasket & clamp. Tested operation, no further leaks | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | REPALCE DASH LIGHTS N/W - Found 2 dash lights out. Removed dash cluster, removed faulty lights & replaced with new. Refit dash, lights working okay. | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | CLEARNACE LIGHTS TO COME ON W IGNITION - Connect wiring from lights to the relay in the battery box, turned key on to accessories, all clearance lights illuminate with ignition.<br>Carry out A Service as per job card for T909 X15 | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | PO# L082820 | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 06/12/2023 | 331177 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine | BLOCKED BREATHER - Removed the sender unit & flushed out the breather tube to clear any blockages. Refit sender unit. Checked breather and found to be blovked. Replaced breather canister.<br>Test operation, all okay. | | 15/11/2023 | 319448 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | DOOR SEAL LEAKING - Loosened the door hinge & adjusted the top on the door inward towards the cab. Tighten the hinge and test operation, all working okay.<br>Service As Per Attached Checklist | | 15/11/2023 | 319448 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | PO# L082260 | | 15/11/2023 | 319448 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Carry out A Service as per job card for T909 X15 | | 15/11/2023 | 319448 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | PO# L082052 | | 05/11/2023 | 313981 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 05/11/2023 | 313981 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | ADJUST CLUTCH - carried out clutch adjustment to spec, all okay. | | 05/11/2023 | 313981 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | DASH LIGHTS - removed dash panel and replaced blown globes as required. Tested, all okay.<br>refit dash and secured. | | 05/11/2023 | 313981 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | CTI\CTI Drive | CTI TAPS LEAKING - Removed leaking taps and replaced with new. | | 05/11/2023 | 313981 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\DOOR LOCK | CHECK LEAKING DOOR SEAL - readjusted RH door, sealing okay. | | 05/11/2023 | 313981 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 17/10/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Albury - Workshop | Tyres\TP9+10 | Tyre Position 9 + 10 | | 17/10/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Body | FIT TOW HOOKS TO FRONT OF TRUCK - Supply & installed two new tow hooks to front bumper.<br>Tensioned bolts to spec. | | 12/10/2023 | 299351 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 12/10/2023 | 299351 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | PO#L081583 | | 12/10/2023 | 299351 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | Body | FIT TOW HOOKS TO FRONT OF TRUCK - Supply & installed two new tow hooks to front bumper.<br>Tensioned bolts to spec. | | 12/10/2023 | 299351 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\BATTERY | AFTER HRS BREAKDOWN - jumpstart<br>Travelled to yard, jacked cab, connect jumper pack & jump start truck.<br>Carry out A Service as per job card for T909 X15 | CHECK & LOAD TEST BATTERIES - Disconnect terminals & load tested all batteries. All had failed. Removed faulty batteries & replaced with new. reconnected battery cables & secured. Tested starting all okay. | 25/09/2023 | 290709 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L081222 | | 23/09/2023 | 290706 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\WINCH/STRP | CHECK BINDER. A COUPLE LOCKING. NEED BAR TO LOOSEN. | | 23/09/2023 | 290706 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\PANELS | TIGHTEN GRILL. HANGING LOOSE. | | 23/09/2023 | 290706 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>AFTER HOURS BREAKDOWN - JUMP START<br>Travelled to Greenfeight yard. Jacked cab, connect jumper pack & jump start truck. Checked alternator | | 23/09/2023 | 290706 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\BATTERY | charge, all okay.<br>AFTER HRS BREAK DOWN - JUMP START TRUCK<br>Travelled to Greenfreight, jacked cab & connect jumper pack. Started truck, tested alternator, | | 20/09/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\BATTERY | all okay.<br>Annual insepction as per check sheet | | 12/09/2023 | 285724 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Insp\ANN INSP | Barry Manev PO# TBA<br>Service As Per Attached Checklist | CARRY OUT ANNUAL INSPECTION | 31/08/2023 | 279413 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | Barry Maney PO# L080628 | | 30/08/2023 | 279413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Carry out A Service as per job card for T909 X15 | | 30/08/2023 | 279413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L080274 | | 15/08/2023 | 272027 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 15/08/2023 | 272027 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering\WHEEL ALGN | Carried out wheel alignment as required. | | 28/07/2023 | 258445 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 28/07/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\FIFTH WHEE | TCTC supply parts | SWAP TURNTABLE WITH ONE SUPPLIED BY GF - 03/08/2023<br>Removed turntable from truck. Removed torque rods to access & remove air supply for trailer. Run and cable tie neatly in place. Refit torque rods and mount new turntable in place, tensioned mounting bolts to spec. Reroute hoses to allow for correct use with no rubbing. Test operation, okay. | 25/07/2023 | 265856 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Mini B Service As Per Attached Checklist | | | | | | | | | | |
| 1052 | Wodonga - Workshop | VehService\BS | Barry Maney PO# L079706 | | 21/07/2023 | 259642 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Tyres | STEERING SHUDDER. SHAKES WHOLE CAB AT 85-90KM. | WHEEL ALIGNMENT PERFORMED AT TRIDENT. | 21/07/2023 | 259642 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 21/07/2023 | 259642 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Tyres | STEERING SHUDDER. SHAKES WHOLE CAB AT 85-90KM. | | 21/07/2023 | | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body | Fit Bumper Bar | | 20/07/2023 | 259642 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\ROTATION | Rotation | | 29/06/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L079183 | | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\FUEL TANK | ADBLUE BREATHER BLOCKED. | | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering | STEERING PULLS. | | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\GEARBOX | WHEN PUT CLUTCH IN ALL THE WAY GEARBOX PRESSURE LIGHT COMES ON. | | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\FUEL TANK | ADBLUE TANK BUILDING UP VACUUM. (BLOCKED BREATHER) | | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\WIPERS | WINDOW WASHER NOT WORKING. | Done previous service. | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\MIRRORS | RIGHT HAND MIRROR NEEDS TIGHTENING. | Done previous service. | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | JAKE BRAKE LIGHT NOT WORKING. | Done previous service. | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 24/06/2023 | 250110 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService | | | 30/05/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 29/05/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Service As Per Attached Checklist | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\BS | PO# L078652 | | 29/05/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP10 | puncture repair | | 17/05/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 12/05/2023 | 232387 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L078251 | | 12/05/2023 | 232387 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | Repair Loading Light Switch | | 05/05/2023 | 307932 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | B 1 Service, | | | | | | | | | |
| | | | Jack up steer axle check bearings and king pins. | | | | | | | | | |
| | | | Replace cabin filter. | | | | | | | | | |
| 1052 | Wodonga - Workshop | VehService\B1 Svc | Barry Maney PO# L077830 | | 18/04/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | Replace windscreen | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Body\WINDSCREEN | Supply screen and arrange installation | | 23/03/2023 | 214117 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L077234 | | 15/03/2023 | 209862 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 15/03/2023 | 209862 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 23/02/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\WHL HUB | BM supply Hub Cap | | 15/02/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP7+8 | Tyre Position 7 + 8 | | 14/02/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP5+6 | Tyre Position 5 + 6 | | 14/02/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP3+4 | Tyre Position 3 + 4 | | 14/02/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | Tyre Position 1 + 2 | | 14/02/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | Service As Per Attached Checklist | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\CS | PO# L076628 | | 11/02/2023 | 199138 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine | CLUNK IN DRIVELINE TAILSHAFT/ DIFFS/ GEARBOX WHEN POWERING ON FROM COASTING. | CHECKED OVER. | 11/02/2023 | 199138 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | SCALES KEEP BLOWING EARTH/ NEGATIVE FUSES. WENT THROUGH 5 IN A 12 HOUR SHIFT. | | 11/02/2023 | 199138 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | CTI\CTI Elect | CTI "VALVE COMMS LOST" MESSAGE ON SCREEN, NO PRESSURE VALVE READING. | | 11/02/2023 | 199138 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 11/02/2023 | 199138 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| | | | Service As Per Attached Checklist | | | | | | | | | |
| | | | Barry Mayne Carrying Out B Service | | | | | | | | | |
| 1052 | Wodonga - Workshop | VehService\BS | Purchase Order Number: WW076254 | | 20/01/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 20/01/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | Service As Per Attached Checklist | | 20/01/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 20/01/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 20/01/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | VehService\AS | Service As Per Attached Checklist | | 20/01/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | Greenfreight Logging, Test/Repair 2x air transducers | | | | | | | | | |
| | | | Greenfreight fleet #1052. | | | | | | | | | |
| | | | EA-A4-1064 - Unrepairable. No replacement required. | | | | | | | | | |
| | | | EA-A4-0774 - No fault found. Changed the filter and cleaned down unit. | | | | | | | | | |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | Unit works fine. Collected by Scott Alexander 17/1. | Test/Repair 2x 490 loadcells | 19/01/2023 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | No Park Lights On Trailers | | | | | | | | | |
| | | | The Truck Specialists Are Attending | | | | | | | | | |
| 1052 | Wodonga - Workshop | Elect\TRL LIGHTS | Purchase Order Number: WW076028 | | 06/01/2023 | 421493 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | VehService\AS | Service As Per Attached Checklist | | 24/12/2022 | 179729 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 24/12/2022 | 179729 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\FIFTH WHEE | Replace turntable locking pin, bracket & sleeve | | 15/12/2022 | 178669 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\DAMAGE | REPAIR KANGAROO DAMAGE TO LEFT HAND FRONT SIDE OF CAB - TCTC 21/12/2022 | | 02/12/2022 | 176916 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\DAMAGE | Roo damage, water leaking, replace broken headlight & refit light in other hole, light broken out | Deaon's Signs - repair sign damage | 02/12/2022 | 176916 | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\TRL LIGHTS | Tested trailer lights all ok, removed plug and cleaned terminals, spread pins refit plug all ok | | 29/11/2022 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L075312 | | 25/11/2022 | 173985 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Steering | CHECK BALL JOINTS. GRINDING WHEN TURNING. | | 25/11/2022 | 173985 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 25/11/2022 | 173985 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP10 | puncture repair - call out | | 16/11/2022 | | Completed | Mt Gambier | STK | XV15VU | Albury Workshop | P/MOVER |
| | | | Service As Per Attached Checklist | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\BS | Barry Maney PO# L075037 | | 10/11/2022 | 163771 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 10/11/2022 | 163771 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L074687 | | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DRV LN SER | HARD SHUNT WHEN BACKING OFF AND THEN ACCELERATING. | MOVEMENT IN A TRAILER. | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Susp\WHEEL ALGN | TRUCK PULLS TO THE LEFT. (NEEDS WHEEL ALIGNMENT) | TRIDENT. | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Susp\AXLES | KNOCKING SOUND COMING FROM L/H WHEEL WHEN GOING OVER BUMPS. | JACKED UP AND CHECKED ALL COMPONENTS. COULDN'T FAULT. | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\PANELS | NO BOLTS IN CHECK PLATE BEHIND PM. | NOT IN BOOK. | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes\BRAKE ADJ | BRAKES NEED ADJUSTMENT. | ADJUSTED. | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CLUTCH | CLUTCH NEEDS ADJUSTING. GEARS RIDICULOUSLY TIGHT. | CLUTCH OK. GREASED ALL PIVOTS. CLLEANED ARUND CABLES. | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 21/10/2022 | 153013 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\ROTATION | Pos 1&2 | | 03/10/2022 | | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ALT | ALTERNATOR LIGHT FLICKERS ON/OFF. | | 30/08/2022 | 138563 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Cooling\RADIATOR | CHECK COOLANT LEVEL AS LEVEL IS LOW IN SIGHT GLASS. | | 30/08/2022 | 138563 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 30/08/2022 | 138563 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | Service As Per Attached Checklist | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | Barry Maney PO# L073750 | | 30/08/2022 | 138563 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | | Removed damaged plug, supply and fit new. | | | | | | | | |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | Trailer Plug Damaged | Tested all good | 27/08/2022 | 137950 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| | | | Carry out A Service as per job card for T909 X15 | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L072889 | | 14/07/2022 | 129378 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\INST/GAUGE | ALT LIGHT FLASHING ON/OFF ON DASH. | NO FAULT FOUND | 14/07/2022 | 129378 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Body\FUEL TANK | ADBLE TANK STILL SUCKING IN. | REPLACED FILTER. | 14/07/2022 | 129378 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Susp\WHEEL ALGN | PULLS TO THE LEFT. NEEDS WHEEL ALIGNMENT. | COMPLETED WHEEL ALIGNMENT. | 14/07/2022 | 129378 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DriCabRep\ST Weel | STEERING COLUMN WON'T TILT. | REPLACED CABLE. | 14/07/2022 | 129378 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 14/07/2022 | 129378 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | Tyre Replacement | | | | | | | | | |
| 1052 | Myrtleford - Workshop | Tyres\TP1+2 | PO# L072946 | | 13/07/2022 | 119240 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | Service As Per Attached Checklist | | | | | | | | | |
| 1052 | Myrtleford - Workshop | VehService\BS | PO # L072544 | | 23/06/2022 | 120413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\WHL HUB | DRIVER'S SIDE WHEEL HUB CAP/ DUST COVER MISSING. | | 23/06/2022 | 120413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | TOP CLEARANCE LIGHT ABOVE THE DRIVE OCCASIONALLY FLASHES ON/OFF. IT'S THE ORANGE C | | 23/06/2022 | 120413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\WHL HUB | DRIVERS SIDE WHEEL HUB CAP/ DUST COVER MISSING. | | 23/06/2022 | 120413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |

| | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | TOP CLEARANCE LIGHT ABOVE THE DRIVE OCCASIONALLY FLASHES ON/OFF. IT'S THE ORANGE C | | 23/06/2022 | 120413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 23/06/2022 | 120413 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| | | | | Correction:<br>-Connect laptop and take download Remove rocker cover<br>Carry out tune up<br>All valves tight, adjust<br>Refit rocker cover and reuse gasket Check over engine for leaks<br>Check belts and tensioners<br>-Replace air filter<br>-Pressure test CAC; ok<br>-Flush adblue airside<br>-Check turbo wastegate travel, out of spec<br>-Remove turbo & adjust wastegate<br>-Refit turbo & air pipes | | | | | | | |
| 1052 | Myrtleford - Workshop | Engine\ENG TUNE | Tune Up. Air Filter | -Steam clean & road test; ok | 15/06/2022 | 114600 | Completed | Mt Gambier | STK | XV15VU | CUMMINS SOUTH PACIFIC P/L - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP10 | puncture repair<br>Carry out A Service as per job card for T909 X15 | | 02/06/2022 | 119240 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L072192 | | 02/06/2022 | 110341 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 02/06/2022 | 110341 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\TP06 | puncture repair<br>Front & Rear Diff Oils | | 28/05/2022 | 135891 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\DIFF OIL | Spicer (no Filter) | | 21/05/2022 | 100339 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 20/05/2022 | 100339 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | PO # L071876 | | 20/05/2022 | 100339 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Tyres\Punct | Puncture<br>Carry out A Service as per job card for T909 X15 | | 20/05/2022 | 135891 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L071610 | | 05/05/2022 | 91675 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 05/05/2022 | 91675 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | Barry Maney PO# L071360 | | 21/04/2022 | | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Carry out A Service as per job card for T909 X15 | | 21/04/2022 | | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L071115 | | 09/04/2022 | 72474 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 09/04/2022 | 72474 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 22/03/2022 | 61321 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\B1 Svc | Barry Maney PO# L070806<br>Carry out A Service as per job card for T909 X15 | | 22/03/2022 | 61321 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | Barry Maney PO# L070569 | | 08/03/2022 | 53121 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 08/03/2022 | 53121 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\CTCH PACK | adjust clutch | | 22/02/2022 | 42600 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrivLine\WHEEL SEAL | front left wheel seal<br>Service As Per Attached Checklist | | 22/02/2022 | 42600 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | PO # L070296 | | 22/02/2022 | 42599 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Carry out A Service as per job card for T909 X15 | | 22/02/2022 | 42599 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\AS | PO # L069932 | | 03/02/2022 | 32695 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Elect\ELECT P&W | RH ROOF LIGHT NOT WORKING | | 03/02/2022 | 32695 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Service As Per Attached Checklist | | 03/02/2022 | 32695 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\BS | O/N L12878 ******* MINI B SERVICE ****** | | 14/01/2022 | | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job<br>Carry out A Service as per job card for T909 X15 | | 14/01/2022 | | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Wodonga - Workshop | VehService\AS | O/N L12808 | | 18/12/2021 | 14906 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | 18/12/2021 | 14906 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Engine\FUEL TANK | engine light on plug in computer water in fuel code, drain water and was 50% full of water, repla<br>Service As Per Attached Checklist | | 11/12/2021 | 8884 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | VehService\CS | O/N L12732 | | 04/12/2021 | 4842 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Myrtleford - Workshop | Brakes | Record Check Results As Attached To This Job | | 04/12/2021 | 4842 | Completed | Mt Gambier | STK | XV15VU | BARRY MANEY - 3 | P/MOVER |
| 1052 | Wodonga - Workshop | Elect\ELECT P&W | RH ROOF LIGHT NOT WORKING | | 23/11/2021 | 688 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Insp\Truck Pre | Truck Pre Delivery<br>2 x Stickers 3 Points of Contact<br>Safepak Albury | TARE= 10900KG | 23/11/2021 | 688 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Wodonga - Workshop | Body\CONSUMABLE | PO# WW068695 | | 23/11/2021 | 688 | Completed | Mt Gambier | STK | XV15VU | Wodonga Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\SCALES | fit scale and elphinstone trailer supply lines<br><br>Tablet serial # 000041720<br>Tracking unit serial # 479001822<br>Tracking unit sim card # 8200098249509<br>Tag #'s 024982 & 024981<br>MDVR serial # C704CBAFC1721<br>Phone # 0409823708 | Mount and wire up supplied IAP tracking unit under passenger seat.<br>Mount GPS and high gain antennas on rope rail above LH door just behind door. Mount tablet and mic above radio & gauges, mount speaker above rear of RH door. Mount MDVR under passenger seat, wire up, mount forward facing camera, run wiring and connect camera to MDVR. Connect and wire in engine data control box to CAN wiring & power and earth as necessary. Connect scales to tracking unit. Connect power, earth & ignition, mic and speaker, re-assemble truck and test. Contact MtData support to setup and test unit. Complete IAP paperwork & send off. | 05/11/2021 | 526 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | DrCabElect\IAP | Support persons name - Kad | | 21/10/2021 | | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |
| 1052 | Myrtleford - Workshop | Chassis\FIFTH WHEE | MAKE UP TURN TABLE WITH SCALES AND GREASE LINES L12497 | | 20/09/2021 | 421493 | Completed | Mt Gambier | STK | XV15VU | Myrtleford Workshop | P/MOVER |