EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
1046	Mt Gambier - Mt Gambier	Engine\ADBLUE	CHECK AFTER TREATMENT LIGHT ON DASH	Plug in and check codes - ambient temp sensor open circuit. Inspect sensors and found smashed. Replaced temp sensor, clear codes and road test, all okay	20/08/2026	966330	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Steering\WHEEL SEAL	check front R/H wheel seal	LABTC - Labour Labour and oarts included in WO 208429	19/08/2026	965795	Completed	Mt Gambier	STK	XV66MC	HALLORAN DIESEL - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\SEAT	drivers seat air ride lets down	LABTC - Labour Not addressed Noted aaainst truck for future	19/08/2026	965795	Completed	Mt Gambier	STK	XV66MC	HALLORAN DIESEL - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	DIGITAL GEAR SELECTOR NOT WORKING Found intermittently not working. If faults continue will need new sweedo and wirind iwear screen in in sawedo)	LABTC - Labour Mechanic could not fault, will continue to monitor Noted GI (grease interval) code Labour (minimall included in WO 208429	19/08/2026	965795	Completed	Mt Gambier	STK	XV66MC	HALLORAN DIESEL - 3	P/MOVER
1046	Myrtleford - Workshop	Steering\KING PIN	king pins require replacing	Disconnected prime mover and supported front axle- Removed wheels, brakes, hub and stub axle- Removed worn king pin bushes- Installed new bushes and reamed to correct clearance- Reassembled stub axle, king pin, steering arms and brake components- Reinstalled hub with new bearing cups and seals- Adjus	18/08/2026	965795	Completed	Mt Gambier	STK	XV66MC	HALLORAN DIESEL - 3	P/MOVER
1046	Myrtleford - Workshop	Susp\AIR BAG	replace leaking airbag		18/08/2026	965795	Completed	Mt Gambier	STK	XV66MC	HALLORAN DIESEL - 3	P/MOVER
1046	Mt Gambier - Mt Gambier	VehService\BS	VehService\BS B Service		14/08/2026	965795	Completed	Mt Gambier	STK	XV66MC	HALLORAN DIESEL - 3	P/MOVER
1046	Myrtleford - Workshop	DrivLine\SHOCK ABS	BOTH 2ND DRIVE SHOCKERS LOOSE	Remove and replace worn shocker bushes on rear axle, all OK KWK066-310 BUSH-RUBBER 2 38.42 KW73D2002 BUSH-SHOCK ABSORBER	28/07/2026	952904	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Steering\HOUSEKEEP	STEERING COLUMN WONT ADJUST OR LOCK IN	Remove steering column surround and found spring not attached. Refit spring and check steer column functions, all okay	28/07/2026	952904	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE STEER SHOCKER BRACKET VehService\AS A Service	Found shocker bracket worn, remove old. Organise new bracket (bolt on style). mark and drill holes. Fit new bracket and re fit new shocker. All okay KWB11-1259 BRACKET-SHOCK ABSORB. FR	28/07/2026	952904	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	VehService\AS	L134923		28/07/2026	950418	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Engine\EXHAUST	CHECK EXHAUST SYSTEM FOR LEAKS AND FOR BOOST LEAK	Pressure test boost system and spray over with soapy water to detect leaks - unable to fault. Inspect connections and found exhaust gaskets leaking and soot around manifold. Advise for truck to return separate to service day to rectify issue.	17/07/2026	944415	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Steering\DAMAGE	PITMAN ARM LOOSE - FIX	Found and found splines on pitman arm worn. Remove and replace pitman arm, fit new split pin and tension to spec. KW123-1008 ARM-PITMAN 1 1243.86 NGPB85 PINCH BOLT TA585	17/07/2026	944415	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		13/07/2026	944415	Completed	Mt Gambier	STK	XV66MC	BORDER BANDAG PTY LTD -3	P/MOVER
1046	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6		13/07/2026	944415	Completed	Mt Gambier	STK	XV66MC	BORDER BANDAG PTY LTD -3	P/MOVER
1046	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12		13/07/2026	944415	Completed	Mt Gambier	STK	XV66MC	BORDER BANDAG PTY LTD -3	P/MOVER
1046	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		13/07/2026	944415	Completed	Mt Gambier	STK	XV66MC	BORDER BANDAG PTY LTD -3	P/MOVER
1046	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter. L134647	Inspect and found pressure sensor faulty. Replace pressure sensor, all OK.	03/07/2026	939096	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Engine\FAULT CODE	ENGINE OIL PRESSURE AND ALARM ON SOMETIMES	KW1745-2443 SWITCH-LOW OIL PRESSURE	03/07/2026	939096	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Engine\FAULT CODE	CHECK ENGINE LIGHT SOMETIMES COMES ON	Plug in and check codes - ABS inactive code showing. Clear codes. monitor and advise if returns	03/07/2026	939096	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	ENGINE BRAKE LIGHT OUT ON DASH	Remove dash, replace blown globe and check - all OK	03/07/2026	939096	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrivLine\CLUTCH	CLUTCH SLIPPING SOMETIMES	Clutch adjusted on service. Check over clutch operation on road test, all OK	03/07/2026	939096	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\ST Weel	steering column wont adjust due to locking cable coming of latch	Remove plastic covers around steering column. Remove steering dampener and fit new tilt strut. Reassemble and check, all OK KW4990808 TILT LOCK-GAS STRUT GEN 2.5 ST	03/07/2026	939096	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\DAMAGE	DRIVER SIDE 2ND STEP FROM BOTTOM CRACKED FIT NEW STEP	repair broken steps swap from Left to right if possible Removed step, checked other side step but found to be faulty. Installed new step as required. KWR82-1007 STEP - CAB ACCESS	30/06/2026	939096	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Air Con\AIR CON	Check AIR CON. blows hot air. may need gas CHECK AIR CONDITIONING OPERATION replace a/con compressor had a short in the clutch	REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Jack cab over, check pressures and found A/C to have correct gas. Test power at compressor and found 12 volts. Test coil of compressor clutch and found to have a short. Recover gas, remove A/C belt and replace compressor as required. Refit belt, refill with gas and check operation, all OK KWF69-1019 COMPRESSOR-REFRIGERANT 1 559.89 KWDCT110H1RW-10P brake hose cable tie E 25.20 POL AIRCONDITIONING GAS R134A	24/06/2026	934713	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Body\FUEL TANK	x2 tank strap rubbers worn	Replase 1 strap on LHS and 2 straps on RHS as required, all OK KWK89-1004-1260 LINING-TANK STRAP	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Susp\Torque Rod	LH front torque rod bushes needs replacing	Remove torque rod bolts. Remove old bushes then press in new bushes. Fit torque rod and tighten all bolts to spec, all OK KW83910 BUSHING-TORQUE ROD	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Check LH front drive wheel bearing adjustment	CHECK LH FRONT DRIVE WHEEL BEARING Jack up axles and check for movement in front drive wheel bearings - within ssec	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Susp\SHOCK ABS	CHECK PRIME MOVER SHOCKERS	During service found LHS top steer shocker mount worn. Remove shocker off stud, oxy out of stud. Clean off surfaces, paint new stud same colour. Fit new stud and refit shocker. Ordered different style of shocker mount, to fit next service. Discussed with WD. RHS drive shocker leaking, replace with new shocker. LHS front & RHS rear shocker bushes worn. Remove and replace top and bottom bushes as reauired.	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	ENG BRAKE LIGHT OUT ON DASH	ENGINE BRAKE LIGHT OUT) Remove dash covers and replace x2 dash globes as required. KW47762 GLOBE-DASH PANEL.12V 1.2W BLACK BASE B8.	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	CHECK ENGINE LIGHT , ENG OIL & ALARM COMES ON SOMETIMES	CHECK ENGINE LIGHT AND ALARMS COMING ON INTERMITTENTLY Plug in and inspect fault codes - electric lift pump open codes & short to low source. Cut all cable ties and inspect wiring, found rubbed and broken sections of wiring. Cut sheath from wiring and repair as required. Re-secure all wiring, all OK	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrivLine\CLUTCH	CHECK CLUTCH SLIPPING SOMETIMES	ADJUST CLUTCH Carry out clutch adjust through computer	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Engine\AIR LEAK	AIR COMPRESSOR DISCHARGE LINE LEAKING		18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\RADIO	CHECK REPLACE UHF ARIAL. BAD RANGE RECEPTION VehService\AS A Service	CHECK UHF OUTPUT & ANTENNA , NOT MUCH RANGE Test and found antanna faulty. Remove and replace, check operation, all OK	18/06/2026	931711	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	VehService\AS	L134289 Insp\ANN INSP Annual insepction as per check sheet		17/06/2026	931162	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Insp\ANN INSP	L134290 VehService\BS B Service		17/06/2026	931162	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	VehService\BS	L133919		26/05/2026	922013	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\WIPERS	R&R WIPER BALDES	Remove and replace wiper blades as required, all okay KWWW7108R WIPER REFILL 710MM x 8MM RAIL	25/05/2026	918933	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\ST Weel	TIGHTEN STEERING WHEEL ADJUSTER	Remove covers around steering column and inspect, found lever was loose. Tightened adjuster, reassemble and check, all okay	25/05/2026	918933	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\RADIO	MOUNT STEREO CORRECTLY IN DASH	Remove all components to access, remove radio and housing from dash. Refit radio to holder and check stable, all okay. Refit all components	25/05/2026	918933	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Body\AIR BAG	CHECK AIR BAG ON DRIVERS SIDE WHEN PUMPED UP. BOUNCES AND GRABS. J	Disconnect all components to seat then remove. Remove and replace seat shocker from spare seat, refit and reconnect seat. check over. all okay	25/05/2026	918933	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrivLine\WHEEL SEAL	RH FRONT DRIVE LEAKING WHEEL SEAL VehService\AS A Service	jack up middle axle, back off brakes, remove air CTI. Unbolt and remove wheels then remove axle. Unbolt hub and remove brake and drum. Clean hub, stub, and bearings. Fit new wheel seal and fit new shoes and drums, refit hub and adjust bearings. Refit axle, wheels, and CTI. Tension and adjust brakes, road test all okay KW220851215 GASKET 1 3.60 KW47697S SCOTSEAL 1 33.61 KWK58AA31247070P KIT-BRAKE SHOE DRIVE 16.5 X 7 MERITOR Q- 1 130.00 KWP53-123537-002 BRAKE DRUM-X30 PACGEN 10X285 CAN USE	30/04/2026	910609	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	VehService\AS	L133571		30/04/2026	910609	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 29-30		29/04/2026	910609	Completed	Mt Gambier	STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Myrtleford - Workshop	Body\LIGHTS	REPLACE HEADLIGHT PROTECTORS DRIVERS SIDE BROKEN. PASSENGER SIDE CR		21/04/2026	904526	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Tyres\ROTATION	Tyres\ROTATION 1-2 VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.		20/04/2026	904526	Completed	Mt Gambier	STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Myrtleford - Workshop	VehService\B1 Svc	L133340		17/04/2026	901719	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Steering\SUSPENSION	R&R STEER SHOCKER	Inspect front right steer shocker, found mount loose. Remove shocker and tahten mount. Refit shocker. all OK	30/03/2026	891770	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Steering\UNI JOINTS	R&R WORN STEERING UNI'S	Remove shaft and old uni joint. Fit new uni joint and grease. Check steering wheel position and ensure all straight, all OK KWS.103X UJ KIT 100	30/03/2026	891770	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Engine\BELTS/TENS	CHECK BELTS	Inspect A/C belt, found belt severely freyed. Remove A/C belt and fit new as required, all OK CU3103233	30/03/2026	891770	Completed	Mt Gambier	STK	XV66MC	BARRY MANEY - 3	P/MOVER

1046	Myrtleford - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL Replace Diff oils VehService\AS A Service	CHECK AND REPLACE DIFF OIL IF REQUIRED Check diff oil, found severely dirty. Check history BMG never done C service on 1046. Unsure how long ago diff oil was changed, drain and replace as required, all OK POL CASTROL DYNADRIVE 80W/90	30/03/2026	891770	Completed	Mt Gambier STK	XV66MC	Myrtleford Workshop	P/MOVER
1046	Myrtleford - Workshop	VehService\AS	L138029 VehService\BS B Service		27/03/2026	889209	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	VehService\BS	L099251		10/03/2026	882512	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		13/03/2026	880372	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\Rims	Tyres\Rims	1 new 9" alloy rim 2 nwr done in mount gambier	13/03/2026	880372	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Myrtleford - Workshop	Steering\WHEEL HUB	RH FRONT WHEEL BEARINGS	Jack axle and inspect wheel bearing movement, all OK	11/03/2026	880372	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REPAIR DASH LIGHTS AXLE OIL TEMP FUEL LEVEL LIGHT	ound fuel level and axle oil temps not working. Remove dash panels and inspect. Found globes for both blown. Remove and replace globes as required. Reassemble dash and check operation, all OK KWB00005002 HOLDER-GLOBE INCLUDE GLOBE	11/03/2026	880372	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Engine\BELTS/TENS	CHECK BELTS - SQUEALING	Upon service found minor belt squeal. Inspect belts and found slight wear. Re-check next service	11/03/2026	880372	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Tyres\Punct	Tyres\Punct POS 7		03/03/2026	880372	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Myrtleford - Workshop	DrivLine\SHOCK ABS	TIGHTEN SHOCKER BOLTS VehService\AS A Service L099044	Removed LH steer shocker, tightened stud. Refit shocker and tensioned nut.	24/02/2026	872340	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	VehService\AS			17/02/2026	872340	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Air Con\AIR CON	CHECK AIR CONDITIONING OPERATION FAN IN CAB N/W	REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Inspect blower fan operation, found not working at all. Go over and check all fuses, all OK. Remove LHS kick panels, test blower and Hvac fuses, all OK. Have fit new blower motor to truck recently, look over diagrams and found extra relay not listed. Test power and found to only have power at coil side of relay but no power on main side. Unplug Hvac #1 relay and found 12 volts at main power indicating relay faulty. Remove and replace relay and test, all working as should. Refit dash with new screws and bolts as numerous were missing, all OK KW31887 PHD TX25 M5X20 BZN	13/02/2026	866678	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Elect\ELECT P&W	LOADING LIGHTS ON DRIVERS SIDE N/W	Found RH mirror loading lights not working. Inspect fuse for lights and found blown. Carry out isolation process for lights. Remove door card and inspect with loom unplugged, found fuse still blowing. Remove dash panels to inspect wiring, found wire for trailer work lights shorting out. Inspect wiring further and found short on truck side. Remove dash panels to gain access, inspect and test relevant wiring to find short. Repair short in wiring as required then refit dash back together. When fitting mirror cover back on found not clipping in, get new cover painted and fit new cover as required, all OK. DF2138517 COVER- MIRROR. MAIN. UNPAINTED MAIN MIRR	09/02/2026	866678	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Susp\SHOCK ABS	TIGHTEN LOOSE SHOCKERS	Found x2 drive shockers loose. Tighten both middle shockers as required.	09/02/2026	866678	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	trailer abs light on dash nw	TRAILER ABS LIGHT ON (MAYBE RELATING TO EBS MODULE TO BE REPLACED ON A TRAILER ?) Replace trailer EBS module, all OK	09/02/2026	866678	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrivLine\CTI Drive	REPLACE LH REAR AIR CTI ROTATOR	Inspect LH rear AIR CTI rotator. Remove and replace with one from GF stock. all OK awd to Nangwarry and inspect truck, found LH tank pressure protection damaged, causing it to not hold air. Return to workshop to get correct parts. Return to truck and fit new valve as required. Test and check over for leaks, all okay. KWKN31200 VALVE 1 171.55	09/02/2026	866678	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Body\AIR LEAK	TRUCK BROKEN DOWN OUT BACK OF NANGWARRY - AIR LEAK UNDER CAB VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.	POL Travel kms: 60	31/01/2026	859271	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	VehService\B1 Svc	L098727		31/01/2026	860131	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	FUEL GUAGE LIGHT DIM-OUT	FUEL GAUGE LIGHT OUT Removed dash, replaced blown globe as required. Refit dash, all okay. KWB00005002 HOLDER-GLOBE INCLUDE GLOBE	12/01/2026	851283	Completed	Mt Gambier STK	XV66MC	Myrtleford Workshop	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\RADIO	REPLACE CRACKLY SPEAKER IN BUNK	CRACKLY SPEAKER IN BUNK Listened for crackly speaker, was hard to hear which speaker was at fault. Not major issue or roadworthy item. Driver to monitor.	12/01/2026	851283	Completed	Mt Gambier STK	XV66MC	Myrtleford Workshop	P/MOVER
1046	Myrtleford - Workshop	DrivLine\GEARBOX	TRUCK SHIFTING SOLID CLUNK 11TH 12 TH 13TH 14TH GEARS	CHECK TRANS SHIFTING ISSUES CLUNK IN 11th, 12th, 13th AND 14th GEARS CHECK FAULT CODES IN TRANSMISSION AND SPLITTER Connect laptop and inspect for trans faults. Found no active or inactive codes. Adjust clutch via computer. Cleaned out plugs to ECU. Reconnect and road test, all okay.	12/01/2026	851283	Completed	Mt Gambier STK	XV66MC	Myrtleford Workshop	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\RADIO	UHF MIC DODGY -CRACKLY	FIT NEW UHF MIC Remove dash panel, remove and replaced UHF hand piece. KWMC553B	12/01/2026	851283	Completed	Mt Gambier STK	XV66MC	Myrtleford Workshop	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\AIR LEAK	CHECK BRAKES - RED BUTTON N/W	Found trailer exhaust button not working. Brakes would only apply and release via yellow button. Inspect further and found trailer supply button was not releasing when park brake was released. Removed pressure protection valve and replaced with new. Tested, all okay. KWAQ68-D0T-6N6 PTC CNCTR 3/8 X 3/8 M 2 12.58 KW233061 PIPE STREET TEE 3/8 F 1 10.06 KWAQ68-D0T-4X6 PTC CNCTR 1/4 X 3/8 M 1 8.06 KWAQ64-D0T-4 PTC UNION TEE 1/4 1 11.32 KWTRP2819A6 VALVE DASH PP5	09/01/2026	851283	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Elect\BATTERY	LOAD TEST AND CHECK BATTERIES	Load test and check batteries. Found batteries needing charge, put on charge overnight. Retest, all okay. Return truck to Greenfreight yard.	09/01/2026	851283	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Steering\SUSPENSION	REPLACE LH STEER SHOCKER	Found LH steer shocker had a broken shroud. Unbolt and remove shocker, replaced with new and tensioned, all okay. KW090-2205SP3B SHOCK ABSORBER-KONI,FRONT TAPERED LEAF	09/01/2026	851283	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\RADIO	UHF BUTTON AFFECTS STEREO & TABLET CHARGING ?	DONE BY B/M 11/11/25	09/01/2026	851283	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DriCabRep\DOOR LOCK	ADJUST DRIVERS DOOR FOR TIGHTER SEAL. DUST GETTING IN	DRIVER SIDE DOOR LETTING DUST IN Found grommet between door and cab, containing all wiring was damaged and possible fault for letting dust in cab. Removed old seal and replaced with new. KWR42-1105 GROMMET-	09/01/2026	851283	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Engine\BATTERY	batteries tested & current draw test done VehService\AS A Service	jump start truck, load test and check batteries replace if needed Checked starting condition and truck was dead flat at yard. Jump start and bring back to workshop to charge. Once charged load tested all batteries. Found 2 were no good and other 2 were low. Removed all batteries and replaced with new. Started truck and checked, all okay. KWTRP-700HD SEALED MAIN FREE BATTERY CCA 700, RC 160	07/01/2026	851038	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	VehService\AS	L098304		05/01/2026	851038	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Elect\BREAKDOWN	Elect\BREAKDOWN	JUMP START TRUCK AT YARD TRUCK WONT START Travel to GF yard, jack cab and connect to batteries. Jump start truck as required. all okay Unbolt and remove RHP torque rod. Remove and replace bushes as required then refit torque rod, all okay	17/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Susp\Torque Rod	Torque rods worn	KW839310 BUSHING	11/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	DriCabRep\WIPERS	BLOCKED WINDSCREEN WASHER ON DRIVERS SIDE	Remove washer lines and blow out. Reconnect and operate windscreen washers, all okay	11/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	DrivLine\SHOCK ABS	LH REAR DRIVE SHOCKER RUBBERS WORN	Remove and replace worn shocker rubber on LHR drive KWK066-310	11/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Elect\WORK LIGHT	CONNECT WORK LIGHT ONTO SWITCH IN CAB	CONNECT WORK LIGHT ONTO SWITCH IN CAB Check plug operation, change over wires. Check scales power, checked wiring in cab. Found trailer work light wiring was to ignition constant power and wires in plug needed changing. Disconnect wiring to ignition constant power, sourced power from mirror loading light switch. Removed panels and join length of wire from loading lights switch for trailer work lights. Tidy up wiring and secure, tested operation, all working as required. Refit dash panels.	11/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	AD BLUE TANK IS LOOSE AND HAS A BLOCKED BREATHER	Removed ad blue breather and flushed out breather and tube, refit. Loosened ad blue straps and slide rubbers back into place. Refit straps and tightened.	11/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	DrivLine\OIL LEAK	REPAIR FRONT DIFF INTERFACE OIL LEAK JUMP START VEHICLE	Check over front diff for oil leak, all okay. Check oil level, all okay.	11/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Elect\BREAKDOWN	Travel to yard, lifted cab over. Jump started truck as required. Lowered cab. VehService\BS B Service	1 88KWZZZ03 AFTER H'RS BREAKDOWN Tech(s): 040472 120.00 CALL OUT FEE	11/12/2025	846165	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	VehService\BS	L098071		09/12/2025	839328	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER

			VehService\AS A Service											
1046	Myrtleford - Workshop	VehService\AS	L097771					14/11/2025	831232	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
				WATER TEMP LIGHT OUT ON DASH Check dash lights and found engine brake and water temp lights out. Pull dash apart, remove and replace both dash										
1046	Myrtleford - Workshop	DrCabElect\ELECT P&W	water temp light out on dash1	globes. check. all working as should. Reassemble dash. all				13/11/2025	830159	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Susp\SHOCK ABS	Rear right shockie leaking	WO checked shocker 11/11/25 all ok				13/11/2025	830159	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Susp\SHOCK ABS	Drive shockies worn	WO checked all shocker bushes 11/11/25 they are all ok				13/11/2025	830159	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
				UHF AFFECTS STEREO AND TABLET & TABLET NOT CHARGING Test UHF and radio with Wayne, but unable to fault. Inspect further and found a fault in charger cable for tablet.										
1046	Myrtleford - Workshop	DrCabElect\RADIO	REPLACE OR FIT NEW AERIAL FOR AM / FM RADIO	Cable to be reslaced to rectify issue. UHF AFFECTS STEREO AND TABLET & TABLET NOT CHARGING Test UHF and radio with Wayne, but unable to fault. Inspect further and found a fault in charger cable for tablet.				13/11/2025	830159	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabRep\RADIO	UHF AFFECTS STEREO & TABLET. TABLET NOT CHARGING	Cable to be replaced to rectify issue.				13/11/2025	830159	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Wodonga - Workshop	Tyres\FITMENT	Tyres\FITMENT CTI LINE POS 6					07/11/2025	827456	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
				Found air gauge on dash blown. Pull dash apart and replace globe. Reassemble dash and check, all ok										
1046	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REAR AIR GAUGE DASH LIGHT N/W	KW80005002 HOLDER-GLOBE INCLUDE GLOB Remove and replace windscreen wipers				27/10/2025	819324	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabRep\WIPERS	REPLACE WINDSCREEN WIPERS	KW13600803800 RUBBER-WIPER REFILL SUITS WIPER BLADE 13 Check for power to tablet, all ok. Check switch for tablet,				27/10/2025	819324	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
				found not working. Remove and replace switch and check operation, all ok.										
1046	Myrtleford - Workshop	DrCabElect\ELECT P&W	TABLET NOT CHARGING ALL THE TIME	KW2086874-2 USB CHARGE PORT - DUAL. NO BAC Check scales, all ok. Check gauge in cab, all ok. Check dump switch, found to be fully closed, driver to monitor and provide more info if continues to fault.				27/10/2025	819324	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabElect\SCALES	SCALES NOT WORKING	Isusoect faulty A trailer unit- JB Sooken with BO to aet				27/10/2025	819324	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	DrCabRep\DOOR LOCK	GLUE SEAL ON DRIVERS DOOR	Glue door seal on secure, check, all ok.				27/10/2025	819324	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter.											
1046	Myrtleford - Workshop	VehService\B1 Svc	L097436					24/10/2025	820966	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
				Get to One Forty One, get inducted to be on site. Get to truck and inspect. Found black button leaking. Call out parts to get new black button. Remove dash and replace black button. Test operation, all ok.										
1046	Myrtleford - Workshop	DrCabRep\AIR LEAK	AIR LEAK BEHIND DASH @ ONE FORTY ONE YARD	KWTRP275176 VALVE DASH PPI ROUND BLACK BUTTON 1 44.14NGCALLOUT PARTS A/HRS CALLOUT Inspect operation and found tablet not charging. Remove fuse panel and centre triangle and trace wiring to FMS plug and test. Found power at plug but not after plug. Inspect further and found plug not connected properly. Check operation, all ok. Found while inspecting USB not working.				20/10/2025	815679	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
			Cigarette Lighter Socket Not Functioning And Also USB Sockets - Again	Trace wiring and found wires to be connected back to front.										
1046	Myrtleford - Workshop	DrCabElect\ELECT P&W	done b/m 9/10/25	Switch wires around and test. all ok.				15/10/2025	815679	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	Elect\BREAKDOWN	TRAVEL TO GF AND JUMP START TRUCK	Travel to yard and jump start truck, all ok				14/10/2025	815679	Completed	Mt Gambier STK	XV66MC	BARRY MANEY - 3	P/MOVER
1046	Myrtleford - Workshop	ElecLab	CHANGE SEAT BELT BUCKLE/STALK TO ONE WITH A WIRE FOR WARNING ACTIV					09/10/2025	822652	Unlocked	Mt Gambier STK	XV66MC	JF MECHANICALS - 3	P/MOVER
1046	Myrtleford - Workshop	CTILab	MOUNT CTI UNIT & COMMISSION.					09/10/2025	822652	Completed	Mt Gambier STK	XV66MC	JF MECHANICALS - 3	P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2	CHANGED OVER TO LOGGING FROM LINEHAUL HAD ALL TYRES CHANGED TO SUIT LOGGING SPEC				29/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4	CHANGED OVER TO LOGGING FROM LINEHAUL HAD ALL TYRES CHANGED TO SUIT LOGGING SPEC				29/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8	CHANGED OVER TO LOGGING FROM LINEHAUL HAD ALL TYRES CHANGED TO SUIT LOGGING SPEC				29/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\TP09	Tyres\TP09	CHANGED OVER TO LOGGING FROM LINEHAUL HAD ALL TYRES CHANGED TO SUIT LOGGING SPEC				29/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6	CHANGED OVER TO LOGGING FROM LINEHAUL HAD ALL TYRES CHANGED TO SUIT LOGGING SPEC				29/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Myrtleford - Workshop	Engine\RERATE	Apply New Cummins Engine Program. Change Diff Ratio From 3.91 To 4.30, Cha MT Data Not Tracing.					26/09/2025	851283	Completed	Mt Gambier STK	XV66MC	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1046	Wodonga - Workshop	DrCabElect\GPS	iArkon Auto Electrical P/O: WW097159					26/09/2025	792787	Completed	Mt Gambier STK	XV66MC	ARKON AUTO ELECTRICAL	P/MOVER
1046	Wodonga - Workshop	Tyres\FITMENT	Tyres\FITMENT CDI LINES IN TYRE POS 3-10					22/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6					06/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8					06/09/2025	792787	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
				Electrical issues traced new alternator fitted New bearings replaced in air con idler pulley Fixed drivers side door card Cigarette lighter fixed										
1046	Wodonga - Workshop	VehService\AS	VehService\AS A Service	Ad blue pump clean and flush				29/08/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\WORK LIGHT	REPLACE WORK LIGHT ON BUNK.	-globes for tacho were blown parts replaced				29/08/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	Service					29/08/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
				-fuse blown for Acc socket in dash, replaced with resetable fuse										
1046	Wodonga - Workshop	DrCabElect\ELECT P&W	Cigarette Lighter Plug Not Working	-usb socket in dash broken, part replaced				29/08/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\DOOR LOCK	Door Trim - Drivers Side					29/08/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrivLine\OIL LEAK	Re-fit oil dipstick for Haldar.					18/08/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\AIR FITTIN	FIT NEW AIR CONNECTION.					25/07/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\DOOR LOCK	Over head locker lid/door has Hinge Broken.					25/07/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\BS	VehService\BS Susp\SHOCK ABS					25/07/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Susp\SHOCK ABS	Replace 4 rear shock Replace Front & Rear Diff Heads Using Diff's Out Of 1003, Rerace Both Diff Heads.					25/07/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrivLine\DIFF REPMN	(Parts Supplied By TCTC P/O: WW0053131)	REPLACED DIFF HEADS WITH LOGGING SPEC REBUILT HEADS. FITTED CROSS-LOCK PLUMBING AND WIRING. FITTED CTI WHEEL COMPONENTS. PLUMBED IN DIFF LOCK SWITCH LINES AND FITTED WIRING.				12/07/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\PANELS	FITTED CHECKER PLATE					12/07/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL	COMPLETED				12/07/2025	792787	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12					30/06/2025	778102	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10					30/06/2025	778102	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	CALL OUT- HOOKED UP T610/611. CHECKED OVER. DIAGNOSED AND REPLACED					15/06/2025	772425	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 9					04/06/2025	765460	Completed	Mt Gambier STK	XV66MC	BORDER BANDAG PTY LTD	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	G & S DIESEL SERVICE- REPAIR AFTER TREAT FAULT.	Fitted new dose pump in Wodonga workshop				21/05/2025	761312	Completed	Mt Gambier STK	XV66MC	G & S DIESEL SERVICE	P/MOVER
1046	Wodonga - Workshop	Engine	Exughst manifold gasket on cylinder 2 leaking					19/05/2025	761312	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
				-rear cab illumination light working but has LED's out recommended replacing in future -side spot lights working as intended										
1046	Wodonga - Workshop	VehService\AS	VehService\AS A Service	-radio checked over, BT, TURNER, AUX functions working as intended ((possible reception issue during travel))				12/05/2025	762089	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\HOUSEKEEP	New stereo be nice. CD player not working.					12/05/2025	762089	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	wiper blade needs replacing					05/05/2025	757433	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
				Added 3 litres of oil to Engine. Replaced X2 blown dash globes for tank air pressure gauges front and back. Reattached camera to windscreen. Adjusted turntable.										
1046	Wodonga - Workshop	VehService\AS	VehService\AS	Made bracket to clamp suzi assembly in place.				11/04/2025	747127	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\HOUSEKEEP	forward face camera needs attach to windscreen good double sided tape	Reattached during service				11/04/2025	747127	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	Adblu tank not vent	Flushed out breather during service				11/04/2025	747127	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	REPLACE DASH GAUGE GLOBE.	Completed during service				11/04/2025	747127	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\HOUSEKEEP	pogo stick bracket needs bolt D/S	Fixed during service				11/04/2025	747127	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	REPLACE DASH GAUGE GLOBE.	Completed during service				11/04/2025	747127	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	REPLACE DASH GAUGE GLOBE.	Completed during service				11/04/2025	747127	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Air Con\AIR CON	Aircon / fan not work	Tested HVAC fan circuit. Found blower fan not working. Replaced fan and confirmed repair				21/03/2025	735684	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	BLOWN GASKET-AIR DRYER.	Replaced blown gasket				18/03/2025	730536	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection					17/03/2025	730536	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
				R.S 9¼ HOURS LABOUR K.RYAN 5 HOURS LABOUR										
1046	Wodonga - Workshop	VehService\CS	C Service	D.H ¼ HOUR LABOUR				15/03/2025	730536	Completed	Mt Gambier STK	XV66MC	Wodonaa Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK					04/03/2025	730536	Completed	Mt Gambier STK	XV66MC	BEAUREPAIRES	P/MOVER
1046	Wodonga - Workshop	Body\WIPERS	REPLACE WIPER BLADES.					21/02/2025	714716	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\WINDSCREEN	P/S Windscreen.					12/02/2025	713248	Completed	Mt Gambier STK	XV66MC	AUTOTEK AUSTRALIA	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	Ad Blu Tank Not Venting.	Duplicate job				06/02/2025	713248	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	VehService\AS					06/02/2025	713248	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	AD-Blu Tank NOT Venting.	Duplicate job				06/02/2025	713248	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	Ad Blu Tank NOT Venting.	Bocked out let				06/02/2025	713248	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\DAMAGE	P/Side Windscreen Cracked. (Albury Autoscreen P/O: WW0031713)					31/01/2025	713248	Completed	Mt Gambier STK	XV66MC	AUTOTEK AUSTRALIA	P/MOVER
1046	Wodonga - Workshop	Cooling\RADIATOR	Ad-Blu Tank Not venting, check exhaust flex pipe, clean radiator/intercooler's -1	Found tank breather hose had been cable tied to adblue hose's, removed cable tie tank started breathing correctly.				22/01/2025	680146	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Cooling\RADIATOR	Clean Out Radiator & Intercooler (Debug)	Blow and wash radiator				22/01/2025	680146	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	CUT CABLE AT ADBLUE TANK BREATHER HOSE.					22/01/2025	680146	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\EXHAUST	REPLACED EXHAUST FLEX, GASKETS AND CLAMPS. TESTED. OK.					22/01/2025	680146	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\BS	VehService\BS					11/01/2025	680146	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
				SHANE McCABE										
1046	Wodonga - Workshop	VehService\AS	VehService\AS	KEITH R				06/12/2024	680146	Completed	Mt Gambier STK	XV66MC	Wodonaa Workshop	P/MOVER
1046	Wodonga - Workshop	VServLab	A SERVICE					06/12/2024	680146	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	breather pipe ad blue blocked	Breather blocked on ad.blue tank blow out and refit blow tank out, fit new wiper blades.				27/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\HOUSEKEEP	wiper blades					27/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Susp\AIR LEAK	Truck has air leak somewhere -Bloody Annoying.	Filled air tanks to capacity parked out back for an hour no visible loss of air pressure over that time				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\AIR LEAK	Very Slow to Build Up Air	At 1000 rpm time was 2minutes 34 seconds from zero to blow off				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\HOUSEKEEP	Remove Number Plate Cover & Clean	Drivers job not mechanics				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\STEER TYRE	match up steer tyres / rim	tyre fitter is happy with them where they are				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\DOOR LOCK	D/S DOOR LINER LOOSE.	Used new Christmas tree				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
			A Service.											
1046	Wodonga - Workshop	VehService\AS	Serviced @ 670925 Klms	Duoplicate iob				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonea Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\HOUSEKEEP	Guardian Loose Flopping Around					15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	Truck Has Air Leak Somewhere Dumps All Air	Duplicate job				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VServLab	A SERVICE.	Duplicate job				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	Truck loses Air Very Quick A Service.	Duplicate job				15/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	Serviced @ 660640 Klms					15/11/2024	664843	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\WIPERS	Wiper Blade Broken					07/11/2024	670925	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	VehService\AS					26/10/2024	664843	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service					26/10/2024	664843	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\HOUSEKEEP	Have previously mention clean radiator / intercooler. Truck gets hot real quick.	CLEANED RADIATOR.				26/10/2024	664843	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\TP01	Tyres\TP01					16/10/2024	571110	Completed	Mt Gambier STK	XV66MC	BEAUREPAIRES	P/MOVER

			Rear diff front input seal leaking REPAIR OIL LEAK AT THROUGH SHAFT SEAL TO FRONT DIFF . * Unbolted & removed jackshaft * Undo yoke nut & removed yoke * Removed through shaft seal * Cleaned down all sealing surfaces * Installed replacement seal * Refit yoke with new nut & tensioned * Refit jackshaft with replacement bolts * Aligned & tensioned all components * Test operations - All ok REPAIR OIL LEAK AT PINION SHAFT SEAL TO REAR DIFF . * Unbolted & removed jackshaft * Undo yoke nut & removed yoke * Removed pinion sea * Cleaned down all sealing surfaces * Installed replacement pinion seal * Refit yoke with replacement nut & tensioned * Refit jackshaft with replacement bolts * Aligned & tensioned all to specifications												
1046	Wodonga - Workshop	DrivLine\OIL LEAK	* Test operations - All ok. fault no lonaer oresent Brakes\BRAKE ADJ / Replacement WHILST CARRYING OUT REPAIRS, FOUND 3 DRIVE BRAKES LOW . * Ballast axles & removed wheel end equipment * Removed drums & hub assemblies * Inspected bearings - All ok * Removed & replacement brake shoes * Refit hubs with replacement seals * Adjust bearings & brakes & greased all components * Found brake drums to be worn * Installed replacement brake drums * Refit wheel end equipment * Aligned & tensioned all to specifications										16/10/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	* Test operations - All ok DrivLine\DRV LN SER POWER DIVIDER O-RINGS LEAKING . * Unbolted & removed driveshaft * Unbolted & removed power divider * Replaced o-rings * Refit power divider * Removed shims as required to take out excessive end float * Removed yoke * Removed leaking input seal * Cleaned down all sealing surfaces * Installed replacement seal * Refit yoke * Aligned & tensioned all components										16/10/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	DrivLine\DRV LN SER	* Test operations - All ok. fault no lonaer oresent Needs new cab mounts INSPECT CAB SHOCKS - REPLACE IF REQUIRED . * Inspected cab shocks & confirmed leaking & require replacement * Supported cab * Secured, unbolted & removed shocks * Installed replacement shocks * Secured in place * Aligned & tensioned all components * Test operations - All ok INSPECT CAB MOUNTS - REPLACE IF REQUIRED . * Inspected cab mounts & confirmed rear mounts worn & require replacement * Attempted to remove cab mounts but found bolt to be seized * Fabricated removal of bolt * Removed cab mounts * Cleaned down all surfaces * Installed replacement cab mounts * Aligned & tensioned all components * Test operations - All ok										16/10/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	DriCabRep\MOUNTS	Engine\RADIATOR REPORTS ENGINE OVERHEATING . * Test operations * Unable to confirm fault * Connected laptop & scanned for faults - none present * Test drove with laptop connected - unable to confirm fault										16/10/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	Engine\RADIATOR	* Customer to monitor DrCabElect\INST/GAUGE DURING REPAIRS, LOCATED BLOWN DASH GLOBES . * Checked electrical routing * Confirmed dash lights out * Removed dash panel & components for access * Removed/replaced blown dash globes * Re check electrical routing * Install dash components complete										16/10/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	* Test, confirm & quality check repair										16/10/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	Truck Has Air Leak Somewhere Dumps All Air										14/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Brakes\BRK RELINE	Reline Drive Brake's All Axles	Has been completed by twincity									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	Main trans temp & cruise globes	Previously completed									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Susp\SHOCK ABS	After 650km back shocks probably passed use by date	All shocks look OK and are not loose nor are they leaking Mirror covers areok									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Body\MIRRORS	Mirror Covers	1									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonaa Workshop P/MOVER
1046	Wodonga - Workshop	DriCabRep\ELECT P&W	Cruise Globe Blown	Previously completed									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	DrivLine\DAMAGE	Front and rear torque rod bushes will need replacing have begun to bulge out	Do not need replacing they are more than ok									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	DriCabRep\ELECT P&W	Fuel Gauge Globe Blown	Previously completed									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Engine\RADIATOR	radiator & intercooler needs clean out- getting hot.	Has been cleaned out									01/10/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Engine\FAULT CODE	Job Created from Purchase Order #: 104197										01/10/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	Engine\ENG TUNE	Tune Engine (Cummins Wodonga P/O: WWOB8941) B Service.										26/09/2024	571110	Completed	Mt Gambier STK XV66MC CUMMINS SOUTH PACIFIC P/L P/MOVER
1046	Wodonga - Workshop	VehService\BS	Serviced @ 650.640 Klms	I									23/09/2024	571110	Completed	Mt Gambier STK XV66MC Wodonaa Workshop P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	After Treatment Light On	No after treatment light however adblue o ring was pinched									23/09/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Body\DAMAGE	A-Service.New Wiper Blades. Cruise & Fuel Gauge Globes Blown. Put Chrome A										23/09/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service										23/09/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\AS	VehService\AS										23/09/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	DriCabRep\WIPERS	Replace Combination Switch										07/09/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\AS	VehService\AS										07/09/2024	641158	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	After Treatment Faults Truck Derated /Brown & Hurley Coffs Habour P/O: WA										19/08/2024	571110	Completed	Mt Gambier STK XV66MC PACCAR PARTS FLEET SERVICES P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	Brake Squeal D/S Rear Axle? Or Front Axle										17/08/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\BS	O/Due For Services	Duplicate entry									17/08/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\BS	B SERVICE DUE PLUS OTHER STUDD ON R&RS B Service Serviced @ 628804 Klms	Duplicate entry									17/08/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\BS		DEGAS A/C SYSTEM REMOVE COMPRESSOR AND RECIVER DRIER. FIT NEW COMPRESSOR AND BELT SUPPLIED BY GREENFRIGHT. FIT NEW RECIVER DRIER REGAS SYSTEM TEST OK. DRIVE TRUCK BACK TO GREENFRIGHT EVACUATE AND REGAS ADD UV DYE AND OIL									17/08/2024	571110	Completed	Mt Gambier STK XV66MC Wodonaa Workshop P/MOVER
1046	Wodonga - Workshop	Air Con\AIR CON	A/C Comoressor Bearine Noisv. Reolace A/C Comoressor & Reeas Svstem. IHas	CHECK PRESSURES AND TEMPS ALL OK.									03/08/2024	571110	Completed	Mt Gambier STK XV66MC HAGANS AUTO ELECTRICAL SERVICE P/MOVER
1046	Wodonga - Workshop	Engine\BELTS/TENS	Check Belt Idlers & Tensioners. Klms Were 615,659 Klms At Time Of Repair. TRAVEL OUT TO GREENFRIGHT CHECK OUT TRAUER PLUG ON TRUCK FOUND FAULTY TRAUER PLUG, RR TRAUER PLUG	Replaced A/C Tensioner & Idler Pulley, A/C Comoressor To Be Reolaced Noisv Bearine. Soins Like Drv Bearine.									27/07/2024	571110	Completed	Mt Gambier STK XV66MC Wodonaa Workshop P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	TEST OK TRAVEL BACK HOME Replace Leaking Hub Seal R/H Front Drive										24/07/2024	571110	Completed	Mt Gambier STK XV66MC HAGANS AUTO ELECTRICAL SERVICE P/MOVER
1046	Wodonga - Workshop	DrivLine\OIL LEAK		DAN W 5 HOURS LABOUR.									20/07/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service										20/07/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\AS	VehService\AS										20/07/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Tyres\TPI+2	Tyres\TPI+2										29/06/2024	571110	Completed	Mt Gambier STK XV66MC BEAUREPAIRES P/MOVER
1046	Wodonga - Workshop	VehService\AS	O/Due for A Service										28/06/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Tyres\STEER TYRE	Due To Tyre Wear Possibly Needs Wheel Alignment	Brand new steer tyres on it no indication it needs a wheel alignment									28/06/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\AS	A service	600514									28/06/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	DriCabRep\MOUNTS	Probably Due For Cab Mounts	Cab mounts r OK front shocks were very poor									28/06/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Susp\SHOCK ABS	Front Shock Absorbers										28/06/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	VehService\AS	VehService\AS										28/06/2024	571110	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Tyres\TPY+8	Tyres\TPY+8										03/06/2024	569827	Completed	Mt Gambier STK XV66MC BEAUREPAIRES P/MOVER
1046	Wodonga - Workshop	Tyres\TPY+8	Tyres\TPY+8										03/06/2024	569827	Completed	Mt Gambier STK XV66MC BEAUREPAIRES P/MOVER
1046	Wodonga - Workshop	Tyres\TPY+10	Tyres\TPY+10	Read diff input seal weaping. All shock absorbers were tightened.									03/06/2024	569827	Completed	Mt Gambier STK XV66MC BEAUREPAIRES P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service	Cody was also on service									25/05/2024	569827	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	DrCabElect	Mtdata 4G Update										20/05/2024	569827	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER
1046	Wodonga - Workshop	Air Con											24/04/2024	569932	Completed	Mt Gambier STK XV66MC Wodonga Workshop P/MOVER

1046	Wodonga - Workshop	Elect\BATTERY	AS PER R&R 129596 PLUS CHECK/ REPLACE BATTERIES. HARD TO START & FEW T		24/04/2024	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\TRL LIGHTS	TRAILER PLUG PIN PUSHED IN. KEEP LOSING INDICATORS OCCASIONALLY. POSSI		24/04/2024	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Insp\ANN INSP	Annual inspection		24/04/2024	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\BATTERY	truck shut down	found loose battery terminal	18/04/2024	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Workshop\MOVE ASSET	PICKED UP CUMMINS.		09/04/2024	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	B service		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\WIPERS	Fit new wiper blades		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\FIFTH WHEE	Check turntable jaws for wear		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\FITMENT	Tyre shed fit new on rear axle	BEAUREPAIRS FITTER ADVISED TO LEAVE FOR A MONTH.	07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	Check steer brakes especially P/S		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Susp\SHOCK ABS	New shock absorbers on truck getting very rough		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	Engine brake light globe blown, also left side globe tacho		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	TRUCK HAS AIR LEAK SOMEWHERE. O/NITE DUMPS ALL AIR.		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	PM LOSE AIR. POSSIBLY AIR DRYER OR AUTO DRAIN?		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/04/2024	563743	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE		22/03/2024		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\GOV VALVE	Air Leaking @ Governor Valve	REPLACED GOVERNOR VALVE. CHECKED FOR LEAKS. OK.	06/03/2024	545686	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	Ad Blue & Doser		04/03/2024	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
			CALLOUT AFTER HOURS TRAVEL TO DEPOT FOUND WIRING BETWEEN TRAILER DAMAGED REMOVE DAMAGED WIRING AND REPLACE WITH CURLY CABLE									
1046	Wodonga - Workshop	Elect\ELECT P&W	OPERATION OK		04/03/2024		Completed	Mt Gambier	STK	XV66MC	Albury Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	Removed & Cleaned Blocked Doser Injector		01/03/2024	541461	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		22/02/2024		Completed	Mt Gambier	STK	XV66MC	Albury Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		22/02/2024		Completed	Mt Gambier	STK	XV66MC	Albury Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	B SERVICE.		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	PM LOSE AIR. POSSIBLY AIR DRYER OR AUTO DRAIN?		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	CRACKED P/S WINDSCREEN.		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\BLK VALVE	ROLL PIN ON BLACK BUTTON COMING OUT.		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	CHECK FRONT BRAKES- GRAB TO LEFT.		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\HOUSEKEEP	O/HEAD LOCKER HINGE BROKEN.	tightened hinges,	09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	CHECK FRONT BRAKES- PULLS TO LEFT.	adjusted brakes, driver to monitor	09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Susp\WHEEL ALGN	-TRUCK PULLS TO THE LEFT-		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR TANKS	P/S AIR DRAIN CORD IS BROKEN.		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	AND STRAIGHTEN STEERING WHEEL!		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/02/2024	531622	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	REPAIRED LEAK AT STRAINER ON FRONT DIFF.	26/01/2024	524633	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\HOUSEKEEP	O/HEAD LOCKER HINGE BROKEN.		26/01/2024	524633	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	CHECK FRONT BRAKES- PULLS TO LEFT.		26/01/2024	524633	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR TANKS	P/S AIR DRAIN CORD IS BROKEN.		26/01/2024	524633	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2024	524633	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Steering\HUBCAP	Tightened Both Steer Hubcaps & Replaced Rubber Bungs		23/01/2024	522691	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\HOUSEKEEP	O/HEAD LOCKER HINGE BROKEN.		07/01/2024		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\PANELS	TOP LOCKER BOX HINGE IS BROKEN.		07/01/2024		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine	STILL LACKS POWER. TURBO BOOST UP HILLS MAX OUT 180-190 & DOWN TO 17		05/01/2024	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine	*TRUCK IS GUTLESS- LACKS BOOST- GET IT GOING!!!		05/01/2024	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Prevent\SHOCK ABS	Replace All Shock absorbers		28/12/2023	514555	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	TIGHTENED FILLER TUBE.	28/12/2023	514555	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\ENG TUNE	engine low on power	ADJUSTED WASTEGATE. CHECKED FOR BOOST LEAKS. REPLACED BOOST HOSE FROM TURBO.	28/12/2023	514555	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR TANKS	P/S AIR TANK DRAIN CABLE BROKEN.		28/12/2023	514555	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	DRIVER'S SIDE WINDSCREEN CRACKED IN FIELDS OF VIEW.		28/12/2023	514555	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/12/2023	514555	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine	STILL LACKS POWER. TURBO BOOST UP HILLS MAX OUT 180-190 & DOWN TO 17		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\HOUSEKEEP	O/HEAD LOCKER HINGE BROKEN.		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	CHECK FRONT BRAKES- PULLS TO LEFT.		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\PANELS	TOP LOCKER BOX HINGE IS BROKEN.		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	AND STRAIGHTEN STEERING WHEEL!		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Susp\WHEEL ALGN	-TRUCK PULLS TO THE LEFT-		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine	*TRUCK IS GUTLESS- LACKS BOOST- GET IT GOING!!!		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\BRAKE ADJ	CHECK/ ADJUST FRONT BRAKES.		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Chassis\AIR TANKS	P/S AIR DRAIN CORD IS BROKEN.		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	P/S WINDSCREEN.		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/12/2023	506740	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\COMPRESSOR	TCTC SUPPLY AIR DRYER KIT		13/11/2023	571110	Completed	Mt Gambier	STK	XV66MC	Albury Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	AND STRAIGHTEN STEERING WHEEL!		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\STEER TYRE	STEER TYRES CHECK/ ROTATE.		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	DRIVER'S SIDE WINDSCREEN CRACKED IN FIELDS OF VIEW.		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	P/S WINDSCREEN.		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Prevent\TRANS OIL	Transmission Oil Change		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrivLine\DIFF OIL	Diff Oil Change		10/11/2023	569932	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine	RETAIL DURING PREEMPTIVE LOW LINER REPAIR		07/11/2023	492461	Completed	Mt Gambier	STK	XV66MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		29/10/2023	488690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	AND STRAIGHTEN STEERING WHEEL!		29/10/2023	488690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	P/S WINDSCREEN.		29/10/2023	488690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\STEER TYRE	STEER TYRES CHECK/ ROTATE.		29/10/2023	488690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrivLine\OIL LEAK	rear Diff weep	TIGHTENED LOOSE HOUSING BOLTS AND DRAIN PLUG. CLEANED OIL OFF DIFF.	29/10/2023	488690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/10/2023	488690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
			- ATTEND CALLOUT TO ALPINE MDF WANGARATTA TO VEHICLE WITH TRAILER PLUG FAULT. UPON INSPECTION FIND PLUG TO BE UNSECURE IN HOUSING. DISMANTLE PLUG AND SECURE PLUG IN CORRECT LOCATION. CONNECT PLUG TO TRAILER SOCKET AND TEST ALL LIGHTS. RETURN TO WORKSHOP.									
1046	Wodonga - Workshop	Elect\BREAKDOWN	After treat issues Brown & Hurley Darra		27/10/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\BREAKDOWN	POH WWDB3045. Exhaust Leak (Cummins Laverton)		14/09/2023	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\EXHAUST	Purchase Order Number: WWDB0976		12/09/2023	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\TURBO	TCTC supply KIT TURBOCHARGER ACTUATOR/WASTEGATE		11/09/2023	571110	Completed	Mt Gambier	STK	XV66MC	Albury Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		19/08/2023	451824	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.		19/08/2023	451824	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\YEL VALVE	CHECK/ REPLACE MAXI BRAKE (YELLOW) BUTTON. LEAKS AIR.		19/08/2023	451824	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	Left Windscreen Cracked.		19/08/2023	451824	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		19/08/2023	451824	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrivLine\OIL LEAK	rear Diff weep		08/08/2023	452697	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.		08/08/2023	452697	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		08/08/2023	452697	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	AND STRAIGHTEN STEERING WHEEL!		08/08/2023	452697	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	P/S WINDSCREEN.		08/08/2023	452697	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\STEER TYRE	STEER TYRES CHECK/ ROTATE.		08/08/2023	452697	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/08/2023	452697	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		18/07/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	Left Windscreen Cracked.		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	STRAIGHTEN STEERING WHEEL.		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	REVERSING BEEPER- COLES STYLE-		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	CHECK/ REPLACE ELEC PLUG.		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ALT	CHECK ALTERNATOR- CONTACT GRAHAM IN REGARDING ALTERNATOR.		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Replace L/H Windscreen (Albury Autoscreen)		18/07/2023	438864	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Body\WINDSCREEN	Purchase Order Number: WW079580		14/07/2023	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		01/07/2023	429888	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	"A" SERVICE.		01/07/2023	429888	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	CHECK/ REPLACE ELEC PLUG.		01/07/2023	429888	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	STRAIGHTEN STEERING WHEEL.		01/07/2023	429888	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ALT	CHECK ALTERNATOR- CONTACT GRAHAM IN REGARDING ALTERNATOR.		01/07/2023	429888	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2023	429888	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		11/06/2023	419445	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.		11/06/2023	419445	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	CHECK/ REPLACE ELEC PLUG.		11/06/2023	419445	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	STRAIGHTEN STEERING WHEEL.		11/06/2023	419445	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ALT	CHECK ALTERNATOR- CONTACT GRAHAM IN REGARDING ALTERNATOR.		11/06/2023	419445	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job engine de-rating		11/06/2023	419445	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\FAULT CODE	Brown & Hurley Coffs Habour to repairs Check Electrical Fault (Hagan's)		07/06/2023	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	Purchase Order Number: WW078484		22/05/2023	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		07/05/2023	399414	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/05/2023	399414	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
				Test drive and unable to confirm fault. - Inspect all steering and suspension components.								
1046	Wodonga - Workshop	Susp\SHOCK ABS	Front end very rough, needs new shocks.	- Found RHF drive shock bushe to be u/s.	06/04/2023		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER

				CUSTOMER REPORTS TRANS DOESN'T SHIFT PROPERLY AND GETS STUCK IN GEAR. - Connect to TECU and check faults. - Found multiple inactive codes for communication faults.										
			Gear changes in lower few gears are getting slower and slower.	- Disconnect harness from trans and inspect for damage or moisture, ok.										
			A few times when lifting off on a corner with a slight grade gearbox goes up and down.	- Reconnect with d-electric grease. - Inspect harness from ECU to engine harness and found 2x rubbed wires.										
			Gears not know what gear to take off in. It then takes off and then stops again.	- Strip back harness andrepair wires as required, - Resecure harness.										
			Near stalling up & down gears till it works out what to do.	- Carry out tests of remainder of harness to cab, all ok.										
1046	Wodonga - Workshop	DrivLine\GEARBOX	This can haopen 3-4 times for us to a minute. A SERVICE. (TCTC)	- Clear fault codes and test drive. all ok		06/04/2023		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	Purchase Order Number: WW077674. A SERVICE.			06/04/2023		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\ENG TUNE	Needs to be tuned for more get up & go.11/04/2023 CUMMINS			06/04/2023		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Elect\ALT	CHECK ALTERNATOR- CONTACT GRAHAM IN REGARDING ALTERNATOR. A Service As Per Attached Checklist			06/04/2023		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	DONE BY TCTC			06/04/2023	1	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/04/2023	1	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist			18/03/2023	386645	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.			18/03/2023	386645	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACE TURNTABLE DOGBONES.			18/03/2023	386645	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/03/2023	386645	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACE TURNTABLE DOGBONES.			26/02/2023	377206	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist	ADJUSTED TURNTABLE JAWS. REPLACED AIR FILTERS.		26/02/2023	377206	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job CHECK A/C N/W TRAVEL TO GREENFREIGHTS YARD CHECK AC NW. LIFT CAB AND CONNECT AC GAUGES. LOCATE LOW ON GAS REMOVE AND REPLACE R/DRIER LOCATE PRESSURE SW HAD BUNRT PINS AND REPLACE. EVACUATE NO REGAS AC SYSTEM ADD UV DYE AND OIL			26/02/2023	377206	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Air Con\AIR CON	CHECK PRESSURES AND TEMPS			20/02/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			15/02/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			15/02/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	DrivLine	CHECK TRUCK SHAKING CAB & STEER.			14/02/2023	571110	Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			09/02/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP05	Tyre Position 5			09/02/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			04/02/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			04/02/2023		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE. TRUCK OVERHEATING. -RUNNING UP TO 105-.			04/02/2023	367045	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\RADIATOR	REFER SHAUN.	DISMANTLED. ATTEMPTED TO DEBUG RADIATOR AND INTERCOOLER. PRESSURE WASHER CUTTING IN & OUT. REASSEMBLED AND TEST DROVE. RESEALED INTAKE FLANGE AND REPLACED TURBO COUPLING.		04/02/2023	367045	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\PANELS	BROKEN DRIVER'S STEP.			04/02/2023	367045	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	REPLACED STEPS.		21/01/2023	359442	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\PANELS	DRIVER'S STEPS BROKEN.			21/01/2023	359442	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/01/2023	359442	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	SERVICE.			31/12/2022	348454	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist			31/12/2022	348454	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\PANELS	DRIVER'S STEPS BROKEN.			31/12/2022	348454	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/12/2022	348454	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP04	runout			21/12/2022		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			04/12/2022		Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist			19/11/2022	325993	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.			19/11/2022	325993	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabRep\WIPERS	FIT NEW WIPER BLADES.			19/11/2022	325993	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Oil leaking from filter housing. Brown & Hurley Kyogle.			19/11/2022	325993	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\BREAKDOWN	PO# WW075086			15/11/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\OIL LEAK	Engine Oil Leak	Refer Job # 395587		10/11/2022	322119	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\OIL LEAK	Tightened Oil Filter			10/11/2022	322119	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\EXHAUST	EXHAUST MANIFOLD LEAKING.			04/11/2022	319159	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Chassis\AIR TANKS	AIR TANKS LEAKING.			28/10/2022	318003	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Chassis\AIR TANKS	Replaced Purge Tank	FITTED TANK REMOVED FROM 1002.		28/10/2022	318003	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP09	Tyre Position 9			28/10/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Albury - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMENT- PULLS TO THE RIGHT.			25/10/2022	314792	Completed	Mt Gambier	STK	XV66MC	Albury Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\FITMENT	pos 1 flipped			22/10/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist			20/10/2022	314789	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	C SERVICE.			20/10/2022	314789	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.			20/10/2022	314789	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\BALANCE	WHEEL BALANCE.			20/10/2022	314789	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Elect\BATTERY	CHECK BATTERIES.	REPLACED BATTERIES.		20/10/2022	314789	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\EXHAUST	EXHAUST MANIFOLD LEAKING.			20/10/2022	314789	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2022	314789	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	Unblock Breather Hose	REPLACED TEA BAG FILTER.		28/09/2022	304803	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Elect\TRL LIGHTS	Replaced Trailer Plug			28/09/2022	304803	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\FUEL TANK	ADBLUE TANK BREATHER BLOCKED.			22/09/2022	300998	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Chassis\FUEL TANK	Unblock Adblue Tank Breather			22/09/2022	300998	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	balance & rotation			17/09/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.			17/09/2022	297951	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabRep\ST Weel	STRAIGHTEN STEERING WHEEL.	TEST DROVE. ADVISED TYRE FITTER- ROTATED STEERS AND BALANCED. TEST DROVE.		17/09/2022	297951	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabRep\WIPERS	P/S WIPER BLADE.	REPLACED WIPERS BLADES.		17/09/2022	297951	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	"FRONT AIR" GAUGE BULB BLOWN.	REPLACED.		17/09/2022	297951	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	ADDED 3.5L ENGINE OIL.		17/09/2022	297951	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/09/2022	297951	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\FAULT CODE	CONNECTED LAPTOP. RE-SET 3 TIMES TO CONNECT INSITE. DE-ACTIVATED ECM			03/09/2022	290663	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	TIGHTENED LEAKING OIL FILLER.		25/08/2022	228338	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\EXHAUST	EXHAUST MANIFOLD LEAKING.			25/08/2022	228338	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.			25/08/2022	228338	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/08/2022	228338	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Workshop\MOVE ASSET	PICK UP TCTC.			24/08/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	ELECTRICAL PROBLEMS. Covid Clean by Border Cleaning Services.			23/08/2022	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabRep\COVID	PO# WW073727			23/08/2022	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\ELECT P&W	step lights ,interior lights and door alarm not working			23/08/2022	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Elect\ELECT P&W	ELECTRICAL PROBLEMS.			19/08/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Susp\AIR LEAK	BROKEN AIR LINE.			19/08/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Susp\AIR LEAK	BROKEN AIR LINE.			18/08/2022	285057	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\ELECT P&W	step lights ,interior lights and door alarm not working	CHECKED FUSES AND RELAYS. COULDN'T FIND FAULT.		18/08/2022	285057	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Chassis\AIR LEAK	air leak at dump valve	REPLACED AIR LINE DUE TO BEING BRITTLE.		18/08/2022	285057	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Insp\END WARR	End of Warranty Inspection			17/08/2022	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Workshop\MOVE ASSET	DROP OFF TCTC.			17/08/2022	285035	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\ADBLUE	engine has derated and aftertreat light is on	kenworht wagga POww073323		10/08/2022	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist			06/08/2022	279070	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/08/2022	279070	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist			16/07/2022	266838	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabRep\WIPERS	Wiper blades worn			16/07/2022	266838	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Elect\IERATE	WHEN LOADED TRUCK MAX SPEED IS 98. SOMETIMES 99 ON THE FLAT-DOWNH	Inspected via cummins insite, will need cummins to change, refer Ash		16/07/2022	266838	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/07/2022	266838	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist	Engine Oil Sample SIF # 42623399		03/07/2022	258693	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/07/2022	258693	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.			01/06/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\BOOST HOSE	TURBO BOOST ONLY GOES UP TO 19S. NEED BOOSTING UP. IT USED TO GO TO ;			01/06/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres	CHECK STEERS FOR WEAR.			01/06/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Engine\ENG TUNE	ADJUSTED WASTEGATE. TEST DROVE WITH LOADED TRAILERS.			31/05/2022	241847	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	supply and fit 2tyres			28/05/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist			28/05/2022	241847	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\STEER TYRE	Check steer tyres for wear on edges. Possible need to rotate on rims.			28/05/2022	241847	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Elect\IERATE	WHEN LOADED TRUCK MAX SPEED IS 98. SOMETIMES 99 ON THE FLAT-DOWNH			28/05/2022	241847	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/05/2022	241847	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service due.	Refer job # 379145		01/05/2022	225540	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist			01/05/2022	225540	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2022	225540	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			13/04/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			13/04/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			13/04/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	supply and fit 8 tyres			13/04/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Unknown	A SERVICE.			03/04/2022	217048	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	REPLACED FAULTY GOVERNOR VALVE. REBUILT AIR DRYER. REPAIRED DASH LIGHTS.		03/04/2022	217048	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Drivers side Windscreen cracked Albury Autoscreens to replace.			03/04/2022	217048	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	PO# WW070787. Drivers side Windscreen cracked			18/03/2022	571110	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			14/03/2022	205308	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Tyres\TP1+2	tyre rotation			14/03/2022	205308	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\Pogo	EXTEND SLIZI COIL POLE.			12/03/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Susp\SHOCK ABS	CHECK FRONT AXLE SHOCKS- FRONT ENDVERY ROUGH AND SKIPS AROUND ON I	CHECKED STEER AND CAB SHOCKS. CHECKED STEER TYRES. 107PSI. KING PINS AND SHACKLES JUST GREASED SO WILL NEED TO BE CHECKED LATER. BEAUREPAIRS INFLATED TYRES TO 120PSI AND ROTATED STEERS. TEST DROVE. OK.		12/03/2022		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	REPAIRED OIL PRESSURE LIGHT.		11/03/2022	205308	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\Pogo	Needs High Pogo Fitted.	REMOVED AND ORGANISED ANDREW TO EXTEND. FITTED.		11/03/2022	205308	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	REPLACE DASH GLOBES.			11/03/2022	205308	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2022	205308	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Insp\RWC COMP	CLEAR RMS DEFECT NOTICE NUMBER HVN061160S - 25/2/22			26/02/2022	198810	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabElect\ELECT P&W	FUSE BLOWN CIG LIGHTER.	REPLACED FUSE. TESTED. REPLACED FIRST AID KIT. DRAINED AIR TANKS. REPLACED BELTS.		23/02/2022	197675	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist	Enaine Oil Samole SIF # 42629618		20/02/2022	195853	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	REPLACE DASH GLOBES.			20/02/2022	195853	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/02/2022	195853	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER
1046	Wodonga - Workshop	Body\DAMAGE	TCTC supply BUMPER-FRONT	REPLACED FRONT BAR.		17/02/2022	198797	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop		P/MOVER

1046	Wodonga - Workshop	Unknown	A SERVICE		06/02/2022	188447	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service due		06/02/2022	188447	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		06/02/2022	188447	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabRep\ST Wwel	Straightened steering wheel		06/02/2022	188447	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\Pogo	Needs High Pogo Fitted.		06/02/2022	188447	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/02/2022	188447	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes\ABS	NEEDS NEW ABS PLUG		23/01/2022	181075	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Unknown	A SERVICE		23/01/2022	181075	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	ADDED 4L ENGINE OIL	23/01/2022	181075	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes\ABS	ABS PLUG BROKEN	REPLACED BROKEN PLUG. REPLACED SUZI LEADS AND NEATENED UP.	23/01/2022	181075	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabElect\CRUISE CON	Cruise control light globe blown.	REPLACED GLOBE	23/01/2022	181075	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/01/2022	181075	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Engine\ADBLUE	ADBLUE FAULT.	CLEANED ALL LINES WITH HOT WATER AND BLEW CLEAR. REPLACED DOSER. REPLACED TEA BAG FILTER. ATTEMPTED TO CLEAR CODE. REPEATED PROCESS.	15/12/2021	171807	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A service		05/12/2021	167618	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		05/12/2021	167618	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/12/2021	167618	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Workshop\MOVE ASSET	PICK UP TCTC		01/12/2021	165776	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\Pogo	Needs High Pogo Fitted.		30/11/2021	168728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\STEER TYRE	Tyres need flipping on the rim.		30/11/2021	168728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\ROTATION	Rotate Drives.	INSPECTED WITH TYRE FITTER. FOUND TO BE OK.	30/11/2021	168728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\STEER TYRE	STEER TYRES WORN OUT	INSPECTED WITH TYRE FITTER. FOUND TO BE GOOD.	30/11/2021	168728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
				* Removed windscreen strip & wiper arm									
				* Removed camera from windscreen									
				* Removed chipped windscreen									
				* Cleaned out seal									
				* Lubed seal & installed new windscreen									
				* Adjusted seal over new windscreen									
				* Reinstalled wiper arm & strip									
				* Cleaned new windscreen									
			LH WINDSCREEN CHIPPED	* Reinstalled camer & secured									
				* Tested wiper operation									
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	REPLACE CHIPPED L/H WINDSCREEN - 30/11/21	* Repair comolete	30/11/2021	165728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	LH WINDSCREEN CHIPPED	REPLACED	30/11/2021	165728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrivLine\GEARBOX	GEARBOX FILTER HOSE LEAKING	WASHED AND TESTED. OK	30/11/2021	165728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Engine\EXHAUST	EXHAUST MANIFOLD LEAKING	REPLACED	30/11/2021	165728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrivLine\OIL LEAK	THROUGH-SHAFT SEAL LEAKING		30/11/2021	165728	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Steering\WHEEL ALGN	Perform laser wheel alignment on K200 prime mover		27/11/2021	165677	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Unknown	A SERVICE		07/11/2021	158700	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	LH WINDSCREEN CHIPPED		07/11/2021	158700	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabRep\ST Wwel	STRAIGHTEN STEERING WHEEL	STRAIGHTENED STEERING WHEEL AND TEST DROVE	07/11/2021	158700	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	ADJUSTED TURNTABLE JAWS	07/11/2021	158700	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/11/2021	158700	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check		26/10/2021	153018	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\TP1+2	supply and fit 2 tyres		26/10/2021	153018	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service Due.	Refer Job# 356751	09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\ROTATION	Tyre Rotation needed.	Refer Job# 356898	09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\ROTATION	Rotate Drives.		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\STEER TYRE	STEER TYRES WORN OUT		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabRep\WINDSCREEN	LH WINDSCREEN CHIPPED		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrivLine\GEARBOX	GEARBOX FILTER HOSE LEAKING		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Engine\EXHAUST	EXHAUST MANIFOLD LEAKING		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrivLine\OIL LEAK	THROUGH-SHAFT SEAL LEAKING		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist	REPLACED ADBLUE TEABAG FILTER	09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\Pogo	Needs High Pogo Fitted.		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/10/2021	146944	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
			1.Supply and fit Coolabah 6.5kw battery with 12v back charger – Kenworth										
			K200 – Chassis # 465981 – REGO # XV66MC										
1046	Wodonga - Workshop	Air Con\AIR CON	air conditioner fitment through Hume Truck Technics		21/09/2021		Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service due	Refer Job # 354393	18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service due.	Refer Job # 354393	18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Elect\SUZI COIL	ABS Plug truck side.	Refer Job# 354400	18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabRep\ST Wwel	Steering wheel locked up.		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\ROTATION	Rotate Drives.		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\STEER TYRE	Check Steer tyres	Refer Job # 354396	18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	ABS Light on dash.	Replaced coroded and damaged plug.	18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\MIRRORS	Drivers side mirror needs tightening up wobbles around.		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\Pogo	Needs High Pogo Fitted.		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\MIRRORS	Mirrors loose flap around.		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\STEER TYRE	Tyres need flipping on the rim.		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Engine\FILTERS	Need to change.		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/09/2021	137479	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A service due.	Refer Job# 351064	22/08/2021	127234	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		22/08/2021	127234	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\MIRRORS	Drivers side mirror needs tightening up wobbles around.		22/08/2021	127234	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\MIRRORS	Mirrors loose flap around.		22/08/2021	127234	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/08/2021	127234	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Chassis\HOUSEKEEP	Chequer plate repair.	Repair walk plate lock due to damage.	11/08/2021	122331	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A service due.		31/07/2021	117785	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		31/07/2021	117785	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\MIRRORS	Drivers side mirror needs tightening up wobbles around.		31/07/2021	117785	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
			Weight gauges fitted and spring pressures gauges set up equally.										
1046	Wodonga - Workshop	Susp\WGHT GAUGE	At the moment 100 KPA difference.		31/07/2021	117785	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\Pogo	Needs High Pogo Fitted.		31/07/2021	117785	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\MIRRORS	Mirrors loose flap around.		31/07/2021	117785	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		31/07/2021	117785	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Engine\FUEL TANK	UNBLOCK AD-BLUE TANK BREATHER		08/07/2021	110268	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Workshop\MOVE ASSET	Drop truck off to TCTC for warranty repairs.		02/07/2021		Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\TP1+2	tyre rotation & balance		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Unknown	B- Service Due.		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	Engine Brake and Turbo Boost globes U/S		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Engine\TURBO	Turbo Boost 190 - Dean.	Turbo boost should be between 190-210 KPA	01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabElect\INST/GAUGE	Set spring pressure gauges so they both read the same.	Previously completed.	01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\Pogo	Needs High Pogo Fitted.		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
			Mirrors loose flap around.										
1046	Wodonga - Workshop	Body\MIRRORS	Truck RPM needs increasing.	Truck RPM needs increasing.	01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
				Timed truck to see how quick it drained air.									
				Rear tank dropped 200+ KPA over 25-30 minutes.									
1046	Wodonga - Workshop	Brakes\AIR TANKS	Drives dump air after 10 mins.	Airtank feed connection loose. tightened up fittina.	01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\STEER TYRE	Tyres need flipping on the rim.		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Engine\FILTERS	Need to change.		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Chassis\FIFTH WHEE	Turn Table eyes worn	Nothing wrong with bushes.	01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/07/2021	107540	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Maintenance		29/06/2021	106454	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Workshop\MOVE ASSET	Drive to TCTC to pick up Graham & T598 and return to Wodonga Depot.		19/06/2021	106096	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Chassis\FIFTH WHEE	Turn Table eyes worn		18/06/2021	105692	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		18/06/2021	105692	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
			Pick up from TCTC, had flat batteries.										
			On drive back to yard, stalled at lights twice.										
1046	Wodonga - Workshop	Engine\BATTERY	Recommend return to TCTC for repair.	TCTC attended Wodonga yard, corrected issue.	18/06/2021	105692	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/06/2021	105692	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
			Pick up from TCTC, had flat batteries.										
			On drive back to yard, stalled at lights twice.										
1046	Wodonga - Workshop	Engine\BATTERY	Recommend return to TCTC for repair.		16/06/2021	106041	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
			Remove load scales										
			Travel to TCTC. Pull roof console out, dash forward and A-pillar panel out to										
			remove load scales from inside truck. Remove cable running to battery box.										
1046	Wodonga - Workshop	DrCabElect\SCALES	Put truck back toaether. Return to workshop.		16/06/2021	105651	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		02/05/2021	90375	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/05/2021	90375	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrCabRep\HOUSEKEEP	Job Added From Invoice		26/04/2021	0	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	Completed, Included Smoko and Leading Hand Duties	31/03/2021	80216	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Chassis\SUZI COIL	No Brake & Reverse Lights	No Brake or Reverse Lights, inspected trailer plug and lead for obvious faults. None found reset circuit breaker and tested all ok.	31/03/2021	80216	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes\ABS	need longer ABS lead	Previously Completed	31/03/2021	80216	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	DrivLine\OIL LEAK	gearbox is leaking oil inside bell housing	previously completed	31/03/2021	80216	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		31/03/2021	80216	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body	Job Added From Invoice		27/03/2021	0	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	completed	03/03/2021	66738	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/03/2021	66738	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes\SPAREWHEEL	change EBS plug as 12v fitted not suitable for 24v plugs on trailers		18/02/2021		Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
				replace suzi coils									
1046	Wodonga - Workshop	Body\HOSES	suzi coil stretched	completed	10/02/2021	56513	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Chassis\SUZI COIL	damaged suzi coils due to not being disconected when uncoupling from trailer	hallum truck centre to repair P/O WW061754	06/02/2021		Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	Carry Out A Service	16/01/2021	50526	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Carry Out A Service	16/01/2021	50526	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Body\FUEL TANK	adblue tank sucking in	unblock adblue breather, popped out adblue tank walls	03/12/2020	35038	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		01/12/2020	33592	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Workshop\CLEAN	clean workshop		01/12/2020	33592	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/12/2020	33592	Completed	Mt Gambier STK	XV66MC	Wodonga Workshop	P/MOVER		

				TCTC looked at it at holbrook , taking back to TCTC * Customer contacted dealership to report breakdown * Technician currently situated not far from location * Technician travelled to breakdown site at Holbrook, NSW * Inspect truck to diagnose repair * Customer advised that truck has ABS light on, service light on cobra shift, F flashing in gear display, cruise control won't work * Attempt to connect diagnostic tooling - unable to connect * Tested J1939 @ 60 ohms * Tested continuity to ECM OEM plug - no failure evident * Technician unable to further diagnose * Truck will have to return to dealership * Technician returned home. * Customer advised that they tried to change ECM settings & the computer dropped out * Technician attempted to connect diagnostic tooling * Unable to connect to ECM & transmission warning light on * Technician attempted with another computer to connect diagnostic tooling - unable connect * Technician then connected to transmission & braking via diagnostic plug * Pinned out diagnostic plug & tested continuity - 60 ohms evident * Jacked cabin over & inspected fuses, battery box & components - no failure evident * Check & test CAN splice connector at engine - no failure evident * Disconnect OEM plug at ECM, check pins & components - no failure evident * Attempt to connect diagnostic tooling to engine again - unable to connect * Connected to engine ECM via engine harness * Technician successfully got to connect & communicate * Aging 3Dhr Inactive code 2377 evident * Check codes in transmission & ABS - no brake pedal signal * CAN message - incorrect disable hill start assist * Disconnected batteries & left idle * Check engine settings * Located turned off service brake switch * Customer had turned this off & locked ECM * Technician was unable to change * Checked over CAN wiring to ECM - no failure evident * Actioned Cummins to perform ECM update * Technician								
1046	Wodonga - Workshop	Engine\FAULT CODE	elec issue with ECM	attemoted to connect diaenostic toolina - successful * Secure & weatherproof all wirina * Road test. confirm & quality check repair * Return truck to service	19/11/2020	28051	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Workshop\MOVE ASSET	pick up from TCTC broken down at Nolbrook - swapped 1047 with 1046 xscorted Grant up and back just in case 1046 broke down again		17/11/2020		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Workshop\MOVE ASSET	dropped 1046 off at TCTC. picked Grant up from TCTC		13/11/2020	28873	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Elect\TRL LIGHTS	make trailer plug adapter	completed	12/11/2020		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	Carry Out A Service	29/10/2020	23690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Carry Out A Service	29/10/2020	23690	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Engine\FAULT CODE	download ecm data and email to Dean Salmon		27/10/2020	22754	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	Carry Out A Service	29/09/2020	14138	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/09/2020	14138	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Workshop\MOVE ASSET	park on pad		28/09/2020		Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
				carry out A Service								
1046	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	truck needs to go to TCTC - gearbox oil leak inside bell housing	18/09/2020	155841	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	DrivLine\OIL LEAK	gearbox is leaking oil inside bell housing		18/09/2020	155841	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist		18/09/2020	155841	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/09/2020	155841	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Carry out A Service	18/09/2020	155841	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist		06/09/2020	6940	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		06/09/2020	6940	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Rosewood - Workshop	VehService\CS	Service As Per Attached Checklist		06/09/2020		Completed	Mt Gambier	STK	XV66MC	Rosewood Workshop	P/MOVER
1046	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job		06/09/2020		Completed	Mt Gambier	STK	XV66MC	Rosewood Workshop	P/MOVER
1046	Wodonga - Workshop	Brakes\VALVES	THIRD BUTTON * SUPPLY AND FIT THIRD BUTTON TRAILER BRAKE RELEASE park and unhook trailers	Removed dash panels. * Fabricated brackets for solenoid mountine. * Mounted solenoid. * Removed dash panel for third button mountine. * Marked. drilled hole and mounted safety latch. * Ran olumbine as required. * Ran wirine as required and connected. * Started truck and checked for leaks. * Tested system. .	03/09/2020	4252	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER
1046	Wodonga - Workshop	Workshop\MOVE ASSET	drop off at TCTC		31/08/2020	4239	Completed	Mt Gambier	STK	XV66MC	Wodonga Workshop	P/MOVER