EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	DistanceDone	Workstate	Location	Division	Rego	Supplier	EquipmentType
				MINI B SERVICE								
			VehService\B1 Svc B 1 Service,	Jack up steer axle, check bearing & king pin. Replace cab								
			Jack up steer axle check bearings and king pins.	filter								
1047	Mt Gambier - Mt Gambier	VehService\B1 Svc	Replace cabin filter.		26/08/2026	860527	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Mt Gambier - Mt Gambier	Tyres\STEER TYRE	2 new steer tyres		25/08/2026	859675	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\WINDSCREEN	FIT NEW WINDSCREEN		19/08/2026	858704	Completed	Mt Gambier	STK	XV67MC	WESTON TINTING & WINDSCREENS	P/MOVER
				SEAT BELT ALARM NOT GOING OFF								
				Used buzzer as originally charged on 404744. Installed new								
				buzzer for seat belt alarm and joined all wiring. Checked								
1047	Myrtleford - Workshop	DriCabRep\SEAT	SEAT BELT ALARM NOT GOING OFF	operation, all okay.	18/08/2026	858570	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		13/08/2026	855951	Completed	Mt Gambier	STK	XV67MC	HALLORAN DIESEL - 3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\WINDSCREEN	SUPPLY WINDSCREEN	paid for with credit card	12/08/2026	858704	Completed	Mt Gambier	STK	XV67MC	Myrtleford Workshop	P/MOVER
				will take time to change, clutch also possibly slipping								
				Connect eaton laptop and check for faults - clear GI code.								
				Road test and couldn't get to fault. Remove dash cluster								
				and replaced blown globes. No gearbox pressure light or ABS								
				present.								
			Gearbox pressure light coming on, having trouble selecting	KW47762 GLOBE-DASH PANEL,12V 1.2W BLACK BASE B8. 2 2.66								
1047	Myrtleford - Workshop	DrivLine\ELECT P&W	gears. Light will come on for gear selected and flash but	Misc:DFT DIAGNOSTIC TOOL FEE	22/07/2026	846216	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Tyres\ROTATION	Tyres\ROTATION 1-2		20/07/2026	846216	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
				Remove and replace air tank drain bung as required								
1047	Myrtleford - Workshop	Body\AIR LEAK	AIR TANK DRAIN BUNG	KW12104 VALVE-DRAIN	10/07/2026	840251	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				previously diagnosed but ran out of time								
				Remove seat base. Remove and replace seat shocker. Refit								
				seat base, all OK								
				KW98889-07 SOCK ABSORBER TO SUIT SEAT 1 380.30								
			drivers seat bottoms out (possible seat dampener)	KWCSC82052 BOLT 8 46.32								
1047	Myrtleford - Workshop	DriCabRep\SEAT	SEAT NEEDS NEW SHOCKER	KWP14362-104 CLAMP-CUSHIONED 5/8'ID	10/07/2026	840251	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\TAIL SHAFT	JACK SHAFT AROUND THE WRONG WAY - FIX	Remove jack shaft and fit correct way - bolt and tension.	10/07/2026	840251	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Body\WHL HUB	CHECK AND ADJUST WHEEL BEARINGS	Check over all wheel bearings, all OK	10/07/2026	840251	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				Remove pitman arm and inspect - found splines worn and								
				un-serviceable. Replace pitman arm as required. Refit all								
				components, road test and check, all OK								
1047	Myrtleford - Workshop	Steering\DAMAGE	CHECK STEERING - PITMAN ARM LOOSE	KWJ23-1008 ARM-PITMAN	10/07/2026	840251	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\SEAT	drivers seat belt fraying		10/07/2026	840251	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			VehService\BS B Service									
1047	Myrtleford - Workshop	VehService\BS	L134666		09/07/2026	840251	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				Plug into truck and check codes - pedal faults. Trace faults								
				in pedal and found wiring rubbed on clamps. Cut cable ties								
				holding wiring then repairs rubs. Re-tape loom and secure								
				with cables ties and kenworth style cable strap. Plug back								
				in and clear codes, all OK								
				KWW84-1000 STRAP-HARNESS TIE 1 11.56								
				NGSCRAPH0SE scrap hose 1 4.55								
1047	Myrtleford - Workshop	Engine\FAULT CODE	CUMMINS INSITE SERVICE TOOL CHECK ENGINE LIGHT ON	Misc:DFT DIAGNOSTIC TOOL FEE	26/06/2026	835757	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				Connect laptop and found low coolant code active. Check over								
				coolant and found low by 15L. Refill with coolant and check								
				over for leaks - unable to detect. Pressure test system for								
				20 minutes and did not drop. Remove coolant pump and drive								
				belt, unscrew return hose from radiator. Carried out liner								
				test, all OK. Clear fault and road test, no lights or faults								
				active. Possible air lock in cooling system, driver to								
			STOP ENGINE & CHECK ENGINE LIGHTS COME ON, HORTON FAN WONT	monitor								
			COME ON UNLESS MANUALLY TURNED ON BY DRIVER	KWELC40-5M PACGEN ELC40 PREMIX 5L EXTENDED LIFE COO 3 89.61								
1047	Myrtleford - Workshop	Engine\FAULT CODE	COOLANT HAS BEEN CHECKED THIS MORNING AND WAS OK	Misc:DFT DIAGNOSTIC TOOL FEE	12/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				Found gauges to be dropping in and out when truck running.								
				Carry out trouble shooting and diagnose faulty governor								
				valve. Fit new valve and check, all working as should.								
1047	Myrtleford - Workshop	Body\AIR LEAK	AIR GUAGES ON DASH DROP RIGHT DOWN (GOVERNOR/AIR COMPRESSOR)	KW275707 VALVE GOVERNOR D2	12/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				Inspect coolant leak and found coming from radiator hose on								
				thermostat housing. Drain coolant and remove hose. Fit new								
				hose and tighten. Refill coolant and check over for leaks,								
			STOP ENGINE & CHECK ENGINE LIGHTS COME ON	all okay								
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	RECTIFY COOLANT LEAK	KWV31-TP-1011 HOSE-SILICONE,2.5'ID RADIATOR 300 MM LEN	12/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				REPLACE STEERING COLUMN AS PER QUOTE								
				Remove column covers, steering wheel, and steering column.								
				Fit new steering column as required. refit all components								
				and check truck on road test, all okay								
			Advise new steering column	KW10CS0016 COLUMN-STEERING,REMAN TRP CORE DEPOSIT A 1 1587.36								
1047	Myrtleford - Workshop	Steering\DAMAGE	REPLACE STEERING COLUMN AS PER QUOTE	NGFREIGHT FREIGHT	12/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			RH WORK LIGHT ON MIRROR N/W									
			Remove mirror and check over fuses and wiring. Check power	Remove mirror and check over fuses and wiring. Check power								
			supply and found power supply ok. Diagnose faulty light,	supply and found power supply ok. Diagnose faulty light,								
			replace light and check operation, all okay	replace light and check operation, all okay								
1047	Myrtleford - Workshop	Elect\WORK LIGHT	KWKWL0ADL1GHTR	KWKWL0ADL1GHTR	12/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			R/H side locker door has trouble shutting	Fit new striker to RH tool box door. Had to secure with new								
1047	Myrtleford - Workshop	DriCabRep\DOOR LOCK	(STRICKER ON ORDER)	bolts to suit, all okay	12/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				RH WORK LIGHT ON MIRROR N/W								
				Remove mirror and check over fuses and wiring. Check power								
				supply and found power supply ok. Diagnose faulty light,								
			R/H work light (mounted above mirror) not working	replace light and check operation, all okay								
1047	Myrtleford - Workshop	Elect\WORK LIGHT	RH WORK LIGHT ON MIRROR N/W	KWKWL0ADL1GHTR KW LOAD LIGHT - RIGHT	12/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			Insp\ANN INSP Annual insepction as per check sheet									
1047	Myrtleford - Workshop	Insp\ANN INSP	L134216		11/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			VehService\AS A Service									
1047	Myrtleford - Workshop	VehService\AS	L134211		11/06/2026	829924	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				FIT NEW DRIVERS SIDE STEPS AS REQUIRED								
				Remove and fit new steps as required to RH side middle and								
				lower steps.								
1047	Myrtleford - Workshop	Chassis\DAMAGE	2 x drivers side steps cracked require repairs or replacing	KWR82-1007 STEP - CAB ACCESS	15/05/2026	821078	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				STEERING PITMAN ARM LOOSE								
1047	Myrtleford - Workshop	Steering\STEER UNI	excessive movement (free play) in steering	Check and tension pitman arm bolt to spec - re-check all ok	14/05/2026	821078	Completed	Mt Gambier	STK	XV67MC	Myrtleford Workshop	P/MOVER
				STEERING PITMAN ARM LOOSE								
1047	Myrtleford - Workshop	Steering\SUSPENSION	CHECK THE FRONT END FOR VIBRATION UP THE STEERING COLUMN.	Check and tension pitman arm bolt to spec - re-check all ok	14/05/2026	821078	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
				Inspect and found Rh front air CTI leaking at rotator.								
				Disconnect air lines, removed rotator and replaced with								
				new. Connect air lines, tested no further leaks.								
				Found black air cti filter was leaking. Removed, cleaned								
				out housing, replaced seals and applied sealant to threads.								
				Reinstalled filter and checked, all okay.								
1047	Myrtleford - Workshop	DrivLine\CTI Drive	black round cylinder on CTI leaking air back of cab.(Possible pressure protect valve)	Rotator from GF stock.	14/05/2026	821078	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER

1047	Myrtleford - Workshop	Steering\STEER UNI	steering column not locking in	Remove steering covers and inspect operation of steer lock - found not locking in. Possible faulty dampener, found when replacing dampener steering column had a pin hole in it and was cracked in the casting. Fit bolt into steering to lock it in place for now. (temp repair) recommend replacing column KWAQ69-D0TS-8X8 PTC ELBW 1/2 X 1/2 M 1 17.30 NG13CS0003 S/COLUMN STRUT	14/05/2026	821078	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	USB CHARGER N/W	Remove triangle, positive and negative wires, and test - 12 volts both sides. Plug in cord and check, found working as should. Advise driver needs new cord	14/05/2026	821078	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	VehService\B1 Svc	VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins. Replace cabin filter. L133749		12/05/2026	820425	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Air Con\AIR CON	CHECK A/C NO GAS? L133600	REFRIGERANT TRADING AUTHORISATION CERTIFICATE AU47563 Connect gauges and found low pressure. Went to recover gas but found system empty. Fill system with nitrogen and check over for leaks - RH top corner of condenser leaking. Remove and replace condenser and receiver dryer. Pressure test with nitrogen again - no leaks detected. VAC down system for 45 minutes and charge with new A/C gas. Run truck and check operation, all okay KW55304128 CONDENSOR 1 727.75 KWM200-70EP BUSHING-RADIATOR 2 72.10 KWGD11350 TRP RECEIVER DRYER 1 45.71 POL AIRCONDITIONING GAS R134A 1.4 123.20 <<< Total For Job 1 >>> 1618.76 Misc:E-2 ENVIRONMENTAL LEVY 26.00 Misc:SHOPT SHOP SUPPLIES 26.00 Misc:RND ROUNDING	29/04/2026	815508	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Elect\INDICATORS	INDICATOR WARNING BUZZER	Diagnosed faulty indicator audible buzzer. Tested wiring and parts. Locate and ordered new parts. Truck to return for fitting. KWP27-1149 BUZZER-AUDIBLE FLOYD BELL 1 198.75 KWM5010-0110 PLUG-DIODE PACK 10 P1N	24/04/2026	812769	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\GEARBOX	HECK TRANS FILTER, NOT SITTING IN CORRECTLY AND SEVERELY DIRTY	Found trans filter was not sitting correctly and was contaminated. Removed filter and replaced with new filter from spare stock.	24/04/2026	812769	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\HOUSEKEEP	ROOF LEAKING THROUGH OVERHEAD CONSOLE	Inspect for water leak, found water marks from sunvisor bolts. Unbolted visor and filled holes with silicone. Refit sunvisor and let silicone seal properly. Checked for leaks with pressure washer, all okay. KWK036-206 BEARING DOOR LATCH 1 14.91 KWL0C59530 LOCTITE 595 SUPERFLEX CLEAR RTV SILICONE	24/04/2026	812769	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	VehService\AS	VehService\AS A Service L133293		13/04/2026	810178	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Engine\ENG TUNE	TUNE ENGINE REPLACE ROCKER COVER GASKET FIT NEW BELT TENSIONER		23/03/2026	800224	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1047	Myrtleford - Workshop	Engine\RERATE	SPEED REDUTION SETTINGS		23/03/2026	800224	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1047	Myrtleford - Workshop	Prevent\WHEEL ALGN	Prevent\WHEEL ALGN REPLACE AUTO CLUTCH KIT FIT G/BOX INSTALL KIT		17/03/2026	800224	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\CTCH PACK	REPLACE REAR MAIN SEAL MACHINE FLYWHEEL	NEW CLUTCH & INSTALL KIT FITTED 800858 KMS Remove and replace seal on 2nd fuel cap filter as required. Check for leaks, all OK	07/03/2026	800224	Completed	Mt Gambier	STK	XV67MC	QT DIESEL SERVICES - 3	P/MOVER
1047	Myrtleford - Workshop	Engine\OIL LEAK	2nd fuel filter cap wont seal correctly replace ring	NG39467065 COLLAR FH230/FH234	27/02/2026	799727	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	left hand side diff lock switch. its come away from the dash engine brake & cruise control lights not working	- ENGINE BRAKE - CRUISE CONTROL - GAUGE LIGHTS Remove dash panel and check all lights. Replace blown globes for all dash lights, check lights operation, all OK KW800005002 HOLDER-GLOBE INCLUDE GLOBE 4 29.76	27/02/2026	799727	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REPAIR DASH LIGHTS check all ball joints & suspension & steering & king pins AL STEERING COMPONENTS WERE CHECKED AT C SERVICE 25/2/26	KW47762 GLOBE-DASH PANEL,12V 1.2W BLACK BASE B8.	27/02/2026	799727	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Susp\SUSPENSION	AT 799727 KMS Engine water temp & fuel guage and axle oil lights not working	- ENGINE BRAKE - CRUISE CONTROL - GAUGE LIGHTS Remove dash panel and check all lights. Replace blown globes for all dash lights, check lights operation, all OK KW800005002 HOLDER-GLOBE INCLUDE GLOBE 4 29.76	27/02/2026	799727	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	REPAIR DASH LIGHTS	KW47762 GLOBE-DASH PANEL,12V 1.2W BLACK BASE B8.	27/02/2026	799727	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Steering\STEER UNI	pack grease into steering column VehService\CS C Service	GREASE STEERING COLUMN & STEERING SHAFT UNI'S Check steering column and steering unis. Grease steering column as required, all okay. Carried out C service as per Greenfreight checklist. Replaced diff, trans, power steering oils. Drained steer hubs and checked bearings, all okay.	27/02/2026	799727	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	VehService\CS	L099177	Replaced gaskets and filled with new oil.	26/02/2026	799727	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\MOUNTS	DriCabRep\MOUNTS	G2-SP-FFC-1001231 Guardian Gen 2 - Forward Facing Camera Kit Forward Facing Camera Mounting Foot Alcohol Wipes Guardian Seeing Machine Service Call to 1047. Remove and replace Front Facing Camera. Controller unsecured in overhead console so hard mounted to side pillar. Checked software, running 1.6.1. Reimaged to 1.7.2 latest software. Run through installation wizard. Confirmed test events and working ok with Tech Support. Guardian Seeing Machine Service Call to 1052. Remove and replace Front Facing Camera. Reimaged to 1.7.2. Run through installation wizard. Confirmed test events and working ok with Tech Support. ($20 discount for failing to clean our boot mark from centre floor- our apologies) Guardian Seeing Machine Service Call to 1046. Reimage to latest software 1.7.2. Run through installation wizard.	24/02/2026	800224	Completed	Mt Gambier	STK	XV67MC	TELEMATICS - 3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\MOUNTS	DriCabRep\MOUNTS FIT NEW GUARDIAN KIT	Confirmed test events and working ok with Tech Suppor	10/02/2026	800224	Completed	Mt Gambier	STK	XV67MC	TELEMATICS - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\CLUTCH	AUTOSHIFT PROGRAM CHECK CODES DISPLAYING 'F' ON DASH	Connect eaton laptop and check codes, found 2 inactive codes for clutch slip. Reset clutch using laptop and take SAR report.	09/02/2026	794837	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER

1047	Myrtleford - Workshop	Body\TOOLBOX	driver side locker seal needs realigning	CHECK BODY/TRIM - RH BUNK DOOR SEAL N/W Remove old locker box seal and fit new seal. KWT42-1001-1770 SEAL -TOOLBOX/SLEEPER DOOR	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INDICATORS	indicator audible warning not working.(beeping)	INDICATOR WARNING BUZZER N/W Indicator buzzer n/w, checked fuse relays and power to buzzer. All okay, chase parts nil stock will order and replace next service.	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	USB charger on dash broken. needs replacing	Remove dash and wiring. Push out old USB and plugged in new one as required. Refit dash, all okay. KW2086874-2 USB CHARGE PORT - DUAL, NO BAC	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\WIPERS	CHECK WIPER WASHER JETS BLOCKED	Wiper washer jets blocked, attempt to clean out but no luck. Remove and replace jets. KW120510739C0	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Elect\INDICATORS	LH INDICATOR R&R	Found LH indicator light not working. Remove light and check all plugs correct. Remove and replace light as required, all okay. KWP54-1093	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Chassis\SUZI COIL	MAKE & ATTACH SUZIE COIL TO OPERATE TRAILER LOADING LIGHTS.	MAKE AND CONNECT SUZI COILS TO OPERATE TRAILER LOAD LIGHTS Check all lights and work lights, use cab functions to operate lights, all functions working as should, no need for changes.	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Truck ABS light stays on REPLACE ABS TRUCK CAB MODULE	ARKON SUPPLIED NEW ABS MODULE L098753 Attempt to connect Bendix but unsuccessful. Restart multiple times but still no connection. Check cummins side, found small fault. Inspect fault, found was for abnormal update rate. Check over all relevant fuses, and used Bendix information books to identify plugs and wiring then get wiring diagram to find powers and ground. Remove kick panel and test, all power and ground okay. Inspect further and found engine worn and G - 130X fault.Check both systems and found related to same issue. Quote parts and order. Once parts arrived remove kick panel to access ABS ECU. Remove and replace ECU. Road test truck and found ABS light came on. Check codes found open circuit LH drive wheel speed sensor. Inspect and test wheel speed sensor, tested fine. Jack up and check wheel speed sensor on computer, all okay. Reconnect wheel speed sensor and road test, all okay	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\INST/GAUGE	microphone on dash mounting clip broken	FIT MAGNETIC UHF MIC MOUNT Remove mount and UHF clip. Fit new mount as required, all okay. KWMB207 MICROPHONE MOUNT MAGNETIC	31/01/2026	790313	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Engine\WATER PUMP	Engine\WATER PUMP VehService\BS B Service	Inspect and found water pump leaking. Drain coolant, remove and replace water pump as required. Refill coolant and road test, check over, all okay. Confirmed with WD. CU5719759 CORE, WATER PUMP 1 1661.57 CU3684384	29/01/2026	789507	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	VehService\BS	L098554		19/01/2026	789507	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Tyres\Punct	Tyres\Punct POS 6	DONE IN COLAC	15/01/2026	789191	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	Engine\BATTERY	Truck flat at yard, load test and replace batteries if needed	Truck was flat, jump started and run. Return to BMG and put on charge. Tested batteries and found all 4 batteries had failed. Removed batteries and replaced with new. KWTRP-700HD SEALED MAIN FREE BATTERY CCA 700, RC 160	07/01/2026	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Engine\BREAKDOWN	TRUCK DERATED AT GREENWALD TED	Greenwald. Plug into truck and inspect codes, had high pressure ad blue fault. Unable to run proper diagnosis as computer was not connecting properly. Found computer would not connect due the ECM being locked. Attempt numerous times to get code for ECM. Eventually got it unlocked Attempt to flush and flushed several times. Carry out override test and all passed. Clear codes and sent driver on his way. All okay.CHECK ENGINE PORTLAND TO ASSIST Sublet1S112285 ASSIST WITH BREAKDOWN Internal Misc:E-2 ENVIRONMENTAL LEVY 35.75 Misc:SHOPT SHOP SUPPLIES 35.75 Misc:RND ROUNDING	19/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Engine\ELECT P&W	Engine\ELECT P&W DIODES PACK 10 PIN	COMPLETED BY COLAC WORKSHOP. REMOVED FROM TRUCK 999	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	Myrtleford Workshop	P/MOVER
1047	Myrtleford - Workshop	Engine\ADBLUE	ADBLUE INJECTOR LINE - LEAKING	On service found adblue injector line leaking. Remove P Clamp and cut out worn section of adblue line. Fit joiner, tape up and re-secure with p-clamp, all okay. NGCVCI7 3MM STRAIGHT JOINER	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Engine\ENG FAN	HORTON FAN FRICTION PLATE WORN	Found Horton fan friction plate very worn. Remove fan, belt and Horton assembly then re-kit Horton fan. Refit Horton fan assembly and tensioned all bolts. Refit fan and replace Horton belt as was worn. KWF350808 HT/S OUTBACK UPGRADE KIT KW12PK2380 V BELT-MICRO	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Body\MOUNTS	FIRE EXTINGUISHER BRACKET SNAPPED AND EXTINGUISHER MISSING	Fire extinguisher missing and bracket snapped off, go to SE Fire Extinguishers and get new 9kg one as required. Source new bracket, went to mount but found would not align to mount on truck. Make up 2 new brackets for extinguisher bracket so would mount to truck. Measure and make bracket sit straight, clamp and weld supporting brackets onto main bracket. Remove bracket, prime and paint as required, refit and fit extinguisher, all okay NGWVBH70076 9KG BRACKET 1 78.00 SubletSll2I67 FIRE EXTINGUISHER	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Steering\SUSPENSION	TIGHTEN LHF STEER SHOCKER STUD	Remove shocker, double nut shocker stud, tighten and refit shocker. Found drive shockers about to pull through top mount. Undo bottom shocker nuts, remove and replace bottom shocker bushes and nuts as and tighten as required. KW7150-08-4840 KIT-TOP BUSH, SUITS C71-1006 KW7150-08-4840 KIT-TOP BUSH, SUITS C71-1006	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\SHOCK ABS	FRONT DRIVE SHOCKER BUSHES - WORN	KW7050-06-6860 SHOCK ABS BOTTOM BUSH KIT SUITS C71-1006	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Body\MOUNTS	REPLACE STUD ON BOTTOM BATTERY	Found batteries unsecure during service. Stud that holds bottom tray in broken. Remove bottom bolt assembly, replace worn bolt with 3/8 UNC bolt. Weld in new bolt and refit bolt assembly, tighten tray, all okay.	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER

				Found front engine mounts very worn and engine fan fouling on shroud. Jack engine and remove engine mount bolts. Remove and replace engine mounts as required, tighten all bolts then lower engine, all okay KWDI3-1012 BUSHING-FRONT ENGINE							
1047	Myrtleford - Workshop	Engine\MOUNTS	R&R FRONT ENGINE MOUNTS UNSERVICEABLE	KWKO66-404 BUSHING-FRONT ENGINE	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	Elect\BREAKDOWN	JUMP START VEHICLE	Travel out to GF yard. Jack up cab, remove battery box and connect jumper pack. Jump start truck and check starting all okay. Return to workshop	18/12/2025	785049	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\BREAKDOWN	AUTOSHIFT PROGRAM	Sent second tech, inspect all faults but no faults, re set clutch data and adjust clutch/ Start and check operation. Selected gears and would now drive. Got back to workshop and re check over all gearbox components. All okay.	12/12/2025	783649	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			ULTRA SHIFT FAULTS TRUCK WONT SELECT GEARS AT K & S AMPOL SERVO NGCALLOUT PARTS A/HRS CALLOUT AFTER H'RS BREAKDOWN	Received call for truck not starting and would not select gear, travel to location and plug in to check codes found fault code 61 relating to X Y shifter. Follow trouble shooting test all wiring and components, all tested okay and wiring in spec. Carry out rest of the trouble shooting and diagnosed as faulty XY shifter. Remove and replace XY shifter. Start truck and select gears all operating. Packed up and return to work. Received second call and truck still not moving. Had to wait until tech got back to work. Sent second tech, inspect all faults but no faults, re set clutch data and adjust clutch/ Start and check operation. Selected gears and would now drive. Got back to workshop							
1047	Myrtleford - Workshop	DrivLine\BREAKDOWN	CALL OUT FEE VehService\AS A Service	and re check over all gearbox components. All okay.	12/12/2025	783649	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	VehService\AS	L098175		12/12/2025	783221	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			Engine\RERATE	Apply New Cummins Engine Program. Change Diff Ratio From 3.91 To 4.30, Change Tyre Size To 11R 22.5, 315 Rev Per Klm.								
1047	Myrtleford - Workshop	Engine\RERATE	DONE AT CUMMINS WOD 9/9/25	(Cummins Wodonga P/O: WW096806)	08/12/2025	777509	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L - 3	P/MOVER
1047	Myrtleford - Workshop	DriCabRep\WIPERS	REPLACE WIPER BLADES	Remove and replace wipers as required, all okay. Drop truck back to yard KW1362060DC04 BLADE ASSY-WIPER	26/11/2025	774880	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\DRV LN SER	All driveline components and suspension and kingpins need to be checked as there is b	CHECK VIBRATION THROUGH STEERING COLUMN INSPECT KING PINS, DRIVELINE AND STEERING COLUMN Check over wheel bearings, shackle pins and king pins for movement, no movement. Check over shockers and torque rod bushes, all were okay. Check over drive line and all ball joints in steering components, all okay. Check pitman arm pinch bolt, found loose, remove and replace bolt as required, fit with loctite and tension to spec. Check and found movement in steering uni, mark slip joint and steering shaft positions at steering box. Remove steering shaft from box and pull out slip shaft. Remove and replace steering uni. refit slip shaft then line up and fit back to steering box. Tension pinch bolt, grease unis and slip shaft. Lower cab and test drive to ensure steering wheel straight and vibration gone away, all okay.	21/11/2025	774880	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\GEARBOX	gearbox error when putting it in neutral	ALTER TRANS PROGRAM - MAKE SAME AS 1046 Adjust auto shift parameters to suit that same as unit 1046 - requested by GF	21/11/2025	774880	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.									
1047	Myrtleford - Workshop	VehService\B1 Svc	Replace cabin filter.		11/11/2025	772352	Completed	Mt Gambier	STK	XV67MC	JF MECHANICALS - 3	P/MOVER
1047	Myrtleford - Workshop	Tyres\TP05	Tyres\TP05	NO FITTING CHARGED	29/10/2025	774880	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	BodyLab	DIAGNOSE & REPAIR AIR LEAK IN OR AROUND THE SEAT.		28/10/2025	760618	Completed	Mt Gambier	STK	XV67MC	JF MECHANICALS - 3	P/MOVER
1047	Myrtleford - Workshop	ChassisLab	FIT WALK PLATE TO REAR OF PRIME MOVER		28/10/2025	760618	Completed	Mt Gambier	STK	XV67MC	JF MECHANICALS - 3	P/MOVER
1047	Myrtleford - Workshop	VehService\AS	VehService\AS A Service		28/10/2025	760618	Completed	Mt Gambier	STK	XV67MC	JF MECHANICALS - 3	P/MOVER
1047	Myrtleford - Workshop	ElecLab\ELECT P&W	DIAGNOSE & REPAIR MT DATA GPS FAULT		17/09/2025	760618	Completed	Mt Gambier	STK	XV67MC	JF MECHANICALS - 3	P/MOVER
1047	Myrtleford - Workshop	DrCabElect\SEAT	DIAGNOSE & REPAIR LOW AIR/ SEAT BELT ALARM		17/09/2025	785049	Completed	Mt Gambier	STK	XV67MC	QT DIESEL SERVICES - 3	P/MOVER
1047	Myrtleford - Workshop	ElecLab\ELECT P&W	DIAGNOSE & REPAIR HEATER / AC FAN FAULT		16/09/2025	760618	Completed	Mt Gambier	STK	XV67MC	JF MECHANICALS - 3	P/MOVER
1047	Myrtleford - Workshop	DrivLine\CTI Drive	FIT CTI TO DRIVES CUMMINS ADELAIDE-	SUPPLY AIR FITTINGS	13/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	JF MECHANICALS - 3	P/MOVER
1047	Wodonga - Workshop	Engine\BREAKDOWN	STOP ENGINE LIGHT ON- BURTON, ADELAIDE.		10/09/2025	703088	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1047	Wodonga - Workshop	Brakes\ABS	ESC LIGHT COMING ON INTERMITTENTLY.		09/09/2025	750216	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\FAULT CODE	truck abs light keeps coming on intermittently		09/09/2025	750216	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL	Diff Oil's Replaced When Diff Heads Were Changed	09/09/2025	750216	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\AIR LEAK	Massive Air Leak In Seat	Repaired Air Leak In Seat Main Air Supply Line.	09/09/2025	750216	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
			Apply New Cummins Engine Program. Change Diff Ratio From 3.91 To 4.30, Change Tyre Size To 11R 22.5, 315 Rev Per Klm.									
1047	Wodonga - Workshop	Engine\RERATE	(Cummins Wodonga P/O: WW096806)		09/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1047	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 6		08/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	Tyres\TP05	Tyres\TP05		08/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	Tyres\TP11+12	Tyres\TP11+12		08/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	Tyres\TP7+8	Tyres\TP7+8		08/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10		08/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Myrtleford - Workshop	Tyres\TP1+2	Tyres\TP1+2		08/09/2025	754451	Completed	Mt Gambier	STK	XV67MC	BORDER BANDAG PTY LTD -3	P/MOVER
1047	Wodonga - Workshop	DrivLine\DIFF REPMN	Replace Diff Heads (Rebuilt From 1003)	REBUILT THROUGH-SHAFT. REPLACED DRIVE SHAFT UNIVERSAL JOINTS. FITTED WIRING, AIR PLUMBING AND SWITCHES FOR DIFF L	28/08/2025	754451	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\DIFF REPMN	Rebuild diffs from 1003 for 1047		15/08/2025	730994	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	indicator stalk missing screw		30/07/2025	744675	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	STEERING WHEEL WON'T LOCK IN PLACE (UNSAFE)	#461126	30/07/2025	744675	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Steering\HOUSEKEEP	repair steering column		30/07/2025	744675	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\SUSPENSION	AIRBAG DUMP VALVE IS NOT WORKING.		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\INST/GAUGE	OIL PRESSURE LIGHT AND BRAKE AIR LOW LIGHTS COME ON AT RANDOM.		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE BOTTOM SHOCK BUSHES		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\Torque Rod	REPLACE FRONT TORQUE ROD BUSHES	Previously completed	25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\TAIL SHAFT	REPLACE DRIVESHAFT UNIVERSAL JOINTS		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	Water leak inside truck through speaker passenger side above windscreen.		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	Coolabah Unit Leaking Water Onto Shelf/Down Back Wall		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	VehService\BS B Service		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	CHANGE MANUAL LOCK OUT FOR GEARBOX.		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\INDICATORS	RHS INDICATOR NOT WORK		25/07/2025	743898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\TRL LIGHTS	REPLACED LIGHT DUTY PLUG.		27/06/2025	733401	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Steering\HOUSEKEEP	Steering\HOUSEKEEP STEERING COLUMN WONT LOCK Alternator Not Charging.		25/06/2025	731801	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ALT	(Parts Supplied By TCTC P/O: WW095054)		19/06/2025	729349	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\Torque Rod	Torque rod bushes need replacing on front diff	BELLA (ON WORK EXPERIENCE) ASSISTED	12/06/2025	726942	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\FIFTH WHEE	excessive play / lash in turntable. Trailers slam back / forward when accelerating and b	IN SPEC	11/06/2025	726941	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\WHEEL ALGN	EXCESSIVE DRIVELINE LASH/ TURNTABLE.	IN SPEC	11/06/2025	726941	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\AIR CON	REPLACE POLAND FILTER.		11/06/2025	726941	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	passenger door lower window has something fallen inside partially obscuring blind spo	REMOVED SILVER TAPE.	11/06/2025	726941	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER

1047	Wodonga - Workshop	VehService\AS	VehService\AS A Service		11/06/2025	726941	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\SUSPENSION	CHECK FRONT END.		11/06/2025	726941	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Air Con\HEATER	heater doesnt work		16/05/2025	714052	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	VehService\AS A Service		09/05/2025	712628	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				REPLACED THROUGH-SHAFT SEAL.								
1047	Wodonga - Workshop	DrivLine\OIL LEAK	LEAKS AT DIFF INPUTS.	S.McCABE.	09/05/2025	712628	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ELECT P&W	Fit Inverter & Microware Steven (Driver) Will Supply	PREVIOUSLY COMPLETED.	09/05/2025	712628	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
			PULL BADLY TO THE LEFT.									
1047	Wodonga - Workshop	Susp\WHEEL ALGN	THIS WAS REPORTED APPROX 5 MONTHS AGO.	BOOKED INTO HTT FOR 31/1	03/05/2025	708480	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\WHEEL ALGN	Truck pulls to the left - wheel alignment?. (Hume Truck Technics P/O: WW091707)		03/05/2025	708480	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Cooling\RADIATOR	TOP UP ENGINE COOLANT 2LTS		29/04/2025	707443	Completed	Mt Gambier	STK	XV67MC	QT DIESEL SERVICES	P/MOVER
			ADJUST T/TABLE JAWS (FULLY ADJUSTED NEED JAW KIT)									
1047	Wodonga - Workshop	Chassis\FIFTH WHEE	698342KMS		29/04/2025	707443	Completed	Mt Gambier	STK	XV67MC	QT DIESEL SERVICES	P/MOVER
1047	Wodonga - Workshop	VServLab	truck due for service		27/03/2025	689293	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	VehService\AS A Service	K.RYAN ½ HOUR LABOUR.	27/03/2025	689293	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				Connect laptop & download ECM image found to have 71 counts								
				of 1911 Injector Metering Rail 1 Pressure Data Valid But								
				Above Normal Operating Range - Most Severe Level.								
				Followed trouble shooting steeps as per QSOL.								
				Inspect for air being ingested into the fuel system.								
				Fitted clear fuel lines and started engine and no air found.								
				Removed clear fuel lines.								
				Measure the fuel pump actuator resistance.								
				The maximum resistance is 5 ohms and tested within spec.								
				Install pressure gauge at the compuchek fitting at the inlet								
				to the fuel filter head.								
				Disconnect the lift pump electrical connector, if equipped.								
				Crank the engine for 10 seconds and observe the fuel gear pu								
				mp pressure to get a minimum of 20psi and was within spec.								
				Remove fuel pump head and actuator and inspect for damage an								
				d found fuel pump Adapter bleed orifice to be blocked								
				replaced.								
				Refit fuel pump head and actuator with new gaskets as per								
				QSOL.								
				Test drive vehicle and monitor with Insite, check over all								
				okay.								
			Truck Derate/Loses Power On Long Steep Descent, Fixed By Turning Truck Off And	Wipe off grease marks on vehicle.								
			Back On.	Steam clean engine.								
1047	Wodonga - Workshop	Engine\FAULT CODE	(Cummins Wodonga P/O: WW093718)	Return vehicle to service.	25/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1047	Wodonga - Workshop	Brakes\BRK RELINE	Brakes\BRK RELINE		20/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\MOUNTS	DriCabRep\MOUNTS / BRACKETS FOR GUARDIAN TIGHTENED UP	Needs new swivel braket taped up to hold for now	20/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\ABS	TRUCK ABS LIGHT ON DASH.		20/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Air Con\AIR CON	coolabah unit leaking water on shelf / down back wall	Drain hose been knocked off back of unit	20/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	VehService\AS		20/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\DRV LIGHT	Can Spot Lights Be Fitted	He won't fit	20/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ENG TUNE	truck derate / loses power on long steep descent. Fixed by turning truck off and back o		20/02/2025	688316	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				Torque rod bushes need doing								
				Through shaft leaking								
				Front input shaft both diffs								
1047	Wodonga - Workshop	VehService\CS	C Service	Heater tap needs doing	31/01/2025	678715	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	TRANSMISSION SHIFT VERY ROUGH ON OCCASION.		31/01/2025	678715	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		31/01/2025	678715	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ELECT P&W	Cig Socket On Dash Keeps Blowing Fuse	Couldn't find fault and didn't pop	30/01/2025	678705	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\FIFTH WHEE	Excessive driveline / turntable lash/play		30/01/2025	678705	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\INDICATORS	Right indicator flashes fast		30/01/2025	678705	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\HOUSEKEEP	Roof Water Leak Passenger Side From Speaker Above Windscreen		30/01/2025	678705	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\INDICATORS	Right Indicator Flashes Fast		30/01/2025	678705	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
			Engine\FAULT CODE (Cummins Adelaide P/O: WW088940)									
1047	Wodonga - Workshop	Engine\FAULT CODE			31/12/2024	672811	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				REPORTS CAB SHOCKS REQUIRE REPLACING								
				.								
				* Inspected cab shocks & confirmed to be leaking								
				* Supported cab								
				* Secured, unbolted & removed shocks								
				* Installed replacement shocks								
				* Secured in place								
				* Aligned, adjusted & tensioned all components to specifications								
				* Test operations - All ok, fault no longer present								
				* Dropped truck back to GF yard								
1047	Wodonga - Workshop	Body\SUSPENSION	Check Cabin Shocks, Replace If Required. (TCTC P/O: WW091103)		25/12/2024	672811	Completed	Mt Gambier	STK	XV67MC	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
				Tilted the cab over to check the a/c system, found the compressor								
				belt was missing. Checked the a/c clutch and found it was loose,								
				need to replace the compressor, dryer and condenser. Connect the								
				recovery unit to the vehicle and de-gas the vehicle. Removed the								
				compressor. Removed the front grill to get to the condenser.								
				Removed the dryer. Flush the a/c hoses and system , fit the new compressor.								
				Needed to remove the driving lights to fit the new condenser as it is								
				bigger than the old one. Mount the new condenser. Replaced all the								
				o'rings and fit the hoses to the compressor and condenser. Mount the								
				new dryer and connect the hoses. Pressure test for leaks. Vac the								
				system down and re-gassed the system with the recommended gas								
				charge (1. 4kg). Test the a/c. The a/c was working correctly. Put the								
1047	Wodonga - Workshop	Air Con\AIR CON	Air Conditioning Not Working. (Arkon Auto Electrical P/O: WW091077). (Parts Supplier	cab back down.	19/12/2024	672811	Completed	Mt Gambier	STK	XV67MC	ARKON AUTO ELECTRICAL	P/MOVER

				FUEL COLLAR & FUEL FILTER R&R COMPLAINT: Towed in, due to shut down and low power Cause: Fuel collar ill-fitting resulting in FC1911, shutting down (air being sucked into fuel system) Correction: Guidanz SO Number: 01151142 Hrs/Klms: 9,405h / 666,051kms Fuel Burn: 377,064L - Connected to Insite and retrieved ECM image - Found 10 counts of FC1911 - Attempted to start, confirmed engine is hard starting - Checked for air in fuel, confirmed air in fuel between fuel pro and engine - Checked fuel pro collar, confirmed to be bent / warped. Also note: collar was loose - Carried out Fuel Filter R&R and replaced fuel collar as required - Started engine, confirmed no more hard starting, took for roadtest, no faults logged - Bring back to workshop and confirm nil boost / power concerns **Note: engine also had 1 count inactive of 2311, 2182, 2367, 322,331, 324,332,323, 325. FC							
1047	Wodonga - Workshop	Engine\BREAKDOWN	Loss Of Power. (Cummins Wetherill Park P/O: WW091236)	memory cleared	16/12/2024	671164	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1047	Wodonga - Workshop	Engine\BREAKDOWN	Squealing Noise From Engine. (Gilbert & Roach Huntingwood P/O: WW091031)		13/12/2024	672811	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	DriCabRep\AIR CON	Coolabah A/C Not Working		12/12/2024	670475	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Air Con\AIR CON	Coolabah A/C not working. (Hume Truck Technics P/O: WW090384)		26/11/2024	672811	Completed	Mt Gambier	STK	XV67MC	HUME TRUCK TECHNICS	P/MOVER
1047	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 3-10 Low Power. (Gilbert & Roach Huntingwood P/O: WW090684)		19/11/2024	667477	Completed	Mt Gambier	STK	XV67MC	BEAUREPAIRES	P/MOVER
1047	Wodonga - Workshop	Engine\BREAKDOWN	B Service. (CMV Truck Centre Adelaide P/O: WW088955)		15/11/2024	672811	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	VehService\BS			05/10/2024	638383	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4+5+6+7+8+9+10		27/09/2024	646135	Completed	Mt Gambier	STK	XV67MC	BEAUREPAIRES	P/MOVER
1047	Wodonga - Workshop	Engine\FAULT CODE	Stop Engine Light Keeps Coming On Dash. (Barry Maney P/O: WW089220)	STOP ENGINE LIGHT INTERMITTENTLY COMING ON check codes and diagnose, if not a quick fix, let customer know to get fixed later Connected computer to truck and checked for codes. Found active codes for transmission. Inspected wiring at gearbox, unable to fault. Found codes for accelerator sensors. Replaced TPS sensor at accelerator pedal. Evened the sensors up slightly. New wiring is required from bulkhead to ECU due to a short somewhere in the line.	26/09/2024	646627	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Wodonga - Workshop	Chassis\AIR LEAK	Repair Air Leak/s. (Graham Thomson Motors P/O: WW088796)		18/09/2024	672811	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	VehService\AS	VehService\AS DrCabElect\ELECT P&W		26/07/2024	613884	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	DrCabElect\ELECT P&W	FIT INVERTER TO BUNK AND MICROWAVE. FIT SPOTLIGHTS AN SWITCH DriCabRep\HOUSEKEEP		26/07/2024	613884	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	INVESTIGATE ROOF LEAK		26/07/2024	613884	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	Body\WINDSCREEN	Body\WINDSCREEN SERVICE/TRANS PRESSURE LIGHT ON DASH Inspected and found ECA faulty. Removed and replace ECA, updated ECU and configured.		26/07/2024	613884	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	DrCabElect\INST/GAUGE	Driver test drove around block – All OK. After Treat Light On Dash Engine Derated (Barry Maney P/O: WW087196)		24/07/2024	612338	Completed	Mt Gambier	STK	XV67MC	PACCAR PARTS FLEET SERVICES	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE			04/07/2024	610285	Completed	Mt Gambier	STK	XV67MC	BARRY MANEY - 3	P/MOVER
1047	Wodonga - Workshop	Engine\BREAKDOWN	Engine Derated After Treat Issues (Cummins Adelaide P/O: WW0870 After Treat Light On (Cummins Laverton P/O: WW087023)		02/07/2024	607616	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE			27/06/2024	606065	Completed	Mt Gambier	STK	XV67MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1047	Wodonga - Workshop	VehService\BS	B Service	Doug cherysh Cody 586823 km is the entry on the speedo in the truck the computer system is wrong and will not allow the job to be signed off or completed. Job is complete all boxes ticked off all work done. To complete job the incorrect speedo reading has been retained and re entered	25/05/2024	594403	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\DIFF OIL	DrivLine\DIFF OIL	Km in this truck 586823 computer system is incorrect job can't be signed off or completed with the actual km entered	25/05/2024	594403	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\GPS	4G update		24/05/2024	588064	Completed	Mt Gambier	STK	XV67MC	ARKON AUTO ELECTRICAL	P/MOVER
1047	Wodonga - Workshop	Prevent\SEAT	Seat & Seat Belt		22/05/2024	335467	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Prevent\BELTS/TENS	Belts & Tensioners		22/05/2024	498144	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Prevent\TRANS OIL	Transmission Oil Change		22/05/2024	498144	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Prevent\STEER W/B	Steer wheel bearings		22/05/2024	498144	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\DIFF OIL	Diff Oil Change		22/05/2024	498144	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\DAMAGE	Body\DAMAGE FREEWAY (INBOUND) JUST PAST OSHEAS ROAD ONRAMP TO CHECK AND REPORT ON THE TRANSMISSION STUCK IN TENTH GEAR. DRIVER - 0407 023 333 TRAVELLED TO SITE. CONNECTED LAPTOP AND FOUND INACTIVE CODES FOR CI=URRENT FAULTS AT BOTH RANGE AND SPLITTER SOLENOID. CHECKED WIRING AND ALL OK. CLEARED CODES AND STARTED VEHICLE. NO FAULTS.		22/05/2024	593792	Completed	Mt Gambier	STK	XV67MC	ROYANS WODONGA PTY LTD	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	FOLLOWED VEHCILE AND THEN RETURNED HOME.		14/03/2024		Completed	Mt Gambier	STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2 * Sourced parts * Travelled to GF yard * Inspected vehicle & confirmed fault * No power to Cobra shifter or display * Jacked up cab * Removed battery box cover * Inspected batteries * Found transmission power supply line earth connection to battery not connected * Refit line as required * Cleared all fault codes * Test operations - All ok, fault no longer present		28/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ELECT P&W	* Cleaned up & travelled back to TCTC workshop		23/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		20/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\WHEEL SEAL	REPLACE LEAKING LF DRIVE HUB SEAL.		20/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\SUSPENSION	lot of rough feed back through steering doesn't like to sit on the road		20/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\WHEEL ALGN	truck pullls badley to the left		20/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\DOOR LOCK	drivers door weather sheild broken		20/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\DOOR LOCK	drivers door leaks badly at R/H top		20/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\FAULT CODE	DERATING WHEN DRIVING.		20/02/2024	1549000	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER

1047	Wodonga - Workshop	Brakes\YEL VALVE	TRAILER BRAKE TAKE 10 SECONDS TO APPLY.		20/02/2024	1549000	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\YEL VALVE	YELLOW HANDBRAKE TAKING LONG TIME TO APPLY.		20/02/2024	1549000	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\FAULT CODE	DERATING TO LOW BOOST.		20/02/2024	1549000	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine	TRUCK DERATING BOOST ONLY AT 160KPA.		20/02/2024	1549000	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	repair steering columnb lock		20/02/2024	1549000	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR DRIVES.		20/02/2024	1549000	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		20/02/2024	1549000	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	repair steering columnb lock		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\FAULT CODE	DERATING WHEN DRIVING.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\YEL VALVE	TRAILER BRAKE TAKE 10 SECONDS TO APPLY.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\ABS	ABS LIGHT ON.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT STILL ON FROM TIME TO TIME.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\YEL VALVE	YELLOW HANDBRAKE TAKING LONG TIME TO APPLY.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT ON.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\FAULT CODE	DERATING TO LOW BOOST.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT STILL ON.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR DRIVES.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine	TRUCK DERATING BOOST ONLY AT 160KPA.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT IS ON.		20/01/2024	1538464	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
			STEERING WON'T LOCK IN PLACE.								
			VERY DANGEROUS. STEERING WHEEL MOVES FORWARD WHILE TURNING CORNERS								
1047	Wodonga - Workshop	DriCabRep\ST Weel	AND ROUND A BOUTS.		13/01/2024		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	STEERING WHEEL FREE TILTING.		13/01/2024		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	STEERING WHEEL STILL FREE TILTING.		13/01/2024		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	STEERING WHEEL FREE TILTING.		13/01/2024		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	STEERING WHEEL NOT TILTING.		13/01/2024		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\FUEL TANK	Refit LH Fuel Tank	STRAIGHTENED 3RD LHS J-BRACKET. REPLACED SEVERAL TANK STRAP RUBBERS AND BREATHER.	06/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR DRIVES.		05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Unknown	SERVICE DUE.		05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\WIPERS	NEW WIPERS.		05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	STEERING WHEEL NOT TILTING.		05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\FUEL TANK	LOOSE FUEL TANK STRAP.	OK.	05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	ERROR F ON GEARBOX AND SERVICE LIGHT.		05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/12/2023	1519271	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\FUEL TANK	repair damaged fuel tank	TCTC supply	04/12/2023	608394	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection		10/11/2023	608394	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/11/2023	608394	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		10/11/2023	608394	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\AIR FITTIN	PRIME MOVER AIR LINES AND POWER.		17/10/2023	1498896	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ENG REBLD	pre emptive low liner		14/10/2023	498108	Completed	Mt Gambier STK	XV67MC	CUMMINS SOUTH PACIFIC P/L	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		04/10/2023	49192	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\AIR FITTIN	PRIME MOVER AIR LINES AND POWER.		04/10/2023	49192	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\HOUSEKEEP	Can the chequer plate behind the cab go back on please, got no where to stand hookin		04/10/2023	49192	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		04/10/2023	49192	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Insp\ANN INSP	To Complete R/W within 12 months		15/09/2023	608394	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist		15/09/2023	498144	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\AIR FITTIN	PRIME MOVER AIR LINES AND POWER.		15/09/2023	498144	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\HOUSEKEEP	Can the chequer plate behind the cab go back on please, got no where to stand hookin		15/09/2023	498144	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/09/2023	498144	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
			Dropped Liner Rework (Cummins Wodonga)								
1047	Wodonga - Workshop	Engine\ENG REBLD	Purchase Order Number: WW080986		12/09/2023	608394	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
			ATTEND CALL-OUT TO HUME FREEWAY SOUTH BOUND TO								
			VEHICLE WITH TRAILER BRAKES LOCKED ON. UPON								
			INSPECTION FIND SERVICE BRAKE LINE ON TRUCK TO BE								
			FEEDING AIR WITH MAXI BRAKES RELEASED. AFTER								
			ATTEMPTING TO DIAGNOSE THE ISSUE THE SYSTEM STOPPED								
			FAULTING. CONSULT GREENFREIGHT WORKSHOP - DECISION								
			WAS MADE TO LET THE TRUCK PROCEED.								
1047	Wodonga - Workshop	Brakes\BREAKDOWN	RETURN TO WORKSHOP.		06/09/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
			CHECK WARINING BUZZER GOING OFF								
			23/06 CALL OUT AFTER HOURS								
			TRAVEL GREENFREIGHTS YARD								
			CHECK FUSES- LOCATE X3 BLOWN AND RECTIFY- DISMANTLE DASH AND								
			DISCONNECT WARNOING CLUSTERBUZZERS								
			STILL GOING OFF.								
			DISCONNECT GAUGES- BUZZES STILL GOING OFCF CHECK SWITCHES AND RELAYS								
			DISCONNECT DIODE PACKS- STILL BUZZERS GOING OFF BUT NOW LOW AIR								
			PRESSURE								
			TRUCK HAD TO GO -INFORM SHAUN THAT TRUCK NEEDS TO COME INTO W/SHOP								
1047	Wodonga - Workshop	DrCabElect\INST/GAUGE	FOR FURTHER WORK		24/06/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\WINDSCREEN	replace Left Hand windscreen		08/06/2023		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		25/05/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		25/05/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6		25/05/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4		25/05/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2		25/05/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
			Check & Adjust Brakes (Elite Diesel Services)								
1047	Wodonga - Workshop	Brakes\BRAKE ADJ	Purchase Order Number: WW077546		29/03/2023	608272	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\SLACK ADJ	TCTC supply		28/03/2023	608272	Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
				CHECK BRAKE LIGHTS N/W							
				CHECK AND RESET CIRCUIT BREAKER							
				CHECK LIGHTS ALL OK							
				TRACE FAULT							
				CHECK TEAILER PLUG							
			BRAKE CIRCUIT BREAKER KEEPS FLICKING OFF. 2 TIMES THIS WEEK.	LOCATE SHORTING							
1047	Wodonga - Workshop	Elect\ELECT P&W	INDICATOR AS WELL.	REMOVE AND REPLACE	25/03/2023		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		22/03/2023	421495	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/03/2023	421495	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP09	runout		10/03/2023		Completed	Mt Gambier STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		08/03/2023	416343	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\EXHAUST	EXHAUST FLEX PIPE DRIVERS SIDE ISN'T CONNECTED PROPERLY- NEEDS INSERTING IN'		08/03/2023	416343	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\ABS	ABS LEAD WAS STUCK BETWEEN TANK & CHASSIS. DROPPED DOWN AND DRAGGED O		08/03/2023	416343	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/03/2023	416343	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
			Major oil leak engine compressor.								
1047	Wodonga - Workshop	Engine\OIL LEAK	To be repaired by TCTC under extended Warranty.		28/02/2023	608272	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\ABS	ABS PLUG- PULLED WIRES OUT, PLUG IS IN TOOLBOX BEHIND DRIVER SEAT.		28/02/2023	608272	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER

				CHASSIS & GENERAL CHECKS LIST . * Check engine oil * Check for engine oil leaks * Check V-belts, tensioner, fan and hub * Check cooling system levels * Check brakes & adjust * Drain air tanks * Check fluid level in clutch * Check differential for lubricant leaks * Check transmission for lubricant leaks * Check universal joints and centre bearing * Grease all components . *** Please note: Wheel nuts & tyre pressures owners' responsibility								
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	*** Any parts, replacement of lubricants or water additives, bulbs, or non A schedule repairs, are additional costs to the service	28/02/2023	608272	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT BEEN ON 3HRS TO GOULBURN & FROM YASS TO WODONGA 6HR		28/02/2023	608272	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		28/02/2023	608272	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP06	puncture repair		15/01/2023		Completed	Mt Gambier	STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist	EXTEND LEAD AND REPLACE LIGHT PLUG.	15/01/2023	396663	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Comp\Truck Safe	TRUCKSAFE STICKER OUT OF DATE.		15/01/2023	396663	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		15/01/2023	396663	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Comp\Truck Safe	TRUCKSAFE STICKER OUT OF DATE.		10/12/2022	379569	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		10/12/2022	379569	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/12/2022	379569	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				REVERSE N/W ON TRAILER TRAVEL TO GREENFREIGHTS WORKSHOP TEST AND LOCATE NO REVERSE POWER IN TRAILER PLUG. OPEN LOOM AND LOCATE WIRE NOT FITTED TO PLUG REMOVE AND REPLACE PLUG AND WIRE UP ALL 7 PINS								
1047	Wodonga - Workshop	Elect\TRL LIGHTS	NEW TRL PLUG.	TEST OPERATION OK	24/11/2022		Completed	Mt Gambier	STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		22/11/2022	1	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Replace Faulty Fridge		22/11/2022	1	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\HOUSEKEEP	Covered under Warranty.	DROPPED OFF AND PICKED UP TCTC.	12/11/2022	367459	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	ADDED 4L ENGINE OIL.	12/11/2022	367459	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		12/11/2022	367459	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				- Inspect and confirm fridge not working. - Remove fridge and send to Arkon for testing. - Fit new fridge and test operation, ok.								
1047	Wodonga - Workshop	DrCabElect\ELECT P&W	CUSTOMER REPORTS UNDER BUNK FRIDGE NOT WORKING. INSPECT AND REPORT	NEW FRIDGE COVERED UNDER ENGEL WARRANTY. NO CHARGE FOR FRIDGE*	12/11/2022	367459	Completed	Mt Gambier	STK	XV67MC	Albury Workshop	P/MOVER
1047	Wodonga - Workshop	Body			08/11/2022	364488	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\BATTERY	Replaced Batteries		07/11/2022	608221	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				Check over batteries and starter motor connections. Load test all 4 batteries. Check Earth Block. Tighten all nuts on starter.								
1047	Wodonga - Workshop	Elect\START MOTR	Check Starter.	Driver to Monitor.	05/11/2022	364314	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\INST/GAUGE	Speedo has stopped working while traveling to Adelaide	Paccar assist to organise repairer P/O WW074799	01/11/2022	608221	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ELECT P&W	Fridge not working	REPLACED.	25/10/2022	367459	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	REPLACED BLOWN DASH GLOBES AND FUSES. INSPECTED BUNK COOLER AND FRIDGE. ADJUSTED TURNTABLE.	25/10/2022	360040	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\ELECT P&W	FRIDGE NOT WORKING.	Refer Job Card # 169832	25/10/2022	360040	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Air Con\AIR CON	BUNK COOLER NOT WORKING.	Sent to HTT for repairs.	25/10/2022	360040	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/10/2022	360040	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP1+2	SUPPLU AND FIT 2TYRES Elite Diesel Replaced Water Pump and Belts		19/10/2022		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\BREAKDOWN	Attempting to get Warranty Claim out of Cummins. AAA Towing contacted to collect and take to Elite Diesel Workshop.		10/10/2022	608221	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\BREAKDOWN	AAA Towing PO# WW074531 Failed Water Pump Elite Diesel Contacted to attend.		10/10/2022	608221	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\BREAKDOWN	Elite PO# WW074532		10/10/2022	608221	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	REPOSITIONED ADBLUE TANK. DOWNLOADED ECM.	08/10/2022	352592	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/10/2022	352592	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\ST Weel	STEERING ADJUST BROKEN.	REPAIRED CABLE.	23/09/2022	343827	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\TRL LIGHTS	REPLACE TRAILER LIGHTS PLUG. Coolant smell in cab after 5 minutes driving.		23/09/2022	343827	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Cooling\RADIATOR	Radiator debug. Drivers seat reported in incident report to be cause of injury.		09/09/2022	336876	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\SEAT	Inspect and rectify as required.		08/09/2022	335467	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Prevent\STEER W/B	replace steer wheel bearings		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Unknown	A SERVICE.		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\ELECT P&W	FRIDGE NOT WORKING.		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
				REPLACED TURNTABLE DOG BONES AND DASH GLOBES. Engine Oil Sample SIF # 43276871 Gearbox Oil Sample SIF # 42627986 Front Diff Oil Sample SIF # 42627992								
1047	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist	Rear Diff Oil Sample SIF # 42627921	07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Cooling\ENG FAN	HORTON FAN ON ALL THE TIME.		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\EXHAUST	REPLACE EXHAUST FLEX		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\OH&S	FIRE EXTINGUISHER OUT OF DATE.		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine	0-100KM IN THREE K'S. SLOW.		07/09/2022	335928	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\BELTS/TENS	REPLACE WORN ENGINE BELTS	**BELTS NOT COVERED AFTER FIRST YEAR OF WARRANTY**	16/08/2022	607253	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Insp\END WARR	End of Warranty Inspection.		16/08/2022	607253	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	PICK UP FROM TCTC.		16/08/2022	331725	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	DROP OFF TCTC.		14/08/2022	330314	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		13/08/2022	330301	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\EXHAUST	REPLACE EXHAUST FLEX		13/08/2022	330301	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		13/08/2022	330301	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\ELECT P&W	RE-SET TRIP VALUES.		03/08/2022	335847	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		31/07/2022		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP7+8	supply and fit 4 tyres		31/07/2022		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		30/07/2022	320308	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Tyre Puncture		30/07/2022	320308	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP12	Bridgestone Wetherill Park		20/07/2022		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		16/07/2022	309392	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		16/07/2022	309392	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		07/07/2022	301169	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\OH&S	FIRE EXTINGUISHER OUT OF DATE.		07/07/2022	301169	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/07/2022	301169	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check		27/06/2022		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		18/06/2022	287957	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER

1047	Wodonga - Workshop	Body\WINDSCREEN	LEFT WINDSCREEN BROKEN.		18/06/2022	287957	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\WINDSCREEN	LH WINDSCREEN CRACKED.		18/06/2022	287957	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/06/2022	287957	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\PANELS	FIT LOCKS TO CHECKER PLATE.	SECURED PLATE.	17/06/2022	286869	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\Pogo	Replace broken pogo stick		28/05/2022	277382	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\WINDSCREEN	LEFT WINDSCREEN BROKEN.		28/05/2022	277382	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Cooling\ENG FAN	HORTON KEEPS CUTTING IN AND OUT.	TESTED. DUE TO A/C BEING ON.	28/05/2022	277382	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\ELECT P&W	FRIDGE NOT WORKING. Left Hand Windscreen Replacecment		28/05/2022	277382	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\WINDSCREEN	Albury Autoscreens PO# WW072055		27/05/2022	607253	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP1+2	supply and fit 2tyres		26/05/2022		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\WINDSCREEN	LH WINDSCREEN CRACKED.		26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist	Engine Oil Sample SIF #42628686	26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\TRL LIGHTS	CLEANED AND FITTED CONDUIT TO LIGHT LEAD.		26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	Service due. Ad Blu needs calibrating urgently, uses 1 full tank to adelaide and back. Uses 1 1/2 tanks to Brisbane and back.		26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	A Tank hardly lasts at least a full week.	MEASURED ADBLUE DURING OVER-RIDE TEST. IN SPEC.	26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ENG TUNE	No Power, too slow to get going.	CHECKED TURBO ADJUSTMENT. HOOKED UP. TEST DROVE. BOOST 200KPA	26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\STEER TYRE	STEER TYRE WORN.	ORGANISED BEAUREPAIRS.	26/05/2022	277337	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP09	Tyre Position 9		25/05/2022		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP7+8	supply and fit 4 tyres		25/05/2022		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	TIGHTENED LOOSE OIL FILTER. ADDED 8L ENGINE OIL.	21/05/2022	374864	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job TRAVEL TO ST MARY'S R & R SUZI AIR LINE CHECK FOR AIR LEAKS - OK		21/05/2022	374864	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\SUZI COIL	TRAVEL TO WORKSHOP		03/05/2022		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		10/03/2022	237117	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Engine Oil Sample SIF # 42617317	10/03/2022	237117	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist	REPLACED DASH GLOBE	09/02/2022	219646	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\STEER TYRE	STEER TYRE WORN.		09/02/2022	219646	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/02/2022	219646	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	TIGHTENED ALL BATTERY TERMINALS	26/01/2022	210955	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		26/01/2022	210955	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Unknown	A SERVICE		08/01/2022	201769	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	ADBLUE TANK SUCKING IN.		08/01/2022	201769	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\PANELS	REMOVE LEFT WEATHER SHEILD		08/01/2022	201769	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\MIRRORS	LEFT MIRROR BACK FELL OFF.		08/01/2022	201769	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	REMOVED ADBLUE TOP AND UNBLOCKED BREATHER. REPLACED TEA BAG. POPPED TABK BACK OUT. ADJUSTED JAWS. ADDED 2L E	08/01/2022	201769	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		08/01/2022	201769	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist	DROPPED OFF AT TCTC	05/12/2021	182434	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/12/2021	182434	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up from TCTC		02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10		02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8		02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP1+2	supply and fit 6 tyres		02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
				.The following engine tune up as per manufacturer specification included: - * Removed & check air intake for restrictions * Check radiator for oil indicating compression or oil leaks * Removed rocker cover to access internal components * Check top end components * Adjust valve clearance to specification * Set all parameters to specification * Install rocker cover & components complete * Check & adjust all belts * Pressure test CAC * Test, confirm & quality check engine operation							
1047	Wodonga - Workshop	Engine\ENG TUNE	CARRIED OUT ENGINE TUNE AND CHECK INTERNAL COMPONENTS IN TOP OF ENGINE	* Complete ECM download	02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\CLEAN	MOVED TRUCK. CLEANED WORKSHOP. REPAIRED PIT BILGE PUMP SUCTION LEAK.		02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\CS	C Service As Per Attached Checklist	CLEANED FRONT DIFF BREATHER	02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\OIL LEAK	RH Engine oil filler weeping.	DROPPED OFF AT TCTC- WARRANTY.	02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/11/2021	158474	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		03/10/2021	142658	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/10/2021	142658	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	B Service due.	Refer Job# 355673	01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\CLEAN	Clean Pit.		01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\OIL LEAK	RH Engine oil filler weeping.		01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\HOUSEKEEP	Left air cleaner stack loose.		01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ELECT P&W	fuse for power socket blown		01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\HOUSEKEEP	air intake pipe loose		01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/10/2021	141970	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Air Con\AIR CON	1.Supply and fit Coolabah 6.5kw battery with back charger – Kenworth K200 – Chassis # 466914 1 x Left Hand Windscreen Albury Auto Glass		15/09/2021		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\WINDSCREEN	PO# WW067022		11/09/2021		Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\FIFTH WHEE	Adjusted Jaws		09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ENG TUNE	No Power, too slow to get going.		09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\Pogo	Needs Taller Pogo Stick.	Refer Job# 353221	09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\DAMAGE	Raise/Lower Valve broken on Cab Jack.		09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService	A Service due	Refer Job# 353219	09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\Pogo	Fit taller pogo stick.		09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/09/2021	132188	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\EXHAUST	Exhaust Leak.	Replaced exhaust flex and power socket.	25/08/2021	124333	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		06/08/2021	114308	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	Fit weight Gauge. Route 1/4 Air lines. Route wiring for light and gauge. Checked for air leaks.	06/08/2021	114308	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Susp\WGHT GAUGE	Fit weight gauge. Broken left mirror. Attempted to replace mirror assembly and repair. Wrong side ordered.	Reassemble dash and over head console.	05/08/2021	113208	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\MIRRORS	Reassemble and attempt to secure for the time being.	Refer Job# 348539	31/07/2021	111203	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ENG TUNE	Check engine computer power is up and down. Using a lot of Ad Blu.	Checked engine parameters - Nothing wrong. Tested Ad Blu usage all OK.	31/07/2021	111203	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\ADBLUE	Sucking Ad Blu tank in.	Unblock Ad Blu breather in pick up unit + hose.	31/07/2021	111203	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\MIRRORS	Repair left hand mirror.	Fit left hand mirror.	31/07/2021	111203	Completed	Mt Gambier STK	XV67MC	Wodonga Workshop	P/MOVER

1047	Wodonga - Workshop	Tyres\BLOWOUTS	Tyre Blow out. Frank Vanz Lismore attended. Invoice number 00192 Copy attached. Broken left mirror. Attempted to replace mirror assembly and repair. Wrong side ordered.	Attempted to replace mirror assembly and repair. Wrong side ordered.	23/07/2021	104900	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\MIRRORS	Reassemble and attempt to secure for the time being.. Broken left mirror.	Reassemble and attempt to secure for the time being.	20/07/2021	102624	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		09/07/2021	96605	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\BOOST HOSE	Inspect boost pressure	TESTED AND FOUND TO BE ALL GOOD	09/07/2021	96605	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		09/07/2021	96605	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Maintenance POS 1-10		25/06/2021	86867	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	B Service As Per Attached Checklist		22/06/2021	84912	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		22/06/2021	84912	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\SCALES	Remove Load scales Travel to TCTC. Remove scales and all wiring and sensors from truck as required. Interior was already pulled apart when arriving at job. Return to workshop. Assist Graham in hooking up A - Double.		18/06/2021	84898	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	Pick Graeme up from TCTC after dropping off combination.		09/06/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\PRES CHECK	Pressure check POS 1-10		02/06/2021	81913	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\TP1+2	Supply and fit 2 tyres		25/05/2021	78643	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	Job Added From Invoice		26/04/2021	0	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Maintenance POS 1-10		25/04/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\LIGHTS	Brake Reverse Lights L/S	Brake/reverse circuit breakers reset.	24/04/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service As Per Attached Checklist		24/04/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\WINDSCREEN	Windscreen cracked on left side	SUPPLY AND FIT LAMINATED TINTED LHS WINDSCREEN TO KENWORTH K200	24/04/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\WGHT GAUGE	on board truck saddles out malec w/b - 74-620 truck saddles 76.300		24/04/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		24/04/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\TRL LIGHTS	No indicators on trailers.	Found truck plug set to 5 pin & trailers set to 7 pin. Fixed adaptor and tested all OK Had to move 1046 & trailers to get to 1047 and trailers.	20/04/2021	67145	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Steering\OIL LEAK	Oil Leks in Front Hubs	Found to be overfilled, rectified and cleaned.	09/04/2021	63633	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ELECT P&W	check trailer lights, change wiring in adaptor plug to suit truck and trailer. Assemble an		26/03/2021	60059	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ELECT P&W	trailer ligth issue	wagga kenworth Poww062989	24/03/2021		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	oil leak LHS of engine, TCTC to warranty	18/03/2021	57281	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\WIPERS	can hear something in dash being hit when using wipers		18/03/2021	57281	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\WIPERS	can hear something in dash being hit when using wipers	Inspect wipers. Dissassemble dash locate air line hitting on wiper arm. Cable tie to loom as required. park and unhook trailers	18/03/2021	57281	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\OIL LEAK	LHS of engine covered in oil, possibly air comprlessor gasket	wash of engine & test drive	18/03/2021	57281	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		18/03/2021	57281	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ELECT P&W	replaced trailer light plug, and base on T621 found lights still not working. Tested wirin		09/03/2021	51902	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\ELECT P&W	wire trailer plug on truck to match trailer 7 pin set up		23/02/2021	44673	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	completed	17/02/2021	42108	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\SUZI COIL	replace suzi leads and air leads back of truck	previously completed	17/02/2021	42108	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	gear shift and base very loose	previously completed	17/02/2021	42108	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\WGHT GAUGE	on board truck saddles out malec w/b - 74-620 truck saddles 76.300	pending	17/02/2021	42108	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\WGHT GAUGE	some axle weights not always showing air weight scales (mainly dolly and rear axle gro	previously completed	17/02/2021	42108	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job	completed as per service	17/02/2021	42108	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Tyres\STEER TYRE	steers need flipping on rim		05/02/2021	40136	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	Carry Out A Service	05/02/2021	40136	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Steering\WHEEL SEAL	right hand steer hub leaking		05/02/2021	40136	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job suzi coil damage due to not being disconnected from trailers, replace both suzi pipes, replaced ebs lead, replaced light plug, confirmed with light tested all repairs were working	Carry Out A Service	05/02/2021	40136	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Body\DAMAGE	replaced 30amp ebs fuse (including leading hand duties)		29/01/2021	39598	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	drop at TCTC		25/12/2020		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		23/12/2020	31936	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		23/12/2020	31936	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	A Service		19/12/2020	31034	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\HOUSEKEEP	bolt missing out of checker plate over R/hand fuel tank		19/12/2020	31034	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Steering\WHEEL SEAL	right hand steer hub leaking		19/12/2020	31034	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	gear shift and base very loose		19/12/2020	31034	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist	also included unblocking adblue tank breather	01/12/2020	24707	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		01/12/2020	24707	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	move truck		29/10/2020	14003	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		29/10/2020	14003	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		29/10/2020	14003	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Engine\FAULT CODE	download ecv data and email to Dean Salmon		27/10/2020	13343	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	put gear stick and clutch pedal in or unlock gearbox so can hold/change all 18 gears		22/10/2020		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\WGHT GAUGE	some axle weights not always showing air weight scales (mainly dolly and rear axle gro		14/10/2020	8052	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	unlock manual mode in gearbox so cab be shifted manually in all 18 gears or put clutch		14/10/2020	8052	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\CS	Service As Per Attached Checklist	The following 1st service inspection for Greenfreight to a K200 Kenworth Truck, Chassis#466914, and registration #XV67MC include	11/10/2020	6715	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		11/10/2020	6715	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	pick up truck and trailers from TCTC		11/10/2020		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	first service needed 5000km		07/10/2020	4728	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	gear box needs to be unlocked so can be driven in manual to shift all 18 gears		07/10/2020	4728	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	VehService\AS	1000km off 5000km TCTC inspection		03/10/2020	4070	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrCabElect\WGHT GAUGE	on board truck saddles out malec w/b - 74-620 truck saddles 76.300		03/10/2020	4070	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DrivLine\GEARBOX	unlock manual made on g/box so can chainge up/down all		03/10/2020	4070	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\BATTERY	hook up to trailers had to move skip out out the way Attempt to jump start with 884 left 884 on high idle tp charge.		30/09/2020	2752	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Elect\BATTERY	Ended up swapping out 884 with 976 and left in high charging	replaced batteries	30/09/2020	2752	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Chassis\FIFTH WHEE	grease turntable		28/09/2020		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\VALVES	THIRD BUTTON * SUPPLY AND FIT THIRD BUTTON TRAILER BRAKE RELEASE	Removed dash panels. * Fabricated brackets for solenoid mounting. * Mounted solenoid. * Removed dash panel for third button mo	03/09/2020	2741	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	DriCabRep\HOUSEKEEP	Fit new seat covers		01/09/2020	52	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Brakes\EBS FAULTS	replace ebs lead and secure suzi's move truck		31/08/2020	2750	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	Hook up to trailers		31/08/2020	2750	Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	pick up 1047 from TCTC		29/08/2020		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER
1047	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up new truck & trailers from TCTC		27/08/2020		Completed	Mt Gambier	STK	XV67MC	Wodonga Workshop	P/MOVER