Tax invoice

Purchase order no	Invoice number	Issue date	Due date
909		10/02/2026	10/02/2026

Item ID	Description	UoM	Qty	Unit price ($) *excluding tax*	Disc. (%)	Tax	Amount ($) *excluding tax*
Labour	Hourly Labour Rate - Equipment Details Rego: 909SCT ESN: 79596111 Chassis: 448186 Speedo: 226,230 kms Taco: 29,047 hrs ECM Distance: 1,251,102 Km ECM Engine Distance: 1,920,407 Km ECM Fuel Used: 639,763 Litres ECM Hours: 29,635 Hrs ECM Engine Hours: 29,446 Hrs Model: Kenworth T909 Work Carried Out -Found the lube oil filter to be leaking excessive oil over the floor, found the lube oil filter to be loose and only hand tight at the best, tighten the lube oil filter up with filter strap -Drain and collect the engine coolant, install ball valve in the lower coolant pipe to allow controlled drainage to occur -Drain the cylinder block at the EGR coolant return adapter and remove the coolant filter -Cut the coolant filter open and found the filter media to be blocked up with debris -Remove both left and right side charge air pipe assemblies	Hrs	15	155.00	0.00	GST	2,325.00

Item ID	Description	UoM	Qty	Unit price ($) *excluding tax*	Disc. (%)	Tax	Amount ($) *excluding tax*
	-Remove the charge air hoses from the right side charge air pipe assembly -Remove the turbocharger compressor outlet adapter -Soak the right side charge air pipe and turbocharger outlet adapter in diesel to soften up the caked on oil sludge -Remove the air intake trunking -Disconnect the VG turbocharger electronic wiring, coolant and oil plumbing along with the exhaust outlet clamps -Remove the VG turbocharger retaining nuts and remove the VG turbocharger off the engine -Remove the left side air handling system -Clean the oil debris from the left side air handling system and charge air pipe assembly -Reinstate the air handling system and left side charge air pipe assembly -Install two mount studs onto the new VG turbocharger -Prime the new turbocharger oil plumping and reinstate the oil supply fitting and oil supply hose -Install the VG turbocharger and its retaining nuts, tension the retaining nuts to specification -Reinstate the exhaust outlet retaining clamps						
	-Replace the broken electrical connectors for the compressor air inlet temperature sensors -Reinstate the VG turbocharger oil and coolant plumbing and the electronic wiring -Calibrate the VG actuator to the engine ECM -Calibrate the VGT actuator to the VG turbocharger -Clean the turbocharger outlet adapter with pressure wash and degreaser and right side charge air pipe to remove the caked on oil sludge -Install the compressor outlet adapter along with the charger air pipe work to work out the alignment angles -Make up and install a turbocharger anti rotation bracket from a cylinder head lift bracket on the right side to the turbocharger outlet adaptor, use an exhaust U bolt on the outlet adaptor to retain bearing housings from rotating under compressor outlet pressure pulsations and cycling -Install the air intake trunking and the right side charger air hoses and retaining clamps -Install a new coolant filter and fill the engine cooling system up with new coolant						

Item ID	Description	UoM	Qty	Unit price ($) *excluding tax*	Disc. (%)	Tax	Amount ($) *excluding tax*
	-Clear the engine ECM fault code history -Start and operate the engine -Pressure wash and clean the engine -Run and operate the engine at an elevated RPM to vent the cooling system of any entrapped air and to heat up the cooling system -Carry out road test to confirm engine repairs and performance						
Parts	4298220 - Stud	Qty	2	58.27	0.00	GST	116.54
Parts	5394262 - Connector Electrical Repair	Qty	1	74.84	0.00	GST	74.84
WF2077	WF2077 - Water Filter	Qty	1	24.99	0.00	GST	24.99
Parts	HE8761XL - Hump Hose 4"X 4.5"X7	Qty	1	78.38	0.00	GST	78.38
Parts	HE8701 - Hump Hose 4"X 4"X8"	Qty	1	83.98	0.00	GST	83.98
Clamp 4.5" CAC	4.5" Charge Air Cooler Clamp	Qty	1	22.80	0.00	GST	22.80
Parts	1/2" Ball Valve	Qty	1	18.00	0.00	GST	18.00
Parts	104mm - U Bolt	Qty	1	20.75	0.00	GST	20.75
Hose 1"	1" Silicon Heater Hose Blue	Qty	0.3	44.65	0.00	GST	13.40
Subcontract Work	5496312H Turbocharger (No Actuator) HE500VG Cummins ISX EGR CM871 Series SN: P2500400153	Qty	1	7,710.23	0.00	GST	7,710.23
PGXLV	PGXL Vital Coolant	Qty	80	9.24	0.00	GST	739.20
Consumables	Consumables	Qty	1	50.00	0.00	GST	50.00

Subtotal *(exc. tax)*	$11,278.11
Tax	$1,127.81
Total Amount *(inc. tax)*	$12,405.92
Total paid	$0.00
Balance due	**$12,405.92**

Invoice number

Due date: **10/02/2026** Balance due: **$12,405.92**