PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Equipment: TT1006

Work Order #: 51719
Date: 01/29/25

Completed Date: 01/31/25

Year: 2005
Make: LAZER
Model: LA22-3PPCR

Serial Number: 2L9TC43135D079350

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...		Bursey, Justice	9.00	60.00	540.00
LABOUR INTERNAL (PVT ...		Hooey, Nathan	4.00	60.00	240.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
12110, VALVE	1.00	18.00	18.00
110170, RELAY VALVE	1.00	171.65	171.65
LGS3A105, LG SET 28" OUTTER SKID FOOT W/O ACCESSORIES	1.00	850.40	850.40
90554107, VALVE, PRESSURE PROTECTION	1.00	62.10	62.10
2001A, TANK, AIR 9.5 X 22.5	1.00	149.40	149.40
6100065, HUB, MOUNTING BRKT	1.00	22.85	22.85
650-0532, HUBMETER STEMCO	1.00	94.00	94.00
15-730, 7 WAY PLUG	1.00	12.29	12.29

1) Complete CVIP level inspection
Inspected unit. - Justice(1)

2) install Samsara
Installed samsara and wired into unit. - Justice(2)

3)Replace air tank
Modify air tank to fit in mounting spot. Install all valves needed. Install all airlines. Air up and test air tank. Nathan 4hrs

4) 7 WIRE PLUG
Replaced 7 wire plug. - Justice(.5)

5) REMOVED LEFT OVER HEAT TRACE
Removed remaining heat trace. - Justice(.5)

6) VENT LINE AIR LEAK
Cut out section of leaking line and replaced with union. - Justice(.5)

7) 2ND AIR TANK
Completed on line 14.

8) QUICK RELESAE VALVE
Removed air lines and valve, swapped fittings over to new valve, installed and hooked up airlines. - Justice(1.5)

9) BRAKE VALVE 2ND AIR TANK
Disconnect air lines from tank, brake valve and ppv, fight out seized mounting bolts and removed tank/brake valve/ppv all as one. Ordered new parts but wrong tank came, can make it work possibly or will need proper tank ordered. -

PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Justice(2.5)

10) HUBMETER
Replaced hob odometer, could not read the kms on the old one. - Justice(.5)

Total Labor	780.00
Total Parts	1,380.69
Total Returns	.00
Total Sublet	.00
Shop Supplies	39.00
Invoice Total	2,199.69

PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Equipment: TT1006

Work Order #: 53094
Date: 04/04/25

Completed Date: 04/24/25

Year: 2005
Make: LAZER
Model: LA22-3PPCR

Serial Number: 2L9TC43135D079350

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...		Hooey, Nathan	21.50	60.00	1,290.00
LABOUR INTERNAL (PVT ...		Farquhar, Brian	3.00	60.00	180.00
LABOUR INTERNAL (PVT ...		Sparrow, Mick	5.00	60.00	300.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
8091, TRAILER AIRBAG S21784	3.00	99.50	298.50
S-28890, S-CAM TUBE, 16.5"	1.00	53.65	53.65
SSD6722, BRAKE DRUM16.50X7.00 10 HOLE - SUB PRT# 3600A	2.00	100.85	201.70
XSS714707QPK, SHOE KIT, MERITOR Q+ 16.5X7	2.00	56.65	113.30
E11866, CAM, 28 SPLINE	1.00	32.25	32.25
78433, 2" LED ABS LAMP	1.00	19.15	19.15
40072, REFLECTOR, 2-1/2" RED ADH.	2.00	1.19	2.38
G1004, 4" GATE VALVE FLANGE/THREAD	1.00	351.91	351.91
10233C, 4" GASKET BETT'S GATE VALVE	1.00	9.16	9.16

1) Complete CVIP level inspection
Pull wheels and perform wheels off CVIP. Make repair list. Nathan -4hrs
Install drums Install wheels and torque. Set brakes Nathan- 2hrs
Checked for cvip and repairs. - Brian(3)

2) #1R brakes walking out of drum
Replace brake shoes and drum with new anchor pins and bushings. Nathan -1hr

3)#2R brakes worn.
Replace Brake shoes and drum with new anchor pins and bushings. Nathan -1hr

4)#1L cam out of spec
Replace #1L cam and tube. Reinstall brake shoes. Nathan -1hr

5)Safety chains worn out.
Replace safety chains on both sides with new 1/2" chain. Nathan -2hrs

6)#2L,#2R,#3L,#3R Airbags showing chords
Replace all 4 airbags with new hardware. Nathan -5hrs

7)Air leak on brake application
Diagnose. Found air leak at push in fitting. Repair fitting and test. Nathan - 1hr

8)ABS light not marked ABS
Replace light with properly marked ABS light -0.5hrs

PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

9)RR &LR reflectors not reflecting
Scrape off old reflectors and clean surface. Place new reflectors on LR & RR. Nathan 0.5hrs

10) Test all valves on tank
Apply air to tank. Test all valves. Make repair list. Nathan -2hrs

11) front load valve (screw) bypassing
Took out faulty load valve and installed new betts valve - Mick(1.5)

12) vent valve on top is manual
Took out manual vent to have switched for air actuated one. - Mick(1.5)
Installed new air actuated valve on vent line. - Nathan(1.5)

13) other vent not operating
Help confirm vent is working when enough air pressure is used. - Mick(.5)

14) front side valve handle spring seized
Replaced handle, cut off old seized one, installed new handle and confirmed working properly. - Mick(1)

Total Labor	1,770.00
Total Parts	1,082.00
Total Returns	.00
Total Sublet	.00
Shop Supplies	88.50
Invoice Total	2,940.50