Vehicle History Summary

Fleet #	PM071
Registration	XB44PW
Make	Mercedes
Model	Actros 2658
VIN / Chassis	WDB96342420318476
Build Date	2016

Number	Date	Km	Hours	Fuel Usage	Type	Repairer Notes	Repairer
R-1237	2026-02-09	806903		0	Radiator	OIL COOLER MODULE REPLACED BY CUSTOMER RADIATOR REPLACED BY CUSTOMER REMOVED SUMP AND FOUND COOLANT COMING DOWN BY TIMING GEARS INTO SUMP HOOKED UP COMPUTER AND FOUND MULTIPLE FAULTS FOR OVERHEATING AND LOW COOLANT CUSTOMER ADVISED OF RADIATOR BEING REPLACED BY OTHER PARTY CHECKED COOLANT CONDITION AND FOUND TO BE NONE EXISTENT, JUST WATER REMOVED CLINDER HEAD AND INSPECTED, FOUND GASKET HAS MULTIPLE HEAT STRESS SPOTS AND COLOURING FOUND BUILD UP OF RUST AROUND ORINGS AND PORTS FROM LACK OF COOLANT SENT HEAD AWAY TO BE TESTED AND CAME BACK SLIGHTLY OUT OF SPEC, 004" REFACED BY MACHINESHOP TO BRING BACK INTO SPECIFICATION CHECKED INTERNALS OF ENGINE FOR SIGNS OF WEAR AND DAMAGE CYLINDER BORE CONDITION STILL GOOD, NO SCORING LINER HEIGHT CHECKED AND ALL GOOD, WITHIN SPEC AT TIME OF BUILD REFITTED HEAD WITH GENUINE VOR DETROIT GASKET KIT TORQUED TO SPECIFCATION AND SET VALVES TO MANUFACTURERS SPECIFICTATION REFILLED WITH MERCEDES/DETROIT GP40 GENUINE COOLANT AND TESTED TO 50% CARRIED OUT MULTIPLE ROAD TESTS ON LONG DRIVES TO CHECK FOR ANY ISSUES ALL OK CLEARED ALL FAULTS AND CHECKED FOR ANY NEW ONES BUT ALL CLEAR CLEAN DOWN AND DEGREASE ENGINE AND FRONT OF TRUCK AND CHECK FOR ANY LEAKS NONE FOUND	Marshall Truck Solutions
I-146	2025-08-28	784727		0	NHVR Heavy Vehicle Inspection		
S-1329	2025-08-28	801722	0		A - Minor	Pressure test cooling system. Flush coolant. Replace V-stays. Tighten loose wheel guards. Resolve wiring issue at rear diff. Replace abs sensor position 5. Replace diff lock position switch.	Fez
R-1246	2025-08-22	797156		0	Radiator	CORRECTION: BREAKDOWN 22-08-2025 TRAVEL 10KMS SOUTH OF BOWEN. INSPECT VEHICLE AND FOUND RHS AND LHS HEATER HOSES BLOWN. REMOVE RHS AND LHS HEATER HOSE AND REPLACED WITH NEW. TOP UP COOLANT, START TRUCK, TOP UP COOLANT. CHECK FOR LEAKS - ALL OK, DRIVE BACK TO MACKAY.	RGM Mackay
R-1244	2025-08-20	794844		0	Radiator	Flush vooling system again	Fez
R-1203	2025-08-04	790812		0	Radiator	Flush Cooling System	Fez
R-1199	2025-07-21	787532		0	Radiator	Diagnose fault. Removed oil cooler and pressure test. Found hairline crack in oil cooler housing. Replaced: EGR seals, cab tilt pump, inlet horn gasket, water pump, thermostat, EGR coolant feed pipe, front cab shock absorbers, cabin storage bins, various lights. Flush cooling system several times. Will need to return to workshop to flush cooling system and replace coolant	Fez
R-1081	2025-06-06	769893	0	0	Cab	Modified fridge panel to gain access to release cable. Removed contents from fridge. (New parts have been ordered to complete repair)	Fez
R-1081	2025-06-06	769893		0	Lights	Replaced both headlight bulbs with LED and fitted canbus modules.	Fez
R-1081	2025-06-06	769893		0	Radiator	Coolant leak	Fez
R-975	2025-05-08	763216		0	Engine		
R-959	2025-04-22	756878		0	Battery	replaced batteries Alternator tested and all ok	All Sorts Heavy Mechanical
R-1095	2025-04-10			0	Radiator	Received breakdown callout. Contact sublet agent. Travel to Wyagga parking bay. Top up vehicle with coolant the kink over leaking hoses Get vehicle to Gundy. Next day new parts and coolant arrived, fit new parts. Find brackets missing from top of radiator. Zip tie in place drain and refill. All ok.	Daimler Trucks
R-926	2025-04-10			0	Radiator	breakdown Campbell street Millmerran supply 2 x hose clamps technician picked up hose tail on junction fitting broken escort truck back to workshop tilt cab remove junction valve and broken fitting as required drill and tap thread fit brass hose tail wit adaptor as required refit junction refill radiator with coolant took 15 ltrs supplied last 5l to driver tilt cab back start and test completed	Haical Hydraulic Hoses
R-887	2025-04-09			0	Windscreen		RACQ
R-942	2025-04-08	752041		0	Radiator	Description of work carried out: Pressure test cooling system. Found radiator leaking. Removed: Plastic surrounds, fan hub assembly, idler pulley, fan, fan shroud, coolant, various coolant hoses, wiring harness, condenser, egr pipes, intake pipes, drive belts, radiator, intercooler. Replaced radiator various hoses and custom fit brackets to suit. Refit all components. Repair battery box. Pressure test system and test drive. OK	All Sorts Heavy Mechanical
R-1095	2025-04-07	0	0	0	Radiator	Actros Raditor 1835/ 1840/ 2643/ 2651/ 2653/ 2663	STRATHPINE RADITOR

R-942	2025-04-07	0	0	0	Radiator	Actros Raditor 1835/ 1840/ 2643/ 2651/ 2653/ 2663	STRATHPINE RADITOR
R-82	2025-03-17	662004	0	0	Cab	repaired by Marshalls	Marshall Truck Solutions
R-647	2025-03-17			0	Cab	repaired or replaced at Marshalls	Marshall Truck Solutions
S-1090	2025-03-17	744727			D - Major	Had engine work and D service Diagnose misfire and coolant usage Possible head issue Hooked up computer and found faults for cylinder imbalance Carried out compression test and cylinder leak down test Leak down readings high on cylinder 1 and 2 Compression test readings low on 1 and 2 confirming internal issue Removed rocker cover and found valve adjustment out significantly on cylinder 1 and 2 Carried out valve adjustment and misfire corrected but after discussion with customer and nature of trucks workload, decision made to inspect further Noticed header tank already replaced, signs of engine issue also Stripped down engine and removed cylinder head for inspection Found cylinder 1 and 2 valves deeply recessed into valve seats Valve sealing surface worn out and burnt away Inspect all parts for damage and wear including camshaft hard facing Clean down all parts ready for reassembly Supply and fit Aftermarket DD16 Cylinder head Supply and fit genuine Detroit Top end rebuild gasket kit Replace cracked exhaust manifold centre and end piece Replace all injector lines as they are one use Inspect head bolts and found out of spec and stretched, Replaced Carry out valve adjustment Carry out service and replace oils and filters Replace fuel filters Replace coolant Bleed system and start Test drive for extended period to confirm no issues Recheck all levels and check for leaks Headlight and bonnet panel missing, Replaced Secured loose air horn on roof Attach service sticker Clean down truck	Marshall Truck Solutions
R-703	2024-12-17	744727		0	Engine	Repairs for Rego: XB44PW PM071 Odometer/hours: 744727km Faults/Defects: Engine misfire Description of work carried out: Checked operation of EGR valve. No functioning correctly. Removed intake pipe. Audible noise from intake manifold. Removed rocker cover and inspected top end. Removed fuel system and intake manifold. Refit fuel system. Started engine. Intake valves on cylinders 1, 2 exhausting from intake. Suspect cracked head/Valve issue. Refit all components as customer requested.	All Sorts Heavy Mechanical
T-101	2024-10-28	731437		0	Steer	reaplaced steers	Internal Workshop
R-560	2024-10-23	729557	0	0	Lights		
R-590	2024-10-09	722348		0	Engine	Performed cylinder cutout test. Checked fuel parameters. No faults present. Replaced QCV valve. Tested. OK	All Sorts Heavy Mechanical
T-102	2024-10-08	722348		0	Truck Drive	replaced front drives - all 4	Internal Workshop
R-514	2024-10-01	719556		0	Gearbox	VEHICLE TOWED IN - INVESTIGATE TRANSMISSION FAULT ON DASH FOUND MAJOR OIL LEAK FROM FRONT TRANSMISSION HOUSING Tow - $890.51	Daimler Trucks
R-414	2024-07-29	711356		0	Electrical	Traced wiring for A/C. Found break in wiring harness engine bay. Replaced batteries. Replaced front engine mounts. Diagnosed air leak. Found faulty turbo wastegate solenoid. Replaced turbo. Test drive vehicle. OK	All Sorts Heavy Mechanical
R-389	2024-07-22			0	Air Conditioner	Traced wiring to pressure switch. Found power supply at pressure switch. Need wiring schematics to further diagnose as it has a 3 wire pressure switch. Reinstated dash.	All Sorts Heavy Mechanical
R-342	2024-07-18	705041		0	Air Conditioner	INVESTIGATE AIR CON POOR DEGASSED SYSTEM - ONLY 0.6 BAR REGASSED SYSTEM TO 0.88 BAR FOUND AC NOW WORKS BUT PRESSURE IS FLUCTUATING CHECKED PRESSURE SENSOR WIRING AND PLUG CONNECTION FOUND WIRING CHAFFED INSIDE CONDUIT REPAIRED WIRING CHECKED OPERATION OF PRESSURE SENSOR FOUND NOW HAS A STEADY PRESSURE - ALL OK	Daimler Trucks
S-724	2024-07-18	705041	0		D - Major	CARRY OUT ENGINE OIL SERVICE CARRIED OUT ENGINE OIL AND FILTER SERVICE CARRIED OUT INSPECTION REPLACED FUEL FILTERS AND POLLEN FILTER CHECKED ALL LIGHTS AND LEVELS REPLACED WIPER BLADES GREASED VEHICLE RESET PARAMETERS IN SSAM FOR LED LIGHTS SECURED AC COMPRESSOR WIRING HARNESS SECURED ADBLUE PLUG CONNECTION REPOSITIONED REAR GUARDS AND SECURED CARRIED OUT ROAD TEST - ALL OK	Daimler Trucks

R-340	2024-07-18	705041	0	0	Engine	DRAINED ENGINE OIL INTO CLEAN CONTAINERS REMOVED SUMP REMOVED AND REPLACED OIL SUCTION MANIFOLD REFIT SUMP WITH NEW GASKET REFILLED WITH ENGINE OIL CLEANED ENGINE CARRIED OUT ROAD TEST - ALL OK	Daimler Trucks
R-341	2024-07-18	705041		0	Gearbox	CARRIED OUT ROAD TEST - NO FAULTS DRAINED TRANSMISSION OIL TO CHECK - NO METAL PRESENT REPLACED OIL CARRIED OUT TEACH IN PROCEDURE ALL OK - NO FAULT FOUND	Daimler Trucks
I-112	2024-07-18	653972		0	NHVR Heavy Vehicle Inspection		
R-343	2024-07-18	705041		0	Brakes	JACKED UP ALL REAR AXLES REMOVED ALL REAR WHEELS REMOVED AND REPLACED BRAKE PADS AND ADJUSTED BRAKES REFIT WHEELS AND TORQUED WHEEL NUTS RESET BRAKES IN MS CONTROL UNIT CARRIED OUT ROAD TEST - ALL OK REMOVED AND REPLACED BOTH FRONT VOSS FITTINGS ON BRAKE BOOSTERS (LEAKING)	Daimler Trucks
R-344	2024-07-18	705041		0	Engine	REMOVED AND REPLACED STARTER MOTOR	Daimler Trucks
T-42	2024-05-24	682496	0	0	Steer		Internal Workshop
R-198	2024-05-02	0	0	0	Lights		All Sorts Heavy Mechanical
R-167	2024-04-21	673897	0	0	Lights		All Sorts Heavy Mechanical
S-619	2024-04-16	673837	0		A - Minor	Maintenance - CARRIED OUT GENERAL SERVICE AS REQUIRED (40000KM) Electrical System - CHECK AND REPORT ON ENGINE FAULTY WARNING ON DASH - Cause: Open circuit for signal wire in the injector harness for cylinders 1,2,3. Heater, Ventilation, A/C - CHECK A/C OPERATION - NOT COLD - Correction: Took truck for 45 minute test drive before carrying out service. Could not fault the Air con system. Was very cold and worked as it should do. Engine Cooling - CHECK AND REPORT ON COOLANT LEAK AT HEADER TANK AREA - CAUSE- PLASTIC DISTORTED Engine Lubrication - CHECK AND REPORT ON OIL LEAKS AT CYLINDER HEAD NEAR INJECTOR LINE SEALS - CAUSE- SEAL FATIGUED	
T-15	2024-03-01	659226	0	0	11R 225	Positions 7,8,9,10 replace with new(+4 Haulstar tyres(11R22.5)DH 608 Position 6 replaced with runout(11R22.5) Checked all pressures	Internal Workshop
S-200	2023-10-24	632364			A - Minor	DAIMLER- CARRY OUT SERVICE AS REQUIRED (620000KMS)	Daimler Trucks
I-113	2023-10-18	676665		0	NHVR Heavy Vehicle Inspection		
S-634	2023-10-18	621150	0		B - Middle	CHECK & REPAIR HUB OIL LEAK AT L.H FRONT DRIVE CARRY OUT SERVICE AS REQUIRED (620000KMS) CHECK & REPAIR ENGINE WARNING LIGHT	Daimler Trucks
S-422	2023-05-02	601461			B - Middle	DAIMLER TRUCKS- CARRIED OUT 560000KLM SERVICE	Daimler Trucks
S-633	2023-05-02	544442	0		B - Middle	CARRY OUT ENGINE SERVICE AS REQUIRED (7TH 560k)	Daimler Trucks
R-210	2022-10-17	412568		0	Windscreen	Downloaded - found radar dirty fault current. Removed front panels - cleaned covers and radar (no damage evident). Refitted panels and carried out calibration drive - all ok CABOOLTURE AUTOGLASS SUPPLY AND FIT OF WINDSCREEN HAD TO CALIBRATE SENSOR ON WINDSCREEN	Daimler Trucks
S-516	2022-03-08	413972			D - Major		Daimler Trucks
S-632	2022-03-08	407177	0		D - Major	D SERVICE + REPAIRS Inspected wiring harness to ACM, checked all temp sensors, removed acm, found moisture and diagnosed and replaced 2x nox sensors	Internal Workshop
S-631	2021-07-31	331999	0		B - Middle	CARRY OUT SERVICE AS REQUIRED-(4TH) + REPLACED BROKEN SIDE MARKER LIGHT AT R.H FUEL TANK REPLACED MISSING WASHER BOTTLE LID	Daimler Trucks
S-630	2019-10-12	76214	0		B - Middle	CARRY OUT FIRST SERVICE (80000)	Daimler Trucks