# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **29/06/2023** | **R54020815** | | | |
| | | 101 | 01UD | SERVICE |
| | | 102 | 01 | SERVICE LABOUR |
| | | 103 | n | Carry out A service as per service schedule. |
| | | 104 | VTAMP24078863 | COOLANT VCS-2 PREMIX VOLVO 5LTR CONTAINER |
| | | 105 | vds4 | VGA CAL85121795 ENGINE OIL |
| | | 106 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| | | 107 | STAR | ********** |
| | | 108 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **03/12/2024** | **R54023540** | | | |
| | | 101 | 01UD | B SERVICE |
| | | 102 | 01 | B SERVICE |
| | | 103 | n | C: B service |
| | | 104 | n | C: Due kms |
| | | 105 | n | C: Carry out B service as per service schedule. |
| | | 106 | UD99999FK037 | KIT FILTER BASIC UD QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| | | 107 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| | | 108 | vds4 | VGA CAL85121795 ENGINE OIL |
| | | 109 | gr | GREASE |
| | | 110 | STAR | ********** |
| | | 401 | 63UD | RH BLINKER FLICKERING |
| | | 402 | 63 | RH BLINKER FLICKERING |
| | | 403 | n | C: RH blinker flickering |
| | | 404 | n | C: Faulty globe |
| | | 405 | n | C: Remove and replace globe, test all ok. |
| | | 406 | KE13496ML | AMBER 24V 21W GLOBE |
| | | 407 | STAR | ********** |
| | | 701 | 64UD | A/C MAKING NOISE |
| | | 702 | 64 | A/C MAKING NOISE |
| | | 703 | n | C: Noise from heater fan |
| | | 704 | n | C: Wires in blower fan |
| | | 705 | n | C: Remove dash panels to gain access, found GPS system wiring fallen |
| | | 706 | n | into HVAC box. Remove wires and tie up, all ok |
| | | 707 | STAR | ********** |
| | | 708 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# |
|---|---|
| 30/12/2025 | R54026519 |

| Line# | Product | Description |
|---|---|---|
| 101 | 01UD | B SERVICE |
| 102 | 01 | B SERVICE |
| 103 | 01UD0001 | RESET VEHICLE SERVICE INTERVAL DISPLAY |
| 104 | n | C: Truck B service |
| 105 | n | C:due for kms |
| 106 | n | C:carried out Truck B service as per service sheet. |
| 107 | vds4 | VGA CAL85121795 ENGINE OIL |
| 108 | gr | GREASE |
| 109 | STAR | ********** |
| 110 | UD99999FK037 | KIT FILTER BASIC UD QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| 111 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| 112 | SP8403750 | RED REFLECTORS 70 X 28MM |
| 113 | SP84036S | REFLECTOR AMBER SELF AD SINGLES |
| 401 | 31UD | BROKEN SHOCKER MOUNT |
| 402 | 31 | BROKEN SHOCKER MOUNT |
| 403 | N | C: Broken shock mount L/H 2nd steer axle |
| 404 | N | C: Wear&Tear/Fatiuge |
| 405 | N | C: Inspect and found lower shock mount on lh 2nd steer axle to have |
| 406 | N | snapped off, alkso found shock has been rubbing on steering arm, will |
| 407 | N | require replacement, jack up axle and remove wheel, remove u bolts |
| 408 | N | and shock mount, fit new shock mount with new u bolts, tension and |
| 409 | N | mark, R&R steering arm, tension and mark, took photos on driveway app |
| 410 | N | refit wheel and tension, all ok |
| 411 | STAR | ********** |
| 412 | UD5223457368 | SHOCK ABSORBER |
| 413 | UD5223194282 | SHOCK ABSORBER ANCHORAGE |
| 414 | UD5224476036 | TIE ROD UD QUON STEER AXLE |
| 415 | UD5222406557 | U-BOLT |
| 416 | UD55249Z0000 | NUT UBOLT |
| 417 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **21/07/2025** | **R54025337** | | | |
| | | 101 | 34UD | AIR LEAK |
| | | 102 | 34 | AIR LEAK |
| | | 103 | c | CONSUMABLES;CLEANING;EPA |
| | | 104 | n | C: Air leak |
| | | 105 | n | C: EBS valve leaking |
| | | 106 | n | C: r & r valave test for air leaks all ok |
| | | 107 | STAR | ********** |
| | | 108 | UD5224362980 | MODULATOR BRAKE REAR |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **10/12/2024** | **R54023593** | | | |
| | | 101 | 11UD | BELT AND TENSIONER REPLACEMENT |
| | | 102 | 11 | BELT AND TENSIONER REPLACEMENT |
| | | 103 | n | C: Belt replacement |
| | | 104 | n | C: Split belt and noisy tensioner |
| | | 105 | n | C: Lift cabin, remove fan. Remove and replace belt and tensioner. |
| | | 106 | n | Re-fit fan and lower cabin |
| | | 107 | UD5222872933 | BELT FAN-ALT-A/C UD QUON GH8 D8L EURO6 |
| | | 108 | UD5222307251 | BELT TENSIONER FAN UD QUON GH8 D8L EU6 |
| | | 109 | STAR | ********** |
| | | 110 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **01/03/2023** | **R54020157** | | | |
| | | 101 | 01UD | ANNUAL SERVICE |
| | | 102 | 01 | SERVICE LABOUR |
| | | 103 | n | Carry out Annual service as per service schedule. |
| | | 104 | 01UD0001 | RESET VEHICLE SERVICE INTERVAL DISPLAY |
| | | 105 | UD99999FK037 | KIT FILTER BASIC QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| | | 106 | UD5222631101 | FILTER AIR OUTER UD QUON EURO 6 |
| | | 107 | UD5222631115 | FILTER AIR INNER UD QUON EURO 6 |
| | | 108 | UD5223636765 | FILTER AIR DRYER QUON EURO 6 |
| | | 109 | gr | GREASE |
| | | 110 | VTAMP23068344 | OIL ENGINE VDS-4.5 VOLVO 15W-40 20LTR DRUM PER LITRE |
| | | 111 | VTAMP23068343 | OIL ENGINE VDS-4.5 VOLVO 15W-40 5LTR CONTAINER |
| | | 112 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| | | 113 | star | ********** |
| | | 401 | 11TER | TOP END RESET INCLUDING INJECTOR PRELOAD |
| | | 402 | 11 | TOP END RESET INCLUDING INJECTOR PRELOAD |
| | | 403 | STAR | ********** |
| | | 701 | 17UD | COOLANT LEAK |
| | | 702 | 17 | COOLANT LEAK |
| | | 703 | n | C: Coolant leak |
| | | 704 | n | C: Cold coolant leak from bottom radiator hose clamps |
| | | 705 | n | C: Tighten all hose clamps and top up coolant. |
| | | 706 | VTAMP24078863 | COOLANT VCS PREMIX VOLVO 5LTR CONTAINER |
| | | 707 | STAR | ********** |
| | | 708 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **19/06/2024** | **R54022649** | | | |
| | | 101 | 01UD | A SERVICE |
| | | 102 | 01 | A SERVICE |
| | | 103 | n | C: A Service |
| | | 104 | n | C: Due to kms |
| | | 105 | n | C: Carry out A service as per service schedule. |
| | | 106 | gr | GREASE |
| | | 107 | 01UD0001 | RESET VEHICLE SERVICE INTERVAL DISPLAY |
| | | 108 | STAR | ********** |
| | | 401 | 62UD | WIPER BLADES |
| | | 402 | 62 | INSTRUMENTS LABOUR |
| | | 403 | n | C: Wiper blades replacement |
| | | 404 | n | C: Wear |
| | | 405 | n | C: Remove and replace wiper blades. |
| | | 406 | n | Note: Parts supplies on previous invoice. |
| | | 407 | STAR | ********** |
| | | 701 | 62UD | RADIO AERIAL |
| | | 702 | 62 | RADIO AERIAL |
| | | 703 | n | C: Radio dropping out |
| | | 704 | n | C: Faulty aerial |
| | | 705 | n | C: Remove interior panels to gain access. Remove and replace aerial |
| | | 706 | n | and re-fit interior panels. |
| | | 707 | UD2812002Z00 | ANTENNA CONDOR AM/FM RADIO |
| | | 708 | STAR | ********** |
| | | 709 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **10/04/2025** | **R54024405** | | | |
| | | 101 | 01UD | A SERVICE |
| | | 102 | 01 | SERVICE LABOUR |
| | | 103 | n | C: A service |
| | | 104 | n | C: Due |
| | | 105 | n | C: Carry out A service as per service schedule. |
| | | 106 | gr | GREASE |
| | | 107 | STAR | ********** |
| | | 401 | 63UD | TRAY & CLEARANCE LIGHTS |
| | | 402 | T126281CAARKBV | LUCIDITY RED/AMBER |
| | | 403 | STAR | ********** |
| | | 701 | 17UD | REPLACE RADIATOR |
| | | 702 | 17 | REPLACE RADIATOR |
| | | 703 | n | C: Replace radiator |
| | | 704 | n | C: Leaking |
| | | 705 | n | C: Drain coolant. Remove radiator coolant pipes. Remove charge air |
| | | 706 | n | cooler hoses. Remove gearbox cooler hoses. Discharge AC gas, remove |
| | | 707 | n | AC pipes and brackets. Remove AC condenser. Remove radiator mounting |
| | | 708 | n | top and bottom brackets. Remove radiator split Charge Air cooler and |
| | | 709 | n | Radiator. Clean Air cooler and remove and replace radiator torquing |
| | | 710 | n | of bolts of Charge Air cooler done. Fitted radiator back in torquing |
| | | 711 | n | mountings bolts done .ReFitted everthing back in torquing done .Top |
| | | 712 | n | up coolant and Vaccum done for AC lines ,charging of AC gas done .Run |
| | | 713 | n | the Truck and check for any leak ,no leak found all ok and Road test |
| | | 714 | n | done. |
| | | 715 | UD5224307220 | CAP RADIATOR UD QUON GH11 |
| | | 716 | UD5224303869 | RADIATOR QUON GW2646 FRAME 300 GH11 EURO |
| | | 717 | UD2422000Z0H | BAND |
| | | 718 | UD5223960973 | SCREW KIT |
| | | 719 | UD201269Z00C | FLANGE LOCK NUT |
| | | 720 | STAR | ********** |
| | | 721 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **29/08/2025** | **S54020129** | | | |
| | | 102 | 01 | B SERVICE |
| | | 108 | UD99999FK037 | KIT FILTER BASIC UD QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| | | 109 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| | | 110 | N | INCORRECTLY INVOICED TO CASH SALE ACCOUNT |
| | | 402 | 30L | CHECK SHOCK ABSORBERS |
| | | 702 | 52 | CHECK DRIVERS SEAT |
| | | 708 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# |
|---|---|
| 24/03/2026 | R54027178 |

| Line# | Product | Description |
|---|---|---|
| 101 | 01UD | A SERVICE |
| 102 | 01 | A SERVICE |
| 103 | gr | GREASE |
| 104 | n | C:A Service. |
| 105 | n | C:Due |
| 106 | n | C:Carry out service as per CMV service sheet. |
| 107 | STAR | ********** |
| 401 | 34OT | AIR LEAK |
| 402 | 34 | AIR LEAK |
| 403 | n | C:Air leak. |
| 404 | n | C:EBS valve internal fault |
| 405 | n | C:Drain all air in truck. Remove valve. Re fit new valve. Re assemble |
| 406 | n | everything. Start truck. Build air. Check for Air leaks. Check for |
| 407 | n | error codes. Test drive All okay. |
| 408 | c | CONSUMABLES;CLEANING;EPA |
| 409 | STAR | ********** |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **18/04/2024** | **R54022340** | | | |
| | | 101 | 62UD | ENTERTAINMENT UNIT CUTTING OUT |
| | | 102 | 62 | ENTERTAINMENT UNIT CUTTING OUT |
| | | 103 | n | Note: All audio cutting out intermittantly, comes back after a number |
| | | 104 | n | of minutes. |
| | | 105 | n | C: Radio losing screen |
| | | 106 | n | C: Radio fault, not working |
| | | 107 | n | C: Remove and replace radio entertainment unit as required |
| | | 108 | n | op/code: 88000 - 1.5 hrs |
| | | 109 | n | defect: 44 |
| | | 110 | n | causal p/n: 99999HW102 |
| | | 111 | UD99999HW102 | QUON MAIN UNIT |
| | | 112 | STAR | ********** |
| | | 113 | n | claim no: 9101229 |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **02/06/2026** | **R54027620** | | | |
| | | 101 | 01UD | C SERVICE |
| | | 102 | 01 | C SERVICE |
| | | 103 | VDS4 | VGA CAL85121795 ENGINE OIL |
| | | 104 | dextron3 | DEXTRON3 |
| | | 105 | n | C: "C" Service |
| | | 106 | n | C: Due km |
| | | 107 | n | C: Carried out "C" service per service sheet |
| | | 108 | 01UD0001 | RESET VEHICLE SERVICE INTERVAL DISPLAY |
| | | 109 | STAR | ********** |
| | | 110 | UD5223636765 | FILTER AIR DRYER UD QUON EURO 6 |
| | | 111 | UD5222631115 | FILTER AIR INNER UD QUON GH8 & 11 D8-11L EU6 |
| | | 112 | UD5222631101 | FILTER AIR OUTER UD QUON GH8 & 11 D8-11L EU6 |
| | | 113 | VT21743197 | FILTER FUEL TANK BREATHER FH-M V4 B7R |
| | | 114 | UD99999FK037 | KIT FILTER BASIC UD QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| | | 115 | UD48717NY00B | FILTER POWER STEERING UD QUON & CONDOR |
| | | 401 | 11ter | TOP END RESET INCLUDING INJECTOR PRELOAD |
| | | 402 | 11 | TOP END RESET INCLUDING INJECTOR PRELOAD |
| | | 403 | n | C: Top end reset |
| | | 404 | n | C: Due km |
| | | 405 | n | C: Carried out valve tune |
| | | 406 | STAR | ********** |
| | | 1001 | 63OT | R/H REAR STOP TAIL LIGHT NW |
| | | 1002 | 63 | R/H REAR STOP TAIL LIGHT NW |
| | | 1003 | n | C: RH Rear stop tail light not working |
| | | 1004 | n | C: Replace |
| | | 1005 | n | C: Remove and replaced light |
| | | 1006 | STAR | ********** |
| | | 1007 | VT992517 | GLOBE H3 24VOLT 70WATT LONG LIFE |
| | | 1301 | 63UD | NUMBER PLATE LIGHT NOT WORKING |
| | | 1302 | 63 | NUMBER PLATE LIGHT NOT WORKING |
| | | 1303 | n | C: Number plate light not working |
| | | 1304 | n | C: Internal fault |
| | | 1305 | n | C: Remove and replaced number plate light |
| | | 1306 | STAR | ********** |
| | | 1307 | VT982560 | GLOBE 24VOLT 5WATT WEDGE PARKLIGHT FLE FLH |
| | | 1308 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

**RO Date** **RO#**

| Line# | Product | Description |
|---|---|---|
| **17/04/2024** | **R54022232** | |
| 101 | 01UD | C SERVICE |
| 102 | 01 | C SERVICE |
| 103 | n | C: Carry out C service as per service sheet |
| 104 | n | C: Due |
| 105 | n | C: Carry out C service as per service schedule. |
| 106 | 01UD0001 | RESET VEHICLE SERVICE INTERVAL DISPLAY |
| 107 | UD99999FK037 | KIT FILTER BASIC UD QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| 108 | UD5223636765 | FILTER AIR DRYER UD QUON EURO 6 |
| 109 | UD5222631115 | FILTER AIR INNER UD QUON GH8 & 11 D8-11L EU6 |
| 110 | UD5222631101 | FILTER AIR OUTER UD QUON GH8 & 11 D8-11L EU6 |
| 111 | VT21743197 | FILTER FUEL TANK BREATHER FH-M V4 B7R |
| 112 | vds4 | VGA CAL85121795 ENGINE OIL |
| 113 | gr | GREASE |
| 114 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| 115 | star | ********** |
| 401 | 11TER | TOP END RESET INCLUDING INJECTOR PRELOAD |
| 402 | 11 | TOP END RESET INCLUDING INJECTOR PRELOAD |
| 403 | n | C: Top end reset |
| 404 | n | C: Due Kms |
| 405 | n | C: Carry out top end reset |
| 406 | STAR | ********** |
| 701 | 11UD | OIL LEAK |
| 702 | 11 | OIL LEAK |
| 703 | n | C: Oil leak |
| 704 | n | C: Sump gasket leaking |
| 705 | n | C: Remove and wash sump. Remove and replace gasket, install sump and |
| 706 | n | oil filler and dip stick. Tension sump. |
| 707 | UD111129Z00B | SUMP GASKET UD D8L |
| 708 | VT21780376 | SEAL RING TIMING CHEST FRONT D12-DD9A D8-7 |
| 709 | STAR | ********** |
| 1001 | 62UD | WIPER BLADES WORN |
| 1002 | 62 | WIPER BLADES WORN |
| 1003 | n | C: Wiper blades |
| 1004 | n | C: Worn |
| 1005 | n | C: Remove and replace wiper blades. |
| 1006 | UD5223499717 | WIPER BLADE |
| 1007 | STAR | ********** |
| 1008 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **03/01/2024** | **R54021732** | | | |
| | | 101 | 01UD | A SERVICE |
| | | 102 | 01 | A SERVICE |
| | | 103 | n | Carry out A service as per service sheet. |
| | | 104 | n | Note: |
| | | 105 | n | Drivers seat stays down after hitting bumps in road. |
| | | 106 | n | Remove seat base and found HCV stopper catching on base. |
| | | 107 | n | Bend stopper to correct position and test drive - all ok. |
| | | 108 | gr | GREASE |
| | | 109 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| | | 110 | STAR | ********** |
| | | 701 | S3724 | S3724 - UD SOFTWARE CAMPAIGN |
| | | 702 | 02UD | UD CAMPAIGN |
| | | 703 | 02 | CAMPAIGNS LABOUR |
| | | 704 | N | C: S3724 CAMPAIGN |
| | | 705 | N | C: ACCELERATOR PEDAL MALFUNCTION |
| | | 706 | N | C: CARRY OUT SOFTWARE PROGRAMMING AS PER |
| | | 707 | N | CAMPAIGN INSTRUCTIONS. CHECK SOFTWARE |
| | | 708 | N | NUMBER - OK. CLEAR DTCS |
| | | 709 | N | DC 49 |
| | | 710 | N | C/P: 5224273806 |
| | | 711 | N | 17091-3 CAMPAIGN PROGRAMMING |
| | | 712 | N | 17010-2 CONNECT/DISCONNECT TECHTOOL |
| | | 713 | N | TOTAL - 0.5HRS |
| | | 714 | STAR | ********** |
| | | 1001 | 02VO | CAMPAIGN UD - C0217 |
| | | 1002 | 02 | CAMPAIGN UD - C0217 |
| | | 1003 | n | Carry out campaign C0217 |
| | | 1004 | n | op/code: 17010 - .2 hrs |
| | | 1005 | n | op/code: 17054 - .1 hrs |
| | | 1006 | n | op/code: 56100 - .1 hrs |
| | | 1007 | n | defect: 49 |
| | | 1008 | n | caual p/n: 5222771640 |
| | | 1009 | STAR | ********** |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **02/07/2026** | **R54027847** | | | |
| | | 101 | 17UD | REPLACE WATER PUMP |
| | | 102 | 17 | REPLACE WATER PUMP |
| | | 103 | n | C- Replace water pump |
| | | 104 | n | C- Leaking |
| | | 105 | n | C- Removed and replaced water pump following impact procedure |
| | | 106 | STAR | ********** |
| | | 107 | UD210879Z00B | O-RING WATER PUMP |
| | | 108 | VT85022484 | EXC WATER PUMP FE-3 EURO6 D8K |
| | | 109 | VT21752732 | GASKET THERMOSTAT HOUSINF F3-3 D8K |
| | | 110 | VT990821 | O RING EXHAUST MANIFOLD D8-D11 |
| | | 111 | VT994041 | O RING THERMOSTAT HOUSING D8K |
| | | 112 | VTAMP24754665 | COOLANT VCS-2 PREMIX VOLVO 20LTR DRUM PER LITRE |
| | | 113 | VTAMP24754661 | COOLANT VCS-2 PREMIX VOLVO 5LTR CONTAINER |
| | | 114 | VT22707521 | BELT FAN-ALTERNATOR-A/C FE D8K ENGINE |
| | | 115 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# |
|---|---|
| 18/06/2025 | R54025015 |

| Line# | Product | Description |
|---|---|---|
| 101 | 01UD | B SERVICE |
| 102 | 01 | B SERVICE |
| 103 | 01UD0001 | RESET VEHICLE SERVICE INTERVAL DISPLAY |
| 104 | n | C: B Service |
| 105 | n | C: Due KMs |
| 106 | n | C: Carry out B service as per service sheet |
| 107 | STAR | ********** |
| 108 | UD99999FK037 | KIT FILTER BASIC UD QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| 109 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| 401 | 30UD | CHECK SHOCK ABSORBERS |
| 402 | 30L | CHECK SHOCK ABSORBERS |
| 403 | n | C: Check steer shockers |
| 404 | n | C: Requsted |
| 405 | n | C: Remove all steer  lower shocker bolts, checked operation. all |
| 406 | n | good, refit shocker bolts and tensioned to specs. |
| 407 | STAR | ********** |
| 701 | 52UD | CHECK DRIVERS SEAT |
| 702 | 52 | CHECK DRIVERS SEAT |
| 703 | n | C: Inspect driver seat |
| 704 | n | C: Broken seat shock and bent frame |
| 705 | n | C: Remove seat base and inspect, Broken seat shock and bent frame. |
| 706 | n | new seat to be ordered |
| 707 | STAR | ********** |
| 708 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **03/09/2024** | **R54023054** | | | |
| | | 101 | 01OT | A SERVICE |
| | | 102 | 01 | A SERVICE |
| | | 103 | n | C: A service |
| | | 104 | n | C: Due/kms |
| | | 105 | n | C: Carry out A service as per service schedule. |
| | | 106 | vds4 | VGA CAL85121795 ENGINE OIL |
| | | 107 | gr | GREASE |
| | | 108 | STAR | ********** |
| | | 109 | n | RADIO CUTTING OUT - INTERMITTANT |
| | | 110 | n | Test unit, couldn't get to fault. |
| | | 111 | STAR | ********** |
| | | 112 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **24/06/2025** | **R54025068** | | | |
| | | 101 | 52UD | REPLACE DRIVERS SEAT |
| | | 102 | 52 | REPLACE DRIVERS SEAT |
| | | 103 | n | C: Replace driver's seat |
| | | 104 | n | C: Shock absorber mount broken and seat frame bent internally |
| | | 105 | n | C: Disconnect & airline,electrical plugs, remove seat pannels and |
| | | 106 | n | seat cover .Remove the faulty seat and replace as required tension |
| | | 107 | n | mounting bolts to spec. fit back the airline,electrical plugs,seat |
| | | 108 | n | pannels/ cover. Test operation all ok |
| | | 109 | UD5223564858 | SEAT |
| | | 110 | N | APPLIED FOR GOODWILL RECIVED 40% |
| | | 111 | STAR | ********** |
| | | 401 | 52UD | INTERIOR SEATS UD - RECEIVED 40% SEAT ONLY |
| | | 402 | STAR | ********** |
| | | 403 | UD5223564858 | SEAT |
| | | 404 | N | C: Replace driver's seat |
| | | 405 | N | C: Shock absorber mount broken and seat frame bent internally |
| | | 406 | N | C: Disconnect airline, electrical plugs, remove seat panels and seat |
| | | 407 | N | cover. Remove the faulty seat and replace as required tension |
| | | 408 | N | mounting bolts to spec. fit back the airline, electrical plugs, seat |
| | | 409 | N | panels/ cover. Test operation, all ok |
| | | 410 | N | 85224 |
| | | 411 | N | C/P: 5223564858 |
| | | 412 | N | DEF CODE: 82 |
| | | 413 | N | CLAIM NR: 9104898/1 |
| | | 414 | N | GRT: 19769 |

# Repair Order History

| | | | | | |
|---|---|---|---|---|---|
| **Stock#:** | 603184 | **Rego:** | XV41ZI | **VIN:** | JNCMBM0G1MU061284 |
| **Model:** | CG30360VAA | **Body:** | | **Color:** | |

| RO Date | RO# |
|---|---|

| Line# | Product | Description |
|---|---|---|
| **01/03/2024** | **R54022091** | |
| 101 | 01UD | A SERVICE |
| 102 | 01 | A SERVICE |
| 103 | n | C: Service |
| 104 | n | C: Age/kms |
| 105 | n | C: Carry out A service as per service schedule. |
| 106 | vds4 | VGA CAL85121795 ENGINE OIL |
| 107 | gr | GREASE |
| 108 | VTWUR0892333 | WINDSCREEN WASHER ADDITIVE ONE SHOT |
| 109 | STAR | ********** |
| 110 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **27/09/2023** | **R54021268** | | | |
| | | 101 | 01OT | B SERVICE |
| | | 102 | 01 | B SERVICE |
| | | 103 | n | Carry out B service as per service schedule. |
| | | 104 | UD99999FK037 | KIT FILTER BASIC UD QUON 8LTR GH8 NEW GEN EU6 D8L UD |
| | | 105 | vds4 | VGA CAL85121795 ENGINE OIL |
| | | 106 | VTAMP24078863 | COOLANT VCS-2 PREMIX VOLVO 5LTR CONTAINER |
| | | 107 | gr | GREASE |
| | | 109 | STAR | ********** |
| | | 701 | 61UD | CARRY OUT MULTIPLE SOFTWARE UPDATES AS REQUIRED |
| | | 702 | 61 | CARRY OUT MULTIPLE SOFTWARE UPDATES AS REQUIRED |
| | | 703 | STAR | ********** |
| | | 704 | c | CONSUMABLES;CLEANING;EPA |

# Repair Order History

**Stock#:** 603184 **Rego:** XV41ZI **VIN:** JNCMBM0G1MU061284

**Model:** CG30360VAA **Body:** **Color:**

| RO Date | RO# | Line# | Product | Description |
|---|---|---|---|---|
| **11/02/2025** | **R54023882** | | | |
| | | 101 | 01UD | A SERVICE |
| | | 102 | 01 | A SERVICE |
| | | 103 | n | C: A service |
| | | 104 | n | C: Due kms |
| | | 105 | n | C: Carry out A service as per service schedule. |
| | | 106 | gr | GREASE |
| | | 401 | 63UD | BEACON LIGHTS WORKING INTERMITTENTLY |
| | | 402 | 63 | BEACON LIGHTS WORKING INTERMITTENTLY |
| | | 403 | n | C: Beacon lights not working |
| | | 404 | n | C: Faulty wiring |
| | | 405 | n | C: Test switch and wiring found corroded deutsch plug at front of |
| | | 406 | n | tray body. Cut out plug and hard wire lights and test operation, all |
| | | 407 | n | ok |
| | | 408 | STAR | ********** |
| | | 409 | c | CONSUMABLES;CLEANING;EPA |