South Central Trucks Pty Ltd
PO Box 369
Enfield Plaza SA 5085

ARC Number: AU12722

SOUTH CENTRAL TRUCK & BUS

South Central Trucks Pty Ltd ABN 29 007 726 043

Telephone: 08 8360 4400
Freecall: 1800 627 718
eMail: info@sctb.com.au
Website: www.sctb.com.au

**TAX INVOICE 704507** Date: **30/08/2025** Rego: **XS47DG** 

Charge to: **453250**
**Hispec Heavy Haulage Pty Ltd**
PO Box 147
PARA HILLS SA 5096

ABN: **26 642 089 398**

Customer: **453250**
**Hispec Heavy Haulage Pty Ltd**
PO Box 147
PARA HILLS SA 5096

Phone 08 8252 7075 Mobile
Contact: **Lisa Hughes or Graeme Swan - 0437 816 808**

| | | | | | |
|---|---|---|---|---|---|
| Order No: | **XS47DG** | Next Service Date: | **00/00/0000** | Next Service Kms: | **10,000,000** |
| Service Adviser: | **SS** | Odometer reading: | **245875** | Warranty Start Date: | **16/11/2020** |
| VIN | **YV5RP90D3LD211273** | Last Clocking Date: | **28/08/2025** | Repair Order: | **R159894** |
| Stock Number | **20047116** | Fleet No. | | Engine hours | **4,209** |
| Model | | | | Delivery Date: | **16/11/2020** |

***** RECOMMENDATIONS *****

AS PER OSP
30,000KM BASIC SERVICE INTERVAL
180,000KM DRIVELINE OIL CHANGE
***(synthetic)***
Engine oil VDS-4
Gearbox oil Alternative (97315)
Rear axle oil Alternative (97312)

| Product | Description | Quantity | Price Excl. |
|---|---|---|---|
| **ANNUAL SERVICE AS PER VOSP** | | | |
| | 17746-2 Annual service<br>25627-3 Filter insert, air cleaner, replace. Only valid for primary filter<br>25625-3 Secondary air filter, replace. Air filter insert removed<br>32204-3 Charging regulator, replace<br>26010-2 Coolant, replace<br>23306-3 Fuel filter, replace (one)<br>17513-2 Engine, oil and filter, replace. Lube area<br>23311-3 Filter, water separator, replace<br>23414-3 Filter for fuel tank ventilation, replace<br>21413-2 Valves and unit injectors, adjust<br>56166-3 Air drier cassett, replace<br>25822-2 Pump filter, AdBlue, replace<br>87210-3 Air and ventilation filters, air conditioning, replace. All<br>17511-2 Fifth wheel, lubrication<br>carried out annual service. checked all oil levels. checked and lubricated fifth wheel. changed engine oil, oil and fuel filters. performed laptop checks. changed air con filters. changed both fuel vent filters. changed both air cleaners. calibrated air drier. changed charging regulator. performed all checks. washed and checked over after road test. | | |
| *1L* | LABOUR ANNUAL SERVICE AS PER VOSP | | 1,080.00 |
| *EO* | ENGINE OIL | 42 | 352.80 |
| *c* | CONSUMABLES/ENVIROMENT LEVY | 1 | 100.00 |
| *gr* | NLGI GREASE | 1.5 | 19.50 |
| *VT21716424* | AIR FILTER | 1 | 235.56 |
| *VT23429024* | AIR FILTER | 1 | 247.34 |

Continued ...

VOLVO UD TRUCKS MACK

| | | | |
|---|---|---|---|
| *VT21579977* | CHARGE REGULATOR | 1 | 246.57 |
| *VTAMP24078864* | COOLANT VCS 20LTR | 40 | 270.40 |
| *VT24122024* | SERVICE KIT OIL,FUEL | 1 | 253.19 |
| *VT21743197* | AIR CLEANER FUEL | 2 | 88.42 |
| *VT23690622* | KIT AIR DRIER CARTRIDGE | 1 | 165.76 |
| *VT23381562* | FILTER ADBLUE | 1 | 135.86 |
| *VT84813190* | AIR FILTER | 1 | 40.91 |
| *VT23515329* | VENTILATION FILTER | 1 | 40.91 |
| | ********** | | |
| | | Sub Total: | 3,277.22 |

**VALVE SET ADJUSTMENTS**

| | | | |
|---|---|---|---|
| | carried out valve and unit injector adjustment(done) | | |
| *2L* | LABOUR VALVE SET ADJUSTMENTS | | 720.00 |
| | ********** | | |
| | | Sub Total: | 720.00 |

**ENGINE LIGHT COMES ON**

| | | | |
|---|---|---|---|
| | connected computer to truck proceeded to carry out multiple adblue tests including, pressure test, and dosage test all test passed checked adblue pump filter and replaced due to being damaged applied pressure to adlue pick up filter and popped which means filter is blocked started to remove adblue tank flushed adbue tank too drain all the corrosion out of tank. installed new adblue pick up filter reinstalled adblue tank filled adblue tank with 245L of adblue washed truck checked over truck all was ok checked and cleared fault codes | | |
| *2L* | LABOUR ENGINE LIGHT COMES ON | | 900.00 |
| *VT20744599* | CONNECTOR,5/16 | 1 | 14.93 |
| *VTWUR05392812* | HOSECLMP-FUEL-B9MM | 1 | 1.64 |
| *VT22406383* | ADBLUE FILTER-'TEA BAG' STYLE | 1 | 58.79 |
| *VT980464* | HOLD DOWN STRAP | 5 | 5.65 |
| *VT20428158* | Cable Tie 7mm x 370mm Chassis | 10 | 39.60 |
| *VT21954674* | STRAINER | 1 | 27.13 |
| *VT20428158* | Cable Tie 7mm x 370mm Chassis | 7 | 27.72 |
| *2AECOBLUE* | ADBLUE PER LITRE | 154 | 246.40 |
| | ********** | | |
| | | Sub Total: | 1,321.86 |

**2 LED LIGHTS ON THE FRONT FLASHING 1 LIGHT IS OFF**

| | | | |
|---|---|---|---|
| | truck did not re-create fault | | |
| | ********** | | |
| | | Sub Total: | 0.00 |

**CABIN SHOCK ABSORBER ISWEEPING-QUOTE FIRST**

| | | | |
|---|---|---|---|
| | Cab shockers are still in good condition, not leaking | | |
| *8L* | LABOUR CABIN SHOCK ABSORBER ISWEEPING | | 72.00 |
| | ********** | | |
| | | Sub Total: | 72.00 |

**AIR COMPRESSOR IS WEEPING AT THE TOP -QUOTE FIRST**

disconnected coolant lines and air intake piping before removing mounting bolts of compressor and separating compressor head off.

Continued ...

VOLVO UD TRUCKS MACK

| | | | |
|---|---|---|---|
| | Cleaned off leakage and roughed up surface before installing new head & gasket. Torque all bolts to manufacturer specifications and installed fittings for coolants hoses and intake piping. Started truck and everything worked fine. Came back all good from road test | | |
| *2L* | LABOUR AIR COMPRESSOR IS WEEPING AT THE TOP | | 720.00 |
| *VT22203109* | REPAIR KIT | 1 | 1,620.73 |
| *VT471708* | SEALING RING | 1 | 7.10 |
| *VT23413384* | CONNECTOR | 1 | 37.53 |
| | ********** | | |
| | | Sub Total: | 2,385.36 |

**WINDSCREEN RESERVIOR HAS THE LEVEL SENSOR OUT**

| | | | |
|---|---|---|---|
| | Put sensor back in and sealed the sensor with silicone to avoid leakage in the future | | |
| | ********** | | |
| | | Sub Total: | 0.00 |

**RHS FUEL TANK CLEANANCE LIGHT OUT**

| | | | |
|---|---|---|---|
| | customer didn't want job to be done | | |
| | ********** | | |
| | | Sub Total: | 0.00 |

**FIFTH WHEEL LOCK CABLE MISSING**

| | | | |
|---|---|---|---|
| | Installed new handle on and works fine | | |
| *4L* | LABOUR FIFTH WHEEL LOCK CABLE MISSING | | 108.00 |
| *NGSK352102* | RELEASE CABLE | 1 | 15.00 |
| | ********** | | |
| | | Sub Total: | 123.00 |

**POWER STEERING HOSE ON LHS REAR TANK WEEPING**

| | | | |
|---|---|---|---|
| | Removed old hose and fitting that connect to power steering hose to pump. Installed new one with new connecting fitting and tightened all brackets back to spec and zip tied any loose cable. Tightened banjo bolt back up. Bleed system and top it up to spec level. Check over after road test and everything was all good. | | |
| *6L* | LABOUR POWER STEERING HOSE ON LHS REAR TANK WEEPING | | 720.00 |
| *VT23478792* | SERVO PIPE | 1 | 168.45 |
| *VT23044511* | FUEL FILTER | 1 | 88.90 |
| | ********** | | |
| | | Sub Total: | 977.35 |

**REPLACE WHEEL NUT CAP MISSING**

| | | | |
|---|---|---|---|
| | Installed 3 wheel nut covers | | |
| *4L* | LABOUR REPLACE WHEEL NUT CAP MISSING. | | 90.00 |
| | ********** | | |
| | | Sub Total: | 90.00 |

Continued ...

Parts: $4,084.49 Labour: $4,410.00 Others: $472.30

| | |
|---|---|
| Sub Total: | $ 8,966.79 |
| Total GST: | $ 896.68 |
| **INVOICE TOTAL** | **9,863.47** |

** 24 MONTHS/500,000km WARRANTY ON FITTED PARTS**
When our workshop installs genuine parts to your
Mack UD or Volvo Truck. You recieve
24 months / 500,000km warranty
This includes parts & labour How's that for uptime value
**Please check terms & conditions

Payment by EFT: BSB: 065 000
Account #: 1208 0520
Reference: 704507
Please email deposit details to
accounts@southcentraltrucks.com.au

For terms and conditions see last page

VOLVO UD TRUCKS MACK