1L	LABOUR CARRY OUT ANNUAL SERVICE AS PER THE VOSP		1,200.00
VT24122024	SERVICE KIT OIL,FUEL	1	272.11
VT21743197	AIR CLEANER FUEL	2	110.84
VT84813190	AIR FILTER	1	77.85
VT23515329	VENTILATION FILTER	1	70.71
VT24623238	KIT AIR DRIER CARTRIDGE	1	200.77
VT24283117	SERVICE KIT, TRANS	1	63.03
VT21579977	CHARGE REGULATOR	1	309.09
VT21716424	AIR FILTER	1	253.16
VT23429024	AIR FILTER	1	265.82
VT23381562	FILTER ADBLUE	1	164.65
EO	ENGINE OIL	42	457.80
GO	GEARBOX OIL SAE50	17	151.30
DO	DIFF OIL 85/140	38	311.60
C	CONSUMABLES/ENVIROMENT LEVY	1	100.00
GR	NLGI GREASE	1.5	19.50
	**********		
		Sub Total:	4,028.23

TRUCK IS DERATING AND HAS AD BLUE ISSUE

Complaint- truck is derating and has ad blue issue
Cause- dirty adblue filter (inside tank)
adblue pump not build up pressure
dirty adblue filter (breather filter)
Correction- connected laptop. read fault code. carried out adblue pressure test found pump not building up pressure. checked filter found dirty(inside on tank and breather filter). removed all hoses on adblue tank. lifted up the truck. removed tank out. washed adblue tank. fitted back the tank with new filter. fitted back all hoses connected to tank. removed and replaced adblue pump. replaced filter breather. refilled adblue. clear fault code. road tested, checked over. no fault active.
note; active fault on battery sensor (tried to calibrate but still active the fault, driver took the truck)
---------- please let customer know not all jobs were completed ---------- 5, 12, 13, 14 ,15 , 16, 17 job lines not done due to not having time, customer took truck knowing all the faults
---

1L	LABOUR TRUCK IS DERATING AND HAS AD BLUE ISSUE		800.00
VT85031170	EXCH, PUMP UNIT	1	2,263.73
2AECOBLUE	ADBLUE PER LITRE	89	142.40
VT3944785	FILTER AIR COMP/ADBLUE/FUEL BREATHER FH-M	1	106.35
VT24911045	ADBLUE FILTER-'TEA BAG' STYLE	1	133.59
	**********		
		Sub Total:	3,446.07

CHECKED THE BATTERY TERMINALS

Complaint: checked the battery terminals
Cause: wrong terminal used on the battery
Correction: removed and battery cover and inspected the fault found wrong terminals used on one of ther battery terminals we didnt have

Continued ...

VOLVO UD TRUCKS MACK

the correct part in stock and truck ha
to go and get from different source please advise
****

Sub Total:

CARRY OUT VALVE SET

	21413-2 Valves and unit injectors, adjust		
	Carry out valve adjustment,		
	Removed rocker cover and carry out		
	adjustment as per specifications,		
	Checked and refit rocker cover,		
	LABOUR CARRY OUT VALVE SET		800.00
1L	**********		
	Sub Total:		800.00

CARRY OUT BELTS AND TENSIONERS

	32130-2 Belt tensioner, alternator, replace		
	32123-3 Alternator drive belt, replace		
	26307-3 Drive belt fan, replace		600.00
	26308-3 Fan belt tensioner, replace		65.53
	26375-2 Fan belt idler pulley, replace	1	392.93
	LABOUR CARRY OUT BELTS AND TENSIONERS	1	4.18
1L	V-RIBBED BELT	2	393.08
VT24636033	BELT TENSIONER	1	381.79
VT23669027	FLANGE SCREW 10X30	1	109.08
VT990861	IDLER PULLEY	1	6.00
VT21753149	BELT TENSIONER	10	
VT21631484	V-RIBBED BELT		
VT24635967	SUPPORT STRAP		
VT948211	**********		
	Sub Total:		1,952.59

RUNNING HOT UNDER LOAD

	Complaint: running hot under load		
	Cause: engine fan wiring rubbed through and short circuit.		
	Correction: connected techtool and found an active fault code for		
	engine fan short circuit cabbed over truck and inspected the engine		
	fan and found the wiring had been rubbed and caused it to short		
	circuit drained coolant removed engine support bracket, thermost		
	mousing, header tank, coolant lines, electrical lines to get room for		
	engine fan to come out removed engine fan and fitted new engine fan		
	fitted all part back and secured all wiring checked work all ok		
	filled back coolant and recheck all work all ok started truck and		
	left it running and rechecked for leaks and all ook		600.00
	LABOUR RUNNING HOT UNDER LOAD	1	2,720.22
2L	FAN	10	6.00
VT24017083	SUPPORT STRAP		
VT948211	**********		
	Sub Total:		3,326.22

CARRY OUT TURBO REPLACEMENT

25518-2 Engine turbocharger, replace

Continued ...

VOLVO UD TRUCKS MACK