014-4
NOV

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 26022
Date: 09/08/2026

Completed Date: 09/09/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 09/08/2026
Entered By: Ashley

Labor

Category	Description	Technician Notes	Mechanic	Amount
ORDER PARTS / SUBLET	hose clamp with spring	Gregg 057-389621 (PO 182427)		.00
DVIR	DVIR 9/9 Tony Service, glad hand need replacing.	resolved by raimand 9/9		.00
Shop Inspection Check / A...	coolant leak	Resolved 9/8		.00
Labor -Jones Journeyman	TASK #	Supervise and advise on repairs	Randy Donaldson	40.53
Labor - Jones Apprentice	TASK #	Wash out 5-gallon buckets x3. Drain coolant out of system.	Daniel Massner	61.05
Labor - Jones Apprentice	TASK #	Removed down pipe/removed 2.50" hose/order parts. Look for parts/charge out parts.	Daniel Massner	15.26
Labor - Jones Apprentice	TASK #	Grind down pipe ends/install new hose boot/install new pressure clamp. Spray soap water to clean area x2. Fill back up with coolant. Pressure test/move unit out/run up to temp. Re-torqued clamps down after unit got to temp. Let cool/top up coolant. Fill out paperwork. Re-torque clamp again/wipe down.	Daniel Massner	122.10
Labor - Jones Apprentice	TASK #	Truck blue gladhand replaced	Raimand Noronha	15.26

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
38-1326, Clamp 2 1/4 X 3 1/8		2.00	8.70	17.40
81-0001-B, Brake Glad Hand - Blue		1.00	3.86	3.86

Total Labor	254.20
Total Parts	21.26
Total Returns	.00
Total Sublet	.00
Shop Supplies	25.42
Invoice Total	300.88

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 25965
Date: 08/27/2026

Completed Date: 08/27/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 08/27/2026
Entered By: Valerie

Labor

Category	Description	Technician Notes	Mechanic	Amount
DVIR	DVIR 08/24 Antonio - Antifreeze leak	Resolved by Daniel 08/27		.00
DVIR	DVIR 08/27 Antonio - Trailer cord on truck requires attention. Short in left signal when wiggling cord -- shim wasn't put in last time.	Resolved by Daniel 08/27		.00
Labor - Jones Apprentice	TASK #	replace 7-way, tighten clamp	Daniel Massner	45.79

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
15-730, Male 7 Wire Plug		1.00	12.19	12.19

Total Labor	45.79
Total Parts	12.19
Total Returns	.00
Total Sublet	.00
Shop Supplies	4.58
Invoice Total	62.56

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 25811
Date: 08/01/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 08/01/2026
Entered By: Valerie

Labor

Category	Description	Technician Notes	Mechanic	Amount
DVIR	DVIR 07/27 Antonio - Engine, making same sound as before. When speeding up like the Jake, is on at the end of each shift.	Resolved by DGN 08/14		.00
DVIR	DVIR 07/31 Antonio - Fifth, wheel will not stay disengaged sometimes when unhooking from trailers	Resolved by Daniel 08/18		.00
ORDER PARTS / SUBLET	pressure relief valve, pressure relief seal	Kenworth 02NP983970		.00
DVIR	DVIR 08/19 Antonio - Truck shakes when using Jake with a load on	not resolved. added to excel.		.00
Labor - Jones Apprentice	TASK #	Adjust 5th wheel/inspect	Daniel Massner	15.26
ORDER PARTS / SUBLET	Repairs to jake brake — Ghulam to advise if we will see an invoice from DGN or not	DGN		.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP983970 Supplier: Edmonton Kenworth Ltd.	VALVE PRESSURE RELIEF, SEAL-PRESURE RELIEF PX8	1.00	709.64	709.64

Total Labor	15.26
Total Parts	.00
Total Returns	.00
Total Sublet	709.64
Shop Supplies	72.49
Invoice Total	797.39

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 25766
Date: 07/22/2026

Completed Date: 07/31/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 07/22/2026
Entered By: Valerie

Labor

Category	Description	Technician Notes	Mechanic	Amount
Shop Inspection Check / A...	07/22 - Service Due	Resolved by Daniel 07/23		.00
DVIR	DVIR 07/22 Tony - Fifth wheel needs to be rebuilt. Jaws will not stay open when trying to unhook	Resolved by Daniel 07/24		.00
DVIR	DVIR 07/22 Tony - Hose on Turbo, rubbing through	Resolved by Daniel 07/24		.00
ORDER PARTS / SUBLET	5th wheel rebuild kit	SIF 001-261516		.00
ORDER PARTS / SUBLET	fan hub/clutch assembly + CORE charge	SIF 001-261643		.00
ORDER PARTS / SUBLET	CORE return credit	SIF 001-262301 (Credit)		.00
Labor - Jones Apprentice	TASK #	Shop helper for Daniel fifth wheel	Adam Veinot	61.05
Labor - Jones Apprentice	TASK #	Shop helper for Daniel fifth wheel	Adam Veinot	30.53
Labor - Jones Apprentice	TASK #	Shop helper for Daniel	Adam Veinot	30.53
Labor - Jones Apprentice	TASK #	Shop helper Daniel	Adam Veinot	15.26
Labor - Jones Apprentice	TASK #	Shop helper for Daniel	Adam Veinot	45.79
Labor - Jones Apprentice	TASK #	Full service - PM. Order parts/charge parts	Daniel Massner	106.84
Labor - Jones Apprentice	TASK #	Finish full service/PM. Rebuilt/replaced intake hose. Fix coolant leak. Start removing 5th wheel. Take out 5th wheel components	Daniel Massner	122.10
Labor - Jones Apprentice	TASK #	Continue to remove parts. Wash down/clean up 5th wheel. Start installing components onto 5th wheel	Daniel Massner	91.58
Labor - Jones Apprentice	TASK #	Finish rebuild on 5th wheel/install	Daniel Massner	91.58
Labor - Jones Apprentice	TASK #	Shop helper Daniel - fan clutch.	Adam Veinot	30.53
Labor - Jones Apprentice	TASK #	Shop helper Daniel - fan clutch.	Adam Veinot	30.53
Labor - Jones Apprentice	TASK #	Adjust 5th wheel/get second opinion/clean LP tools/work area/treas. Test 5th wheel on trailer in yard. Move unit into middle bay. Drain oil catcher. Start to drain coolant.	Daniel Massner	106.84
Labor - Jones Apprentice	TASK #	Continue to remove components to remove fan hub/clutch. Order parts.	Daniel Massner	106.84
Labor - Jones Apprentice	TASK #	Fight to install new fan hub/clutch.	Daniel Massner	76.31
Labor - Jones Apprentice	TASK #	Start putting on components.	Daniel Massner	76.31
Labor - Jones Apprentice	TASK #	Finish putting all parts/components back on. Fill with coolant. Drill holes/empty J-box. Bolt down J-box. Put all stuff back in. Air up/test. Move unit back in line, up on high idle. Top up coolant.	Daniel Massner	137.36
ORDER PARTS / SUBLET	rad rods x2 (used)	Red Ram 2613303		.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
HE8716, Engine Air To Air hose		1.00	40.26	40.26
BF46129, Filters		1.00	55.83	55.83
BD50000, High Efficiency Dual-Flow		1.00	42.72	42.72

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 001-261516 Supplier: SIF Superiors Industrial Frictions Ltd.	Rebuild Kit LH	1.00	492.33	492.33
	Invoice: 001-261643 Supplier: SIF Superiors Industrial Frictions Ltd.	2 SPEED CUMMINS FAN CLUTCH	1.00	1,346.29	1,346.29
	Invoice: 001-261643 Supplier: SIF Superiors Industrial Frictions Ltd.	core	1.00	700.00	700.00
	Invoice: 001-262301 Supplier: SIF Superiors Industrial Frictions Ltd.	core return	1.00	-700.00	-700.00
	Invoice: 2613303 Supplier: Red Ram	Rad Rods used	1.00	400.00	400.00

Total Labor	1,159.98
Total Parts	138.81
Total Returns	.00
Total Sublet	2,238.62
Shop Supplies	339.86
Invoice Total	3,877.27

JONES
TRANSPORTATION INC.

Date: JULY 23/2026
Unit # 9107
Odometer Reading: 1338227
Hour Reading: 26985.2
Work Order # 25766
(Full Service)

✓ CHECKED & OK
/ ADJUSTED
✓ REPAIR or REPLACEMENT REQUIRED
X REPAIRED, REPLACED or COMPLETED

Service interval as per Manufacturer's Specification

TRUCK / TRACTOR

	BODY & FRAME	▲	★
✓	Body		1
✓	Frame & Cargo Body	11	3
✓	Bumpers		1
✓	Cab	2	
	Coupling Devices	4	
✓	Door Releases/Latches		1
✓	Doors		1
✓	Drive Shaft		6
✓	Driver Controls	6	
✓	Driver Seat	7	
✓	Emergency Equipment & SafetyDevices	9	
✓	Fenders		1
X	Fifth Wheel & Coupling Devices	4	31
✓	General	13	23
✓	Heater & Defroster	15	25
✓	Horn	16	
✓	Mirrors	14	7
✓	Mudflaps		1
✓	Sun Visors		1
✓	Underbody		5

✓	Windshield & Windows	14	7
✓	Windshield Wipers & Washer	23	24
	BRAKES		
✓	Air Brake System	1	14
✓	Brake Pedal		13
	Electric Hydraulic Brake System N/A		16
✓	Mechanical Components		12
✓	Parking/Emergency Brake		15
	ELECTRICAL COMPONENTS		
✓	Lamps & Reflectors	18	27
	Neutral Safety Starting Switch		26
	STEERING		
✓	Steering Column & Box		18
✓	Steering Linkage		21
✓	Power Assist	19	
✓	Wheel Alignment (Visual)		19
	FUEL & EXHAUST		
✓	Exhaust System	10	9
✓	Filler Cap & Fuel Lines		8
✓	Fuel System	12	8
✓	Fuel Tank		8

	SERVICE		
X	Complete Lubrication		30
X	Oil Change		
✓	Check/Replace Air Filters		
✓	Check Diff Oil		
✓	Check Trans Oil		
✓	Check Power Steering Fluid		
✓	Check Front Hub Oil		
	SUSPENSION		
✓	Suspension System	20	22
✓	Shock Absorber Condition	20	22
OK	Spring Condition	20	22
	WHEELS & TIRES		
✓	Tires	21	28
	Torqued Fasteners	22	29
	Wheels, Hubs, Fasteners	22	29
	OTHER		
✓	Cargo Securement	3	
	Dangerous Goods N/A	5	

★ **Inspected Per AR 121/2009 Schedule 2 Section # (as shown above ★)**

▲ **Inspected Per NSC Standard 13, Part 2, Schedule 1, # (as shown above ▲)**

Notes: 5th wheel out of Spec, Fan Hub Leaking Air, Hose on Hood Rubbing through, Small Coolant Leak, J-Box Loose

Rev 12.18

Signature: _____

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 25602
Date: 06/18/2026

Completed Date: 07/03/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 06/18/2026
Entered By: Valerie

Labor

Category	Description	Technician Notes	Mechanic	Amount
DVIR	DVIR 05/29 Antonio - A/C not working properly.	Resolved Jul 6, 10:11 AM by Antonio Sousa. Moved from 25515		.00
DVIR	DVIR 06/17 Antonio - Power steering binding when turning in low speeds	Resolved by DGN 07/03		.00
DVIR	DVIR 06/17 Antonio - Jake kicking in at higher gears when picking up speed.	Resolved by DGN 07/03		.00
ORDER PARTS / SUBLET	A/C Condensor	ABS Truck 322868		.00
ORDER PARTS / SUBLET	New cummins injectors, cleaning and testing of old ones	Sunset Diesel 39462		.00
ORDER PARTS / SUBLET	Camshaft	DGN VIN2122227		.00
ORDER PARTS / SUBLET	gaskets, seals, gear cover, lever/rocker	Kenworth 02NP972877		.00
ORDER PARTS / SUBLET	oil seal, damper	Kenworth 02NP973518		.00
ORDER PARTS / SUBLET	lever rockers	Kenworth 02NP973756		.00
DVIR	DVIR 07/08 Antonio - Low voltage	Resolved by Ghulam 07/08		.00
ORDER PARTS / SUBLET	repairs to power steering and jake brake	DGN 2122243		.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 322868 Supplier: ABS Truck and Trailer Parts	condensor	1.00	225.00	225.00
	Invoice: 02NP972877 Supplier: Edmonton Kenworth Ltd.	SEAL O-RINGx2, SEAL, RECTANGULAR RING, LEVER,ROCKER, PLUG GEAR COVER, SEAL, RECTANGULAR STRIP, GASKET, CAMSHAFT COVE	1.00	432.60	432.60
	Invoice: 39462 Supplier: Sunset Diesel Services Ltd	Clean and test 6 Cummins ISX injectors. (2872405) Clean and test six injectors. Injectors #1, #4 & #5 are OK to reuse. The other three fail [flow out of spec]. Go over results with customer. Exchange all six injectors.	1.00	6,606.78	6,606.78
	Invoice: 02NP973518 Supplier: Edmonton Kenworth Ltd.	oil seal, damper viscous vibration	1.00	1,540.96	1,540.96
	Invoice: 02NP973756 Supplier: Edmonton Kenworth Ltd.	LEVER,ROCKER, SHAFT LEVER ROCKER x2	1.00	1,139.25	1,139.25
	Invoice: VIN 2122227 Supplier: DGN Truck & Trailer Repair Ltd.	Camshaft part	1.00	1,364.00	1,364.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: VIN 2122243 Supplier: DGN Truck & Trailer Repair Ltd.	Engine BRIG IN UNIT.CHECKED AND FOUND FUEL LEAKAGE CODES. STARTED T/S DID FUEL RESTRICTION TEST. FOUN D INJECTORS LEAKING AND TEST IS GETTING ABORTED.TALKED TO THE CUSTOMER.SEND OUT INJECTORS FOR TESTING. GOT NEW INJCTORS. INSTALLED WITH NEW TUBES. DID TRIM CODE INSTALLATION. Engine WHILE WORKING ON THE INJECTORS FOUND CAM PITTEDA ND ALSO SOME OF THE ROCKERS ROLLERS TOO.TALKED TO THE CUSTOMER. ORDERED NEW CAM SHAFT. REMOVED THE RAD ASSMBLY.REMOVED THE FRONT COVER. FOUND FRONT CRANK SEAL LEAKING ALSO.REMOVED THE ROCKERS. POLISH ...	1.00	1,560.00	1,560.00

Total Labor	.00
Total Parts	.00
Total Returns	.00
Total Sublet	12,868.59
Shop Supplies	1,286.86
Invoice Total	14,155.45

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 25485
Date: 05/25/2026

Completed Date: 05/28/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 05/25/2026
Entered By: Valerie

Labor

Category	Description	Technician Notes	Mechanic	Amount
DVIR	DVIR 05/25 Antonio - Drivers side front wheel leaking	Resolved by Daniel 05/27		.00
DVIR	DVIR 05/25 Antonio - Air leak, Losing air	Resolved by Daniel 05/27		.00
RE-TORQUE REQUIRED	D/S 1st axle			.00
RE-TORQUE COMPLETED		Resolved by Raimond 05/28		.00
Labor - Jones Apprentice	TASK #	Air up / move unit back / jack up axle / removed wheel / back off brakes / removed brake pads / removed caliper all seized up / removed hub	Daniel Massner	61.05
Labor - Jones Apprentice	TASK #	Remaining primary & secondary air tanks off 9105 for 9107	Daniel Massner	122.10
Labor -Jones Journeyman	TASK #	Discuss repairs with mechanic - for time line and extent of job requirements in order to maintain hire line	Randy Donaldson	20.26
Labor - Jones Apprentice	TASK #	Removed wheel seal. Inspect spindle, bearings, races. Wash hub, grind down seal surfaces. Look for parts	Daniel Massner	61.05
Labor - Jones Apprentice	TASK #	Install seal, bearings. Set seal, bearings. Order parts. Install caliper pads. Torqued caliper bolts to 475. Put wheel on, wash wheel down. Lower axle, torqued wheel down to 500ft torque toes. Clean up work area. Fight to remove battery cover/step due to exhaust stack	Daniel Massner	106.84
Labor - Jones Apprentice	TASK #	Look for parts/order parts. Removed all fittings on tank, make tool for pressure testing. Pressure test air tanks. Install new hub cap. Fill hub cap with oil. Removed battery holder. Removed batteries. Wash down air tanks/plugs up	Daniel Massner	122.10
Labor - Jones Apprentice	TASK #	Move tanks back in shop, dry off and chip rust off. Spray paint one side. Spray paint other side. Removed air lines to tank. Drop air tank from unit	Daniel Massner	76.31
Labor - Jones Apprentice	TASK #	Blow out battery box. Line up air tanks, install air tanks. Cut out old exhaust saddle clamps, remove. Fight to lift exhaust stack and fight to install exhaust saddle clamps x2. Removed fittings off old air tanks, start to install fittings on newer tank. Remove all plug fittings from pressure testing	Daniel Massner	137.36
Labor - Jones Apprentice	TASK #	Plumb in second air tank. Put batteries back in/hook up wiring. Put battery cover/step back on. Air up unit, test for leaks, put unit in line up. Sweep up bay, clean up and put tools away. Paper work, charge rests	Daniel Massner	106.84
Labor - Jones Apprentice	TASK #	Plumb in first air tank	Daniel Massner	61.05
Labor - Jones Apprentice	TASK #	Truck left side 1st axle retorque	Raimand Noronha	15.26

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Labor

Category	Description	Technician Notes	Mechanic	Amount

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
MC-400, 4" Exhaust / Muffler Clamp w/ saddle		2.00	9.88	19.76
1612, CR Scotseal - Hub Cap		1.00	32.33	32.33
382-8036 / 36058 PRO, Wheel Seal		1.00	11.31	11.31
330-3024, Gasket-Hubcap		1.00	2.15	2.15

Total Labor	890.22
Total Parts	65.55
Total Returns	.00
Total Sublet	.00
Shop Supplies	89.02
Invoice Total	1,044.79

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 25386
Date: 05/06/2026

Completed Date: 05/13/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 05/06/2026
Entered By: Valerie

Labor

Category	Description	Technician Notes	Mechanic	Amount
CVIP	CVIP - CV8713568	Resolved by Randy 05/12		.00
DVIR	DVIR (Tony Sousa Jul/8/25) 141120 rock chip passenger side windshield.	Resolved by Veer 05/11. Moved from 24061-24178.		.00
DVIR	DVIR 05/06 Tony - Hood scratched, hand deflector bent and scratched.	Not resolved. added to excel sheet.		.00
RE-TORQUE REQUIRED	100-150 km from 1332289 km all tires			.00
ORDER PARTS / SUBLET	torque rods	SIF 001-253448		.00
ORDER PARTS / SUBLET	dismount/mount 4 used tires	Premium Tire 9975		.00
ORDER PARTS / SUBLET	led lights x3	Traction 115136343		.00
Labor - Jones Apprentice	TASK #	Air up / move unit in / start up / inspect	Daniel Massner	76.31
ORDER PARTS / SUBLET	Windshield	Veer 002051		.00
Labor - Jones Apprentice	TASK #	Move / back into bay 2	Daniel Massner	15.26
Labor - Jones Apprentice	TASK #	Start filling out CVIP doc	Daniel Massner	30.53
Labor - Jones Apprentice	TASK #	Take measurements of tires. Jack up all drives / removed wheels / removed pad cover plates. Continue CVIP. Put all pad covers back on. Check studs / put front drive wheels back on / lamer axle. Start fixing lights / fill out CVIP doc	Daniel Massner	167.89
Labor - Jones Apprentice	TASK #	Fixing lights x2 (drilling). Start ordering front marker and signal lights	Daniel Massner	91.58
Labor - Jones Apprentice	TASK #	Removing sized lights off unit / cut bolts	Daniel Massner	30.53
Labor - Jones Apprentice	TASK #	Torqued all drives to 500ft	Daniel Massner	15.26
Labor - Jones Apprentice	TASK #	Working on lights / wiring installing / testing. Move unit over pit	Daniel Massner	15.26
Labor - Jones Apprentice	TASK #	Lift front-end R.H.S./torch lug nuts/remove wheels. Removed inspection plate. Took measurements/check king pins/put all back together. Torqued wheels to 500 ft. Same with other side (L.H.S.)	Daniel Massner	122.10
Labor - Jones Apprentice	TASK #	Fix side/signal/marker light. Fix/replace hose on air line hopper. Fix all air leaks	Daniel Massner	91.58
Labor - Jones Apprentice	TASK #	Remove and install torque bars/fill out CVIP doc. Move unit over to pit	Daniel Massner	152.63
RE-TORQUE COMPLETED		Resolved by Raimond 05/13		.00
Labor -Jones Journeyman	TASK #	CVIP inspection of mechanics work performed	Randy Donaldson	121.58
Labor -Jones Journeyman	TASK #	Final walk through before paperwork filing	Randy Donaldson	20.26
Labor -Jones Journeyman	TASK #	File paperwork with E-facility, one for truck/one for file	Randy Donaldson	20.26
Labor - Jones Apprentice	TASK #	Torque all wheel retorque right and left side	Raimand Noronha	45.79

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
92420, Oval Lamp Grommet		1.00	2.08	2.08
G6002, LED Lamp - Red		1.00	23.36	23.36
45583, AMBER LED W/ 180 BULLETS & BEZEL		1.00	36.86	36.86
177.3005 / 9820-2, TENDER KIT 16" DOUBLE WITH TEC CLAMP		1.00	34.12	34.12

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 9975 Supplier: Premium Tires Acheson Ltd	4 c/o from jones used tires	1.00	120.00	120.00
	Invoice: 001-253448 Supplier: SIF Superiors Industrial Frictions Ltd.	torque rod	1.00	545.78	545.78
	Invoice: 115136343 Supplier: Traction Heavy Duty Parts	high count 2 sided LED	1.00	273.52	273.52
	Invoice: 002051 Supplier: Veer Windshields & Tire	windshield replacement	1.00	275.00	275.00

Total Labor	1,016.82
Total Parts	96.42
Total Returns	.00
Total Sublet	1,214.30
Shop Supplies	223.11
Invoice Total	2,550.65

DGN TRUCK & TRAILER REPAIR LTD.
7710, YELLOWHEAD TRAIL
EDMONTON AB T5B 1G3
+17808634113
dgntrucktrailerrepair@gmail.com
GST/HST Registration No.:
710012295RT0001

INVOICE

BILL TO
JONES TRANSPORTATION
INC
KW
KMS 1332261
VIN 969534
UNIT 9107

INVOICE # VIN 2122179
DATE 05/06/2026
DUE DATE 05/06/2026
TERMS Due on receipt

ACTIVITY	QTY	RATE	AMOUNT

Date: 05.06.26 UNIT # 9107
Received By: TONY
WO# or PO# 25213
Approved By:

ACTIVITY	QTY	RATE	AMOUNT
Engine BRING IN UNIT FOR COOLANT LOSE. PRESSUER TEST EXTERNALLY ALL OK,DRAINED OIL AND REMOVE THE OIL PAN.CHECKED AND FOUND COOLANT LEAKING FROM THE NO 2 LINER.SEND PICTURE TO THE CUSTOMER. START STRIPPING REMOVED THE CYLINDER HEADAFETR REMOVEING RAD ASSEMBLY,ROCKERS ,INJECTORS. CLEANED THE SURFACES .DID BLOCK INSPECTIONA ND LINER HT.NO 2 AND 5 LINER DROPPED.INFO THE CUSTOMER. REMOVED THE PISTONS.CUSTOMER WANT TO DO THE ELLITE KIT.DID COUNTER BORE AND WASHED THE ENGINE.GOT READY FOR NEW KIT. PLAN CHANGED ONE CUSTOMERS TRUCK TOWED UNIT 9105 TO THE SHOP TO SWAP THE ENGINE. REMOVED THE HOOD ,RAD ASSMBLY,TRANSMISSIONA AND ENGINE TO THE FLOOR.INSTALLED HOOD BACK.LOOSE TRANSMISSION AND RAD ASSMBLY GAVE BACK TO THE CUSTOMER. REMOVED 9107 PREP ENGINE TO THE FLOOR. FRONT ENGINE MOUNTS SEIZED.HAD TO USE THE TORCH AND CUT THEM OFF.REAR ENGINE MOUNTS BROKEN. REPLACED THE ENGINE MOUNTS. INSTALLED OTHER ENGINE IN .SWAPPED THE ENGINE HARNESS AND ECM. INSTALLED THE RAD ASSEMBLY.INSTALLED NEW REAR ENGINE SEAL. INSTALLED THE TRANSMISION BACK AS PR CUSTOMER NEW OIL AND FILTER REPLACED. RUN THE TRUCK. PUT ALL OLD ENGINE PARTS IN THE CAB AND SOME TAKEN BY THE CUSTOMER. IT WAS TAOLAL 90 HRS BUT CHRGED 81 HRS ONLY	81	110.00	8,910.00
Engine COUNTER BORE	1	1,450.00	1,450.00

ACTIVITY	QTY	RATE	AMOUNT
Transmission TRIED TO DO THE ROAD TEST TRANSMISSION NOT SHIFTING. CODE 27 .DID CLUTCH RESET PROCEDURE DID NOT WORK.PERFORMED THE CLUTCH ADJUSTMENT.REMOVED THE CLUTCH.BOLTED AGAIN.DID ROAD TEST SAME PROBLEM.SEEMS LIKE ADJUSTABLE KNOB SEIZED.TALK TO THE CUSTOMER. GOT NEW CLUTCH AND SIUTCASE KT. DRAINED THE COOLANT.REMOVED THE DRIVE LINE AND EXHAST PIPES AGAIN.DROPPED THE TRANSMISSION .REMOVED THE FLYWHEEL AND GOT MACHINED. REPLACED THE INPUT SHAFT,INERTIA BRAKE AND INSTALLED THE FLYWHEEL AND TRANSMISSION WITH NEW CLUTCH.DID XY SHIFTER GASKET WAS LEAKING. HOOK UP COMPUTER AND PRFORMED THE CLUTCH ADJSUTMENT PROCEDURE. PUT COOLANT BACK IN. INSTALLED THE EXHAUST PIPES AND DRIVE LINE.ROAD TEST .SEEMS OK NOW.INFO THE CUSTOMER TO TAKE THE TRUCK.	21.50	110.00	2,365.00
STEERING STEERING SYSTEM IS HARD TO TURN.CHCKED FITTINGS AND OIL SUPPLY LINE IS LEAKING .REPLACED THE FITTING O RINGS AND STEERING HOSE.PUT NEW OIL IN .BLEED THE SYSTEM.	1	110.00	110.00
AIR CONDITIONING DID AC SERVICE ,VACUUM ,RECHARGE AND REPLACED THE REC DRYER.	1	145.00	145.00
Services AC GAS AND OIL	1	126.50	126.50
PARTS AND SHOP SUPPLY. FRONT ENGINE MOUNTS ,BOLTS AND HEX NUTS.	1	146.81	146.81
Services MACHING THE FLYWHEEL.	1	144.50	144.50
Services ENGINE OIL 15W40 DELO CHV.	1	301.20	301.20
Services FILTER OIL LF14000	1	78.50	78.50
Services FILTER FUEL.	1	81.40	81.40
Services FILTER W/S	1	44.60	44.60
Services GASKET XY SHIFTER ,GASKET 5" EXHAST PIPES ETC	1	52.40	52.40

ACTIVITY	QTY	RATE	AMOUNT
Services STEERING FLUID AND O RINGS.	1	33.40	33.40
Services V CLAMP DPF PIPE.	1	26.99	26.99
Services SHOP SUPPLY	1	310.00	310.00

SUBTOTAL	14,326.30
GST @ 5%	716.33
TOTAL	15,042.63
BALANCE DUE	**$15,042.63**

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	716.33	14,326.30

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 25213
Date: 03/30/2026

Completed Date: 04/30/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 03/30/2026
Entered By: Valerie

Labor

Category	Description	Technician Notes	Mechanic	Amount
ORDER PARTS / SUBLET	Engine swap	DGN 2122179		.00
ORDER PARTS / SUBLET	used actuator installed by DGN	ABS Truck 289756		.00
ORDER PARTS / SUBLET	Clutch, clutch kit	Edm KW 02NP958231		.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 289756 Supplier: ABS Truck and Trailer Parts	used actuator	1.00	700.00	700.00
	Invoice: 02NP958231 Supplier: Edmonton Kenworth Ltd.	clutch ultrashift	1.00	4,632.75	4,632.75
	Invoice: VIN 2122179 Supplier: DGN Truck & Trailer Repair Ltd.	transmission not shifting, steering system hard to turn, AC service	1.00	14,326.30	14,326.30

Total Labor	.00
Total Parts	.00
Total Returns	.00
Total Sublet	19,659.05
Shop Supplies	1,965.91
Invoice Total	21,624.96

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 24178
Date: 07/30/2025

Completed Date: 03/09/2026

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 07/30/2025
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
DVIR	DVIR (Tony Sousa Jul/8/25) 141120 rock chip passenger side windshield.	not resolved - moved to from/to 24601-24178-25386	Service Writer	.00
Labor - Jones Trucks	Wash	Wash truck	Estanilao Nasitem	100.00
DVIR	DVIR (Sept/26/25 Tony Sousa) 142475 power steering hose leaking.	Resolved - Daniel 7/29	Service Writer	.00
Labor - Jones Trucks	TASK#	Initiate DVIR repair regarding right front fender mount direction indicator being inoperative	Randy Donaldson	50.00
DVIR	DVIR (Oct, Nov, Dec/2025 Tony) Add Anti-freeze. The truck won't start. it just keeps cranking like it's not getting fuel.TASK #	Resolved - JasDei 2/13		.00
ORDER PARTS / SUBLET	Rear engine mount , pilot bearing, motor mount	ABS Truck 283351		.00
ORDER PARTS / SUBLET	motor mount return	ABS Truck 29197 - credit		.00
ORDER PARTS / SUBLET	seal kit, pipe exhaust, clamp exhaust	Edmonton Kenworth Ltd. 02NP946364		.00
ORDER PARTS / SUBLET	oil pressure sensor ordered for 9107 from Kenworth, Stan will pick up and deliver to DGN	Edmonton Kenworth Ltd. 02NP947976		.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP946364 Supplier: Edmonton Kenworth Ltd.	seal kit, pipe exhaust, clamp exhaust	1.00	221.18	221.18
	Invoice: 29197 Supplier: ABS Truck and Trailer Parts	return motor mount	1.00	-37.98	-37.98
	Invoice: 283351 Supplier: ABS Truck and Trailer Parts	BRG Pilot bearing, motor mount, rear engine mount	1.00	537.97	537.97
	Invoice: 02NP947976 Supplier: Edmonton Kenworth Ltd.	sensor pressure	1.00	163.75	163.75

power steering hose, windshield crack, anti-freeze

Total Labor	150.00
Total Parts	.00
Total Returns	.00
Total Sublet	884.92
Shop Supplies	103.49
Invoice Total	1,138.41

JONES
TRANSPORTATION INC.

Date: July 28 2025
Unit # 9107
Odometer Reading: 320578
Hour Reading: 26266.0
Work Order # 24178

CHECKED & OK
ADJUSTED
REPAIR or REPLACEMENT REQUIRED
REPAIRED, REPLACED or COMPLETED

Service interval as per Manufacturer's Specification

TRUCK / TRACTOR

BODY & FRAME	▲	★
Body		1
Frame & Cargo Body	11	3
Bumpers		1
Cab	2	
Coupling Devices	4	
Door Releases/Latches		1
Doors		1
Drive Shaft		6
Driver Controls	6	
Driver Seat	7	
Emergency Equipment & SafetyDevices	9	
Fenders		1
Fifth Wheel & Coupling Devices	4	31
General	13	23
Heater & Defroster	15	25
Horn	16	
Mirrors	14	7
Mudflaps		1
Sun Visors		1
Underbody		5

Windshield & Windows	14	7
Windshield Wipers & Washer	23	24
BRAKES		
Air Brake System	1	14
Brake Pedal		13
Electric Hydraulic Brake System		16
Mechanical Components		12
Parking/Emergency Brake		15
ELECTRICAL COMPONENTS		
Lamps & Reflectors	18	27
Neutral Safety Starting Switch		26
STEERING		
Steering Column & Box		18
Steering Linkage		21
Power Assist	19	
Wheel Alignment (Visual)		19
FUEL & EXHAUST		
Exhaust System	10	9
Filler Cap & Fuel Lines		8
Fuel System	12	8
Fuel Tank		8

SERVICE		
Complete Lubrication		30
Oil Change		
Check/Replace Air Filters		
Check Diff Oil		
Check Trans Oil		
Check Power Steering Fluid		
Check Front Hub Oil		
SUSPENSION		
Suspension System	20	22
Shock Absorber Condition	20	22
OK Spring Condition	20	22
WHEELS & TIRES		
Tires	21	28
Torqued Fasteners	22	29
Wheels, Hubs, Fasteners	22	29
OTHER		
Cargo Securement	3	
Dangerous Goods	5	

★ **Inspected Per AR 121/2009 Schedule 2 Section # (as shown above ★)**

▲ **Inspected Per NSC Standard 13, Part 2, Schedule 1, # (as shown above ▲)**

Notes: ~~Fitting on Compressor to Rear Spring Rez Suspension, Diff Temp Sensor/Weather Pack Broken, Rt Hub Rear Pomper Loose, Cat walk Loose, Driver Side Right Side Loose~~

Rev 12.18

Signature: _____

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 24061
Date: 07/08/2025

Completed Date: 07/31/2025

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 07/08/2025
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR (Jul/8/25 Tony Sousa) 141120 rock chip passenger side windshield.	WO# 24178	Service Writer	100.00
ORDER PARTS / SUBLET	Temp Sensor, weather pack	Edm Kenworth 02NP894712	Service Writer	.00
Labor - Jones Trucks	DVIR (Jul/28/25 Tony Sousa) 133121 power steering hose leaking	Daniel repaired	Service Writer	100.00
Tractor SERVICE	250 Hours or 25000 kms	Oil service/PM on 9107	Daniel Massner	300.00
Tractor SERVICE	250 Hours or 25000 kms	Finish up service, adjust 5th wheel, start repairs fix up RHS rear fender, buid up pigtail, clean off area around diff temp sensor	Daniel Massner	300.00
Labor - Jones Trucks	Diff temp sensor	Wire up pigtail, removed broken diff temp sensor, isntalled new diff temp sensor, clean up oil, top up oil in diff, tighten down cat walk, tighten power steer fitting, test leaks, tighten light skit on drivr side, move unit out/top up ATF	Daniel Massner	100.00
Labor - Jones Trucks	Hanger	Driver side Mudflap hanger weld	Raimand Noronha	100.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP894712 Supplier: Edmonton Kenworth Ltd.	sender temperature, connector ELC repair	1.00	221.76	221.76

Total Labor	1,000.00
Total Parts	.00
Total Returns	.00
Total Sublet	221.76
Shop Supplies	122.18
Invoice Total	1,343.94

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23962
Date: 06/14/2025

Completed Date: 06/23/2025

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 06/14/2025
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR (May/13/25 Tony Sousa) 137814 fuel gauge drops down to empty then slowly moves up and down	WO# 24037	Service Writer	100.00
Labor - Jones Trucks	DVIR (May/13/25 Tony Sousa) 140283 leaking at hose	Daniel	Service Writer	100.00
Labor - Jones Trucks	DVIR (May/13/25 Tony Sousa) 140283 passenger side hose leak	Daniel	Service Writer	100.00
Labor - Jones Trucks	Power steering hose leak	Inspect hose clamps, tighten, replace, clean oil off	Daniel Massner	100.00
Labor - Jones Trucks	Hood	Inspect hood repairs in yard, take pictures of cracks and missed area	Daniel Massner	100.00

Total Labor	500.00
Total Parts	.00
Total Returns	.00
Total Sublet	.00
Shop Supplies	50.00
Invoice Total	550.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23856
Date: 05/13/2025

Completed Date: 06/06/2025

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 05/13/2025
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR (May/13/25 Tony Sousa) 137814 fuel gauge drops down to empty then slowly moves up and down	WO# 23962	Service Writer	100.00
Labor - Jones Trucks	DVIR (May/13/25 Tony Sousa) 139512 Driver's side hood bracket requiring bolts.	Edmonton Diesel Doctor	Service Writer	100.00
Labor - Jones Trucks	DVIR (May/20/25 Tony Sousa) 139653 Power steering making noise possibly kink in the line.	Daniel	Service Writer	100.00
Labor - Jones Trucks	DVIR (May/30/25 Tony Sousa) 139901 Power steering hose leaking again.	Daniel	Service Writer	100.00
Labor - Jones Trucks	TASK #	Inspect power steering hose on 9107 in yard	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Removed line, cut new hose, installed, tie down, add ATF in resevoir, clean up with brake cleaner	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Removed and replaced oil line with proper line, fill up	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Inspect hood, try to fix	Daniel Massner	100.00
ORDER PARTS / SUBLET	Hood Remove and Refitting, Hood Mount Stud Fixed with Welding epoxy glue	EdmontonDieselDoctor 2235, WO# 24037	Service Writer	.00

Total Labor	800.00
Total Parts	.00
Total Returns	.00
Total Sublet	.00
Shop Supplies	80.00
Invoice Total	880.00

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23719
Date: 04/07/2025

Completed Date: 05/12/2025

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 04/07/2025
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR (1/20/25 Tony Sousa) 137814 fuel gauge drops down to empty then slowly moves up and down		Service Writer	100.00
Labor - Jones Trucks	DVIR (Apr/3/25 Andy Toole) Jones yard foot brake pedal needs worked on sticking down		Service Writer	100.00
Labor - Jones Trucks	DVIR (Apr/7/25 Tony Sousa) 138778 power steering line leaking	WO# 23856	Service Writer	100.00
Labor - Jones Trucks	DVIR (Apr/24/25 Tony Sousa) 138512 Driver. Side hood bracket missing bolts	WO# 23856	Service Writer	100.00
Labor - Jones Trucks	DVIR (May/5/25 Tony Sousa) 139637 passenger side shock leaking		Service Writer	100.00
Labor - Jones Trucks	DVIR (May/5/25 Tony Sousa) 139637 antifreeze leak passenger side		Service Writer	100.00
ORDER PARTS / SUBLET	Kenworth NoPSP60200 / INV 02NP876987	CAP filler	Service Writer	.00
Tractor SERVICE	250 Hours or 25000 kms	Full service / PM	Daniel Massner	300.00
Tractor SERVICE	250 Hours or 25000 kms	Complete full service / PM	Daniel Massner	300.00
Labor - Jones Trucks	TASK #	Removed front steer shock, installed new shock, found loose hose clamp on coolant line, removed power steer res hose, drain ATF, installed new hose/clamps, fill back up with ATF	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Removed T-handle on J-box * 2, installed one, ordered parts, fixed up marker light, loosend up brake pettale, clean up tools	Daniel Massner	100.00
ORDER PARTS / SUBLET	SIF 001-215662	whale tale handle ext		.00
ORDER PARTS / SUBLET	SIF 001-218382	T-HANDLE STAINLESS HANDLE, T" HANDLE RUBBER GASKET		.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP876987 Supplier: Edmonton Kenworth Ltd.	cap filler	1.00	98.95	98.95
	Invoice: 001-218382 Supplier: SIF Superiors Industrial Frictions Ltd.	T-HANDLE STAINLESS HANDLE, T" HANDLE RUBBER GASKET	1.00	51.10	51.10
	Invoice: 001-215662 Supplier: SIF Superiors Industrial Frictions Ltd.	whale tale handle	1.00	115.94	115.94

Total Labor	1,400.00
Total Parts	.00
Total Returns	.00
Total Sublet	265.99
Shop Supplies	166.60

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Invoice Total	1,832.59

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23610
Date: 02/28/2025

Completed Date: 02/28/2025

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 02/28/2025
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR (Feb 28, 25) 136166 oil leak		Service Writer	100.00
Labor - Jones Trucks	TASK #	Change out oil filter	Daniel Massner	100.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
B7139 / BWF, Engine Oil Filter		1.00	7.11	7.11

Total Labor	200.00
Total Parts	7.11
Total Returns	.00
Total Sublet	.00
Shop Supplies	20.00
Invoice Total	227.11

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23583
Date: 02/17/2025

Completed Date: 02/26/2025

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 02/17/2025
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	TASK #	Service/PM 9107	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Finished service/inspection	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Diagnose whre air leaks are, removed fitting on fan clutch, installed new fitting, test for leaks	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Chsing all air leaks, fixed air leaks * 3, test	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Install leak defender on fuel cap	Daniel Massner	100.00
Labor - Jones Trucks	TASK #	Didanose and install switch for trailer aux scully system	Randy Donaldson	100.00
ORDER PARTS / SUBLET	brake shoe kit	SIF 001-208290/001-208287	Service Writer	.00
Labor - Jones Trucks	TASK #	Finished installed scully system	Randy Donaldson	100.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 001-208290 Supplier: SIF Superiors Industrial Frictions Ltd.	brake shoe kit	1.00	-131.98	-131.98
	Invoice: 001-208290 Supplier: SIF Superiors Industrial Frictions Ltd.	core	1.00	-68.00	-68.00
	Invoice: 001-208287 Supplier: SIF Superiors Industrial Frictions Ltd.	brake shoe kiit, fuse holder	1.00	134.31	134.31
	Invoice: 001-208287 Supplier: SIF Superiors Industrial Frictions Ltd.	core	1.00	68.00	68.00

Total Labor	700.00
Total Parts	.00
Total Returns	.00
Total Sublet	2.33
Shop Supplies	70.23
Invoice Total	772.56

DGN TRUCK & TRAILER REPAIR LTD.
7710, YELLOWHEAD TRAIL
EDMONTON AB T5B 1G3
7808634113
dgntrucktrailerrepair@gmail.com
GST/HST Registration No.:
710012295RT0001

INVOICE

BILL TO
JONES TRANSPORTATION
INC
KW
KMS 1310411
VIN 969534
UNIT 9107

INVOICE # 2911
DATE 09/28/2024
DUE DATE 09/28/2024
TERMS Due on receipt

Date: 9-28-24 **UNIT #** 9107
Received By:
WO# or PO# 23220
Approved By:

ACTIVITY	QTY	RATE	AMOUNT
Engine BRING IN UNIT FRO LOW OIL PRESSURE WARNING.STARTED TO T/S. HOOK UP COMPUTER. CHECKED WIRING CHECKED PRESSURE AT BLOCK ALL OK.FOUND SENSOR SHORTED OUT. BOUGHT SENSOR AND INSTALLED.START THE TRUCK .CHECKED AND FOUND ALL OK NOW.	3	110.00	330.00
COOLANT STARTED TO VERIFY COOLANT ISSUE.PRESSURE TEST.FOUND ONE HOSE IS LEAKING.FIXED THE LEAK AND ORESSUER TEST AGAIN.SEEMS LIKE OK NOW.	1	110.00	110.00
PARTS AND SHOP SUPPLY. SENSOR OIL PRESSURE.	1	165.80	165.80
Services SHOP SUPPLY	1	20.00	20.00

23220

SUBTOTAL	625.80
GST @ 5%	31.29
TOTAL	657.09
BALANCE DUE	**$657.09**

TAX SUMMARY

DGN TRUCK & TRAILER REPAIR LTD.
7710, YELLOWHEAD TRAIL
EDMONTON AB T5B 1G3
7808634113
dgntrucktrailerrepair@gmail.com
GST/HST Registration No.:
710012295RT0001

INVOICE

BILL TO
JONES TRANSPORTATION
INC
KW
KMS 1310192
VIN 969534
UNIT 9107

INVOICE # 2910
DATE 09/23/2024
DUE DATE 09/23/2024
TERMS Due on receipt

Date: 9-23-24 **UNIT #** 9107
Received By:
WO# or PO# 23220
Approved By:

ACTIVITY	QTY	RATE	AMOUNT
Heating an air conditioning BRING IN UNIT FOR CAB HEAT NOT WORKING.STARTED TO T/S FOUND WATER VALVE IS NOT MOVING.CHECKED ALL THE ELECTRICAL SYSTEM.FOUND CONECTOR IS CORRODE ALSO WIRING BROKEN.MADE THE CONECTRO ,INSTALLED THE PINS.DRAINED THE COOLANT.REMOVED THE WATER VALVE.TOOK TIME.ONE HOSE IS BAD.PREPARED AND INSTALLED NEW VALVE.INSTALLED NEW HOSE.PUT COOLANT IN.TESTED ALL OK NOW.	4.50	110.00	495.00
Services SHOP SUPPLY	1	44.60	44.60

PO# 23220

SUBTOTAL	539.60
GST @ 5%	26.98
TOTAL	566.58
BALANCE DUE	**$566.58**

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	26.98	539.60

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23220
Date: 09/14/2024

Completed Date: 10/09/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 09/14/2024
Entered By: King

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR (09/13/24 Tony Sousa) 138905 AC stuck on won't go to heating mode.		Service Writer	100.00
Labor - Jones Trucks	DVIR (09/19/24 Tony Sousa) 138986 passenger side front axle		Service Writer	100.00
Labor - Jones Trucks	TASK #	Spit out B train out of shop, bring 9107 into bay 2	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Wheel seal driver side leak reported, check all axles	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Jack up #2A axle both sides	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	#2A RHS hub axle gasket taken off, clean hub seized, top up oil, tires on, jack down axle, torque tire, install torque tag inside	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Park 9107 outside, clean bay	Paramvir Bling	100.00
ORDER PARTS / SUBLET	AC stuck without heating mode	DGN 2910	Service Writer	.00
ORDER PARTS / SUBLET	Water valve assy	Kenworth 02NP825859	Service Writer	.00
ORDER PARTS / SUBLET	Connector, termnal, seal packard cable	Kenworth 02NP825867	Service Writer	.00
ORDER PARTS / SUBLET	Low Oil Pressure	DGN 2911	Service Writer	.00
Labor - Jones Trucks	TASK #	Torque in yard	Paramvir Bling	100.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP825859 Supplier: Edmonton Kenworth Ltd.	valve-assy water	1.00	230.62	230.62
	Invoice: 02NP825867 Supplier: Edmonton Kenworth Ltd.	connector packard female way, terminal F- spade, seal paackard cable	1.00	23.47	23.47
	Invoice: 2910 Supplier: DGN Truck & Trailer Repair Ltd.	BRING IN UNIT FOR CAB HEAT NOT WORKING.STARTED TO T/S FOUND WATER VALVE IS NOT MOVING.CHECKED ALL THE ELECTRICAL SYSTEM.FOUND CONECTOR IS CORRODE ALSO WIRING BROKEN.MADE THE CONECTRO ,INSTALLED THE PINS.DRAINED THE COOLANT.REMOVED THE WATER VALVE.TOOK TIME.ONE HOSE IS BAD.PREPARED AND INSTALLED NEW VALVE.INSTALLED NEW HOSE.PUT COOLANT IN.TESTED ALL OK NOW.	1.00	539.60	539.60

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 2911 Supplier: DGN Truck & Trailer Repair Ltd.	FRO lowoil pressure	1.00	625.80	625.80

Total Labor	800.00
Total Parts	.00
Total Returns	.00
Total Sublet	1,419.49
Shop Supplies	221.95
Invoice Total	2,441.44

HeavyTek Truck and Trailer
MAIL CHEQUES TO: 56 Dawson Cresent
Sherwood Park AB T8H 1Z6
accounts@heavytek.ca
www.heavytek.ca
GST/HST Registration No.: 73882 1701
RT0001
Business Number 738821701 RT0001

INVOICE

BILL TO
JONES TRANSPORTATION

INVOICE # 1828
DATE 15/07/2024

TERMS Net 30

UNIT NUMBER/MAKE	VIN	MILEAGE/HOURS
9107 2013 KENWORTH	1XKDD49X8ER969534	1301228 KM

	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Admin fee	Receive unit, go over customer concerns, open work order	GST	1	30.00	30.00
Labor	Job: A/C - Check over a/c system and found a/c pump clutches seized and pump belt missing - Evac system - Perform pressure test - failed - Repair leak at o ring @ condenser - Install new compressor and belt - Re pressure test system - No leaks found - Charge system - Run and check system operation - Good	GST	2.50	135.00	337.50
Parts purchased	A/C Pump	GST	1	533.67	533.67
Parts purchased	A/C Pump belt	GST	1	37.19	37.19
Pag oil	Pag Oil per oz	GST	2	6.27	12.54
Shop Supplies	Shop Supplies	GST	1	47.55	47.55
	CUSTOMER PO 23030				

We appreciate your business and look forward to helping you again soon

SUBTOTAL	998.45
GST @ 5%	49.93

AT THIS TIME WE APPRECIATE PROMPT PAYMENT VIA EFT, EMT, OR CHEQUE.
***MAIL CHEQUES TO:
56 Dawson Cresent, SHERWOOD PARK, AB T8H 1Z6
E-TRANSFER: ACCOUNTS@HEAVYTEK.CA

TOTAL	1,048.38
BALANCE DUE	**$1,048.38**

Date: 07/15/24 UNIT #9107
Received By: _____
WO# or PO# 23030
Approved By: _____

AT THIS TIME WE APPRECIATE PROMPT PAYMENT VIA EFT, EMT, OR CHEQUE.
***MAIL CHEQUES TO:
56 Dawson Cresent, SHERWOOD PARK, AB T8H 1Z6
E-TRANSFER: ACCOUNTS@HEAVYTEK.CA

JONES
TRANSPORTATION INC.

Date: 10 Sept, 2024
Unit #: 9107
Odometer Reading: 1308845
Hour Reading: 25291
Work Order #: 23030

✓ CHECKED & OK
/ ADJUSTED
R REPAIR or REPLACEMENT REQUIRED
X REPAIRED, REPLACED or COMPLETED

Service interval as per Manufacturer's Specification

TRUCK / TRACTOR

	BODY & FRAME	▲	★
✓	Body		1
✓	Frame & Cargo Body	11	3
✓	Bumpers		1
✓	Cab	2	
✓	Coupling Devices	4	
✓	Door Releases/Latches		1
✓	Doors		1
✓	Drive Shaft		6
✓	Driver Controls	6	
✓	Driver Seat	7	
✓	Emergency Equipment & SafetyDevices	9	
✓	Fenders		1
✓	Fifth Wheel & Coupling Devices	4	31
✓	General	13	23
✓	Heater & Defroster	15	25
✓	Horn	16	
✓	Mirrors	14	7
✓	Mudflaps		1
✓	Sun Visors		1
✓	Underbody		5

✓	Windshield & Windows	14	7
✓	Windshield Wipers & Washer	23	24
	BRAKES		
✓	Air Brake System	1	14
✓	Brake Pedal		13
✓	Electric Hydraulic Brake System		16
✓	Mechanical Components		12
✓	Parking/Emergency Brake		15
	ELECTRICAL COMPONENTS		
✓	Lamps & Reflectors	18	27
✓	Neutral Safety Starting Switch		26
	STEERING		
✓	Steering Column & Box		18
✓	Steering Linkage		21
✓	Power Assist	19	
✓	Wheel Alignment (Visual)		19
	FUEL & EXHAUST		
✓	Exhaust System	10	9
✓	Filler Cap & Fuel Lines		8
✓	Fuel System	12	8
✓	Fuel Tank		8

	SERVICE		
✓	Complete Lubrication		30
✓	Oil Change		
✓	Check/Replace Air Filters		
✓	Check Diff Oil		
✓	Check Trans Oil		
✓	Check Power Steering Fluid		
✓	Check Front Hub Oil		
	SUSPENSION		
✓	Suspension System	20	22
✓	Shock Absorber Condition	20	22
	Spring Condition	20	22
	WHEELS & TIRES		
✓	Tires	21	28
/	Torqued Fasteners	22	29
✓	Wheels, Hubs, Fasteners	22	29
	OTHER		
✓	Cargo Securement	3	
✓	Dangerous Goods	5	

★ **Inspected Per AR 121/2009 Schedule 2 Section # (as shown above ★)**

▲ **Inspected Per NSC Standard 13, Part 2, Schedule 1, # (as shown above ▲)**

Notes: ✓ Power steering reservior hose leak (New clamps installed)
✓ Shock leaking last axle RHS (Installed New 2 shocks)
✓ Coolant low

Rev 12.18

Signature: Paramvir

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23030
Date: 07/10/2024

Completed Date: 09/11/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 07/10/2024
Entered By: wendy

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR [04.27.24 Tony] fuel crossover line bracket broke causing line to drag on ground,. Requires replacement and tap handles required			100.00
Labor - Jones Trucks	DVIR [05.27.24 Tony] 136764 power steering hose leaking near box			100.00
ORDER PARTS / SUBLET	New hose as per sample	Gregg INV 057-30156	Service Writer	.00
Labor - Jones Trucks	TASK #	Fuel tank cross over line leaking, turn taps off, remove lines, change one Tic fittins, wash old hose for sample, order new hose	Kevin Thornton	100.00
Labor - Jones Trucks	TASK #	Install new hose, tie hose into place, clean up tools	Kevin Thornton	100.00
ORDER PARTS / SUBLET	A/C	HeavyTek 1828	Service Writer	.00
ORDER PARTS / SUBLET	2 MON M65523 GAS-MAGNUM 65 SHOCK	SIF 001-190727	Service Writer	.00
Labor - Jones Trucks	TASK #	Service 9107, oil change, filters, grease, oil, diff levels, hub levels, trans level	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Service, oil top up, check tire pressure refill, other defects notes	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Change power steering hose, clamp leaking	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Clean hose and power steering box to check further leaks	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Coolant top up, service sheet make up	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	#3A LHS, shock take off, seized, cut off loft to take off	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	3A RHS shock take off, air out lower part to take off seized	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	3A RHS/LHS clean new shock seating surface wire wheel bolts old	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	3A RHS shock install	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	3A LHS shock install	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Move truck outside, throw garbage	Paramvir Bling	100.00
Labor - Jones Trucks	TASK #	Clean bay	Paramvir Bling	100.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 057-309156 Supplier: Gregg Distributors	hose assembly, pressure hose,	1.00	221.22	221.22
	Invoice: 1828 Supplier: HeavyTek Truck and Trailer	AC pump, belt, pag oil, shop supplies	1.00	998.45	998.45
	Invoice: 001-190727 Supplier: SIF Superiors Industrial Frictions Ltd.	GAS magnum 65 shock	1.00	218.42	218.42

Total Labor	1,600.00
Total Parts	.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Total Returns	.00
Total Sublet	1,438.09
Shop Supplies	303.81
Invoice Total	3,341.90

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 23022
Date: 07/09/2024

Completed Date: 09/20/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 07/09/2024
Entered By: Aaron

Labor

Category	Description	Technician Notes	Mechanic	Amount
Tractor SERVICE	250 Hours or 25000 kms	completed		300.00
Labor - Jones Trucks	service	hub levels, diff levels, trany level and fill up	Paramvir Bling	100.00
Labor - Jones Trucks	service	oil change, filters, fuel and engine oil	Paramvir Bling	100.00
Labor - Jones Trucks	service	grease truck, check for defects under truck, fill out service sheet	Paramvir Bling	100.00
Labor - Jones Trucks	service	fifth wheel service, play check and clean up lube, tire pressure and fill note down defects, torque wheels, clean brake caliper for seal sweating for further leaks	Paramvir Bling	100.00
Labor - Jones Trucks	air tank drain cord broken	air tank drain cord change install new	Paramvir Bling	100.00
Labor - Jones Trucks	light side lhs back not working	take off old light and install new, wiring fix	Paramvir Bling	100.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
SPC500010047, 10W-30 Bulk Oil	41 litres	41.00	4.16	170.56
BD50000, High Efficiency Dual-Flow		1.00	39.86	39.86
BF46129, Filters		1.00	51.15	51.15

Total Labor	900.00
Total Parts	261.57
Total Returns	.00
Total Sublet	.00
Shop Supplies	90.00
Invoice Total	1,251.57

JONES
TRANSPORTATION INC.

Date: 10 July, 2024
Unit # 9102
Odometer Reading: 973472
Hour Reading: 25037
Work Order # 23022

CHECKED & OK
ADJUSTED
REPAIR or REPLACEMENT REQUIRED
REPAIRED, REPLACED or COMPLETED

Service interval as per Manufacturer's Specification

TRUCK / TRACTOR

BODY & FRAME	▲	★
Body		1
Frame & Cargo Body	11	3
Bumpers		1
Cab	2	
Coupling Devices	4	
Door Releases/Latches		1
Doors		1
Drive Shaft		6
Driver Controls	6	
Driver Seat	7	
Emergency Equipment & SafetyDevices	9	
Fenders		1
Fifth Wheel & Coupling Devices	4	31
General	13	23
Heater & Defroster	15	25
Horn	16	
Mirrors	14	7
Mudflaps		1
Sun Visors		1
Underbody		5

Windshield & Windows	14	7
Windshield Wipers & Washer	23	24
BRAKES		
Air Brake System	1	14
Brake Pedal		13
Electric Hydraulic Brake System		16
Mechanical Components		12
Parking/Emergency Brake		15
ELECTRICAL COMPONENTS		
Lamps & Reflectors	18	27
Neutral Safety Starting Switch		26
STEERING		
Steering Column & Box		18
Steering Linkage		21
Power Assist	19	
Wheel Alignment (Visual)		19
FUEL & EXHAUST		
Exhaust System	10	9
Filler Cap & Fuel Lines		8
Fuel System	12	8
Fuel Tank		8

SERVICE		
Complete Lubrication		30
Oil Change		
Check/Replace Air Filters		
Check Diff Oil		
Check Trans Oil		
Check Power Steering Fluid		
Check Front Hub Oil		
SUSPENSION		
Suspension System	20	22
Shock Absorber Condition	20	22
Spring Condition	20	22
WHEELS & TIRES		
Tires	21	28
Torqued Fasteners	22	29
Wheels, Hubs, Fasteners	22	29
OTHER		
Cargo Securement	3	
Dangerous Goods	5	

★ **Inspected Per AR 121/2009 Schedule 2 Section # (as shown above ★)**

▲ **Inspected Per NSC Standard 13, Part 2, Schedule 1, # (as shown above ▲)**

Notes: Air tank Drain Cord Broken, Temp. Sensor Front Diff. Broken Fuel line Need's new rubber off, LHS side marker light back not working

Rev 12.18

Signature:

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 22842
Date: 05/08/2024

Completed Date: 09/20/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 05/08/2024
Entered By: yamanpreet

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR [04.27.24 Tony] fuel crossover line bracket broke causing line to drag on ground,. Requires replacement and tap handles required	Move to WO 23030 Note: Did a temporary fix	Service Writer	100.00
Labor - Jones Trucks	DVIR [05.06.24 Tony]making popping sounds jumping in and out of gear	Resolved	Service Writer	100.00
Labor - Jones Trucks	DVIR [05.06.24] possible axle broke . Had to drive back with power divider on	Check drive line , drive turs going into rear diff remove plugs from front diff and very little meatal on magnet. check rear diff and lots of metal and chunk of metal on inspection plug magnet. Drain diff and took sample. Use bora scope and can see lots metal chunks bearing parts.	Kevin Thornton	100.00
Labor - Jones Trucks	Inspect diff damage	Clean up and drain used oil in tank . Order parts for rear diff replacement.	Kevin Thornton	100.00
ORDER PARTS / SUBLET	Rear Diff	Western Star inv# 00104267934	Service Writer	.00
Labor - Jones Trucks	Core Rear Diff return	Western Star	Service Writer	100.00
Labor - Jones Trucks	replace rear diff	Remove drive drive shaft and remove diff housing bolts were packed with lock tight. Remove air line and switch wiring. move from pit to another bay.	Kevin Thornton	100.00
Labor - Jones Trucks	rear diff	Assisted Kevin, clean nuts, bolts and assigned duties	Paramvir Bling	100.00
Labor - Jones Trucks	tie up cross over fuel hose between fuel tanks	Tie down cross over fuel hose with ties	Paramvir Bling	100.00
Labor - Jones Trucks	rear diff	Assisted Kevin with taking out shaft and other duties	Paramvir Bling	100.00
Labor - Jones Trucks	Replace rear diff	Remove both rear axles and problems with removing RHS axle . Order parts (u-joint strap kit	Kevin Thornton	100.00
Labor - Jones Trucks	parts pick up from western star	Pick up parts from western star in Acheson and come back	Paramvir Bling	100.00
Labor - Jones Trucks	Rear Diff	Assisted Kevin with Rear diff and rear axles	Paramvir Bling	100.00
Labor - Jones Trucks	Rear Diff	Assisted Kevin with Rear diff	Paramvir Bling	100.00
Labor - Jones Trucks	Replace rear diff	Remove diff from truck are time getting diff on to the floor very tight area. remove yoke from diff and clean RHS axle hub	Kevin Thornton	100.00
Labor - Jones Trucks	rear diff	Assisted Kevin with rear diff, put back drive line, grease drive line and park truck into bay	Paramvir Bling	100.00
Labor - Jones Trucks	replace rear diff	Clean LHS axle hub . Get diff into placeand install diff. Put truck on pit and install old yoke and install drive line with new strap kits and torque strap bolts to 120 ft/lb . Install both axles and torque axle nuts to 100 ft/lb . Clean up tools and clean floor and put core on pallet. and lock up	Kevin Thornton	100.00
ORDER PARTS / SUBLET	KIT, Strap SPL170	Western Star Inv# 00104269706	Service Writer	.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	Tail lights and side marker on hood not working	check all fusses in cab and under hood and all tested good . Check power in trailer cord and tail light circut is dead. Check for power in junction box and got no power coming into box. I bypass power to tail light circut and got all lights working. This a tempary Fix .	Kevin Thornton	100.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
R170D391, Differential Assembly		1.00	4,215.59	4,215.59

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 00104269706 Supplier: Western Star Trucks (North) Ltd.	Kit strap	1.00	66.36	66.36
	Invoice: 00104267934 Supplier: Western Star Trucks (North) Ltd.	differential assy	1.00	4,215.59	4,215.59
	Invoice: 00104267934 Supplier: Western Star Trucks (North) Ltd.	diff assy core	1.00	1,905.00	1,905.00
	Invoice: 00104271737 Supplier: Western Star Trucks (North) Ltd.	core return	1.00	-1,905.00	-1,905.00
	Invoice: 00104271737 Supplier: Western Star Trucks (North) Ltd.	core damage	1.00	952.50	952.50

Total Labor	1,700.00
Total Parts	4,215.59
Total Returns	.00
Total Sublet	5,234.45
Shop Supplies	693.45
Invoice Total	11,843.49

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 22723
Date: 03/27/2024

Completed Date: 04/22/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 03/27/2024
Entered By: yamanpreet

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	136508 hose clamp from Turbo broke off		Service Writer	.00
Labor - Jones Trucks	136508 hose clamp from Turbo broke off	installed new clamp	Daniel Massner	25.00
Labor - Jones Trucks	136496 Park light s on hood not working only signal lights .	Diagnose problem and found blown fuse. Check wiring no problems found and shake wiring left lights on for 1 hour and fuse did not blow.	Kevin Thornton	50.00
Labor - Jones Trucks	136497 passenger side front axle		Service Writer	.00
Labor - Jones Trucks	136497 Park light s not working	completed	Kevin Thornton	.00
Tractor SERVICE	250 Hours or 25000 kms / Repairs	full service and pm/ repairs on axle gasket leaking/ installed new gasket and torqed axle nuts too 100F.P/ installed new air line / 7 way hanger	Daniel Massner	975.00
Unit In/Out Shop - Truck / ...	Move unit in or out of the shop/washbay	moved unit outa shop	Daniel Massner	25.00
Labor - Jones Trucks	#2A RHS axle gasket leaking	Start on removing axle	Kevin Thornton	25.00
Labor - Jones Trucks	Front diff oil level	Check front diff oil level after gasket was changed.	Kevin Thornton	25.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
SPC500010047, 10W-30 Bulk Oil		42.00	4.16	174.72
BD50000, High Efficiency Dual-Flow		1.00	39.86	39.86
BF46129, Filters		1.00	48.99	48.99
177-3004, Tender Kit 16" - Single		1.00	13.87	13.87
9888, TEC-Clamp 3 Hole		1.00	7.93	7.93

Total Labor	1,125.00
Total Parts	285.37
Total Returns	.00
Total Sublet	.00
Shop Supplies	112.50
Invoice Total	1,522.87

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 22698
Date: 03/14/2024

Completed Date: 09/20/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 03/14/2024
Entered By: Aleda

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR [03.14.24 Tony] 136393 added 2 litres of antifreeze to reservoir		Service Writer	100.00
Labor - Jones Trucks	134784 missing A/C belt		Service Writer	100.00
Labor - Jones Trucks	134547 Air conditioning not working.		Service Writer	100.00
Labor - Jones Trucks	DVIR [03.15.24 Tony] 136407 hose clamp for the air to air boot broke off		Service Writer	100.00
Labor - Jones Trucks	DVIR [03.15.24 Tony] 136406 antifreeze leak.		Service Writer	100.00
Labor - Jones Trucks	Charging system not working	Voltage gauge reading 11 volts. Diagnose problem test charging system twice and alt is charging. 14.15 volts and passes on the Snap on charging system tester. Remove all cables on bateries and inspect end and positive were a little bit green and install cables to start diagnose guage. Start unit and now gauge is reading proper 13.8 volts.	Kevin Thornton	175.00
Labor - Jones Trucks	Charging system not working	Remove loose and seized rear hold down bolts. Remove damage rivet nut and repair threads on hold bolt and install bolt with a nut and lock washer. Front hold down bolt not installed when batteries were replaced last. Remove striped rivet nut and install Hold down bolt with nut and lock washer. Clean corision off all positive cable ends and replace small wire end. Clean all negitive cables. Hook up batereies and test charging system Key on 12 volts on gauge in dash and running 14 volts and when starting turns over better.	Kevin Thornton	650.00
ORDER PARTS / SUBLET	valve assy water	Edm kw 02NP782496	Service Writer	.00
Labor - Jones Trucks	charging system not working and coolant leaks		Kevin Thornton	100.00
ORDER PARTS / SUBLET	ball valve 1/2 in M NPT	SIF 001-172140	Service Writer	.00
Labor - Jones Trucks	Coolant leaks	Install Heater valve. Replace 2 heater hoses . Fill with coolant and park unit in wash bay.	Kevin Thornton	300.00
Labor - Jones Trucks	service call truck moving	service from tony truck would not move. Put power divder in and he got it move he going to limp it back to the shop	Kevin Thornton	100.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP782496 Supplier: Edmonton Kenworth Ltd.	valve assy water	1.00	218.60	218.60
	Invoice: 001-172140 Supplier: SIF Superiors Industrial Frictions Ltd.	ball valve 1/2 in M NPTx1	1.00	19.87	19.87

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Total Labor	1,825.00
Total Parts	.00
Total Returns	.00
Total Sublet	238.47
Shop Supplies	206.35
Invoice Total	2,269.82

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 22567
Date: 01/11/2024

Completed Date: 09/24/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 01/11/2024
Entered By: Aleda

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR [01.11.24 Tony] 135529 Stop engine light on	Perform comp. diag. again, open up the issues, removed the DPF & DOC for testing/cleaning! Talk with the DPF comp. tech...	Laszlo Sarkozi	100.00
Labor - Jones Trucks	DVIR [01.09.24 Tony] 135573 wiper blades require replacement	installed wiper blads	Daniel Massner	100.00
Labor - Jones Trucks	DVIR [01.01.01 Tony] 135483 Rock chip	Veer to come and replace	Service Writer	100.00
ORDER PARTS / SUBLET	The DPF Company - pick up DPF and DOC for cleaning.	Invoice# 23635	Service Writer	.00
Labor - Jones Trucks	DVIR [01.11.24 Tony] 135529 Stop engine light on	Perform comp. diag. on SCR system and ...	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	Happy Tire - Change over	Invoice# 15716	Service Writer	.00
Labor - Jones Trucks	Amber Check engine light is ON still and the DPF pluged up warning came back on right away after a good system test...	Mount the DOC & DPF back with new gaskets and replaced the Preasure Differential Sensor, perform a Aftertreatment system test - PASS, but DPF pluged up warning came back on immediately - probably cleaned, used DPF or DOC is done its lifetime! Inspect Inlet NOx sensor and its wire harness - all good!	Laszlo Sarkozi	350.00
ORDER PARTS / SUBLET	The DPF Company - clamps for filter	Invoice# 23697	Service Writer	.00
Labor - Jones Trucks	side step removed for DPF and DOC	put P.S sidestep back on	Daniel Massner	100.00
ORDER PARTS / SUBLET	DGN - Did tech support and updated the calibration and aftertreatment system	Invoice# 2725	Service Writer	.00
Labor - Jones Trucks	DVIR [02.14.24 Tony] 135717 side marker lights shorting out when on		Service Writer	100.00
Labor - Jones Trucks	DVIR[02.16.24 Tony] 135542 short in markers and taillights .	founf wires rubbing on fram/ fixed up and good to go	Daniel Massner	100.00
ORDER PARTS / SUBLET	Veer - Replaced windshield	Invoice# 000314	Service Writer	.00
Tractor SERVICE	250 Hours or 25000 kms	full service and pm	Daniel Massner	600.00
Labor - Jones Trucks	Service repairs	all repairs on unit /small coolant leak / crosover line haning low tied up / changed out battires	Daniel Massner	250.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 15716 Supplier: Happy Tire Corporation	tire rotationx4	1.00	105.00	105.00
	Invoice: 23635 Supplier: The DPF Company	DPF Restoration and cleaning	1.00	828.00	828.00
	Invoice: 23976 Supplier: The DPF Company	v-band clamp, gasket, pipe flange gasket, v-band clamp	1.00	203.60	203.60
	Invoice: 2725 Supplier: DGN Truck & Trailer Repair Ltd.	Tech support, updated calibration and after treatment system	1.00	3,460.00	3,460.00
	Invoice: 000314 Supplier: Veer Windshield & Tire / Metro Tire Edmonton	windshield replacement	1.00	210.00	210.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount

Total Labor	1,900.00
Total Parts	.00
Total Returns	.00
Total Sublet	4,806.60
Shop Supplies	670.66
Invoice Total	7,377.26

JONES
TRANSPORTATION INC.

Date: FEB/23/2024
Unit # 9107
Odometer Reading: 1289849
Hour Reading: 24531.9
Work Order # 22567

✓ CHECKED & OK
/ ADJUSTED
✓ REPAIR or REPLACEMENT REQUIRED
✓ REPAIRED, REPLACED or COMPLETED

Service interval as per Manufacturer's Specification

TRUCK / TRACTOR

BODY & FRAME	▲	★
Body		1
Frame & Cargo Body	11	3
Bumpers		1
Cab	2	
Coupling Devices	4	
Door Releases/Latches		1
Doors		1
Drive Shaft		6
Driver Controls	6	
Driver Seat	7	
Emergency Equipment & SafetyDevices	9	
Fenders		1
Fifth Wheel & Coupling Devices	4	31
General	13	23
Heater & Defroster	15	25
Horn	16	
Mirrors	14	7
Mudflaps		1
Sun Visors		1
Underbody		5

✓	Windshield & Windows	14	7
✓	Windshield Wipers & Washer	23	24
BRAKES			
✓	Air Brake System	1	14
✓	Brake Pedal		13
✓	Electric Hydraulic Brake System		16
✓	Mechanical Components		12
✓	Parking/Emergency Brake		15
ELECTRICAL COMPONENTS			
✓	Lamps & Reflectors	18	27
✓	Neutral Safety Starting Switch		26
STEERING			
✓	Steering Column & Box		18
✓	Steering Linkage		21
✓	Power Assist	19	
✓	Wheel Alignment (Visual)		19
FUEL & EXHAUST			
✓	Exhaust System	10	9
✓	Filler Cap & Fuel Lines		8
✓	Fuel System	12	8
✓	Fuel Tank		8

SERVICE		
✓	Complete Lubrication	30
✓	Oil Change	
✓	Check/Replace Air Filters	
✓	Check Diff Oil	
✓	Check Trans Oil	
✓	Check Power Steering Fluid	
✓	Check Front Hub Oil	
SUSPENSION		
✓	Suspension System	20 22
✓	Shock Absorber Condition	20 22
OK	Spring Condition	20 22
WHEELS & TIRES		
✓	Tires	21 28
	Torqued Fasteners	22 29
✓	Wheels, Hubs, Fasteners	22 29
OTHER		
✓	Cargo Securement	3
✓	Dangerous Goods	5

★ Inspected Per AR 121/2009 Schedule 2 Section # (as shown above ★)

▲ Inspected Per NSC Standard 13, Part 2, Schedule 1, # (as shown above ▲)

Notes: (1) small coolant Leak, (2) Scribe crossover line. Hanging Lamp

Rev 12.18

Signature: [signature]

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 22452
Date: 11/22/2023

Completed Date: 12/30/2023

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 11/22/2023
Entered By: Laszlo

Labor

Category	Description	Technician Notes	Mechanic	Amount
RE-TORQUE REQUIRED	ALL TIRES			25.00
Tractor CVIP	CVIP REQUIRED	Perform CVI & service + documentation for both!	Laszlo Sarkozi	1,000.00
Tractor SERVICE	250 Hours or 25000 kms	Completed with CVIP !	Laszlo Sarkozi	300.00
Labor - Jones Trucks	Power steering reservoir still leaks	completed with water pump core fix		100.00
Labor - Jones Trucks	Torque rods of front differential worn out	Remove 5th. wheel and the front diff. torque rods for replacement!	Laszlo Sarkozi	150.00
Labor - Jones Trucks	1 of the exhaust clamps broken/loose	Completed with other repairs for CVIP!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Front drive axle PS. wheel hub seal leaks	Replaced that seal (having dificulties to mount the new inner bearing on) and mount everything back on axle!	Laszlo Sarkozi	275.00
Labor - Jones Trucks	Coolant leak at the water pump core!	Assist to remove the pump & core then reseal them ...	Laszlo Sarkozi	225.00
Tractor SERVICE	250 Hours or 25000 kms	full servicde and pm/ moved to wash bay to wash back of unit	Daniel Massner	600.00
Tractor CVIP	CVIP REQUIRED	CVIP/ took off wheels took messurments/	Daniel Massner	700.00
Labor - Jones Trucks	CVIP repaires	removed whole 5th wheel and removed touqer bars/ installled new hub gasket/ put wheels back on/ ajausted brakes / drain coolant/ installed new coolant line/ starting to remove parts to get at water pump	Daniel Massner	400.00
Labor - Jones Trucks	Torque rods of front differential worn out	Mount up the new torque rods and mount back the 5th. wheel! Perform a test run!	Laszlo Sarkozi	225.00
Tractor SERVICE	250 Hours or 25000 kms	Finalize all the jobs!	Laszlo Sarkozi	150.00
Labor - Jones Trucks	Coolant leak at the water pump core!	removal of parts to get to water pump and housing/removed and cleaned all serfaces/ installed all parts back on/ helped laszlo with touq rods and 5th wheel/ put all coolant back into unit/ tested/ installed new power steer res and new lines.	Daniel Massner	700.00
Labor - Jones Trucks	DVIR [11.24.23 Tony] 135343 service engine light on		Service Writer	100.00
Labor - Jones Trucks	DVIR [11.27.23 Tony] 135137 rock chips on windshield	Moved to WO 22567	Service Writer	100.00
ORDER PARTS / SUBLET	Ed Ken - Seal rings, gasket o ring, fastener, torque rod	Invoice# 02NP754335	Service Writer	.00
ORDER PARTS / SUBLET	SIF - powern steering res and bushings - was taken back not the right part	Invoice - 001-160068	Service Writer	.00
Labor - Jones Trucks	7 way trailer cord plug worn out	Replaced that plug!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	7 way and air line holder broken	installed new	Daniel Massner	100.00
Labor - Jones Trucks	Air escaping from air compressor intake elbow	Replaced that rubber elbow!	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	SIF - bushing, torque rod, pwer steering res	Invoice# 001-159978	Service Writer	.00
ORDER PARTS / SUBLET	Ed Kenworth - hose- elbow	Invoice# 02NP758285	Service Writer	.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
BD50000, High Efficiency Dual-Flow		1.00	38.40	38.40
SPC500010047, 10W-30 Bulk Oil		42.00	4.16	174.72
90-0013, Clamp V Band - 5" Exhaust		1.00	17.31	17.31
449-4973, Pro-Torque Spindle Nut		1.00	69.95	69.95
180-10613, Drive Flange Gasket		4.00	2.17	8.68
47691XT, Scotseal X-Treme Wheel Seal		2.00	55.06	110.12
6122215, Paccar Belt 12 Ribs 2215mm		1.00	100.99	100.99

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP754335 Supplier: Edmonton Kenworth Ltd.	Seal rings, gasket o ring, fastener, torque rod	1.00	2,032.10	2,032.10
	Invoice: 001-159978 Supplier: SIF Superiors Industrial Frictions Ltd.	bushing, torque rod, power steering reservoir	1.00	744.15	744.15
	Invoice: 001-160068 Supplier: SIF Superiors Industrial Frictions Ltd.	power steering rod, torque rod, bushing returns	1.00	-744.15	-744.15
	Invoice: 02NP758285 Supplier: Edmonton Kenworth Ltd.	hose elbow	1.00	76.54	76.54

Total Labor	5,450.00
Total Parts	520.17
Total Returns	.00
Total Sublet	2,108.64
Shop Supplies	755.86
Invoice Total	8,834.67

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 22160
Date: 08/15/2023

Completed Date: 09/20/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 08/15/2023
Entered By: Aleda

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	P.S second axle air bag for air ride blow up	removed wheels for space/ removed old air bag/ replased with new air bag/ put all back together !	Daniel Massner	100.00
Labor - Jones Trucks	Engine Heater Cord missing	removed Battire cover/ traced back Existing 3 way wires for engine heater/ installed new plug and tide up	Daniel Massner	100.00
Labor - Jones Trucks	missing mud flap	making up mud flap for unit	Daniel Massner	100.00
Labor - Jones Trucks	Check Engine lights is on due to Intake NOx sensor problem	Perform comp. diag. and open up the possible issues! Check out the sensor and its wire harness!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Water in the Fuel mulfunction message	Mount new/used sensor on the wires and requested a new	Laszlo Sarkozi	100.00
Labor - Jones Trucks	DVIR [08.17.23 Tony] 134231 air and electric lines need to be secured up			100.00
Labor - Jones Trucks	DVIR [08.22.23 Tony] 134456 Exhaust service required light on			100.00
Labor - Jones Trucks	DVIR [08.22.23 Tony] 133941 transmission service light flashing			100.00
Labor - Jones Trucks	DVIR [08.22.23 Tony] 133941 ABS light comes on periodically since air bag was replaced			100.00
Labor - Jones Trucks	DVIR [08.25.23 Tony] 134483 headache rack handles require replacement won't stay closed	drilling/removed/ installed new x2	Daniel Massner	100.00
Labor - Jones Trucks	DVIR [08.25.23 Tony] 134483 mudflap hangers requires spot weld to prevent twisting up	Brand new brackets mounted on both sides!	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	Diamond Detailing	Diamond Detailing 1050		.00
Tractor SERVICE	250 Hours or 25000 kms	oil service and pm	Daniel Massner	300.00
Labor - Jones Trucks	4 lights on headache rack out	changed out lights	Daniel Massner	100.00
Labor - Jones Trucks	power steer ressivour leaks	removed oil/ removed old clamp/put on gasket maker/put together/ filled and cleand	Daniel Massner	100.00
Labor - Jones Trucks	D.S steer hub cap leaking oil	removed and installed new/ filled up	Daniel Massner	100.00
Labor - Jones Trucks	hood mouting bolt missing	adjusting/lining back up for new bolt	Daniel Massner	100.00
Labor - Jones Trucks	Somthing wrong with fan clutch	Boosted up unit/ran and tested/ inspected for noise and air leek (notthing good to go	Daniel Massner	100.00
Unit In/Out Shop - Truck / ...	Move unit in or out of the shop/washbay	moved unit outta dshop	Daniel Massner	100.00
Tractor SERVICE	250 Hours or 25000 kms	Finalize service & doc.	Laszlo Sarkozi	300.00
Labor - Jones Trucks	DVIR [08.31.23 Tony] 134547 Air conditioning not working	Compressor seized, belt broken off!	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	SIF - T handle	SIF 001-150924	Service Writer	.00
ORDER PARTS / SUBLET	Diamond Shine - Detailing of unit	Diamond detailing 1050 - duplicate entry	Service Writer	.00
ORDER PARTS / SUBLET	gasket, clamp	Edm KW 02NP739612	Service Writer	.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
PS5266-X, Straight blade plug		1.00	20.00	20.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
SPC500010047, 10W-30 Bulk Oil		40.00	4.16	166.40
BD50000, High Efficiency Dual-Flow		1.00	39.86	39.86
1612, CR Scotseal - Hub Cap		1.00	32.33	32.33
92420, Oval Lamp Grommet		1.00	.01	.01
91400, Light 2.5" Gromet Grote		2.00	.80	1.60
G1032, G2 LED 2.5" High Count Red		2.00	7.37	14.74

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 1050 Supplier: Diamond Shine Detailing	detailing	1.00	380.00	380.00
	Invoice: 001-150924 Supplier: SIF Superiors Industrial Frictions Ltd.	t-handle stainless steel	1.00	121.50	121.50
	Invoice: 02NP739612 Supplier: Edmonton Kenworth Ltd.	gasket, clamp	1.00	26.61	26.61

Total Labor	2,400.00
Total Parts	274.94
Total Returns	.00
Total Sublet	528.11
Shop Supplies	292.81
Invoice Total	3,495.86

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 21957
Date: 06/05/2023

Completed Date: 09/19/2024

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 06/05/2023
Entered By: Laszlo

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	Lack of power, RPM doesn't go above 1600 !	Perform comp. diag. on engine and open up some problems!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	DVIR - Air bag dump switch light not working. 01.09.23			100.00
Labor - Jones Trucks	DVIR - Service Advise light on dash. 01.09.23			100.00
Labor - Jones Trucks	DVIR - Audible Air Leak tractor brake release button. 01.13.23			100.00
Labor - Jones Trucks	DVIR [03.20.2023-Tony] Air nozzle under drivers seat slowly leaking air.			100.00
Labor - Jones Trucks	DVIR [04.19.2023-Tony] passenger side steer tire wearing on one spot.			100.00
Labor - Jones Trucks	DVIR [04.19.2023-Tony] turning hard			100.00
Unit In/Out Shop - Truck / ...	Move unit in or out of the shop/washbay	moved out of shop	Daniel Massner	100.00
Labor - Jones Trucks	Block heater plug missing			100.00
Labor - Jones Trucks	oil leaking from oil pan	installed new oil pan gasket	Daniel Massner	100.00
Labor - Jones Trucks	removed TCM for 9109	removed TCM for another unit (9109)	Daniel Massner	100.00
Labor - Jones Trucks	PUT TCM BACK IN UNIT	installed TCM back into unit	Daniel Massner	100.00
Labor - Jones Trucks	Lack of power, RPM doesn't go above 1600 !	draining coolant	Daniel Massner	100.00
ORDER PARTS / SUBLET	Turbo Actuator Needed	Ordered from GCL Diesel 815672	Service Writer	.00
Labor - Jones Trucks	Lack of power, RPM doesn't go above 1600 !	Replaced/Mount the new Actuator on new VGT, perform calibration! Mount all the disassembled engine parts back on & refill the coolant! Put batt. charger on to boost the truck! perform test run & finalize the repairs!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	DVIR [06.20.2023-Tony] 133859 Engine stall when pulling loaded trailer. Check engine light on.	Perform comp. diag. on engine, read out the fault codes again - only 1 inactive code is present! Inspect the pre-fuel filter & housing, removed them and by-passed that fuel lines! Take it for test drive twice !	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Lack of power, RPM doesn't go above 1600 !	drining coolant and helping laszlo wiyh terbo	Daniel Massner	100.00
Labor - Jones Trucks	Lack of power, RPM doesn't go above 1600 !	Perform comp. diag. on engine operation again, disassembled and inspected the VGT & its actuator!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	5th. wheel sometimes doesn't lock in, I have to repeate the hook up	Move the truck in & out, wash the 5th. wheel and removed it for rebuild ! Rebuild and reinstall it, grease it up... Inspect steering/front wheel king pins and bearings!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	5th. wheel sometimes doesn't lock in, I have to repeate the hook up	washed up 5th wheel and helped remove and install with forklift	Daniel Massner	100.00
Labor - Jones Trucks	Lack of power, RPM doesn't go above 1600 !	Replaced the VGT and removed the old actuator!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Lack of power, RPM doesn't go above 1600 !	Mount the new actuator on new VGT and all the engine parts back! Put a booster pack on batteries and perform a test run, finalize the repaires!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	DVIR [06.27.23 - Tony] 133874 2 lights out on back jones yard Acheson ab			100.00
ORDER PARTS / SUBLET	Rebuild kit for FW35	SIF 143628		.00

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR [06.27.23 - Tony] 133703 Check engine light on and noise coming from front of Engine			100.00
Labor - Jones Trucks	DVIR [04.19.23 -Tony] Passenger side steer tire wearing on one spot, Turning hard			100.00
Labor - Jones Trucks	DVIR [07.05.23 Jason] Clipped a bird, bottom cover of mirror went flying			100.00
RE-TORQUE COMPLETED	DS/SP steer tries	re torqued complet on both steers	Daniel Massner	.00
Labor - Jones Trucks	DVIR [07.18.23 Tony] 134127 added 5 litres motor oil			100.00
Labor - Jones Trucks	unit will not start/ low volts	put on booster	Daniel Massner	100.00
Labor - Jones Trucks	DVIR [08.10.23 Kevin Brown] Check engine light came on.. truck in the yard			100.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
M90684, Oil Pan Gasket		1.00	129.61	129.61
3684284CUM, Washer, Sealing		1.00	5.95	5.95
5264570, Gasket, Oil drain		1.00	4.51	4.51
4298975, Lock Nut		4.00	12.08	48.32
4966441, Gasket-Exh Out Connection		1.00	17.47	17.47
561-29475, Turbo V-Band Clamp 4.75		1.00	8.15	8.15
3684359, Gasket EXH out connection		1.00	.00	.00
FW35, FIFTH WHEEL HOLLAND (USED)		1.00	500.00	500.00

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 815672 Supplier: GCL Diesel Injection Service	ISX VGT actuator kit	1.00	1,578.00	1,578.00
	Invoice: 001-143628 Supplier: SIF Superiors Industrial Frictions Ltd.	rebuild kit for FW35	1.00	452.51	452.51
	Invoice: 821141 Supplier: GCL Diesel Injection Service	core credit	1.00	-175.00	-175.00
	Invoice: 815672 Supplier: GCL Diesel Injection Service	core charge	1.00	175.00	175.00

Total Labor	2,800.00
Total Parts	714.01
Total Returns	.00
Total Sublet	2,030.51
Shop Supplies	483.05
Invoice Total	6,027.57

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 21587
Date: 01/10/2023

Completed Date: 06/08/2023

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 01/10/2023
Entered By: Shuzelle

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	DVIR - Air bag dump switch light not working. 01.09.23	moved to 21957		100.00
Labor - Jones Trucks	DVIR - Service Advise light on dash. 01.09.23	moved to 21957		100.00
Labor - Jones Trucks	DVIR - air dump valve for suspension very slow releasing air. 01.13.23	air hose of the exh. port pinched - removed it	Laszlo Sarkozi	100.00
Labor - Jones Trucks	DVIR - Audible Air Leak tractor brake release button. 01.13.23	moved to 21957		100.00
Wash Bay per hour soap c...	Wash bay per hour soap charge @ 2.50/ Minute		Harisch De Costa	150.00
Tractor SERVICE	250 Hours or 25000 kms	oil service	Daniel Massner	300.00
Labor - Jones Trucks	Rear structure leaks oil bad	Trany jobs -	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Coolant leaks out from DEF dozer injector hoses	Start to work on those coolant lines and replaced the doser nozzle!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Oil pan gasket should be replaced	moved to 21957		100.00
Labor - Jones Trucks	Rear structure leaks oil bad	starting to remove parts	Daniel Massner	100.00
Labor - Jones Trucks	Rear structure leaks oil bad	remoing oil cooler and wire harness	Daniel Massner	100.00
Labor - Jones Trucks	Rear structure leaks oil bad	Removed the drive line, exh. pipes, frame supports, start to work on the wires...	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	appt for resshaping for the fly wheel	Edmonton Brake & Clutch [214154]		.00
Labor - Jones Trucks	Rear structure leaks oil bad	trany/bell house/clutch pack/fly wheel removal	Daniel Massner	100.00
Labor - Jones Trucks	Rear structure leaks oil bad	Remove the trany & clutch from engine! Removed the Bell housing and clean up all the surfaces for new seals !	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	parts / injector & gasket	Edmonton Kenworth		.00
Labor - Jones Trucks	MUX3 & CECU moved to #9108 for tests	Mount both of those ECUs back and all the interior!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Rear structure leaks oil bad	Mount the bell housing, rear crankshaft seal, pilot bearing, flywheel back !	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Rear structure leaks oil bad	Mount the bell housing, rear crankshaft seal, pilot bearing, flywheel back/ wire harness	Daniel Massner	100.00
Labor - Jones Trucks	new dozor injector	helping install / remove dozer and lines	Daniel Massner	100.00
Labor - Jones Trucks	Rear structure leaks oil bad	Mount the clutch & trany back on engine! Mount all the disassembled drive line &... parts back! Perform comp. diag. to cancell the fault codes and...	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Coolant leaks out from DEF dozer injector hoses	Replaced both coolant lines and the DEF line of the doser nozzle! Cleared all the negine codes!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	P.S marker light out and siglan	repaired all green death in lines	Daniel Massner	100.00
Tractor SERVICE	250 Hours or 25000 kms	full service and pm	Daniel Massner	300.00
Unit In/Out Shop - Truck / ...	Move unit in or out of the shop/washbay	moved outa shop	Daniel Massner	100.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
SPC500010047, 10W-30 Bulk Oil		51.00	4.16	212.16

JONES
TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
BD50000, High Efficiency Dual-Flow		1.00	38.40	38.40
P27-1181-002, Switch-Mirror Single Aix LH & RH		1.00	240.48	240.48
63062RSC3, Koyo Bearing M2209		1.00	18.33	18.33
562.U3104SS, Exhaust Band Clamp Performed 4"		1.00	7.73	7.73
562.U3105SS, Exhaust Band Clamp Performed 5"		2.00	13.10	26.20
SPC 500010047, ROTELLA T5 10W-30 Bulk		41.00	4.33	177.53
BD50000, High Efficiency Dual-Flow		1.00	38.40	38.40
BF46129, Filters		1.00	43.71	43.71
PF46081, FUEL ELEMENT		1.00	38.16	38.16

Sublet

Category	Description	Invoice Description	Quantity/Hours	Price/Rate	Amount
	Invoice: 02NP688334 Supplier: Edmonton Kenworth Ltd.	HOSE ASSY	1.00	689.01	689.01
	Invoice: 02NP685223 Supplier: Edmonton Kenworth Ltd.	INJECTOR	1.00	643.86	643.86
	Invoice: 02NP685223 Supplier: Edmonton Kenworth Ltd.	GASKET	1.00	62.27	62.27
	Invoice: 02NP685223 Supplier: Edmonton Kenworth Ltd.	SCREW HEXAGON HEAD	1.00	25.11	25.11
	Invoice: 02NP686656 Supplier: Edmonton Kenworth Ltd.	gasket flywheel housing	1.00	128.34	128.34
	Invoice: 02NP686609 Supplier: Edmonton Kenworth Ltd.	Gasket, kit seal, clamp	1.00	250.51	250.51
	Invoice: 02NP686666 Supplier: Edmonton Kenworth Ltd.	returned gasket housing	1.00	-29.58	-29.58
	Invoice: 001-214154 Supplier: Edmonton Brake & Clutch Ltd.	enviro and shop supplies	1.00	81.75	81.75

Total Labor	2,750.00
Total Parts	841.10
Total Returns	.00
Total Sublet	1,851.27
Shop Supplies	460.13
Invoice Total	5,902.50

JONES
TRANSPORTATION INC.

Date: FEB/17/2023
Unit #: 9107
Odometer Reading: 933438
Hour Reading: 23454.8
Work Order #: 21587

✓ CHECKED & OK
/ ADJUSTED
✓ REPAIR or REPLACEMENT REQUIRED
✓ REPAIRED, REPLACED or COMPLETED

Service interval as per Manufacturer's Specification

TRUCK / TRACTOR

BODY & FRAME	▲	★
Body		1
Frame & Cargo Body	11	3
Bumpers		1
Cab	2	
Coupling Devices	4	
Door Releases/Latches		1
Doors		1
Drive Shaft		6
Driver Controls	6	
Driver Seat	7	
Emergency Equipment & SafetyDevices	9	
Fenders		1
Fifth Wheel & Coupling Devices	4	31
General	13	23
Heater & Defroster	15	25
Horn	16	
Mirrors	14	7
Mudflaps		1
Sun Visors		1
Underbody		5

Windshield & Windows	14	7
Windshield Wipers & Washer	23	24
BRAKES		
Air Brake System	1	14
Brake Pedal		13
Electric Hydraulic Brake System		16
Mechanical Components		12
Parking/Emergency Brake		15
ELECTRICAL COMPONENTS		
Lamps & Reflectors	18	27
Neutral Safety Starting Switch		26
STEERING		
Steering Column & Box		18
Steering Linkage		21
Power Assist	19	
Wheel Alignment (Visual)		19
FUEL & EXHAUST		
Exhaust System	10	9
Filler Cap & Fuel Lines		8
Fuel System	12	8
Fuel Tank		8

SERVICE		
Complete Lubrication		30
Oil Change		
Check/Replace Air Filters		
Check Diff Oil		
Check Trans Oil		
Check Power Steering Fluid		
Check Front Hub Oil		
SUSPENSION		
Suspension System	20	22
Shock Absorber Condition	20	22
OK Spring Condition	20	22
WHEELS & TIRES		
Tires	21	28
Torqued Fasteners	22	29
Wheels, Hubs, Fasteners	22	29
OTHER		
Cargo Securement	3	
Dangerous Goods	5	

★ **Inspected Per AR 121/2009 Schedule 2 Section # (as shown above ★)**

▲ **Inspected Per NSC Standard 13, Part 2, Schedule 1, # (as shown above ▲)**

Notes: Rear Structure Leaking oil Bad, Oil Pan gasket
Coolant leak coming from Dozer

Rev 12.18

Signature:

JONES TRANSPORTATION
ACHESON, ALBERTA, CANADA

DISPATCH# 780-453-1156
DISPATCH FAX# 780-453-1146
DISPATCH@JONESTRANSPORTATION.CA
WWW.JONESTRANSPORTATION.CA

PROUDLY SERVING CANADA AND THE USA WITH FULL LOAD AND LTL SERVICE

BULK · FLATDECKS · STEPDECKS · DOUBLE DROP DECKS · VANS
TRACTOR SERVICE · INTERMODAL CONTAINERS / CHASSIS · TRANSLOADING

Equipment: 9107-J-PR-Jones Transportation

Work Order #: 21507
Date: 10/25/2022

Completed Date: 12/08/2022

Year: 2014
Make: Kenworth
Model: Construct

Serial Number: 1XKDD49X8ER969534
Date: 10/25/2022
Entered By: rormiston

Labor

Category	Description	Technician Notes	Mechanic	Amount
Labor - Jones Trucks	PS. fuel tank leaks diesel from cap!	Mount on the "Leak Defender" fitting	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	"Leak Defender" fitting from Heavy Truck Solutions	PO 180254	Laszlo Sarkozi	.00
Tractor CVIP	CVIP REQUIRED	Perform CVI & doc.	Laszlo Sarkozi	400.00
RE-TORQUE REQUIRED	Define Tire(s) / Position(s) or ALL TIRES	all drives have been retorqed	Daniel Massner	25.00
Tractor CVIP	CVIP REQUIRED	helped do CVIP messuerd/ removed wheels/ put all back on	Daniel Massner	400.00
Labor - Jones Trucks	DVIR# PS. rear fender damaged	Mount a new fender and antisailing bracket on!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	DVIR# PS. rear fender damaged	removing fender/ bending braket/ helping install	Daniel Massner	100.00
Labor - Jones Trucks	No or low battery charge	Put batt. charger on then boosted it up and moved into the shop for inspection!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	No or low battery charge	put on booster to bring inside	Daniel Massner	100.00
Tractor SERVICE	250 Hours or 25000 kms	service and repairs	Daniel Massner	300.00
Labor - Jones Trucks	No or low battery charge	Looking for replacement part, replaced that alternator, inspect the charge!	Laszlo Sarkozi	100.00
Labor - Jones Trucks	Ends of trailer cord worn out	Replaced 1 end	Laszlo Sarkozi	100.00
ORDER PARTS / SUBLET	Part #8600889 "DELCO REMY" new alternator (found in a really old box on the shelf in the shop)		Laszlo Sarkozi	.00

Parts

Description	Description Detail	Quantity/Hours	Price/Rate	Amount
TU-1031, Anti Sail Bracket - Chrome		1.00	1.00	1.00
15-730, Male 7 Wire Plug		1.00	11.42	11.42
SPC500010047, 10W-30 Bulk Oil		38.00	4.16	158.08
BD50000, High Efficiency Dual-Flow		1.00	36.66	36.66
00212335P, LED BULLET AMBER ACCENT LIGHT		1.00	.00	.00

Total Labor	1,825.00
Total Parts	207.16
Total Returns	.00
Total Sublet	.00
Shop Supplies	182.50
Invoice Total	2,214.66

JONES
TRANSPORTATION INC.

Date: Dec 18 22

Unit # 907

Odometer Reading: 928370

Hour Reading: 23136.2

Work Order # 21507

✓ CHECKED & OK

/ ADJUSTED

R REPAIR or REPLACEMENT REQUIRED

X REPAIRED, REPLACED or COMPLETED

Service interval as per Manufacturer's Specification

TRUCK / TRACTOR

BODY & FRAME	▲	★
Body		1
Frame & Cargo Body	11	3
Bumpers		1
Cab	2	
Coupling Devices	4	
Door Releases/Latches		1
Doors		1
Drive Shaft		6
Driver Controls	6	
Driver Seat	7	
Emergency Equipment & SafetyDevices	9	
Fenders		1
Fifth Wheel & Coupling Devices	4	31
General	13	23
Heater & Defroster	15	25
Horn	16	
Mirrors	14	7
Mudflaps		1
Sun Visors		1
Underbody		5

Windshield & Windows	14	7
Windshield Wipers & Washer	23	24
BRAKES		
Air Brake System	1	14
Brake Pedal		13
Electric Hydraulic Brake System		16
Mechanical Components		12
Parking/Emergency Brake		15
ELECTRICAL COMPONENTS		
Lamps & Reflectors	18	27
Neutral Safety Starting Switch		26
STEERING		
Steering Column & Box		18
Steering Linkage		21
Power Assist	19	
Wheel Alignment (Visual)		19
FUEL & EXHAUST		
Exhaust System	10	9
Filler Cap & Fuel Lines		8
Fuel System	12	8
Fuel Tank		8

SERVICE		
Complete Lubrication		30
Oil Change		
Check/Replace Air Filters		
Check Diff Oil		
Check Trans Oil		
Check Power Steering Fluid		
Check Front Hub Oil		
SUSPENSION		
Suspension System	20	22
Shock Absorber Condition	20	22
OK Spring Condition	20	22
WHEELS & TIRES		
Tires	21	28
Torqued Fasteners	22	29
Wheels, Hubs, Fasteners	22	29
OTHER		
Cargo Securement	3	
Dangerous Goods	5	

★ **Inspected Per AR 121/2009 Schedule 2 Section # (as shown above ★)**

▲ **Inspected Per NSC Standard 13, Part 2, Schedule 1, # (as shown above ▲)**

Notes: Bell housing Studs to leak | oil pan + small coolant leak

Rev 12.18

Signature: