Y38-1
Nov

2012 Peterbilt 1NPTP4EX7CD167922

December	2024	Rebuilt engine by Adrenaline Diesel
January	2025	New Turbo from GCL
January	2025	New engine mounts
March	2025	New Injectors from GCL
May	2025	New 30/30 break pot
		Wheel alignment
July	2025	New fuel gauge and sender
		Rear slack ADJ
August	2025	Second drive axle pinion seal
		Transmission and Drive axle fluids 75/90
September	2025	Window regulator replaced
		HD transmission cooler and lines
		Front drive axle air bags
		New PTO from Drive Products
		New Hvac control

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

RED RAM
TRUCK PARTS & SERVICE

Invoice: **2503381**
Date: **5/27/2025**

Bill To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA
P: 780-257-9077

Ship To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA

Remit Payment To
Red Ram Sales Ltd
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
4202	COD	5/27/2025	Cory Rudyk	ST-7922-PO-1929	Redekopp, Mike	Lucy

Item	Description	Quantity	Rate	Amount
	Complaint: FRONT STRUCTURE LEAKING OIL.			
	Cause: Customer request Type: Customer Request			
Labor	Correction: Engine / Lubrication / STARTED DRAINING COOLANT AND ENGINE OIL. REMOVED WIRING HARNESS AND INTAKE/ COOLANT PIPES, UNBOILTED AC CONDENSOR AND CAREFULLY SET ASIDE AND REMOVED COOLING PACK. UNPLUGGED ENGINE/OE WIRING HARNESS RUNNING ALONG FRONT OF ENGINE AND SET ASIDE DISCONNECTING ALL RELATED PLUGS MOUNTED ACROSS FRONT STRUCUTURE. REMOVED AC COMPRESSOR/ ALTERNATOR WITH ACCESSORY MOUNT BRACKET, BELTS, OIL PAN AND FRONT COVER. USED HOIST TO LIFT FAN HUB/ BLADE OFF AND THEN ON FRONT ENGINE LIFTING EYE TO REMOVE FRONT MOTOR MOUNT, CRANK PULLEY AND DAMPER. BARRED ENGINE OVER TO PIN/ WEDGE MARK AND THEN REMOVED MOUNTING BOLTS FOR FUEL PUMP, UNBOLTED AIR COMPRESSOR AND SLID BACK. MARKED GEARS AND REMOVED CAM, SISSOR AND IDLER GEARS. THEN UNBOLTED FRONT STRUCTURE AND REMOVED FROM BLOCK. CLEANED GASKET MATING AND CRANK END SURFACES, PAN GASKET SURFACE, CLEANED GEARS AND WASHED FRONT STRUCTURE, CLEANED HARDWARE AND REPLACED SEALING WASHERS/ REQURED COMPONENETS. INSTALLED FRONT STRUCTURE WITH NEW GASKET AFTER INSPECTING FOR CRACKS ONTO BLOCK, TORQUED ALL BOLTS DOWN IN SEQUENCE TO SPEC.	24.00000	$146.95	$3,526.80

Item	Description	Quantity	Rate	Amount
	BOLTED FRONT MOUNT BACK ON, SET ENGINE BACK DOWN ON FRONT CROSSMEMBER AND BOLTED IN. INSTALLED GEARS PRE-LUBED AND LOADED SISSOR GEAR, PUT FRONT SEAL IN AND DAMPER/ PULLEY BACK ON CRANK. WHEN SETTING TIMING AND PUTTING CAMSHAFT AND IDLER GEARS IN, COULD NOT GET PROPER BACKLASH SET.....HAD ANOTHER TECH ASSIST AND TRIED MULTIPLE TIMES WITH REMOVING AND RE-INSTALLING CAM GEAR, BARRING ENGINE OVER AND IDLER GEAR WOULD BE OUT BY 0.015" EXCESSIVE LASH ONCE ENGINE ROTATED. HAD TO RE-PIN THE BLOCK AND INSERT TIMING WEDGE, INSTALL GEARS DRY SPIN ENGINE TO RE-SEAT CAM WEDGE, USE PULLER TO REMOVE GEARS AGAIN FOR 4 ATTEMPTS AT SETTING, RE SEATING AND GOING THROUGH TORQUE PROCEDURE FOR BOTH GEARS, USED ANOTHER GOOD USED CAM IDLER GEAR FROM INVENTORY SUSPECT PROBLEM WITH ORIGINAL IDLER HUB. WITH DIFFERENT GEAR WAS ABLE TO SET TIMING AND GET LASH ADJUSTED TO CUMMINS SPEC FINALLY. PUT OIL PAN BACK UP, INSTALLED FRONT COVER AND FAN HUB, GOT WIRING HARNESS BACK ON AND SECURED, BOLTED VALVECOVER ON, SHROUD AND INSTALLED RAD. FILLED UNIT W/ FRESH OIL - **Completed: 5/22/2025**			
Parts	Cap Screw	13.00000	$18.795	$244.34
Parts	Frt Structure Gasket	1.00000	$150.67	$150.67
Parts	Seal Rectangular	1.00000	$19.80	$19.80
Parts	Seal	1.00000	$19.075	$19.08
Parts	Seal Front Crankshaft	1.00000	$102.57	$102.57
Parts	Seal Front Cover	1.00000	$51.59	$51.59
Parts	Gasket	1.00000	$26.075	$26.08
Parts	Gasket Fuel Pump	1.00000	$38.325	$38.33
Parts	ISX Oil Pan Gasket	1.00000	$233.87	$233.87
Parts	3/4-10 NC Nylon Locknut	2.00000	$1.03504	$2.07
Parts	Ultra Black	1.00000	$17.6721	$17.67
Parts	Gasket, Camshaft Cover	1.00000	$17.44	$17.44
Parts	Seal, O Ring	1.00000	$29.41	$29.41
Parts	Gasket Adaptor	1.00000	$22.37	$22.37
			Subtotal	$4,502.09

Complaint: RADIATOR POSSIBLY LEAKING

Cause: Customer request Type: Customer Request

Item	Description	Quantity	Rate	Amount
Labor	**Correction:** Engine / Cooling / BROUGHT UNIT INTO SHOP, HOOKED UP COOLING SYSTEM PRESSURE TESTER AND CHECKED FOR WHERE POSSIBLE LEAK IS COMING FROM. LEAK AT 15 PSI IS COMING FROM COOLANT LINE THAT RUNS ABOVE AND PAST RIGHT REAR ENGINE MOUNT TO BUNK HEATER, HOSE RUBBED THROUGH ON BRACKET AND IS DRIPPING DOWN REAR STRUCTURE/ EXHAUST AREA. PUT A 5/8 UNION BARB ON THE END AFTER CUTTING 4 INCHES OUT, REPLACED A FOOT OF HOSE THAT RUNS UP TO STEEL LINE AT THE BACK OF THE HEAD AND PRESSURED AGAIN. DID NOT SEE ANY LEAKS COMING FROM RAD, REMOVED AND PRESSURE TESTED COOLING PACK BY ITSELF SPRAYING WITH SOAPY WATER AND HEATING WITH HEAT GUN. FOUND BUBBLING AT BOTTOM LEFT IN THE VERY CORNER BEHIND SHROUD WHERE CORE MOUNTS TO BOTTOM PLASTIC. ORDERED NEW RADIATOR AND DISSASEMBLED OLD FRAME/ CHARGE AIR COOLER, WASHER TANK AND SURGE TANK. PUT NEW RAD IN AND BOLTED BACK TOGETHER, PUT AIR COOLER, TANK AC CONDENSOR BACK ON, INSTALLED IN UNIT CONNECTING RAD HOSES AND LINES. PRESSURE TESTED SYSTEM AGAIN ONCE FILLED W/ COOLANT TO CHECK OVER AGAIN FOR ANY MORE POSSIBLE LEAKS. NO LEAKS FOUND. - Completed: 5/22/2025	4.50000	$146.95	$661.28
Parts	5/8 Hose Splice	1.00000	$4.20572	$4.21
Parts	1/2 - 1 Clamp	2.00000	$4.67048	$9.34
Parts	Radiator	1.00000	$998.60	$998.60
Parts	5/8 Silicone Heater Hose	2.00000	$7.2248	$14.45
Parts	2.75"-3.06" T Bolt Clamp	2.00000	$27.4575	$54.92
Parts	Tie Wrap 15x0.30	12.00000	$0.49352	$5.92
Parts	7.5" x 3/16 Tie Wrap	12.00000	$0.1774	$2.13
			Subtotal	$1,750.85

Complaint: OIL AND FILTER CHANGE. GREASE TRUCK AS WELL.

Cause: Customer request Type: Customer Request

Labor	**Correction:** Chassis / Chassis / GREASED UNIT, CHANGED OIL, CHECKED AND TOPPED FLUIDS - Completed: 5/22/2025	1.00000	$146.95	$146.95
Parts	Oil Filter	1.00000	$93.90	$93.90
Parts	High Temp EP2 Grease	1.00000	$13.11	$13.11
Parts	ATF DEX III Transmission Oil	3.00000	$10.58	$31.74
Parts	15W40 CK-4 Synthetic Blend Oil	46.00000	$9.66	$444.36
			Subtotal	$730.06

Complaint: SUPPLY CUSTOMER PARTS

Cause: Customer request Type: Customer Request

Item	Description	Quantity	Rate	Amount
(Inspection)				
Labor	Chassis / Chassis / SUPPLY CUSTOMER PARTS - Completed: 5/22/2025	0.00000		$0.00
Parts	Sensor Pressure	1.00000	$282.76	$282.76
			Subtotal	$282.76

Unit: Lucy VIN: 1NPTP4EX7CD167922
2012 Peterbilt 367
In Service Date: 5/24/2024
Chassis: 1,245,116 Kilometers
Engine: 28,881 Hours

Labor	$4,335.03
Parts	$2,930.73
Shop Supplies	$303.45
Pre-Charge Subtotal	$7,569.21
GST (5% of $7,569.21)	$378.46
Total	$7,947.67
Payments & Credits	$0.00
Balance Due	$7,947.67

Work (Estimate) Authorized at 3:26PM 5/12/2025 by:



Workmanship: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) provides a limited warranty for a period of one (1) year on labor performed, exclusively covering defects in workmanship. This warranty expressly excludes coverage for parts, materials, misuse, neglect, or modifications made after the completion of service. Claims under this warranty must be submitted within one (1) year of service completion and are strictly limited to the correction of the original services provided.

Parts: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all warranties, expressed or implied, including but not limited to implied warranties of merchantability, fitness for a particular purpose, condition, quality, or suitability of parts sold. New parts may be subject to warranties provided by the original manufacturer. All used parts, including used engines, are sold on an "as-is" basis without warranty unless expressly specified in writing on the invoice.

Overhauled parts require the submission of a completed warranty form within thirty (30) days from the date of purchase. Failure to submit the warranty form within this period will result in a reduced warranty term of thirty (30) days from the date of purchase.

Acknowledgment of Terms and Conditions: By authorizing the work, the Buyer expressly acknowledges and agrees to these terms and conditions, including the "as-is" nature of used parts sales and the finality of all transactions with no returns, refunds, or exchanges permitted.

Vehicle Modifications Our warranty is void if the serviced vehicle has been altered from the manufacturer's original specifications, including but not limited to emissions modifications, structural changes, or engine tuning. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all liability for defects, failures, or operational issues resulting from such modifications. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) reserves sole discretion in determining the extent of any assistance offered in these cases.

Authorization for Additional Repairs or Service: The Customer hereby authorizes Red Ram Truck Parts & Service (Red Rams Sales Ltd) to perform repairs or services exceeding the original estimate by up to an additional amount of 15% without requiring further approval. Should additional costs exceed this threshold, the Service Provider shall obtain the Customer's consent before proceeding. Failure to obtain such consent does not relieve the Customer from the obligation to pay for authorized repairs or services performed.

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

RED RAM
TRUCK PARTS & SERVICE

Invoice: **2502794**
Date: **4/24/2025**

Bill To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA
P: 780-257-9077

Ship To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA

Remit Payment To
Red Ram Sales Ltd
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
4107	COD	4/24/2025	Cory Rudyk	CT7922-PO-1837	Rendell, Laura	Lucy

Item	Description	Quantity	Rate	Amount
Complaint: COMPLETE SERVICE				
Cause: Customer request Type: Customer Request				
Labor	**Correction:** Chassis / Chassis / COMPLETE SERVICE DRAINED THE OIL AND TOOK OFF THE OIL FILTER, FUEL FILTER, FUEL WATER FILTERS THEN CHECKED AIR FILTERS THEY WERE GOOD ,SO I PUT THEM BACK IN THEN ORDER THE OTHER FILTERS THEN ONCE I GOT THEM I FILL THE OIL FILTER UP THEM PUT IT ON. PUT ATF IN THE FUEL FILTER AND PUT THAT ON THE TRUCK AND CHANGE THE FUEL WATER FILTER THEN FILLED THE ENGINE UP WITH OIL THEN GREASED THE TRUCK. - Completed: 4/7/2025	2.50000	$146.95	$367.38
Parts	Oil Filter	1.00000	$93.90	$93.90
Parts	Fuel Filter	1.00000	$104.64	$104.64
Parts	ATF DEX III Transmission Oil	2.00000	$10.58	$21.16
Parts	10 OZ Tube Grease	2.00000	$11.26662	$22.53
Parts	Fuel Filter	1.00000	$88.8125	$88.81
Parts	15W40 CK-4 Synthetic Blend Oil	50.00000	$9.60	$480.00
			Subtotal	$1,178.42

Complaint: ABS LIGHT ON

Cause: Customer request Type: Customer Request

(Inspection)

Item	Description	Quantity	Rate	Amount
Labor	**Correction:** Brakes / Air Brakes / TEST THE WHEEL SPEED SENSORS ON L2 AND L3 AND FOUND THAT THE L2 WIRES GOING TO THE SENSOR ARE LOW ON VOLTS. WENT DOWN THE WIRING HARNESS TAKING OFF THE LOOM TRYING TO FIND A BREAK, BUT DIDNT FIND ANYTHING SO WENT TO THE NEXT CONNECTION IN THE WIRING AND TESTED TO SEE HOW MUCH VOLTAGE I WAS GETTING FROM THERE AND STILL WAS GET LOW VOLTAGE.KEPT GOING DOWN THE LINE TAKING OFF THE LOOM BUT THEN THE CUSTOMER WANTED HIS TRUCK, SO I PUT ALL THE LOOM BACK ON AND PLUG EVERTHING BACK IN. CUSTOMER TO BRING BACK AT LATER DATE FOR REPAIR. - Completed: 4/7/2025	1.70000	$146.95	$249.82
			Subtotal	$249.82

Unit: Lucy VIN: 1NPTP4EX7CD167922
2012 Peterbilt 367
In Service Date: 5/24/2024
Chassis: 1,223,621 Kilometers
Engine: 28,284 Hours

Labor	$617.20
Parts	$811.04
Shop Supplies	$43.20
Pre-Charge Subtotal	$1,471.44
GST (5% of $1,471.44)	$73.57
Total	$1,545.01
Payments & Credits	$0.00
Balance Due	$1,545.01

Workmanship: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) provides a limited warranty for a period of one (1) year on labor performed, exclusively covering defects in workmanship. This warranty expressly excludes coverage for parts, materials, misuse, neglect, or modifications made after the completion of service. Claims under this warranty must be submitted within one (1) year of service completion and are strictly limited to the correction of the original services provided.

Parts: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all warranties, expressed or implied, including but not limited to implied warranties of merchantability, fitness for a particular purpose, condition, quality, or suitability of parts sold. New parts may be subject to warranties provided by the original manufacturer. All used parts, including used engines, are sold on an "as-is" basis without warranty unless expressly specified in writing on the invoice.

Overhauled parts require the submission of a completed warranty form within thirty (30) days from the date of purchase. Failure to submit the warranty form within this period will result in a reduced warranty term of thirty (30) days from the date of purchase.

Acknowledgment of Terms and Conditions: By authorizing the work, the Buyer expressly acknowledges and agrees to these terms and conditions, including the "as-is" nature of used parts sales and the finality of all transactions with no returns, refunds, or exchanges permitted.

Vehicle Modifications Our warranty is void if the serviced vehicle has been altered from the manufacturer's original specifications, including but not limited to emissions modifications, structural changes, or engine tuning. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all liability for defects, failures, or operational issues resulting from such modifications. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) reserves sole discretion in determining the extent of any assistance offered in these cases.

Authorization for Additional Repairs or Service: The Customer hereby authorizes Red Ram Truck Parts & Service (Red Rams Sales Ltd) to perform repairs or services exceeding the original estimate by up to an additional amount of 15% without requiring further approval. Should additional costs exceed this threshold, the Service Provider shall obtain the Customer's consent before proceeding. Failure to obtain such consent does not relieve the Customer from the obligation to pay for authorized repairs or services performed.

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

RED RAM
TRUCK PARTS & SERVICE

Invoice: **2502093**
Date: **3/17/2025**

Bill To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA
P: 780-257-9077

Ship To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA

Remit Payment To
Red Ram Sales Ltd
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
4057	COD	3/17/2025	Cory Rudyk	ST-7992-PO-1665	Rendell, Laura	Lucy

Item	Description	Quantity	Rate	Amount
Complaint: CHANGE OUT ALL INJECTORS				
Cause: Customer request Type: Customer Request				
Labor	**Correction:** Engine / Fuel / TOOK VALVE COVER OFF. UNHOOKED INJECTOR WIRE HARNESS. TOOK OFF FUEL LINES AND TUBES. PULLED THEM OUT THEN REMOVED INJECTORS. CLEANED UP HOLES. INSTALLED NEW INJECTORS WITH NEW TUBES (CUSTOMER SUPPLIED) AND TORQUED TO SPEC. HOOKED UP WIRE HARNESS. PUT FUEL LINES BACK ON AND TORQUED TO SPEC. PUT VALVE COVER BACK ON. PROGRAMMED NEW TRIM CODES FOR INJECTORS.*** HAD PROBLEMS PROGRAMMING AFTERMARKET INJECTORS. FINALLY GOT PROGRAMMED***. RAN TRUCK UP TO TEMP. SENT ON ROAD TEST. - **Completed: 3/13/2025**	9.00000	$146.95	$1,322.55
Parts	Fuel Filter	1.00000	$81.74625	$81.75
Parts	Fuel Filter	1.00000	$87.4375	$87.44
Parts	Automatic Transmission Fliud	2.00000	$7.16	$14.32
Parts	Tie Wrap 15x0.30	10.00000	$0.4838	$4.84
			Subtotal	$1,510.90

Complaint: BAD BOOST LEAK AT TURBO

Cause: Customer request Type: Customer Request

(Inspection)

Item	Description	Quantity	Rate	Amount
Labor	**Correction:** Engine / Exhaust / FOUND LEAK AT TURBO ELBOW. REMOVED ELBOW AND FOUND ORING BLOWN OUT. INSPECTED ELBOW MOUNTING FLANGE, HAD DAMAG, WAS HIGH ON ONE SIDE. WOULD NOT SEAL PROPERLY. TOOK PICS TO SHOW CUSTOMER. DRAW FILE FLAT. REINSTALL ELBOW. HAD ANOTHER LEAK FROM TURBO COMPRESSOR HOUSING MOUNTING TO TURBO CENTER CARTRIDGE. CLAMP WAS NOT TORQUED POSSIBLY FROM SUPPLIER ASSEMBLY. REMOVED AND FOUND MATING SURFACE NOT FLAT DUE TO FRETTING CAUSED FROM BEING LOOSE. DRAW FILE FLAT AND INSTALL. TORQUE TAP CLAMP TO SPEC. CHECKED ALL OTHER CLAMPS. - Completed: 3/13/2025	3.00000	$146.95	$440.85
Parts	Seal, O Ring	1.00000	$17.8325	$17.83
Parts	Tie Wrap 15x0.30	4.00000	$0.4838	$1.94
Parts	Super Lube Syn Grease	1.00000	$23.9225	$23.92
Parts	Gasket	1.00000	$27.6325	$27.63
Parts	Turbo Drain Gasket	1.00000	$7.98	$7.98
			Subtotal	$520.15

Complaint: POSSIBLE TURBO ACTING UP.

Cause: Customer request Type: Customer Request

(Inspection)

Labor	**Correction:** Engine / Exhaust / DRAINED THE COOLANT. SWAPPED OUT ACTUATOR TO TRY TEST WITH. PUT COOLANT BACK IN AND RUN ENGINE. DID NOT CURE PROBLEM. DRAIN COOLANT AGAIN, TOOK THE EXHAUST OFF THE BACK OF THE TURBO. REMOVED INTAKE, OIL LINE, COOLANT LINES OFF THE TURBO. TOOK THE TURBO OFF THE TRUCK AND TOOK THE ACTUATOR OFF TO INSTALL ON TEST TURBO. ORDERED THE PARTS REQUIRED TO PUT THE TURBO ON THE TRUCK. PUT TEST TURBO ON ENGINE HOOKED ALL LINES BACK UP. TORQUED TURBO MOUNTING NUTS. THEN HOOKED UP THE COMPUTER TO THE TRUCK SO I COULD CALIBRATE THE ACTUATOR TO THE TURBO. FILLED THE TRUCK BACK UP WITH COOLANT. TESTED IT TO SEE IF IT WAS WORKING BETTER NOW. BUT IT WAS STILL NOT WORKING RIGHT THEY TOOK TRUCK FOR WEEKEND AND CAME BACK ON MONDAY AND I DRAINED THE COOLANT AND PULLED OFF THE TURBO AND REINSTALLED THERE TURBO HAD TO HOOK UP TO COMPUTER AND RESET THE ACTUATOR THEN INSTALLED AND FILLED BACK UP WITH COOLANT. - Completed: 3/13/2025	9.50000	$146.95	$1,396.03
			Subtotal	$1,396.03

Complaint: POSSIBLE PLUGGED CHARGE AIR COOLER.

Cause: Customer request Type: Customer Request

(Inspection)

Item	Description	Quantity	Rate	Amount
Labor	**Correction:** Engine / Cooling / REMOVED CHARGE AIR COOLER GOT GOOD USED ONE AND TESTED IT BEFORE I INSTALLED AND IT TESTED GOOD SO I INSTALLED CHARGE AIR COOLER AND TORQUED BOOTS ONTO PIPING. wAS NOT PROBLEM. CUSTOMER CHARGE AIR COOLER STILL GOOD. LEFT RED RAMS ON TO SAVE LABOR COSTS. - **Completed: 3/13/2025**	2.00000	$146.95	$293.90
			Subtotal	$293.90

Complaint: TOOK TRUCK TO MHPD TO HAVE PROGRAMMING CHECKED.

Cause: Customer request Type: Customer Request

(Inspection)

Labor	**Correction:** Engine / Exhaust / MHPD CHECKED TUNE. FOUND NOTHING WRONG. TOLD RED RAM TURBO WAS FAULTY. RED RAM TOLD MHPD THAT A DIFFERENT TURBO WAS TRIED, OPENED EXHAUST, SWAPPED CHARGE AIR COOLER OUT. CHECKED RODA VALVE. NOTHING CHANGED. MHPD DID SOME MORE AND FOUND A GHOST FAULT FOR EXHAUST BACK PRESSURE SENSOR. MHPD INSTALLED TEST SENSOR. RAN GOOD. RED RAM PURCHASED NEW EXHAUST BACK PRESSURE SENSOR AND WENT TO MHPD AND INSTALLED. TEST DROVE UNIT. DROPPED OFF AT KICHTON YARD. NOT ACTING UP ANYMORE. - **Completed: 3/13/2025**	0.00000		$0.00
Parts	Sensor Pressure	1.00000	$291.9045	$291.90
			Subtotal	$291.90
	50% LABOR CREDIT FOR ACTION #4	1.00	-$146.95	-$146.95
	50% LABOR CREDIT FOR ACTION #3	4.75	-$146.95	-$698.01

Unit: Lucy **VIN:** 1NPTP4EX7CD167922
2012 Peterbilt 367
In Service Date: 5/24/2024
Chassis: 1,213,421 Kilometers
Engine: 28,284 Hours

Labor	$3,453.33
Parts	$559.55
Shop Supplies	$241.73
Pre-Charge Subtotal	$4,254.61
50% LABOR CREDIT FOR ACTION #4	-$146.95
50% LABOR CREDIT FOR ACTION #3	-$698.01
GST (5% of $3,409.65)	$170.48
Total	$3,580.13
Payments & Credits	$0.00
Balance Due	$3,580.13

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

RED RAM
TRUCK PARTS & SERVICE

Invoice: **2501807**
Date: **2/28/2025**

Bill To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA
P: 780-257-9077

Ship To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA

Remit Payment To
Red Ram Sales Ltd
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
4028	COD	2/28/2025	Cory Rudyk		Rendell, Laura	Lucy

Item	Description	Quantity	Rate	Amount
	Complaint: ENGINE MISS			
	Cause: Customer request Type: Customer Request			
Labor	**Correction:** Engine / Fuel / UNIT CAME IN WITH ENGINE MISFIRE. HOOKUP COMPUTER AND FOUND NO CODES. TRIED TO DO INJECTOR PERFORMANCE TEST AND TEST WOULDN'T RUN DUE TO TOO MUCH FUEL DECAY. ENGINE WAS POPPING THROUGH THE EXHAUST INDICATING POSSIBLE TIGHT EXHAUST VALVE CLEARANCE. DID INDIVIDUAL INJECTOR CUT OUT TEST AND POPPING SOUND IS NOT SO PRONOUNCED WITH #2 INJECTOR CUT OUT. DID HI PRESSURE FUEL LEAK TEST WITH COMPUTER AND FOUND #2 AND #4 INJECTOR FUEL TUBES TO BE LEAKING SLIGHTLY. PULLED VALVE COVER, ALL FUEL TUBES AND INJECTORS TO CHECK FOR WEAR ON TUBES AND POSSIBLE CRACKED INJECTOR TIPS. ALL FUEL TUBES WERE LOOSE WHEN I WAS REMOVING THEM. INJECTORS VISUALLY LOOKED FINE. VERIFIED ALL INJECTOR CODES WERE PROPER AND INPUT INTO THE ECM. RE-INSTALLED ALL INJECTORS AND TORQUED INTO PLACE BUT I SWAPPED #2 AND #3 INJECTORS TO SEE IF THE POPPING MISFIRE SOUND WOULD FOLLOW THE INJECTOR. I CHECKED OVERHEAD SETTING AND FOUND VALVE AND JAKE SETTINGS WERE ALL OVER THE PLACE AND OUT OF SPEC. I DID A COMPLETE READJUSTMENT OF THE OVERHEAD. WITH EVERYTHING REASSEMBLED I RAN INJECTOR CUT OUT TEST AGAIN AND #3 CYLINDER IS NOW POPPING AND MISFIRING. I REPLACED THAT INJECTOR WITH A GOOD USEDTESTED INJECTOR AND RE-RAN THE TRUCK AGAIN. ENGINE SOUNDS GOOD NOW AS IT SHOULD. RE-RAN HI PRESSURE FUEL LEAK TEST AND PRESSURE HOLDING GOOD NOW WITH NO VISIBLE LEAKS. WASHED ENGINE AND RAN UP TO TEMPURATURE. TOOK UNIT FOR ROAD TEST TO VERIFY EVERYTHING IS OPERATING AS IT SHOULD. - **Completed: 2/21/2025**	7.00000	$146.95	$1,028.65

Item	Description	Quantity	Rate	Amount
			Subtotal	$1,028.65
	Unit: Lucy VIN: 1NPTP4EX7CD167922 2012 Peterbilt 367 **In Service Date:** 5/24/2024 **Chassis:** 1,206,247 Kilometers **Engine:** 28,135 Hours		**Labor**	$1,028.65
			Shop Supplies	$72.01
			Pre-Charge Subtotal	$1,100.66
			GST (5% of **$1,100.66**)	$55.03
			Total	$1,155.69
			Payments & Credits	$0.00
			Balance Due	$1,155.69

Workmanship: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) provides a limited warranty for a period of one (1) year on labor performed, exclusively covering defects in workmanship. This warranty expressly excludes coverage for parts, materials, misuse, neglect, or modifications made after the completion of service. Claims under this warranty must be submitted within one (1) year of service completion and are strictly limited to the correction of the original services provided.

Parts: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all warranties, expressed or implied, including but not limited to implied warranties of merchantability, fitness for a particular purpose, condition, quality, or suitability of parts sold. New parts may be subject to warranties provided by the original manufacturer. All used parts, including used engines, are sold on an "as-is" basis without warranty unless expressly specified in writing on the invoice.

Overhauled parts require the submission of a completed warranty form within thirty (30) days from the date of purchase. Failure to submit the warranty form within this period will result in a reduced warranty term of thirty (30) days from the date of purchase.

Acknowledgment of Terms and Conditions: By authorizing the work, the Buyer expressly acknowledges and agrees to these terms and conditions, including the "as-is" nature of used parts sales and the finality of all transactions with no returns, refunds, or exchanges permitted.

Vehicle Modifications Our warranty is void if the serviced vehicle has been altered from the manufacturer's original specifications, including but not limited to emissions modifications, structural changes, or engine tuning. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all liability for defects, failures, or operational issues resulting from such modifications. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) reserves sole discretion in determining the extent of any assistance offered in these cases.

Authorization for Additional Repairs or Service: The Customer hereby authorizes Red Ram Truck Parts & Service (Red Rams Sales Ltd) to perform repairs or services exceeding the original estimate by up to an additional amount of 15% without requiring further approval. Should additional costs exceed this threshold, the Service Provider shall obtain the Customer's consent before proceeding. Failure to obtain such consent does not relieve the Customer from the obligation to pay for authorized repairs or services performed.

Payment Terms: Payment in full is due immediately upon completion of repairs or services rendered. Customers are required to have payment or financing arrangements established before the completion of repairs. **The serviced unit will not be released until payment has been made in full.**

Red Ram Truck Parts & Service (Red Ram Sales Ltd.) does not offer direct financing. However, third-party financing options are available. Acceptable payment methods include cash, certified cheque, credit card, debit card, and wire transfer. No exceptions.

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

RED RAM
TRUCK PARTS & SERVICE

Invoice: **DRAFT INV**
Date: **1/30/2025**

Bill To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA
P: 780-257-9077

Ship To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA

Remit Payment To
Red Ram Sales Ltd
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
3996	COD	DRAFT INV	Cory Rudyk		Rendell, Laura	Lucy

Item	Description	Quantity	Rate	Amount
Complaint: CALIBRATE TURBO				
Cause: Customer request Type: Customer Request				
Labor	**Correction:** Engine / Exhaust / DRAINED COOLANT, REMOVED BANJO FITTINGS FROM VGT ACTUATOR AND REMOVED FROM TURBO. CHECKED HOT HOUSING SECTOR GEAR IS MOVING (SLIGHTLY STICKS BUT MOVES FULL RANGE) AND VGT MOTOR CALIBRATED CORRECTLY, PUT BACK ON AND COMPLETED INSTALLATION. REPLACED SEALING WASHERS TO ACTUATOR, REMOVED INACTIVE TURBO CODES AND FILLED BACK UP WITH COOLANT. TEST DRIVE. TOPPED UP COOLANT. - Completed: 1/30/2025	2.50000	$146.95	$367.38
			Subtotal	$367.38

Unit: Lucy **VIN:** 1NPTP4EX7CD167922
2012 Peterbilt 367
In Service Date: 5/24/2024
Chassis: 1,195,500 Kilometers
Engine: 27,880 Hours

Labor	$367.38
Shop **Supplies**	$25.72
Pre-Charge **Subtotal**	$393.10
GST (5% of $393.10)	$19.66
Total	$412.76

Work (Estimate) Authorized at 8:23AM 1/29/2025 by:

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

RED RAM
TRUCK PARTS & SERVICE

Invoice: 2501310
Date: ST-7922-PO-1346
1/24/2025

Bill To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA
P: 780-689-1110

Ship To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA

Remit Payment To
Red Ram Sales Ltd
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
3987	COD	1/24/2025	Cory Rudyk		Rendell, Laura	Lucy

Item	Description	Quantity	Rate	Amount
Complaint: ABS LIGHT ON				
Cause: Customer request Type: DOT Requirement				
Labor	**Correction:** Brakes / Brakes / CHECK FOR ABS CODES. RIGHT SIDE REAR AXLE CODE FOR OPEN OR SHORTED SENSOR. CHECK SENSORS AND SUPPLY VOLTAGE AS REQUIRED. CENTER DRIVE AXLE WHEEL SPEED SENSOR HAS HIGH RESISTANCE AND REAR RIGHT SIDE RESISTANCE CLOSE TO 1750 OHMS ALL THE REST ARE AT 1180 OHMS AND CONNECTIONS ARE FULL OF WATER. LUBE UP AND CLEAN ALL CONNECTIONS AS REQUIRED. PULL AXLE 3 RIGHT SIDE WHEELS AND BRAKE DRUM. REMOVE WHEEL SPEED SENSOR AND REPLACE WITH NEW ONE. PUSH SENSOR UP AGAINST TONE RING. REINSTALL DRUM AND WHEELS AND TORQUE TO 500LBS. INSTALL RETORQUE TAG ON KEY RING CLEAR CODES FROM ECM. - Completed: 1/24/2025	2.00000	$146.95	$293.90
Parts	Tie Wrap 15x0.30	4.00000	$0.48382	$1.94
Parts	Tie Wrap 14 x 0.2	15.00000	$0.3285	$4.93
Parts	Wheel Speed Sensor	1.00000	$106.725	$106.73
Parts	1/4 Push Connect Union	1.00000	$11.85428	$11.85
			Subtotal	$419.35
Complaint: GREASE TRUCK				
Cause: Customer request Type: Customer Request				
Labor	**Correction:** Chassis / Chassis / GREASE UNIT COMPLETE - Completed: 1/24/2025	0.50000	$146.96	$73.48
Parts	10 OZ Tube Grease	1.00000	$11.26664	$11.27

Item	Description	Quantity	Rate	Amount
			Subtotal	$84.75
PM: L1 Wheel Seals				
Cause: Customer request Type: Customer Request				
(PM)				
Labor	**Correction:** Chassis / Tire & Wheels / JACKED UP TRUCK, REMOVED L.S. STEER TIRE/DRUM/HUB OFF AS A SINGLE UNIT, REMOVED OLD SEAL. CLEANED BRAKE SHOES, DRUM, BACKING PLATE AND SPINDLE. INSTALLED NEW SEAL, REMOUNTED WHEEL/DRUM/HUB, REFILLED WITH HUB OIL AND ADJUSTED BRAKES. - **Completed: 1/24/2025**	2.20000	$146.95	$323.29
Parts	Wheel Seal	1.00000	$70.10179	$70.10
Parts	Brake Clean	1.00000	$9.05176	$9.05
Parts	Synthetic Transmission Oil	2.00000	$15.76	$31.52
			Subtotal	$433.96
Complaint: BROKEN BOLT IN SUSPENSION.				
Cause: Customer request Type: Customer Request				
(Inspection)				
Labor	**Correction:** Chassis / Chassis / DRIVE AXLE 2 LEFT SIDE OUTER SPRING TORQUE ARM BOLT IS BROKEN OFF. HEAT TORQUE ARM EYLET AND SUSPENSION BRACKET AND USE TORCH AND IMPACT TO GET BOLT TO BREAK FREE AND REMOVE. CLEAN OUT BOLT BORE AND INSTALL NEW HARDWARE AND TORQUE TO SPEC. - **Completed: 1/24/2025**	1.50000	$146.95	$220.43
Parts	5/8x6 NC Gr8 Bolt	1.00000	$4.21852	$4.22
Parts	5/8 Flat Washer	2.00000	$0.47788	$0.96
Parts	5/8-18 UNC Stover Locknut	1.00000	$0.64616	$0.65
			Subtotal	$226.26
Complaint: AXLE 4 R/S BRAKE PUSH ROD TRAVEL IS EXCESSIVE				
Cause: Customer request Type: Customer Request				
(Inspection)				
Labor	**Correction:** Brakes / Air Brakes / JACKED REAR AXLE UP, RELEASED BRAKES AND ADJUSTED BOTH SIDES THE SAME, SLACK ADJUSTERS RATCHETING PROPERLY, DID A FEW BRAKE APPLICATIONS AND ENGAGED PARK BRAKES AGAIN. BOTH CHAMBER PUSH RODS ARE SAME LENGTH WITH NO ISSUES APPARENT, ADJUSTMENT ON RIGHT CORRECTED PUSHROD STROKE. - **Completed: 1/24/2025**	0.40000	$146.95	$58.78
			Subtotal	$58.78
	ACTION #3 SERVICE DEPT WARRANTY PARTS AND LABOR.	1.00	-$433.96	-$433.96

Unit: Lucy VIN: 1NPTP4EX7CD167922
2012 Peterbilt 367
In Service Date: 5/24/2024
Chassis: 1,195,462 Kilometers
Engine: 27,826 Hours

Labor	$969.88
Parts	$253.22
Shop Supplies	$67.89
ACTION #3 SERVICE DEPT WARRANTY PARTS AND LABOR.	-$433.96
Pre-Charge Subtotal	$1,290.99
GST (5% of $857.03)	$42.85
Total	$899.88
Payments & Credits	$0.00
Balance Due	$899.88

Workmanship: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) provides a limited warranty for a period of one (1) year on labor performed, exclusively covering defects in workmanship. This warranty expressly excludes coverage for parts, materials, misuse, neglect, or modifications made after the completion of service. Claims under this warranty must be submitted within one (1) year of service completion and are strictly limited to the correction of the original services provided.

Parts: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all warranties, expressed or implied, including but not limited to implied warranties of merchantability, fitness for a particular purpose, condition, quality, or suitability of parts sold. New parts may be subject to warranties provided by the original manufacturer. All used parts, including used engines, are sold on an "as-is" basis without warranty unless expressly specified in writing on the invoice.

Overhauled parts require the submission of a completed warranty form within thirty (30) days from the date of purchase. Failure to submit the warranty form within this period will result in a reduced warranty term of thirty (30) days from the date of purchase.

Acknowledgment of Terms and Conditions: By authorizing the work, the Buyer expressly acknowledges and agrees to these terms and conditions, including the "as-is" nature of used parts sales and the finality of all transactions with no returns, refunds, or exchanges permitted.

Vehicle Modifications Our warranty is void if the serviced vehicle has been altered from the manufacturer's original specifications, including but not limited to emissions modifications, structural changes, or engine tuning. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all liability for defects, failures, or operational issues resulting from such modifications. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) reserves sole discretion in determining the extent of any assistance offered in these cases.

Authorization for Additional Repairs or Service: The Customer hereby authorizes Red Ram Truck Parts & Service (Red Rams Sales Ltd) to perform repairs or services exceeding the original estimate by up to an additional amount of 15% without requiring further approval. Should additional costs exceed this threshold, the Service Provider shall obtain the Customer's consent before proceeding. Failure to obtain such consent does not relieve the Customer from the obligation to pay for authorized repairs or services performed.

Payment Terms: Payment in full is due immediately upon completion of repairs or services rendered. Customers are required to have payment or financing arrangements established before the completion of repairs. **The serviced unit will not be released until payment has been made in full.**

Red Ram Truck Parts & Service (Red Ram Sales Ltd.) does not offer direct financing. However, third-party financing options are available. Acceptable payment methods include cash, certified cheque, credit card, debit card, and wire transfer. No exceptions.

Garage Keeper's Lien Notice: The vehicle described above is subject to a garage keeper's lien in favor of Red Ram Truck Parts & Service (Red Ram Sales Ltd.) for the full invoiced amount of parts, accessories, materials, and services provided. The lien shall remain in effect until full payment has been received and cleared, in accordance with the Garage Keepers Act (Alberta), as amended.

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

RED RAM
TRUCK PARTS & SERVICE

Invoice: **2501113**
Date: **1/13/2025**
ST-7922-PO-1345

Bill To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA
P: 780-689-1110

Ship To
K Energy
22644 112 Avenue Northwest
Edmonton, AB T5S 1Y5, CA

Remit Payment To
Red Ram Sales Ltd
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
3972	COD	1/13/2025	Cory Rudyk		Rendell, Laura	Lucy

Item	Description	Quantity	Rate	Amount
Complaint: REPLACE REAR ENGINE MOUNTS				
Cause: Customer request Type: Customer Request				
Labor	**Correction:** Chassis / Chassis / REPLACE REAR ENGINE MOUNTS, LEFT SIDE WAS A SUPER TIGHT FIT TO GET MOUNT LINED UP TO FRAME BOLTS, HAD TO REMOVE BOTH FENDERS TO COMPLETE SERVICE, HAD TO REMOVE BOTH REAR STRUCTURE BRACKETS TO REPLACE MOUNTS. REPLACED LEFT REAR STRUCTURE BRACKET, HAD TO CUT AND THEN REPAIR WIRING FOR RH FENDER TO MAKE ROOM FOR WORK. NOTE: RH FENDER BROKEN, ADVISED CUSTOMER.*** - Completed: 1/13/2025	9.50000	$146.95	$1,396.03
Parts	11/16-1 1/4 Clamp	1.00000	$4.8996	$4.90
Parts	Rear Engine Mount	2.00000	$484.48	$968.96
Parts	M16 Flat Washer	4.00000	$0.5992	$2.40
Parts	16MM X 70 GR10.9 Bolt	4.00000	$2.34334	$9.37
Parts	Sealed Beam	1.00000	$29.365	$29.37
Parts	5/8 Flat Washer	4.00000	$0.47788	$1.91
Parts	Tie Wrap 14 x 0.2	12.00000	$0.32318	$3.88
Parts	3/8-16 x 1-1/14 UNC Hex Bolt	2.00000	$0.34044	$0.68
Parts	3/8 Flat Washer	4.00000	$0.09398	$0.38
Parts	3/8-16 UNC Nylon Locknut Gr8 ZN	2.00000	$0.1596	$0.32
Parts	7.5" x 3/16 Tie Wrap	4.00000	$0.18672	$0.75
			Subtotal	$2,418.95
Complaint: REPLACE FRONT DRIVE AXLE GASKETS				
Cause: Customer request Type: Customer Request				

Item	Description	Quantity	Rate	Amount
Labor	**Correction:** Chassis / Tire & Wheels / AXLE FLANGE GASKETS LEAKING ON BOTH LEFT AND RIGHT SIDES ON FRONT DRIVE AXLE. LIFTED THE TRUCK UP AND PUT CAGING BOLTS IN THE BRAKE POTS THEN PUT DRIP TRAYS UNDER THE AXLES. UNDID THE AXLE BOLTS. REMOVED AXLES. CLEANED UP MOUNTING SERVICES. APPLED SILICONE TO THE NEW GASKETS. INSTALL AXLES. THEN TIGHTEN DOWN ALL THE BOLTS AND PUT THE AXLE BACK ON THE GROUND. CHECKED THE OIL IN THE DIFF. WAS GOOD. - Completed: 1/13/2025	1.50000	$146.95	$220.43
Parts	Axle Gaskets	2.00000	$3.32	$6.64
Parts	Brake Clean	1.00000	$9.05176	$9.05
Parts	Ultra Black	1.00000	$18.60	$18.60
Parts	5/8 Axle Stud	1.00000	$12.28	$12.28
Parts	5/8-18 UNC Stover Locknut	1.00000	$0.62706	$0.63
			Subtotal	$267.63

Complaint: COOLANT LEAK AT REAR OF ENGINE.

Cause: Customer request Type: Customer Request

(Inspection)

Labor	**Correction:** Engine / Cooling / COOLANT LEAKING DOWN FROM TRANSMISSION OIL COOLER CONNECTION HOSE. PINCH OFF COOLANT IN AND OUT CONNECTIONS TO TRANS OIL COOLER AND REPLACE SPRING CLAMP WITH GEAR CLAMP TO REPAIR COOLANT LEAK AT OIL COOLER CONNECTION. - Completed: 1/13/2025	1.00000	$146.95	$146.95
Parts	11/16-1 1/4 Clamp	1.00000	$4.8996	$4.90
			Subtotal	$151.85

Unit: Lucy **VIN:** 1NPTP4EX7CD167922
2012 Peterbilt 367
In Service Date: 5/24/2024
Chassis: 1,187,353 Kilometers
Engine: 27,671.40 Hours

Labor	$1,763.41
Parts	$1,075.02
Shop Supplies	$123.44
Pre-Charge Subtotal	$2,961.87
GST (5% of $2,961.87)	$148.09
Total	$3,109.96
Payments & Credits	$0.00
Balance Due	$3,109.96

Adrenaline Diesel
13019 - 151 Street NW
Edmonton, AB T5V 1A7, CA
info@adrenalinediesel.ca
(780) 907-1965

Invoice: 7937
Date: 12/16/2024

Bill To
K Energy Ltd.

P: (780) 257-9077

Remit Payment To
Adrenaline Diesel
13019 - 151 Street NW
Edmonton, AB T5V 1A7, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
6879	COD	12/16/2024	Cory Rudyk		Kremer, Jeff	ST7922

Item	Description	Quantity	Rate	Amount
PM: PRE-INSPECTION CHECKLIST				
Cause: Customer request				
(PM)				
Labor	**Correction:** Engine / Top End / pre inspection - Completed: 11/18/2024 - Assigned tech(s): Chase Denomme-McKibbin	0.00000		$0.00
			Subtotal	$0.00
Inspection				
Labor	UNDER HOOD CHECKLIST: Items to check BEFORE any unit leaves the shop. - Assigned tech(s): Chase Denomme-McKibbin, Christian Schram	0.00000		$0.00
			Subtotal	$0.00
Complaint: Repair for coolant pressuring up, possible head gasket??				
Cause: Cylinder liner 3 height below spec **Type:** Unscheduled repair				
Labor	**Correction:** Engine / Bottom End / drained engine oil and removed oil pan. pressure tested coolant system and found leak coming out of cylinder #3 .drained coolant and power steering fluid. removed rad. removed intake piping, coolant hoses. removed exhaust clamps and turbo. removed head. cleaned bottom of head and top of engine block. measured liner protrusions (will take picture of paperwork and upload). removed pistons and liners. found crack in counterbore shelf. Advised customer of block needing to be machined to correct issue. - Assigned tech(s): Chase Denomme-McKibbin Agreed to replace block with one we have in stock. unhooked remaining electrical and fuel lines. undid mount bolts, removed transmission bolts, and clutch bolts. removed engine. cleaned inside of frame. Strip engine down and find counterbores to be cracked remove all engine parts and put new engine block onto engine stand and install crankshaft plasti gauge crank find to be at 3 thou in spec remove crankshaft and lube all bearings reinstall and torque all main caps to spec install all new pistons and liners install new piston cooling nozzles and oil pump assembly install front structure and install lower timing gears and fuel pump plus new air compressor assembly install new cylinder head and torque to spec install new camshaft and retainer plates and torque to spec perform engine base timing and install rockers perform valve set and install new oil cooler into new housing as old one was damaged install onto engine and torque to spec finish assembling engine assembly ready to put back into frame Prescott - Assemble radiator, CAC and condenser.	55.00000	$160.00	$8,800.00

Item	Description	Quantity	Rate	Amount
	Lift and install radiator assembly. Install hood springs/cables. Install upper/lower rad hose and secure. Loom accessory wiring. Mount and install intake piping and charge pipes. - Completed: 12/13/2024			
Parts	ISX BLOCK, REMAN	1.00000	$4,000.00	$4,000.00
Parts	12OZ SPRAY SAFETY RED	4.00000	$25.96	$103.84
Parts	engine overhaul kit	1.00000	$13,654.13	$13,654.13
Parts	lower engine gasket kit	1.00000	$1,633.45	$1,633.45
Parts	oil pump assembly	1.00000	$1,461.44	$1,461.44
Parts	Inherent Core for oil pump assembly	1.00000	$211.20	$211.20
Parts	Dirty Core for oil pump assembly	-1.00000	$211.20	-$211.20
Parts	cylinder head locating dowels for cylinder block	2.00000	$26.53	$53.06
Parts	M16X1.5 CYLINDER BLOCK PLUGS	3.00000	$40.83	$122.49
Parts	sensor plate adapter gasket	1.00000	$31.48	$31.48
Parts	oil cooler housing	1.00000	$1,443.49	$1,443.49
Parts	ISX15 SINGLE CAM, INCONEL VALVE CYL HEAD, PERFORMANCE	1.00000	$6,500.00	$6,500.00
Parts	short cylinder head bolts	8.00000	$58.38	$467.04
Parts	coolant tube	1.00000	$176.70	$176.70
Parts	M8x4" 10.9 bolt	1.00000	$0.00	$0.00
Parts	Hawkins camshaft	1.00000	$0.00	$0.00
Parts	COOLANT FILTER	1.00000	$75.76	$75.76
Parts	OIL COOLER KIT	1.00000	$1,021.65	$1,021.65
Parts	THERMOSTAT (FOR UPGRADED OIL COOLER HOUSING 4386026CUM)	1.00000	$198.18	$198.18
Parts	RING,RETAINING	1.00000	$17.82	$17.82
Parts	PLUG,THREADED	1.00000	$88.61	$88.61
Parts	EGR, BELLOWS V BAND CLAMP	1.00000	$133.07	$133.07
Parts	cover plate gasket	1.00000	$39.48	$39.48
Parts	INTAKE PLUG/BLOCK PLATE, SMALL (CM2250/2350) - also need o-ring #138	2.00000	$100.00	$200.00
Parts	O-RING FOR INTAKE PLUG / PLATE (SM)	2.00000	$0.00	$0.00
Parts	15W40 HD DIESEL OIL BULK/L * GD	42.00000	$6.29	$264.18
Parts	REFRIGERANT /LB	4.00000	$39.52	$158.08
Parts	SUPER ATF POWER STEERING FLUID	2.00000	$9.95	$19.90
Parts	WINDSHIELD WASHER FLUID, -40 DEG	1.00000	$11.08	$11.08
Parts	15W40 HD DIESEL OIL BULK/L * GD	6.00000	$6.29	$37.74
			Subtotal	$40,712.67

Complaint: Sublet to machine flywheel

Cause: Customer request

(Inspection)

Labor	**Correction:** Engine / Bottom End / - Completed: 12/12/2024 - Assigned tech(s): Chase Denomme-McKibbin	0.00000		$0.00
Labor	MACHINE FLYWHEEL	1.00000	$150.00	$150.00
			Subtotal	$150.00

Item	Description	Quantity	Rate	Amount
Complaint: Remove engine and install engine				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Engine / Bottom End / removed engine from chassis. Install engine after overhaul. Had to straighten up wiring and correct some loose grounds in OEM harness as power would cut out as harness was moved. Install rad assembly after CAC and radiator were washed out and tested. Reflash ECM with our programming to insure proper runability. Ready unit for dyno. - Completed: 12/12/2024 - Assigned tech(s): Chase Denomme-McKibbin	12.00000	$160.00	$1,920.00
Parts	1/4" SPLIT LOOM / FT	4.00000	$0.00	$0.00
Parts	3/8" SPLIT LOOM / FT	2.00000	$0.00	$0.00
Parts	2.5" RAD HOSE / FT	1.00000	$200.80	$200.80
Parts	GASKET, DOSER TO TURBO	1.00000	$46.60	$46.60
Parts	GASKET, (THIN, EXHAUST 4"x4.75") CUMMINS	1.00000	$16.10	$16.10
Parts	ENGINE MOUNTS, FRONT	2.00000	$33.86	$67.72
Parts	STARTER	1.00000	$895.88	$895.88
Parts	LINKAGE ROD, CLUTCH	1.00000	$69.70	$69.70
			Subtotal	$3,216.80
Complaint: Sublet to dyno				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Chassis / Chassis / - Completed: 12/16/2024 - Assigned tech(s): Chase Denomme-McKibbin	0.00000		$0.00
Labor	BREAK-IN DYNO	1.00000	$831.40	$831.40
			Subtotal	$831.40
Complaint: Sublet to machine cylinder head				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Engine / Top End / - Completed: 12/3/2024 - Assigned tech(s): Chase Denomme-McKibbin	0.00000		$0.00
Labor	Machine cylinder head	1.00000	$1,045.43	$1,045.43
			Subtotal	$1,045.43
Complaint: Replace air compressor				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Chassis / Air Brake / R&R air compressor - Completed: 12/12/2024 - Assigned tech(s): Chase Denomme-McKibbin	1.00000	$160.00	$160.00
Parts	air compressor	1.00000	$3,223.98	$3,223.98
Parts	Inherent Core for air compressor	1.00000	$211.20	$211.20
Parts	Dirty Core for air compressor	-1.00000	$211.20	-$211.20
			Subtotal	$3,383.98

Item	Description	Quantity	Rate	Amount
Complaint: Replace clutch and install kit				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Transmission / Clutch / installed new suitcase kit and new clutch - Completed: 12/12/2024 - Assigned tech(s): Chase Denomme-McKibbin	2.00000	$160.00	$320.00
Parts	eaton 2050 easy pedal clutch (EATON ONLY)	1.00000	$1,673.33	$1,673.33
Parts	suitcase clutch install kit (EATON ONLY)	1.00000	$549.47	$549.47
Parts	2 PC CLUTCH BRAKE (see also BAC SB200)	1.00000	$82.71	$82.71
Parts	cross shaft washer	1.00000	$22.55	$22.55
Parts	thin cross shaft bolt	1.00000	$11.45	$11.45
			Subtotal	$2,659.51
Complaint: Sublet to tow out and back into shop				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Chassis / Chassis / - Completed: 12/11/2024 - Assigned tech(s): Chase Denomme-McKibbin	0.00000		$0.00
Labor	Tow in shop	2.00000	$0.00	$0.00
			Subtotal	$0.00
	Unforeseen parts, approx cost	1.00	$2,000.00	$2,000.00

Unit: ST7922 **VIN:** 1NPTP4EX7CD167922
License Plate: (AB) CSX-6305
2012 Peterbilt 367
Chassis: 1,178,622 Kilometers

Labor	$13,226.83
Parts	$38,772.96
Shop Supplies	$784.00
Pre-Charge Subtotal	$52,783.79
Unforeseen parts, approx cost	$2,000.00
GST (5% of $54,783.79)	$2,739.19
Total	$57,522.98
Payments & Credits	$0.00
Balance Due	$57,522.98

GST # 846835908 RT0001

Account terms are Net 30 days. Interest of 2.4% per month may be accrued and on accounts over 30 days. Warranty is subject to suspension or termination on services that are not paid within 90 days of invoice date. Acceptable payment methods include: Cash, Debit (+ $2.50 processing fee), Visa (+ 2.5% processing), Mastercard (+ 2.5% processing), AMEX (+ 3.0% processing), e-transfer to: accounting@adrenalinediesel.ca, EFT, wire transfer, certified cheque, bank draft, and PayPal to:

1635623 Alberta Inc. o/a
Adrenaline Diesel
@adrenalinedieselca

Adrenaline Diesel
13019 - 151 Street NW
Edmonton, AB T5V 1A7, CA
info@adrenalinediesel.ca
(780) 907-1965

Estimate 6879
Date: 11/13/2024

Bill To
K Energy Ltd.

P: (780) 257-9077

Remit Payment To
Adrenaline Diesel
13019 - 151 Street NW
Edmonton, AB T5V 1A7, CA

Service Order	Purchase Order	Service Writer	Authorizer
6879		Kremer, Jeff	Cory Rudyk

Item	Description	Quantity	Rate	Amount
PM: PRE-INSPECTION CHECKLIST				
Cause: Customer request (PM)				
Labor	**Correction:** Engine / Top End / pre inspection	0.00000		$0.00
			Subtotal	$0.00
Inspection				
Labor	UNDER HOOD CHECKLIST: Items to check BEFORE any unit leaves the shop.	0.00000		$0.00
			Subtotal	$0.00
Complaint: Repair for coolant pressuring up, possible head gasket?? OOS				
Cause: cylinder liner 3 height below spec **Type:** Unscheduled repair				
Labor	**Recommended Correction:** Engine / Bottom End / return cylinder liner 3 height back to factory spec	55.00000	$160.00	$8,800.00
Parts	ISX BLOCK, REMAN - A	1	$6,000.00	$6,000.00
Parts	engine overhaul kit - O	1	$13,654.13	$13,654.13
Parts	lower engine gasket kit - O	1	$1,633.45	$1,633.45
Parts	air compressor - O	1	$3,223.98	$3,223.98
Parts	oil cooler - O	1	$1,145.55	$1,145.55
Parts	DAMPER, SEVERE DUTY, ISX / SIGNATURE 600 / X-15 - A	1	$950.00	$950.00
Parts	oil pump assembly - O	1	$1,461.44	$1,461.44
Parts	sensor harness - O	1	$2,587.06	$2,587.06
Parts	Rocker Shaft Front - O	1	$576.50	$576.50
Parts	WATER PUMP - O	1	$801.50	$801.50

Item	Description	Quantity	Rate	Amount
Parts	sensor plate adapter gasket - O	1	$31.48	$31.48
Parts	rocker shaft rear - O	1	$578.46	$578.46
Parts	HDEO Mobil Delvac Oil 15W40 BW - A	52	$6.57	$341.64
Parts	COOLANT CONCENTRATE, HD EXPERT RED - A	40	$5.03	$201.20
			Subtotal	$41,986.39

Complaint: Sublet to machine/repair engine block

Cause: Customer request (Inspection)

Labor	**Recommended Correction:** Engine / Bottom End / Sublet to machine/repair engine block	0.00000		$0.00
			Subtotal	$0.00

Complaint: Remove and install engine

Cause: Customer request (Inspection)

Labor	**Recommended Correction:** Engine / Bottom End / Remove and install engine	12.00000	$160.00	$1,920.00
Parts	engine mounts front - A	2	$33.86	$67.72
Parts	engine mounts rear - A	2	$439.44	$878.88
			Subtotal	$2,866.60

Complaint: Sublet to dyno

Cause: Customer request (Inspection)

Labor	**Recommended Correction:** Chassis / Chassis / Sublet to dyno	0.00000		$0.00
Labor	BREAK-IN DYNO - O	1	$812.50	$812.50
	831.40		**Subtotal**	$812.50

Complaint: Sublet to machine cylinder head

Cause: Customer request (Inspection)

Labor	**Recommended Correction:** Engine / Top End / Sublet to machine cylinder head	0.00000		$0.00
Labor	Machine cylinder head	1	$3,660.00	$3,660.00
			Subtotal	$3,660.00
	Unforeseen parts, approx cost	1.00	$2,000.00	$2,000.00
	Shop Supplies			$750.40

Item	Description	Quantity	Rate	Amount
Unit: ST7922 VIN: 1NPTP4EX7CD167922 License Plate: (AB) CSX-6305 2012Peterbilt367 Chassis: 1,178,622 Kilometers				
	Labor			$15,192.50
	Parts			$34,132.99
	Unforeseen parts, approx cost			$2,000.00
	Subtotal			$52,075.89
	GST (5% of $52,075.89)			$2,603.79
	Total			$54,679.68

***: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.**
Estimates are valid for 30 days unless otherwise stated. FOB: Adrenaline Diesel Edmonton unless otherwise noted. Adrenaline Diesel is not responsible for delays due to parts shortages, freight delays, nor supply chain issues.

Shop Supplies of up to $1500 are applicable to all service estimates even if not noted. Additional fees for fluids and testing may apply. ALL engine projects are subject to Dyno prior to release and may, or may not, be included in original estimate. Engine projects that decline the dyno will forfeit all warranty. Dyno is required to activate warranty.

PARTS: Special Order parts may require a deposit and are final sale. Parts kits must be returned complete. Returns of partial kits will not be accepted. Kits must be in resalable condition. **NOTE:** Parts kits are supplied with all general components; however, due to variations in makes and models, additional parts and/or fabrication may be required. All Parts must be sent back in resalable, original packaging to qualify for credit. Cores must be returned within 30 days to be eligible for credit. Core charges will be refunded to the Customer only when the Supplier / Manufacturer accepts the core and issues credit. Parts not picked up within 30 days will be considered abandoned and will become property of Adrenaline Diesel.

Projects involving Customer supplied parts and components are subject to a 15% Parts Handling Fee that will be applied to the sub-total of the job.

Returns will not be accepted, nor processed, without a Returned Goods Authorization (RGA). Materials received without an authorized RGA will be returned to the sender at the sender's cost. Returns are subject to a minimum 15% restocking fee. Kits must be returned complete and unopened. Electronic components, used parts, and parts returned in non-saleable conditon will not be accepted. Please verify with your Representative prior to purchase and prior to return.

STORAGE: Units must be authorized for repair within 48 hours of notification. After 48 hours, storage fees of $50 / day will apply. After 7 days, Adrenaline Diesel reserves the right to remove the unit and all associated parts from our shop. Adrenaline Diesel is not responsible for loss or damage to units that are removed from our premises. Units that have been left for more than 90 days will be considered abandoned. Adrenaline Diesel is not responsible for loss or damages to vehicles remaining after 48 hours of completion. Customer acknowledges that units left for more than 48 hours after completion will be subject to additional costs for any assistance required to get the unit started. Vehicles left for more than 48 hours after completion are subject to storage fees at a minimum fee of $50 per day.

WARRANTY: Adrenaline Diesel honors manufacturer warranty. 1 year Parts & Labour warranty from original repair commencement date unless otherwise specified. Full Warranty details are available at **www.adrenalinediesel.ca/warranty**. Warranty is subject to suspension or termination on services that remain unpaid after 90 days.

Adrenaline Diesel is not responsible to ensure compliance of regional regulations.

ST- 7922 - PO - 1704

Red Ram Sales Ltd.
11210 Winterburn Rd NW
Edmonton, AB T5S 2B5, CA
service@redramtruck.ca
(780) 447-4946

Invoice: 125013
Date: 9/30/2024

Bill To	Ship To	Remit Payment To
K Energy 22644 112 Avenue Northwest Edmonton, AB T5S 1Y5, CA P: 780-689-1110	K Energy 22644 112 Avenue Northwest Edmonton, AB T5S 1Y5, CA	Red Ram Sales Ltd 11210 Winterburn Rd NW Edmonton, AB T5S 2B5, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
3774	COD	9/30/2024	Jim Olson		Redekopp, Mike	Lucy

Item	Description	Quantity	Rate	Amount
Complaint: CHECK ENGINE LIGHT ON.				
Cause: Customer request **Type:** Customer Request				
Labor	**Correction:** Engine / Ignition / ENGINE LIGHT ON CODE FOR CRANKCASE PRESSURE ACTIVE, REMOVED FILTER COVER POSSIBLY CLOGGED AND FOUND NO FILTER IS INSTALLED. PUT COVER BACK AND FOUND WIRING FROM ENGINE HARNESS THAT RUNS DOWN FRONT COVER SPLICED TOGETHER IN 2 SPOTS W/ BUTT CONNECTORS. CLEARED CODE AND WIGGLED WIRING AROUND TRYING TO TRIP ENGINE LIGHT AGAIN, COULD NOT GET CODE TO COME BACK. SECURED WIRES BETTER AWAY FROM FAN, NO MAJOR PROBLEMS CAUSED ENGINE LIGHT TO COME ON - Completed: 10/1/2024	1.30000	$137.95	$179.34
			Subtotal	$179.34
Complaint: OIL AND FILTER CHANGE.				
Cause: Customer request **Type:** Customer Request				
Labor	**Correction:** Chassis / Chassis / DRAINED OIL AND REMOVED OIL FILTER, PRE-FILLED AND INSTALLED NEW OIL FILTER, FILLED ENGINE WITH FRESH OIL, RAN AND TOPPED UP VERIFIED OIL LEVEL IS GOOD - Completed: 10/1/2024	0.60000	$137.95	$82.77
Parts	15W40 Bulk oil	44.00000	$6.88	$302.72
Parts	Oil Filter	1.00000	$65.42	$65.42
			Subtotal	$450.91
Complaint: GREASE JOB.				

Item	Description	Quantity	Rate	Amount
Cause: Customer request **Type:** Customer Request				
Labor	**Correction:** Chassis / Chassis / GREASED UNIT - Completed: 10/1/2024	0.50000	$137.96	$68.98
Parts	10 OZ Tube Grease	1.00000	$11.26662	$11.27
			Subtotal	$80.25
Complaint: LIGHTS DIAGNOSES				
Cause: Customer request **Type:** Customer Request				
(Inspection)				
Labor	**Correction:** Chassis / Lighting & Electrical / CHECKED LIGHT SYSTEMS, CHECKED FUSE PANEL IN FRONT OF PEDALS. FOUND BURNT FUSES, REPLACED FUSES- POWER LOCKS FUSE BURNT, FOUND SEVERED/CRUSHED WIRE AT DRIVER'S DOOR HINGE HARNESS PASS THROUGH POINT. REMOVED KICK PANEL, REPAIRED WIRE AND HARNESS, ROUTED AND SECURED HARNESS SO THAT IT WOULD NO LONGER BUNCH AND BE CRUSHED WHEN DOOR CLOSES. CHECKED FUSE PANEL UNDER HOOD, REPLACED BURNT FUSE, CHECKED ALL LAMPS-ALL LAMP AND TRAILER PLUG FUNCTIONS RESTORED. FOLLOWED WIRING HARNESS TO FIND THE REASON FOR BURNING FUSES. WIGGLE-TESTED WIRING HARNESS ALONG FRAME RAIL, FOUND 5 PIN CONNECTOR RUBBED RAW ON THIRD DRIVE AXLE TORQUE ROD BOLTS. RUB POINTS WERE NEAR TERMINALS, REPLACED TERMINALS, SECURED HARNESS TO PROTECT AGAINST FUTIURE WEAR. VERFIED LAMPS AND TRAILER CORD WORKING POST WIGGLE-TEST. - Completed: 10/1/2024	4.50000	$137.95	$620.78
Parts	18-22 Red Butt Connectors	1.00000	$1.02952	$1.03
Parts	7.5" x 3/16 Tie Wrap	5.00000	$0.17302	$0.87
Parts	1/2 Split Loom	1.00000	$0.6952	$0.70
Parts	15 Amp Fuse	1.00000	$0.62	$0.62
Parts	20 AMP Fuse	1.00000	$0.62	$0.62
Parts	5 Amp Fuse	1.00000	$0.70	$0.70
Parts	Ultra Black	1.00000	$18.60	$18.60
			Subtotal	$643.92
Complaint: INSTALL BOOST GASUGE				
Cause: Customer request **Type:** Customer Request				
(Inspection)				
Labor	**Correction:** Chassis / Instrument & Controls / REPLACED DEF LEVEL GAUGE WITH BOOST GAUGE, PROGRAMMED CECU TO IGNORE DEF LEVEL GAUGE AND UTILIZE BOOST GAUGE. VERIFIED GAUGE OPERATION - Completed: 10/1/2024	1.50000	$137.95	$206.93

Item	Description	Quantity	Rate	Amount
Parts	Used Boost Gauge	1.00000	$50.00	$50.00
			Subtotal	$256.93

Unit: Lucy **VIN:** 1NPTP4EX7CD167922
2012 Peterbilt 367
In Service Date: 5/24/2024
Chassis: 1,172,096 Kilometers
Engine: 27,318 Hours

Labor	$1,158.80
Parts	$452.55
Shop Supplies	$81.12
Pre-Charge Subtotal	$1,692.47
GST (5% of $1,692.47)	$84.62
Total	$1,777.09
Payments & Credits	$0.00
Balance Due	$1,777.09

Workmanship: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) provides a limited warranty for a period of one (1) year on labor performed, exclusively covering defects in workmanship. This warranty expressly excludes coverage for parts, materials, misuse, neglect, or modifications made after the completion of service. Claims under this warranty must be submitted within one (1) year of service completion and are strictly limited to the correction of the original services provided.

Parts: Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all warranties, expressed or implied, including but not limited to implied warranties of merchantability, fitness for a particular purpose, condition, quality, or suitability of parts sold. New parts may be subject to warranties provided by the original manufacturer. All used parts, including used engines, are sold on an "as-is" basis without warranty unless expressly specified in writing on the invoice.

Overhauled parts require the submission of a completed warranty form within thirty (30) days from the date of purchase. Failure to submit the warranty form within this period will result in a reduced warranty term of thirty (30) days from the date of purchase.

Acknowledgment of Terms and Conditions: By authorizing the work, the Buyer expressly acknowledges and agrees to these terms and conditions, including the "as-is" nature of used parts sales and the finality of all transactions with no returns, refunds, or exchanges permitted.

Vehicle Modifications Our warranty is void if the serviced vehicle has been altered from the manufacturer's original specifications, including but not limited to emissions modifications, structural changes, or engine tuning. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) disclaims all liability for defects, failures, or operational issues resulting from such modifications. Red Ram Truck Parts & Service (Red Ram Sales Ltd.) reserves sole discretion in determining the extent of any assistance offered in these cases.

Authorization for Additional Repairs or Service: The Customer hereby authorizes Red Ram Truck Parts & Service (Red Rams Sales Ltd) to perform repairs or services exceeding the original estimate by up to **an additional amount of 15%** without requiring further approval. Should additional costs exceed this threshold, the Service Provider shall obtain the Customer's consent before proceeding. Failure to obtain such consent does not relieve the Customer from the obligation to pay for authorized repairs or services performed.

Payment Terms: Payment in full is due immediately upon completion of repairs or services rendered. Customers are required to have payment or financing arrangements established before the completion of repairs. **The serviced unit will not be released until payment has been made in full.**

Red Ram Truck Parts & Service (Red Ram Sales Ltd.) does not offer direct financing. However, third-party financing options are available. Acceptable payment methods include cash, certified cheque, credit card, debit card, and wire transfer. No exceptions.