Vehicle History Summary

Local Mix Concrete

Fleet #	E04
Registration	ZX470-3
Make	Hitachi
Model	ZX470-3 new
VIN / Chassis	24463
Build Date	2012

Number	Date	Km	Hours	Fuel Usage	Type	Repairer Notes	Repairer
R-7930	2026-07-15		12307	0	Bucket	Remove both lower guards. Clean out dirt packed under them. Re-fit guards with new pins and retainers (x4). Upper guards are ok.	
R-7929	2026-05-29		12307	0	Fire extinguisher	Remove old mounting bracket. Modify existing mounting to take new style bracket. Install new bracket and fire extinguisher.	
R-7856	2026-05-22		12301	0	quick hitch	Remove tube over boom that was leaking, had rubbed through on a bracket. Have Pirtek make up a hose to replce it. Return and fit new hose. All ok now.	
R-7535	2026-05-07		12295	0	Welding	Welded up, job complete.	
R-5420	2024-10-08		12147	0	Hydraulics	May be intermittant. When tested machine worked correctly. Slew was positive and responsive, with full bucket also. Spec is 9 RPM. Tested at exactly 9 RPM. All ok.	
S-814	2024-04-16		12043		C - 2000hr		
R-4395	2024-02-06		11924	0	Engine	Checked key start switch and turbo timer. Ignition , dash, and accessories were all powered up like main relay had stuck on. Re-set seat switch, which had been used to stop engine and started machine. When switched off, it shut down as normal, several times. All ok. Replaced battery isolator switch, which had failed. (Contacts always closed regardless of switch position.) Needs new E-stop switch. NC switch fitted now, should be NO. Switch on order. 5.2.2024 install new n/o contact E stop switch. All ok now.	
R-4301	2024-01-15		11905	0	Hose	Track brake supply hose. Removed by operator. Pirtek made new hose as per sample. Install new hose between valve and swivel joint. Refill hydralic tank to full level, and bleed air from pump case drain. Tested, all ok now.	
R-4252	2023-12-21		11894	0	Hydraulics		
R-4126	2023-12-14	0	11905	0	Fabrication	bucket repairs cracks tooth adaptors plated side walls	

R-3950	2023-10-19	0	0	0	Welding	Repair the bucket side wall and hydraulic hose(completed). One on one conversation with operator on technique and needs to demonstrate due diligence when using equipment.	
R-2524	2023-02-20		11615	0	Fuel Cap	Replace missing fuel cap with new one. Also supplied one spare , to keep on site.	
R-2473	2023-01-24		11591	0	Chassis	Replace bonnet latches with new ones.	
R-2472	2023-01-24		11591	0	Electrical	Replace non genuine travel alarm with new Hitachi alarm which connects all wires through a sealed connector plug.	
S-442	2022-12-20		11517		A - 500hr	500 hour service, top up hydraulics, adjust a/c and alternator belts, adjust tracks.	
R-875	2022-03-28	0	0	0	G.E.T	old Arrowhead gouged back and bucket prepper for new arrowhead New arrowhead welded on Crack in middle of back wall of bucket excavated and fixed New bisloy plate added to bottom of bucket wear old one was worn Two cracks fixed on outside adaptors of bucket still a few in the middle adaptors/ noted	
R-840	2022-03-23	0	11274	0	Hitch		
R-24	2022-01-27			0	Windscreen		
R-161	2021-11-18	0	0	0	Electrical		
S-142	2021-10-26	0	11000		B - 1000hr	needs new windscreen	
S-97	2021-02-24		10500		A - 500hr	Service completed	