Vehicle History Summary

Local Mix Concrete

Fleet #	E02
Registration	CAT 330D
Make	CAT
Model	330D
VIN / Chassis	AMEY00453
Build Date	2010

Number	Date	Km	Hours	Fuel Usage	Type	Repairer Notes	Repairer
R-7414	2026-01-15			0	Air Conditioner		
R-7094	2026-01-07			0	Airconditioner		
R-6724	2025-08-27		14255	0	Windscreen	Replace windscreen retracting cable and spring mechanism. Replace top latch, all with new parts. Window raises and lowers correctly now.	
R-6583	2025-07-25		14227	0	Hose	Replaced SOS valve for hydraulics, replaced case drain hose from pump and quick coupler hose from pump. All ok now.	
R-5762	2025-01-08		14115	0	Hydraulics	Replaced steel boom hydraulic line with new one, which supplies stick cylinder, rod in.	
R-5366	2024-09-25		14095	0	Chassis	Topped up slew gear with heavier grease to monitor result. 8 x tubes of hi tec EP red grease.	
R-5215	2024-08-08			0	Hydraulics		
S-859	2024-07-09		14000		C - 2000hr		
R-4125	2023-12-01			0	Welding	steps straightened as per request	
R-4069	2023-11-23		13817	0	Hydraulics	pulled off hyd pump, replaced drive coupling, rear main seal and seal in hyd pump. replaced all three hyd filters. replaced x1 hyd line and x1 oil line	
R-4124	2023-11-14			0	door		
R-3042	2023-05-02			0	Tracks		
R-2980	2023-05-01		13595	0	Hydraulics	Check machine, tracknow working properly. Will monitor to see if fault re-occurs...	
R-2880	2023-05-01		13595	0	quick hitch	Replaced bent quick hitch safety pin with new one. Secured with bot and lock nut.	
R-3016	2023-05-01			0	Hydraulics		
R-2882	2023-04-18		13512	0	Hydraulics	Rammer hammer due for reconditioning. Oil leaking from breather, oil leaking from cylinder seals and filling cylinder mounting cavity...leaking out from breather.	
S-549	2023-04-06		13512		A - 500hr		
R-2733	2023-02-21			0	dip stick		
R-2445	2023-01-11			0	Hydraulics		
R-2276	2022-12-22		13288	0	Pin	new pin in set. Pin made by Boardmans, done	
R-791	2022-12-22		13228	0	Welding	new pin coming from william adams Pin made by Boardmans, done	
R-2252	2022-12-22		13228	0	Pin	Replaced pins (4) and bush's (9) and seals and shimmed quick hitch/stick. Dale line bored as required (8 holes). New safety pin and lock plate fitted, pin for hitch jaw made by Boardmans.	
R-2103	2022-12-02		13195	0	Engine	William Adams field service attended at Shepparton, noted engine running rough , with a missfire. Running on 5 cylinders. #3 injector had failed. New injector supplied and installed by William Adams field service.	
R-2051	2022-11-04			0	Hydraulics		
R-1926	2022-10-14			0	Electrical		
R-1880	2022-10-11			0	G.E.T		
R-1877	2022-10-05			0	G.E.T		
S-422	2022-09-21		13020		B - 1000hr		
R-1690	2022-09-21		13020	0	cabin	Remove old lever and replace with new safety lever. Tested ok now.	

R-1513	2022-08-26		12915	0	Hydraulics	Repaired on site by Enzed.	
R-1647	2022-08-24			0	Hydraulics		
R-830	2022-04-19			0	Exhaust	Parts supplied to Steven R, he is going to install.	
S-244	2022-03-18	0	12547		A - 500hr	Also bonnet, seat and wiper repairs	
R-657	2022-03-17	0	12500	0	Wipers	Replace front windscreen wiper motor and linkage assembly with new one. Wiper working correctly now.	
R-656	2022-03-17	0	12500	0	Guards	Replaced rh bonnet latch with new one.	
R-655	2022-03-17	0	12500	0	Seat Base	Inspect seat suspension base. Some movement is evident in the seat track slides and rollers. Not too bad. to repair would need new suspension base assembly. Lubricated all suspension pivot points with Inox. Seat now moves up and down without squeaking.	
R-792	2022-03-17	0	12500	0	cabin		
S-62	2021-08-02		12000		C - 2000hr	Service completed	Service Mechanic