



YELLOW HIRE



Atlas Industrial Holdings Pty Ltd
 Email: accounts@atlasholdings.com.au
 Phone: 1800 784 453
 ABN: 55 154 445 137
 Address: 526 Benetook Ave, Mildura Vic 3500

Service History

Date Generated: 18/03/2026 04:25 PM

Equipment Details

Equipment Number	YH164	Make:	Isuzu
Equipment Description	Isuzu FVZ260-300 Auto - 12,000L Diesel Fuel Truck	Model:	260-300
Serial Number	JALFVZ34SK7000007		

Date	Type	Description	Last Meter Reading
12/02/2020 12:50 PM	Work Order - Repair	844 - Travel to site. Illuka (balranald). Inspect machine, fuel leak in compartment. Removed fuel hose off hose reel and resealed threads. Reassembled and found fuel leaking from crimp fitting. Removed hose assembly and returned to workshop. Had new fitting crimped onto hose. Returned to site, reassembled and tested for correct operation.	
13/02/2020 03:32 PM	Work Order - Repair	727 - complaint: leaking fuel connections inside locker boxes. Cause: three different types of sealant were found on connections, some had no sealant, no thread tape used. Correction: pick up machine from site. Decanter all fuel from tanks at fuel depot. Remove and dismantle all connection in lockers, on all hose reels etc. reseal and replace any damaged fittings. Reassembled and partly filled with diesel. Tested and checked for leaks. Refilled tanks and returned machine to site.	
20/03/2020 06:03 PM	Work Order - Repair	1100 - Complaint: compressor not starting. Fuel filler overflowing Correction: checked over compressor unit. Checked all electrical connections. No faults found. Suspect battery isolator switch may have played up but working fine now. Fixed clearance lights on rh front pod. Inspect fuel quick fill and found hose off breather inside tank. Fished hose up and reconnected. Reassembled. Mal to test unit and report.	
30/03/2020 11:39 AM	Work Order - Repair	1110 - Carried out inspection service	
16/06/2020 08:28 AM	Work Order - Repair	1325 - travel to site and check over machine perform minor repairs run manual dp burn. Sublet MMM	
13/07/2020 08:06 AM	Work Order - Repair	1411 - travel to site, supply and fit new 30m hose reel.	
07/08/2020 08:13 AM	Work Order - Repair	1616 - Perform inspection based off 13k water truck noted compressor hard to start look at options to fit solar panel	
07/10/2020 08:57 AM	Work Order - Repair	1643 - Procure 40w solar panel with regulator. Sublet Dean Hibberd to fit	
07/10/2020 09:01 AM	Work Order - Repair	1847 - Supply filters for service	

Date	Type	Description	Last Meter Reading
07/12/2020 04:33 PM	Work Order - Repair	2263 - service compressor at 480 hours fit solar panel and hook in fuse protection check all hoses and attachments for use. Fit tap on high flow side of hose reel to protect the nozzles. Strip front compartment door to repair seized door catch.	
25/02/2021 04:51 PM	Work Order - Repair	2567 - run around and check all lights etc check tyres, run compressor, Sunraysia Petroleum dropped fuel into rear compartment, pump from rear to front, check gauges and fittings for leaks. Refit drain plugs and wash machine ready for hire.	
13/05/2021 03:07 PM	Work Order - Repair	2997 - E stop on compressor not working. Replaced E-stop. Compressor isolator not working, repaired isolator. UHF not working. Replaced UHF. Test ok.	553.00
25/05/2021 09:08 AM	Work Order - Repair	2911 - Take photos for risk assessment, Recheck lights and tyres etc, label beacon and work lamps, complete paper work for Leed. Check compressor operation. Remove side panel check,Found battery dry and flat. ,Procure new battery and terminals, wire in PWM to solar panel to control input amps, r and r battery and clamps, Service fire extinguisher, fit first aid kit.	553.00
01/09/2021 08:16 AM	Work Order - Repair	3737 - travel to site inspect fault found throttle control ramp adjuster arm fallen off remound and test and adjust no further fault travel.back to work shop comptesser hours 663	768.00
01/09/2021 02:09 PM	Work Order - Repair	3086 - Job started not completed due to truck going out on hire.	768.00
10/09/2021 10:08 AM	Work Order - Repair	3813 - Travel to site. Inspect fault found no fault instructed operator on how to shut dow the truck correctly. Travel back to depot.	
11/10/2021 09:10 AM	Work Order - Repair	3979 - Travel to site wait 3 hours to gain access to site(covid rules) inspect e1 code found no oil in receiver dryer. travel to local suppler for oil travel back tosite fill up oil tank run up unit and check discharge no oil present. pump 400 ltrs of diesel found no oil leaks.	768.00
02/12/2021 12:17 PM	Work Order - Repair	4335 - Travel to site. Found split hose near filler nozzle. Cut out splint refitted nozzle. Test ok.	
16/12/2021 05:00 PM	Work Order - Repair	BE4446 - Travel to site,sign in travel to location of unit. inspect issue found loose fitting on hand peice in front compartment. remove clean and reseal test found no further fault tighten x2 other fittings.	
22/03/2022 10:03 AM	Work Order - Repair	BE4795 - Replace flow meter and repaired leaks.	793.00
31/08/2022 03:18 PM	Work Order - Repair	BE5442 - Replaced Flowed due to one being smashed and the other stopped working.	1644.00
14/11/2022 12:48 PM	Work Order - Repair	BE5978 - Flow meter not required (kept as spare in Bendigo).	1652.00
14/11/2023 12:27 PM	Work Order - Repair	M8441 - supply only grease drum pump for fuel truck hours only an estimate on repair	1750.00