

**4718 Sergeant Road
Waterloo, IA 50701
319-234-8710
www.midcountry.co**

Ship To:

Invoice To:

STK#/FLEET#
W004063
JD 700K DOZER
700K
HRS
2687
PIN/EIN
KXLHF312424

DOCUMENT# 1 C 166 NA 06/05/25 06/05/25

HYD HOSE LEAK

CORRECTION:

6/5/24 MG

REMOVED BLOWN HOSE. REPLACED SECOND TRIP.

6/6/25 TB

INSTALLED 2 NEW HOSES AND

B2JCFX0808

CBTMP

CHINA
WIGLE3700

TECHN

4	18.18
4	4.25
3	1.50
14	7.27
	PARTS
	LABOR

SEGMENT TOTAL==>

72011000

06/05/25 06/05/25

SEMENT#	C	166	NA

TRAVEL. SEGMENT

TRAVELER DEC:
CORRECTION:

LOCATED EAST OF KWIK TRIP NEXT TO 827 FISH
LOCATED EAST OF KWIK TRIP NEXT TO 827 FISH

DROVE 3 MILES TO CUSTOMER

DROVE 3 MILES BACK TO SHOT.
DROVE 3 MILES BACK TO JOB SITE

MID COUNTRY MACHINERY, LLC.

4718 Sergeant Road
Waterloo, IA 50701
319-234-8710
www.midcountry.com

Branch		WATERLOO		Page	
Date	09/22/25	Time	11:42:05 (Q)	01	
Account No.	VIETH001	Phone No.	3192771006	Invoice No.	
Ship Via	Purchase Order		W18265		
Salesperson			248		

SAME AS BELOW

Vieth Construction Corp
6419 Nordic Dr
Cedar Falls IA 50613

SERVICE INVOICE

STK#/FLEET# W004063 HRS PIN/EIN 2860 KX1HF312424 WARRANTY DATE HRS

SEGMENT# 1 C 241 NA 09/15/25 09/16/25

BROKEN BLADE PIVOT BOLTS

CORRECTION:

9/16/25 MG

BEGAN REMOVING BLADE CYLINDER PINS.

9/17/25 MG-CR

REMOVED BLADE. EXTRACTED BROKEN BOLTS. CLEANED GREASE CHANNELS.

9/18/25 MG

INSTALLED BLADE. TORQUED ALL BOLTS TO SPEC. GREASED MACHINE. FOUND RIGHT SIDE ENGINE DOOR TO HAVE A BROKEN LOWER HINGE PIN. SUGGEST NEW DOOR.

PERFORMED A 30 MINUTE PRESSURE TEST ON COOLING SYSTEM. SYSTEM DID NOT DROP PRESSURE. NO SIGNS OF A COOLANT LEAK AT THIS TIME INSTALLED MACHINE PANELS. RAN MACHINE, MACHINE IS OPERATING NORMALLY AT THIS TIME.

ADDITIONAL DESCRIPTION:

NEED TO LOOK AT BROKEN BLADE PIVOT BOLTS ALSO SAID IT WAS USING COOLANT LEFT SIDE ENGINE DOOR MISSING BOTTOM PIN.

9/15/25 EK

OP06830231

HARDWARE

1 71.11 PARTS

71.11 71.11 71.11