



**SERVICE ORDER  
CUSTOMER COPY**



User [REDACTED] Page 2

3	Advisor	[REDACTED]	F	[REDACTED]	C	[REDACTED]	Tag	
	Shop	S1	C	[REDACTED]	C	[REDACTED]	Location	04 9:00AM #2
	Priority		Cashiered				PO #	

License No	Odometer In	Odometer Out	InServ Date	Stock No
	257909	257909		
Year	Make	Model	Model No	Colour
2006	FORD	SUPER DUTY F-350 DRW	X33	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FTWX33P86EC43969				
Engine Size	6.0L OHV DI 32-VALVE V8 TURBO-	Fleet #		

GEN				CP	25.00
Technician	235 -		Est Parts		0.00
Cause	TAIL LIGHT COVER		Est Labour		0.00
Correction	NEED TO REMOVE TAIL LIGHT COVERS. REMOVED TAIL LIGHT COVERS. NEED TO HAVE GLUE CLEANED OFF.		Labour Total		25.00
			<b>Request Sub-total</b>		<b>25.00</b>
			Labour		950.74
			Parts		717.50
			Supplies		75.00
			<b>SUB-TOTAL</b>		<b>1,743.24</b>
			GST		87.16
			PST		104.59
			<b>TOTAL INVOICE</b>		<b>1,934.99</b>

**Operator is Responsible To Have Wheels Retorqued Within 100 Kilometers**

**Privacy Statement:** Personal information is collected in accordance with applicable privacy legislation and is governed by Moose Jaw Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

*Thank you for your business!*

DATE: \_\_\_\_\_ CUSTOMER SIGNATURE: \_\_\_\_\_

GST# 77557 8115 RT0001



**SERVICE ORDER**  
**CUSTOMER COPY**



User [REDACTED] MY Page 1

13	Advisor	[REDACTED]	P	[REDACTED]	0	[REDACTED]	Tag	
	Shop	S1	C	[REDACTED]	0	[REDACTED]	Location	04 9:00AM #2
	Priority		Cashiered				PO #	

License No	Odometer In	Odometer Out	InServ Date	Stock No
	257909	257909		
Year	Make	Model	Model No	Colour
2006	FORD	SUPER DUTY F-350 DRW	X33	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FTWX33P86EC43969				
Engine Size	6.0L OHV DI 32-VALVE V8 TURBO-	Fleet #		

Request	Description	Job	CSR	Status
CSGI	SGI INSPECTION	1	726	Original
<b>Labour</b>	<b>Description</b>		<b>Type</b>	<b>Amount</b>
CINSPECTIO			CP	169.95
Technician	97 -			0.00
Cause				169.95
Correction	PERFORMED SGI TRUCK INSPECTION.			169.95
	COVERS ON TAIL LIGHTS			
	EX LEAK AT R MANIFOLD OR DOWN PIPE- HARD TO TELL EXACT			
	LOCATION AS IT'S BEEN SPRAY PAINTED.			
			<b>Request Sub-total</b>	<b>169.95</b>

Request	Description	Job	CSR	Status			
GEN	INSPECT FOR EXHAUST LEAK- CUSTOMER WANTS IT REPAIRED WHAT DOES IT NEED?	2	726	Approved			
<b>Labour</b>	<b>Description</b>		<b>Type</b>	<b>Amount</b>			
GEN			CP	755.79			
<b>Part</b>	<b>Description</b>	<b>Shp</b>	<b>Bin</b>	<b>Type</b>	<b>Price</b>	<b>Amount</b>	
6C3Z 9448 A	GASKET	2	09D03	CRO	45.75	91.50	
EDM							
3C3Z 9S425 AA	BOLT - HEX.HEAD	16	01A10	CRO	6.50	104.00	
EDM							
W300013	BOLT	4	02C03	CRO	17.00	68.00	
EDM							
W300051	NUT - LOCKING	4	02C02	CRO	27.75	111.00	
EDM							
3C3Z 9430 AB	MANIFOLD ASY - EXHAU	1	RTN3	CRO	343.00	343.00	
EDM							
Technician	235 -					0.00	
Cause	EXHAUST MANIFOLDS					0.00	
Correction	CHECKED FOR EXHAUST LEAK. FOUND BOTH MANIFOLDS LEAKING. WILL					717.50	
	NEED TO REMOVE MANIFOLDS AND CHECK WARPAGE. REPLACE					755.79	
	MANIFOLDS IF NECESSARY, INSTALL GASKETS AND ALL HARDWARE.						
	REMOVED EXHAUST MANIFOLDS AND INSPECTED. RIGHT MANIFOLD IS						
	WARPED BEYOND SPEC AND SHOULD BE REPLACED. LEFT IS OKAY.						
	INSTALLED LEFT MANIFOLD. INSTALLED NEW RIGHT MANIFOLD AND						
	GASKET. RETESTED AND EXHAUST LEAK IS GONE.						
						<b>Request Sub-total</b>	<b>1,473.29</b>

Request	Description	Job	CSR	Status
GEN	INSPECT TAIL LIGHTS- WHAT DO THEY NEED TO PASS SAFETY	3	726	Approved
<b>Labour</b>	<b>Description</b>		<b>Type</b>	<b>Amount</b>

Operator is Responsible To Have Wheels Retorqued Within 100 Kilometers

**Privacy Statement:** Personal information is collected in accordance with applicable privacy legislation and is governed by Moose Jaw Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Thank you for your business!

DATE: \_\_\_\_\_ CUSTOMER SIGNATURE: \_\_\_\_\_

GST# 77557 8115 RT0001