



Repair Order Detail

RO: RO7H-0004221 **Status:** CLOSED **Repair Class:** SCHEDULED
Shop: SER3 Roosevelt Service Truck
Unit: B1103 PETERBILT 2018 567 X15 46K HEAVY
Customer PO #: **Repair Site:** FACILITY
Domicile: SAL **Make:** PTRBL **Opened:** 2/23/2026
Cost Cntr: 000 **Model:** 567 **Closed:** 3/17/2026
License: Z057123 **Year:** 2018 **Completed:** 3/13/2026
VIN: 1XPCD49X0JD472488 **In Service:** 7/26/2017
Odometer: 387,310

Section: 1	Priority: 5	Complaint: NOISEY	Rep Reason: INSPECTION
Component: 043-004		Cmp Descrip: Turbocharger	
War Type: EXPIRED		Unit War: None	
Comments: Jody called in noise from turbo			

Comment					
Date	Comment Text				
3/13/2026	Turbo bearings failed causing turbine to rub house ING drained coolant removed intake oil and coolant line turbo and studs installed new studs gasket and turbo ran install and calibration dumped oil into gally on turbo to prelude bearing finished assembly filled coolant cleaned up mess				

Labor					
Date	Mechanic	Description	Hours	Rate	Total
3/13/2026	SLA700	SLA700 - Turbocharger, WORN OUT, INSTALLED, REPLACED NEW	2.78	110.00	306.16

Part						
Date	Part ID	Description	After Mkt	Qty	Unit Price	Total
3/15/2026	SS1	Shop Supplies		1.00	21.62	21.62
3/16/2026	170-032-3873	Compressor - Turbocharger		1.00	5683.54	5,683.54
3/16/2026	3695041	Mounting Gasket - Turbocharger		1.00	15.44	15.44
3/16/2026	4298242	Stud - Mounting, Turbocharger		4.00	17.36	69.44
3/16/2026	4298975	Nut - Mounting Studs, Turbocharger		4.00	9.63	38.52
3/16/2026	5264570	Gasket - Turbo Oil Drain Tube		1.00	3.64	3.64

Task Details

Totals Repair Order RO7H-0004221	
US\$ - United States Dollars	
Total Parts Issued:	12.00
Total Labor Hours:	2.78
Total Part Charges:	5,832.20
Total Labor Charges:	306.16
Total Tax Charges:	0.00
Total Fee Charges:	0.00
Total Service Charges:	0.00
Repair Total:	6,138.36



Cost For Each Line Type

LABOR	306.16
PART	5,832.20

